

Title List of Documents Made Publicly Available

Docket 50 Documents from October through December 1978

U.S. Nuclear Regulatory Commission

Office of Administration



Available from

GPO Sales Program

Division of Technical Information and Decement Control

U.S. Nuclear Regulatory Commission

Washington, DC 20555

Printed copy price: \$8.00

and


National Technical Information Service Springfield, VA 22161

Title List of Documents Made Publicly Available

Docket 50 Documents from October through December 1978

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555





CONTENTS

reface	
rrangement of Items by Docket Number	ix
Iphabetic Arrangement of Docket 50 Items by Facility Name	xii
omestic Licensing of Production and Utilization Facilities – Docket 50	1
ersonal Author Index	245
orporate Source Index	285
eport Number Index	319
ross Reference of Enclosures to Principal Documents	321
ppendix - Definitions of Docket 50 Categories	341

: :			·	


PREFACE

This special edition of the *Title List* contains Docket 50 material from 1978 that has not appeared in previous issues of the *Title List*. The documents in this supplement are indexed by personal author, corporate source, and report number. The listings of this material on the domestic licensing of production and utilization facilities, divided into the categories used for filing and searching in the NRC Public Document Room, are as follows:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence
- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters
- U. Congressional/executive correspondence
- V. Licensing operators and related correspondence
- W. Decommissioning stage documents and correspondence

The Appendix sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:



- 1. NRC/PDR Document category (see Appendix).
- 2. NRC Accession Number (year, month, day, and sequence number of item)
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position Indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source
- 6. Date of document described
- 7. Pages in document
- 8. This five-digit portion of this entry is the number of the microfiche copy of this document that is available to NRC staff who do not have access to microfiche files.
- 9. This three digit portion of this entry is the number of the microfiche frame on which this document starts.
- 10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO." See NOTES on this page for information about ordering publications.

The Docketed Items list is arranged sequentially by category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

NOTES:

1. The address for NRC is:

Director
Division of Technical Information and Document Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

To place orders, send check or money order, payable to the Superintendent of Documents. GPO Deposit Account holders may charge their orders by calling (301) 492-9530.

2. The address for NTIS is:

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this publication may be purchased. Reproduction charges for duplication are as follows: 8ϕ per page for standard size paper; 11ϕ per page for oversized paper (drawings); 25ϕ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Name	Page	Docket	Name	Page
Univ. of Michigan Research Reactor	1	50-99	Babrock & Wilcox Test Reactor	16
Indian Point Station, Unit 1	I	50-106	Oregon State Univ.	17
Battelle Memorial Inst. Research Reactor	3	50-112	Univ. of Oklahoma Research Reactor	17
Dresden Nuclear Power Station, Unit 1	3	50-113	Univ. of Arizona Research Reactor	18
Babcock & Wilcox Co. Critical Facility	6	50-116	Iowa State Univ. Research Reactor	18
Enrico Fermi Atomic Power Plant, Unit 1	6	50-123	Univ. of Missouri Research Reactor	18
Vallecitos Boiling Water Reactor	6	50-128	Texas A&M Univ. Research Reactor	18
Massachusetts Institute of Technology Research Reactor	6	50-131	Omaha Veterans Administration Hospital Research Reactor	18
Westinghouse Test Reactor	7	50-133	Humboldt Bay Power Plant, Unit 3	18
Washington State Univ. Research Reactor	7	50-134	Worcester Polytech Institute Research	19
Yankee-Rowe Nuclear Power Station	7	50.140	Reactor	19
Plum Brook Research Reactor Facility	10	50-142	UCLA Training Reactor	
Union Carbide Research Reactor	10	50-146	Saxton Nuclear Experimental Facility	19
State Univ. of New York Research Reactor	10	50-147	Rockwell International Corp. Critical Facility	20
Texas A&M Univ. Research Reactor	11	50-148	Univ. of Kansas Research Reactor	20
Univ. of Virginia Research Reactor	11	50-155	Big Rock Point Nuclear Plant	20
General Electric Test Reactor	11	50-157	Cornell Univ. Research Reactor	23
Univ. of Utah Research Reactor	15	50-160	Georgia Institute of Technology Research	23
General Electric Nuclear Test Reactor	15		Reactor	
Catholic Univ. of America Research Reactor	15	50-163	General Atomic Company	24
Univ. of Florida Training Reactor	15	50-170	National Naval Medical Center	24
Westinghouse Critical Experiment	16	50-171	Peach Bottom Atomic Power Station, Unit 1	24
General Atomic Co.	16	50-182	Purduc Univ. Research Reactor	24
Rockwell International Research Reactor	16	50-183	Vallecitos Experimental Superheat Reactor	24
Cornell Univ. Zero Power Reactor	16	50-184	National Bureau of Standards Reactor	24
Univ. of Delaware Research Reactor	16	50-186	Univ. of Missourl Research Reactor	25

Docket	Name	Page	Docket	Nate	Page
50-187	Space Radiation Research Reactor	25	50-269	Oconee Nuclear Station, Unit I	97
50-188	Kansas State Univ. Research Reactor	25	50-270	Oconec Nuclear Station, Unit 2	101
50-193	Rhode Island & Providence Plantations AEC	25	50-271	Vermont Yankee Nuclear Power Station	104
50-200	B&W Test Reactor	25	50-272	Salem Nuclear Generating Station, Unit 1	106
50-201	West Valley Reprocessing Plant	25	50-274	U.S. Geological Survey Research Reactor	110
50-206	San Onofre Nuclear Station, Unit 1	26	50-275	Diablo Canyon Nuclear Power Plant, Unit 1	110
50-213	Haddam Neck Plant	30	50-276	Georgia Technology Research Reactor	116
50-219	Oyster Creek Nuclear Power Plant	33	50-277	Peach Bottom Atomic Power Station, Unit 2	116
50-220	Nine Mile Point Nuclear Station, Unit 1	37	50-278	Peach Bottom Atomic Power Station, Unit 3	119
50-223	Univ. of Lowell Research Reactor	40	50-279	Santa Maria De Garona Nuclear Power Plant	121
50-224	Univ. of California Research Reactor	40	50-280	Surry Power Station, Unit 1	122
50-225	RPI Critical Experiment	40	50-281	Surry Power Station, Unit 2 .	126
50-227	TRIGA Thermionic Prototype Reactor	40	50-282	Prairie Island Nuclear Station, Unit 1	130
50-236	Lockheed Aircraft Corp.	40	50-284	Idaho State Univ. Research Reactor	132
50-237	Dresden Nuclear Power Station, Unit 2	40	50-285	Fort Calhoun Station, Unit 1	132
50-243	Oregon State Univ. Research Reactor	45	50-286	Indian Point Station, Unit 3	135
50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	45	50-287	Oconee Nuclear Station, Unit 3	139
50-245	Millstone Nuclear Power Station, Unit 1	.48	50-288	Reed College Research Reactor	142
50-247	Indian Point Station, Unit 2	52	50-289	Three Mile Island Nuclear Station, Unit 1	142
50-249	Dresden Nuclear Power Station, Unit 3	55	50-290	Proof Test Facility	144
50-250	Turkey Point Plant, Unit 3	59	50-293	Pilgrim Nuclear Power Station, Unit 1	144
50-251	Turkey Point Plant, Unit 4	64	50-295	Zion Nuclear Power Station, Unit 1	146
50-252	Univ. of New Mexico Research Reactor	69	50-296	Browns Ferry Nuclear Power Station, Unit 3	150
50-254	Quad-Cities Station, Unit 1	69	50-297	North Carolina State Univ. Pulstar Reactor	154
50-255	Palisades Nuclear Plant	72	50-298	Cooper Nuclear Station	154
50-259	Browns Ferry Nuclear Power Station, Unit 1	75	50-301	Point Beach Nuclear Plant, Unit 2	157
50-260	Browns Ferry Nuclear Power Station, Unit 2	79	50-302	Crystal River Nuclear Plant, Unit 3	159
50-261	H.B. Robinson Plant, Unit 2	82	50-304	Zion Nuclear Power Station, Unit 2	163
50-263	Monticello Nuclear Generating Plant	85	50-305	Kewaunee Nuclear Power Plant	166
50-264	Dow Chemical Co.	88	50-306	Prairie Island Nuclear Station, Unit 2	169
50-265	Quad-Cities Station, Unit 2	88	50-309	Maine Yankee Atomic Power Plant	171
50-266	Point Beach Nuclear Plant, Unit 1	91	50-311	Salem Nuclear Generating Station, Unit 2	173
50-267	Fort St. Vrain Nuclear Generating Station	94	50-312	Rancho Seco Nuclear Generating Station	176

Name	Page	Docket	Name	Page
Arkansas Nuclear One, Unit 1	179	50-325	Brunswick Steam Electric Plant, Unit 1	213
Donald C. Cook Nuclear Power Plant, Unit 1	182	50-326	Univ. of California at Irvine Research Reactor	216
Donald C. Cook Nuclear Power Plant, Unit 2	185	50-237	Sequoyah Nuclear Plant, Unit 1	216
Calvert Cliffs Nuclear Power Plant, Unit 1	190	50-328	Sequoyah Nuclear Plant, Unit 2	220
Calvert Cliffs Nuclear Power Plant, Unit 2	192	50-329	Midland Plant, Unit 1	223
Three Mile Island Nuclear Station, Unit 2	195	50-330	Midland Plant, Unit 2	229
Edwin 1, Hatch Nuclear Plant, Unit 1	199	50-331	Duane Arnold Energy Center	234
Shoreham Nuclear Power Station	202	50-332	Barnwell Reprocessing Plant	238
Diablo Canyon Nuclear Power Plant, Unit 2	205	50-333	James A. Fitzpatrick Nuclear Power Plant	238
Brunswick Steam Electric Plant, Unit 2	210	50-334	Beaver Valley Power Station, Unit 1	241

-313 -315 -316 -317 -318 -320 -321 -322 -323 -324

ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket
Arkansas Nuclear One, Unit 1	50-313	179	Dresden Nuclear Power Station, Unit 2	50-237
Duane Arnold Energy Center	50-331	234	Dresden Nuclear Power Station, Unit 3	50-249
Babcock & Wilcox Co. Critical Facility	50-13	6	James A. Fitzpatrick Nuclear Power	50-333
Babcock & Wilcox Co. Test Reactor	50-99	16	Plant	
Beaver Valley Power Station, Unit 1	50-334	241	Fort Calhoun Station, Unit 1	50-285
Big Rock Point Nuclear Power Plant	50-155	20	Fort St. Vrain Nuclear Generating Station	50-267
Browns Ferry Nuclear Power Station, Unit 1	50-259	75	General Atomic Co.	50-89
			General Atomic Co.	50-163
Browns Ferry Nuclear Power Station, Unit 2	50-260	79	General Electric Nuclear Test Reactor	50-73
Browns Ferry Nuclear Power Station,	50-296	150	General Electric Test Reactor	50-70
Unit 3			Georgia Institute of Technology Research Reactor	50-160
Brunswick Steam Electric Plant, Unit 1	50-325	213	Georgia Tech Research Reactor	50-276
Brunswick Steam Electric Plant, Unit 2	50-324	210	•	
Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	190	Robert Emmet Ginna Nuclear Plant, Unit 1	50-244
Calvert Cliffs Nuclear Power Plant,	50-318	192	Haddam Neck Plant	50-213
Unit 2	20-210	1,2	Edwin I. Hatch Nuclear Plant, Unit 1	50-321
Catholic Univ. of America Research Reactor	50-77	15	Humboldt Bay Power Plant, Unit 3	50-133
Donald C. Cook Nuclear Power Plant, Unit 1	50-315	182	Idaho State Univ. Research Reactor	50-284
Donald C. Cook Nuclear Power Plant, Unit 2		185	Indian Point Station, Unit 1	50-3
•		-	Indian Point Station, Unit 2	50-247
Cooper Nuclear Station	50-298	154	Indian Point Station, Unit 3	50-286
Crystal River Nuclear Plant, Unit 3	50-302	159	Iowa State Univ. Research Reactor	50-116
Diablo Canyon Nuclear Power Plant, Unit 1	50-275	110	Kansas State Univ. Research Reactor	50-188
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	205	Kewaunee Nuclear Power Plant	50-305
Dow Chemical Co.	50-264	88	Maine Yankee Atomic Power Plant	50-309
Dresden Nuclear Power Station, Unit 1	50-10	3	Massachusetts Institute of Technology Research Reactor	50-20

ne	Docket	Page	Name	Docket	Page
land Plant, Unit 1	50-329	223	Quad-Cities Station, Unit 2	50-265	88
land Plant, Unit 2	50-330	229	Rancho Seco Nuclear Generating Station	50-312	176
stone Nuclear Power Station, Unit 1	50-245	48	Reed College Research Reactor	50-288	142
nticello Nuclear Generating Plant	50-263	85	Rhode Island & Providence Plantations AEC	50-193	25
ional Bureau of Standards Reactor	50-184	24	H.B. Robinson Plant, Unit 2	50-261	82
ional Naval Medical Center	50-170	24	Rockwell International Research Reactor	50-94	16
e Mile Point Nuclear Station, Unit 1	50-220	37	RPI Critical Experiment	50-225	40
th Carolina State Univ. PULSTAR	50-297	154	Salem Nuclear Generating Station, Unit 1	50-272	106
Reactor			Salem Nuclear Generating Station, Unit 2	50-311	173
nee Nuclear Station, Unit 1	50-269	97	San Onofre Nuclear Station, Unit 1	50-206	26
nee Nuclear Station, Unit 2	50-270	101	Sequoyah Nuclear Plant, Unit 1	50-327	216
nee Nuclear Station, Unit 3	50-287	139	Sequoyah Nuclear Plant, Unit 2	50-328	220
aha Veterans Administration Hospital Research Reactor	50-131	18	Shoreham Nuclear Power Station	50-322	202
gon State Univ.	50-106	17	Space Radiation Research Reactor	50-187	25
gon State Univ. Research Reactor	50-243	45	State Univ. of New York Research Reactor	50-57	10
ter Creek Nuclear Power Plant	50-219	33	Surry Power Station, Unit 1	50-280	122
sades Nuclear Plant	50-255	72	Surry Power Station, Unit 2	50-281	126
ch Bottom Atomic Power Station, Unit 1	50-171	24	Texas A&M Univ. Research Reactor	50-59	11
ch Bottom Atomic Power Station,	50-277	116	Texas A&M Univ. Research Reactor	50-128	18
Unit 2	30-277	110	Three Mile Island Nuclear Station, Unit 1	50-289	142
ch Bottom Atomic Power Station, Unit 3	50-278	119	Three Mile Island Nuclear Station, Unit 2	50-320	195
			Turkey Point Plant, Unit 3	50-250	59
rim Nuclear Power Station, Unit 1	50-293	144	Turkey Point Plant, Unit 4	50-251	64
m Brook Research Reactor Facility	50-30	10	UCLA Training Reactor	50-142	19
nt Beach Nuclear Plant, Unit 1	50-266	91	Union Carbide Research Reactor	50-54	10
nt Beach Nuclear Plant, Unit 2	50-301	157	Univ. of Arizona Research Reactor	50-113	18
irie Island Nuclear Station, Unit 1	50-282	130	Univ. of California at Irvine Research Reactor	50-326	216
irie Island Nuclear Station, Unit 2	50-306	169	Univ. of California Research Reactor	50-224	40
due Univ. Research Reactor	50-182	24	Univ. of Florida Training Reactor	50-83	15
ad-Cities Station, Unit 1	50-254	69	Univ. of Kansas Research Reactor	50-148	20

Name	Docket	Page	Name	Docket
Univ. of Lowell Research Reactor	50-223	40	Vallecitos Boiling Water Reactor	50-18
Univ. of Michigan Research Reactor	50-2	1	Vallecitos Experimental Superheat Reactor	50-183
Univ. of Missouri Research Reactor	50-123	18	Vermont Yankee Nuclear Power Station	50-271
Univ. of Missouri Research Reactor	50-186	25	Washington State Univ. Research Reactor	50-27
Univ. of New Mexico Research Reactor	50-252	69	Westinghouse Critical Experiment	50-87
Univ. of Oklahoma Research Reactor	50-112	17	West Valley Reprocessing Plant	50-201
Univ. of Utah Research Reactor	50-72	15	Yankee-Rowe Nuclear Power Station	50-29
Univ. of Virginia Research Reactor	50-62	11	Zion Nuclear Power Station, Unit 1	50-295
U.S. Geological Survey Research Reactor	50-274	110	Zion Nuclear Power Station, Unit 2	50-304

DOCKETED ITEMS

DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

F. Security, medical, emergency & fire protection plans

7810230163 Changes to Security Plan for subj facil have been eval as subsitted, in ltrs dtd 780712 & 780825. Changes do not decrease effectiveness of plan & are acceptable. Submittals contain proprietary info & are w/held from pub disclosure.

REIO.R M. Operating Reactors Branch 4 (Pre 790625). 78/10/06. 1p. 94170.142.

P. Operating license stage documents & correspondence

- 7811020140 Forwards Amend#25 to Fecil Oper LiceR-28 revising tech specs as requested in 780913 ltr w/Bafety Evaluation Rept. REID.R.W. Operating Reactors Branch 4 (Pre 790625), 78/10/12, 2pp. 94334:287.
- --7811020146 Amend#25 to Facil Oper Lic#R-28 revising tech speca re auth of intermetallic Uranium Alminide (UAIX) & Uranium Oxide (U308) Cermet Fuels in addition to uranium-aluminum alloy fuel & deletion of cold sump alerm.

 REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/12.
 20p 94354:289.
- --7811020150 Safety Evaluation Rept Supporting Amend#25 to Fecil Oper LiceR-28 concluding that UAIX & U308 fuels are acceptable alternatives in the FML. • Office of Nuclear Reactor Regulation, Director. 78/10/12. 7pp. 74334:296.
- 7811080013 Forwards Amend@26 to Facil Open LiceR-28 revising tech specs 4s requested in 780928 ltm w/safety Evaluation. REID.R.W. Operating Reactors Branch 4 (Pre 790626). 78/10/13. 2pp. 94422:225.
- --78i1060015 Amend826 to Facil Open LiceR-28 revising Tech Specs to auth pwr level for Ford Nuc Reactor when iO-plate fuel assemblies from PSU Res Reactor are utilized in E.W. & 8 frings locations of reactor core. REID.R.W. Openating Reactors Branch 4 (Pre 790625). 78/10/13. 799. 94422:227.
- --78:1060019 Safety Evaluation Rept supporting Amend#26 to Facil Oper-LiceR-28 concluding that an increase from 1 Nw to 2 Nw in sattawn allowed pur of FNR w/10-plate fuel assemblies in E/W & B core positions is accepteble. • Office of Nuclear Reactor Regulation, Director. 78/10/13. 3pp. 9442:234.
- Q. Inspection reports, IE Bulletins & correspondence
- 78:1090037 Forwards IE Inspec Rept#50-002 on 780905-08 & w/p Notice of Violation,
 DAVIS.A.S. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch, 78/10/03, 2pp. 02732:317.
- --7811090040 IE Inspec Rept#50~002/78-03 on 780905~08 during which i item of noncompliance was noted inadequate documentation of surveillance requirements.

 OREOER, L. R., FIBHER, W. L. Region 3. Chicago, Fuel Facility & Materials Safety Branch. 78/09/28. 9pp. 02732:319.
- --7811090041 Notice of Violation from inspec on 780906-08.

 Region 3: Chicago, Fuel Facility & Materials Bafety Brench.
 78/09/28. ip. 02732:328.

- 7811080135 Responds to 781003 NRC ltr re-noncompliance noted in inspe on 780906-08. Corrective actions calibr of gamma spectrometry equip & preparation of health physics procedure req quarterly calibr of gamma spectrometry equip by 781201. KERR, W. Michigan, Univ. of. 78/10/24. 1p. 94398:007.
- 7811200052 Ack receipt of 781024 itr informing NRC of steps taken to correct violations noted during inspec. DAVIS.A B. Region 3. Chicago. Fuel Facility & Materials Safety Branch. 78/11/08. 1p. 94215:344.

DOCKET 50-3 INDIAN POINT STATION, UNIT 1

- F. Becurity, medical, emergency & fire protection plans
- 781120018: Forwards revs to Mod Amend Security Plan of subj facil & requests withholding from public disclosure IAW Section 2.790(d). GARKLLW.J. Consolidated Edison Co. of New York. 78/11/09. [p. 94292-997]

Q. Adjudicatory correspondence

- 7811090188 Forwards recent NRC memos re problems w/pige support base plate design Staff will inform 8d of conclusions after study of add info from licenses (See AND: 7811020332, 7811020338, & 7811020343.)
 SMITH B. H. Office of the Executive Legal Director. 78/10/24, 2pp 94031-028
- J. Insurance & indemnity information
- 7811220076 Porwards Endorsements#98 to ANI Policy#NF-100 k #86 to MAEI Policy#NF-29. which reflect return premium due to subjfccil shutdown Prom 780214-0522. CAHLL-H J. Consolidated Edison Co. of New York. 78/11/15. 1p. 94071:276.
- +-7811220078 Endorsement#98 to ANI PolicyWNF-100.

 Nuclear Energy Liability Insurance Association. 78/08/30. 19 94071:277.
- --7811220081 Endorsement#86 to MAELU Policy#MF-29.

 * Nuclear Energy Liability Insurance Association. 78/09/05. Lp. 94071:278.
- P. Operating license stage documents & correspondence
- 7812050004 Porwards Licenses Performance Eval Questions for subj fact in response to 771123 request Feels it is possible that dev of statistical methodology for such eval may not justify the effort. Quelitative eval may be as good. Urges 1-year test. ORIEN.8 H. Region I. Philadelphia. Office of the Director. 77/12/13. 12pp. 94200:114.
- ---78:2050013 Requests views of Regional Directors on Licensee performed of sub; facils. Forwards questions to be answered by 77:209.
 THORNBURG, H. Division of Reactor Construction Inspection, 77/11/23. Rpp. 94200;126.
- 7810240108 Forwards data specified in Section 401 Certification for Sept Includes species code list, grass elec output, circulating water temp, river water discharge, chem discharges & daily fish counts. MONTI, M. A. Consolidated Edison Co. of New York, 78/10/13, 17pp.

- 7811070120 Informs NRC IAW Yerh Spet that Strawtown Dairy has ceased open & therefore milk sample is unobtainable Samples of leafy green vegetables & milk from Shenandoah Farm will be taken.

 CAMILL.W J Consolidated Edison Co of New York 78/10/30. 2pp. 74038:290
- 7811170160 Forwards data specified in Section 401 Certification for the conth of October,1978 MONTI W A Consolidated Edison Co of New York 78/11/10 16pp. 74048;031
- 7812150088 Notice of workshops to implementation of training & qual requirements contained in Append B of 10CFR73 Requests pre-workshop registration of attendees to facilitate sending out Matl Wrenci Registration Form & List of Locations. MILLER_JR Assistant Director for Bite & Safeguards (Pre 791030). 78/11/15 5pp 94211.343
- 7812190016 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PHR's(NUREG-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Per Plants" (NUREG-0133) ORINES-8 K. Assistant Director for Engineers & Projects (Pre 790625), 78/11/15 6pp 94214:286.
- 7812070153 Notice of seminar on 781209 on new Model Radiological Effluent Tach Space for nuc pur plants Raquesta advance submission of seminar spacific questions Myencl Saminar info Sheet. Proposed Agenda & maps GRIER, B. H. Region 1, Philadelphia. Office of the Director. 78/11/21. 8pp. 94373 192
- 7812150026 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Myencl ANGW 7812080207 SCHMENCER. A. Operating Reactors Branch I (Pre 790525) 78/11/28. 5pp. 94210-001
- 7812150321 Responds to 78112) memo requesting mod to Environ Tech Specs to req continuous monitoring & recording of effluents from detargent Waste Collector tanks Memo has been forwarded to DSE.
 EISENHUT.D.O Assistant Director for Systems Engineering (Pre 791030). 78/12/04 ip 94022:014
- 78120701B0 Forwards application for amend to OLs ZARAMAS.P Consolidated Edison Co of New York 78/12/05. ip. 94375:030
- --7812070182 Application for amend to OLs.Certificate of Bvc encl CAHILL, W.J. Consolidated Edyson Co. of New York 78/12/05 12pp. 94375 031.
- 7812280126 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or snforcement action will result. DAVIS. J. 0. Office of Inspection & Enforcement. Office of the Director 78/12/00 2pp 94310.262.
- 7812030013 Requests views of Regional Directors on Licensee performance eval of subj facils. Forwards questions to be answered by 771207.
 THORNBURG, H. Division of Reactor Construction Inspection. 77/11/23.
 289
- 7812190174 Forwards copies of "Appl for Amend to Oper Lic" which request amends to section 4 1 2a of Environ Tech Spec Requirements for subj facils. Amends would restructure present Aquatic Environ Monitoring Prog. Cert of Svc encl. CAHILL.M. J. Consolidated Edison Co. of New York. 78/12/14. 3pp. 94340:002.
- --7812190180 Appl for amend to Licensee DPR-3, DPR-26 & DPR-64 requesting rev to Environ Tech Baccs Rev Tech Specs & praposed mode are designed to provide a monitoring grog for continuous assessment of Hudson River fish population. CAHILL-H. J., EARLY-P. J. Consolidated Edison Co. of New York. 78/12/14. 46pp. 94340:005
- G. Inspection reports, IE Bulletins & correspondence
- 7810160246 Forwards IE Bulletin#78-12: "Atypical Weld Material in Reactor Prossure Vessel Welds" requesting action w/n 60 days is ist of IE Bulletin Issued in 1978 (See AND # 7810040283)

 ORIER, B. H. Region 1, Philadelphia, Office of the Director. 78/09/29. App. 94003:308

- 7811040201 Forwards 1E Circular#78-17 (See AND 7810230221 Doctat #50-133, 781013)
 0R1ER.6 H Region i, Philadelphia, Office of the Director.
 78/10/13 1p 94489 200
- 7811050224 Ack receipt of 780B18 ltr informing NRC of steps taken to correct violations noted during inspec#50-003/78-06 & #50-247/78-19 ORIER.8 H Region i. Philadelphia. Office of the Director. 78/10/20 2pp 94488.141
- --7811060238 Responds to 780712 NRC ltr re Violations noted in Inspec Repts#50-003/78-06 & #50-247778-19. Corrective actions. Quality Assurance checklists mode environ audit procedures & related environ procedures revised ZARAKAS.P Consolidated Edison Co of New York 78/08/18. 4pp 94488.143
- --7811060239 Forwards IE Inspec Repts#30-003/78-06 & #50-247/78-16 on 780516-18 & 780522-23 & Notice of Violation.
 GRIER.B.H. Region 1. Philadelphia. Office of the Director 78/07/12. 3pp. 94488-147
- ~~7811060244 Notice of Violation from inspec on 780516-18 & 780522-23 BTOHR, J. P. Region 1, Philadelphia, Defice of the Director, 78/07/12 3pp 94488:150
- --78i1060247 iE Inspec Repts#50-003/78-06 & #50-247/78-19 on 780516-18 during which 5 items of noncompliance were nated failure to monitor cooling water sys temp & approve procedural changes in accord w/EBTR/failure to submit timely measurement repts BCRES.R. J. Region 1. Philadelphia. Office of the Director 78/07/07. 24pp. 74488 153
- 7812010345 Forwards licensee performance evaluation for Region 1 No operating reactor in Region 1 is considered to have either abnormal or unusual safety concern. ORIER.B H. Region i. Philadelphia. Office of the Director 78/11/01. 4pp. 94418:254.
- 7811140252 Ack receipt of 781018 ltr informing NRC of steps taken to correct violations noted during inspec#30-003/78-11 & #50-247/78-29.

 SMITH O H. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. 78/11/03. 1p 94400.106
- --7811140255 Responds to 780926 NRC ltr re violation noted in Inspec Repts#50-003/78-11 & #50-247/78-29. Corrective actions. malfunctioning pen linkage mechanism in recorder of monitor CT-1014 repeired & monitor flushed CAHLL, M. J. Consolidated Edison Co. of New York 78/10/18 2pp
- --7811140256 Forwards IE Inspec Repts#50-003/78-11 & #50-247/78-29 on 780905-00 & Notice of Violation. CROCKER.H.W. Region I. Philadelphia, Fuel Facility & Materials Safety Branch. 78/09/26 2pp. 94400 109
- --7811140259 Notice of Violation from Thepec on 780905-08 CROCKER-H.W. Region 1. Philadelphia. Defice of the Director. 78/09/26. 1p. 94400:111.
- --7811140262 IE Inspec Repts#50-D03/78-11 & #50-247/78-29 on 780905-08 during which 1 item of noncompliance was noted: failure to continuously monitor & record liquid effluent discharges. THONUS.L. Region 1. Philadelphia. Diffice of the Director 78/09/26. 6pp. 94400-112.
- 7812180037 Forwards IE Inspec Repts#50-003/78-12 & 50-247/78-33 on 781011-12 during which no items of nancompliance were noted. SMITH-0. H. Region 1, Philadelphia, Fuel Facility & Materials Safety Branch. 78/11/03. 2pp. 94133:092.
- --7812180058 IE Inagec Rapts#50-003/78-12 & #50-247/78-33 on 781011-12 during which no items of noncompliance were noted Major areas inapected incl-observation of licenses conducted emergency drill & circulating cooling water temp monitor. BREES.R.J.. STOHR.J.P. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch. 78/11/02. App. 94133-094
- 7811290214 Forwards IE Circular #78-18. "UL Fire Test. "W/encl AND: 7811150002. GRIER.B.H. Region i, Philadelphia, Défice of the Director. 78/11/06 1p. 94237.327.
- 7812150133 Forwards IE Bulletin#78-12A, suppl to IE Bulletin#78-12. W/encl ANO.7811300055. ORIER.8.H. Region I. Philadelphia, Office of the Director. 78/11/24. 1p. 94212:174.

ept 1978 including breakdown & total weight AHILL.W J. Consolidated Edison Co. of New York 78/10/13 Spp. 4412:171

(210340 Forwards Monthly Open Rept for Oct 1978 AMILLAW J. Consolidated Edison Co. of New York 78/11/15. 1p 4484:328

811210344 Monthly Oper Rept for Oct 1978 MANULA,L., MAKEPEACE,J. Consolidated Edison Co. of New York. 78/11/08. 9pp 94484 229

2010206 Forwards corrected copy of Chem Discharges sheet in Section iO1 Cert Rept for Oct 1978. IONTI, W. A. Consolidated Edison Co. of New York. 78/11/15. 2pp. 14409 265

.1220153 Forwards tabulation of daily record of fish collections for lct 1978 w/deily species breakdown & total weight. AHILLIH J. Consolidated Edison Co. of New York 78/11/16. 4pp. 74074:277

12180:52 Forwards data specified in Section 401 Certification for Commonwealth Edison Co. 78/12/10. 17pp. 94366:056

12270188 Forwards rept of fish impingement & corrective action for Nov 1978 CAHILLIN J. Consolidated Edison Co. of New York. 78/12/14. Spp. 94018: 037

12210207 Forwards Monthly Open Rept for Nov 1978, CAHILLIN, J. Consolidated Edison Co. of New York 78/12/15. 1p. 94279, 103,

7812210Q11 Monthly Open Rept for Nov 1978 KANULAL Consolidated Edison Co. of New York. 78/12/05. 7pp. 94279 104.

CHET 50-6 BATTELLE MEMORIAL INST. REBEARCH REACTOR Inspection reports. IE Bulleting & correspondence

iii170316 Forwards 1E Inaper Repts 0-0008/78-04.#30-05728/78-03 & #50-006/78-01 on 780911-15 during which no items of noncompliance were noted. DAVIB.A B. Region 3. Chicago, Fuel Facility & Materials Bafety Branch. 78/10/10. 2pp. 02763:322.

-7811170319 IE Inspec Repts 70-0008/78-04,30-05728/78-03 & 50-006/78-01 on 7B0911-15 during which no items of noncompliance were noted. Areas inspecinediat protec progradioactive waste mgt. tech spec requirements for retired res reactor.

HiLLER, D. E. Region 3, Chicago, Fuel Facility & Materials Bafety
Branch, 78/10/10, 7pp. 02763:324.

JCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT I Adjudicatory correspondence

812270230 Proposed stipulation re NRDC & CBE's representation of unnared members in Dresden-Guad Cities transshipment is not acceptable to NRC NRC position on NRDC's petition to intervene remains as stated in 781103 pleading GODDARD, R. J. Office of the Executive Legal Director. 78/12/06. 1p. 94017.138.

. Deneral correspondence

810310024 Informs that for SEP normal channel of oral communication will be followed, but to espedite reviews direct oral communication between subj facil staff & members of SEP branch is encouraged. Z I EMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/10. 2pp. 94094: 345

1. Insurance & indemnity information

'812180210 Forwards copies of insurance policies #NELIA.NF-43 & MAELU. OBTER, J. Commonwealth Edison Co. 78/12/12. 2pp. 94365:062.

- 7812190109 Requests refund of 86 per mut in excess indemity fee paid for Lic#DPR-2, #DPR-19, #DPR-25, #DPR-29, #DPR-30, #DPR-39, #DPR-4B
 - PODLE, R.D. Commonwealth Edison Co. 78/12/13 1p. 94376.323
- P. Operating license stage documents & correspondence
- 7812080026 FDIA request for all records incl.quantity of radioactive matl disposed of from former Manhantten proj in IL known as Chicago Pileawi 2 & 3. Matl disposed of in IL by Lindsay Cos et Morris facil & Dresden facil MANBELL, D. 11linois, State of 78/11/06 2pp
- 7812050013 Requests views of Regional Directors on Licensee performanc eval of subj facils Forwards questions to be answered by 771209 THORNBURG, H. Division of Reactor Construction Inspection. 77/11/23. 94200 126 500
- 78:11:30059 Forwards initial eval of 8 complete SEP topics & response to request for clarification of SEP documentation procedures made at 780531 meeting. Requests response re facts used to define plants by NRC staff. EleBNUT.D 9 Assistant Director for Systems Engineering (Fre 791000). 78/08/17 2pp 94010-225.

- --7Biii30337 NRC response to the SEP owners group suggestions for documentation procedures for the NRC Systematic Evaluation Prog Forwards conclusions re individual areas of concern at nuc power plants * Assistant Director for Systems Engineering (Pre 791030) 78/08/17. 23pp. 94010:293
- 7810190149 Reports on use of Type B ATCOR caskWBC-48-220 STEPHENSON, B. B. Commonwealth Edison Co 78/10/03. 1p 94414:058.
- 7811080275 Notification of 781023-24 site visit to observe, discuss & identify site specific salamic design features & info.
 Aganda-list of pertinent info required for review by senior seismic review team & description of SEP review encl
 ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625) 78/10/11 8pp.
- 7810200084 Analytic work re-tasting of core spray distribution at facility in progress Work must be finished before conclusions can be drawn from test program Rept will be submitted by mid-Dec 1978 TURBAN,M.S. Commonwealth Edison Co. 78/10/13. ip. 94367:094.
- 7810240158 Forwards evaluation of surveillance requirements on BWR recirculation pumps & discharge valves in operation w/less than all loops in sec. BHR jet sump operating indications & supper plenum injection w/DBEs affectd in LOCA
 TURBAK.M.B. Commonwealth Edison Co. 78/10/18. 19pp
- 7811100105 Forwards copy of NUREG-0485, "Status Summary Rept-Systematic Eval Prog. ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625) 7B/10/19.
- ---7811100109 "Btatus Bummary Rept. Systematic Evaluation Program "
 Office of Management and Program Analysis. NUREO-0485 V01 78/09/22. 205pp.
- 78:0260153 Requests 45-day extension to allow time to provide add inf re accuracy of environ qualification of sefety-related electrical equipment.

 TURBAKIN S. Commonwealth Edison Co. 78/10/23 Ip Commonwealth Edison Co. 78/10/23 Ip 94055: 338.
- 7811020322 Withdraus request to amend Tech Specs re reporting requirements for reactivity enomelies as Reg Guide "Interpretation" by NRC on 780701 does not require rept for reactivity increase of less than 5 secs. REED C. Commonwealth Edison Co. 78/10/26 2pp. 94255: 223
- 7811030161 Forwards proposed Amend changing Tech Specs w/regard to updating station organizational charts. Changes have received onsite & offsite approval. REED.C. Commanwealth Edison Co. 78/10/26. 9pp. 02724:009.

- 7811140014 Requests add) into on FSF suitchover from injection to Fedirculation mode, (solation of reactor protecting from nonsafety sys. SSF sus logic tidesign to specific drawings of elective. A complete plant electorating indices ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790525) 78/10/26 3pp. 74425-340
- 78iii40002 Natifies applicant of 78ii28 NRC-sponsered seminer re Model Radiological Effluent Tech Specs for Nuc Pur Plants w/encl Seminer Info Sheetito be completed b returned by 78iii7) b Progosed Agenda. KEPPLER.J. G. Region 3. Chicago. Office of the Director 78/11/07. App. 94426:022
- 7811270071 Forwards Amend#27 to Facil Oper LickDPR-2 & associated Safety Eval & Notice of Issuance 21EMANN.D.L. Operating Reactors Branch 2 (Pre 790625) 78/11/09 2pp. 94246-303.
- --7811270073 Amend#27 to Facil Lic#DPR-2.permitting open of subjfacil for low pur physics test. ZIEMAN, D.L. Operating Reactors Branch 2 (Pre 790625) 78/11/09. 4pp 94246:305
- --7811270078 Safety Eval Supporting Atend#27 to Facil Oper Lic#DPR-2.
 Concludes there is no increased risk from its
 implementation

 1 Office of Nuclear Reactor Regulation, Director. 78/11/09 4pp.
 94246-309
- --7811270081 Notice of Issuance of Amend #27 to Facil Oper LicMDPR-2 permitting oper of subj facil for low pur physics test ZIEMANN, D.L. Operating Reactors Brench 2 (Pre 790628). 78/11/09. 28p. 94246:313.
- 78:1280430 Forwards draft Bys Evel Prog Safety Inputs re Tapic VIII-3 A. Station Bettery Text Req Requests they be transmitted to licensees. DAVIB. D.K. Systematic Evaluation Programs Branch (Pre 790425). 78/11/14. 23pp. 94381:119.
- 78:2150071 Notification of workshops in Jan-Hay 1979 in Regions 1-5 to explain techniques of job analysis & performance testing & how to relate such testing to qualification plan development & training. Designed for working level personnel HILLER.J.R. Assistant Director for Site & Safeguerds (Pre 791030). 78/11/15. Spp. 94210: 215
- 78:2180248 Forwards RevW1 "Oreft Radiological Effluent Tech Specs" for BMR's(NVREQ-0423) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NVREQ-0133).

 ORINES:8. K. Assistant Director for Engineers & Projects (Pre 790425). 78/11/15. 69p 94366:125
- 78:2050107 Forwards rev page to Topical Rept CE-1-A: "Qual Assurance Prog. Rev 6." Rev reflects Reg Quidel. 28 & 1 33 rev. TURBAK-M. 6 Communumenth Edison Co. 78/11/17 2pp. 94335;354.
- 7811280213 Forwards current lic status list for subj facils. REED.C. Commonwealth Edison Co. 78/11/20. 9pp. 94012:130.
- 7812040194 Rept on 780927 visit to facil for familiarization & addlinfo. Industrial & transp facils & control room area were observed. FBAR subjects were discussed W/list of participants.
 FONTECILLA.H M. Bystematic Evaluation Programs Branch (Pre 790625).
 78/11/20. opp. 94497:122.
- 7812060303 Notification of 781207 meeting w/8EP Owner's Group in Bethesda. MD to discuss plans to address seismic input for use in BEP seismic review.
 LEVIN.H.A. Systematic Evaluation Programs Branch (Pre 790625), 78/11/24. 2pp.
- 7812080114 Proposes Tech Spec change re min reactor vessel head stud tansioning temp. changing it from 130 F to 70 F Change is req because 130 F temp is difficult to maintain when solvent is in primary sye. Wistress fracture analysis.

 REED. C. Commonwealth Edison Co. 78/12/01. 6pp. 94104:354.
- 78:2110055 Forwards safety evaluation re need for feedwater pump trip on reactor high water level. Trip determined unnecessary to ensure eafe operation of facility.
 71EPANN.D. L. Operating Reactors Branch 2 (Pre 790625), 78/12/01.
 4pp. 94408:262.
- 78:2120:35 Forwards revised lists w/environ qualification of safety-related electrical equipment in response to NRC 780906 ltr. Includes 8EP by equipment type, 8EP submittel ref. location. time required 5 type of anylron.
 TURBAN, M.S. Commonwealth Edison Co. 78/12/01. 31pg. 94276:297.

- 7812280129 Emphasizes importance of submitting accurate & complete NRC by licensees & applicants Info submitted must be substantiated by date & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB. J Q Office of inspection & Enforcement. Office of the Director 78/12/06. 2pp. 94311:336
- 78(214034) Requests eval of systems designed to accompdate effer pipe breaks inside containment at subj facil in order for NRC to complete BEP review. ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625). 78/1 3pp 03557
- 7812150097 Requests add1 info from SEP licensess re elec penetr of reactor containments in order to complete eval IlEMANN.D L Operating Reactors Branch 2 (Pre 790625) 78/1 4pp 94212 032
- 7812210078 Forwards NUREQ-0485,Vol 1.Number 2, "Status Summary 95P," N/o enc! TIEMANN.D.L. Operating Reactors Granch 1 (Pre 790625) 78/1 2pp. 94269-360.
- 7812190097 Accepts topical reptWCE-1-A RevW6. "Comm Edison Co Qu Assumance Prog for Nuc Generating Stations." Requests submittel of 36 copies. HAABS.W.P Quality Assurance Branch. 78/12/13 1p. 94376:
- HAASS.W.P. Quality Assurance Branch. 78/12/13 1p. 94376
- 7812270375 Responds to 781120 request for temporary waiver of R Prog for Lic Operators & Banior Operators(Limited), Bection 3. paragraph B Requests proposed determination of amend class, state the basis & submit fee of \$1200. D1005 R.M License Fee Management Branch. 78/12/19. ip. 94227:264.
- 7812270327 Describes and plane to lines to make them comply w/A local leak rate test requirement Mpd will be completed during chamical cleaning.
 TURBAK.M.S. Commonwealth Edison Co. 78/12/20. 3pp. 94232.
- G. Inspection reports, IE Bulletins & correspondence
- 7810110052 Forwards IE | Insp. Repts 50-010/78-23,50-237/78-21 & 5 78-23 on 780807-10 & 16-18 & notice of deviation. DAVIS, A. 8. Region 3, Chicago, Office of the Director. 78/05 2pp. 74080:049.
- --7810110034 Natice of Deviation from inspec on 780807-10 & 780 * Region 3, Chicago, Fuel Facility & Materials Barety Bran 78/09/08. ip. 94063:226
- --7810110062 IE Inspec Repts#50-010/78-23.#50-237/78-21 & #50-2 on 780807-10 & 16-18 during which I item of deviation was noted failure to meet F6AR commitment for monitoring unit 2/3 liquid rad waste effluents. ORGER.L.R., F18HER.W.L. Region 3, Chicago Office of the Director. 78/09/06 lipp. 94063:227.
- 78:1010018 Forwards IE Inspec Repts#50-10/78-25.#50-237/78-22 & 78-24 on 780705-06.11-12.19-20.780817.23-25.29-31 & 780901. during which no Items of noncompliance were noted. FIGRELI-G. Region 3. Chicago. Reactor Operations Nuclear Su Branch. 78/09/20. 2pp. 94290-141.
- --781010022 IE Inspec Repts#50-10/78-25, #50-237/78-22 & #50-24 780705-06, 11-12, 19-20, 780817, 23-25, 29-31, 780901, during which no items of noncompliance were noted Major areas inspect followup of noncompliances & review of plant open.

 BANKER, J. L. Region 3, Chicago, Office of the Director. Magion 3, Chicago, Reactor Openations Nuclear Support Brance 78/09/20, 7pp.
- --7811010022 IE Inspec Rept#30-10/78-25, #50-237/78-22 & #50-245 780703-06, ii-12, i9-20, 780817, 23-25, 29-31, 780901, during which no items of noncompliance were noted Major areas inspect followup of noncompliances & review of plent oper. BARKER, J. L. Region 3, Chicago, Reactor Operations Nucleer Branch. 78/09/20. 7pp.
- 7810110277 Responds to 780908 NRC 1tr re deviation noted in Int Repts 50-010/78-23, 50-237/78-21, 50-249/78-23. Corrective actions: liquid radwaste discharge monitor will be returned to svc & alarm will be made operable. REED, C. Commonwealth Edison Co. 78/09/22. 3pp. 94079:148.
- 78i1010009 Response to 780921 NRC 1tr re deviation noted in IE Rept#50-10/78-27. Corrective actions: lubricating oil pressure readings were w/in ranges resommended by vendor. Procedures will be revised by 781006.
 REED.C. Commonwealth Edison Co. 78/10/06, 2pp. 94290:244.

- 1p 94290 248
- --7811010029 IE Inspec Rept#50-10/78-27 on 780816-17 during which 1 item of noncompliance was noted/failure to adhere to approved procedures while testing record of temporary diesal generator, acceptable criteria values had not been met. SMITH. J. D. Region J. Chicago. Office of the Director NEVES.L. A., STREETER, J.F. Region J. Chicago. Reactor Degrations Nuclear Support Branch 78/09/19 4pp 94290-249.
- 7810200203 Ack receipt of 780922 Itr informing NRC of steps taken to correct item of noncompliance identified in 1tr of 700900 DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Gafety Branch. 78/10/12. 1p. 94367:089
- 7810300030 Forwards 1E Circular#78-17 (See ANO 7810230221)
 KEPPLER, J G. Region 3. Chicago, Office of the Director 78/10/13
- 7810310093 Forwards review of weld portion of inservice than program. New tables show total number of welds or components requiring insployer plant lifetime for each code catagory TURBAKIM B. Commonwealth Edison Co. 78710719 120pp 94091.170.
- 7811300261 Forwards IE Inspec Repte#50-010/78-26.50-231/78-23 & 50-249/78-23 on 780905-08.12-14.20-22. & 26-28 & Notice of Violetian FioRELLI.0. Region 3. Chicago, Reactor Operations Nuclear Support Statts. 78/10/25. 2pp. 94075.233.
- --7811300264 Notice of Violation from inspec on 780905-00.12-14.30-22 & 26-28.

 Region 3, Chicago, Reactor Operations Nuclear Support Branch 78/10/25. ip. 94075:061.
- --781130026B IE Inspec Repts#30-010/7B-26.50-237/78-23 t 50-249/786-25 un 780905-08.12-14.20-22 t 26-28 during which I item of noncompliance was noted: failure to rept 4 30 day reportable event in 30 days.

 BAKKER, J. L., CHRISBOTIMOB.N., HUGHES, J. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/25. 15pp. 94075.237
- 7811020335 Ack receipt of 781006 ltr informing NRC of steps taken to correct violations noted during inspecs80-010. FIDRELLI G. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78710726. pp. 94241016.
- 7812050011 Forwards IE Inspec Repts#50-010/78-29.50-337.-254,-275.-304/78-25.50-249/78-27 t 50-265/78-26 on 781002 during which no items of honcompliance were noted.

 KEPPLER.J. Q. Region 3. Chicago. Defice of the Director. 78/10/30.
 2pp. 74200:183.
- --7812050027 IE Inspec Repts for subj facils on 701002 during which no items of noncompliance were noted. Major areas inspected inclidiscussion of actions being taken by util to improve its reg performance & tour of Zion station.

 MODER. C., FIDRELLI.O. Region 3, Chicago, Reactor Operations Nuclear Support Branch KEPPLER. J. Q. Region 3, Chicago, Défice of the Director. 78/10/30. 3pp. 94200:185
- 7811150063 Forwards IE Circular 78-18, "Underwriters Lab Fire Test" KEPPLER, J. G. Region 3, Chicago, Office of the Director. 78/11/06 jp. 74112:240.
- 7811280486 Unresolved items noted in IE Inspec Repts#50-010/77-20. #50-237/77-25 & #50-249/77-25 have been reviewed & recommendations made.Documentation of unresolved items withold per 10CFR2.790(4). HIND. J. A. Region 3. Chicago, Bafeguerds Branch. 78/11/16. 1p. 94381.358.
- 7812030287 Forwards IE Bullstin 78-12A, "Atupical Weld Mat) in Reactor Pressure Vessel Welds."
 KEPPLER.J. G. Region 3. Chicago, Defice of the Director 78/11/24.
- 78121400B1 Forwards IE Inspec Repts#80-010/78-2B.#50-237/78-24 & #50-249/78-26 on 781010-13,781016-19 & Notice of Violation. KEPPLER, J. C. Region 3. Chicago, Diffice of the Director 78/12/01. 2pp. 9412B: 227.

- 7812290026 Forwards IE Bulletin 70-14. "Deterioration of Buna-N Components in ABCO Bolenoids." KEPPLER, J. O. Region D. Chicago, Office of the Director 70/12/19 1p. 94208 009
- R Puriodic operating reports & related correspondence
- 7810100078 Manthly Progress Rept required for scheduled ECCS, 1266-279 & fire protec mode TURBAKINS Commonwealth Edison Co. 78/10/04 Dpp 94032:206
- 7810180101 Forwards monthly operating rept for 8ept 1978 STEPHENSON, 8 8 Commonwealth Edison Co. 78/10/12 ip 943166 208
- --7810180104 Monthly operating rept for Bept 1978 PHELANJ F. Communication Edison Co. 78/10/10 63pp 945166 209
- 7811140099 Monthly rept for Oct 1970 on progress re completion of scho ECC8.1666-179 & fire protec mods All work is still underway. TURBAKIN 8 Commonwealth Edison Co. 70/11/00 2pp. 94489, 108
- 7011140119 Forwards monthly operating rept for Oct 1970 SYEPHENSON. 0 8 Commonwealth Edison Co. 70/11/00 ip 94485 104
- --7011140169 Monthly operating cept for Oct 1970. PHELANJ F. Cormonwealth Edison Co. 70/11/00 5pp. 94425-185.
- 7812130184 Forwards monthly operating rept for Nov 1978 BYEPHENSON, B.B. Commonwealth Editor Co. 70/12/08 ip 94306-001
- --7012130106 Monthly Oper Rept for Nov 1970 PIECAN J F Commonwealth Ediann Co 78/13/00 App 94306 002
- 9. Reportable occurrences. LERs & related correspondence
- --7810170216 LER 78-030/03L-0 on 780914, while performing DDB 1600-1, amergency condenser nutlet valve M0101 failed to close remotely from control room. Caused by valve aperator needing lubrication Valve sercised & closed manually MDIR. T. Commonwealth Edison Co. 78/10/03 ip 94236-362.
- 7810240148 Forwards LER 78-029/03L-0 STEPHENSON.8 B Commonwealth Edison Co 28/10/12 to
- --7810240150 LER 78-029/03L-0: on 780914, leak found in recirculation 16 (4446-3" GI-R) at weld approx 1 ft above collector tank where pipe reduces from 3 to 2 inches, causing continuous bunding of redweste bldg morth sump pump Caused by erosion.
 TRAXLER, D.V. Commonwealth Edison Co. 78710712 ip
- 7811090113 Forwards LER 78-031703L-0 8TEMHENBON.8 8 Commonwealth Edison Co 78/10/30 ip 94042 293.
- --7811090124 LER 78-031/031-0.on 781007, insplof turbine pipeway locate two leaks in Electron bypass line (2705-4"-FB). Caused by pipe erosion. One hole repaired w/welded patch & other w/clamp-on patch. Line scheduled to be replaced during outing of TRAXLER, D. V. Commonwealth Edison Co. 78/10/27 1p. 94042-294.
- 7811210388 Forwards LER 78-032/017-0. BTEPHENSON.B.B. Commonwealth Edison Co 78/11/13 ip 94406 200
- --7811210392 LER 78-032/017-0 on 781031, following spurious reactor screening normal shutdown.cooldown rate discovered to be 35 F greater than Tech Specs limits. Caused by failure of operator to isolate 8.AG in time to prevent cooldown.

 ALLEN.R Commonwealth Edison Co 78/11/13 2pp 94486-281
- 7812180174 Forwards LER 78-034/03L-0 8TEPHENSON, B. B. Commonwealth Edison Co. 78/18/09, 2pp. 94059.050
- --7812180127 LER 78-034/03L-0:on 781201; channeled fuel assembly dropps from grapple while being transferred to spent fuel pool Caused by assembly not being properly letched to grapple FARRAN.D. Commonwealth Edison Co. 70/12/01 3pp 74359:352

- V. Operator Examinations
- 7811270138 Requests temporary waiver from Section I[I.Paragraph B. af "Requelification Program For Licensed Operators Sentor Operators & Sentor Operators (Limited)." Current program of lectures exams & mod training to continue during shutdown. TURBAK-M.B. Commonwealth Edieon Co. 78/11/20. 2pp. 94253:393.

١

DOGREY 50-13 BABCOCK & WILCOX CD. CRITICAL FACILITY
J. Insurance & indemnity inforestion

- 7809130309 Signed Amend#18 to Indemnity Agreement#8-8. adding new Article VIII re: payment of ascessed deferred premiums for subj facile.

 84LIZHAN.J. Antitrust & Indemnity Group. 78/09/01. 2pp.
- P. Operating license stage documents & correspondence
- 7811000166 Forwards corrected copy of 781016 ltr to recipient, which should have referenced Doctet#50-19 in addition to #50-99. REID.R.H. Operating Reactors Brench 4 (Prs 790628). 78/10/24. 1p. 02724:025.
- 7812180060 Forwards Amend#10 to Oper LicMCX-10 & Sefety Eval rept in response to 780626 request. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/29. 1p. 74133:102.
- --7812180064 SePety Evel Rept in support of Amend #10 to Oper Lic MCX-10. REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/11/29. 2pp. 94133:106.
- G. Inspection reports. IE Bulletins & correspondence
- 7810270103 Forwards IE Inspec Repts#50-99/77-4 & #50-13/77-4 on 771129-771201 during which no items of noncompliance were noted. KENNA-H.B. Region 2. Atlanta. Safeguards Branch. 77/12/27. 2pp. 94059:287.
- --7810270i13 IE Inspec Repts#50-13/77-4 & #50-99/77-4 on 771129-77120i during which no items of moncompliance were noted. Hajor erees inspected included; physical security prog. Becurity plan. Becurity organization, Burvsillance. Access controls. JCYNER, J. H. Replan 2. Atlanta, Office of the Director. 77/12/22. ip. 94059; 288.
- 7812030001 Forwards IE Inspec Repts#30-99/78-2,#30-13/78-2 & #70-824/78-10 on 780911-15 & Notice of Violation.

 8UTHERLAND.J.T. Region 2, Atlanta: Fuel Facility & Materials Safety Branch. 78/10/27. 2pp. 94200:001.
- --7812050002 Notice of Violation from inep on 780911-15.

 * Region 2, Atlanta: Fuel Facility & Materials Safety Branch. 78/10/27. 1p. 94200:003.
- ---TB12050Q05 IE Inspec Repts #50-99/78-2,#50-13/78-2 & #70-824/78-10 on 780911-15 during which J liem of noncompliance was noted: storage of flammable liquids in containers that are not safety approved cans.
 PERROTTI.D. J. Region 2. Atlanta. Office of the Director. 78/10/27. 17pp. 94200:004.
- 78:2080215 Forwards Inspec Rept#50-099/78-03 & Inspec Rept#50-013/78-03 on 780918-22 during which no items of noncompliance wers noted.

 8UTHERLAND, J. T. Region 2: Atlanta, Fuel Pacility & Materials Safety Branch. 78/10/30. 2pp. 94137:074.
- --7812080219 IE Inspec Rept#50-099/78-03 & IE Inspec Rept #30-013/78-03 on 780918-22 during which no items of soncompliance were nated. Major eress inspec inclinated protec procedures & posting & labeling. DAVIB.J.H. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 78/10/30. 7pp.
- 7812200136 Concurs that inspec rept contains no proprietary info & agrees to placing it in NRC PDR.
 ENGELDER.T. C. Beboock & Wilcox Cp. 78/12/08. ip. 94136:354.
- ~~7812200158 Forwards Inspec Repts#50-13/78-4 & #50-99/78-4 on 781115-17 during which no items of noncompliancs were noted. LCNG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/12/01. 2pp. 94156:358.

--7812200161 JE Inspec Repts #80-013/78-04 & #80-099/78-04 on 781115-1 during which no items of noncompliance were noted Major areas inspected incl: logs & records: reviews & audits: especiments: refueling: procedures & IE Circular review. HINCKLEY, D. Q., MCHENRY, T. J., DANCE, H. C. Region 2, Atlanta, Office of the Director. 78/12/08. Dpp. 94156:337.

DOCKET 30-16 ENRICO PERMI ATOMIC POHER PLANT, UNIT 1

J. Insurance & indemnity information

- 7810120021 Forwards endorsement#90 to Nuc Energy Liability Insurance Policy NF-92 requested in 780922 NRC ltr. MATERS.B.R. Detroit Edison Co. 78/10/05. 3pp. 94230:170.
- P. Operating license stage documents & correspondence
- 7810310025 Ack ltr & mgt meeting w/ NRC at util on 780823. WHIDDON,D. Detroit Edison Co. 78/10/03. ip. 94094:362.

DOCKET 50-18 VALLECITOS BOILING WATER REACTOR

- O. Advisory Committee on Reactor Bafeguards reports & correspondence
- 7B12060002 Comments on exam of Trenches A.B. & E at facility.Finel eval must be based on evidence indicating whether thrusts near reactor are due to lendsliding as tectonic processes & whether there are other faults comme
- P. Operating license stage documents & correspondence
- 78:1080345 Supports a permanent shutdown of the Vallecitos plant in G because of tritium sespage into underground water. PLANCK-C. Affiliation Unknown. 78/19/18. Ip. 94406:317.
- 7811130177 Forwards preliminary trenth logs for facil site.
 DARMITZEL, R. W. General Electric Co. 78/11/02. 73pp. 94087: 250.
- 7812260096 Summary of 781205-06 site visit to observe trenches & discuss seismic implications of derived data. JACKBON. R. E., GREEVES J. T. Geosciences Branch. 78/12/13. App. 94349: 330.
- DOCKET 50-20 MASSACHUSETTS INST. OF TECH. RES. REACTOR
 P. Operating license stage documents & correspondence
- 7812140095 Forwards Amend#15 to facil lic#R-37 which identifies currently approved security plan & incorp this plan as a condition of the license. Becurity plan w/held pursuant to 2.790.
 REID.R.U. Operating Reactors Branch 4 (Pre 790685). 78/11/28.
- ~~78)2140098 Amend#J5 to Facil Open Lic#R-37 re incorp of security # into a condition of the lic.
 REID.R.H. Openating Reactors Branch 4 (Pre 790625). 78/11/28.
 2pp. 94126:353.
- 7812080093 Requests that Tech Specs for subj facil be amended by adda definition for the term "Frequency." Lack of such a definition has resulted in varying interpretations of time intervals. Suggested definition preferred. CLARK.L. Massachusetts Institute of Technology. 78/12/04. 2pp. 74108.032.
- G. Inspection reports, IE Sulletine & correspondence
- 7810180178 Forwards IE Inspec Repta#50-020/78-04,70-0089/78-02, 70-0194/78-02,70-0095/78-02 & 70-0938/78-02 on 780809-18 during which no items of noncompliance were noted. MARTIN.W.O. Region 1, Philadelphia, Befeguards Branch. 78/09/Od 2pp. 94317:146.
- --7810180181 IE Inspec Repts#50-020/79-04:70-00899/78-02:70-0194/2/1
 70-0095/78-02 & 70-0938/78-02 on 780809-11 during which no items of nancompliance were noted. Area inspected: nuc mat1 control & accounting prog. inventory & records.
 HQLODY, D. J., 8188ETT, P. M. Region I. Philadelphia, Bafeguards Brench. 78/08/30. 7pp. 94317:148.

- 7811300355 Forwards IE Inspec Rept#05000020/78-05 & Notice of violation. BMIM.O.H. Region i, Philadelphia, Fuel Facility & Materials Bafety Branch 78/10/18. 2pp 94116:303
- --7811300377 Notice of Violation from inspec on 780913-15 • Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch 78/10/18 1p. 94116:305
- --78113003BD lE Inspec Rept#50-020/78-05 on 7B0913-15 during which I item of noncompliance was noted failure to submit a timely notice to NRC & failure to have a copy of a shipping container certificate.

 BERABIAN.J. A., PLUMLEE.K.E., KNAPP.P.J. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. 78/10/05. 11pp 94116-306.
- 7812180078 Forwards IE Inspec Rept#50-020/78-07 on 781004 during which no items of noncompliance were noted.
 CARLEGN, R. T. Region 1. Philadelphia, Reactor Construction & Engineering Bupport Branch. 78/11/03 2pp 94131:342
- --7812180082 IE Inspec Rept#50-020/78-07 on 781004 during which no items of noncompliance were noted. Major areas inspected incl. fabrication & installation of new addl stainless steel heat sithager in reactor coolent water sys.

 SANDERS, W.F., EBNETER, B.D. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 78/10/30. 3pp 94131 344
- 7812060180 Ack receipt of 781107 ltr informing NRC of steps taken to correct violations noted during inspect®00-020/78-06.
 BRUNNER.E. J. Region i. Philadelphia. Reactor Operations Nuclear Bupport Branch 78/11/24. 1p. 94382:105
- --78120601B3 Responds to 781016 NRC Itr re deviations in Inspec Rept 800-020/78-06.MIT will apply for amend of toch specs to define frequency.permitting an extension of time interval between surveillance test & other functions by 23%. CLARK.L. Massachusetts Institute of Technology. 78/11/07. 2pp. 94382.106.
- --7812060194 Forwards IE Inspec Rept #50-020/78-06 & Notice of Violation. BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/16 2pp. 94392:108.
- --7812060203 Notice of violation from inspec on 780927-29.

 Region i, Philadolphia, Diffice of the Director. 78/10/16. ip. 94382-110.
- --7812040219 IE Inspec#30-020/78-06 on 780927-29 during which 1 item of noncompliance was noted Reactor Bafeguards Comm neetings were too infrequent.

 8TETKA.T., GREENMAN.E. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/16. 7pp. 94382:111.

DOCKET 50-22 WESTINGHOUSE TEST REACTOR

- G Inspection reports. IE Bulletins & correspondence
- 7811030146 Forwards Addendum to Annual Inspec Rept For Lic#TR-2 Answers questions or isotopic composition & source of radioactivity in MTR canal water.

 DIPTAZZA: R.P. Wastinghouse Electric Corp. 78/10/31. 3pp. 02723: 261
- DOCKET 50-27 WASHINGTON STATE UNIV. RESEARCH REACTOR

 F. Security, medical, emergency & fire protection plans
- 7811030014 Amend submitted in 780825 ltr is an admin mod of security plan & does not affect Facility security. Finds amend acceptable.
 REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/10/17. 1p. 02720: 282.
- DOCKET 50-29 YANABE-ROME NUCLEAR POWER STATION

 F. Security, medical, emergency & fire protection plans
- 7810200051 Comments on fire protec eval safe shutdown methods &

- 7811020012 Forwards subj facil Fire Protec Review describing sunmary of staff positions, licensee response & status of corrective actions taken to satisfy staff (oncerns LAINABA Plant Systems Branch (Pre 791030) 78/10/24. 38pp. 94351-193
- 7811070300 Notice of 781109 meeting w/util to discuss fire protection program including fire brigade staffing & interim fire protection mode BURGER.A Operating Reactors Branch 2 (Pre 790625) 78/11/01 2pp 07893-093
- 7811130321 Forwards staff positions to avail of subj facil fire protecting on 780925-28 Identifies areas of concern in the prognat adequately addressed by YAE ZIEMANN.O.L. Operating Reactors Branch 2 (Pre 790625) 78/11/01 53pp. 94087 069
- 7812050128 Forwards latest rev of mod amend security plan(MASP) to meet 780609 NRC comments. Encl w/held from put disclosure pursuant to 2 790.

 GROCE, R. Wankee Atomic Electric Co. 78/11/29 ip 94335 049
- 7812030210 Informs NRC of util's positions on outstanding fire protectissues. W/encl 761019 MA Fireflighting Academy ltr to util re-training prog MODDY. D.E. Yankee Atomic Electric Co. 78/12/01 14pp. 94331.216
- 76:2190087 Describes util revirs interim fire brigade site YAE has agreed to an interim fire brigade of 5 trained firefighters on each operating shift & to an hourly fire watch patrol util util also contract for firefighting course MOODY.D E Yankey Atomic Electric Co. 78/12/13 2pp 94343.025

H General correspondence

- 7810310159 Informs that for SER normal channel of oral communication will be followed, but to expedite reviews direct oral communication between subj facil staff & members of SEP branch is encouraged ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625) 78/10/10 Zpp. 94090.216.
- J. Insurance & indomnity information
- 7811240044 Forwards copy of York 280927 itr re endorsements to the ANI & MAELU policies. PARADISO, P.J. Harsh & McLennan.inc., M & M Nuclear Consultants.inc. Div. 78/10/10. 1p. 94459:267.
- --7811240048 Forwards certified copies of a number of endorsements to ANI & MAELU policies. Copies of endorsements are encl along widates they were originally sent to J Belzman YORK.R. N. New England Power Co. 78/09/27. 23pp. 94455: 268
- P. Operating license stage documents & correspondence
- 7811130100 Forwards initial eval of 8 complete SEP topics & response to request for clarification of SEP documentation procedures made at 780331 meeting. Requests response re-facts used to define plants by NRC staff. (See ANO#7811130337)
 E18ENHUT.D. Q. Assistant Director for Systems Engineering (Pre 791030). 78/08/17 2pp 94010:291
- 7810110177 Re meeting of 780905 subj facil. Will undertake evaluation of assymetric LOCA loads. Evaluation will include study of magnitude of loads on reactor vessel supports dev of models. A preparation of seismic assessments.

 VANDENBURGHOR, D. Yankee Atomic Electric Co. 78/10/03 App. 94069-102.
- 7810110163 Forwards add1 info requested 780908 re reduction of incore neutron detector symbols.Tech Specs changes & commitment to construct map from video tape of as-loaded core JOHNSON, W. P. Yenkse Atomic Electric Co. 78/10/04. 7pp. 94059:260
- 7810130127 Util will submit tabulated info requested in 780906 ltr 45 days later than requested. GRUCE.R.H. Yankes Atomic Electric Co. 78/10/06. 19 94003:059.
- 7Bi0190158 Forwards Amend 91 to License #DPR-3 revising Tech Specs as requested in 7B0713 ltr w/sefety evaluation & notice of issuance.
 21EMANN.D.L. Operating Reactors Branch 2 (Pre 790623). 78/10/06.

- --7810190169 Amend 51 to License DPR-3 revising Tech Speck re limitation of crane travel over spent fuel pit & surveillence requirements for travel of over 900 lb loads over spent fuel pit.
 ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625). 78/10/06 4pp. 94414:070
- --TBiO190175 Safety evaluation supporting Amend 51 to DPR-3 concluding that rearrangement in pit of spant fuel & racks. & installing new roof hatch over pit. & temporary gate support brackets in pit are acceptable # Office of Nuclear Reactor Regulation, Director. 78/10/06. Spp. 9444:074
- --7810190182 Notice of Issuance of Amend #51 to Facil Oper LIC #DPR-3 on 781006 ZIEMANN,D L. Operating Reactors Branch 2 (Pre 790625). 78/10/06. 3pp. 94414,082.
- 7810260160 Objects to continuous NRC demands that util meet addl criteria re overpressurization events, while NRC review process is unjustifiably lengthy & results only in requests for addl info Believes \$4000 fee request is unauthorized VANCENBURGH.D. Maine Yantee Atomic Power Co. 78/10/16. 5pp. 74059:742.
- 78102400B5 Presents results of grout investigation described in 780925
 Itr to NRC Concludes that heavy metals are present which
 will affect pool water chamistry
 JOHNSON.W P. Yankes Atomic Electric Co. 78/10/18. 1p. 07893:046.
- 7811020247 Repts on review of 8 Systematic Evel Prog topic assessments.
 Confirms that 4 are applicable to subj facil & that it is
 essential that assessments be generalized enough to apply
 to all plants
 VANDENBURGH. D Yankee Atomic Electric Co. 78/10/20. 2pp.
 94249: 112.
- 7811030011 Forwards Safety Eval of Proposed Mode to ECCS Recirculation SystTAC7667).
 LAIMAS.O. Assistant Director for Plant Systems. 78/10/26. 2pp. 02720:266.
- 7911100027 Requests add1 info on ESF switchover from injection to recirculation mode, isolation of reactor protec sys from non-safety sys. ESF sys logic & design, & specific drawings of elec sys & complete plant elec drawing indices.

 ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/26.

 3pp. 94178.284
- 7811020246 Proposes mode to Append A of Oper LiceDPR-3 Would change Table 3 &-1 to reflect addition of 4 manual isolation valves which become containment isolation boundaries & are subj to type C tests
 MINNICK.L.E. Yankee Atomic Electric Co. 78/10/30. 3pp. 94247:107.
- 7811240090 Returns 7 copies of Proprietary Drawing#001-33679."N"-Pump. L.P.B. I. by Ingersoll-Rand Co which was submitted as encl to 780822 itr but was not req for review completion. Only B copies were received & 1 was destroyed.

 ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625), 78/11/06. 2pp. 94496,330
- 7811210223 Responds to 780908 appl for lic amend to permit facil oper w/planned loading pattern for Core 14 & requests addl info re fuel design.accident analysis & LOCA analysis.
 ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/08.
 3pp. 94486:333
- 7811140190 Describes 2 supporting analysis re core boron concentration following unlikely event of LOCA occurring during reactor vessel hydrostatic test on zero power physics test. VANDENBURGH, D. Yankee Atomic Electric Co. 78/11/10. 2pp. 94384: 278.
- 7811170201 Responds to 780711 NRC itr requesting util to submit lic amend appl to incorp applicable Specs of Hodel Tech Spec. Util is having difficulty meeting response sched outlined in 780711 ltr due to sched refueling.

 QROCE.R.H. Yankee Atomic Electric Co. 78/11/13: 1p. 94047:339.
- 7811280080 Forwards Amend 52 to License DPR-3, safety evaluation & notice of issuance & availability.
 218MANN,D.L. Deprating Reactors Branch 2 (Pre 790625), 78/11/14.
 2pp. 02728:145.
- --78112B00B2 Amend 52 to License DPR-3, changing Tech Space to permit operation w/mod to ECCB recirculation cooling subsystem. ZIEMANN. D. L. Operating Reactors Branch 2 (Pre-790625). 78/11/14. 27pp. 02728:147.

- ~7811280083 Bafety evaluation supporting Amend 32 to License DPR-3 = Dffice of Nuclear Reactor Regulation, Director. 78/11/14. App 02728-175.
- ~~7811280084 Notice of issuance & availability of Amend 52 to License DPR-5 HAMBACH, T.V. Operating Reactors Branch 2 (Pre 790625). 78/11/14 2Pp. 02728:179.
- 7811280430 Forwards draft Bys Eval Prog Safety inputs re Topic VIII-3
 A. Station Battery Test Req. Requests they be transmitted to
 Licensees.
 DAVIS. D. W. Gustamatic Evaluation Programs Branch (Prog. 200425)
- DAVIB: D K Systematic Evaluation Programs Branch (Pre 790625) 78/11/14. | 23pp. | 94381:119.
- 78:R150092 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73.Requests pre-workshop registration of attendees to facilitate sending out math. Whenci Registration Form & List of Locations MILLER.J R. Assistant Director for Site & Sefeguards (Pre 791030). 78/11/15. 5pp. 94212-001.
- 7812190063 Forwards RevNt "Draft Radiological Effluent Tach Specs" for PMR "IfNARES-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plents" (NUREG-0133). H/o encl AND-7811270173 & 781127018.
 GRIMES.B.K. Assistant Director for Engineers & Projects (Pre 790625). 78711/15. dpp. 94215:107.
- 7811240167 Requests auth to change Tech Spec by adding add1 limit on Allowable Peak Rod Linear Heat Generation Rate for recycled fuel from Core XIII.assuring plant open w/in limits defined by LDCA analyses for referenced fuel.
 VANDENBURCH, D. Yankee Atomic Electric Co. 78/11/21. 4pp. 94458:288.
- 78:1240238 Forwards response to NRC questions requesting add1 into on core performance analysis rept YAEC-1162. NRC questions have nacessistated a Tech Spec change, which will be submitted shortly.

 VANDENBURGH, D. Yankee Atomic Electric Co. 78/II/21. ISpp. 94498:231
- 7811280221 Submits design & safety class info applicable to parts of alternate shutdown methods mod Entire new sys piping designed per util Engineering Dept QA Manual & components purchased & installed per Operational QA Manual YOQAP~1-A QROCE:R.H. Yankee Atomic Electric Co. 78/11/21. ip. 94012:090
- 7812070138 Notification of 781208 seminar in King of Prussie.PA to discuse new model radiological effluent Tech Specs. Seminar info sheat & proposed agends encl.

 ORIEP.8.H. Region 1. Philadelphia. Office of the Director.

 78/11/21. Spp. 94375: 184.
- 7811290255 Proposes emend to Tech Specs for facil lic.Proposed changes consist of wording changes & clarifications.None of the changes will alter acope or basis for any Tech Bpecs.
 Proposed emend attached w/check for \$1200.
 VANDENBURGH.D. Yankee Atomic Electric Co. 78/11/24. 18pp. 94237:08A
- 7812060297 Requests comments on draft eval of Systematic Eval Progtopic 8-3 A re Station Battery Test Requirements. ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/24. App. 94382:225.
- 7812110135 Forwards Amend 53 to License DPR-3, safety evaluation & natice of issuance & availability.
 ZIEMANN,D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/24.
 2pp. 94393:213.
- --7812(10139 Amend 53 to License DPR-3, changing Tech Space by reducing neutron detector thimbles required to be operable from 17 to 12 ZIEMANN D. L. Operating Reactors Stanch 2 (Pre 790625). 78/11/24. 13es. 9439:215.
- --7812110143 Safety evaluation supporting Amend 53 to License DPR-3.

 * Office of Nuclear Reactor Regulation. Director. 78/11/24. 9pp.
 94393:228.
- --7812110145 Notice of issuance & availability of Amend 53 to License DPR-3.

 8/LVER.R.O. Operating Reactors Branch 2 (Pre 790625). 78/11/24.
 2pp. 94393:235.

- Ouring current refueling shutdown ECCS Sys was mod resulting in deletion of number of items from original list. ORDCE.R.H. Vankse Atomic Electric Co. 78/11/27. 35pp. 94456:173.
- 7812040234 Responds to 760924 NRC 1tr request by forwarding Specs 3.4.10 k 4.4 10 to Append A to smand current Oper Lic. Also forwards results of Nov 1978 Eddy Current Inspecs. VANDEMBURGH.D. Yanksa Atomic Elsectric Co. 78/11/27. 14pp. 94329 002
- 78:2140040 Finds Yankee Pur Boile Model(YAEC-1140) acceptable. Forwards REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/27. Ppp
- --7812:40042 Sefety Eval Rept for Yankee Pur Spike Model.Finds model acceptable W/encl BER Supplet dtd Aug 1978.

 Operating Reactors Branth 4 (Fre 790625). 78/11/27. 15pp. 94126:315.
- 7812110004 Discusses possible dangers of LUCA in continment purging during normal plant open. Requests either commitment to limit purging or justification for continuing Wienci ANO: e7812080207.
 71FMANN.D.L. Dassating Reactors Branch 2 (Pre 790625). 78/11/29. Operating Reactors Branch 2 (Pre 790625). 78/11/29. ZIEMANN, D. L. Bpp. 94339: 157.
- 7812080116 Transmits current sched for mech struc work prog for SEP/Asymmetric LOCA loads re sub, facil Activities involve dev of analytic models, seismic assessments & piping analuses. VANDENBURGH. D. Yankes Atomic Electric Co. 78/12/04. 2pp. 94104: 361.
- 7812140340 Authorizes refund of \$4,000 Class III amend fee submitted in 781030 ltr. NRC has determined that waiver of fee is appropriate. DIGGS.R.M. License Fee Management Branch. 78/12/05. 1p. 03557: 164.
- 7812210295 Forwards Amend 54 to License DPR-3, safety evaluation & notice of issuance & availability. ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/06. 2pp. 94167:323.
- --7812210301 Amend 54 to License DPR-3 revising Tech Specs re facility operation w/refueled Core 14 performance of subsequent steam generator insp IAM Section 3/4.4.10 & inclusion of four containment isolation valves in Table 3.6-1.

 INCHANN. D. L. Operating Reactors Branch 2 (Pre 790625). 78/12/06. ITEMANN, D. L. Ope 40pp. 94168: 001.
- --7812210308 Sefety evaluation supporting Amend 54 to License DPR-3. Office of Nuclear Reactor Regulation, Director. 78/12/06. 1492. 94168: 004.
- --7812210312 Notice of issuance & availability of Amend 54 to License ZIEHANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/12/06. 2pp. 94168:018.
- 7812280117 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB.J.O. Office of inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94310:211.
- 7812150115 Requests addl info from SEP licensees re elec penetrations of reactor containments in order to complete eval.

 ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 770625). 78/12/08.

 App. 94212:149.
- 7812210034 Forwards NUREG-0485, Vol 1. No 2 "Status Summary Rept-Sys Eval Prog. W/o encl. ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625). 78/12/08. 2pp. 94267:332.
- 7812140145 Responds to 781026 & 1124 NRC requests for addl info re Systematic Eval Prog topics Provides info on automatic ECCS realignment, qual of isolation devices, engrd safety features RESIDENCE R.H. Yankes Atomic Electric Co. 78/12/12. 2pp. 94133:342.
- 7812200230 Forwards drawings re several SEP elec topics as requested in 781026 NRC ltr. Drawings available in Central Files. 9RDCE.R.H. Yankes Atomic Electric Co. 78/12/13. 1p. 94288:359.

- Q. Inspection reports: IE Bulletins & correspondence
- 78:0160236 Forwards IE Bulletin 78-12. "Atypical Weld Material in Reactor Pressure Vessel Welds" requesting action w/in 60 days & list of IE Bulletins issued in 1978 (see AND#7810040253)
 QRIER.B.H. Region 1, Philadelphia, Defice of the Director 78/09/29. 6pp. 94004:331.

- 7812010277 Forwards IE Insp Rept 50-029/78-14 on 780926-28.No noncompliance noted.
 BRUNNER.E. J. Region i. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/10 2pp. 94417 225
- --7812010278 IE Insp Rept 50-029/78-14 on 780926-28 No noncompliance noted Major areas inspected:preparations for refueling.ECCB procedures & in-office review of monthly operating repts. Inspector assisted fire protection survey team. LAZARUS, H. J. Region I. Philadelphia, Office of the Director 78/10/06. 4pp. 94417:227
- 7811060181 Forwards IE Circular#78-17 (See AND. 7810230221. Docket #50-133,781013.) ORIER 8 H. Region 1, Philadelphia, Dffice of the Director 78/10/13. ip. 94489:134.
- 7812010108 Forwards 1E Insp Rept 50-029/78-15 on 780925-28 No noncompliance noted.
 CARLBON.R. T. Region i. Philadelphia. Reactor Construction & Engineering Support Branch. 78/10/18. 2pp 94418:001
- --7812010111 IE Insp Rept 50-029/78-15 on 780925-28 No nancompliance noted, Major areas inspected; arrangement of safety-related equipment, fire hazards, fire protection equipment & administrative controls.

 PAOLING, R. J. Region i. Philadelphia, Office of the Director.

 ESNETER, B. D. Region i. Philadelphia, Reactor Construction &

 Engineering Support Branch. 78/10/17. 4pp. 94418:003
- 7811290151 Forwards IE Circular #78-18. "UL Fire Test. "W/encl ANO: 7811150002. GRIER, B. H. Region 1. Philadelphia: Office of the Director. 78/11/06. 1p. 94239:344.
- 7812010146 Responds to IE Bulletin 78-12 Requests time extension unt 790131 to provide record searches requested. ORDCE.R.H. Yankee Atomic Electric Co. 78/11/13. ip. 94418: 088.
- 7812180026 Forwards IE Bulletin#78-12A. Suppl to IE Bulletin 78+12. W/encl ANO.7811300055. GRIER.8.H. Region I. Philadelphia. Office of the Director. 78/11/24. 1p. 94130:335.
- R. Periodic operating reports & related correspondence
- 7810170176 Forwards Monthly Statistical Rept for Sept 1978
 MDDDY, D.E. Yankee Atomic Electric Co. 78/10/10. ip. 94270: 093
- --7810170178 Monthly Statistical Rept 78-9 for Bept 1978. BJOREN.R.M. Yankes Atomic Electric Co. 78/10/06. Spp. 94270.084.
- 7811140120 Forwards Monthly Statistical Rept for Oct 1978 MODDY, D. E. Yankes Atomic Electric Co. 78/11/10. ip. 94428: 205.
- ~-7811140122 Monthly Statistical Rept 78~10 for Oct 1978. SUDGREN, R. M. Yankee Atomic Electric Co. 78/11/10. 5pp.
- 7812150286 Forwards Monthly Statistical Rept for Nov 1978 MODDY, D. E. Yankee Atomic Electric Co. 78/12/11. ip 94409-185
- --7812150288 Monthly Statistical Rept 78-11 for Nov 1978. SJOOREN, R. M. Yankee Atomic Electric Co. 78/12/11. 94409: 186.
- B. Reportable occurrences, LERs & related correspondence
- 7810180008 Forwards LER#78-023/03L-0. AUTIO, H. A. Yankee Atomic Electric Co. 78/10/13. 1p. 94422:007

- --7810180009 LER 78-023/03L-0 on 780913.during 5-h shutdown dose equivalent i-131 concentration of primary coolant sys exceeded 1 0 rC1/g dose equivalent of 1-131 Caused by cladding defect in single fuel rod BOUTWELL.R L Yantee Atomic Electric Co 78/10/13 4pp. 94422 008
- 7810180015 Forwards LER#78-024/03L-0 AUTIO, H A Yantee Atomic Electric Co 78/10/13 1p 94422 004
- --7810180017 LER#78-024/031-0 on 780913 during unscheduled shutdown steam generator bloudoun chloride concentration exceeded 0 3ppm Caused by phenomenon of hideout of impurities in eteam MAY.E L Yankee Atomic Electric Co 78/09/13 29p 94422:003
- 7810240152 Forwards LER 78-025/03L-0 AUTID.H A Yankee Atomic Electric Co 78/10/18 1p 07893 047.
- --7BiO240154 LER#7B-025/O3L-0 on 7B091B during normal oper source check failed to give proper response while performing surveillance on Main Coolant Bys Leakage Air Particlate Monitor Caused by end of life of photomultiplier & electron tubes a Yankee Atomic Electric Co 78/10/18 2pp 07893 048
- 7810240156 Forwards LER 78-026/03L-0 AUTID, H. A. Yankee Atomic Electric Co. 78/10/18 ip. 07893.090
- --7810240165 LER 78-026/03L-0 on 780918, while checking primary vent stack monitoring equipment during Mode 1 operation plastic container used to collect condensation from primary vant stack monitor air dryer was found lealing.

 Yankee Atomic Electric Co. 78/10/18 2pp 07893 051
- 7811090145 RO 50-029/78-29, during Mode & refueling shutdown w/#23 guide tube removal being initiated, load increased above normal base load & anticipated guide tube weight observed Caused by incorrectly set load cell.

 AUTIO, H.A. Yankee Atomic Electric Co. 78/11/06. 2pp. 94042-350.
- 7811280473 Reportable Occurrence#50-29/78-29 during Mode 6 refueling shutdown guide tube weight fluctuated 100-300 lbs above base load Caused by manipulator load cell set incorrectly.

 ANTID. H.A. Yankee Atomic Electric Co. 78/11/06. 2pp. 94379: 356.
- 78ii170200 RO 50-29/78-30 on 78ii09, approx 100% eddy current exam of steam generators | & 4 revealed that 15 tubes in steam generator | & 12 tubes in steam generator | & 12 tubes in steam generator | & 12 tubes in steam generator | 4 have degraded tubes of more than 40% wall thickness.

 AUTIO. H A Yankee Atomic Electric Co 78/11/09. 1p 94:36:082.
- 7811170211 RO 50-29/78-31: on 781113, abnormal degradation found in fuel cladding in following through on cause for ROs 77-55, 78-03, 78-19 & 78-23, sipping of spent fuel from Core B completed & three suspect fuel assemblies identified AUTIO, H.A. Yankee Atomic Electric Co. 78/11/13 ip. 94136:112.
- 7811300378 Reportable Documence 50-29/78-31. Abnormal degradation discovered in fuel cladding while following through on their reportable occumences Complete report follow w/in 2 wks.

 AUTIO.H A. Yankee Atomic Electric Co. 78/11/13. 1p. 94136-251.
- 7811210317 Forwards LER#78~029/01T-0 AUTIG: H A. Yankee Atomic Electric Co 78/11/15 Ip. 94468: 035.
- --7811210325 LER 78-027/017-0. on 781101. during refueling while removing guide tubes, en auxiliary set of latches closed on M23 control rod drive sheft. Hanipulator handling tool loads cell controller was read justed.

 ARON. R. Yantee Atomic Electric Co. 78/11/15. 20p. 94488-056
- 7811280290 LER#78-027/03L-0 on 781021: during shutdown, steam generator's chloride concentration exceeded 0. Sppm Caused by steam generator's chem hidmout.
- BOUTHELL, R. L. Yankee Atomic Electric Co 78/11/20. ip. 94395:235.
- AUTIG.H A. Yankee Atomic Electric Co. 78/11/20. 1p 94395.234.
 7811280328 Forwards LER#78-028/03L-0.

7811280284 Forwards LER 78-027/03L-0

AUTIO, H. A.

--7811280332 LERH78-028/03L-0 on 781021: during test 0P-4502, two safety valves, Type HD36 Style HC65 & Type BD33 Style HC65 nfg by Crosby Valve & Oage Cl.had low setpoints. Setpoint drift was caused by spring characteristic changes

MAY.E L. Yankes Atomic Electric Co. 78/11/20. 2pp. 94395:349.

Yenkee Atomic Electric Co. 78/11/20. 1p. 94395:348.

- 7811280323 LER#78-030/017-0 on 781109 during eddy current tes tubes in #1 & 12 tubes in #4 steam generators had greater than 40% wall degradation. Degradation of one tube caused by mfg defect other causes unknown. MAY.E L Yankee Atomic Electric Co 78/11/22 3pp. 9439
- 7811280314 Forwards LER#78-030/01T-0. AUT10.H A Yankee Atomic Electric Co 78/11/22 ip 943
- 7811290198 Forwards LER#78-031/01T-0 AUTIO, H A Yanker Atomic Electric Co 78/11/25. 1p 942
- --7811290203 LER#78-031/01T-0 on 781111 during Core X111-x1v shutdown.fuel sipping revealed degradation of fuel claddi in assembiles#492E.88026.8490E & 8492E.Cause is under investigation by Exton.
 BDUTHELL.R L. Yankee Atomic Electric Co. 78/11/25 ip 94239-300
- 7812010224 LERW78-028/03L-1 on 781021 during test OP-4502.2 s valves mpg by Crosby Valve & Oage.were found to have setpoints lower than Tech Specs limits. Cause is unknown. Valves reset & uill be retested before startup. MAY.E.L. Yankee Atomic Electric Co. 78/11/27. 2pp.
- DOCKET 90-30 PLUM BRODK RESEARCH REACTOR FACILITY
 P. Operating license stage documents & correspondence
- 7812180435 Submits conformed copies of selsmic analysis & con info re subj facil IAW 771107 request Belisves selsmic analysis gives assurance that facil can be oper safely w/in present tech specs. DARMITZEL, R W. General Electric Co. 77/11/29. 42pp. 943
- DOCKET 50-54 UNION CARBIDE REBEARCH REACTOR

 F. Security, nedical, emergency & fire protection plans
- 78:2270:64 Forwards Physical Security Plan changes Revisions from pub disclosure pursuant to 2 790
 PARADIBO.J W Union Carbide Corp. 78/12/20. 1p 940:8.0
- J. Insurance & indemnity information
- 7812290157 Requests explanation as to why UCC is asked to add to indemnity Agreement 8-14 re assessment of deferred premiums when it has no relevance to the five megawatt themal res reactor numed by UCC.

 VOTHUM M. Union Cerbide Corp. 78/12/21. 1p. 94190:291.
- P. Operating license stage documents & correspondence
- 7811160147 Forwards ltrs re appl of 10CFR73.50 requirements to site whenever total U-235 in unirradiated fuel elements to irradiated to unirradiated target mat 1 arroads 5.000 to note inapplicability to facil Proprietary info w/held VOTH M H. Union Carbide Corp. 78/11/10. ip. 94135:263.
- 781219009: Forwards final draft of Tech Specs & recommends so compliance w/new specs. GEORGE, K. D. Union Carbide Corp. 78/12/15. 2pp. 94341:01
- DOCKET 50-57 STATE UNIV. OF NEW YORK RESEARCH REACTOR
 H. General correspondence
- 7810300187 Notifies NRC of respondent's appointment as Acting of Nuc Science & Tech Facil at SUNY/Buffalo, & other appointments.
 CHDN M.Y. New York, State Univ. of, Buffalo 78/07/25.
 94034:003
- P. Operating license stage documents & correspondence
- 7811280092 Reminder that subj Pacil lic expires on 780915 & requires timely appl Wantl "Lic Renewal Review Items." REID.R. M. Operating Reactors Branch 4 (Pre 790625). 78/10 02726: 328.

- O Inspection reports. IE Bulletins & correspondence
- 7810190104 Ack receipt of 780919 ltr informing NRC of steps taken to correct violations noted during Inspec#50-057/78-04 MARTIN-W.O. Region I. Philadelphia, Bafeguards Branch 78/09/29 to 94413 280
- --7810190107 Forwards IE Inspec Rept#50-057/78-04 & Notice of Violation. MARTIN: H G Region 1: Philadelphia: Safeguards Branch. 78/08/30 2pp 94413.279
- --7810190116 IE Inspec Rept#50-097/78-04 on 780726-28 during which 2 items of noncompliance were noted. Security Drganization-quarterly audit not performed first quarter 1970, & Surveillance-deter clock checks not conducted by police BALEY, R. J. SMITH.R. Region 1, Philadelphia, Bafeguards Branch. 78/08/14 jp. 94413-281.

DOCKET 90-59 TEXAS A&M UNIV RESEARCH REACTOR

- 7811020277 Value/Impact Assessment of Outdance to Applicants relative to Emergency Planning Requirements for Research Reactors Recommends Reg Guide.

 REID.R.W. Operating Reactors Branch 4 (Pre 790625) 78/10/12 4pp. 94260 272.
- F. Security, medical, emergency & fire protection plans
- 7811030222 Forwards copies of Reg Quide 2 XX and Final draft ANS 15 16 to assist in formulation of emergency plan for subj facil. M/O encl.
 REID. R. H. Operating Reactors Branch 4 (Pre 790625) 78/10/12 ip 02/24 251.
- 7812220079 Forwards "Emergency Plan for TXAM Univ AGN-201M Reactor." MILLER, J. Texas A & M. Univ. 78/12/18 1p. 94343:300
- --7812220080 "Emergency Plan for TXAM Univ AGN-201M Reactor (Serial 105) as Mod to Incl AN815.16 & Reg Ouide 2. XX Quidance " # Texas A & M Univ. 78/12/12. 24pp 94343.301.
- P. Operating license stage documents & correspondence
- 7811020272 Forwards proposed Reg Guide 2.XX w/ Value/Impact Assessment & final draft ANS 15.16 re emergency planning as assistance for rev Memphis State Univ Tech Spec rev REID.R.W Operating Reactors Branch 4 (Pre 790625). 78/10/12. ip. 94260:241.
- --7811020274 Proposed NRC Rag Ouide 2. XX, "Emergency Planning for Research Reactors". REID.R.W. Operating Reactors Branch 4 (Prø 790629). 78/10/12 4400 94260-242
- --7811020298 Draft "Std for Emergency Planning for Research Reactors."
 Identifies elements & procedures of emergency plan re coping
 W/emergencies & minimizing consequences of research reactor
 eccidents.
 RICHARDB.W. American Nuclear Society 77/12/30 14pp.
 94260.276
- 781213023B Responds to 781012 NRC 1tr & forwards mode to Tech Specs as rev Append A to lic(R-23)renewal appl of 77031. Tech Specs rev to incl ANSI N378-1974 & Reg Guide 2.2 guidance.
 MILLER.J.E. Terms A & M Univ. 78/12/11. 30pp. 94213.126.
- G. Inspection reports. IE Bulletins & correspondence
- 7812190421 Forwards Inspec Rept#50-059/78-01 on 781107-08 during which no items of noncompliance were noted.
 MADESNO L. Region 4, Dallass Reactor Operations Nuclear Support Branch. 78/12/01. 2pp. 94359:342.
- --7812180424 Inspect Rept#50-059/78-01 on 781107-08 during which no items of noncampliancs were noted Hajor areas inspected incl: implementation of Physical Security Plan relative to SNM protection, addaes control alarm sus locks, keys to hardware. WARD, J. J., EVANS, C. A., MADSEN, G. L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 78/12/01 ip. 94358:344

- DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR

 P Operating license stage documents & correspondence
- 7812200222 Requests arend of Tech Spec Sec 4.1 C re visual inspec of boron-stainless steel safety rods for LickR-66 Amend also requested for change in Tech Spec Sec 1 12d for LickR-66 & Sec 1 15D for LickR-123 wording is unnecessarily vague WILLIAMSON, T. O Virginia, Univ of 78/07/14. 2pp 94162-303.
- 78ii010i02 Responds to IE Bulletin 78-08 Bulletin does not apply to subj fecility as reactor has no such tuber IE Bulletin 78-07. does not apply.

 MILLIAM ADDIT 0 Virginia Univ. of 78/08/31 ip. 74391-344
- 7811030063 Responds to 770309 appl for renewal of Facil Oper LiceR-UVA Res Reactor Requests add1 info re financial considerations & emergency planning w/in 60 days REID.R.W. Operating Reactors Brench 4 (Pre 790625) 78/10/16
- 7811080179 Offers comments on NRC regs for self protecting SNM in r reactor fuel element. Asserts that weakness in spec is that dose rate is not connected w/specific quantity of SNM Supporting documentation from med treatises encl WILLIAMSON.T. Q. Virginia. Univ of 78/10/30 21pp
- 7812200232 Requests amend for Facil Oper Lic*R-66, to rev sections 3 4 & of Tech Specs to allow oper of reactor when Emergency Exit Manhole Natch is closed in order to enhance reactor security
- WILLIAMSDN.T.Q. Vinginia, Univ of. 78/12/11 2pp 94162:319.
- 7812200221 Requests approval of amend to Facil Oper Lic#R-66 allowing Univide receive possess & use Np237. Math will be used for neutron dosimetry in an irradiat test of pressure vessel steels WILLIAMSON, T. Q. Virginia, Univ. of. 78/12/18 1p. 94162.302
- 7812260144 Provides info requested in NRC 781016 ltr re lic renewel items. Info incl financial & environ considerations, & gen info concerning Univ WILLIAMSON.T. Q. Virginia, Univ. of 78/12/18. 28pp. 94161-197
- 7812290007 Forwards Amend#12 to Facil Lic#R-66 & Bafety Eval REID.R.W. Operating Reactors Brench 4 (Pre 790623). 78/12/19. 94207:321
- --7812290003 Amend #12 to Facil LickR-66 changing Tech Spec re surveillance of tafety rods REID.R.H. Operating Reactors Branch 4 (Pre 790623) 78/12/19 4pp 94207:383
- --78:2290010 Bafety Eval supporting Amend#12 to Facil LitHR-66 Concissuance of amend will not be inimical to public or national interests

 * Office of Nuclear Reactor Regulation, Director 78/12/19, 94207:327.
- DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR
- 7809260256 Response to 771219 itr.Havakawa to Former Chairman M. Rore NRC allowing interim oper by Gen Elec Go of its GETR facil pending completion of pub hearings. Decision to allow interim oper rests with ABLB.

 DIRCKB.M.J. Office of the Elecutive Director for Operations. 78/02/07. 2pp. 01384:028
- · A Application/construction stage documents & correspondence
- 7810230144 Ack receipt of 780818 proposed site fault investigation Expects that NRC safety eval could be issued by Jan 1979. REID.R.M. Operating Reactors Branch 4 (Pre 790625). 78/09/27. 94164:083.
- 7811200088 Responds to 781015 ltr to J Hendrie re subj facils. Rept eval of both facils continues & that discharges of tritium have been small fraction of reg limits of 100FR Part 20. W/out encl NRC eval of site. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 78/11/13. 2pp. 94218:344.

FOX:A Affiliation Unknown. 78/11/06 1p. 94252 296.

G. Adjudicatory correspondence

- 7810230026 Forwards "Gen Elec Co Establishment of ASLS to Rule on Petitions".to be pub in Fed Register 771116 Hat1 to be charged to requisition wb-149 CHILM-S J. Office of the Secretary of the Commission 77/11/11. 1p. 94169.265
- --7810230030 Notice of "Establishment of ASLS to Rule on Petition" to be pub in 771116 Fed Register YORE-J.R. Atomic Safety and Licensing Board Panel. 77/10/21. 20p. 94169:247.
- 7810110268 "Intervenors' Answers to Licensee's Interrogetories dtd 780626" gave reasons why certain info cannot be provided & agrees that nuc reactors should not be located near earthquake faults.

 DELLUMB.R. V. House of Rep. 78/09/18 3pp. 94068:001
- 7810110271 "Intervenors' Discovery Status Rept" listing all documents received & sent out since 780816 in QETR Show Cause proceedings DELLUMS.R.V. House of Rep. 78/09/22. 3pp. 94068:041.
- 781030006≥ Intervenor's Interrops to the Gen Elec Co re piping in subj fact1. M/enc1 Cert of evc. BALDHIN M A. Baldwin W. A. 78/09/25. 3pp. 94034:283.
- 7810190193 Intervenor's Discovery Status Rept. Lists what FOE has received to data BALDMIN.M. A. Friends of the Earth. 78/09/27. 3pp. 94270:017.
- 7810140100 Believes that reopening subj facil would pose a severe threat to his health & safety. Requests limited appearance at public hearings.

 TRAFFLEABURE.L. Affiliation Unknown. 78/09/28. ip. 94002:242.
- 7810120019 Responds to 780929 request for copy of Steff draft rept on earthquake potential. W/encl 780817 rept "Bhow Cause Proceeding Safety Evaluation Rept Input.0E Test Reactor Bite /Vallecitos Nuc Center".

 78897.5 A. Office of the Executive Legal Director. 78/09/29. 38pp. 94300: 133.
- 7810140113 Denies request of N Snow, acting on behalf of intervenor R.
 Dellums that USOS provide estimates of maximum strong ground
 motion & surface offset at site of sub; facil.
 LUTONE. Atomic Bafety and Licensing Board Panel. 78/10/03. 2pp.
- 7810140130 8d has yet to receive opinions re-subj facil that were to be transmitted via Congressman Dellums by the US Attorney General & House Select Committee on Ethics.

 # Atomic Safety and Licensing Board Penel. 78/10/03. 1p. 94466:360.
- 7810130188 Order re intervenors' motion for order suspending preparation of SER pending results of hearing.NRC will show neither the SER nor any contributing staff member was biased by er parte communications.

 LUTON.E. Atomic Safety and Licensing Soard Panel. 78/10/03. 3pp. 94003.116.
- 7810300PRD NRC Staff's Answer to Intervenor's Motion for Reference of Questions. Intervenors are Friends of the Earth & Congressman Ronald Deliums. NRC Staff opposes their motion of the 780913. Certificate of Svc ancl. CHANDLER, L. U. Office of the Elecutive Legal Director. 78/10/05. opp. 74034:089.
- 7810230084 Intervenor's Response to Licensee's Cross-Motion for Imposition of Sanctions. Licensee had filed request for imposition of Sanctions against intervenors for not answering interrogs. Requests GE 780928 motion be dented. BALDMIN.M. A. Friends of the Earth. DELLUMS.R.V. House of Rep. 78/10/06, 12pp. 94170:146.
- 7810230009 NRC Staff Response to Licensee's Cross Nation for Imposition of Santtions. Staff Recommends that in lieu of such action, the 8d direct Intervenors, Congressman Ronald Dellums & Friends of the Earth, to state their intentions re 8d's order. BHANSON, D. T. Office of the Executive Legal Director. 78/10/10.

- 78:1200044 Responds to 78:013 ltr requesting that Test Reactor be shutdown permanently because of tritium seepage. Facil is shut down because of potential for surface faulting not seepage. which is w/in reg limits. W/o Show Cause Order encl. DENTON-H R. Office of Nuclear Reactor Regulation. Director. 78/10/13. 1p. 94215:325.
- 781107036; Requests Gen Elec Nuc Test Reactor remain closed until proper seismic & geological tests are concluded. Also expresses concern over tritium which may be seeping into ground water from facil. Requests info re hearings on facil. DELFINO, J. B. Affiliation Unknown. 78/10/15. 1p. 94043: 200
- 7811130246 Intervenor R Dellums'discovery status rept.listing documents received & sent re-proc re-subj facil since 780922. Cert of 8vc encl.

 BUC encl.

 BELLUMS, R. V. House of Rep. 78/10/23 3pp 94011:279.
- 781102024) Danies licenses GE's cross-motion for imposition of sanctions upon intervenors Dellums & Burton for failure to respond to GE's discovery requests. Denies intervenors' request for referral of 780814 ruling to NRC.

 LUION.E. Atomic Befety and Licensing Board Panel. 78/10/24. 13pp. 94247:090.
- 7811270297 Ack 781003 ltr participation as intervenor in GETR Vallecitos Nuc Center proc. States legal counsel approves representation at proc. DELLUMS, R. V. House of Rep. 78/10/26. 2pp. 94239:260.
- --7811290304 States informal views reparticipation as intervenor Member of Congress are permitted to furnish representational svc for private parties in proc before Fed agency if no compensation is received. W/Cert of Svc. KEUCH. R. L. Justice Dept. of. Attorney General's Office. 78/06/R6. App. 74239:262.
- 78:1200064 Btates that since the last status rept, staff has neither received nor issued any new discovery requests rallsubjecti.

 8MANBON.D.T. Défice of the Executive Legal Director. 78/11/02. 1p. 94218: 351.
- 78:1270049 Requests to be informed of all hearings re subj facil. Absolutely opposes all facil oper until completion of addequate seismic studiation bearings & consideration of all evidence. GETR & Pu labs must be shut down & lic revoked. LEWIB. A. B. Affiliation Unknown. 78/11/05. 1p. 94260:361.
- 7812040348 Intervenor's Discovery Status Rept. Lists correspondence sent & received since last Status Rept. BARLOW, Q. Friends of the Earth. 78/11/07. 3pp. 94489:308.
- 7812040360 Forwards 780929 memo from ofc of Nuc Reactor Reg to Comm raresults of recent fire protec res test by Undarwriters lab. W/encl ANO.7810050359.

 BMANBON, D. T. Diffice of the Executive Legal Director. 78/11/07. 1480. 94127:149.
- 7811210451 Licensee GEVN's discovery status rept. Interroge were submitted by Rep R Dellums on 780808 & 7808181 licensee responded on 780821 & 780830 respectively. Cert of eve encl. EDGALO. L. Horgan, Lewis & Bockius. 78/11/08. 8pp. 94480:344.
- 7811300393 Requests that subj facil be kept closed because of the unspeakable threat its operation would pose for the pub. HAWK C. Affiliation Unknown. 78/11/10. ip. 94136:300.
- 7812010323 Strongly supports keeping subj facil closed Beliaves it is an unspeakably great danger to present & future generations. HAWK.C. Affiliation Unknown. 78/11/10, ip. 94417:324.
- 7811220133 Orants intervenors' 780818 motion for order compelling responses to their 780803 interrops by licensee Gen Elec. Denies licensee's cross-motion for protective order re this discovery.

 LUTON-E. Atomic Bafety and Licensing Board Penel. 78/11/13. ip. 94074:259.
- 7811220137 Denies Motion of intervenors Deliums, J Surton & P Burton for licenses Oen Elec to make photographs in verification of primary & secondary cooling pipe & support locations. GEVN Motion for protective order is granted.

 LUTCN: E. Atomic Safety and Licensing Board Pensl. 78/11/13. ip. 94074:283.

Friends of the Earth. /8/11/13

tes apposition to subj facil Requests order halting tritium into groundwater. Affiliation Unknown 78/11/15. ip 94304-323.

ervenora Response to NASLB Memorandum & Order dtd 781024. refuse to reveal names of any persons aiding unless intervenors intend to call these persons. Gert of Svc encl. House of Rep. 78/11/15 2pp. 94278: 272.

ensee OEVN's Response to ASLB Memorandum & Order of ting intervenors Friends of the Earth & Dellums o GEVN interrogs Responses are nonresponsive. s imposing of sanctions Cert of Svc encl. Morgan, Lewis & Backlus. 78/11/17. Spp. 94071 304.

uests subj facil remain closed until it can be shown that h & safety are completely assured. Afiliation Uninown. 78/11/20 1p. 94306:327.

tervenors' Response to Discovery Requests." Intervenors. tervenors Response to Discovery Requests. "Interveni the Earth.do not believe production of Btdl:men in response to eny discovery requests preliminary rept.Cest of Svc encl. Friends of the Earth. 78/11/27. 6PP. 94407:311.

Staff's Answer to intervenors FDTE's & R Dellums'request refusal to answer licensee GEVN's interrogs be Comm Staff urges that request be denied & that ed from discovery. W/Cert of 8vc.

Qffice of the Executive Legal Director. 78/11/29 310.

passe QE's Anguers to intervenor R Dellum's interrogs tions concern fuel flooding sys, containment uum relish sys & ather tapics re sefety af subj with & Cert of Evc encl. , GillianNp.D.L., DARMITZEL,D.W. General Electric Co. pp. 94347: 334.

rects error in "NRC Staff answer to Intervenors' Request & Licensee's Motion for Imposition of dtd 781129. On p2 "denied" should read "granted." ts Licensee's request to impose senctions. Dffice of the Executive Legal Director 78/12/05 ip.

respondence

uests appearance at all showcause hearings re subj parmament & complete closing of subj facil due ion on a capable fault on Unknown. 78/09/10. ip. 94088:203.

os96 restart of subj facil. Affiliation Unknown. 78/09/30. ip. 94412:225.

resses concern re permanent & complete closing of subjited waste & earthquake heserds. Requests notice to of any NRC hearing related to the status of

filiation Uninown. 78/11/04 2pp. 94273:299.

ponds to 781015 ltr apposing reopening of subj facil. lic process.Recipient is incl in Syc list of eive notice ofhearings on subj (See: AND

Office of Nuclear Reactor Regulation, Director. pp 94449: 196.

pends to 781020 referrel itr re 781019 itr of H Wolch by affety-related design repts explaining sefety
of 21 reactors w/OE Mark I containment W/encl
tr to Holch & congressional correspondence.
Office of the Executive Director for Operations. 3pp. 03558: 090.

leges subj facil shutdown decision be made permanent by NRC. .nfo re status of 150kg of plutonium stored at subj

Affiliation Unknown, 79/10/15, 1p. 03558:108.

- D. Advisory Committee on Reactor Safeguards reports & correspondence
- 78:10:10220 Comments on 780824 meeting at facility Believes that if Verona Fault exists no threat to facility exists Strong earthquake is possible PAGE B.M. Stanford Univ. 78/08/25 ip. 94392:021.
- 7811020313 Bellayes no final conclusions run be drawn from 780824 meeting at subj facil re seismic studies of subj site THOMPSON, G. A. Stanford Univ. 78/08/25. ip 94256: 025
- P. Operating license stage documents & correspondence
- 7812180404 Forwards form reply sent in response to publinquiries re pending lic renswal apple. Forwards mailing list for notices to be issued on renswal apple.

 BURGER. A. Operating Reactors Branch 1 (Pre 790625) 77/05/06. 4pp. 94357:087.
- 7812190408 Forwards draft ltr outlining NRC review process as background info for GETR review Requests comments HANCHETT, J. Q. Region 5, San Francisco, Office of the Director. 77/09/06. App. 94357:101.
- 78:2150069 Requests submittal of addl site-related info w/in 30 days. BCHMENCER, A. Operating Reactors Branch 1 (Pre 790625). 77/05/20 2pp 94210:190
- 7812180355 Reports on briefing by D Herd re detailed field mapping that has identified a number of faults w/relatively young geological movement near subj facil.

 8TEPP.J.C. Geosciences Branch. 77/09/12 2pp. 94356.073
- 7812180357 Summarizes 770803 meeting re discussion of spienic reeval of subj facil. Concluded that addl info re site spienic & gaologic info is needed from Gen Elec BURGER. Operating Reactors Branch | (Pre 790625). 77/09/15 4pp. 74356:075
- 7812180414 Summarizes 770831 briefing on Cen Elec's Phase I Declaying Summerizes //OSJ oriering on wen Elec's rhade 1
 Opological Investigation which presented a new map of
 Livermore Valley & interpreted the geology & setsmology of
 area around Oreenville & Las Positas Faults.
 BURGER, A Operating Reactors Branch 1 (Pre 790625). 77/09/15. App.
 94357:148.
- 7812180411 Discusses rereview re ability to cool core assuming cooling water absence of Full seismic design capability Because of various assumptions, staff must have reasonable assurance of items withstanding seismic forces. SCHMENCER. A. Operating Resctors Branch 4 (Pre 790625). 77/10/04.
- 7812210127 Requests that Opology & Beismology Branch provide tech assistance to Div of Operating Reactors in the geology & seismology review of the subj facil as discussed in enclosed TAC#7062. W/o encl. BTELLO.V. Division of Operating Reactors. 77/10/04. 1p. 94269: 318.
- 7812200053 "Review of Severe Weether Meteorology at Oon Elec Co Vallectics.CA." Provides calculations & info for determining characteristics of design-basis storm. FUJITA.T.T. Argonne National Leboratory. 77/05/31. 25pp. 74159: 083.
- 7812190225 Summarizes 771024 conversation w/GE & consultants to near Vallecitos facil & status of investigations of faulting BTEPP, J. C. Quesciences Branch 77/10/25. 29p. 94381: 230.
- 7810130107 Notice of meeting w/QE on 771029 to provide info to justify resuming open of QETR.

 OOLLER.K.R. Division of Openating Reactors. 77/10/27. 1p. 94003: 167

1

7812180330 Forwards rept on status of assessment of geology & seismology at QETR site, dtd 771025.

QAMMILL, W. P. Assistant Director for Bite Technology. 77/10/28.

App. 74357: 338.

- 7812190231 Discusses status of trench closing at Vallecitos & examination of trenches by NRC & other agencies. Recommends that OE be allowed to backfill trenches 1.2 & 3 & the large bareholes now dug. w/encl comments for 771202 GETR meeting DENTON.H R. Defice of Nuclear Reactor Regulation. Director. 77711/30 5pp 94381. 265.
- 7812210331 Forwards info re facil fuel element decay heat as of 771130 HOGGATT.O.D General Electric Co. 77/12/07. 7pp. 94014.279
- 7810260037 Forwards for review "Beismic & Basis for Struc Analysis of Reactor Bldg by EDAC" dtd 771216 for review Encl already on file in PDR & Central Files
 BAGCHI-Q Engineering Branch (Pre 791030). AT-42-24-0116
 77/12/23 3pp. 01791 037.
- 7809270023 Outlines proposed action plan on Gen Elec's 771216 response to NRC's 771024 Order to Show Cause.

 8CHWENCER, A Operating Reactors Brench 1 (Pre 790625) 78/01/05.

 3pp.
- 7812180428 identifies sys which are req to assure adequate core cooling. & specifies operability conditions that must be met by each sys.

 SAER.R.L. Reactor Safety Branch (Pre 791030). 78/01/09. 3pp. 94358:029.
- 7812180431 Provides results of 771216 site visit to observe topography & gaology exposed in tranches Further study is needed to determine certain absence of faulting at site. KURKUIAN, T. G. Interior, Dept of, Ocological Survey. 78/01/30. Rpp. 94364-282.
- 78:12:80425 Forwards 78:0201 USOB review of potential faulting at subj site Feels staff should not take firm position until after its review. W/encl AND 78:09250067 QAMMILL. W.P. Assistant Director for Bite Technology. 78/02/03. 2pp. 94358:020
- 7812190198 Bummary of 780125 meeting to discuss effect of possible earthquakes generated by Calvernas & Verona faults at site.

 JACKSON R. E Division of Site Safety & Environmental Analysia.
 78/02/03 ip 94076-112
- 7812180401 Forwards info on all GETR scrams which have occurred since plant was initially started in 1930 DARMITZEL,R.W. General Electric Co. 78/02/14. 2pp.
- 7810110200 Responds to 780911 request for info on status of OETR. GE is conducting a fault investigation.will take 2 months before NRC can produce safety evaluation & another month before show cause issues go before ASLB DIRCKS! M J. Office of the Executive Director for Operations. 78/10/94. 3pp 94069:001.
- --7810110203 In 780209 ltr.author was informed that US Geological Survey & an independent consulting firm were advising NRC on matters re subj facil geology & seismology. Requests a rept on status of proceedings. TOWER, J. Senate. 78/09/11. 2pp. 94069:004.
- --7810110205 Expresses concern about OETR shutdown because it may disrupt the supply of radioisotopes, some of which are only made commercially at the subj facil. Requests restart oper to begin as soon as possible. TOWER, J. Benate. 77/12/20. 2pp. 94069:006.
- --7810:10207 In response to 771220 ltr.forwards info on status & issues relevant to subj facil. Pub hearings are being held & the ASLB will make the final decision re restart.

 DIRCKS.W J. Office of the Exacutive Director for Operations. 78/02/09. 2pp. 9405:00B.
- 7910110165 Responds to 780406 request for edd1 info re resumption of oper of QETR. DARMITZEL.R. W. General Electric Co. 78/10/06 39pp 94069:279.
- 7810270110 Requests that subj facils remain classed, inesmuch as Celavars fault is only a few hundred fest from plant.
 F18CHER. B. Affiliation Unknown. 78/10/08. ip. 94059:302.
- 781024020A Notification of 781013 meeting in Pleasanton.CA to inspect trenches completed in site fault investigation.
 NELBON.C.C. Operating Reactors Branch 4 (Pre 790625). 78/10/10.
- 7811020033 Opposes reopening of subj facil because it is built on a gaologically unstable site. VANTHIEL, M. Affiliation Unknown 78/10/20. 1p. 94355:198.

- 7811080039 Requests rept of attached 781018 constituent ltr re attempts by Mendrip of NRC to suppress potential damaging info re nuc pur safety as reported by Union of Concerned Scientists HAYAKAMA, 8 I Senate 78/10/20 Ip. 94398:113
- --7811080056 Contends NRC shut-down order for Gen Elec Test Reactor be made parmanent since safety against maximum seismic activity can not be guaranteed Also requests discharges of tritium cease & info on hearings be provided HDLCH, H. Affiliation Unknown. 78/10/15. 1p. 94398:115.
- 7811070391 Responds to 781006 ltm to J Schlesinger re facil in Livernore Valley Region DOE is collecting the requested info re LLL Questions he Vallecitos facil are being forwarded to NRC.

 BRATTON, J K Defense, Dept of 78/10/24 1p. 94043:179.
- ---78:1070355 Requests info an seismic & geologic testing in the Liverace Valley Region & what effect faulting in the area has had on the Vallecitos Atomic Lab & Livermore Lab. Questions whether facil siting meets U808 & NRC criteria. RYANL J House of Rep. 78/10/05 ip. 94043:178.
- 7812190169 Notification of 771028 meeting in Bathesda w/OE to allow 9E to give NRC its assessment of all NRC-lic activities at Vallecites as req by 771024 Show Cause Order.
 OALLER: K R Division of Operating Reactors. 77/10/26. 1p. 94381:161.
- 7811030259 Rept on 781017 sits visit to make preliminary observations of Oen Elec-proposed site investigation. Believes that until main scarp & sesoc rupture surface are located for mapped landslide complex the stability energies is questionable. ORECVES.J. T. JACKSON.R.E. Geosciences Branch. 78/10/27. 7pp. 94272:059.
- 7811070113 Responds to 781002 NRC request for add1 info re appl for addition to Tech Specs. Forwards clarification of term "Cold Bhutdown".

 CUNNINOHAM. 0. E. General Electric Co. 78/11/01. 4pp. 94043:301.

- 7812190178 Requests DOR provide proposed Fed Register Notice repting shutdown of GETR as abnormal occurrence. Myencl copy of previous FRN far Abnormal Occurrence for info. EIBENHUT. D. G. Division of Operating Reactors. 77/11/10. 4pp. 94301:108.
- 7811270169 Forwards comments from 781017 site visit to view trenching excavations of current GETR seismic investigation. For entl see ANO 7811030259.

 REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/11/11. 4pp. 94272:055.
- 7812180293 Notice of 781209 visit to facil in order to inspect tranches completed in the QETR site fault investigation.
 NELBON.C.C. Operating Reactors Branch 4 (Pre 790625). 78/11/27.
 3pp. 94265:219.
- 7812080131 Forwards info considered reportable under Section D2 of Lic TR-1. During 781101 Calibr of primary coolant screm & emergency cooling trip instructrip points indicated switches out of spec.

 DARMITZEL-R. M. General Electric Co. 78/11/29. 2pp. 94106:351.
- 7812140121 Forwards logs of the trenches at & near subj facil.Logs available in Central Files. DARMITZEL.R.M. General Electric Co. 78/11/29. 150pp. 94480:001.
- 7812180329 Forwards status rept of DBE review of peology as it relates to potential for surface faulting of GETR site. Data is incomplete & does not allow final conclusions. Encl request for add1 info. DENTON.H. R. Division of Site Safety & Environmental Analysis. 78/12/13. 9pp. 94357:389.
- 7812190020 Forwards NRC Order to Show Cause, which req that Gen Elec Test Reactor be placed & maintained safely in cold shutdown condition pending further order. QASE.E. Q Office of Nuclear Reactor Regulation, Director.
- 7812280297 Forwards rept to 781205-6 subj facil site visit to trenches & seismic enalysis. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/12/18. 299-74349:348.

- 7810230090 Forwards IE Inspec Rept#50-70/78-07 on 780907-08 during which no items of noncompliance were noted. CREME.J.L. Region 3. San Francisco. Reactor Operations Nuclear Bupport Branch. 78/09/20. 2pp. 94:69:181 Bupport Branch.
- --7810230092 IE Inapec Rept#50-70/78-07 on 780907-08 during which no items of noncompliance were noted. Major areas inspected included logs & records review & auditiesper[ments:LER follows: & independent inspec efforts.
 CANTER.H.L., MILLER.L.E.: CREWS.J.L. Region 3. Ben Francisco. Resitor Operations Nuclear Support Branch. 78/09/20. 400.
- 7811270121 Forwards IE Inspec Rept#50-70/78-08 on 780926-28 during which no items of noncompliance were noted. BRENCER.Q. B. Region 5. Ben Francisco. Reactor Construction & Engineering Bupport Branch. 78/10/19. 2pp. 94271:272.
- --7811270126 IE Inspec Rept#50-70/78-08 on 780926-28 during which no sitems of noncompliance were noted Major areas inspec incl: mode of primary heat exchanger, setamic restraints QA records & followup on previous inspec items.

 BISHOP, T. H., HAIST, D. P., HAYNEB, R. C. Region 5. San Francisco. Resctor Construction & Engineering Support Brench. 78/10/18. Spp. 94271: 274.
- 78:2:40070 Forwards IE Inspec Rept#50-070/78-09 on 78:004-05 during which no items of noncompliance were noted.

 800K-H.E. Region 5, Ban Francisco, Fuel Facility & Materials Bafety Branch. 78/10/31. 2pp. 94:127:356.
- --7812140072 IE Inapec Rept#80-070/78-09 on 781004-05 during which no items of noncompliance were noted. Major areas inspected: radiat safety organization, changes in radiat safety procedures, parsonnel exposure, survey instru & tour of facil. FIBH.R.F., RIEDLINGER, B.A., BOOK, H.E. Region 5, San Francisco, Fuel Facility & Materials Bafety Branch, 78/10/27, App. 74127: 358.
- U. Congressional/Executive Correspondence
- 7811210065 Responds to 781006 ltr to Dept of Energy re present status of sub, facile Desed on seismology & site geology evaluation continued NTR oper & activities authorized by LickSNM-960 were found to be acceptable.
 DIRCKS.W.J. Office of the Executive Director for Operations.
 78/11/13. 3pp. 94488:319.
- --7811210096 Responds to 781006 ltr to Mr Schlesinger re siting of subj facils. Requested info is being collected & will be sent as soon as data is available. Copy of 781006 itr has been forwarded to the NRC. BRATTON, J. H. Energy, Dept. of. 78/10/18. 1p. 94488:323.
- 7811240091 Responds to 781017 ltr by forwarding a copy of NRC's reply to Mrs DelFino's 781015 ltr to Chairman Hendrie. DIRCHS.W.J. Office of the Executive Director for Operations. 78/11/15. 1p. 94458:077.
- --7811940094 Forwards 781015 DalFino ltr to NRC & requests a complete report in duplicate re sub; facil hazards to safety & health. Requests to be informed of all related hearings. HAYAKAHA, S. I. Senate, 78/10/17. ip. 94458:081.
- --7811240096 Recommends that both subj facils remain closed until further info re health & safety(especially the discharge of tritium into the groundwater)& geotech data is made available to the DELFING, J. B. Affiliation Unknown. 78/10/15. 2pp. 94458:083

DOCKET 50-72 UNIV. OF UTAH RESEARCH REACTOR

- P. Operating license stage documents & correspondence
- 7810240006 Reply to 780725 ltr re Memphis State Univ Tech Spec re ANS 15.19 Admin controls. REID.R.W. Operating Reactors Branch 4 (Pre 770625). 78/10/10. App.

- P Operating license stage documents & correspondence
- 7811210002 Reminder that LiceR-33 for subj facil will expire on 790721. & renewal appl req timely filing Consideration will be reveiwed as part of evaluation. W/encl Lic Renewal Review REID R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/06. 7pp. 94482:001.
- 7812270401 Forwards Amend#13 to LickR-33 & Safety Eval Changing Specs EID.R.W. Deerating Reactors Dranch 4 (Pre 790625) 78/12/14 2pp 94232:321 in response to 760811 request REID R. W.

- --7812270409 Amend #13 to Lic #R-33. Changing fech Spec re-calibr surveillance of all inetry & deleting Tech Spec requirement for respiratory protec. Updates NRC organizational titles. REID.R.W. Operating Reactors Branch 4 (Pre 790623). 78/12/14 Spp. 94232:323.
- --7812270416 Seesty Eval supporting Amend #13 to Lic#R-33 Concludes amend will not be inimical to common defense & security or to pub health & safety. Office of Nuclear Reactor Regulation, Director. 78/12/14. 3pp. 94232: 328
- DOCKET 50-77 CATHOLIC UNIV. OF AMERICA REBEARCH REACTOR P. Operating license stage documents & correspondence
- 7810170186 In response to 780929 NRC ltr. Draft tech space for AGN-201 reactor have been reviewed & are acceptable JORDAN,E.D. Catholic Univ. 76/10/10, ip. 94270 046.
- DOCKET 50-03 UNIV. OF FLORIDA TRAINING REACTOR F. Becurity, medical, emergency & fire protection plans
- 7811070376 Accepts Arognaut res reactor security plan & rev. Requests that the basic plan & revisions be consolidated into one document for inclusion in the renewal lic. REID.R.W. Operating Reactors Branch 4 (Pre 770625). 78/10/12. lp 74043:282
- P. Operating license stage documents & correspondence
- 7810180081 Describes preparation of info for renewal of Facil Oper Lic #R-36. New BAR & Tech Spac are being prepared re change of fuel Final submission to NRC will be in June 1977.
 DIAZ. N.J. Florida, Univ. of, Gainesvills. 78/10/10. Spp. 94412: 292.
- 7812060149 Informs NRC effective 780901 MJ Chemien returned to UF Chairmenship of Dept of Nuc Engr Sciences.

 OHANIAN.M.J. Florids, Univ. of Quinesville, 78/11/30, 1p.
- G. Inspection reports. IE Bulletins & correspondence
- 7810110187 Ack receipt of 780918 its informing NRC of steps taken to correct violations noted during inspec#50-083/78-05.
 KENNA, N. B. Region Q. Atlenta, Bafeguards Branch. 78/10/09. ip. 03555: 344.
- -- 7810110196 Responds to Notice of Vialation from 780816 Physical Becurity Inspec which found that a reactor key was inserted welcoming inspec which round that a reactor key was inserted w/o operator present Daily charkout & reactor shutdown procedures will be corrected. DIAZIN.J., DHANIAN.H.J. Florida, Univ. of, Gainesville, 78/09/18. 2pp. 94069:133.
- --7B1011019B Forwards IE Inspec Rept#50-083/78-05 & Notice of Violation. KENNA, M. B. Region 3. Chicago: Befeguards Brench. 78/09/07. Rpp. 94049-136
- ---7810110801 Notice of Violation from inspec on 780817.
 * Region 3. Chicago. Safeguards Branch. 78/08/17. ip.
- --7810110204 IE Inspec Rept#50-083/78-05 on 780817 during which 1 item of noncompliance was noted.

 * Region 3, Chicago, Befaguards Branch. 78/08/17. 4pp. 94069: 136.

- DOCKET 30-87 WESTINGHOUSE CRITICAL EXPERIMENT F. Security, medical, emergency & fire protection plans
- 7810230141 Act receipt of 770919 & 771229 changes to Security Plan. Finds changes acceptable & containing proprietery info REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/09/29 ip.
- G Inspection reports, IE Bulletins & correspondence
- 7810190248 Responds to request for reply to IE DulletinN78-08 Bulletin is not applicable to subj facil & none of actions suggested were instituted ROTH, J.M. Westinghouse Electric Corp. 78/10/05. ip. 94413:342.
- 7811090043 Forwards IE Inspec Rept#50-087/78-05 on 780920-22 Inspec rept details wheld from pub distingure pursuant to 2.770. HIND, J. A. Region 3, Chicago, Office of the Director. 78/10/31. 200. 94040 062
- --7811090044 JE Inspec Rept#50-087/78-05 on 780920-22 during which no items of noncompliance were noted Areas inspected included. security plan & organization; access control alarm syst surveillance: radiological sabotage protec. CHRISTOFFER.Q.M. MADEDA,T.J., HIND.J.A. Region 3, Chicago, Office of the Director, 78/10/30 Ip. 94040.064

DOCKET 50-B9 GENERAL ATOMIC CO.

- F. Security, medical, emergency & fire protection plans
- 7812190145 Forwards current physical security plan in compliance U/regs.classified as "Natl Security Info" pursuent to certain DOE requirements Requests that werlier copies be destroyed, and new copies by withheld.

 MOWRY, M.R. General Atomic Co. (subs. of Gulf Dil Co.). 78/12/15. MOURY, N. R. lp. 94340 070.
- P. Operating license stage documents & correspondence
- 7812040243 Forwards Fed Register Notice containing Gen Atomic Co appl for facil export lic. DPL INGER, Q. Q. Office of International Programs, Director. 78/11/17 10 94415 354.
- --7812040249 Gen Atomic Co Appl for Facil Export Lic to auth export TRIGA Mark I res reactor u/thermal pur level of 100 Kilowatte to Morocco. DPLINGER. 0 G Office of International Programs. Director. 78/11/17. 2pp. 94419: 355.
- V Operator Examinations
- 7810300284 Finds proposed changes to reactor open requal prog-acceptable.Changes do not substantially decrease the frequency duration or scope of the prog. COLLINS.P.F. Operator Licensing Branch. 78/10/25. 1p. 94185:308.

DOCKET 50-94 ROCKUELL INTERNATIONAL RESEARCH REACTOR

- J. Insurance & indemnity information
- 7810270197 Forwards copies of Policy NF-12:Endorsements#75-83,85-89 & 94(Advanced Premium & Standard & Reserve Premium for CY1978) & Policy NF-93 Endorsements 75-79 and B3(Advanced Premium, Standard & Reserve Premium for CY1978. PIERCE, J. W. Rockwell International Corp. 78/10/19. 30pp. 94054-043

DOCKET 50-92 CORNELL UNIV. ZERO POWER REACTOR F. Security, medical, emergency & fire protection plans

7810260021 Forwards NRC Reg Quide 2. XX "Emergency Planning for Res Reactors". Request these documents be used in preparing emergency plan in appl for lic renewal. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/17. 49pp. 94372: 160

- G Adjudicatory correspondence
- 7812210517 Petition by NY Bt Energy Office for leave to participate as an interested state in proc re Cornell Univ Zero Pur Reactor St is acting to protec health safety & environ of NY citizens Cert of Svc encl SHAPIRO, N A New York, State of 78/12/04. 4pp 94407:330.
- P Operating license stage documents & correspondence
- 7810120038 Requests 20 year renewal of LickR-89. Complete appl will be forwarded at a later date. CODME.W D. Cornell Univ. 78/10/06. ip 94332:314
- 7812140065 Forwards Notice of Proposed Renewal of Facil Lic Present lic expires 781121. REID R. W. Opera EID.R.W Operating Reactors Branch 4 (Pre 790625). 78/10/27. 2pp. 94126:337.
- R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/28. 94126:339. --7812140069 Notice of Proposed Renewal of Fecil Lic#R~89 until 981121. REID, R. W 400
- 9. Inspection reports. IE Bulletins & correspondence
- 7812050286 Ack receipt of 781030 ltr informing NRC of steps taken to correct violations noted during inapec#50-97/78-02, #50-157/78-02 & #70-211/78-01. MARTIN. H. G. Region to Philadelphia, Safeguards Branch. 78/11/07 10 94202 321
- --7812050290 Responds to 781004 NRC ltr re deviation noted in Inspec Rep #50-97/78-02, #50-187/78-02 & #70-211/78-01 Corrective actions complete physical inventory & documentation finished CLARK.D.D. Carnell Univ 78/10/30. 1p. 94202:322.
- --7812050295 Forwards IE Inspec Repts#50-97/78-02.#50-157/78-02. #70-211/78-01 & Notice of Violation.
 MARTIN.W.G. Region 1. Philadelphia: Bafeguards Branch. 78/10/04 2pp. 94202:323.
- --7812050298 Notice of Violation from inspec on 780907-08 * Region 1. Philadelphia. Bafeguards Branch. 78/10/04. 1p. 94202 325
- --7812050304 1E Inspec Repts#50-97/78-02.#50-157/78-02.#70-211/78-01 on 780907-08 during which I item of noncompliance was noted: failure to perform complete physical inventory w/in required 12 months. SUMMERB, R. J. Regio Region i, Philadelphia, Bafeguards Branch. 78/10/04. 6pp. 94202:326
- --7812050304 IE Inspec Repts#50-97/78-02,#50-157/78-02,#70-211/78-01 on 780907-08 during which I Item of noncompliance was noted: failure to perform complete physical inventory w/in required 12 months. BUMMERS, R. J. Region 1, Philadelphia, Bafeguards Branch 78/10/04.

DOCKET 50-98 UNIV. OF DELAWARE REBEARCH REACTOR

- P. Operating license stage documents & correspondence
- 7810230145 On 780826, DELU removed all components of its AGN-201 nuc reactor. Burveys of reactor room & reactor components show no removable containination levels in excess of background. DELU requests final inspec per termination of facil.
 RUSSELL.T.W. Dejaware, Univ. of. 78/10/12. 3pp. 94164:200.

DUCKET 50-99 BABCOCK & WILCOX TEST REACTOR F. Security, medical, emergency & fire protection plans

7810230147 States that NRC review of physical security plan & revs is complete, Finds plan acceptable. Requests that vendor plan as single document for inclusion into lie by 790531 in loose-leaf format REID R. W. EEID.R.W. Operating Reactors Branch 4 (Pre 790625), 78/10/06, 2pp. 94194:343,

G. Inspection reports: IE Bulletins & correspondence

- 7812080215 Forwards Inspec Rept#50-099/78-03 & Inspec Rept#50-013/78-03 on 780918-22 during which no items of noncompliance were noted.

 8UTHERLAND. J. T. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch, 78/10/30 2pp. 94137.074,
- --7812080219 IE Inspec Rept#50-099/78-03 & IE Inspec Rept #30-013/78-03 on 780918-22 during which no items of noncompliance were noted. Major areas inspec incl radiat protec procedures & posting & labeling DAVIS.J.H Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 78/10/30. 7pp.
- 7812200156 Concurs that inspec rept contains no proprietary info & agrees to placing it in NRC PDR. ENDELDER.T.C. Babcock & Wilcox Co. 78/12/08 ip. 94156:354.
- 7810270103 Forwards IE Inspec Repts#50-99/77-4 & #50-13/77-4 on 771129-771201 during which no items of noncompliance were noted. KENNA-W.B. Region 2, Atlanta-Safeguards Branch. 77/12/27. 2pp. 94099; 297.
- --7810270113 IE Inspec Repts#30-13/77-4 & #50-99/77-4 on 771129-771201 during which no items of noncompliance were noted Major areas inspected included physical security prog. Security plan. Security organization. Surveillance, Access controls. JUNNER, J H. Region 2. Atlanta, Office of the Director. 77/12/22. 19. 94059 288
- 7812050001 Forwards IE Inappc Repts#50-99/78-2.#50-13/78-2 & #70-824/78-10 on 780911-15 & Notice of Violation. 8UTHERLAND.J.T. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/10/27. 2pp 94200:001.
- --7812050002 Notice of Violation from insp on 780911-15.
 4 Region 2, Atlanta, Fuel Facility & Materials Bafety Branch.
 78/10/27. ip. 94200:003.
- --7812030005 IE Inspec Repts #30-99/78-2, #30-13/78-2 & #70-824/78-10 on 780911-15 during which i item of noncompliance was noted: storage of flammable liquids in containers that are not eafety approved cans.
 PERROTTI.D.U. Region 2, Atlanta, Dffice of the Director. 76/10/27. 17pp. 94200:004.
- 7812200158 Forwards Inspec Repts#50-13/78-4 & #50-99/78-4 on 781115-17 during which no Items of noncompliance were noted. LONG.F.J. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78/12/01. 2pp. 94156:355.
- ~~7912200161 IE Inspec Repts #50-013/78-04 & #50-099/78-04 on 781115-17 during which no items of noncompliance were noted Hejor areas inspected incl. logs & records/reviews & audits/ experiments/refusing/procedures & IE Circular review HINCKLEY, D. Q., MCHENRY, T. J., DANCE, H. C. Region 2, Atlanta, Office of the Director. 78/12/08. Spp. 94136:357.

DOCKET 50-104 DREGON STATE UNIV.

- A. Application/construction stage documents & correspondence
- 7811200009 Forwards FR notice of proposed issuance of orders authorizing dismantling of facil disposition of component parts & termination of facil lic.per 780913 appl. (w/encl ANGW7811150247.)
 REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/31. ip. 94215:256.
- a. Operating license stage documents & correspondence
- 7812270193 Forwards Dismantling & Disposal Plan for AGN-201 training reactor open under LickR-51. Reactor is to be transferred to Northwestern Univ. HANG.C.H., POPOLVICH.M. Dregon State Univ. 78/12/18. 2pp.: 74018:059.

- G. Inspection reports, IE Bullatins & correspondence
- 781207004: Forwards Inspec Rept#30-106/78-02 on 781024-26 during wh no itams of noncompliance were noted CREMS.J L. Region 5. San Francisco. Reactor Operations Nuclear Bupport Branch. 78/10/31. 2pp. 94134.069
- --7812070045 IE Inspec Rept#30-106/78-02 on 781024-26 during which is tams of noncompliance were noted Major areas inspec incl: operation.logs & records.procedures.training & survefilence. HORRILL.P. J., CARLSON.J. D., STERNBERG.D. M. Region 5. Sen Francisco, Reactor Operations Nuclear Support Branch. 78/10/31 2pp. 94134 071.
- 7811150247 Notice of proposed issuance of orders authorizing dismenting of facil at Oregon St Univ.disposition of component part of facil & termination of facil LickR-51.
 REID.R.H. Operating Reactors Branch 4 (Pre 790625) 78/10/31.
 74273:044
- DOCKET 50-112 UNIV. OF OKLAHOMA RESEARCH REACTOR
 P. Operating license stage documents & correspondence
- 7810110167 Requests 20-year extension/renewel of NRC Lic#R-53. Will furnish documentation by mid-Nov 1978. UPTHEGROVELW R. Oklahome. Univ. of. 78/10/06 ip 94069 090.
- 7810310297 Responds to itr re renewal of AON-211 Lic #R-53.Forwards new guidelines re emergency planning for res reactors dev since 780528 NRC itr whenci dreeft Reg Guide 2 XX & ANB Draft Standard for Emergency Planning for Res Reactors.
 REID R.H. Operating Reactors Branch 4 (Pre 790625). 78/10/06. 49pp. 94089.005.
- 7811210212 Notice of proposed renewal of Facil Lic#R-53 for operation of AON-211 Reactor located at UDK Renewal would extend expiration date to 981229 REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/02 94487:142.
- 7811290310 Forwards "Notice of Proposed Renewal of Facil LiceR-53 P AON-211 Reactor". Although expiration date for lic is 781229, existing lic will not be considered expired until appl has been finally determined.
 REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/31/02. 94193:247.
- --7811290315 "Notice of Proposed Renewal of Facil Lic" for Lic#R-63 oper of AON-211. Renewal would extend expiration data to 781229.

 REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/11/02.4pp. 94193.249.
- 7811090082 Informs NRC of reassignment to Martin Jischke of responsibilities re univ reactor & nuc matl activities carried out under Lic SNM-1397.

 UPTHEOROVE.W.R. Oklahoma: Univ. of: 78/11/03 ip. 94041-291.
- Q. Inspection reports: IE Bulletins & correspondence
- 7810130245 Forwards copy of IE Inspec Repts#50-112/78-02 & 70-1430/78-02 on 780821 & 22 during which no items of noncompliance were found.
 HIND.J.A. Region 3, Chicago Safeguards Branch. 78/10/05. 2pp. 74079:176
- --7810130247 IE Inspec Repts#50-112/78-02 & 70-1430/78-02 on 78082: during which no items of noncompliance were noted. Areas inspected incl:nuc metl control & accounting, inventory, shipping, receiving, storage & controls. Wo hept. # Region 3, Chicago, Bafeguards Branch, 78/10/04. ip. 94079-178.

٠

DOCKET 90-113 UNIV OF ARIZONA RESEARCH REACTOR
P. Operating license stage documents & correspondence

- 7811D30224 Forwards Amend@13 to Facil Oper Lic@R-52 revising Tech Spece as requested in 770714 ltr w/sePety Evaluation REID.R W Operating Reactors Branch 4 (Pre 790625). 78/10/12. 2pp. 02724-252
- ~-7811030828 Amend#13 to Fecil Oper Lic#R-52 revising Tech Space re editorial changes to incorporate currently used terminology, onsite org & position titles increase of markeum insertion reactivity & mod of instru oper requirements REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/12. 17pp. 02724.254
- --7811030232 Serety evaluation supporting Amend 13 to License R-52 concluding that proposed Tech Spec changes are acceptable and do not reduce any of the serety margins.

 ** Office of Nuclear Reactor Regulation, Director.

DOCKET 50-116 10WA STATE UNIV. RESEARCH REACTOR

- P. Operating license stage documents & correspondence
- 7812180303 Notifies licensee of expiration of Oper Licen-59 for Argonaut-Type Model UTR-10 on 791012 & forwards specific items that must be addressed in renewal appl REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/12/07. Bpp. 94343:353
- 8. Reportable occurrences, LERs & related correspondence
- 7811060073 Surmarizes File documentation re elimination of inspec of Shim-Sefety Rod Position Potentiometer Rescons: successes of hardware mod is proven.inspec procedure was harmful, elimination of procedure supported by Radiat Safety Comm. HENDRICHEGON.R. I Lowe State Univ. 78/10/28. 2pp. 94423:335.
- --70:1060074 Reportable Occurrence on 780914:UTR-10 Shim-Bafety Rod failed to insert during manual screm. due to loose position potentiometer mounting but. Mod: lock washer added to potentiometer mounting hardware.

 HENDRICKSON, R lower State Univ. 73/09/27. 3pp 94423:357.

DOCKET 50-123 UNIV. OF MISSOURI RESEARCH REACTOR
P Operating license stage documents & correspondence

78:1280210 Forwards specific requirements reviewed in appl for lic renewal. Renewal of lice**re? req submission of an appl that demonstrates that reactor can continue to be operated safely through the term of the renewal.

REID.R. W. Operating Reactors Branch 4 (Fre 790625). 78/11/14. *6pp. 94013:281.

- Q Inspection reports. IE Bulletine & correspondence
- 7811290393 Porwards IE Inspec Rept#50-123/78-04 on 780921-22 during which no items of noncompliance were noted.

 DAVIS, A. B. Region 3. Chicago, Fuel Facility & Materials Safety Branch 78/10/23 2pp. 94181:182.
- --7811290397 IE Inspec Rept#50-123/78-04 on 780921-92 during which no items of noncompliance were noted Major areas inspected incl: emergency planning activities. coordination w/support agencies.training & internal audits.

 AXELSON.W.L. Region 3, Chicago, Fuel Facility & Materiels Bafety Branch. 78/10/20 4pp. 94181.184.

ORCHET 50-128 TEXAS ALM UNIV. RESEARCH REACTOR

G. Inspection reports, IE Bulletins & correspondence

- 78ii170ii1 Forwards IE Inspec Rept#50-120/78-02 & Notice of Violation. MADBEN-0 L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 78/10/26. 2pp 94047-101.
- --781170314 Notice of Violation from inspec on 780911-15.Ltr of 710823 from AEC to TXAM also encl. HADBEN.Q.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 78/10/06. 3pp. 94047:133.

- --7811170119 IE Inspec Rept#50-128/78-02 on 780911-15 during which 2 items of noncompliance were noted failure to post High Radiation Area & failure to post notice to workers MURRAY-B., MADSEN, O.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch, 78/10/04. 9pp. 94047-136
- 7812070001 Forwards IE Inspec Rept#50-128/78-03 on 781107-09.

 MADEEN.O.L. Region 4, Dallas, Reactor Operations Nuclear Support
 Branch. 78/11/20. 1p. 94134:073.
- --7812070002 IE Inspec Rept#50-128/78-03 on 781107-09 during which no items of noncompliance were noted Major areas inspec incl: implementation of approved physical security plan reprotection of SNM, security organization & access control. MARD.J.J. Region 4. Dallas. Reactor Operations Nuclear Support Branch EVANS.C.A. MADBEN.Q.L. Region 4. Dallas. Dffice of the Director. 78/11/20. ip. 94134-076

DOCKET DO-131 OMAHA VET. ADMIN HOSP. RESEARCH REACTOR
P. Operating license stage documents & correspondence

7812180371 Forwards specific items that must be addressed in renewal of Oper Licar-37 which expires 790624. Gen requirements are given in 100FR80.31.35 & 73.
REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/12/07.
10pp. 94358 188

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIY 3

7812150054 Forwards updated svc list pursuant to agreement to discuss discovery procedures at 781114 meeting. WATTB.M.J. McCutchen.boyle.Brown & Emersen. 78/11/21. App. 94211-025.

- J. Insurance & indomnity information
- 7812130002 Forwards Amend#20 to Indomnity Agreement#8-21. CRANE-P.A. Pacific Gas & Electric Co. 78/12/05. ip. 94307:254.
- --78:2:30008 Amend#20 to Indemnity Agreement#8-2:, adding new Article VIII.covering deferred premiums & submission of financial statements.

 8ALTZMAN.J. Antitrust & Indemnity Group. BONNER, J. F. Pacific Gas & Electric Co. 78/12/05. 2pp 94307:255.
- P. Operating license stage documents & correspondence
- 7812040276 Requests registration as user of shipping packages.Cert#6038 & 6144 Quality Assurance Prog will be executed accordingly.

 CRANE.P.A. Pacific Gas & Electric Co. 78/08/10. ip. 94372:282.
- 7810240111 Forwards copies of appl for amend to DPR-7 open lic reminor change in frequency requirement for nuc safeguard systesting & other minor admin changes. As a Class 2 amend.fee is \$1200 & is forwarded.

 CRANE.P.A. Pacific Oss & Electric Co. 78/10/20. ip.
- --7810240113 Requests Facil Oper Lic DPR-7 be amended by making admin changes to Tech Bpecs appended to lic Changes set forth incl changes in frequency of performing Nuc Befaguard Bys Testing & adding Quality Control to Plant Staff Rev Comm.

 SHACKLEFORD.B., CRANE,P.A., MORRISSEY,J.C. Pacific Oas & Electric Co. 78/10/12, 17pp.
- 7810310207 Forwards "Guarterly Status Rept of Investigations & Mods. 780701-780930. Rept#19". Topics incl geologic & seismologic investigations esismic design review. purchase & installations of seismic mods. GROVE, P.A. Pacific Qua & Electric Co. 78/10/27. 2pp. 94090:326.
- 7811280439 Confirms 781024 conversation w/J Carroll re the PQ&E decision to suspend until spring the present cycle of drilling oper because of high winter drilling costs & lack of permission from land owner to dig a trench.
 ROOMSY.V.L. Deerating Reactors Branch 3 (Pre 790625). 78/10/30. 19. 94380; 135.
- 7812130134 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out math. W/encl Registration Form & List of Locations. MILLER-J.R. Assistant Director for Site & Safeguards (Pre 791030). 78/11/13. 5pp.

2180250 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for JR's(NJREG-0473) & "Preparation of Radiological Effluent och Specs for Nuc Pur Plants" (NUREG-0133)
IMES-B.K. Assistant Director for Engineers & Projects (Pre-

2070314 Notification of 781113 meeting w/Dutch & POSE & w/Dutch on 11117 to provide technical info re unit & ref plant for etch 54 MWE natural circulation Dadewaard W/list of

tendess & question encl MMEY,V.L. Operating Reactors Branch 3 (Pre 790625) 78/11/28 94084: 325

12B0095 Emphasizes importance of submitting accurate & complete info.

NRC by licensees & applicants Info submitted must be the stantiated by data & calculations Licensee must notify to fample inaccuracies or enforcement action will result AVIS. J.O. Office of Inspection & Enforcement, Office of the AVIB.J.O. Office of Inspection & Enf rector 78/12/06. 2pp. 03555:311.

inspection reports. IE Bulletins & correspondence

1240092 Forwards 1E Inspec Rept#50-133/78-11 on 780828-31 during lich no items of noncomplience were noted. IEMS.J.L. Region 5. Ban Francisco. Reactor Operations Nuclear Japont Branch. 78/09/18. 2pp.

310240094 IE Inspec Rept#50-133/78-11 on 780828-31 during which no items of noncompliance were noted Major areas inspected included outage activities.records mgt sys followup & Pollowup on Bulletins & Circulars.

MCEBBKR.J.D., JOHNBTON.Q.W., CREWB.J.L. Region 5, San Francisco.

Reactor Operations Nuclear Support Branch. 78/09/18. Spp.

3200255 Forwards IE Inspec Rept#50-133/78-12 on 780821-24 during nich no items of noncompliance were noted Encl contains 790 info & is w/held from public disclosure. DROERHAUG.L.R. Region 5. Ban Francisco, Safeguards Branch. 3/10/11. 2pp. 03555:204

0230221 IE Circular#78-17-Inadequate Quard Training/Qualification & elsified Records Discusses incidents of qualification ecords falsification & recommends action to prevent CUFFENCE.

Office of Inspection & Enforcement, Office of the Director. 3/10/13. App. 94181:356.

0230316 Forwards IE Circular#78-17. (See AND: 7810230221.Docket 0-313,781013) 08ELMEN.R.H. Region 5. San Francisco. Office of the Director 8/10/13. 1p. 94166:347

1150007 Forwards IE Circular 78-18. NGELMEN,R H. Region 5. Sen Francisco, Office of the Director. 8/11/06. lp. 94112:301.

2190194 Forwards IE Inpsec Rept#30-133/78-13 on 781023-26 during hich no items of noncompliance were noted. DOK-H.E. Region 5. San Francisco, Fuel Facility & Materials Gafety ranch. 78/11/17. 2pp. 94381:040.

812190197 IE Inspec Rept#80-133/78-13 on 781023-26 during which no items of noncompliance were noted. Major areas inspected incl:emergency planning radial environ procedures & radiat protec training.
FISH,R.F. Region 5, San Francisco, Office of the Director.
78/11/17. 9pp. 94381:042.

2270450 Forwards IE Inspec Rept#50-133/78-14 on 781113-15 during hitch no items of noncompliancs were noted REWGJL. Region 5. San Francisco, Reactor Operations Nuclear upport Branch. 78/11/22. 2pp. 94015:351.

B12270456 IE Inspec Rept#50-133/78-14 on 781113-15 during which no

titems of noncomplience were noted. Major areas inspected inclicutage activities.pipe support surveillance.calibr & followup on IE Bulletins & LERS.

CANTER.H.L., MORRILL.P.J., WDEBENER.J.D. Region 5, Sen Francisco. Reactor Operations Nuclear Support Branch. 78/11/22. 5pp.

1300663 Forwards 16 Bulletin#78-12A.suppl to 16 Bulletin 78-12. NGBLKEN.R.H. Region 5, Ban Francisco, Office of the Director B/11/24. Ip.

Bii300055 IE Bulletin#78-12A.suppl to IE Bulletin 78-12 modifying requirements to IE Bulletin 78-12 re-info on weld matls used shall be submitted w/in 120 days & correlation of specific heat to weldments is not req.

• Office of Inspection & Enforcement, Office of the Director. 78/11/24. App. 94127:100.

7812290030 Forwards IE Bulletin 70-14. ENOB_KEN.R H Region 5. San Francisco. Office of the Director 78/12/19 ip 06911 001

R Periodic operating reports & related correspondence

7810180123 Forwards Monthly Open Rept for Sept 1978.
RAYMOND, W. A. Pacific Gas & Electric Co. 78/10/09 1p 94140 257

--7810180125 Monthly Oper Rept for Sept 1978 B1ERBAUM. Q A Pacific Gas & Electric Co 78/10/04 4pp 94140 258

7811130146 Forwards Monthly Oper Rept for Oct 1978 RAYMOND, W A Pacific Gas & Electric Co. 78/11/10 1p 94272 267

--7811150149 Montly Oper Rept for Oct 1978 BIERBAUM, G A Pacific Gas & Electric Co 79/11/01 4pp. 94272 268

7812130310 Forwards Monthly Open Rept for Nov 1978
RAYMOND, H. A. Pacific Gas & Electric Co. 78/12/08 1p. 94021 340

--7812150311 Monthly Oper Rept for Nov 1978 GETTY, B C Pacific Gas & Electric Co 78/12/01 4pp

B Reportable occurrences. LERs & related correspondence

7810180028 Forwards LERW78-003/017-0 CRANE, P. A. Pacific Oas & Electric Co. 78/10/11 1p 94195 193

--7810180035 LER#78-003/01T on 780912 during cald shutdown. #3 fire/low pressure pump was operated but would not reseat rendering it inoperable Caused by valve which was installed horizontally instead of vertically. REDEKER, S. J. Pacific Oas & Electric Co. 78/10/11 lp 74195 194

DOCKET 50-134 WORCESTER POLYTECH INST. REBEARCH REACTOR V Operator Examinations

7811240038 Requests sched of operator examination in Jan 1979 for 3 persons Formal appl & Pacil approval will be forwarded upon completion of training prog WILBUR, L. C. Worcester Polytechnic Inst. 78/11/10 ip. 94437: 247

DOCKET 50-142 UCLA TRAINING REACTOR P. Operating license stage documents & correspondence

7812080099 Forwards ltr from Director of UCLA Los Angeles Nuc Energy Lab re items in 780922 NRC ltr.W/o ltr. EVRAETS.J.C. California, Univ. of, Los Angeles 78/12/01. ip 74109:008

O Inspection reports. IE Bulletins & correspondence

7812270421 Forwards Inspec Rept#50-142/78-03 on 781030-31 & Notice of

Violation W/o encl. NORDERHAUG, L. R. Region 5. Ban Francisco, Bafeguarda Dranch 78/12/18. 2pp. 94312:328.

DOCKET 50-146 BAXTON NUCLEAR EXPERIMENTAL FACILITY J. Insurance & indemnity information

7812010127 Forward: Endorsement#60 & 69 to Seion NELIA Policy NF-107. States Endorsement#60 amended:advance premium \$425 & standard premium & reserve premium \$284, 75. Endorsement #66 amended:stendard premium & reserve premium \$227. 80 W/encl. MONTODMERY.C R. General Public Utilities 78/11/27. Ip 94418:058

DOCKET 50-147 ROCKWELL INTL CORP CRITICAL FACILITY
J. Insurance & indemnity information

7810270197 Forwards capies of Policy NF-12 Endorsements#75-83.85-89 k 94(Advanced Premium & Standard & Reserve Premium for CY1978) k Policy NF-93 Endorsements 75-79 and 83(Advanced Premium 8tandard & Reserve Premium for CY1978.
PIERCE.J. W. Rockwell International Corp. 78/10/19 30pp 94054.043

DOCKET 50-148 UNIV. OF MANBAS REBEARCH REACTOR
P. Operating license stage documents & correspondence

- 7812040071 Forwards Amend#12 to Facil Lic#R-78 for res reactor changing Tech Spec re surveillance of rod magnets. REID/R.W. Operating Reactors Branch 4 (Pre 790625) 78/11/16. 2pp. 94455:075.
- --7812040074 Amend#12 to Facil Lic#R-78.changing Tech Spac re **surveillance of rod magnets. REID;R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/16. 5pp. 94455:077.
- --7812040079 Sefety Eval supporting Amend#12 to Facil LiceR-78.Concludes amend would not be inimical to pub interests.

 Operating Reactors Branch 4 (Pre 790625), 78/11/16 2pp. 94455.082
- Q. Inspection reports. IE Bulletins & correspondence
- 7812060324 Forwards IE Inspec Rept#50-148/78-0) & Notice of Violation. MADEKN.Q L Region 4. Dellas. Reactor Operations Nuclear Support Branch. 78/10/13. 2pp. 94329:344.
- --7812060326 Notice of Violation from inspec on 781004-06. * Region 4. Dallas, Reactor Operations Nuclear Support Brench, 78/10/13 1p. 94329, 346.
- --7912060332 IE Inspec Rept#50-148/78-01 on 781004-06 during which 1 item of noncompliance was noted: fuel elements were removed from core out of order DICKERBON.M W. Region 4. Delias. Reactor Operations Nuclear Support Branch. 78/10/13. App. 94329:347
- 7811170289 Ack receipt of 781026 ltr informing NRC of steps taken to correct deviations noted in Inspec Rept#30-148-78-01.Finds that add1 info is reg. MADEEN, Q. L. Region 4. Dallas. Reactor Operations Nuclear Support Branch. 78/11/02. ip. 94044:235.
- --7811170293 Responds to 781018 NRC ltr re violation noted in Inspec Rept#50-148/78-01.01d fuel unloading procedure has been sugerseded. KRAFT.D.C. Kanass, Univ. of. 78/10/26. 1p. 94046:236.
- 7812060311 Act receipt of 781026 & 781113 ltrs informing NRC of steps taken to correct violations noted during inspec #30-148/78-01.

 MADSEN 9, L. Region 4, Dallas, Reactor Operations Nuclear Support Branch, 78/11/20, 1p. 94332:012.
- --7812060319 Supple info contained in 781026 ltm. There has been a check of procedures to see that all superseded procedures are clearly marked. Marking superceded procedures should avoid repetition of generic prob of oper w/old procedures. KRAFT.D. C. Kansas. Univ. of. 78711713. ip. 94332:013.

DOCKET 50-155 BIQ ROCK POINT NUCLEAR PLANT F. Security, medical, emergency & fire protection plans

- 7812130161 Forwards rev security plans for subj facils as requested by NRC.Plans withheld tref 10CFR2.7901. HDFFMAN.D.P. Consumers Power Co. 78/12/08. 1p. 94309:120.
- P. Operating license stage documents & correspondence
- 78:01:01:04 Forwards fire protection plan describing fire protection administration controls & fire barrier tests. HOFFMAN, D. P. Consumers Power Co. 78/10/06. Ip. 94069: 267.

- 7810190218 Forwards ejectric diagrams omitted from 780808 package. Set of aperture cards advanced directly to R Silver HDFPHAN,D P. Consumers Power Co. 78/10/10. 1p. 94415.191.
- 7810310027 Informs that for SEP normal channel of oral communication will be followed, but to expedite reviews direct oral communication between subj facil staff & members of SEP branch is encouraged.

 ZIETANN.D L. Operating Reactors Branch 2 (Pre 790625). 78/10/10. 2pp. 94094 347.
- 7810160097 Informs of delay in providing NRC w/info re environ qualification of safety-related equip due to slow review of tables presented.

 BIXELP A Consumers Power Co. 78/10/11. 1p. 94004:221.
- 7810250065 Discusses use of continuous control rod drive feature during power operation. Concludes that ability to reliably verify coupling integrity is important. Change does not supersede or replace 741101 Tech Specs change request.

 81XEL+D A. Consumers Power Ca 78/10/19. Rpp. 07587-001.
- 7811090039 Forwards AmendW21 to Facil Oper LicMDPR-6 for subj facil. Amend changes Tech Bpecs as requested in 780517 ltr by incomponating requirements of 10CFER50 Append J for periodic test schedule & formula for reduced pressure leak rates. ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/20. 2pp. 94040 048.
- --7B11090071 Amend#21 to Facil Oper Lic#DPR-6 changes Tech Spece to incl periodic test schedule & formula for reduced pressure leak rates. ZIEHANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/20. 4pp 94040:050.
- --7Bi1070079 Safaty Eval by Ofc of Nuc Reactor Reg Supporting Amend#21 to Lic#DPR-6 of subj facil. Amend chamges Tech Specs reperiodic test schedule & formula for reduced pressure leak rate. Concludes issuance of amend is security & health safe.

 **Office of Nuclear Reactor Regulation: Director. 78/10/20. 3pp. 74040:034.
- --7811090088 Natice of Issuance of Amend#21 to Feril Oper Lic#DPR-6 IEMANN D L. Operating Reactors Branch 2 (Pre 790625). 78/10/20. 2pp.
- 7811210172 Eval of cable splices in reactor containment as referenced in 780224 submittal has been completed Splicing matl may be inadequate to preclude failure of LOCA. Plant is shut-down & splices are being repaired.
 FDQ0.H.C. Consumers Power Co. 78/10/23. 1p. 01791:057.
- 7810270075 Responds to 780817 NRC ltr requesting review of initial eval of 8 SEP topics. No errors were identified during review. Review rept entl. HOFFNAN.D.P. Consumers Power Co. 78/10/24. 23pp. 94057:169.
- 7811010165 Forwards add1 \$2,800 fee for consideration of license amend request dtd 780517.

 BIXEL, D.A. Consumers Power Co. 78/10/26. 1p. 94091:207.
- 7811130047 Requests add1 info re EBF switchover from injection to recirculation mode.isolation of reactor safety protec sys from non-safety sys B engr safety features.(EBF) sys logic & design.
 ZIEFANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/26.
 3pp. 94010:231.
- 7811030277 Forwards requests for add1 info re fire protection per 781010-13 site visit Response desired by 781113. LAINAS.Q. Plant Systems Branch (Pre 791030). 78/10/27. 9pp. 02719:346.
- 78:1020212 Forwards add1 description of Reactor Physics Methodology of subj facil for discussions leading to issuance of Amend#15 to DPR-6.

 BIXELD A. Consumers Power Co. 78/10/30. ip. 94287:137.
- --7811020218 Describes methods used in physics model dev by CPC included descriptions of techniques used in generation of input & modeling of core & comparisons of plant data to results generated by physics model.

 4 Consumers Power Co. 78/08/25. 61pp. 94257:138.
- 7811060084 Notifies NRC of possible deficiency found in analysis for very small break LOCA, but which is not considered reportable occurance under tech speca.

 BIXEL, D. A. Consumers Power Co. 78/10/31, 2pp. 94422; 120.

DOCKETED ITEMS

- 7811130167 Notifies applicant of 781128 NRC-sponsored seminar re Model Radiological Effluent Tech Specs for Nuc Pur Plants Encl w/Seminar Info Sheet(to be completed & returned by 781117) & Proposed Agenda KEPPLER, J Q Re Region 3. Chicago. Office of the Director 78/11/07 6gp. 03553: 215.
- 7811150158 Forwards proposed change to Tech Specs for License BPR-6. incorporating requirements implementing 10CFR50 App 1 per NRC 780711 1tr BIXEL.D. A. Consumers Power Co 78/11/13 18pp 94242:216.
- 7811280430 Forwards draft Sys Eval Prog Safety inputs re Topic VIII-3 A Station Battery Test Req Requests they be transmitted to
- DAVIG.O.K. Systematic Evaluation Programs Branch (Pre 790625) 78/11/14. 23pp 94381 119 7811270140 Forwards names of attenders at meeting on 781116 re site geologic & geotech features at subj facil W/att agenda & Items to be reviewed
- Operating Reactors Branch 2 (Pre 790625) 78/11/15 ZIEMANN.D L D 3pp. 94271:327
- 7812150173 Natice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out matt. W/encl Registration Form & List of Locations.
 MiLER.J. R. Assistant Director for Site & Bafeguerds (Pre 791030). MILLER, J. R. As 78/11/15, 5pp.
- 7812180264 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for BWR's(NUREO-0473) & "Proparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133) W/o encl AND: 7811280104 & 7811270180.

 ORIMES-B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp.
- 7812060377 Ack receipt of 780714 tech info. Forwards request for eddl info based on review & site visit. Response requested by
- Operating Reactors Dranch 2 (Pre 790625). 78/11/20. ZIEMANN. D. L. 10ap. 94331 318
- 7811270094 Forwards req ECCS ring spray sys design eval*Big Rock Point Core Spray Spranger & Steam Baffle Design Rept."
 BIXELD.A. Consumers Power Co. 78/11/21. Ip. 94437:119.
- --7811270099 Forwards "Big Rock Point Core Spray Sparger & Steam Baffle Design Rept" & append 3&4. Rept describes improved flow distrib characterisics. Recommends confirmation test be gerformed prior to installation. LEGATE, R. E. General Electric Co NEDC-21974, 78/11/27, 500pp. 94437: 120.
- 7812040220 Responds to 780522 NRC 1tr requesting add1 info relating to empineered safety features available to mitigate consequences of postulated fuel handling accident inside containment at subj facility.Related correspondence. BIXEL.D.A. Consumers Power Co. 78/11/29, 12pp 94452: 94452: 295.
- 7812070215 Forwards technical justification for next proposed containment integrated leak rate test (ILRT) in 1980-1981. As a result of successive leak rate uncountered, ILRT considered to be first ILRT failure.
- BIXEL, D. A. Consumers Power Co. 78/11/29, 3pp. 03555:101. 7812110011 Discusses possible dangers of LOCA in containment purging
- during normal plant open. Requests either commitment to limit purging or justification for continuing. W/encl ANO: 47812080207. ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/29. Bpp. 94339; 237.
- 7812050224 Responds to 780906 request for info re wafety-related elected equip qual using NRC stendard data format. Equip addressed is that which will ensure safe shutdown during LDCA & main steam line break, or is subj to hostile environ due to these. BIXEL, D. A. Consumers Power Co. 78/11/30. 46pp. 94201:152.
- 7812130281 Reviews 780307 submittal & concludes feedwater trip on high reactor level is not necessary to assure safe oper of subj Pacil. ZIEMANN. D. L. Operating Reactors Branch 2 (Pre 790525). 78/12/01. 2pp. 94291:338.
- --7812130286 Safety Eval of the proposed actions re BWR feedwater pump trip on reactor high level.Concludes that util decision not

- 78:2280:18 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result DAVIS.JO Office of Inspection & Enforcement, Office of the Director 78/12/06 2pp 94310-213
- 7812120182 Informs 1980 of filter testing condition in respiratory protec equip which is different from regulation in Reg Ouide 8.15, but which meets the regulatory requirements. BIXEL, D.A. Consumers Power Ca. 78/12/08 ip. 94277.082.
- 7812130133 Forwards responses to 781120 NRC request for add1 info re Fire Hazerds Analysis & to NRC staff positions derived from 781010-13 fire protec site visit flod implementation sched will be submitted by 790115 HOFFMAN, D. P. Consumera Power Co. 78/12/08 22pp 94015 127
- penstrations of reactor containments to complete evaluation ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625) 78 4pp 94211 339 7812150085 Requests add1 info from SEP licensees re glectrical 78/12/08
- 7812210091 Forwards NUREG-0485, Vol 1. No 2 "Status Summary Rept-Bys Eval Prog " W/o encl ZIEMANN, D. L. Op 2pp. 94269.154 Operating Reactors Branch 2 (Pre 790625) 78/12/08.
- 7812270039 Requests addl into to complete review of "Big Rock Point LOCA Analysis Using Erron Nuc Co Non-Jet Pump BUR Evel Model Large Break Example Problem" XN-NF-78-25 Revi Info incl. emergency condenser reactor water level & choked flow. ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625) 78/12/14
- 7812260045 Burmary of 781116 meeting w/util to discuss SEP review of site geology & geotechnical data List of attendess encl CHENO,T M. Bystematic Evaluation Programs Branch (Pre 790625) 78/12/15 4pp. 94021:040
- 7812260212 Forwards rev tables describing environ qual of subj facil aquip.Corrected tables represent Attach 2 of 781130 ltr. BIXEL, D.A. Consumers Power Co. 78/12/20 6pp. 94160:177.
- 7812280134 Responds to 781208 request for add) info re SEP Topic VIII-"Electrical Penetrations of Reactor Containments " Requires tabulation of info selected by NRC in docket search by early Jan to grapare reply within schedule.
 BIXEL, D.A. Consumers Power Co. 78/12/22 Ip. 94310:339.
- G. Inspection reports, IE Bulletins & correspondence

6pp. 94160.211

- 7810260179 Forwards IE Insp Rept 50-155/78-05 on 780829-0901 & notice of violation DAVIS, A. S. Region G. Chicago, Fuel Facility & Materials Safety Branch. 78/09/18. 2pp. 94057:284.
- --7810260180 Notice of violation from insp on 780829-0901. * Region 3. Chicago: Fuel Facility & Materials Safety Branch. 78/09/18. 1p. 94057: 286.
- --7810260183 IE Insp Rept 50-155/78-05 on 780829-0901 Noncompliance
- noted: licensee disposal of licensed matls.

 SCHUMACHER.M.C. Region 3. Chicago, Fuel Facility & Materials

 Befety Branch. 78/09/18. Spp. 94057; 287.
- 7811240170 Responds to 780918 NRC ltr re deviation noted in inspec rep 50-155/78-Q5. Corrective action: procedures re transfer or release of industrial-commercial items have been rev & all items leaving control areas will be surveyed.
 BIXEL, D. A. Consumers Power Co. 78/10/06. ip. 94458:262.
- 7810190234 Forwards IE Insp Rept 50-155/78-08 on 780912-22 & notice of HIND.J.A. Region 3, Chicago, Safeguards Branch 78/10/10. 2pp. 94414:214.
- --7810190236 Notice of violation from insp on 780919-22.

 ** Region 3. Chicago. Befeguards Branth. 78/10/09. 1p. 94032 063
- --7810190247 IE Inspec Rept#50-155/78-08 on 780919-22 during which 1 item of noncompliance was noted: failure to prepare corrected Form NRC-741 Proprietary into deleted. HIND, J.A. Region 3. Chicago, Safeguards Branch. 78/10/05. Spp. 94052:064.

- 7810230334 Forwards 1E Circular#78-17 (Bee ANO 781023022).Docket 50-313.781013)
 KEPPLER, J O Region 3. Chicago, Office of the Director 78/10/13. 1p 94194-305
- 7811300135 Parwards IE Insp Rept 50-159/78-07 on 780911-15 & notice of violation.
 FIORELLI.9. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/10/26 2pp. 94073:223.
- --7811300138 Notice of violation from insp on 780911-15

 * Region 3. Chicago, Office of the Director. 78/10/26. 1p
 94073 198
- ~~7811300141 IE Insp Rept 30-155/78-07 on 780911-15 Noncompliance noted: failure to follow procedures for all structures.sys. conponents & safety actions defined in facility quality list.

 HUNTER, D. R., RIDDWAY, M. R., WARNICK, R. F. Region 3, Chicago, Office of the Director. 78/10/26. 22pp. 94073:199.
- 7811150051 Forwards IE Circular 78-18. KEPPLER.J. C. Region 3- Chicago, Office of the Director. 78/11/06. 1p. 94132:163
- 7811280052 Responds to NRC 781010 ltr re violations noted in Imap Rept 50-155/78-08. Corrective actions corrected forms NRC-741 were prepared for two instances cites & will be issued by 781115. Proceedural changes initiated BIXEL-D.A Consumers Power Co. 78/11/09. 2pp. 03554:176.
- 7812080192 Responds to NRC 781026 ltr re violetions noted in Insp Rept 30-155/78-07. Corrective actions: startup checklist & 80P-1 procedure will be revised, time required for stable reactor period defined & blocking of scram capability documented. BIXEL.D.A. Consumers Power Co. 78/11/20 2pp. 94107:341.
- 7812050314 Forwards IE Bulletin878-12A, suppl to IE Bulletin 78-12. W/enc! ANG: 7811300055. KEPPLER, J. G. Region 3. Chicago, Office of the Director. 78/11/24. 1p. 94393:195
- 7812060371 Ack receipt of 781006 ltr informing NRC of steps taken to correct violations noted in Insp Rept 30-135/78-12. DAVIB,A.B. Region 3. Chicago, Fuel Pacility & Materials Befety Branch. 78/11/28 lp. 94331:309.
- 7812080217 Ack receipt of 781109 itr informing NRC of steps taken to correct violations noted in NRC 781010 ltr.
 HIND. J. A. Region 3. Chicago, Bafeguards Branch. 78/11/28. ip. 94137:084.
- 7812260302 Ack receipt of 781120 itr informing NRC of steps taken to correct violations noted in NRC 781026 ltr.
 FIDRELLI.O. Region 3. Chicago: Reector Operations Nuclear Support Branch. 78/12/14. ip. 94160.071.
- 7812280056 Forwards IE Bulletin 78-14. KEPPLER. J. G. Region 3: Chicago Office of the Director. 78/12/19. 19. 03554:346
- 7812270180 Forwards description of inservice insp program for subj facility & requests relief from specific requirements of Section XI of Boiler & Pressure Vessel Code. Notes that issuance of amend to 10CFR30. 53a will modify requests.

 BIXEL.D. A. Consumers Power Co. 78/12/22. 76pp. 94163:001.
- R. Periodic operating reports & related correspondence
- 7812120109 Forwards Monthly Open Rept for Nov 1978.
 HARTMAN, C. J. Consumers Power Co. 78/12/05. 1p. 94275;315.
- -~7812120112 Monthly Oper Rept for Nov 1978. HIMEBAUCH-N. Consumers Power Co. 78/12/05. 7pp. 94275:316.
- 7812270198 Carrected copy of Manthly Oper Rept for Nov 1978. HIMEBAUCH, N. Consumers Power Co. 78/12/05. 2pp. 94017:208.
- S. Reportable occurrences, LERs & related correspondence
- 7811210350 While using fuel transfer cask to move core internals for 780922 maint activities, cable which controls cask sling brake went slack which could prevent timely tripping of cask brake mechanism.

 HARTMAN.C.J. Consumers Power Co. 78/09/25. ip. 94484:357.

- 7810170217 Forwards LER#76-032/03L-0.
 BIXE...D A Consumers Power Co. 78/09/27. 1p. 94236.193.
- 7810110104 Farwards LER#78-036/01L-0.
 BIXEL, D. A. Cansumers Power Co. 78/10/05. 1p. 94066:345.
- --7810110106 LERM78-035/01L-0 on 780905 condensate storage tank level fell below 65% limit due to open error caused by operator oversight incident to be rev to minimize potential for recurrence.

 * Consumers Power Co. 78/10/05. 1p. 94066.346.
- 7811240231 Forwards LER#78-041/01T-0.

 BIXEL-0 A. Consumers Power Co. 78/10/06. 1p. 94458:208.
- --7811240Q35 LER#78-041/01T-0 on 780922: while raising transfer cask to move come components trip line controlling cask sefety sling trip device went slack. Caused by excessive wear on geer driving chain takeup for trip line to safety sling brake.

 # Consumers Power Co. 78/10/06. ip. 94459: 209.
- 7810130171 Forwards LERM78-038/03L~0, M78-039/03L-0 & M78-040/03L-0. 81XEL.D.A. Consumers Power Co. 78/10/09. 1p. 94003:055.
- --7810130175 LER#78-038/03L-0 on 780909: during plant startup control roo drive temps were excessive due to drive cooling water leaks at small control rod drive bolted flange "O-ring" seals. Seal rings replaced. & seal spacers added. « Consumers Power Co. 78/10/09. 7pp. 94003:056.
- --7810130179 LER#78-039/03L-0 on 780911: during shutdown conditions, a control rod drive was removed for maint w/o reactor mode switch being placed in shutdown position. Repairmen feiled to notify control room as required a Consumers Power Co. 78/10/09. ip. 94003:057.
- --7810130183 LERM78-040/03L-0 on 780910: visual inspec showed a blown Put in a pur supply inverter. Hypothesis is that lightly loaded inverter should have a dummy load to practude transient supply voltage problems. Fuse replaced at dncs. 4 Consumers Power Co. 78/10/09. 1p. 94003:058.
- 7811210369 Reportable Occurrence: on 781018.a routine inspec for leakage revealed minor leakage at nonisolatable weld where a 3/4" stub line is connected to 3" reactor clean-up sys return line.

 BIXEL.D.A. Consumers Power Co. 78/10/19. ip. 94485:133.
- 7810250096 Responds to 780906 NRC 1tr questioning control rad drive performance. During 1977-78 facility had no case of failure of control rad to insert during control rad testing & reactor scrams.

 81XELD A. Consumers Power Co. 78/10/20. ip. 07587:001.
- 7810310190 Forwards LER#78-042/03L-0.
 BIXEL-D. A. Consumers Power Co. 78/10/26. 1p. 94090:154.
- --7810310133 LER#78/042/03L→0 on 780929: control rod coupling integrity tests performed in the jog mode white at pur oper(since July 1974) may not have been valid tests. In jog mode the withdrew pressure timing eignal is not of sufficient duration. « Consumers Power Co. 78/10/26, ip. 94090: 155.
- 7811090203 Forwards LER#78-037/01T-1, LER#78-031/01T-1, LER#78-037/03X-1, LER#78-035/01T-1 & LER#78-036/03L-1, Update of previous rept on 780912.
 - * Consumers Power Co. 78/10/26, 1p. 94038; 268.
- --7811090205 LER#78-037/017-1 on 780906:main steam isolation valve MO-7050 failed to close during routine tests. Caused by hardened valve stem packing. Valve operated properly after packing lubricated.

 * Consumers Power Co. 78/10/26. 2pp. 94038: 269.
- --781090223 LERW78-031/01T-1 on 780810: rejectable weld identified in weld made in 1972. Defect based on relience on 1972 radiogr techniques, Defect area being observed. Repairs will be made during future outage.

 ** Consumers Power Co. 78/10/26. 2pp. 94038: 270.
- ---7811090226 LERW78-032/03X-1 on 780819: failurs of check valve providin containment integrity in 2" demineralized water line:25 gallons of conteminated water removed from plant. Caused by valve defects water removal due to inadequate survey.

 * Consumers Power Co. 78/10/26. 2pp. 94038:272.

- ~7811090229 LERM78~035/01T-1 on 780904; supply valve CV/4097 leaked in sicess of Tech Spec limits Caused by maladjustment on 24" butterfly valve seal. Adjustment procedures & valve design will be reviewed. * Consumers Power Co. 78/10/26 2pp. 94038:274
- -7811090234 LER#78-036/03L-1 on 780905 during transfer of water to primary sys during hot shutdown, condensate storage tank level fell below 65 percent level Caused by operator oversight
 - + Cansumers Power Co. 78/10/25, 1p. 94038: 276
- 911030136 Forwards LER#78-044/01T-0. BIXEL.D. A Consumers Power Co. 78/10/31. 1p. 02723: 299.
- -7811030139 LERM78-044/017-0 on 781018: during primary sys startup.minor leak at 3/4*vent pipe weld attachment seen on 3' return line from cleanup sys to 2 reactor recirculating loop.Caused by fetigue cracking from inside to outside coupling weld. b Consumers Power Co. 78/10/31. 3pp. 02723:300.
- 811070217 Forwards LERM78-045/01T-0. HOFFMAN, D. P. Consumers Power Co. 78/11/02. 1p. 94039:1R3.
- -7811070224 LER#78-045/01T-0 on 781020: during Systematic Eval Prog ravious, splice matt used in control & instr circuits for equip req to oper during LOCA was of marginal moisture resistance, due to the quality of the matt itself. * Consumers Power Co. 78/11/02. 2pp. 94039:124.
- 011140146 Forwards LER#78-043/03L-0 & #78-046/03L-0. B1XEL, D. A. Consumers Power Co. 78/11/10. 1p. 94383: 266.
- -7811140130 LER#78-046/03L-0 on 781025: Drive A-2 scrammed in 6.0 seconds, exceeding Tach Spec maximum. Caused by broken Buna-N disc on moving core of one of two screm pilot solenoids. resulting in slow venting action.

 Consumers Power Co. 78/11/10. ip. 94383:267.
- -7811140151 LER#78-043/03L-0 on 781014: Orive C-4 scrammed in 4.4 seconds, exceeding Tech Spec maximum Caused by broken Buna-N disc on moving core of one of two scram pilot solenoids, resulting in slow venting action.

 • Consumers Power Co. 78/11/10. 1p. 94383: 268.
- 012040237 Forwards LERW78-027/03X-1 & #78-047/03L-0. BIXEL, D. A. Consumers Power Co. 78/11/29. 1p. 94328:038.
- ~7812040239 LER#78-027/03X-i on 780601: control Rod Drive E-4 could not be w/drawn beyond Position 20 due to unknown cause Drive was reinstalled in reactor & has operated satisfactorily.

 Consumers Power Co. 78/11/29. ip. 94328:039.
- -7812040241 LER#78-047/03L-0 on 781031:control rod drive temp on Drive E-2 was above 300F degrees & ercessive leakage was observed at E-2 drive flange connection due to "O-Ring" seal failure. Newseal ring installed & tested sotisfactorily. Consumers Power Co. 78/11/29. ip.
- B12110171 Forwards LERW7B-048/03L-0. B1XB., D. A. Consumers Power Go. 78/12/06. ip. 94337: 095.
- -7812110174 LER878-048/09L-0 on 781108: during steady state pur open, the emergency condenser shell side temp noted to be at 205 degrees F. Caused by leakage thru M07053 velve. * Consumers Power Co. 78/12/06. 1p.
- B12220074 Forwards LER#78-049/03L-0. BIXEL, D. A. Consumers Power Co. 78/12/14. 1p. 94342:331.
- -7812220075 LER#78-049/03L-0 on 781115:reactor water low level test circuitry did not provide req test response. Caused by test trip level potentiometer drift.

 a Consumers Power Co. 78/12/14. 1p. 94342:032.
- OCKET 50-157 CORNELL UNIV. RESEARCH REACTOR i. General correspondence
- 811060092 Notifies NRC that subj facil is no longer pert of the School of Applied & Engineering Physics Correspondence should be addressed to Dean Paul McIseac.
 OBMALD.P. I. Cornell Univ. 78/10/31. 1p.

- P. Operating license stage documents & correspondence
- 7811080013 Forwards Amenda? to LickR-80 for Cornell Univ TRIGA react REID.R W. Operating Reactors Branch 4 (Pre 790625). 78/10/24. 94398 (20).
- --7811000018 Amend#7 to Lic#R-80 for Cornell Univ TRIGA reactor, char Tech Specs re receipt, possession & use of special nuc metls. REID.R.W. Operating Reactors Branch 4 (Pre 790625) 78/10/24. 2pp 94398:022
- --7811080024 Rev pages to Lic Amend#7.

 Operating Reactors Branch 4 (Pre 790625). 78/10/24 9pp. 94398 024
- G. Inspection reports. IE Bullstins & correspondence
- 7812030286 Ack receipt of 781030 ltr informing NRC of steps taken to correct violations noted during inspec#50-97/78-02, #30-137/78-02 & #70-211/78-01. MARTIN.W.O. Region 1, Philadelphia, Bafeguards Branch, 78/11/07. 1p. 94202:321
- ~~7812050290 Responds to 781004 NRC ltr re deviation noted in Inspec #50-97/78-02.#50-157/78-02 & #70-211/78-01 Corrective actions: complete physical inventory & documentation finished
- 761023 GLARK, D. D. Cornell Univ. 78/10/30. ip. 94202:322.
- --7812050295 Forwards IE Inspec Repts#30-97/78-02,#50-157/78-02, #70-211/78-01 & Notice of Violation. MARTIN.H.O. Region i, Philadelphia, Bafeguards Branch. 78/10/0 2pp. 94202: 323.
- --7812050298 Notice of Violation from inspec on 780907-08. * Region 1. Philadelphia. Bareguards Branch 78/10/04. 1p. 94202: 325
- --7812050304 1E Inspec Repts#50-97/78-02.#50-157/78-02.#70-211/78-01 780907-08 during which 1 item of noncompliance was noted: failure to perform complete physical inventory w/in required 12 months. SUMMERGR J. Region 1. Philadelphia. Safeguards Sr. Region 1. Philadelphia. Safeguards Branch. 78/10/ 6pp. 94202: 326.
- DOCKET 50-140 GEORGIA INST. OF TECH. RESEARCH REACTOR E. NRC Safety Evaluation Report (BER), supple & correspondence
- 7812180386 Grants exemption for GIT from addl security provisions of 10CFR73.50 & 73.60 until 791130. Forwards concurrence memo & BER STELLD.V. Division of Operating Reactors, 78/11/30, App. 94357: 256.
- --7812180389 SER supporting exemption from 100FR73.50 & 73.60 in and for licensee to properly store PuBe neutron source in reactor bldg w/o providing addl security measures for one usar. • Office of Nuclear Reactor Regulation, Director. 78/11/30,
- G. Inspection reports, 12 Bulletins & correspondence
- 781 2010175 Farwards 18 [nspec Repts#50-160/78-04, #50-276/78-02, #70-297/78-04 & #70-386/78-04 an 780926-27 during which no item of noncompliance were noted.

 KENNA.H.B. Region 2. Atlanta. Bafeguards Branch. 78/10/20: 2ps. 94409: 221.
- ~~7812010182 IE Inspec Repts#50~160/78-04,#50~276/78~02,#50-277/78-0 #70-0386/78-04 on 780926-27 during which no items of noncompliance were noted. Major areas inspec incl: nuc metl control & accounting procedures review. TODD:9.4., WILLIAMS.0.H. Region 2: Atlanta: Bafeguards Brench. 78/10/20, 3pp. 74409:223.
- 7811020440 Forwards IE Inspec Rept#50-160/78-02 on 780717-27 & notic of violation. SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safe Branch, 78/09/15. 2pp. 94351:178.

```
DOCKET 50-163 GENERAL ATOMIC COMPANY
```

- A Application/construction stage documents & correspondence
- 7810270107 Reportable occurrence on 780831.at full power (1500 km).reg control rod continued to withdraw even when operator was not depressing "up" control Faulty up switch replaced & tested MONRY, $\hat{M}(R)$. General Atomic Co. (subs. of Gulf Dil Co.) 78/09/15. 2pp. 94059-290
- F. Becomity, medical, emergency & fire protection plane
- 7812190145 Forwards current physical security plan in compliance w/regs.classified as "Natl Socurity Info" pursuant to certain DOE requirements Requests that earlier copies be destroyed, and new capies be withheld
- S Reportable occurrences. LERs & related correspondence
- 7810270104 Forwards reportable occurences on 780801 MOURY, W.R. General Atomic Co. (subs. of Quif Oil Corp.) 78/09/15. MOURY, W.R. Get Lp. 94059, 289.

General Atomic Co. (subs. of Gulf Oil Co.) 78/12/15.

V. Operator Examinations

MOWRY, W.R.

1p. 94340 070

- 7810300284 Finds proposed changes to reactor open requal prog acceptable. Changes do not substantially decrease the frequency, duration, or scope of the prog COLLINS, P. F. Operator Licensing Branch 78/10/25 ip. 94189.308
- DOCKET 50-170 NATIONAL NAVAL MEDICAL CENTER P. Operating license stage documents & correspondence
- 7810130227 Forwards AFRRI-TRIGA(R-084 YAE)Annual Rept dtd 781031 MCINDOE, D. W. Defense, Dept of, Defense Nuclear Agency. 78/10/06. 94079 324
- DOCKET 50-171 PEACH BOTTOM ATOMIC POWER STATION, UNIT 1 G. Inspection reports, IE Bulletins & correspondence
- 7812010345 Forwards licensee performance evaluation for Region i.No operating reactor in Region 1 is considered to have either abnormal or unusual safety concern ORIER.8 H. Region i. Philadelphia. Office of the Director. 78/11/01. 4pp. 94418:234.
- 78:2050004 Forwards Licensee Performance Eval Questions for subj facils in response to 771123 request. Feels it is possible that dev of statistical methodology for such eval may not justify the effort Qualitative eval may be as good. Urges 1-year test. ORIER. B.H. Region 1. Philadelphia. Office of the Director. 77/12/13. 12pp 94200:114.
- --78:2050013 Requests views of Regional Directors on Licenses performance eval of subj facils. Forwards questions to be answered by THORNBURG.H. Division of Reactor Construction Inspection. 77/11/23, 2pp. 94200.126.
- 7811150116 Forwards copies of Decommissioning Plan ALDEN, H. M. Philadelphia Electric Co. 78/11/06, 1p. 94481:082.
- --7811150119 Decomm plan will progress in 4 phases. Phase I incl loading unloading & transfering fuel to spent fuel pool. Phase II incl shipping fuel to reprocessing plant in ID, & Phase III initiated after fuel is accepted. * Philadelphia Electric Co. 78/07/31. 118pp. 94481:083.
- 7811290288 Responds to 781106 request for info concerning licenses reg performance eval for Region 1 plants by NRC Provides ORIER, B. H. Region i, Philadelphia, Office of the Director. 78/11/09, 9pp. 94239:230.

7812180268 Forwards RevM1 "Draft Radiological Effluent Tech Specs" for BMR's(NWREG-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Por Plants" (NWREG-0133).
GRIMES, B. K. Assistant Director for Engineers & Projects (Pre

- 70:2280035 Emphasizes importance of submmitting accurate & complete inf to NRC by licensees & applicants Info submitted must be substantiated by data & calculations Licensee must notify NRC of eny inaccuracies or enforcement action will result.

 DAVIS, J. C. Office of Inspection & Enforcement. Office of the

 Director 78/12/06 2pp 94133 214
- DOCKET 50-182 PURDUE UNIV. RESEARCH REACTOR
- P Operating license stage documents & correspondence

are not exceeded

- 7812180076 Forwards Amend#3 to subj Pacil lic#R-87 % Safety Evel REID.R.W. Operating Reactors Branch 4 (Pre 790625) 78/11/28 2pp 94131 282 --7812180079 Amend#3 to open lic#R-B7. Changing Tech Specs to provide concise & definitive statement of limits of reactor oper parameters & surveillance measures req to assure that limits
- Operating Reactors Branch 4 (Pre 790625) 78/11/28 44pp. 94131-284 --7812180086 Safety Eval Rept supporting Amend#3 to Oper Lic#R-87. Concludes amend does not involve significant hazards consideration, safety of pub not endangered & activities conducted in compliance will not be infinited to defense.

 • Operating Reactors Branch 4 (Pre 790625) 78/11/28 3pp.
- 94131: 328

Q Inspection reports, IE Bulletins & correspondence

- 7810310029 Forwards Inspec Rept #50~182/78-02 on 780816-18 & Notice of Violation. FIDMELLI.G. Region 3. Chicago: Reactor Operations Nuclear Support Branch. 78/09/21. 2pp. 94094:349.
- --7810310033 Notice of Violation from inspec on 780816-18 Region 3. Chicago. Reactor Operations Nuclear Support Branch 78/09/21. ip 94094: 351.
- --7810310168 IE Inspec Rept#30-182/78-02 on 780816-18 Noncompliance nated operator w/expired license operated reactor.

 BROWN.C. LITTLE.M.S. Region 3, Chicago, Défice of the Director 78/09/21 4pp 94094:352.
- DOCKET 50-183 VALLECITOS EXPERIMENTAL SUPERHEAT REACTOR P Operating license stage documents & correspondence
- 7012190020 Forwards NRC Order to Show Cause, which req that Gen Elec Test Reactor be placed & maintained safely in cold shutdown condition pending further order. QASE.E.O Office of Nuclear Reactor Regulation, Director. 77/10/21.
- DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR G. Inspection reports, 1E Bulletins & correspondence
- 7811300361 Forwards IE Inspec Rept#50-184/78-05 on 780822-24 & Notice of Violation. BRUNNER.E. J. Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/09/13 2pp 94116:290.
- --7811300362 Notice of Violation from inspec on 780822-24. * Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/13 1p. 94116:292.
- ~-7811300363 IE Image: Rept#50-184/78-05 on 780822-24 during which I i of noncompliance was noted; using outdated surveillance test procedures. ARCHITZEL, R.E., MCCABE, E. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/12. App. 94116: 293.
- 7812060275 Responds to NBS 780923 ltr.Fails to find basis for withholding inspec rept IAW 100FR2.790, but will forward to Headquarters for action. QRIEN, B.H. Region i, Philadelphia, Office of the Director. 78/10/13. 1p. 94372:258.
- ~-7812060286 Forwards pages of IE Inspec Rept#50-184/78-04 & requests that noted portions be withheld from out disclosure.

 CARTER.R. S. Commerce.Dept. of, National Bureau of Standards.

JOURE LED HIGHS

- 7812050300 Forwards IE Inspec Rept#50-184/78-04 on 780705,780711, & 780713 & Notice of Violation. CROCKER, H W Region 1. Philadelphia. Fuel Facility & Materials Safaty Branch 78/08/07. 2pp 94372 266
- --7812060308 Notice of Violation from inspec on 780706,780711 & 780713 • Region 1, Philadelphia, Fuel Facility & Materials Bafety Granch 79/08/07. 1p. 94372-268
- --7812060316 IE Inspec ReptM50-184/78-04 on 780706, -11 & -13, during which 1 item of noncomplience was noted air flow rate in fume hoods MC001-2 was too long PLUMLEE, K. E., KNAPP, P. J. Region 1. Philadelphia, Fuel Facility & Material's Bafety Branch. 78/08/07 13pp 94372 269
- 7812080041 Denies request to withhold from pub disclosure 780823 NBS ltr & portions of IE Rept#50-184/78-Q4. Comm does not withhold merely because info relates to reactor fuel gOMER, 9 C Executive Officer for Operations Support 78/11/08 2pp 94104-028
- 8 Reportable occurrences. LERs & related correspondence
- 7811210320 On 781102 during routine test shim arm Wi had drop time in excess of acceptable range caused by slightly longer clutch release. Assembly removed & snap ring on armature hub replaced in fevor of a more uniform support CARTER, R 8 Commerce. Dept. of 78/11/07 8pp 94488 073.

OCCKET 50-186 UNIV. OF MISSOURI RESEARCH REACTOR

- J. Insurance & indemnity information
- 7810110079 Responds to 780922 ltr & forwards copy of Advance Premium & Standard Premium Endorsement to nuc liability policy for 1978 w/Amend #10 to Indemnity Agreement E-45.
 BLANETT.V. Missouri, Univ. of Rolle. 78/09/25. 4pp. 94063 344.
- P. Operating license stage documents & correspondence
- 78122900B0 Repts on failure of Regulating Blade Position Rod run-in on 781127: due to loosened set screw on position indication drive gear Cornective action: reactor shutdown, blade position indication repaired. Set screw will be checked.

 BRUGGER.R.M., MCKIBBEN.U C Missouri, Univ. of, Rolla. 78/12/21 2pp. 94170.087
- S. Reportable occurrences, LERs & related correspondence
- 7811060076 Reportable Occurence on 781022: Control Blade"B"unexpectedly dropped from drive magnet & hung up about 7 inches above full insertion-probably caused by broken outer race of 1 of 8 vertical guide bearings.

 MCKIBBEN. J. C. Missouri, Univ. of, Rolls. 78/10/31. 3pp 94494: 001.

DOCKET 50-187 SPACE RADIATION RESEARCH REACTOR

- H. General correspondence
- 7611140149 Npt1fies NRC of personnel changes at Northrop Reactor Facil. CHALMERS, N. J. Northrop Corp. 76/10/05. 1p. 94383.274.
- P. Operating license stage documents & correspondence
- 7811020248 Forwards "Natural Environ Radioactivity Survey for Bapt 1977 thru Aug 1978"for reactor LicaR-90.
 CRANDALL.W.E. Northrop Corp. 78/10/17. 1p. 94247:114.
- --7811020251 "Natural Environ Radioactivity Survey for the Period of Sept 1977 Through Aug 1978". ADAMS.J., COZENS.G., WODDS.J. Northrop Corp. 78/10/17. 10pp. 94247:115.
- O. Inspection reports. IE Bulletins & correspondence
- 7812130331 Ack receipt of 781114 ltr informing NRC of steps taken to correct deviations noted in Inspec Rept#30-187/78-03.
 CREMB.J.L. Region B. San Francisco, Reactor Operations Nuclear Support Branch. 78/12/01. jp. 94307:342.

- --7812130342 Responds to 781030 NRC ltr re deviation noted in Inapec Re #50-187/78-03 Corrective actions establishes calendar of periodic maint-reinstates prog of periodic b systematic performance eval of lic individuals.omerg procedure review CRANDALL.W E Northrop Corp 78/11/14 2pp. 94307 343
- --7812130346 Forwards Inspec Rept#50-187/78-03 on 781012-1013 & assoc Notice of Violation CREWB.J t. Region 5, Ban Francisco, Reactor Operations Nuclear Support Branch 78/10/30 2pp 94307 345
- --7812130347 Notice of Violation from inspec on 781012-1013 CREWB.J L. Region S. Ban Francisco, Reactor Operations Nuclear Support Branch 78/10/30 to 94307 347
- --7812130350 IE Inspec Rept#50-187/78-03 on 781012-1013 during which 2 items of noncompliance were noted in the following agrees: periodic resint on pulse rod drive cylinder & periodic lic operator evals

 JCHNSON:P H., CARLSON.J. D., STERNBERG.D M. Region 5. San
 Francisco. Reactor Operations Nuclear Support Branch 78/10/30
 4pp 94307-348
- DOCKET 50-188 KANBAS STATE UNIV. RESEARCH REACTOR
 P. Operating license stage documents & correspondence
- 78:01:0029 Forwards changes in procedures for Aug 1977-June 1978 bienniel control rod insp.fuel element insp & teactor Startup w/period scram bypassed.
 FAM.R. E. Kansas Blate Univ. 78/09/25 9pp. 94063.141
- 78:11:30:27 Responds to 78:026 ltr re Dr Eckoff's training & authorizes him to perform licensed duties CDLLINB, P.F. Operator Licensing Branch. 78/10/31 lp. 94076:120
- DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC
 P. Operating license stage documents & correspondence
- 7810200017 Forwards Amend#6 to Facil Oper Lic#R-95 changing Tech Specre U-235 fuel weight limitation REID.R.W Operating Reactors Branch 4 (Pre 790625), 78/10/02. 2pp. 94195:215
- --7810200021 Amend#6 to Fecil Lic#R-95.changing Tech Bpec re U-235 fuel weight limitation.
 REID.R W. Operating Reactors Branch 4 (Pre 790625). 78/10/02.
 4pp. 94195-217
- --7810200024 Safety Evaluation Supporting Amend#6 to Facil Lic#R-95. Concludes that herards will not increase.

 * Operating Reactors Branch 4 (Pre 790625). 78/10/02. 3pp. 94193-221.

DOCKET 50-200 BEW TEST REACTOR

- J. Insurance & indemnity information
- 7809130539 Bigned Amend#18 to Indemnity Agreement#8-8, adding new Anticle VIII re:payment of assessed deferred premiums for subj facils.

 BALTZMAN.J. Antitrust & Indemnity Group. 78/09/01. 2pp.
- DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

 D. NRC Dreft/Finel Environmental Statements, supple & correspondence
- 7811100125 Advises that NFB will submit its eval on items addressed in 780627 NRC ltr prior to 781016, rather than 780930 as originally estimated in NF ltr of 780814. CLARKJR. Nuclear Fuel Services, Inc. (subs. of Oetty Oil Co.). 78/09/22. Ip. 94246:337.
- H. General correspondence
- 78:1280118 NF plans to submit apple for Benoir Operating Lice for D Ploets & C Ross. The add1 training will be completed in Feb 1979 & appropriate NRC examinations are requested for March 1979.
 PIERCE.A.C. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.), 78/10/30. ip. 94013:008.

- 7810170056 Forwards changed papers for incorporation into West Valley Bite Rept ROGERS.V C Ford Dacon & Davis Utah. Inc NRC-02-77-197 78/09/27 1p 94204 351
- 7811200219 Presents hRC persenctive & conclusions re specific criteria for decommissioning level waste tanks at subj facil DGE should lead in dev of disposal option to safely isolate waste should have in-tank solidification scheme MARTIN.J B Assistant Director for Fuel Cycle Safety & Licensing 78/10/10 2pp. 94232-099
- --7811200221 "Compilation of the Radioactive Waste Disposal
 Classification Sys Data Base." Task Rept-analysis of West
 Valley Site Analyses lou-level radioactive waste burial area
 & high level waste storage tanks using RWDCS methodology
 = Ford Bacon & Davis Utah. Inc FBDU-247-01 78/09/30 110pp
 94052 101
- 7811170233 Responds to 780627 NRC request for review & eval of actions recommended by DuPont re Waste Tank Safety Plans to augment procedure for transfer of waste from insvc tank80-2 to spare tank #80-1 in the interest of greater conservation CLARK.JR Nuclear Fuel Services, Inc. (subs of Getty Oil Co) 78/10/12 9pp. 94098 315
- 7811170045 Notice of 781028 visit to subj facil to observe struc characteristics of plant w/respect to tornado resistance & to acquire (nfo necessary to complete status rept on N9C plant mod review PERSON_L S Fuel Reprocess & Recycle Branch (Pre 790727) 78/10/23 1p. 94048.263
- 7811170037 Bummary of 781005 meeting w/Nuc Fuel Svc re dev of info for decomm Nert newting will be 781108 W/encl reference index for Mech Process Plant area HAUGHNEY.C. J. Fuel Reprocess & Recycle Branch (Pre 790727). 78/10/27. 32pp. 94048.212
- 7811280370 Notification of resting U/Nuc Fuel Svc on 781119 in Silver Spring to discuss progress of NFS efforts to process available tech info. Needed as basis for future decontamination & decomm of Nest Valley Pacil HAUCHYP.C J Fuel Reprocess & Recycle Branch (Pre 790727) 78/11/01. 2pp. 94397: 239
- 781128041; Discusses site visit to subj facil to obtain head end ventilation sys info for CRNL analysts Detailed flow diagram of sys was composed by NRC & CRNL analysts & uill be used for constructing model for computer analysis CLARK.A. T. Evel Reprocess & Recycle Branch (Pre 790727). 78/11/01 2pp 94397 326.
- 7B12190058 "W NY Nuc Svc Center Study Final Rept for Pub Comment "
 Presents potentially viable options for dealing w/sub; shut
 down facilithus Fuel Svc fuel reprocessing planti-decomm &
 waste disposal-continued nuc use or non-nuc use of facil.
 * Energy, Dept of, 7B/11/30, 53pp 94210.262.
- 7812180114 Notice of 790109 meeting in Silver Spring.MD u/Nuc Fuel Bycs re info needed to provide basis for Future decontamination & decommissioning of subj Facil. HAUGHLEY.C.J. Fuel Reprocess. & Recycle Branch (Pre 790727). 78/12/04. 3pp. 94130:323.
- G. Inspection reports, IE Bullatins & correspondence
- 7810300334 Forwards 2 memos & 3 ltrs re Inspec Rept #50-201/72-03 conducted 720919-23 & 720926-29 PAULUS, R C Office of Inspection & Enforcement, Office of the Director 78/10/23 tp. 94270.205
- --7810300338 Responds to 730203 AEC ltr re violations noted in Inspec Rept #30-201/72-03 w/detailed objections to matters in reptrequests that rept & present ltr be withhled from PDR, since it contains errors & is not a final document. MILLER,R.N. Nuclear Fuel Services, Inc. (subs. of Getty Dil Co.). 73/03/12. 9pp. 94270:206.
- --7810300343 Ack receipt of 730126 ltr informing NRC of steps taken to correct deviations noted in Inspec Rept #50-201/72-03. NBLSON.P.R. Region 1, Philadelphia. Office of the Director 73/02/05 ip. 94270:215.

- --7810300354 Suggests surprise inspec of subj facil w/subsequent news release to local newspaper or writing a ltr to the local newspaper citing the encl anonymous ltr Subj facil has been a running sore re plant conditions releases etc HENDRIE J M Atonic Energy Commission. 72/09/12 3pp 94270 236
- --7810300008 Recommends investigation of subj facil re working condition careless exposure & working condition of the core.

 4 Affiliation Unknown 72/09/03 2pp 94270:237.
- --7810300362 Suggests making copy of inspec rept available to local press & possibly levying civil penalties O'LEARY, J.F. Assistant Director for Licensing 72/09/19 ip 94270 239
- 7812290076 Forwards IE Inspec Rept#50-201/78-08 on 781024-26 during which no items of noncompliance were noted.

 SMITH.O H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 78/11/13 2pp. 94190 076
- --7812290078 IE Inspec Rept#50-201/78-08 on 781024-26 during which no items of noncompliance were noted Areas inspected environ monitoring prog engt & implementation.
 KOTTAN, J. J., JACKSON, T. J., STOHR, J.P. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch. 78/11/13. 4pp. 94190.078.
- R Periodic operating reports & related correspondence
- 7811270257 Quarterly Rept for period Jul 1-Sept 30, 1978 OLDHAM,W A Nuclear Fuel Bervices, Inc. (subs. of Getty Gil Co.), 78/10/30 12pp 94252:352.
- 7812150036 Forwards results & flow measurements for Oct 1978 OLDHAM,W.A. Nuclear Fuel Services, Inc. (subs. of Getty Oil Co.). 78/11/08 4pp 94210:054.
- DOCKET 50-206 SAN ONOFRE NUCLEAR STATION. UNIT 1
- A. Application/construction stage documents & correspondence
- 7810230375 Believes that there is a potential problem w/Class 1E battery racks supplied to subj facil Addl isolation bar for seismic protec will be available for retrofit win 60 days. MCMANUS.C.K. ESB. Inc. 78/10/11 Ip. 94271:184.
- F. Security, medical, amergency & fire protection plans
- 7810180218 Summary of 780829 meeting re fire protec prog for subj facil w/list of attendees & staff positions identifying open items. "Fire Protec Prog. NRC Positions-SCEC Responses" encl. BURGER.A. Operating Reactors Branch 2 (Pre 790625). 78/09/30 24pp 94421 271
- 7810250142 Following site visit & evaluation of Fire Protec Progrithere are 2 Fire areas critical to shutdown capacity which need add1 fire protec: 4160 volt switchgear room & turbins oil reservoir area.

 DUNNING.T. Plant Systems Branch (Pre 791030). 78/10/12. 10pp.
- 7810230155 Review of fire protec prog for provisional oper lic#DPR-13 re mod to 4160-volt switchgear room (Fire Zone B) & mod to lube oil reservoir & conditioner area (Fire Zone 7A).

 BASHIN.R.P. Sputhern California Edison Co. 78/10/18 29pp.
- 7810300111 Summarizes 780915 meeting re fire protec prog for subj facil Discussed plans & schedules for facil mods for fire protec Handout. "Casualty Procedures to be Implemented Following Total Loss of 4161v Switchgear." encl. BURGER.A. Operating Reactors Branch 2 (Pre 790625). 78/10/18. 11pp. 94033.219.
- 78i1030255 Discusses fire protec plans re subj facils. Before startup, interim mods, casualty procedure for safe shutdown & improved fire fighting & detection capability will be req. LAINAS. 0. Plant Systems Branch (Pre 791030). 78/10/26 2pp. 02/72:317.

- 7811050104 Advises that "Casualty procedure're air supply for Lube 0:1
 Reservoir & Conditioner Area & "station wall-thro"will be
 Performed in response to 781018 NRC request re fire protec
 HAYNES. J D Sauthern California Edison Co 78/10/30 2pp
 74424:300
- 781:130297 Review of 781018 submittal relating to fire protect is found acceptable cending completion & review of final fire protect mod Conclusions based on will's commitment to verify that alternate supply of compressed air will be available TIEMANNO L. Operating Reactors Branch 2 (Pre 790625) 78/10/31 3pp 94086.131
- 7811240060 Forwards summary of open items on subj facil fire protec Proj eval Licensee response to encl staff position is required LAINAS.0 Plant Systems Branch (Pre 791030) 78/11/07 9pp 94489:312
- 7811080:05 Informs NRC that rev of physical security plans will be fubmitted by 781120 due to add1 time requirement HAYNES.J 0 Southern California Edison Co 78/11/08 1p 74399:137
- 7812050059 Forwards surmary of open items in NRC review of fire protect Prog for subj facilirev staff position PF-27A re concarn W/"Cable Spreading Area" & addl staff position PF-51 "Containment" Requests response to staff position by 781127 21EMANN.D.L. Southern California Edison Co. 78/11/17 5pp 94-272:227
- 7812010142 Informs NRC that SCE has established lieison w/US Marshall Svc & US Marine Corps in order to repel criminal activity or sabotage should its own security forces be unable to contain such acts Encl 780814 Itr is w/held from pub disclosure PIODYT.O R Chickering & Gregory 78/11/22 ip 94418.084
- 7812050186 States util is unable to submit response to Fire Protec Review questions by 781128 Will submit by 781201 HAYNES, J G Southern California Edison Co 78/11/28 Ip 94335 175
- 7812050219 Notifies NRC that submission of revisecurity plans will be delayed until 781215 to allow time to incorporate agreements reached u/outside law enforcement agencies, a the methods of Protecting against sabotage by the insider HAYLESJO Southern Collifornia Edison Co 78/11/29 2pp 94018:332
- 7812120101 Responds to NRC staff positions forwarded in 781117 NRC itre Fire Protec Prog Review Staff positions responded to incl: PF-27A. "Cable Spreading Area" & PF-51. "Containment "BASKIN.X P Southern California Edison Co. 78/12/01 App. 94275:020
- 7812220082 Requests review of enclosed and physical security plans and issuance of Security Plan Evel Repts indicating NRC approval. Enclosed security plan documents are proprietary & are w/held IAW 2.790
 MEAD, J T Southern California Edison Co 78/12/19 2pp. 94343, 339
- 9 Adjudicatory correspondence
- 7811100047 Forwards Notice of Appearance for C Kocher as counsel for BCE in proceedings re-subj facil Cert of BVC encl BEOLETTO, J. A. Bouthern California Edison Co. 78/10/17. 3PP. 94178-384
- 7811100048 Forwards Notice of Withdrawal of R Woodbury & D Barry as counsels for BCE in proceedings re-subj facil Cert of Svc BEDLETTO. J A Bouthern California Edison Co 78/10/17 3PP. 94178.337
- H General correspondence
- 78k1010051 Informs that for SER normal channel of oral communication will be followed but to expedite reviews direct oral communication between subj facil staff & members of SEP branch is encouraged.

 21EMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/10 app. 94270 134
- 7812130093 Ack receipt of 781107 natification of change of address CASEY/8 B. Chickering & Gregory 78/11/13. Ip 94294.310

- 7812190150 For all future correspondence w/SCE ie sub, facils.RE Woodburg is to be deleted from svc list & replaced by CR Kocher
 HAYNES.J C Southern California Edison Co 78/12/13 Ip
- J Insurance & indemnity information
- 7810250037 Forwards Endorsements #66.67.68 to Policy NF-146 & #50.59.69 to Policy NF-146 & #50.59.69 to Policy NF-38 HU0HES.4 O Southern California Edison Co 78/10/16 7pp
- D. Advisory Committee on Reactor Safeguards reports & correspondence
- 7812060086 Comments on Tera Comp rept "Simulation of Earthquake Ground Motions" Rept is a breatthrough in understanding seismic wave propogation & ground motion characteristics Should not be used to provide basic plant design criteria SEED. H B. Affiliation Unknown 78/10/05 2pp 94328 350
- P Operating license stage documents & correspondence
- 7810130236 Notice of Issuance of Amenc#36 to Provisional Oper Lic #DPR-13 on 780725 ZIEMANN.D (Operating Reactors Granch ? (Pre 790625) 78/09/25 Zpp 94031 058
- 7810200026 Forwards Amend to License DPR-13, changing Tech Specs by adding requirement for min water level above spent fuel pool max weight to be carried over spent fuel assemblies ZIEMANN.D L Operating Reactors Branch 2 (Pre 790625) 78/09/25 2pp 94402 020
- --7810200029 Amand 36 to License DPR-13 changing Tech Spec requirement for min water level above spent fuel pool & max weight to be carried over spent fuel assemblies ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625) 78/09/29 7pp 94402 022
- --7810200031 Safety Evaluation Supporting Amend#36 to 1.1:#DPR-10. Concludes that there is no increased hazard to the country or the population # Operating Reactors Branch 2 (Pre 7906251 78/09/20 7pp. 94402 029
- 7810110096 Ack receipt of 780817 NRC ltr requesting comments in staff evaluation of Systematic Evaluation Program for subj facil Comments incl HAYNES.J 9 Southern California Edison Co 78/10/03 4pp 94065 356
- 7810230012 Requests add1 inPo on deviations in proposed change # 75 to Tech Specs re insvc Inspec for steam generators to proposed Tech Spec for eddy current tests or gaging to monitor generator tube dents
 ZIEMANN.D t. Operating Reactors Branch 2 (Pre 790625) 78/10/10-4pp
- 7810230105 Info sought by NRC ltm of 780906 re environ qual of safetyrelated elec equip will be provided by 781127 HAYNES, J.Q. Southern California Edison Co., 78/10/13, 1p 94169; 148
- 7810300068 Summary of 781006 meeting w/util to discuss SEE program Summary of util/TERA presentation & attendee list and l DAVIS.D K Systematic Evaluation Programs Granth (Pro 790625) 78/10/16 33p 94034-241
- 7811020053 Forwards BER supporting acceptance of postponement of certain permanent ECCB single failure fires at subj facil Mod incl installation of redundant undervoltage relays, installation of a redundant valve.& redundant control pur 21EMANN.D L. Operating Reactors Branch 4 (Pre 790625) 78/10/14 3pp. 94035 229.
- --7811020059 SER supporting Amend #25 & acceptance of postponement of cartein permanent ECCS Single Failure Fixes at subj facil Postponement of installation of redundant undervoltage relay is not acceptable as discussed

 M Office of Nuclear Reactor Regulation, Director 78/10/16.
 10pp 94353, 222
- 781020026B Forwards list of add1 studies re Site Specific Earthquake prog of sub, facil w/understanding that Site Specific earthquake response spectra dev by TERA will be the basis of seismic reevaluation of sub, facil.

 BASKIN.K P Southern California Edison Co 78/10/18 4pp. 94271-142

- /SIJUDONYB Un 780918 sched retreivel of settling plates round both primary & back—up plates damaged. Problem has been repetitive over 3 years & is attributed to marine studies. Proposes request to delete studies. HEAD, J T. Southern Celifornia Edison Co. 78/10/18 2pp 94035 070.
- 7810310132 Forwards proposed Tech Spec which has been mod to provide add1 info requested in 781010 NRC ltr. Add1 info pertains to inspect to monitor tube denting & imperfections at antivibration bar intersections.

 BABKIN.K.P. Bouthern California Edison Co. 78/10/24 10pp. 94090:144
- 7810250066 Forwards results of BCE examination of facts defining subj facil in each topic assessment for 3 SEP topics as requested in 780911 NRC ltr.
 HAYNES.J.Q. Southern California Edison Co. 78/10/25. 3pp.
- 7811100141 Requests add1 info on ESF Switchover from injection to recirculation mode, solation of reactor protects as from non-sefety sys. ESF sys togic & design, specific drawing of electys. & complete plant electrawing indices w/sntl. ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/26 38ps.
- 7811070243 Responds to NRC request to justify changes in the following physics startup tests: HZP Critical Boron Concentration. HZP Control Bank Worth Acceptance Criteria. Low Pur Core map. Power Coefficient & Pur Defect test. HAYNES. J. 0. Southern California Edison Co. 78/10/27. 3pp. 20070-102
- 78:117005: Forwards dreft eval of 2 SEP topics, radiological consequences of steam generator tube failure & of main line failure outside containment. Concludes that subj facil is safe re both possibilities.
 21EMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/29. 10pp. 94046.238.
- 78:10:60086 Repts insertion of a Containment Spray Sys notitle inspected requirement in Section 4.2 of Tech Specs. "Bafety Injection & Containment Spray Sys Periodic Testing."

 BABKIN-K.P. Southern California Edison Co. 78/10/30. 2pp 94424:080.
- 7811140053 Forwards Amend#37 to Provisional Oper Lic#DPR-13 changing Tech Spec re Cycle 7. 21EMANN D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/31. 3pg. 94420:223.
- ~7811140055 Amend#37 to Provisional Oper Lic#DPR-13.changing Tech Spec re Cycle 7 oper. ZIEMANN,D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/31. 20pp. 94420.226.
- --7811140057 Safety eval supporting Amend 37 to License DPR-13. Amend does increase safety risk.
 ZIEMANN, D. L. Deprating Reactors Branch 2 (Pre 790625). 78/10/31.
 16pp. 94420:231.
- --7811140063 Notice of Issuance of Amend#37 to Provisional Oper Lic #BPR-13, changing Tech Spec:deletes Lic Conditions 3.E.3F(1) 3.F(2):re steam generator inspec & cycle 7 core. ZIEMANN, D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/31. 2pp. 94420:268.
- 7811280007 Initial study rapt for constr & oper of a single circuit 230 KV transmission line from subj facil to Encine Generating Btation in Ban Diego County, CA. W/encl Environ Data Statement & Addendum%: to EDS re cultural resources.

 Ban Diego Gas & Electric Co. 78/11/08. 237pp. 02726:003.
- 7811210316 Forwards corrected part(f) of 770922 add1 info re control room operator doses. HAYNEG: J. G. Southern California Edison Co. 78/11/14. 2pp. 94488: 053.
- 7811210377 Based on review of subj model Tech Spec submitted by 780711 NRC 1tr.3 NRC computers would be nessed to calculate model parameters. Since computers are not now evailable, lic amend requested w/in 120 days of 780711 ltr will not be submitted. HAYNES, J. 9, Southern Celifornia Edison Co. 78/11/14. 2pp. 94485; 147.
- 7811220146 Responds to 780718 NRC ltr requesting comments on rept re 780524+25 sits visit. Finds five incorrect tech details in rept & re-svc water reservoir & sewell constr. HAYNES, J. G. Southern California Edison Co. 78/11/14, 2pp. 94074;337.

A. Station Battery Test Req. Requests they be transmitted to licenses. DAVIS.D.K. Systematic Evaluation Programs Branch (Pre 790625). 78/11/14 23pp

ADDITEDUATO LOUMELOS

- 7812150197 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73 Requests pre-workshop registration of attendees to facilitate sending out math W/encl Registration Form & List of Locations.
 MILLERUR. Assistant Director for Site & Bafaguards (Pre 791030).
- 7812190057 Forwards Revel "Draft Radiological Effluent Tech Specs" for PWR's(NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133). GRIMES, B.K. Assistant Director for Engineers & Projects (Pre 790425) 78/11/15. App. 94215:083
- 7812040007 Parwards Amend #38 to License DPR-13.safety evaluation & notice of issuance.

 ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/17.
- --7812040012 Amend#38 to License DPR-13, changing Tech Space of combined heat up.cooldown & pressure limitations, reactor coolent sys, redipactive gasebus waste release, fire protec sys surveillance & radio environ monitoring.

 ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625). 78/11/17.
 17ap.
- --7812040017 Safety evaluation Supporting Amend#38 to Oper Lic*DPR-13. Supports issuance of emend which would reduce maximum allowable rates for pressurizer heatup. ** Office of Nuclear Reactor Regulation. Director. 78/11/17. 4pp. 94323.342.
- --7812040020 Notice of Issuance of AmendW38 to LicMDPR-13 Rev Tech Specto reduce maximum allowable rate for pressurer theatupy to increase maximum allowable rate for pressurer cooldown & to delete provisions of Respiratory Protec Prog. WAYBACH, T. V. Operating Reactors Branch 2 (Pre 790625). 78/11/17. 2pp. 94325-346.
- 7811280219 Responds to 770926 request for evel of potential boron dilution accident at subj facil, Concludes sys in subj facil has no patential for return to criticality & that except for Chem & Volume Control Bys-no 1 event can cause such failure. BASKIN.K.P. Bouthern California Edison Co. 78/11/20. 2pp. 94012-088.
- 7811280245 Follows up 761116 rept re failed thermal shield flexures in 4 of 6 supports. 1978 inspec found 5 of 6 flexures cracked. Belleves situation does not affect continued oper & plans no corrective action. HEAD, J. T. Bouthern Celifornia Edison Co. 78/11/21, 2pp. 94012:160.
- 7811280212 NRC's steff environ quel tables for BEP Topic III-12, Environ qual of Bafety Related Elec Equip will not be available for submittel until 781218.

 HAYNES-U. 9. Bouthern Celifornia Edison Co. 78/11/22. 1p. 94012: 129.
- 7811280239 Submits proposed mods to air supply sys of subj facil. Mods will ensure evailability of air supply to req equip after loss of main air header due to fire in lube oil reservoir & conditioner area.

 8ABKIN.K.P. Southern California Edison Co. 78/11/22. Ppp. 94375:001.
- 7812130156 Forwards for review draft NRC evals (BEP), "Thermal-Overload Protec for Motors of Motor-operated Valves & & BEP Battery Capacity Tests." ZIEMANN,D.L. Operating Reactors Branch 2 (Pre 790625), 78/11/24. 7pp. 94305:108.
- 7812110056 Discusses possible dangers of LOCA in containment purging during normal plant oper.Requests either commitment to limit purging or justification for continuing.Wenci ANO: 87812080207. ZIEFANN.D.L. Operating Reactors Branch 2 (Pre 790625), 78/11/29. Spp. 94408:256.
- 7812140292 Forwards Amend#39 to Provisional Open Lic#DPR-13, revising Tech Space as requested in 780717 ltr. ZIEMANN.D.L. Operating Reactors Stanch 2 (Pre 790625). 78/11/30.3pp. 03558:017.

- --7812140304 Amend#39 to Provisional Uper Liceurania, rev isca apera receptain growisions in Bections & 5 (Admin Controls) of Append AbB. respectively, to reflect new corp & station org struc. & to increase onsite review comm members ZIEMANN, D.L. Operating Reactors Branch 2 (Pre 18pp. 03558.020 Operating Reactors Branch 2 (Pre 790625). 78/11/30.
- --7812140308 Notice of Issuance of Amend#39 to Provisional Oper Lic#DPR-13 on 781130 ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625) 78/11/30. 2pp 03558: 038.
- 7812280071 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants Info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or anforcement action will result.

 DAVIS.J. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp 03595:188
- 7812140299 Requests addl info re pipe breaks inside containment. Forwards itr summarizing current criteria re pipe breaks for BEP Plants. Operating Reactors Branch 2 (Pre 790625) 78/12/07 Z1EMANN. D. L. 0 3pp. 03556: 282
- --7812140311 Forwards "Sys Eval Prog for Assessment of the Effects of Postulated Breaks in Fluid Sys Piping Inside Containment" which provides guidance for selecting design locations & prishtations of postulated breaks.

 DAVIS.D. K. Systematic Evaluation Programs Branch (Pre 790625).
 78/07/20. 13pp. 03556:285.
- 7812200132 Forwards results of ECE examination of facts defining subj facil in NRC topic assessments HAYNES.J G Southern California Edison Co. 78/12/07 Spp. 74156: 299
- 7812210018 Forwards NUREG-0485. Vol 1. No 2 "Status Bummary Rept-Sys Eval Prog. " W/o encl. ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/12/08. 200. 94249:335.
- 7812270046 Requests add1 info to complete review of Tapic VIII-4 "Elec Penetrations of Reactor containments." Info incl-circuit & elec penetration info. ZIEMANN, D. L. Environmental Projects Branch 2. 78/12/08. 4pp. 94160 251
- 7812270195 Forwards Summary of Physics Startup Tests conducted from 781031 to 781111. Comparison of measured values w/predicted values were w/in limits of Review & Acceptance Criteria agreed upon w/NRC staff. OTTOSON.H. L. Southern California Edison Co. 78/12/15. 1p
- --7812270199 Summary of Physics Startup Tests conducted from 781031 to 781111.Performed Rod Drop Time Test.Hot Zero Pur Physics Test & test of Pur Escelation.Comparison of measured & predicted values w/in limits of Review & Acceptance Criteria Southern California Edison Co. 78/12/11. 3pp. 94017:205
- 7812270165 Equip environ quel tables forwarded 780906, will be completed & forwarded by 790122 Delay tables by efforts to meet NRC sched requirements on other projects incl subj facil Physical Security & Fire Protec Progs. HAYNEB, J. G. Gouthern California Edison Co. 78/12/18. 1p. 94018 OR7
- O Inspection reports. IE Bulletins & correspondence
- 7810300018 Forwards IE Inspec Rept#50-206/78-11 on 780814-15 during which no items of noncompliance were noted. BOOW.H.E. Region 5, Ban Francisco, Fuel Facility & Materials Sefety Branch. 78/09/07. 2pp. 94034:347.
- --7810300020 IE Inspec Rept#50-206/78-11 on 780814-18 during which no tems of noncompliance were noted. Najor areas inspeciations of noncompliance were noted. Najor areas inspeciacluded neutron monitoring prografueling outage planning & treining & post amargancy exercise activity.

 BOOK.H.E., CURTIS.U.R. Region 5. Ban Francisco. Fuel Facility & Materials Befety Branch. 78/09/07. Spp. 94034:349.
- 7810230320 Forwards IE Circular#78-17. (See ANO: 7810230221, Docket 50-313, 7810131 ENOBLEBN.R.H. Region 5. San Francisco, Office of the Director. 78/10/13. ip.

VII Refueling Outage" Results support request for lic amend to delete req to bring facil to a cold shutdown condition to perform inspec HAYNES J 0 Southern California Edison Co 78/10/25. 2pp 94053, 137

1910510514 LOLMALD2 "KEPDICE DE SCEAM ABINE BEAL

- --7810270216 "Results of Steam Generator Inspec Prog for Cycle VII Refueling Outage" Presents results of completed overall inspec prog-corrective actions taken & conclusions based on results re continued plant oper Bouthern California Edison Co. 78/10/23 90pp 94053: 139.
- 7810190135 Fowards IE Inspec Repts#50-206/78-12. 780906-08 during with a de noncompliance were noted IE rept withheld subj to 2 790.
- NORDERHAUG, L. R. Region 5, San Francisco, Bafeguarde Brench 78/10/04. 2pp. 94414:043.
- 7812150180 Forwards IE Inspec Repts#50-206/78-16 on 781016-19 durin which no items of noncompliance were noted BODK.H.E. Region B. San Francisco. Fuel Facility & Materials Saf Branch. 78/11/03. 2pp. 94212-281
- --7812150185 IE Inspec Repts#50-206/78-15 on 781016-19 during which items of noncompliance were noted Major areas inspected inclinadiat protec prog during refueling outage & followup activity CRT18,J R Region B. Ban Francisco, Office of the Director 78/11/03. Bpp. 94212:283
- 7811150019 Forwards IE Circular 78-18 ENGELKEN.R.H. Region 5. San Francisco. Office of the Director. 78/11/06 ip. 94111:221
- 7812070283 Forwards IE Inspec Rept#50-206/78-13 on 780921-28.1012-1 1016-18 during which no items of noncompliance were noted. CREWS, J.L. Region 3. Ban Francisco, Office of the Director. 78/11/08. 2pp. 94085-215.
- --7812070296 IE Inspec Rept#50-204/78-13 on 780921-28,1012-13 & 101 during which no items of noncompliance were noted. Major areas inspected incl:local less rate tests reflueling preparations & oper,maintenance activities & LER's. WDE99NER.J., CANTER.H., HDRN.A. Region 5, San Francisco, Offic the Director. 78/11/07. App. 94080: 217.
- 7812210376 Notice of Violation from inspec on 781010-13 & 1024-27. * Region 5. San Francisco, Reactor Construction & Engineering Support Branch. 78/11/13. 2pp. 94015:040.
- --7812210380 IE Inspec ReptsW30-205/78-14 on 781010-13 & 1024-27 du which I item of noncompliance was noted failure to perform nondestructive exam of vessel closure stude & nuts IAW requirements of ABME Code. PATE R. J., HAIBT, D.P. Ragion 5, Ban Francisco, Reactor Construction & Engineering Support Branch. 78/11/13 94015.042.
- --7812210388 Responds to 781115 NRC ltr re violations noted in Insp ReptM50-205/78-14.Corrective actions: a calibr block equipped w/reflectors has been obtained & prog to eval equivalence of technique initiated.
 MODRE, J. B. Southern California Edison Co 78/12/06. 2pp 94015:050.
- --7812210399 Ack receipt of 781206 ltr informing NRC of steps takes correct violations noted during inaper#50-206/78-14. BPENCER, Q.B. Region 5. San Francisco. Reactor Construction & Engineering Support Branch. 78/12/14. ip. 94015:053.
- 7812210370 Forwards IE Inspec Rept#50-206/78-14 on 781010-13 & 102-& Notice of Violation. SPENCER, G. S. Region 5, San Francisco, Reactor Construction & Engineering Support Branch, 78/11/15, 2pp 94015:038.
- 7811300097 Forwards IE Bulletin #78-12A. suppl to IE Bulletin 78-12 W/encl ANG 7811300055. ENGELKEN.R.H. Region 5. San Francisco. Office of the Director. 78/11/24. 1p. 94073:035.
- 7812290098 Forwards IE Bulletin 78-14 ENGELKEN, R. H. Region 5, Ban Francisco, Office of the Director. 78/12/19. ip. 03695:192.
- R. Periodic operating reports & related correspondence
- 7810130159 Forwards Monthly Open Rept for Bept 1978. CURRAN.J. H. Bouthern California Edison Co. 78/10/02. 1p. 94002:348.

94002: 349.

- 7811160080 Forwards Monthly Open Rept for Oct 1978 CURRANIJ M. Southern California Edison Co 78/11/06 1p. 94133:177
- --7811160082 Monthly Oper Rept for Oct 1978

 9035.D.W. R. Bouthern California Edison Co. 78/11/02. Spp.
 94132.178.
- 7812190157 Forwards Monthly Oper Rept for Nov 1978. CURRAN.J.M. Southern California Edison Co. 78/12/06. 1p. 94340:161.
- --7812190159 Monthly Oper Rept For Nov 1978.
 GOULD, M. Southern California Edison Co. 78/12/05. 3pp.
- B. Reportable occurrences. LERs & related correspondence
- 7810183089 Data from bottom t midwater tump sentors deemed irretrievable due to instru malfunctions. Instrus replaced to personnel afmonished re importance of data retrieval. No environ impact caused by loss of data. HEAD. U.T. Southern California Edison Co. 78/10/13. 2pp. 74400: 339.
- 70:0100:57 Details reportable occurrence at subj facil. During heat treatment on 70:09:13, 2:109 lbs of fish impinged.80% of which were apotfin croakers, Occurrence not deemed to have effect on local soptfin croaker population. HEAD, J.T. Bouthern California Edison Co. 78/10/13. 2pp. 94317:015.
- 7810250123 Repts occurrence per Section 5 & 3.1(3) of Append 8 to Provisional Oper Lic DPR-13. During retrieval of settling plates both primary & backup settling plate racks were found to be severely demaged in Zone OA. Has no environ impact. HEAD. J. T. Southern California Edison Co. 78/10/18. 2pp. 74968: 312.
- 7812130280 During Insvc Inspec Test of knee support & snubbers, two weld indications were found which req repair & during anubber surveillance two snubbers failed, LER will be forwarded.
 CURRAN, J. M. Bouthern California Edison Co. 78/10/24. 2pp. 94278: 355.
- 7811140177 Forwards LER#78-011/01T-0. MODRE.J.B. Southern California Edison Co. 78/11/05. 3pp. 94394:240.
- --7811140181 LERN78-011/01T-0 on 781023: during shock & sway test: 9 shubbers were found to be inoperable & during insvritest: 4 had cracked welds. Shubber failures & cracked ettachment welds are attributed to operating transients. CURRAN-J.M. Southern California Edison Co. 78/11/06. 2pp. 94084:281.
- 7811280277 Forwards LER#78-012/03L-0. HEAD J.T. Southern California Edison Co. 78/11/21. 2pp. 943931216.
- --7811280281 LERW78-012/03L-O on 781023: seal water return line(#2014) & the discharge line(#2002) of the charging pumps dev through wall cracks due to chloride stress corrosion. Affected areas replaced w/new pipe & fittings.

 CURRAN. J. M. Southern California Edison Co. 78/11/09. ip. 74393: 218.

V. Operator Examinations

7811130132 Responds to 781011 k 24 ltrs describing training Cyrus K Anderson received in order to qualify for resumption of likensed duties. Authorizes resumption. GCULINB, P. F. Operator Licensing Branch. 78/10/31, 1p. 94076:149.

DOCKET 80-213 HADDAM NECK PLANT H. General correspondence

78:03:002: Informs that for BEP norms! channel of oral communication will be followed, but to expedite reviews direct oral communication between subj facil staff & members of BEP branch is encouraged.

ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/10.
Zpp. 94094:241.

- 7812180142 Forwards copies of insurance Endorsement#37 which emends the site description at subj facil effective 781117. SEGEN.R.M. Connecticut Yankee Atomic Power Co. 78/12/13. 1p. 94365: 274.
- --7812180131 Insurance Endorsement#57 of Policy#WF-131 Forwards new site description of subj Pecil BARDEB.C.R. Nuclear Energy Liability Insurance Association. 78/11/17. 2pp 94365:275.
- P. Operating license stage documents & correspondence
- 78i1130064 Forwards initial eval of 8 complete SEP topics & response to request for clarification of SEP documentation procedures made at 780531 meeting. Requests response re facts used to define plants by NRC staff. (See ANGR7811130337.)
 EIBENHUT, D. 9. Assistant Director for Systems Engineering (Pre 791030). 78/08/17. 2pp. 94076:227.
- 7810270404 Forwards Amend #28 to Facil Open Lic #DPR-61, changing Tech Spec re fire protec sys. ZIEMANN.D.L. Operating Reacture Branch 2 (Pre 790625). 78/10/03. 3pp.
- --7810270410 Amend#28 Lic#DPR-41.changing Tech Bpsc re fire protec aus : subj facil.
 ZIGMANN,D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/03.
 Lipp.
- --7810270413 Safety eval supporting Amend 28 to License DPR 61. Amend do not increase safety risk to Deprating Reactors Branch 2 (Pre 790625). 78/10/03. 49pp.
- --7810270417 Reviews fire protec in operating nuc pur station.

 Re-evaluation of fire protec prog resulted in identifying areas of plant in which fire could have undesirable effects on safe shutdown of reactor.

 HALLIR.E. Brockhaven National Laboratory. 78/05/10. 3pp.
- --7B10Q70422 Notice of issuance of Amend#28 for Lic#DPR-61, changing Tec Bpec re fire protec sys. 21EMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/03. 2pp.
- 7810260182 Bubmits rept re subjustil test prog on the containment of elec penetrations at subj facil. Safety related elec penetrations modified by Reychem heat-shrink tubing would qualify for the next 2 years.
 CDUNSIL. N. O. Connecticut Yankee Atomic Power Co. 78/10/10. 9pp. 94057-298
- 7810260171 Forwards addl info re main steam line break to support request for amend to Tech Bpecs. Concludes that charging pump flow is not required for remainder of the present cycle.

 COUNGIL, N. O., FEE. H. F. Connecticut Yankee Atomic Power Co. 78/10/20. Spp. 94037:273.
- 7810300125 Notice of 781026 meeting w/CT Yankee & other util using Carborundum-supplied boron-carbide. Carborundum to present status of their test prog for poison plates. HAMBACH.T.V. Operating Reactors Branch 2 (Pre 790625). 78/10/24. 2pp. 94035:145.
- 7811070302 Forwards Amend#29 to Fact Open Lic#DPR-61, deleting lic condition C(3)issued in Amend#26 dtd 780526. & rev Tech Spec re main steam line brack reanalysis.

 IlEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/24.

 2pp. 94041:001.
- --7811070307 Amend#29 to Facil Oper Lic#DPR-61, changing Tech Specs remain steam line break reanalysis.

 ZIEMANN,D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/24.
 10ms./. 94041:003.
- --7811070311 Bafety eval supporting Amend 29 to License DPR-61. Amend do not increase safety risk.

 # Operating Reactors Branch 2 (Pre 790625). 78/10/24. 5pp. 9404t: 013.
- --7811070313 Notice of Issuance of Amend#29 to Facil Oper Lic#DPR-61.
 deleting Lic Condition C(3) of Amend#26 & rev Tech Spec re
 main steam line break reamalysis.
 ZIEMANN.D.L. Operating Reactore Branch 2 (Pre 790625). 78/10/24.
 20p. 94041018.

- 7811030097 Forwards index of elec schematic drawings for subj facil. Also forwards incor or elect schematic grawings for subj facil.
 Also forwards accompanying apprature cards of cards of supplemental drawings submitted on 780929 & safety-related drawings re subj facil.evailable in CF.
 COUNSILH.G. Connecticut Yankee Atomic Power Co. 78/10/27 3pp. 02721:320.
- 7811130193 Forwards "Boron Carbide" rept prepared by Carborundum Co. describing requal prog tests & results re suby facilis
 Answers to NRC queries & other analyses are also encl. as is
 non-projectary version of Carborundum rept.
 CQUESTLATE, Northeast Utilities, 78/11/03, 14pp.
- 7811140155 Discusses Progress of NUSCO Nuc Records Prog for CN Yankee Atomic Pur & NE Nuc Energy Co Microfilming may not be completed by 790731. but hard copy will be available Asks whether projected 790731 date will be satisfactory.
 COUNSILW.O. Northeast Utilities. 78/11/06 2pp. 94393:304.
- 7811170217 Requests that submittal date for lic amend appl be changed from 781108 to 790130 Amend will incorp NRC Draft Append I Tech Specs. COUNBIL. W. Q. Connecticut Yankee Atomic Power Co 78/11/08. 3pp. 94136: 124
- 781:270:32 Forwards tabulation of data re environ qual of safety-related elec equip(SEP Topic III-12) for review & completion by licensee. ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625) 78/11/09. 9pp. 94271:290.
- 7811170208 Provides further info on proposed exemption from 10CFR50 Append J re test of continuous Air Monitoring Bysic(MS) as proposed by 770311 NRC ltm. Util proposes to commence alternated testing sys after 1979 refueling outage.

 COUNSIL-H 0. Connecticut Yankes Atomic Power Co. 78/11/13. 2pp. 94136:099.
- 7611280430 Forwards draft Bys Eval Prog Bafety inputs re Topic VIII~3. A, Station Battery Tast Req. Requests they be transmitted to licensess. DAVIB, D. K. Byste 78/11/14. 23pp. Bystematic Evaluation Programs Branch (Pre 790695).
- 7812180039 Notice of workshops re implementation of training & qual requirements contained in Append B of iOCFR/3. Requests pre-workshop registration of attendees to facilitate sending out math. W/encl Registration Form & List of Locations.
 MILLER.J.R. Assistant Director for Bite & Bafeguards (Fre 791030). 78/11/15. 5pp. 94133:036.
- 7812190025 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PWR's(NUREO-0473) & "Preparation of Rediciogical Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133). ORIMES.B.K. Assistant Director for Engineers & Projects (Pre 770623). 78/11/15. App. 94214:314.
- 7811300212 Reports on fish impingement overruns for 3 species of fish. exceeding ETS limits for month of Oct. No apparent cause is known, but no trend toward increased impingement is discerned. QRAVES:R.H. Connecticut Yankee Atomic Power Co. 78/11/16. 1p. 94073 220
- 7811270183 Responds to 780817 request for comments on Systematic Eval Prog topic assessments. Info is substantively correct, but it is suggested that these & future assessments be written w/ specific ref to documents used by NRC to form conclusions. COUNBIL. H. Q. Northeast Utilities, 78/11/20. 1p. 94272:081.
- 7812040198 Rept of BEP reviewers visit to subj facil on 780913-14 for familiarization. Consisted hydrological review of site & region outside the site & control room safety sys outside containment. H/list of participants. PONTECILLA.H.M. Systematic Evaluation Programs Branch (Pre 790625). 78/11/21. dpp. 94457:129.
- 7912070154 Notice of seminar on 781208 on new Model Rediclogical 912070134 Notice of seminar on 781208 on new Model Radiologics Effluent Tech Specs for nuc pur plants. Requests advance submission of seminar specific questions. W/encl Seminar Info Sheet, Proposed Agenda & maps. GRIER, B.H. Region 1, Philadelphia, Office of the Director. 78/11/21. Spp. 94375:200.
- 7612040303 Notification of 781207 meeting w/SEP Owner's Group in Bethesda, MD to discuss plane to address seismic input for use in SEP seismic review. LEVIN.H.A. Systematic Evaluation Progrems Branch (Pre 790625). 78/11/24. 2pp.

- 7812140033 Mat) on file is insufficient to allow tech eval re pipe breaks inside containment at subj facil Requests meeting to allow comparison of plant design to current criteria & to eval significance of potential deviations. EISENHUT, D. O. Assistant Director for Systems Engineering (Pre 791030). 78/11/28 3pp. 94127-251.
- --781214003B Discusses assessment of postulated pipe breaks inside reactor containment. H/encl SEP outline of 3 potential approaches for postulating pipe break locations.

 DAVIS. D.K. Systematic Evaluation Programs Branch (Pre 790625).
 78/07/20 13pp. 94127-254
- 7812110041 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wencl ANO: e7812080207. Operating Reactors Branch 2 (Pre 790625). 78/11/29. ZIEMANN, D. L.
 - Bpp. 94408:171.
- 7812050134 Submits ETS/NR 78-12 re rate of change of discharge temp. On 781102-reactor trip occurred during surveillance texting of pressurizer pressure & level six week setpoint check. B degree F rate of change limit exceeded No harm discorned. GRAVEB.R.H. Connecticut Yenkee Atomic Power Co. 78/11/20 Ip. 94335: 056.
- 7812210101 Intends to apply GA prog to add1 requirements of 10CFR71 to transp or delivery for transp. of matl outside site confines in Comm approved package design. COUNBIL, H. Q. Connecticut Yankee Atomic Power Co. 78/12/03. 1p. 94269: 208
- 7812280112 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuration or enforcement action will result.

 DAVIB. J. Q. Office of Inspection & Enforcement, Office of the

 Director. 78/12/06 2pp. 94310:209.
- 7812130093 Requests add1 info from 8EP licensess re elec penetrations of reactor containments in order to complete eval.
 ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/OB. 4pp. 94212.002
- 7812210082 Forwards NUREG-0485.Vol 1.No 2 "Status Summary Rept-Sys Eval Prog. " W/o and). ZIEMANN, D. L. Derating Reactors Branch 2 (Pre 790625). 78/12/08. 2pp. 94269: 130.
- 7812220061 Notifies NRC that 24-hour sample of fish impingement backet for 781112 was accidentally discarded & lost.
 QRAVEB.R.H. Connecticut Yankee Atomic Power Co. 78/12/13. 1p. 94342: 264
- 7812270106 Bummary of 781107 meeting re geology.geotechnical & seismic review.Discussions focused on Bystematic Evel Prog topics. LEVIN.H.A. Bystematic Evaluation Programs Branch (Pre 790625). 78/12/13. 4pp. 94161:037.
- G. Inspection reports. IE Bulletins & correspondence
- 7810170030 Forwards IE Bulletin#78-12: "Atypical Weld Material in Reactor Pressure Vessel Welds" requesting action w/in 50 days, & list of IE Bulletins Issued in 1978, (see AND 7B10040253) QRIER, B. H. Region 1, Philadelphia, Office of the Director. 78/09/29. 6pp. 94242:003.
- 7811100075 Forwards IE Inspec Rept#50-213/78-24 on 780911-15 during which no items of noncompliance were noted. BRUNNER, E. J. Region i. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 94179; 276.
- --7811100076 IE Inspec Rept#50-213/78-24 on 780911-15 during which no items of noncompliance were noted Major areas inspected included organization & admin, performance of audits & follows of previous audits.
 LAZARUS, W. J., KNOLL, R. M. Region 1, Philadelphia, Reactor
 Operations Nuclear Support Branch. 70/10/04. 13pp. 74179: 278.
- 7811100092 Forwards IE Inspec Rept#50-213/78-25 on 780911-13 during which no items of noncompliance were noted.

 BMITH G.H. Region i, Philadelphia, Fuel Facility & Materials Bafety Branch. 78/10/04. 2pp. 94173:299.

- 7811060182 Forwards IE Circular#78-17 (Bee AND: 7810230221, Docket #50-133, 781013)
 GRIER, B. H. Region 1, Philadelphia, Office of the Director.
 78/10/13 ip 94489, 142
- 7811300341 Forwards IE Inspec Rept#50-213/78-26 on 781013-16 during which no items of noncompliance were noted.

 8MITH-0 H. Region 1. Philadelphiae Fuel Facility & Materials Safety Branch 78/10/24 2pp. 94116-197.
- --78:1300342 IE Inspec Rept#50-213/78-26 on 781013-16 during which no items of noncompliance were noted Hajor areas inspected incl. results of effluent sample split between licensee & Region I. Noonsite time involved.
 KUITAN.J J. Region 1. Philadelphia: Fuel Facility & Materials Bafety Branch. 78/10/23 App. 94116.199.
- 7811290216 Forwards IE Circular #78-18, "UL Fire Test, "H/encl AND. 7811130002 GRIER.B H. Region 1. Philadelphia, Office of the Director. 78/11/06 1p. 94237.333.
- 7812150131 Forwards IE Bulletin878-12A suppl to IE Bulletin878-12. W/snc1 AND 7811300055 GRIER B H Region 1. Philadelphia. Office of the Director. 78/11/24 pp. 94212:169.
- R. Periodic operating reports & related correspondence
- 7810180134 Forwards Monthly Open Rept for Sept.1978 GRAVES.R. H. Connecticut Vantes Atomic Power Co. 78/10/13. 1p 94401:001
- --7810180136 Monthly Oper Rept for Bept, 1978

 * Connecticut Yankes Atomic Power Co. 78/10/13 9pp. 94401:002.
- 7810240093 Rept re fish impingement overruns. As of 780929 estimated 293 % 60 Hogchokers. 0-3"% 3-6"were impinged. exceeding monthly limits. No apparent cause can be related to plant oper changes Concludes that total numbers were small. GRAVES. R. H. Connecticut Yankee Atomic Power Co. 78/10/13. 1p.
- 7811210282 Forwards Monthly Oper Rept for Oct 1978
 CRAWES.R.H. Connecticut Yankes Atomic Power Co. 78/11/14. 1p.
 94485:205
- --7811210284 Monthly Oper Rept for Oct 1978. KCKOSZNA, C. Connecticut Yankse Atamic Power Co. 78/11/14. Spp. 94495-206
- 7812090160 Farwards rev to Monthly Oper Rept for Oct 1978 ORAVESIR: H. Connecticut Yankee Atomic Pawer Co. 78/11/28. 1p. 94336:106.
- --7812050164 Rev Monthly Oper Rept for Oct 1978. KCKO87MA.C. Connecticut Yankee Atomic Power Co. 78/11/14. 7pp. 94329-107.
- 7812210201 Forwards Monthly Open Rept for Nov 1978. ORAVEB.R H. Connecticut Yankee Atomic Power Cq. 78/12/13. 1p. 94279-070
- --7812210204 Monthly Oper Rept for Nov 1978.

 ANDERSON, D. Connecticut Yankee Atomic Power Co. 78/11/13. Bpp. 94279:080.
- S. Reportable occurrences, LERs & related correspondence
- 78:1240163 Notifies NRC of Reportable Occurrence 78-02/1P: QE terminal block in aluminum box falled during test of ability to perform under conservative values of voltage, temp & pressure w/saturated stem present. Rept to follow. 16 QRAMEB/R. H. Connecticut Yankee Atomic Power Co. 78/03/23. ip. 94457: 071.
- 7811210378 Forwards LER#78-002/01T-0.

 QRAVES.R H. Connecticut Yantes Atomic Power Co. 78/04/04. 1p. 94489:149.

- test of terminal block/box combinations elec degradation was observed on QE Co terminal block type EB-25 mounted in aluminum terminal box due to contact w/aluminum box FLEMINO. 8 T Connecticut Yankee Atomic Power Co. 78/04/04. 2pp. 94485.150.
- 7811210309 Forwards LER#78-002/01X-1. QRAVEB.R M. Connecticut Yankee Atomic Power Co. 78/09/25. 1p. 94488-086
- ---7811210311 LERW78-002/01X-1 on 780322 elec degradation observed on a QE terminal block type E8 & 25 mounted in aluminum terminal box. Failure traced to interfecing w/aluminum boxes Aluminum boxes replaced w/steel boxes. FLEMING S. T. Connecticut Yanies Atomic Power Co. 78/09/25. 2pp. 74488-087
- 7810130166 Forwards LER#78-019/03L-0.

 ORANESHR H Connecticut Yankes Atomic Power Co. 78/10/06 1p. 94003.049.
- --7810130169 LERW78-019/03L-0 on 780909: Alarm indicated #2 high steam flow indicator had failed low Caused by fuse failure Load reducttion started until trip signal put in the logic. Plant load returned to full power & fuse replaced.

 LEVING, J. M. Connecticut Yankee Atomic Power Co. 78/10/06. ip. 94003.090.
- 7810250106 Forwards LER#78-020/03L-0.

 ORAVES.R.H. Connecticut Yankee Atomic Power Co. 78/10/17. 1p.
- --7810250110 LERM7B-020/03L-0 on 781004: during normal oper, Svc manualauto selector switch on pRC-401-1 Charging Flow Recorder/ Controller failed. Caused by component and of life. FERQUSON, J. H. Connecticut Yankee Atomic Power Co. 78/10/16. 2pp.
- 7811060103 Forwards Reportable Occurrence Rept for third quarter 1978 radioactivity in river water. QRAVES.R.H. Connecticut Yankee Atomic Power Co. 28/10/27. 3pp. 94422-297
- --7811060107 Reportable Occurrence on 781027: levels of tritium activity observed in quarterly composite of river water near discharge area exceeded Middletown Control Bettion by greater than a factor of 10. Caused by seasonal river flow.

 4 Connecticut Yankee Atomic Power Co. 78/10/27. 2pp. 94424: 298.
- U. Congressional/Executive Correspondence
- 7810140036 Response to 780911 ltr for comments re individuals who are conterned over radioactive milk contamination in area near facti. Forwards NRC preliminary svaluation of Steinglass rept on Strontium-90 levels in milk near subj facti.
 DIRCKS.W.J. Office of the Executive Director for Operations. 78/10/06 2pp. 94329:073.
- --7810140039 Responds to 771115 ltr requesting NRC to evaluate Bterngle rept re strontium-90 & Cesium-137 in milk from farms near subj facil. Concludes no relationship between elevated radioactive milk level & subj facil.
 HBNDR1E, J. M. Commissioners. 78/01/18. 2pp. 94329:075.
- --7810140043 Forwards add1 NRC comments by M Goldman re allegation rais by Dr Sternglass concerning levels of strontium & Cesium near subjfacil. Concludes risks from exposure to low level radiat exposure small. DENTON, M.R. Office of Nuclear Reactor Regulation, Director. 78/07/27. 1p. 94329:082.
- --7810140045 Review & comment of rept by Dr Sternglass re radioactivity haslth statistics around nuc facil in CT.Finds no support for contention that CT nuc plants have released sufficient radionuclides to cause significant radiat exposure.

 OCLOMAN. If California, Univ. of, Davis. 78/05/31, 4pp. 94329-083
- --781014004B Review of Dr Sternglass rept. Concludes date does not supplicontention that nuc reactors have contributed to significant increases in Strontium-90 & Cestum-137 in milk. Additionally, rept did not consider effluent monitoring from reactor. COBTLE.D.M. Environmental Protection Agency. 78/08/09. 10pp. 94329:087.
- 7812050043 Responds to 78103: Itr.States that all present info is so limited that no meaningful comparisons can be made of the level of radioactivity in desiries near subj facils & deiries in other regions of the State.

 DIRCKS:M.J. Diffice of the Executive Director for Operations.
 78/11/27. 2pp. 94334:119.

20050044 Ack receipt of eval of Sterngless rept Requests any NRC or therngless date indicating radioactivity concentrations of the reas of the State.

CEDD: C. J. House of Rep. 78/10/31 2pp. 94334:121.

T 50-219 OYSTER CREEK NUCLEAR POWER PLANT
CUrity, medical, smergency & Fire protection plans

40:194 Responds to 780914 NRC itr requesting inclusion of early niss of local auth in facil Emergincy Plan. Plan rev will Completed by 790131. Forwards Itrs of agreement & codures of determining dose received.
FREICK, I.R. Jersey Central Power & Light Co. 78/11/16. 27pp. 58: 315.

judicatory correspondence

SO 483 Notice of w/drawal of Appearance by E Friedell & Notice of eartence by C Moodhead as counsel representing NRC in the subjection of Bvc encl.
EDELLE B.: HOODHEAD, C. P. Office of the Executive Legal Director.
/11/03 4pp.

SQ OB5 Forwards environ Tech Spec for subj facil, prepared by NRC ff. Applicant has agreed to imposition of the spec. Wienci 311 Order w/Cert of Svc. 751114 joint motion to terminate Ting & Tech SpeceNUREG-0488.
EDELL, E. 8., HODDHEAD. C. P. Office of the Executive Legal Director. /11/03. 122pp. 94336:175.

meral correspondence

IOO34 Informs that for SEP normal channel of oral communication is be followed, but to expedite reviews direct oral meanication between subj facil staff & members of SEP nch is encouraged.

MANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/10... 74074:358.

OO148 Appointment of new liceneing mgr for GPU Bvc Corp. LACE,E.9. General Public Utilities - GPU Bervice Corp. 78/10/23. 9403:115.

swrence & indemnity information

BDO66 Forwards copy of endorsement #61 to Nuc Liebility Insurance i∈ y NF-164.
EAU#4.N. General Public Utilities - GPU Service Corp. 78/10/04.

40132 Forwards Endorsement#47 to Nuc Energy Liebility Insurance ~44 for subj facil. EA-U, N. Osmeral Public Utilities - OPU Service Corp. 78/10/19

errating license stage documents & correspondence

SOOOS forwards initial eval of 8 complete SEP topics & response to use of all filtration of SEP documentation procedures at 700331 meeting. Requeste response re facts used to irre plants by NRC staff. (8se ANO87811130337.)

ENHUT.D.O. Assistant Director for Systems Engineering (Pre DGSO), 78/08/17, 2pp. 94076:339.

60014 Summary of 780428 meeting w/Jersey Central Pur & Light recurse Use of Prepressurized Fuel Rods in Lead Test embly in Suby Reactor during Next Fuel Cycle. W/encl list attendes.

1CMI.B.J. Operating Reactors Brench 2 (Pre 790625). 78/08/21.
94318:291.

DODIO Forwards Notice of Proposed Issuance of Amend to Provisional r LiceDPR-16. Amend would change Tech Spec to rev Maximum range Planer Linear Heat Generation Rate limits for Exxon 1 Types IIIE, IIIF, V & VB. ***

**ANN.D.L. Derating Reactors Branch 2 (Pre 790625). 78/09/01. 94179:269.

il COO19 Notice of Proposed Issuence of Amend to Provisional Oper Lic CPR-16. Amend would rev Maximum Average Planer Linear Heat streetation Rate limits for certain fuels. Petitions for Issue of intervene must be filed by 781011.
IEMANN.D.L. Operating Reactors Branch 2 (Pre 790625), 78/09/01.
pp. 94179:271.

- 78:01:01:18 Forwards add1 info requested by NRC staff re Tech Spec Change Request #49(Rev#1) submitted 780806 Concerns core spray line & Feedwater line breaks effects on analysis & Tech Spec limits
 FINFRICK I R. Jersey Central Power & Light Co. 78/10/03 19pp 74067:304.
- 7810190045 Concludes tech specs should incl limiting conditions for oper & surveillance requirements for hydrogen content & hydrogen monitors in the off gas sys Requests such specs be proposed as suppl to 780503 appl ILEMANN,D L. Operating Reactors Branch 2 (Pre 790525). 78/10/03.608.
- 7810260018 Confirms understanding that there will be prompt corp review of onsite radiat protec prop per 780809 ltr.
 ALLAN-J M. Region I. Philadelphia. Office of the Director.
 78/10/06 ip. 94410-057.
- 7810160115 Forwards request to amend Tech Spec so that specs will be consistent w/125V DC Mod currently being installed. Tech Spec surveillance requirements will be clarified by emend to conform w/current 125V DC surveillance standards FINFROCK, I R. Jarsey Central Power & Light Co. 78/10/10. 4pp. 94005 1891
- --7810160120 Request for amend to Tech Specs re-provisional operating lic #DPR-16. Change would make specs consistent w/125V DC mod & w/current surveillance requirements. FINFRCCK, I. R. Jersey Central Power & Light Co. 78/10/10. Spp. 94005-187
- 7810160143 Ack receipt of 780807 NRC ltr re deficiencies in subj facil reactor protec sys pur supply Continuous surveillance is being performed. Sequence of events of low probability of occurence.
 FINRROCK, I. R. Jersey Central Power & Light Co. 78/10/10. 1p. 94004:073
- 7Bi03i029B Forwards corrected page 1.05 which incl Bection L.24 & page 1 to make Table of Contents consistent w/contents.
 ZIEMANN,D.L. Operating Reactors Branch 2 (Pre 790625). 7B/10/10.
 App. 94089: 055
- 7810170240 Forwards check for \$12,300 as requested by 780831 NRC steff ltr.Rev of proposed ltc indicates it is in Class III instead of Class IV because amend is addressing single issue & ecceptability of it is clearly defined by an NRC position. FINEROCK.I.R. Jersey Central Power & Light Co. 78/10/12. 1p. 94242:158.
- 7810240020 Requests Class IV fee JCP&L for request relating to MAPLHOR of several fuel types for subj facil. W/o encl NRC 780831 to JCPL which is already on file in PDR.
 HILLER.W.D. License Fee Management Branch. 78/10/13. 2pp.
- 7810300157 Appointment of new licensing mgr for QPU 8vc Corp.

 WALLACE, E. Q. Qeneral Public Utilities QPU Bervice Corp. 78/10/23.

 1p. 94035:117.
- 7811070304 Notice that util will use the following shipping containers: Model#NAGO: HNROO, HNIOOS: HNIOO series 1 & 2. FINFRICK.1.R. Jeresy Central Power & Light Co. 78/10/23. ip. 94041: 021.
- 7811030114 In response to 780626 ltr forwards current revs of drawings in order to facilitate BEP Prog review w/encl index to drawings & 79 oversize drawings. Available in CF only. FINFROCK, I.R. Jersey Central Power & Light Co. 78/10/24. 82pg.
- 7Bill00156 Requests add1 info on ESF Switchover from injection to recirculation mode, isolation of reactor protect sys from nonsefecty sys.ESF sys logic & design, specific drawings of site sys & complete plant elec drawing indices.

 ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625), 78/10/26.

 3pp. 94047: 189.
- 7811130335 Summary of 780914 meeting w/gE representatives & Mark 1 Dwners Group re-progress of Long Term Prog w/attendance list & agenda(RD-9-A-Marki, Standards) GRIMES.C. Plant Systems Branch (Pre-791030), 78/10/26, 67pp. 94007:225.
- 7B11060164 Responds to 780925 ltr granting change in reporting date for second 1978 semiannual rept for Nuc Matl Inventory from 780930 to 781031. One time change is granted because present refueling results in inventory change.

 ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/29.
 1p. 94489:081.

- 7811220129 Lists containers to be utilized by JCPL for shipment of radioactive matl generated by subj facil Package approval on container has been issued to Chem Nuc Bys. Inc. FINFROCK, I R Jersey Central Power & Light Co 78/11/08 ip.
- 7811290095 Forwards Amend#33 to Provisional Open Lic#DPR-16 rev Tech Specs as requested in 780330 Appl w/Safety Evaluation & Notice of Issuance. ZIEMANN.D.L. Operating Reactors Oranch 2 (Pre 790625). 78/11/11 2pp. 94238 204
- --7811290099 Amend#33 to Provisional Oper Lic#DPR-16 rev Tech Specs re MAPLHOR limits for Exten Fuel types III E.F.V & V8 & adding MAPLHOR multiplier ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625). 78/11/11 1499 94238 206
- --7811290104 Safety Evaluation supporting Amend#33 to Provisional Oper Lic#DPR-16 concluding that proposed changes to MAPLHR limit are acceptable contain adequate safety margins & will not be inimical to health & safety of pub # Office of Nuclear Reactor Regulation. Director 78/J1/11 App. 94238: 220
- --7811290106 Notice of Issuance of Amend #33 to Provisional Oper Lic# DRR-16 rev MAPLHOR limits ZIEMANN, D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/11. 200. 94236:224
- 7811280430 Forwards draft Bys Eval Prog Bafety inputs re Topic VIII-3 A. Bitation Battery Test Req Requests they be transmitted to licensees. DAVIS.D H. Bystematic Evaluation Programs Branch (Pre 790625) 78/11/14. 23pp.
- 7811200160 Requests NRC review & approval of Tech Spec change#68 to Append A of Provisional Oper LiceDPR-16. Change will allow for augmented insec inspec of core spray sys spargers & clarify bases upon which core spray sys is operable. FINEROCK, I. R. Jersey Central Power & Light Co. 78/11/15. 1p. 94475-016
- --7811200164 Tech Spec Change Request M6B, submitted by JCPL Change alters sactions 3.4 & 4.3 to core spray sys Also enct is Repair Proposal M320-78-1 & drawing of spenger repair bracket assembly.

 FINFROCK, 1. R. Jersey Central Power & Light Co. 78/11/15. 48pp. 94475-017
- 7812150193 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out math. W/encl Registration Form & List of Locations.
 MILLER, J. R. Assistant Director for Bite & Safeguards (Pre 791030). 78/11/15 5pp
- 78:218025t Forwards Rev#i "Draft Radiological Effluent Tech Specs" for BWR's (NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133) GRIMES D.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94365.245
- 7812070209 Notice of seminer on 781208 on new Model Radiological Effluent Tech Space for nuc pur plants. Requests advance submission of seminar specific questions. W/encl Seminar Info Sheet. Proposed Agenda & maps.

 ORIET, B. H. Region 1. Philadelphia, Dffice of the Director. 78/11/21. Spp. 03555-120.
- 7811280262 Request for exemption from certain provisions of 10CFR50, Append U. Gen Design Criteria Mod 760812 exemption request. Covers Types A.B & C Test Requirement & exemption requests. FINFROCK-I.R. Jersey Central Power & Light Co. 78/11/22. 16pp. 07174:231.
- 7812060420 Forwards Page 3.10-2 of App A to Tech Specs containing correct LHGR's for fuel types III E & III F issued w/Amend #33 to LiceOPR-16 on 781111.
 ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/22.
 3pp. 94084:357.
- 7812080214 Summary of 781103 meeting to discuss proposed repair of subj facil cracked core spray spanger. Forwards Jersey Central Pur & Light Core proposed repair of crack & list of attendaes.

 NONICKLS. J. Operating Reactors Branch 2 (Pre 790625). 78/11/22. 19pp. 94137:055.

- --7812130345 Amend#34 to Provisional Oper Lic#DPR-16 W/encl #mend#d Tech Spece. ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/24. 6pp. 94307:324.
- --78:2:3035: Safety evaluation supporting Ahand #34 to Provisional Oper Lic#DPR-16. * Office of Nuclear Reactor Regulation, Director. 78/11/24. Bpp.
- --7812130359 Notice of Issuance of Amend #34 to Provisional Oper Lic #DRR-16 SILVER.R.D. Operating Reactors Branch 2 (Pre 790625). 78/11/24. 2pp 94307-339.
- 7812080239 Notification of 781130 meeting re-difficulty of obtaining reload fuel, possibility of reloading mixed cores from various vendors impact on lic reviews & scheduling. NDWICKI, B. J. Deparating Reactors Branch 2 (Pre 790623). 78/11/28, 1p. 94137.193
- 78:2110066 Discusses possible dangers of LDCA in containment purging during normal plant open. Requests either commitment to limit purging or justification for continuing Wiencl AND: W78:12080207.
 ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/29.
- 7812200116 Ack receipt of 781117 util ltr to State of NJ containing info on repair of core spray sparger.
 BRUNNER,E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/29, 2pp. 94159:110.

Bpp 94338 189

- ~~7812200276 Ack 781031 request for info re Core Sparger clamping device.
 Info will be released if licensee does not justify
 withholding IAW 10CFR2.790.
 BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear
 Bupport Branch. 78/11/03. 1p. 94159:112.
- --7812200280 Informs util of 781027 State of NJ request for info re Core Spray Sperger, Unless info is claimed as proprietary IAW 10CFR2.790 in 20 days, info will be released. SRWNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/03. ip. 94159:113.
- 7812110326 Responds to 780510 ltr. Feedwater trip on high reactor level not necessary for safe operation. Forwards eafety evaluation. 21EMANN, DL Operating Reactors Branch 2 (Pre 790625). 78/11/30. 2pp. 94204:234.
- --7812110029 Safety Evaluation concluding feedwater pump trip on high reactor level is unnecessary for safe operation of facility.

 * Operating Reactors Branch 2 (Pre 790625). 78/11/30. 2pp. 94204-236
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held a providing task-by-tesk activity summary for the morth. 6080N-b.J. General Electric Co. 78/12/04. 11pp. 94103:174.
- 7812280165 Emphasizes importance of submitting accurate k complete info to NRC by licensee & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J. G. Office of Inspection & Enforcement, Office of the Director. 78712706. 2pp. 94374:360.
- 7812150108 Requests add1 info from SEP licensess relect penetrations of tractor containments in order to complete eval.
 21EMANN.D.L. Operating Reactors Branch 2 (Fre 790625). 78/12/08.
 4pp. 94212:137.
- 7812210095 Forwards NUREG-0485.Vol 1.No 2 "Status Summary Rept-Sys Eval Prog." W/o encl. ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/08. 2pp. 94269:160.
- 7812270048 Requests comments on SEP Topic V~10. A "Residual Heat Removal Bys Heat Exchanger Tube Failures." Into inclidatection & control of radioactive leakage.auxiliary cooling water sys & primery coolant sys.

 ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625). 78/12/13.
 6pp. 94160:295.

- 7812220108 Summary of 781130 meeting w/util to discuss lic requirements of reload submittal using reload fuel from more than I vendor Util requested a future meeting NOMICKLS J. Operating Reactors Granch 3 (Pre 790625) 78/12/18 3pp 94344.138.
- 7812270185 Forwards review of qual tables completed to date plus identity of appropriate references & confirmation of accuracy & completeness of the tables FINRECK: I R Jersey Central Power & Light Co 78/12/19 5pp. 9401B 001
- G. Inspection reports. IE Bulletins & correspondence
- 7810290226 Forwards IE Inspec Rept#50-219/78-21 on 780830-31 during which no items of nancompliance were nated. BRUNNER.E. J. Region I. Philadelphia. Reactor Operations Nuclear Support Branch 78/09/18 2pp 94093 048 Support Branch
- --7810250227 IE Inspec Rept#50-219/78-21 on 780830-31 during which no items of noncompliance were noted Major areas inspected included review of Monthly Statistical Repts & control room MCCABE.E.C Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 78/09/18 Spp 94393 050
- 7810160243 Forwards IE Bulletin#78-12 "Atypical Weld Material in Reactor Pressure Vessel Welds" requesting action w/in 60 days.& list of IE Bulletin issued in 1978 (See AND# 7810040253) CRIER.B.H Region 1. Philadelphia, Office of the Director. 78/09/29. 6pp 94003.315
- 7811060197 Forwards IE Circular#78-17 (See AND 7810230221. Docket #50-133, 781013. 1 ORIER 9 H Region 1. Philadelphia. Office of the Director 78/10/13 19 94489-184
- 7811080293 Ack receipt of 781004 ltr informing NRC of steps taken to correct violations noted during Inspec#50-219/78-20 SMITH.Q.H. Region I, Philadelphia. Fuel Facility & Materials Safety Branch, 78/10/19, 10 94406-127.
- ~-7811080238 Responds to 780913 NRC itr re violations noted in Inspec Rept#50-219/78-20. Corrective actions: dosimeters stored in emergency kits will be placed on dosimeter calibr tickler sheet. ROSE D A Jersey Central Power & Light Co 78/10/04 ip. 94405.128
- --7811080260 Farwards IE Inapec Rept#50-219/78-20 on 780822 & Notice of VIDIATION. CROCKER H. W. Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch 78/09/13 2pp. 94406:129
- --7811080264 Notice of Violation from inspec on 780822-24.

 4 Region 1. Philadelphia, Evel Facility & Materials Safety Branch.
 78/09/13 1p 94406:131.
- --7811080268 IE Inspec Rept#50-219/78-20 on 780822-24 during which 1 item of noncompliance was noted: Pailure to spike & leak test self-reading dosimeters prior to being placed into svc. DONALDSDN.D.E. Region i Philadelphia Fuel Facility & Materials Bafety Branch. 78/09/ii. Bpp. 94406:132
- 7811080229 Ack receipt of 781006 ltr informing NRC of steps taken to correct violations noted during inspects0-219/78-19.

 BRUNER,E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/20. 1p. 94406-007.
- --7811080234 Responds to 780915 NRC ltr re violation noted in Inspec Rept #50-219/78-19. Corrective actions reamphasis of importance of proper classifying of job orders & review of surveillance procedures R088.D A Jersey Central Power & Light Co 78/10/06 2pp 9440A: 00B
- --7811080238 Forwards IE Inspet Rept #50-219/78-19 on 780822-25 & Notice of Violation BRUNNER.E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/15. 2pp. 94406:010.
- --7811080242 Notice of Violation from inspec on 780822-25 * Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/15. 2pp. 94406:012.

- Region 1. Philadelphia Reactor Operations Nuclear BAUNACK, IJ H Support Branch 78/09/12 14pp 94406 014
- 7812010275 Forwards IE Inspec Rept#90-219/78-25 on 780926-29 during which no items of noncompliance were noted BRUNNER. E. J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch 78/10/23 2pp 94417 217
- --7812010276 IE Inspec Rept#50-219/78-25 on 780926-29 during which no items of noncompliance were noted Major areas suspected incl refueling outage maintenance procedures & follow up of non-routine Event Rept 78-18 BRIGOS.L., KALMAN, O. Region 1, Philadelphia, Office of the Director 78/10/20 6pp 94417 219
- 7812010345 Forwards licensee performance evaluation for Region 1 No operating reactor in Region I is considered to have either abnormal or unusual safety concern. GRIER, D.H. Region i, Philadelphia, Office of the Director 78/11/01 4pp 944:8 294
- 7811290208 Forwards JE Circular #78-18, "UL Fire Test "W/encl AND 7811150002 QRIER, D.H. Region i. Philadelphia. Office of the Director 78/11/06. ip 94238 033
- 7912070284 Art roceipt of 781024 ltr informing NRC of steps taken to correct violations noted during inequals 0-219/78-22 BRUNNER.E J Region i. Philadelphia. Reactor Operations Nuclear Bupport Branch 78/11/16 ip 94005-223.
- --7812070288 Responds NRC 781004 1tr re violations noted in Inspec Rep 50-219/78-22 Corrective actions; snubbers inspected & snubber accumulator oil level corrected ROBS.D A Jersey Central Power & Light Co 78/10/24. 3pp 94085:224
- --7812070290 Forwards IE Inspec Rept#50-219/78-22 on 780905-07 & Notic of Violation
 GRIER, B.H. Region 1: Philadelphia. Office of the Diroctor
 78/10/04 2pp 94085.227
- --7812070291 Notice of Violation from inspec on 780905-07. * Region 1, Philadelphia, Office of the Director 78/10/24 1p 94085, 229,
- --7812070295 1E Inspec Rept#50-219/78-22 on 780905-07 during which 2 items of noncompliance were noted failure to inspect 2 enubbars during periodic snubber inspect & failure to inspect 2 enubbars during periodic snubber inspect & failure to failow procedure during snubber inspec & failure to failow procedure during snubber inspec CCLEMAN. B. A. Raylon 1. Philadelphia, Office of the Director 78/09/28. 7pp 94085 230
- 7Bi2010130 Ack receipt of 7Bi030 ltr informing NRC of steps taken to correct violations noted during inspeces0-219/7B-24
 BRUNNER,E J Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 78/11/20 ip 94418.061
- --7812010131 Responds to 781006 NRC ltr re violation noted in Inspec R #50~219/78~24 Corrective actions replaced prints w/latest rev in Document Center.Compliance achieved 780922. ROSS.D.A Jersey Central Power & Light Co 78/10/30 2pp. 94418 062
- --7812010132 Forwards IE Inspec Rept#50-219/78-24 on 780919-21 & Notic of Violation BRUNNER.E J. Region i. Philadelphia. Reactor Construction & Engineering Support Branck. 78/10/06 2pp 94418:064.
- --7812010134 Notice of Violation from inspec on 780919-21 * Region 1, Philadelphia, Office of the Director 78/10/04 1p 94418 066
- --7812010136 IE Inspec Rept#50-219/78-24 on 780919-21 during which 1 of noncompliance was noted failure to use controlled & up-to-date drawings. HIGGINS.J.C., WONG.H.J., FOLEY.T. Region 1, Philadelphia, Dffice of the Director. 78/10/04 Spp. 94418.067.
- 78:2150142 Forwards 1E Bulletin#78-12A.suppl to 1E Bulletin#78-12 W/encl ANG 7811300053. ORIER.B.H. Region i, Philadelphia. Office of the Director. 78/11/24. ip. 94212.196.

- 7810170200 Forwards 1977 effluent release data w/suggested corrections in margin FINFRCCK, I R Jersey Central Power & Light Co 78/10/31 4pp. 940% 747

- 7810270097 'Woodborer Study Associated U/Subj Facil Generating Station' for 780504 to 780610. RICHAROB. B R. DELMORE.C L. HILLMAN.R E Battelle Hemoriel Institute. Columbus Laboratories. 78/09/15 14pp 94059:763
- 7810270094 Forwards copies of "Thirteenth Quarterly Hoodborer Study Rept 780305-780810 " FINFRDCK.1 R Jersey Central Power & Light Co 78/10/20 Jg 24059 262
- 7811210239 Forcards Monthly Open Rept for Oct 1978 RDSS.D A. Jersey Central Power & Light Co. 78/11/14. Ip 94487 342.
- --7811210241 Monthly Open Rept for Oct 1978.
 MCCLAIN, C M Jerseq Central Power & Light Co 78/11/14 8pp 94487 343
- 7812200180 Forwards Monthly Open Rept for Nov 1978. ROSS.D A Jersey Central Power & Light Co. 78/12/14. Ip 94158-344
- ---7812200182 Monthly Open Rept for Nov 1978

 MCCLAIN.C H Jersey Central Power & Light Co 78/12/14 6pp

 94158 345 --
- 8. Reportable occurrences. LERs & related correspondence
- 7811090202 Requests info on occurrences of contro) ross failing to fully insert to position. Reply is requested in 30 days. Recommend maint of ongoing tabulation of any addl events. ZIEMANN.D E. Operating Reactors Branch 2 (Pre 790625) 78/09/06 2pp. 94038:265
- 7810100070 Forwards LER#78-018/017-0. ROSS D.A. Jerbey Central Power & Light Co. 78/09/29. ip. 94033-078
- --7810100075 LERM78-018/017-0 on 780916-3 M81vs(N903A, N804A, N804B) had leakage rates in excess of maximum allowable due to stem packing, cracked stellite weld & fellume of main poppet to seat properly M81V fellumes being investigated RGSB, p.A. Jersey Central Power & Light Co. 78/09/29. 4pp.
- 781012007) Forwards LERN78-020/03L-0. R088.D.A. Jeresy Central Power & Light Co. 78/10/05 lp. 94983-109.
- --7810120076 LERWT8-020/03L-0 on 780917 Tech Specs Table 3.1.1.A.9 violated when Intermediate Range Monitor Channel 17 became inoper in addition to IRM Chennel 16 which was already inoper due to maint activities performed under react vessel ROSB.D. A Jersey Central Pawer & Light Co. 78/10/05 3pp. 94393-110
- 7810180006 Forwards LERM78-017/03L-Q ROBS.D A. Jersey Central Power & Light Co. 78/10/12. ip. 94422:018
- --7810180007 LCR#78-017/03L-0 on 780914 Circuit breaker for motor operated valve tripped when valve closed by isolation signal Caused by corponant failure allowing switch setting to shift. Setting corrected & set screw tightened. RCBS.D.A. Jersey Central Power & Light Co. 78/10/12 3pp 94422.019.
- 7810240105 Forwards LER#78-019/03L-0.
 ROSS D.A Jersey Central Power & Light Co. 78/10/16 ip.

- thamber air operated vacuum treakers V-26-16 & V-26-18 ware found inoperatis. Attributed to lack of lubrication & operator linkage misalignment ROSS.D.A. Jersey Central Power & Light Co. 78/10/16 ip
- 7811080100 RD 50-219/78-21/1P on 781017 discovered possible crack in core spray sparger piping, possibly causing loss of redundany in core spray sys. Further investigation being conducted CARROLL, J.T. Jersey Central Power & Light Co. 78/10/18 3pp 94339 081
- 7811070105 Responds to 780906 NRC ltr re failure of control rod to fully insert on screen signal. There was 1 such occurrence on 771203 in future such events will be recorded to enhance data recovery, though no special effort made to date. FINEROCK, 1 R. Jersey Central Power & Light Co. 78/10/30. 1p 94043-337
- 7811200204 Forwards LERM-022/03L-0 ROSS D.A. Jersey Central Power & Light Co. 78/11/15 1p. 94252:041.
- --7811200207 LER#78-022/03L-0 on 781017 during routing surveillance to of Standby Ges Treatment Bys. the Bys II Discharge Valve failed to open due to stuck solenoid in control air supply to operator for V-28-30.

 RDBS.D A. Jersey Central Power & Light Co. 78/11/15. 3pp. 94252 042
- 7811210321 Forwards LER#78-023/03L-0. RDS8-D A Jersey Central Power & Light Co 78/11/15 ip 94485-263
- --7811210324 LERM78-023/03L-0 on 781019: IRM 12 became inoperative whicable to TRM 14 was disconnected. IRM 12 failure attributed to meint activities under vessel Subesquent inspec showed IRM 12 cable damaged.
 RCSB-0 A. Jersey Central Power & Light Co. 78/11/15. 3pp. 94405.264.
- 7811280193 Forwards LER#78-024/03L-0. ROSS.D.A. Jersey Central Power & Light Co. 78/11/16. ip. 94013:247
- --7811280196 LERW78-024/03L-0 on 781018; isolation valve V-7-31 had damaged nubber seat & drain valve V-7-29 obstructed by place of cork & filter F-1-58 medium disintegrated Cause of V-7-31 & F-7-58 degradations due to detonations in eye. RDS8-0.A. Jersey Central Power & Light Co. 78/11/16 3pp. 94013-248
- --7812110097 ROMSO-219/78/21-1P on 781121: Torus to Reactor Bidg differential pressure switches OP8-66A & B had ruptured disphrams due to excessive containment pressure.

 GUINTENZ.T.E. Jersey Central Power & Light Co. 78/11/22. 2pp 94338 32A.
- 7812280231 Forwards Reportable Occurance Rept#50-219/29-1P CARROLLIJ T Jersey Central Power & Light Co. 78/11/30. ip. 94373:242.
- --7812280236 Reportable Occurence ReptM50-219/78/29-ip:on 781129. containment leakage rate was greater than allowable caused by failure of Isolation Condenser Vent Valves. Dypmes1 Vent Valves & DPB66A Switches. Valves repaired & replaced. FICKEISSEN.X.O. Jersey Central Power & Light Co. 78/11/30. 3pp 94373-243.
- 7812290089 Farwards Reportable Occurence Rept#50-219/78/28-LP.
 CARROLLULT Jersey Central Power & Light Co. 78/11/30. 1p.
 94190: 109.
- --7812290097 Reportable Occurence Rept#50-219/78/28-1P on 781129: Main Steam Line Drain Valve & TIP isolation valve for TIPs 1-1 & 1-3 failed to close 6427 relay replaced Main Steam Drain Valve repaired & TIP Sys switches & logic adjusted GUINTENZ.T E. Jersey Central Power & Light Co. 78/11/30. 2pp. 94190, 109.
- 7812070218 Forwards LER#78-025/03L-0. ROBS.D.A. Jersey Central Power & Light Co. 78/12/01. 1p. 03555.090

- leaking due to galvanic corrosion Leak & other weak spots were patch welded ROS9.DA Jersey Central Power & Light Co 78/11/30. 3pp 0:3555:091
- '812120133 Forwards LER 78-026/01T-0.
 FINEROCK, I.R. Jersey Central Power & Light Co 78/12/05 1p
- --7812120136 LER 78-026/01T-0 on 781121 torus-to-reactor bldg differential pressure suitches DPB-66A & Dad ruptured diaphrams (aused by excessive differential pressures FINFROCK, I R. Jersey Central Power & Light Co. 78/12/05 3pp. 94276:177
- '812120123 Forwards LER 78-026/017-1 FINEROCK, F.R. Jersey Central Power & Light Co. 78/12/07. 1p.
- -7812120127 LER 78-026/01T-1: on 781121, during performance of integrated primary containment look rate test torus-to-reactor bldg differential pressure switches found to have ruptured diaphragms. Caused by design failure of switches FINFROCK.I.R Jersey Central Power & Light Co 78/12/03. 3pp
- 812160204 Forwards LER#78-020/017-0 FINFROCK,I.R. Jeresy Central Power & Light Co 76/12/13 ip 94345 050
- -7812180208 LERM7B-028/01T-0 on 781129 during test,main steam line drain valve V-1-106 did not close 2 incore probes.did not fully w/drew & reactor conlent valve did not indicate closed Due to jammed armature.faulty fuse holder & incorrect settings. FINFROCK, I. R. Jersey Central Power & Light Co. 78/12/13 Opp 94365:031.
- 812190105 Forwards LER#78-029/01T-0. FINFROCK.1.R. Jersey Central Power & Light Co. 78/12/14 1 94381:193
- -7812190107 LERM78-029/01T-Q on 781129 during test noted that containment leakage rate greater than allowable. Discovered that vent valves were leaking. Caused by leakage past the secting surfaces.

 RCSB.D.A. Jersey Central Power & Light Co 78/12/14. 3pp. 94081:194.
- 812200236 Forwards preliminary Reportable Occurrence#50-219/78/33-1P CARROLL, J. Jersey Central Power & Light Co. 78/12/14 1p.
- -7B12200240 Reportable Dicurrence#50-219/7B/33-1P on 7B1214 during routine reactor startup following scram from full pure reactor scram in range 1 of IRMs occurred for less than 5 seconds. There was no safety eignificance.

 RCNE.A.H. Jersey Central Power & Light Co. 7B/12/14 2pp 94162.339
- 812270316 Forwards LERM78-027/03L-0. ROBS.D.A. Jersey Central Power & Light Co. 78/12/21. 1p. 94230:354
- -7812270323 LER#78-027/03L-0 on 781125; switch RE03C was found to trip at pressure less conservative(1075 psig)than specified in Tech Epecs 2.3.5 Cause of pressure switch tripping is attributed to sensor repeatability.

 RDS8.D.A. Jersey Central Power & Light Co. 78/12/21. 3pp. 94230:355.
- 912270213 Forwards LER#78-030/03L-0. ROSB D. A. Jersey Central Power & Light Co. 78/12/22. 1p. 94190:357.
- -7812290219 LER#78-030/03L-O on 781126: during testing containment spray pumps 51C & 51A failed to start on signal due to excess friction in circuit breaker trip bar bearings. Bearings were cleaned & lubricated.
 ROBS:D.A. Jersey Central Power & Light Co. 78/12/22. 3pp. 94490:358

- F Security, medical, emergency & fire protection plans
- 7810170188 Forwards add1 info as requested in 780710 ltr re subj facil Fire Protec Prog. incl organizational chart, fire & security emergency, equipment for safe shutdown.instru & station air system for shutdown system failure analysis DISE, D.P. Niagara Mohauk Power Corp. 78/10/06 101pp. 94239-096
- 7811290192 Forwards requested info.Fire Pump Test Curves.Fire Main Connections.Floor Drain Sys Drawings(27).Test Plan & Specs For Pipe & Cable Penetration Fire Stop Gual Tests Oversized drawings available in Central Files
 DISE.D.P Niagara Mohawk Power Corp 78/11/17 4ipp 94239 283
- 781206018B Forwards steff requests for add1 info re facil fire protoc prog.based on 781017-20 site visit.

 IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/27. 27pp. 94332 080.
- 7812140136 Forwards med to Security Plan to permit storage of equip in new Admin Bldg for Spring 1979 outage Encl w/held pursuant to 2 790. DISE.D.P. Niagara Mohawk Power Corp. 78/12/08. 1p. 94133-336
- G Adjudicatory correspondence
- 7812130090 Requests that NRC place notice in Fed Register of util's appl to install radioactive waste volume reduction incinerator to facilitate holding of pub hearing on appl DILLINBECK.L., MARTIN.K., PARKER.R. Scribe. NY 78/10/18 Ip
- 7811200057 Responds to 8d of Town of Scriba, NY, resolution requesting NRC publish a notice of opportunity for hearing in Fed Register & request of Planning 8d to intervene on behalf of Scriba Matters are under consideration BORDENICK, B.M. Office of the Executive Legal Director. 78/11/06. ip. 94215-348
- 7811240102 Forwards Appl for Amend to Operating Lic for subj facil.
 Appl incls attachments which set forth requested change in
 Tech Bases & supporting data.
 THOMABLE B LeBosuf, Lamb. Leiby & MacRae. 78/11/21 2pp
 94449:240
- --7811240103 Appl for amend to operating lic for subj facil. Incl attachments on proposed changes to Tech Specs & supporting documentation. Changes involve fuel cladding & limiting safety ays setting.

 DISE.D P Niagara Mohawk Power Corp. 78/11/20. 52pp 94449. 242
- 7812280285 Ack receipt of 781031 ltr re Hiagra Hohauk Pur Corp propose to install a low level waste incinerator/calciner at subj facil NRC is now reviewing safety & environ aspects of the proposal & no decision has been made re issuance of an EIS BTELLO.V. Division of Operating Reactors 78/12/15. 1p 94083:114.
- ~-7812280288 Criticises NRC's publicly stated position that NRC does or plan any environ impact statement(EIS) or Fed Register Notice re installation of low level waste incinerator/calciner at subj facil
 # Ecology Action of Oswago. 78/10/31. 2pp. 94083-115
- 7811090052 Resolution auth Oswego County Planning & Dev Comm to intervene as a party-at-interest in Niagers Mohawk proposed radiactive waste volume incinerator proceeding BEST. J. Oswego, NY. 78/10/12. IP. 94040: 098.
- P. Operating license stage documents & correspondence
- 7810110088 Responds to 780807 NRC request for evaluation of motor generator sets that provide pur to reactor protec sys. Info will be available by 781231 Meanwhile surveillance described in 780807 NRC itr will continue.

 DIBE.D.P. Niagara Mohauk Power Corp. 78/10/04 2pp. 94063:360.
- 78:0180187 Surmary of 780921 meeting re proposed installation of radioactive waste incinerator at sub; facil. W/encl meeting agenda.

 BARRETT, L. Environmental Evaluation Branch (Pre 790625). 78/10/05 2599 943:17:172.

- 7811030006 Porwards request for add1 info re expansion of epent fuel be storage capacity at subj facil: measured man-rame exposure to do the work: increased purification sys operiwater leakage from spent fuel pool.content
- 7810300146 In response to 780711 submission of lic amend to delay inspec of sensitized stainless steel samples to meet termination objective all samples will be removed during 1979 Tefueling outage & enalyzed by separate organization. BCHMEIDER: R. R. Niegara Mohawk Power Corp. 78/10/25. ip. 94035:125
- 7811130041 Forwards NRC/NY State contract, w/mod for environ monitoring in vicinity of subj facil as requested in 780619 meeting. SMITH-0 H. Region 1. Philoselphia, Fuel Facility & Materials Bafety Branch. FIN 8-5109. 78/10/26. 18pp. 94010:206.
- 7811130335 Summary of 780914 meeting w/OE representatives & Mark 1 Ouners Group re-progress of Long Term Prog w/attendance list & agendatRD-9-A-Marki.Standards. 1 ORIMES.C. Plant Systems Branch (Pre-791030). 78/10/26. 67pp. 94007:225.
- 7811160022 Notice of Proposed Issuance of Amend to Facil Oper Lic #DPR-63.changing Tach Spac to increase spent fuel storage capacity from 1984 to 3009 fuel assemblies.

 1PPGLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/27.
 4pp. 94316:307.
- 7811220251 Forwards "Notice of Proposed Issuence of Amend to Facil Oper-Lic" to be published in Fed Register. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/27. Zpb. 94379:311.
- --7811220252 Notice of Proposed Issuence of Amend to Facil Oper Lic, revising Tech Spec to increase spent fuel storage capacity from 1984 fuel assemblies to 3009. IPPDLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/10/27. 4pp. 94379:313.
- 7811070114 Advises that subj facil specific Tech Specs will be submitted 90 days after finalization of NRC model specs, estimated date Feb 1979.
 DISE.D P. Niagara Mohawk Power Corp. 78/10/30. 1p. 94043:300.
- 78iii90154 Requests payment of Class 4 fee of re 780901 application for amend to License DPR-63 per 10CFR170, 22. Application relates to installation of radwaste reduction sys & associated waste handling equipment.
 MILLER-W. D. License Fee Management Branch. 78/10/30. 1p. 94275:033
- --7811150159 Ack receipt of fee from Niagra Mohawk dtd 781107, check 251131. D1098 R.M. License Fee Management Branch. 78/11/13. 1p. 94273: 014
- 7811240058 Forwards request for add1 info re control rod removals at subj facil. Info req w/in 60 days.

 IPPCLITO.T.A. Operating Reactors Brench 3 (Pre 790625). 78/11/09.
 300. 94455:309
- 7811290288 Responds to 781106 request for info concerning licensee reg performance eval for Region 1 plants by NRC Provides details.

 ORIER B.H. Region 1 Philadelphia Office of the Director.
 78/11/09. 9pp.
- 7811220186 Responds to 781023 ltr to Secretary of the Comm re health & safety consequences of operating a low level waste incinstrator planned for subj fecil. Forwards Topical Rapt @EI/NNI-77-7-NP & 780901 Niagare Mohawk Pur Corp ltr. DENTON-H R. Office of Nuclear Reactor Regulation, Director. 78/11/15. 1p. 94070:105.
- --7811220191 "RWR-itm Radwasts Vol Reduction Bys." Describes RWR-itm vol reduction sys for appl to radioactive waste produced at nuc slac generating station utilizing fluidized bed to celcine liquids t incinerate solids.

 Nawport News Industrial Corp. (subs. of Newport News Shipbuilding & DryDoct Co.). NNI-77-7NP. 77/06/24. 109pp. 94070:156.
- ---781ii30391 Request for tech info re health & safety consequences of operating low level waste incinerator planned for installation at subj facil. Also seeks info re preparation of EIS.

 CCCHRAN, T. B. Natural Resources Defense Council. 78/10/25. 1p. 94008, 287.

- --78i1220193 Forwards Radwaste Reduction info sys. Bys does not involve unreviewed sefety questions based on fact that no equipment in radwaste bldg is important to safety. Bldg sched to begin Feb 1979 & be completed by Oct 1980.

 DISE,D.P. Niagara Mohawk Power Corp. 78/09/01. 12pp. 94070:273.
- 7812150132 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR3. Requests pre-workshop registration of attendees to facilitate sending out math. H/encl Registration Form & List of Locations. HILLER. J. R. Assistant Director for Site & Safeguards (Prs 791030). 78/11/15. 3pp.
- 7Bii300367 Informs NMP that NRC has contracted w/Hountain Hest Res Inc to Undertake a series of post-licensing studies of nuc pur stations. Studies will analyze socioecon impacts which occurred during constr & post-constr periods o each plant. DEYGUNG.R.C. Division of Bite Bafety & Environmental Analysis. 7B/II/20. 2pp. 94116:317.
- 7812070163 Notice of seminar on 781208 on new Model Radiological Effluent Tech Space for nuc pur plants Requests advance submission of seminar specific questions. M/encl Seminar Info Shaet, Proposed Agenda & maps. ORIER, B.H. Region 1. Philadelphia. Office of the Director. 78/11/21. Spp. 94127:041.
- 7812110048 Discusses possible dangers of LDCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/encl ANO: #7812080207 IPPCLITO.T. Operating Reactors Branch 3 (Pre 790625). 78/11/29. 8pp. 94408:206.
- 781203014B Forwards "New solidification & Assoc Haste Handling Equip."
 Rept for sys capable of splidifying storing & loading radioactive waste for shipment w or w/o vol raduction. Mod does not involve unreviewed safety questions.
 DISE D.P. Niagara Mohawk Power Corp. 78/11/30. opp. 94334:395.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held & providing task-by-task activity summary for the month. BGBCN:L.J. General Electric Co. 78/12/04. https://doi.org/10.174.
- 7812280107 Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB.J. 0. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 03555:325.
- 7812200194 Requests approval of radwaste reduction sys described in Attachment A per requirements of 10CFR20, 305. Repts wastes processed by radwaste reduction sys will decrease amount of solid waste shipped to burial grounds.

 DISE D.P. Niegara Mohauk Power Corp. 78/12/13. 11pp. 94162:249.
- 7812270003 Ack receipt of 781030 ltr re Niegera Mohewk Per Corp's proposal to install a low lavel waste incinerator at subj Facil. Informs that no decision has been made by NRC re EIB preparation. Fad Register Notice. & pub hearing.
 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 78/12/15. 1p. 94139:204.
- --7812270009 forwards 780925 ltr rs low level incinerator proposal by Misgar Hohawk Pur Corp.Protests NRC's recommendation that no EIS be prepared; no Fed Register Notice be Filed & no pub intervention be required. REBNINOFF, M. Sierra Club. 78/10/30. 3pp. 94159:255.
- 7812290049 Ack receipt of 780413 its re need for feadwater pump trip on reactor high water level.Finds trip is not necessary for safe oper of facil.Forwards safety sval.

 IPPCLITO.T.A. Operating Reactors Branch 3 (Pre 790625), 78/12/15.
 2pp. 94190:001
- --7812290052 Bafety Eval of proposed actions re BNR feedwater pump trip on reactor high water level. Concludes licensee-proposed actions to install high water level trip are acceptable.

 Operating Reactors Branch 3 (Pre 790625), 78/12/15, 2pp. 94190:003.
- 7812270175 Responds to 780821 NRC ltr requesting addl info re spent fuel mod Forwards "Boraflex 1 Suitability Rept."

 DISE, D. P. Niagara Mohawk Power Corp. 78/12/20. 73pp. 94018:095.
- 7812270240 Requests refund of \$8300 of amend fee paid 781107 on grounds that the Radwaste Reduction Bys amend actually is a Class 3 amend.
 DISE, D.P. Niagara Mohawk Power Corp. 78/12/21, 1P. 94017;149.

for subj racii LIII WALLE DAFOTIAL C D B FO 8 5 Niagara Mohawk Power Corp. 78/12/21 20pp 94229, 318. DISE D P

811210367 Forwards addl info re multiple consecutive safety/relief valve actuation of Mark I containment program 8080N.L J. General Electric Co. 78/11/13 3pp 94485.126.

. Inspection reports. IE Bulletins & correspondence

- 810260019 Ack receipt of 780928 ltr informing NRC of steps taken to correct violations noted during inspec#50-220/78-11.

 BRUNNER,E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 78/10/06. 1p 94410.058
- -7810260022 Responds to 780906 NRC ltr re violations noted in Inspec Rept#50-220/78-11 Corrective actions Quality Control Manual reviewed by 770101, subj audits done addl clerks madde available to Guality Control Oper. SCHNEIDER, R. R. Niagera Mohawk Power Corp. 78/09/28. 3pp. 94410.059
- -7810260023 Forwards IE Inspec Rept#50-220 on 780914-18 & Notice of BRUNNER, E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 78/09/08. 2pp. 94410:062.
- -7810260025 Notice of Violation from inspec on 780814-18. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/08. 2pp 94410.064.
- -7810260028 IE Inspec Rept#90-220/78-11 on 780814-18 during which 4 items of noncompliance were noted: Guality Control Manual not reviewed or reissued in 3 yrs & deficiency & staffing audits not performed in time.

 NAPUDA.G., BECKMAN.D., BAUNACK.H.H. Region 1. Philadelphia.

 Reactor Operations Nuclear Support Branch. 78/09/07. 20pp.
- 811060208 Forwards IE Circular#78-17. (80e ANO: 7810230221, Docket #50-133, 781013.) ORIER, B.H. Region 1. Philadelphia, Office of the Director. 78/10/13 1p. 94489:219.
- 812010037 Forwards IE Inspec Rept#50-220/78-14 on 780925-27 during which no items of noncompliance were noted. SMITH. C.H. Region 1: Philadelphia. Fuel Facility & Materials Bafety Branch. 78/10/20. 1p. 94416-082.
- -7812010041 IE Inspec Rept#30-220/78-14 on 780725-27 during which no items of noncompliance were noted Major areas inspected incl:analytical measurement quality control programmit results, effluent control records & procedures. KUTTAN.J.J. BTOHR.J.P. Region 1. Philadelphia, Fuel Facility & Haterials Bafety Branch. 78/10/19. Bpp. 94416:084.
- 811130038 Act receipt of 781017 itr informing NRC of steps taken to correct violations noted during Inapac#50-220/78-12.
 8M17H. 0. H. Region 1. Philadelphia. Fuel Facility & Materiale Bafety Branch. 78/11/01. 1p. 94112:332.
- ~781i150041 Responds to 780927 NRC itr re violations noted in Inspec Rept 50-220/78-12. Corrective actions: all radiat work permits drafted by those wiless than 2 yes experience have been reviewed & will be continued. BCHNETDER, R. R. Niegara Mohawk Power Corp. 78/10/17. 3pp. 94112: 333.
- -7811150043 Forwards IE Inspec Rept#50-220/78-12 on 780828-13 & Notice of Violation. CROCKER.H.H. Region 1. Philadelphia, Fuel Facility & Materials Bafaty Branch. 78/09/27. 2pp. 94112-336.
- -7811150045 Notice of Violation from inspec on 780828-31.
 Region I. Philadelphia, Office of the Director. 78/09/27. 2pp. 94112: 338.
- -7811150049 IE Inspec Rept 50-220/78-12 on 780828-31 during which 4 items of noncompliance were noted: 4 HP technicians stems or noncompliance were noted. The secularization especialize short of requirements, feature to perform dosimater calibrations & alpha surveys as req.

 PLUMLER, K. Region i, Philadelphia, Office of the Director.

 CLEMONS, P. E., KMAPP, P. J. Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 78/09/22. 9pp. 94112:340.
- 311190184 Ack receipt of 781017 itr informing NRC of staps taken to correct violations noted during Inspec#50-220/78-13.
 BRUNNER, E. J. Region i Philadelphia, Reactor Operations Nuclear Support Brench. 78/11/03. ip. 94242:234.

- personnel & increased surveillance established BCHNEIDER, R.R. Niagara Mohawk Power Corp. 78/10/17. 2pp. 94242, 235
- --7811150190 Forwards IE Inspec Rept#90-220/78-13 on 780905-08 & Not: of Violation BRUNNER.E J. Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 78/09/26, 2pp. 94242,237.
- --7811150192 Notice of Violation from Inspec on 780905-08 BRUNNER. E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Dranch 78/09/26 1p 94242 239
- --7811150194 IE Inspec Rept#50-220/78-13 on 780905-08 during which 1 of nancompliance was noted failure to adhers to admin procedure re control of test instruments. BAUNACK, W H Region i. Philadelphia. Reactor Operations Nuclear Support Branch 78/09/26 Opp 94242:240
- 7811290170 Forwards IE Circular #78-18. 'UL Fire Test 'W/encl ANO. 7811150002 ORIER. B. H. Region 1. Philadelphia. Office of the Director. 78/11/06 Ip 94238.071
- 7812280199 Forwards 16 Inspec Rept#90-220/78-15 on 780925-29 & Notice of Violation BMITH.O H Region 1, Philadelphia, Fuel Facility & Materiale Safet Branch. 78/11/09. 3pp. 94373:166
- 7812270446 Forwards IE Inspec Rept#30-220/78-18 on 781024-27 during which no items of noncompliance were noted. BRUNNER.E J. Region i. Philadelphia. Reactor Operations Nuclear Bupport Branch 78/11/13 2pp. 94015.149.
- --7812270449 IE Inspec Rept#50-220/78-18 on 781024-27 during which no items of noncompliance were noted. Major areas inspected incl: admin controls for facil procedures & format & tech content of Pacil procedures. CONTE.R J. BLUMBERG.N.J. KIBTER.H.B. Region 1. Philadelphia. Reactor Operations Nuclear Support Dranch 78/11/09. 12pp. 74015:151
- 7812150146 Forwards IE Bulletin878-12A suppl to IE Bulletin878-12. Whencl AND 7811300055 ORIEN B H. Region 1. Philadelphia, Office of the Director 78/11/24 1p 94212:207.
- A. Periodic operating reports & related correspondence
- 7810160119 Forwards Monthly Oper Rept for Sept 1978 BCHNEIDER. R. R. Niagara Mohawk Power Corp. 78/10/05 1p. 94007: 130.
- --7810160121 Monthly Oper Rept for Sept 1978 PERKING, T. J. Niagara Mohawk Power Corp 94007:131. 78/10/04 Sop.
- 7811210302 Forwards monthly Open Rept for Oct 1978 8CHNEIDER, R. R. Niegera Mohawk Power Corp. 78/11/08 94488: 096.
- --7811210303 Monthly Oper Rept for Oct 1978. PERKINB.T. J. Niagara Mohawk Power Corp. 78/11/06 épp. 94488: 097.
- 7812120102 Forwards Monthly Oper Rept for Nov 1978. 8CHNEIDER, R. R. Niegars Mohawk Power Corp. 78/12/07 ip.
- --7812120103 Monthly Oper Rept for Nov 1978. PERKINB. T. J. Niegere Mohawk Power Corp. 78/12/05. 4pp. 74275: 025
- 8. Reportable occurrences. LERe & related correspondence
- 7810100054 Forwards LER#78-033/03L-0. SCHNEIDER, R. R. Niegera Mohauk Power Corp 78/09/29. 1p.
- --7810100039 LER#78-033/03L-0 on 780914: Burveillance tests on Barton Model#289 Pressure Indicating Switches showed changes in setpoints due to instru drift Rev surveillance test acheds now adequate to ensure early detection of drifts. * Niagara Mohawk Fower Corp. 78/09/29. 1p. 94033.101.

- 78:1030141 RQ on 78:1025 waste tanks discharged at rates exceeding calculated max due to failure of flow mater on discharge line & attempts to control discharge rate by manual throttle of discharge valve.

 PERKINS.T. J. Misagara Mobauk Power Corp. 78/10/26. ip. 02723:311.
- 7811130400 Reportable Occurrence #78-35 on 781026 Bept Proportional Composite found concentrations of sodium & sulfate exceeding maximum increase over late ambient concentration specified in E16 Caused by waste tanks flow mater failure PERKINS, T. J. Niagara Mohawk Power Corp. 78/10/26. 1p. 94008:326
- 78iii203i9 RQ 78-35:on 78i028 during routine surveillance test 41i B main stream high flow transmitters were set less conservatively than req due to test pressure gauge out of calibr.
 PERKINS.T J Niagara Mohawk Power Corp. 78/10/20. ip. 94087.067
- 7B11090155 Forwards LER#7B-036/04T-0. SCHNEIDER, R. R. Niagera Mohawk Power Corp. 7B/11/02. 1p. 94043:017
- --7811090165 LERM78-036/04Y-0 on 781029 improper appl of Brook Model#9456 Ovel Gear Flowmeter combined w/failed seel on caustic addition pump caused high concentration of sodium & sulfate & degraded capability to control rate of discharge. MACVITTE: 0 K. Niagara Mohaut Power Corp. 78/11/02: 1p. 94043-018
- --781090205 Details event & cause description & preventative actions re-sodium & sulfate discharges excessing ETS values. SCHNEIDER.R.R. Niagara Mohawk Power Corp. 78/11/02 2pp. 94043:019
- 7811090271 Forwards LERN78-035/017-0.
 86M%[10ER.R.R. Niegars Mohawk Power Corp. 78/11/02. ip. 02729: 355
- --7811090273 LERM70-035/01T-0 on 781020: all main steam high flow pressure indicating instr were found w/estpoints less than Tech Gopes. He is e 0-200 P810 test quage celibrated & used in test had loose screw & was recalibrated. MACVITTEE.D.K. Niagara Mohawk Power Corp. 78/11/01. 4pp. 02729: 356.
- 7811210201 Forwards LER878-037/03L-0.878-038/03L-0 & 878-039/03L-0. 8CHNEIDER, R. R. Niagara Mohawk Power Corp. 78/11/15. 1p. 94485:201.
- --7811210283 LER#78-037/03L-0 on 781027: test revealed trip satpoint of 26.5 inches water on one vacuum suitch in vacuum relief sys from pressure supression chamber to rx bldg. Caused by instrudrift in a Mercolé Model CP4122 vacuum suitch. MACVITTIE, D.K. Niagara Mohawk Power Corp. 78/11/14. 1p. 74485: 202.
- --7811210287 LER#78-038/03L-0 on 781025: review of N1-18P-RE22 test results found 12 instances where procedure was violated. Caused by carelessness in procedure implementation. Re-instruction & closer supervision instituted. MACVITTER.D.K. Niagara Mohawk Power Corp. 78/11/14. 1p. 74485:203
- --7811210292 LERMYB-0039/03L-0 on 781103: surveillance test NI-IBP-RE02 revealed Rx Lo-Lo water level switch w/trip setpoint of +2 inches water Caused by instru drift: Betpoint reset. HACVITTIE. D. K. Niagara Hohawk Power Corp. 78/11/14. 1p. 94485-204
- 7812140149 Forwards LERM78-040/03L-0. SCHNEIDER, R. R. Niagara Mohawi Power Corp. 78/12/08. Ip.
- --7812140154 LER#78-040/03L-0 on 781113:#112 core spray topping pump motor breaker closed starting pump but breaker closing spring motor was running continuously & not charging closing spring. Caused by misaligned motor assembly at latching paul. JUTRAS.R. Niagara Mohaws Power Corp. 78/12/08. 1p. 94127:008.
- DOCKET 50-223 UNIV. OF LOWELL RESEARCH REACTOR

 P. Operating license stage documents & correspondence
- 7812070055 Requests response concerning subj facil location adjacent to proposed constr of a hydro-electric dam. Studies are being conducted by Lowell Corp.

 MALLACE.T. Lowell Univ. of. 78/11/27. ip. 94134:030.

- Q Inspection reports, IE Bulletins & correspondence
- 7811020060 Act receipt of 780926 itr informing NRC of steps taken to correct violations noted during inspect@0~223/78-03.
 BRUNNER,E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/10. ip 94374:159.
- --7811020177 Responds to 780915 Notice of Violation re compliance w/ posting regs As of 780929.10CFR21 & Energy Reorganization Act of 1974 Section 206 are properly posted BEOMAIN.L.E. Lowell, Univ. of. 78/09/26. 1p. 94374:160.
- --7811020178 Forwards IE Inspec Rept#50-223/78-03 & Notice of Violation BRUNNER. E. J. Region I. Philadelphia, Reactor Operations Nuclear Bupport Brench. 78/09/15 2pp. 94374-161.
- --78110R0182 Notice of Violation from inspec on 780817-18 BRUNNER, E. J. Region 1: Philadelphia: Office of the Director 78/09/15. 1p. 94374:163.
- --7811020186 IE Inspec Rept#80-223/78-03 on 780817-18 during which 1 item on noncompliance was noted: failure to comply w/10CFR21 posting requirements QREENMAN,E G. Region 1, Philadelphia, Office of the Director, 78/09/15. Spp. 94374:164.
- DOCKET 30-224 UNIV. OF CALIFORNIA RESEARCH REACTOR
 F. Security, medical, emergency & fire protection plans
- 7811030009 Review of physical security plan revision complete.Plan Acceptable. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/17. 2pp nermon-page
- DOCKET 50-225 RPI CRITICAL EXPERIMENT
 J. Insurance & Indemnity information
- 7811010071 Repts that insurance broker is sending Advance Premium endorsement. Indemnity agreement was forwarded earlier. LEAVITT, J. B. Rensselær Polytechnic Inst. 78/10/26 19 94481:059.
- NOCKET 50-227 TRIGA THERMIONIC PROTOTYPE REACTOR

 F. Security, medical, emergency & fire protection plans
- 7812190145 Forwards current physical security plan in compliance w/regs.classified as "Natl Security Info" pursuant to certain DOE requirements. Requests that earlier capies be destroyed, and naw copies be withheld.
 MDWRY.W R. Denaral Atomic Co. (subs. of Oulf Dil Co.). 78/12/15 ip. 94340.070.
- DOCKET 50-236 LUCKHEED AIRCRAFT CURP.
- U. Congressional/Executive Correspondence
- 7810140036 Response to 780911 ltr for comments re individuals who are concerned over radioactive milk contamination in area near facil. Forwards NRC preliminary avaluation of Steinglass rept on Strontium-90 levels in milk near subj Pacil.
 DIRCKB.W.J. Office of the Executive Director for Operations. 78/10/06. 2pp. 94329:073.
- DOCKET 50-237 DRESDEN NUCLEAR POWER STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7812150228 Classifies lic amend for proposed fuel pool mod as Classes IV & I not Classes III & I.Requires add1 charge of \$8300 for sach of the two applito be paid w/in 15 days. MILLER.H.O. License Fee Management Branch. 78/12/11. 2pp.
- F. Becurity, medical, emergency & fire protection plans
- 7810120080 Forwards analysis of Elec Cable Penetration Fire Barrier Test conducted on 780619. Also forwards 3rd party observer rept of test & 5 detailed drawings associated W/test.

12120175 Informs NRC name of fire protec consulting firm hired by CEIL to fulfill requirements of "Fire Protec Organization of Nuc Flant Fire Protec Functional Responsibilities Admin Controls & GA" will be submitted 770201 NAUGHTON, H. F. Commonwealth Edison Co. 78/11/30. 2pp. 94277:099.

Adjudicatory correspondence

10120112 Applicant's Answer to Petition for Leave to Intervene reproceeding filed 780908 by Attorney Gen of St of IL Includes notices of appearance for M.I.Miller, J.R. Rowe, & P.P. Steptoe. Includes designation of person upon whom sec shall be made. STEPTOE, P. P. Isham, Lincoln & Seele. 78/09/18. 10pp. 94484:039.

(019013) Answer by CEIL to Petition to intervene filed by Atty Gen of it on 780920 Agrees that Atty Gen has standing, but isserts there are no genuine issues to be heard at hearing lequests that Atty Gen request for EIS be denied. NEPTOE.P. P. Jeham, Lincoln & Beele. 78/10/02. 3pp.

0300063 Natural Resources Defense Council Request for Leave to File Response. Response is to applicant's contention remotitutionality of forced disclosure of group's members' ames in order to oper w/in state. OIBMAN, A. Z. Natural Resources Defense Council. 78/10/10. App. 4037:177.

0300324 NRC Staff Answers to Council for Citizens for Better nviron & Natural Resources Defense Council's Petition for save to Intervene. Staff opposes granting petition for f Svc. OPDARD, R J. Diffice of the Executive Legal Director. 78/10/10. pp. 94253: 337.

0230124 NRC Staff's Response to Patition of TEX-LA Cooperative. Inc. or Leave to Intervens. Staff believes Petition should be rented. ESSY, R.P. . BLUME. M. B. Office of the Executive Legal Director. 8/10/10. 9pp.

3310223 Staff Answer to State of IL petition for Leave to Intervens. taff does not oppose admission of IL as party to proc. 300ARD,R. J. Office of the Executive Legal Director. 78/10/10.

1010063 Petition for leave to intervene & for hearing filed by itizens for Better Environ & Natural Resources Defense suncil Request for leave to file response to answers igosing petition is granted. ILHOLLIN.G.L. Atomic Bafety and Licensing Board Panel. 78/10/13. 1. 94302:360.

.150223 "Natural Resources Defense Council Response to Commonwealth lison's & Btaff's Answers to Petition for Leave to itervene. "Intervenor urgss Bd to establish a schedule for liefing challenges to contentions. ILEMAN, A. Z. Natural Resources Defense Council. 78/10/23. 16pp. 270: 137.

130216 NRC request to file response to NRDC response to Comm Ed & C Answer to petition for leave to intervene dtd 781023. If anted, reply will be served by 781103. Cert of 8vc encl. DOARD, R. J. Office of the Executive Legal Director. 78/10/26. DDARD, R. U. 04 P. 03554: 050.

200070 Request by Comm Ed for leave to file a response to NRDC iff which argues that organizations may show standing to rticipate in NRC proceedings merely by alleging that they present anonymous members. Cert of Svc encl. EPTOE, P. . I sham, Lincoln & Beale. 78/10/30. 20p. 74218:348.

390259 Bd grants request by Citizens for a Better Environ & Natural sources Defense Council for permission to file response to swers opposing their petitions to intervene by 781103.

-HOLLIN, O.L. Atomic Sefety and Licensing Board Panel. 78/11/01.

02761:290.

220233 Forwards "Licensing Report Dresden Nuc Pur Plant, Units 2 & Spent Fuel Rack Modification." dated 780203 W/o encl rept. IDARD, R. J. Office of the Executive Legal Director. 78/11/01, 1p. 289: 340.

- 7811160021 Grants request by licensee CEIL to have until 781107 to respond to 781013 Order of ASLB permitting NRDC & Citizens or a Better Environ to file response to answers opposing their petitions to intervene in proceedings re sub; Pacils MILHOLLIN, Q L. Atomic Sefety and Licensing Board Panel 7 p. 94317-090 78/11/03
- 7811220010 NRC Staff's Response to NRDC's Response to Answers to latter's Petition for leave to intervene NRC asserts that NRDC has not demonstrated its standing to intervene as matter of right Cert of Bvc enci. QUDDARD,R.J. Office of the Executive Legal Director. 78/11/03 Bpp. 94273:334
- 7811200003 Special Prehearing Conference in proceedings re-subj facils will be held on 781215 in Rock Island.IL All parties to proc & all petitioners to intervene must attend & should be prepared to discuss all issues.

 MILHULLIN.9 L. Atomic Safety and Licensing Board Panel. 78/11/09.

 2pp. 94215-221.
- 7812130122 Gives notice that A Bielawski enters an appearance on behalf of applicant CEIL in proceedings re subj facils. Cert of Syc BIELAWBK1, A. P. Isham, Lincoln & Geale. 78/11/21. 2pp. 94307:188
- 7812110284 Cencels special prehearing conference scheduled for 781215.
 Conference shall be held on 790111 in Tax Courtroom of US
 Courthouse & Fod Bldg. Chicago, IL. Parties & petitioners must
 rept to Board by 781215 re progress of negotiations
 MILHOLLIN, G.L. Atomic Safety and Licensing Board Panel 78/12/01. 200. 94203:243
- 7812270230 Proposed stipulation re NRDC & CBE's representation of Unnamed members in Dreaden-Quad Cities transshipment is not acceptable to NRC.NRC position on NRDC's petition to intervene remains as stated in 781103 pleading.

 9DDDARD.R.J. Office of the Executive Legal Director 78/12/06 lp. 74017: 138.
- 7812280271 Forwards"Stipulation" of NRDC.CBE & Commonwealth Edison Core identification of members of NRDC & CBE to prove they have interests that may be affected No agreement w/Reg Staff has been reached. ROIBMAN.A. Z. Natural Resources Befense Council. 78/12/08 19. 94374: 334.
- --7812280280 Parties agree that NRDC & CBE have adequately indentified . least one member whose interest may be adversely affacted by the proposed action. Auth to represent these interested members has not been agreed upon. ROIBMAN, A. Z. Natural Resources Defense Council. STEPTDE, P. P. Commonwealth Edison Co. 78/12/11. 3pp. 94374:335.
- 7812270133 Special Prehearing Conf Scheduled for 790111 is postponed until 790201. Parties & petitions are excused from requirement to rept to 8t by 781215 re negotiations progress. MILHOLLIN, Q.B. Atomic Safety and Licensing Board Panel 78/12/13. Rpp. 94161:142.

H. General correspondence

- 7810310024 Informe that for BEP normal channel of oral compunication will be followed, but to expedite reviews direct oral communication between subj facil staff & members of SEP branch is encouraged.
 ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/10
 2pp. 94094:345.
- 7812080158 Forwards CEIL request for amend of OL to allow spent fuel transfer & storage between facils.W/o enci. GODDARD.R.J. Office of the Executive Legal Director. 78/11/17. 1p. 94107: 356

1. Financial information

7811140199 LER#78-056/01T-0 on 781012; diff press switch isolation valve for DPIS 2-1622A was found closed because of unknown cause.

Bub; valve will be opened slowly efter DIS 1600 survey.

LINDBERO, C. Commonwealth Edison Co. 78/11/01. 2pp. 94384: 283.

J. Insurance & indemnity information

7812190109 Requests refund of 06 per mut in excess indemity fee paid for Lic#DPR-2, MDPR-19, MDPR-25, MDPR-29, MDPR-30, MDPR-39, WIPR-48 PODLE, R. D. Commonweelth Edison Co. 78/12/13. 1p. 94376: 323.

- P Operating license stage documents & correspondence
- 7811100105 Forwards copy of NUREQ-0485. "Status Summary Rept-Systematic Eval Prog ' ZIEMANN.D L Operating Reactors Branch 2 (Pre 790625) 78/10/19
- 7812080026 FOIA request for all records incl quantity of radioactive matl disposed of from former Manhantten proj in [L known as Chicago Pileski, 2 % 3 Matl disposed of in [L by Lindsay Cos at Morris facil & Dreaden facil.

 HANSELL,D lliingis, State of 78/11/06 2pp 94104-003
- 7810230198 Notice of Proposed Issuance of Amends to Oper Lics NRC is considering issuance of amends to Provisional Oper Lic #DPR-19 & Facil Oper Lic #DPR-29. Mould change provision in Tech Specs to allow more spent fuel to be stored at facil ZIEMANN,D L. Operating Reactors Branch 2 (Pre 790625) 78/08/03 4pp. 94392,220
- 78:11:3059 Forwards initial eval of 8 complete 98P topics & response to request for clarification of SEP documentation procedures made at 780531 meeting Requests response re facts used to define plants by NPC staff EISENHUT, D.O. Assistant Director for Bystems Engineering (Pre 79:030), 78/08/17 2pp. 94010-275.
- 7810170185 Update & conclusion of diesel generator reliability study Almost all corrective actions taken per investigation have been torpleted Results of study summarized in encl BTEPHENSON, B B Commonwealth Edison Co 78/09/28 5pp 94270.047
- 7810109027 Forwards evaluation of reactor protect sys pur supplies to determine whether undetected failures adversely affect the RPS sys.
 TURBAK.M.S. Commonwealth Edison Co. 78/10/04 Spp
- 7BiO140112 Reevaluation of Lic amend fees for inter-station spent fuel transfer for subj facils as requested by 7B0B17 ltr shows that the class 1 & 3 fees paid for each station are correct MILLER.W O License Fee Management Branch. 7B/10/10 lp. 9442E: 131
- 7811080275 Notification of 781023-24 site visit to observe discuss & identify site specific seismic design features & info. Agenda, isst of pertinent info required for revise by senior seismic review team & description of SEP review encl ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625) 78/10/11. Bpp.
- 7810290165 Notice of meeting on 781023-24 to discuss Gys Evaluation Prog Setsmic Review for subj facil. O'CONVOR.P.W Operating Reactors Branch 2 (Pre 790625). 78/10/16
- 7B10240158 Forwards evaluation of surveillence requirements on BWR recirculation pumps & discharge valves in operation w/less than all loops in svc.BWR jet pump operating indications & & upper plenum injection c/DBEs affectd in LOCA TURBAK.M S. Commonwealth Edison Co. 78/10/18 19pp
- 7Bil100109 "Status Burmary Rept. Bystematic Evaluation Program"
 # GPFice of Management and Program Analysis. NUREG-0485 VOI 78/07/22 203pp.
- 7810260153 Requests 45-day extension to allow time to provide add1 info re accuracy of environ qualification of safety-related electrical equipment TURDAK.M.S. Commonwealth Edison Co. 78/10/23 1p. 94059: 338
- 7810270180 Responds to 781002 NRC ltr re requested Tech Spec change for reactor water cleanup sys return valve. Util accepts change as Class 3 & Class 1 anend. & remits appropriate fee. REED.C. Commonwealth Edison Co. 78/10/23. ip 94057:081.
- 7811060115 Responds to 780919 request for add1 info re H-451 Response will be in 2 parts, first to be sent 781027 second 781124. H-451 review can be completed by mid-Jan Also requests ack of 780714 ltr. WESEMAN, 0. L. Oeneral Atomic Co. (subs. of Quif Dil Corp.). 78/10/25. lp.
- 78:1020322 Withdraws request to amend Tech Space re reporting requirements for reactivity anomalies as Reg Guide "Interpretation" by NRC on 780701 does not require rept for reactivity increase of less than 5 secs.

 REED.C. Commonwealth Edison Co. 78/10/26. 2pg. 94255:223.

- 7811030161 Forwards proposed Amend changing Tech Specs w/regard to updating station organizational charts Changes have received ansite to offsite approval.

 REED.C Communeelth Edison Co. 78/10/26 9pp. 02724 009.
- 7811120335 Summary of 780914 meeting w/OE representatives & Mark | Dwners Group re-progress of Long Term Prog w/attendance list & agenda(RD-9-A-Markl.Standards) GRIMES.C. Plant Systems Dranch (Pre-791030) 78/10/26. 67pp. 94007-225
- 7811140014 Requests add1 info on FSF switchover from injection to recirculation mode.isolation of reactor protect sys from non-safety sys.ESF sys logic & design & specific drawlings of elec sys. & complete plant elec drawing indices ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625). 78/10/26. Dpp 94425 340
- 7811000199 Site visit on 780928 conducted for the purpose of viewing hydrological features & discussing wiltensee hydrological design bases necessary to perform a detailed SEP review Addl hydrological info also requested STALEY.C B Hydrology Meteorology Branch 78/10/31. 3pp 94403.136
- 781110013; Summary of meeting w/CEIL on 781023-24 to discuss questions re-seismic design of subj-facil & obtain seismic design info W/encl list of attendees meeting agenda-charter of SBRT.floor response spectra. & design repts & tech paper. LEVIN.H A Systematic Evaluation Programs Granch (Pre 790625) 78/11/02 410pp 94259-001
- 7811140105 Responds to 780516 MRC ltr requesting addl info re reactor vessel metal surveillance specimen fluence valves at time of withdraual.w/projections based on dosimetry results of previously tosted capsules & BOX tapacity factor:w/o encl. TURBAK:M 8 Commonwealth Edison Co. 78/11/03 2pp 94425 125.
- 7811140002 Notifies applicant of 781128 NRC-sponsered seminar re Model Radiological Efficient Tech Specs for Nuc Pur Plants w/encl Beminar Info Bheetito be completed & returned by 781117) & Proposed Agenda KEPPLER. J G Region 3. Chicago. Office of the Director 78/11/07 &pp. 94426 022
- 7811150246 Notifies of forthcoming mtg w/Commonwealth Edison Co to discuss schedule for inspec of type 3 safe ends at subj facil
 O'CONNOR.P W Operating Reactors Branch 2 (Pre 790625). 78/11/07.
 1p. 94273 063
- 7811170207 Requests add1 info for review of proposed subj facil Spent Fuel Pool Mad. Question items include accupational exposure during SFP mad.effect on exposure level of cut up low density racks, SFP cooling sys.vol of contaminated matl ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/08 7pp. 94045:179.
- 7811210257 Updates 770510 ltr info re control rod drive(CRD)uncoupling prog. Forwards historical data list of all CRD's occurring between 760522 & 771211. Improved duality Control & filter installation procedures are adequate to prevent uncoupling TURBAK:M 9. Commonwealth Edison Co. 78711/13 4pp. 94488:335.
- 781130003B Forwards Amend#39, #37, #48 & #47 for Lics DPR-19, DPR-25, DPR-19 & DPR-30 respectively. Amends revise Tech Specs reoperating temp & pressure limits. Also forwards Safety Evel & Fed Register Notice.

 IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/13.
- --7811300064 Amend#39 to the Operating Lic rev Tech Specs re operating temp & pressure limits
 IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/13.
 80s.
- --7811300067 Amend#37 to the Operating Lic rev Tech Specs re operating temp & pressure limits.

 1PPOLITO.T A. Operating Reactors Branch 3 (Pre 790625). 78/11/13.

 Bop
- --7811300070 Amend#48 to the Operating Lic rev Tech Specs re operating temp & pressure limits.

 IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/13
- --7811300073 Amend#47 to the Operating Lic rev Tech Space re operating temp & pressure limits.

 IPPOLITO.T.A. Operating Reactors Granch 3 (Pre 790625). 78/11/13 Spp.

- -7811300077 Safety Eval Rept in support of Amend#39,#37.#48 & #47 to Oper Lics DPR-19,DPR-23,DPR-29 & DPR-30,respectively * Office of Nuclear Reactor Regulation, Director 78/11/13 4pp
- -7811300089 Notice of Issuance of Amend#39.#37.#48 & #47 to Open Lics CPR-15.DPR-25.DPR-29 & DPR-30.respectively IPPOLITO.T A Operating Reactors Granch 3 (Pre 790625) 78/11/13 2pp
- 311280430 Forwards draft Sys Eval Prog Safety inputs re Topic VIII-3 A.Station Battery Test Req Requests they be transmitted to licensees DAVIB.D K Systematic Evaluation Programs Branch (Pre 790623) 78/11/14 23pp
- #1215007! Notification of workshops in Jan-May 1979 in Regions 1-5 to explain techniques of job analysis & performance testing & how to relate such testing to qualification plan development & training Designed for working level personnel MILLER.J.R. Assistant Director for Bite & Safeguards (Pre 791030) 78/11/15 5pp 94210 215
- 12180248 Forwards Rev#1 "Draft Radiological Effluent Tech Opecs" for BMR 's(NVRE0-0473) & "Preparetion of Radiological Effluent Tech Specs for Nuc Pur Plants" (NVRE0-0133) ORITES.8 & Assistant Director for Engineers & Projects (Pre 790425) 78/11/15 6pp 94364 125.
- 12050107 Forwards rev page to Topical Rept CE-1-A "Qual Assurance Prog.Rev 5." Rev reflects Reg Guidei 28 & 1 33 rev TURBAK.M & Commonwealth Edison Co 78/11/17 2pp 94333 334
- 11280213 Forwards current lic status list for subj Pacils REED.C. Communically Edison Co. 78/11/20 9pp 94012 130.
- 11280246 Forwards "Projected Fluence Values at Withdraue) for the Tapsules Designated to Meet the Requirements of 10CFR30 Append H " Table 1 to be attached to 781103 fir to 1ppolito TURBAK.M S Commonwealth Edison Co 78/11/20 2pp 94012.162
- 12120155 Forwards revised lists w/environ qualification of safetyrelated electrical equipment in response to NRC 780906 ltr (Includes SEP by equipment type, SEP submittal ref. location, lime required & type of snviron (URRAK, M.S. Commonwealth Edison Co. 78/12/01 31pp 94276-297
- .2140176 Forwards Oct 1978 Prog Activity Review listing meetings held a providing task-by-task activity summary for the month 308CN.L J. General Electric Co. 76/12/04 lipp 94103 174
- 2120070 Presents proj & justification for feedwater noizle/sparger & ontrol rod drive return line noizle inspec progs Concludes hat no further inspec of CRD return line noizle is returned.

 URBAK.M S Commonwealth Edison Co 78/12/05 Bpp 94274:001
- 2280129 Emphasizes importance of submitting accurate & complete info o NRC by licensees & applicants info submitted must be ubstantiated by date & calculations Licensee must notify IRC of any inaccuraties or enforcement action will result AVIS.JG Office of Inepection & Enforcement, Office of the irector 78/12/06 2pp 74311:335.
- 2140361 Requests eval of systems designed to accompdate effects of ipe breaks inside containment at subj facil in order for RC to complete BEP review IEMANN, D.L. Operating Reactors Branch 2 (Pre 790625), 78/12/07. PP. 03557-235.
- 2150099 Requests add1 info from SEP licensers relect penetrations freactor containments in order to complete eval IEFMANN.D L. Operating Reactors Branch 2 (Fre 790625) 78/12/08.pp 94212 032
- 2150228 Classifies lic amend for proposed fuel pool mod as Classes / & I not Classes III & I Requires addl charge of 48300 for sth of the two applita be paid w/in 15 days [LLER.W D. License Fee Management Branch. 78/12/i1 2pp.
- 1220093 Repts on problems encountered during integrated primary shainment leak rate test procedure re temp & humidity esurement in subvol bounded by water level Requests emption from IOCFRSO in order to eliminate subvol problem. RBAK-M.S. Commonwealth Edison Co 78/12/12. 6pp 94343:334

- 7812050013 Requests views of Regional Directors on Licensee performance eval of subj facils Forwards questions to be answered by 771209
 THORNBURO. H Division of Reactor Construction Inspection 77/11/23
 200.
- 7812190097 Accepts topical reptHCE-1-A RevMo. Comm Edison Co Quality
 Assurance Prog for Nuc Generating Stations "Requests
 submittal of 36 copies
 HAAES, W.P. Quality Assurance Branch 78/12/13 1p. 94376-317
- 7812220067 Summary of 781130 meeting of SEP Seismic Review Team in San Francisco. CA me progress in seismic review of facility List of attendees agenda & outline of draft final mept on facility seismic review encl
 LEVIN.H A Systematic Evaluation Programs Branch (Pre 790628)
 78/12/13 3pp 94248 311
- G Inspection reports, IE Bulletins & correspondence
- 7810110052 Forcerds IE Insp Repts 30-010/78-23.50-237/78-21 & 50-249/ 78-23 on 780807-10 & 16-18 & nutice of deviation DAVIS, A R Region 3. Chicago. Office of the Director 78/09/08 2pp 94080 049
- --7810110054 Notice of Deviation from inspec on 780807-10 & 780816-19 • Region 3. Chicago, Fuel Facility & Materials Safety Branch 78/09708 1p 94063 226
- --7810110062 IE Inspec Repts#50-010/78-23,#50-237/78-21 & #50-249/78-23 on 780807-10 & 16-18 during which I item of deviation was noted Failure to meet F9AR commitment for monitoring unit 2/3 liquic rad waste effluents

 OREGER, R. FISHER, W. L. Ragion 3. Chicago, Office of the Director 78/09/06 lipp 94063 227
- 7811010018 Forwards IE Inspec Repts#50-10/78-25.#50-237/78-22 & 50-249/78-24 on 780705-06.#1-12.19-20.780817.23-25.29-31 & 780901. during which has items of noncompliance were noted FIDMELLIO Region 3. Chicago, Reactor Operations Nuclear Support Branch 78/09/20 2pp 94290 141
- --7811010022 IE Inspec Repts#30-10/78-25, #50-237/78-22 & #50-249/78-24 on 780705-06.11-12.19-20.780817.23-25.29-31.780901.during which no items of noncompliance were nuted Major areas inspec followup of noncompliances & review of plant oper. BANKER.J L Region 3. Chicago. Office of the Director KNOP, R C Region 3. Chicago. Reactor Directors Nuclear Support Branch. 78/09/20 7pp.
- 7810110277 Responds to 780908 NRC ltr re deviation noted in loss Repts 50-010/78-23,50-237/78-21,50-249/78-23 Corrective actions liquid radwaste discharge monitor will be returned to svc & elem will be made operable REED. C. Componwealth Edison Co. 78/09/22 3pp. 94079:148
- 7810200203 Ack receipt of 780922 ltr informing NRC of steps taken to correct item of noncompliance identified in ltr of 780908 DAVIS.A 8 Region 3. Chicago, Evel Facility & Materials Safety Branch. 78/10/12 lp 94367 089.
- 7810300030 Forwards IE Circular#78-17 (See AND 7810230221) KEPPLER, J. G. Region 3. Chicago, Office of the Director 78/10/13
- 7811300261 Forwards IE Inspec Repts#30-010/78-26.50-237/78-23 & 50-249/78-23 on 780903-08.12-14.20-22. & 26-28 & Notice of Violation.
 FIORRLLI, O. Region 3. Chicago, Reactor Operations Nuclear Support Dranch. 78/10/25. 2pp 94075-233
- --7811300264 Notice of Violation from inspec on 780905-08,12-14,20-22 & 26-28 * Region 3, Chicago, Reactor Operations Nuclear Support Branch, 78/10/25, 1p. 94075-061.
- --7811300268 IE Inspec Repts#50-010/78-26.50-237/78-23 & 50-249/788-25 of 780905-08.12-14.20-22 & 26-28 during which I item of noncompliance was noted failure to rept a 30 day reportable event in 30 days BANKER.J L., CHRISBOTIMOS.N., HUGHSG.J. Region 3. Clicago, Reactor Operations Nuclear Support Branch. 78/10/25 15pp. 94075-237.
- 7811080334 Forwards request for addl info necessary to continue review of Insyc Inspec Prog proposed for subj facils Request relates to pump & valve testing portion of proposed program Requests response by 781130.

 ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 7906251. 78/10/26 9pp. 94406 288

- 7812050011 Forwards IE Inspec Repts#50-010/78-29, 50-237, -254, -295, -304/78-25, 50-249/78-27 & 50-245/78-26 on 781002 during which no items of noncompliance were noted REPPLER.J G. Region 3. Chicago, Office of the Director 78/10/30. 2pp. 94200 183
- --7812050027 IE Inspec Repts for subj facils on 781002 during which no items of noncompliance were noted Major areas inspected inclidiscussion of actions being taken by util to improve its reg performance & tour of Zion station MNDP.R C . FIDRELLI.G. Region 3. Chicago. Reactor Operations Nuclear Support Branch. MEPPLER.J.G. Region 3. Chicago. Office of the Director. 78/10/30. 3pp. 94200.85.
- 7811150063 Forwards IE Circular 78~18. "Underwriters Lab Firs Test " KEPPLER J. G. Region 3- Chicago, Office of the Director. 78/11/06 1p. 94112.240.
- 7811280486 Unresolved items noted in IE Inspec Repts#50-010/77-28, #50-237/77-25 & #50-249/77-25 have been reviewed & recommendations made Documentation of unresolved items witheld per IOCFR2 790(d) HIND. J.A. Region 3. Chicago, Safeguards Branch 78/11/16 (p. 94381:358)
- 7812050287 Forwards IE Bullstin 78-12A, "Atypical Weld Matl in Reactor Pressure Vessel Welds." KEPPLER, J. G. Region G. Chicago, Oppics of the Director 78/11/24. 1p. 94202.332
- 7812140081 Forwards IE Inspec Repts#50-010/78-28.#50-237/78-24 & #50-249/78-26 on 781010-13.781016-19 & Notice of Violation. KEPPLER, J. G. Region D. Chicago, Office of the Director. 78/12/01. 2pp. 94128-227
- --7812140086 IE Inspec Repts 50-010/78-28.50-237/78-24 & 50-249/78-26 on 781010-13 & 781016-19 Noncompliance noted defective security organizationobserved including access controls & physical barriers. Info partially withheld (ref FOIA Exemption 3). 8ELANGER, J. L., HOWELL, J. C., HIND, J. A. Region 3, Chicago, Bafeguards Branch. 78/11/20. 2pp. 94128:229.
- 7012130330 Natification of site visit on 781206-07 to discuss operational considerations re-insvc Inspec prog. ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625) 78/12/05. 1p. 94307.332
- 7812290026 Forwards 15 Sulletin 78-14, "Deterioration of Suna-N Components in ASCO Solenoids." KEPPLER, J. 0 Region 3, Chicago, Office of the Director. 78/12/19. 1p. 94208: 909.
- R. Periodic operating reports & related correspondence
- 7811140119 Forwards monthly operating rept for Oct 1978.
 BTEPHENSON, B. D. Commonwealth Edison Co. 78/11/08. 1p. 94425: 184.
- 8. Reportable occurrences. LERs & related correspondence
- 7810130165 Forwards LER#78-051/03L-0 BTEPHENBON.B.B. Commonwealth Edison Co 78/10/02. 1p. 94003;018.
- --7810130170 LER#78-051/OOL-O on 780907 during survey DIS 1600-11, valve #2-1601-24 failed to open in specified time limit, probably caused by foreign matter lodging in sciencid open 4-way valve.

 ** Commonwealth Edison Co. 78/10/02. 1p. 94003:019.
- 7811210356 Confirms sys trip on low suction pressure Valve line-up changed. Operability proven Caused by low pressure trip switch being out of calibr.
 BTEPHENBON, B. B. Commonwealth Edison Co. 78/10/02. Ip. 94485:019.
- 7810200092 Forwards LERW78-085/01T-0.
 8TEPHEN8ON-B.B. Commonwealth Edison Co. 78/10/13. ip. 94140:338.
- --7810200097 LER#78-095/01T-O on 780930: performing DOS 2300-3 the HPC1 turbine tripped on low pump section pressure of 11.5 psig which exceeds Dresden set point of 9.4inch Hg vacuum increase. Caused by Instru drift of pressure switch P82-2360. LINDBERG, C. Commonwealth Edison Co. 78/10/13. 2pp. 94140:339.
- 7610270234 Forwards LER#78-083/03L-0. BTEPHENBON, B. B. Commonwealth Edison Co. 78/10/17. ip. 94059:001.

- --7810270236 LER#78-053/03L-0 on 780926 Equip Attendent noted Main Steam
 Line Flow Buitch 261-2D was valved out due to unknown cause.
 Event had minimal safety significance & switch returned to
 svc. Burveillance sheets wo require daily check of switches.
 PULLO,R. E. Commonwealth Edison Co. 78/10/17. 1p. 94059:002.
- 7811240210 Forwards LER#78-051/03X-1. BTEPHENSON, B. B. Commonwealth Edison Co. 78/10/17. 1p. 94461:361.
- --7811240211 LER#78-051/03X-1 on 780707: during surveillance test DIS 1600-11. valve 2-1601-24 failed to operate in specified time limit Caused by foreign matter lodged in solenoid operated 4 way valve.preventing proper blead off. CIESZKIENIC2.B. Commonwealth Edison Co. 78/10/17 lp. 74461:362
- 7810270287 Forwards LER#78-052/03L-0 8TEPHENBON-8 B. Commonwealth Edison Co. 78/10/19. 1p. 94023; 339.
- --7810270296 LERM78-052/031-0 on 780922: During surveillance test diesel failed to start due to air start sys fault Second attempt was successful Air start sys will be mod to provided multiple atart attempts.

 DDYLE, J. E. Commonwealth Edison Co. 78/10/19. 1P. 94025: 340.
- 7811030143 Forwards LERW78-054/03L-0. STEPHENSON,8 8. Commonwealth Edison Co. 28/10/24. [p. 02723:312.
- --7811030145 LER 78-054/03L-0: on 780930 torus vacuum relief valve AO-1601-208 would not close. Alarm received Valve fully open. Caused by blown fuse in control circuit due to short in AO-1601-203 air operated solenoid valve. PARCELL Commonwealth Edison Co. 78/10/24 ip. 02723:313.
- 7811090116 Forwards LER#77-015/03X-1 BTEPHENBON.B.B. Commonwealth Edison Co. 78/10/27. 1p. 94042:296
- --7811090119 LERM77-015/03X-1 on 770402:CRD L-5 uncoupled & overtraveled when w/drawn to pos 48. Caused by unlabeled inner filter & abnormally long uncoupling rod Procedure rev & GA coverage improved to prevent future CRD uncouplings.

 WUCIQA: J. Commonwealth Edison Co. 78/04/02, 2pp. 94042:297.
- 7811090129 Forwards LERW77-022/03X-1. STEPHENBON, B. B. Commonwealth Edison Co. 78/10/27. 1p. 94042:303.
- --7811090130 LER#77-022/03X-1 on 770605:CRD L-5 uncoupled & overtravels6 when w/draun to pos 48. Caused by unlatched inner Pilter & abnormally long uncoupling rod. Procedure rev & GA coverage improved to prevent Puture CRD uncouplings.

 WUUCIGALU. Commonwealth Edison Co. 78/06/05. 28p. 94042:304.
- 7811090138 Forwards LERW76-072/03X-1. 8TEPHENSON.8.8. Commonwealth Edison Co. 78/10/27. 1p. 94042:319.
- --7811090142 LERW76-072/03X-1 on 761228:CRD J-11 uncoupled & overtrevelet when w/dreun to pos.48. An unletched inner filter & abnormally long rod resulted in coupling of CRD J-11.QA coverage improved & procedures rev to prevent uncoupling. HUUC10A.J. Cammanweelth Edison Co. 76/10/27. 2pp. 94042:320.
- 7811140160 Forwards LERW77-014/03X-1. 8TEPHENBON, B. B. Commonwealth Edison Co. 78/10/27. 1p. 94383;311.
- ---78i1i40163 LER#77-014/03X-1 on 770402: during normal startup oper.CRD H-8 was found to uncouple & overtravel when withdrawn to pos 48. Caused by an unlatched inner filter & abnormally long uncoupling rod.

 MUUCIOA. J. Commonwealth Edison Co. 78/10/27. 2pp. 94383:312.
- 7811210304 LER#76-068/03X-1 on 761212: during 50X core screen testing CRD F-5 uncoupled & overtraveled when withdrawn to position #48.Unlatched inner filter & abnormally long uncoupling rod resulted in uncoupling CRD F-5 during testing. #UUCIGA.J. Commonwealth Edison Co. 78/10/27. 2pp. 94486:103.
- 7811210301 Forwards LER#76-068/03x-1. 8TEPHENBON.8.8. Commonwealth Edison Co. 78/10/31. ip. 94487:334.
- 7811140193 Forwards LER#78-056/017-0. BTEPHENSDN.B.B. Commonwealth Edison Co. 78/11/01. 1p. 94384:282.
- 7811140203 Forwards LER#77-029/03X-1 "Update". BTEPHEN8ON, B. B. Commonwealth Edison Co. 78/11/02. 1p. 94384:342.

- --7811140213 LERW77-029/03X-1 on 770802 during 1/2 core scram test.CRD8 F-5 & H-7 uncoupled when w/drawn to position 4B Caused by unlatched inner filter & abnormally long coupling rod A pull test has been incorporated into overhaul procedure & Commonwealth Edison Co 78/10/27 2pp 94384 343.
- 7811140215 Forwards LER877-054/03X-1 STEPHENSON, B B Commonwealth Edison Co 78/11/02 lp 94400.033
- --7811140220 LER#77-054/03x-1 on 77-1102 during Unit 2 refueling outage, control rod drivet(CRDIH-5 overtraveled indicating uncoupling during functional testing Caused by unlatched inner filter abnormally long uncoupling rod

 # Commonwealth Edison Co 78/10/27 2pp 94400-034
- 7811160122 Forwards Reportable Occurrence#77-054/03x-1 "Update." STEPHENSON.R. 8. Commonwealth Edison Co 78/11/02 Ip 94125.192
- --7811160125 ROH77-054/03X-1 on 771102:CRD H-5 uncoupled during functional testing caused by unlatthed inner filter & abnormally long uncoupling rod Inner filter pull test in reassembly procedure & improved QA coverage incorporated HUUCIQA, J. Commonwealth Edison Co. 78/10/27, 2pp. 94135:193.
- '8811160112 Forwards LER#78-057/03L-0 STEPHENSON, B 8 Commonwealth Edison Co 78/11/09 1p 94135.138
- -7011160115 LER#78-057/03L-0 on 781013 2-1402-4b flow test valve failed to close fully against pump pressure Caused by value being inadequately lubricated ACHTERBERG. J. Commonwealth Edyson Co. 78/11/09 2pp 94135:159
- G11210177 Forwards LER#78-058/03L-0. STEPHENSQN.B.B. Commonwealth Edison Co. 78/11/13. ip. 94478:327
- -7811210181 LER#78-058/03L-0 on 781018: LPC1 suction valve MC-2-1301-5C failed to close during operability test Failure traced to valve sten not being adequately lubricated. Lubrication interval shortened ACHTERBERG. J. Commonwealth Edison Co. 78/11/13 2pp. 94478-328
- 31204019| Forwards LER#75-048/03:-2
 BTEPHENSON.0 0 Commonwealth Edison Co 78/11/17. 1p. 94457.115.
- -7B12040195 LERH75-04B/03-2 on 751007: during normal oper a through-wail crack was discovered in drywell-torus nitrogen surge line 1604-18. New startup procedure has been written incl precautionary measures to inerting procedure.
 PULLO.R. Commonwealth Edison Co. 78/11/17. 2pp 94497-116.
- 312150270 Forwards LER#78-061/03L-0 8TEPHENSON, B. B Commonwealth Edison Co. 78/12/08 ip. 94213:162.
- 7812150272 LER#78-061/03L-0 on 781108 AD-2-1601-24 failed to close due to solenoid valve stuck open w/dirt in valve internals. Solenoid valve replaced tested & returned to svc PARCELL Commonwealth Edison Co. 78/12/08. 1p 94213.163.
- 12180223 Forwards LERM78-052/03L-0.
 STEPHENSON, B.B. Commonwealth Edison Co. 78/12/08. 1p. 94366:131.
- 7812100228 LER#78-062/03L-0 on 781115 AO 1601-56 velve failed in closed position Caused by shorted out coil on solenoid Solenoid coil & fuse replated & velve verified operational. CLESZMIENICZ.8 Commonwealth Edison Co. 78/12/08. 1p. 74366-132
- 12270300 Forwards LER#78-033/03X-1.
 3TEPHENSON.8.8. Commonwealth Edison Co 78/12/12 1p. 94230:334
- '812270332 LER#78-033/03X-1 on 780522 during test performed on U-2 5/6 to measure overshoot & overspeed setpoint, the diesel tripped 4 times due to overspeed caused by governor speed set too high CHAN. J. Commonwealth Edison Co. 78/12/12 2pp. 94230:335.
- 2210189 Forwards LERW78-063/03:-0. .
 16PHENSON, B. B. Commonwealth Edison Co. 78/12/15. ip. 94278; 340.
- 81:2210195 LER#78-063/03:-0 on 781003: "A" pump flow was 2.6 SCFM, "B" gump was 0.0 SCFM (flow greater then 2.9 SCFM is normal). Caused by improper valve lineup & normal wear products from carbon impeller venes on sample lines, pump cavity & filter. MEIONER, R. Commonwealth Edison Co. 78/12/15, 3pp. 94278:341.
- 2270261 Forwards LER#78-063/03L-0.
 TEPHENSON.8.8. Commonwealth Edison Co 78/12/19 1p. 94232:331

- --7812270271 LERM78-043/03L-Q on 781123 MBIV 2-203-1A closed in tectors & MBIV 2-203-1C in 2 seconds after initiation signal coused by MBIV 2-203-1A & MBIV 2-203-1C valve timing out of adjustment ACHTERBERO, J. Componwealth Edison Co 78/12/19. 2pp 942:
- 7812290210 Forwards LER#78-064/03L-0 BTEPHENSON.B B Commonwealth Edison Co 78/12/21. 10 94190
- --7812290215 LER#78-064/03L-0 on 781124 leak found in 6"x6"x4"x4" ed on the 2/3 waste collector tank recirculation line Caused by acid corresion of carbon steel side of velocarbon steel flange will be replaced w/flange of stainless at eal.

 JANSEN, T. Commonwealth Edison Co. 78/12/21 1 p. 74190 349
- DOCKET 50-243 OREGON STATE UNIV. REGEARCH REACTOR

 9 Inspection reports, IE Bulletins & correspondence
- 7812270432 Forwards IE Inspec Rept#50-243/78-03 on /261024-26 duri which no items of noncompliance were noted. CREUS.J L. Region 5. San Francisco. Reactor Operations Nuclear Support Branch 78/11/22. 2pp 94312:342
- --7812270436 IE Inspec Rept#50-243/78-03 on 781024-245 divising which items of noncompliance were noted Major areas is expected logs & records, review & audit, requal training procedures, refueling, surveillance, experiments & tour of fac 3 I MORRILLP, J. CARLBON, J. C. Region 3, San Francisco, Heactor Operations Nuclear Support Branch 78/11/29 Spp. 94312 14
- DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT, UNIT 1

 F. Sacurity, madical, emergency & firs protection plans
- 7810250018 Request for add1 info on fire protec prog & protec of spreading(relay)room.

 ZIEMANN.D L Operating Reactors Branch 2 (Pre 7406251. 70/10/688.
- 7810170257 Responds to 780913 ltr requesting info re-proposed fir protects structural design mod. Items 1.2. & 3 of request are answered [tems 4 & 5 were enswered in fire protect assistantical of 780922.

 MHITE-L.D. Rochester Cas & Electric Corp. 78/10/11. 4pp 74236:346.
- 78:1060088 Forwards responses to 3 of 5 questions submitted in 70 ltr re fire protec. Add1 time is necessary to respond to questions 78 & 79.

 WHITE L.D. Rochester Ges & Electric Corp. 78/10/31. 11pp 94424:105
- 7812130012 Forwards rev pages of facil security plans (MASP). Requesithholding from pub disclosure pursuant to 2 790.

 WHITE L.D. Rochester Ges & Electric Corp. 78/12/€€3. 1p. 94306:326
- Q. Adjudicatory correspondence
- 7810230238 Forwards App) for Amend to Oper LiceDPR-189 Tech Spec & for \$4000.

 LARBON-L.K. LeBoeuf, Lamb, Leiby & MacRae. 78/10/12, 1p. 94052:245.
- 7810≥30256 Appl for amend to License DPR-18 to revise Tach Specin App A re DC electrical sys operation requirements.

 WHITE.L.D. Rochester Oas & Electric Corp. 78/10/10. 1ipp.
 94052;246.
- H. General correspondence
- 7810310173 informs that for SER normal channel of oral communicate will be followed but to expedite reviews direct oral communication between subj facil staff & members of SEP is encouraged.

 ZIEMANN.D.L. Operating Reactors Branch 2 (Fre 7906RE). 70/10/2pp. 94090:227.
- J. Insurance & indomnity information
- 7811290245 Forwards Endorsement#57 to Liability Policy#NELIA NR-E Endorsement#47 to Policy#MAELU MF-47. WHITE.L.D. Rochester Gas & Electric Corp. 78/11/16. 3pp. 94237:197.

- P. Operating license stage documents & correspondence
- 7811120304 Requests add1 info on pressure shielding steel diaphragm in turbine blogs so that ORBM2 can continue eval of mods.

 ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625). 78/09/13.

 3pp. 94087-241.
- 78:0160129 Requests AO days deferrel on response to 780711 Itr requesting proposed Tech Specs to implement Append I to 10CFRSO Add1 time required due to implementing improvements in Health Physics Prog.

 HHITE.L.D. Rochester Gas & Electric Curp. 78/10/10. 1p. 94004 044
- 7810170182 Forwards response to 780906 ltr This response is not complete & is pending review w/other BEP utils.Final response will be submitted on or before 781130. WHITE, L.D. Ruchester Oas & Electric Corp. 78/10/11. Ip. 94270:071.
- ~~7810170263 Responds to 780906 itr re overpressure protective subj Pacili Buperior addl alarms have replaced original computer alarm. Tech specs submitted 781011 do not inclinated valve testing & besting requirements.

 WHITE, L. D. Rochester Gas & Electric Corp. 78/10/11. ip. 94270.072.
- 7810160108 Forwards appl for amend to open lic & encl which set forth requested change in Tech Specs. Tech besis for change, & tech info asserting change is of no safety or environ significance
 LARSON,L. M. LeBbeuf, Lamb, Leiby & MacRes 78/10/12 App.
 94001-326.
- --7810160311 Appl for amend to operating lic.Requests that Tech Apecs to lic by amended to add definitions for surveillance intervals. Encl mafety eval shows proposed change does not involve change or increase in amounts of effluents.

 WHITE.L. D. Rochester Gas & Electric Corp. 78/30/10. Spp. 94001:330
- 7810310243 Denial of PASN's appl for extension of period of interim oper using the installed once-thru cooling sys. Denial based on NRC deference to EPA decision & NRC desire to evaluate that decision before taking action.

 8ALLARD.R.L. Environmental Projects Branch 1. 78/10/13. 3pp. 94091 325.
- 7810180148 Porwards Appl for Amend to Oper Lic. LARSON-L.K. LeBoeuf, Lamb, Leiby & MacRae. 78/10/16. 2pp. 94316:345.
- --7B101B013O Appl for amend to license DPR-18 requesting Tech Specs be changed to rev organisation. Bafety Eval & Fee Determination are encl. WHITE, L. D. Ruchester Gas & Electric Corp. 7B/10/11. 1ipp. 74316:347.
- 7810310147 Ack receipt of 780905 ltr re Systematic Eval Prog documentation procedures.Forwards response to util comments. ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625), 78/10/17. 28pp. 94090:179.
- 7810190068 Forwards Appl for amend to open liceDPR-18 w/requested changes in Tech Specs & check for \$4000 to cover appropriate fee. LARBON,L. K. LeBosuf, Lamb. Leiby & MacRae. 78/10/18. 3pp. 94413.113.
- --7810190069 Appl for Amend to Oper LiceDPR-18 u/proposed Tech Bpec change to include reactor averpressure protect sys requirements, safety eval & justification for classification of amend. HHITE, L. D. Rochester Gas & Electric Corp. 78/10/11, 15pp. 94413; 118.
- 7811060172 Surmary of 781004 mesting re-prog for review & eval of pips breaks inside subj. facil containment structure. Topics incl aspects of pipe breaks, asymmetric LDCA loads. Mechanistic Approach & costs of addl pipe stress calculations.

 JABBOUR, K. N. Systematic Evaluation Programs Branch (Pre 790625).

 BHEA. J. Uperating Reactors Branch 2 (Pre 790625). 78/10/20. 6pp. 94487:097.
- 7811100152 Requests addl info on ESF Switchover from injection to recirculation mode, isolation of reactor protec sys from nonasfety sys. ESF sys logic & design. specific drawings of slec sys & complete plant elec drawing indices.
 ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/26.
 Gpp. 94047:182.

- 7811070142 Revises schod for completion of Hestinghouse work re resolution of upper plenum injection of ECCS water due to resolution of Zirconium-water inconsistency. Also forwards schod of Erron Nuc Corp work on UPI.
 WHITE, L. D. Rochester Ges & Electric Corp. 78/10/31 2pp. 94044-020
- 7811070182 Proposes to perform radiographic examination of reactor coolant pump casing welds during 1981 refueling & maint outage using portable Linac X-Ray unit by Elec Pur Resinst which should be available in 1980.

 WHITE, L. D. Rochester Gas & Electric Corp. 78/11/01. 2pp. 94036: 399.
- 7811130315 Rept on 780906-07 site visit & 780908 meeting w/util. Examined site & obtained hydrological info FONTECILLA.H.M. Systematic Evaluation Programs Branch (Pre 790625), 78/11/02. 10pp. 94087:043.
- 7811130232 Notifies that Provisional Oper LiceOPR~18 issued on 780328 omitted Tech Specs for piping penetrations w/expension beliows Lealage testing w/air medium is not req for containment penetration sys. WHITE L.D. Rochester Gas & Electric Corp. 78/11/03. ip. 03058:159.
- 7811140241 Furnishes edd1 info re 781004 meeting to discuss BEP Topic 3-5.A. High Energy Line Breaks Inside Containment Discusses pipe stress calculations. high energy line break outside containment, Generic Tesk A-2 & Asymmetric LOGA loads. WHITE.L. D. Rochester Oes & Electric Corp. 78/11/08. 2pp. 94400:099.
- 7811280430 Forwards draft Bys Eval Prog Safety inputs re Topic VIII-3. A. Station Battery Test Req. Requests they be transmitted to licensees. DAVIS.D.K. Bystematic Evaluation Programs Branch (Pre 790625). 78/11/14. 23pp.
- 7812130176 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out matl. W/sencl Registration Form & List of Locations. MILLER, J. R. Assistant Director for Bite & Bafeguards (Pre 791030). 78/11/15. Spp.
- 7812190054 Forwards Rev81 "Draft Radiological Effluent Tech Specs" for PHR's(NAREG-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREQ-0133). ORIMEB.8.X. Assistant Director for Engineers & Projects (Pre 790425). 78/11/18. 6pp. 94215:075.
- 7811270260 Ack receipt of request for approval to amploy the esisting cooling sys for Full core discharge sched for early Spring 1979 at Ginna. Request falls in Class III appl for lic amand & util is requested to forward 64.000.
 MILLER.W. O. License Fee Management Brench. 78/11/17. ip. 94272: 004.
- 7811280216 Describes fuel inspec plans for 1979 shutdown At and of present Cucle 8.8 to 10 Exxon fuel assemblies will be inspec visually whinoculars. Shutdown & inspec planned for late Feb & sarly Narch: 1979.
 WHITE, L. D. Rochsater Oas & Glectric Corp. 78/11/20. 2pp. 94012:061.
- 7812070146 Notice of seminar on 781208 on new Model Radiological Effluent Tach Space for nuc pur plants Requests advance submission of seminar specific questions Wencl Seminar Info Shest, Proposed Agenda & maps.
 ORIER. B. H. Region i, Philadelphia, Office of the Director. 78/11/21. Spp. 94375:248.
- 7811290179 Forwards add1 drawings for systematic eval prog(8EP)in response to 780626 request. Proprietary drawings will be provided under cover. 26 oversize drawings in Central Files. WHITE: L. D. Rochester Gas & Electric Corp. 78/11/22. 443pp. 94474: 218.
- 78:2010373 Rept on 78:109 measurement of nuc pur reactor environ to determine capability of existing personnel desimetry sys at subj facil. Results will be forwarded to NRC for study. Util cooperation was exemplery.

 BLOCK.8. Environmental Evaluation Branch (Pre 770625). 78/11/24.
 2pp. 94416:334.
- 78:2060303 Notification of 78:207 meeting w/BEP Dwner's Group in Bethesda.MD to discuss plane to address selsmic input for use in BEP selsmic review. LEVIN.H.A. Bystematic Evaluation Programs Branch (Pre 790625). 78/11/24.

- from reactor vessel 15 days after shutdown per dileting Tech Spece Refueling should proceed so reactor vessel inspec can be accomplished. ZIEMANN. D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/27. 3pp. 94127: 232.
- 7812140316 Forwards Amend#20 to Provisional Oper Lic#DPR-18 & Notice of Issuance.
 ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625) 78/11/27.
 3pp. 03556:330.
- 7912110038 Discusses possible dangers of LDCA in containment purging during normal plant open Requests either commitment to limit purging or justification for continuing Wencl AND. 47812080207. ZIEFANN.D.L. Operating Reactors Branch 2 (Pre 790628). 78/11/29. 8pp. 94408:147.
- 7812030152 Forwards "Ginna Btation Insvc Pump & Valve Test Prog for the Period 79031-B01231: " Append C to Fecil Quality Assurance Manuel.
 WHITE L. D. Rochester Gas & Electric Corp 78/11/30 3app. 94318: 309.
- 7812030187 Responds to 780906 NRC request for review of environ qualtable for elec equip at subject11. Forwards requested info & ray pages for initial 780224 environ qual rept. Facil does not use connectors or junction boxes.

 HHTE-L D. Rochester Gas & Electric Corp. 78/12/Q1. 31pp. 94335:176.
- 78120B0123 Bummary of 781004 meeting re High Energy Line Breaks inside Containment Add1 info is being gethered on this subj. HHITE: L.D. Rochester Gas & Electric Corp. 78/12/04. 1p. 94104: 335.
- '812080128 Forwards ref list inadvertently omitted from encl of Environ Gual of Elec Equip Rev 1 submitted 781201. WHITE: U.D. Rochester Gas & Electric Corp. 78/12/04. 2pp. 74100:349.
- 812280075 Emphasizes Importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantilated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVISI.J. 0. Office of Inspection & Enforcement, Office of the Director. 78/12/06. Spp. 03555:191.
- 812150101 Requests add1 info from SEP licensees re elec penetrations of reactor containments in order to complete eyel.

 ILEMANN, D. L. Deparating Reactors Branch 2 (Pre 790605). 78/12/08.

 4pp. 94012:058.
- 312210021 Forwards NURE9-0495.Vol 1.No 2 "Btatus Summary Rept-Bys Eval Prog." W/o encl. 21EMNN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/08. 2pp. 94249:337.
- HER10047 Forwards Amend@Pi to Provisions1 Oper Lic@DPR-18 revising Tech Space as requested in 780308 itr w/8afety Eval & Notice of Issuance.

 IIEMANN.D.L. Operating Reactors Branch R (Pra 790625). 78/12/08.

 ZPP. 94269:019.
- 7812210050 Amend#21 to Provisional Oper Lic*DPR-18 revising Tech Space re-reduction in maximum pressurizer heatup rate from 200F per haur to 1006-reduction in frequency of tests for Low Nuc Pur 25% trip setpoint & elimination of valve test.
 ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/12/08. 7pp. 94269:021
- 7812210052 Safety Eval Rept supporting Amend#21 to Provisional Oper LickDPR-1B concluding that proposed changes are acceptable & health & safety of public will not be endangered by oper in proposed manner. ** Office of Nuclear Reactor Regulation, Director. 78/12/08. App. 94269:028.
- 7812210055 Notice of Issuance of Amend#21 to Provisional Oper LiceOPR-18. ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/12/08. Epp. 94269:032.
- 2260010 Natice of 780110 meeting to discuss 10CFRB0 Tech Spec equirements for subj facil. HEA.J.J. Operating Reactors Branch 2 (Pre 790625). 78/12/13. 3pp. 94020:303.

- Full-Term Oper Lic. & Revent to Suppl IV to Applicant's Tech Suppl Accompanying Appl for a Full-Term Oper Lic FARON.R.S LeBosuf, Lamb. Leiby & MacRas 78/12/21 63pp. 94344:144.
- --78:2220118 Amend 8 to appl to convert Provisional License DPR-18 to full term license. Amend transmite Rev#4 to Suppl IV to applicant's tech suppl accompanying appl for full term oper lic.Cert of Svc encl.

 HHTTE.L.D. Rochester Oas & Electric Corp. 78/12/OA. 2pp. 94344:062.
- 7812290090 Ack receipt of 781115 ltr from NRC providing ROE w/rev Standard Tech Specs re radiological effluents Due to delay in reteipt of ltr & to provide time for reviews. ROE plans to submit proposed Tech Specs by 780215(sic). HMITE.L.D. Rochester Ose & Electric Corp. 78/12/21. lp. 74190:111.
- G Inspection reports, 1E Bulletine & correspondence
- 7010180177 Forwards IE Inspec Rept#50-244/78-18 on 780914 during which most teams of noncompliance were noted BRUNNER, E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/05. Spp. 94317:129
- ---7810180179 IE Inspec Rept#50-244/78-18 on 780814-10 during which no teams of nancompliance were noted Mejor areas inspected included plant opers status of previous inspecs findings, them & vol control eys. followup actions.

 Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/05. 15pp. 94317:131.
- 7B11060174 Forwards IE Circular#78-17 (See AND: 7810230221, Docket #30-133, 781013.)

 GRIER, B. H. Region i, Philadelphia, Office of the Director. 78/10/13. 1p. 94489:108.
- 7812010147 Forwards 1E Inspec Rept#50-244/78-19 on 780919-21 during which no items of noncompilance were noted. SMITH, 0.H. Region i, Philadelphia-Fuel Facility & Materials Bafet Branch. 78/10/18. 2gg. 94418:089.
- --7812010150 IE Inspec Rept#50-244/78-19 on 780919-21 during which no items of noncompliance were noted. Hajor arises inspected incl:prog for quality control of analytical neasurements, audit results & effluent control procedures.

 KOTTAN.J.J. 8TOHR.J.P. Region I, Philadelphia, Fuel Facility & Materials Safety Branch. 78/10/18. 9pp. 94418:091.
- 78:10:10:00:36 Responds to 78:05:23 & 78:07:28 ltrs protesting proposed civil penalties etemming from Inspect50-244/78-03. Item 9 of inspectent is recatagorized as a deficiency, reducing penalty from #31:000 to #24:000.

 DAVIS, J. G. Office of Inspection & Enforcement, Office of the Director. 78:10:794. 3pp. 94302:242.
- --78i1010041 Orders licenses to pay civil penalties of 424,000 within days because of noncompliance in Notice of Violation resulting from inspec on 780120-780203 & 780213-17. W/ancl Appendices: correspondence re mitigation of penalty. DAVIB.J. 0. Office of Inspection & Enforcement, Office of the Director. 78/10/20. 4pp. 94302:248.
- 7812060298 Forwards IE Inspec Rept#50~244/78-20 on 780927-28 during which no items of noncompliance were noted.

 BRUNNER.E.J. Region t, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/10/27. Spp. 94382; 231.
- --7812060304 IR Inspec Rept#80-244/78-20 on 780987-28 during which no items of noncompliance were noted Major areas inspected inclisies splice insulation & 818 reast feature.
 RAYHOND, H. J. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/27. Spp. 94382:233.
- 7811290154 Forwards IE Circular #78-18, "UL Fire Test. "W/encl AND: 7811150002. QRIER.B. H. Region i. Philadelphia. Office of the Director. 78/11/06. pp. 94239; 357.
- 78:2:90032 Forwards IE Bulletin#78-:34. Suppl to IE Bulletin 78-:2. W/encl AND:78:1300055. ORIER, B. H. Region i, Philadelphia, Office of the Director. 78/11/24. pp. 94133:009.
- 7812130318 Ack receipt of 781110 ltr & check in the amt of \$24,000 remitted in full payment of Order Imposing Civil Monetery Penalties dtd 781020.

 BRYAM.8 E. Repion i, Philadelphia, Reactor Operations Nuclear Support Br

R Periodic operating reports & related correspondence

- 7810170213 Forwards Monthly Oper Rept for Sept 1978

 BNOW B Rochester Ges & Electric Corp 78/10/06 ip 94236-145
- --7810170215 Monthly Oper Rept for Bept 1978. MCNAMARA, A E. Rochester Gas & Electric Corp. 78/10/05. Spp. 94236-146

DOCKET 30-245 MILLSTONE NUCLEAR POWER STATION. UNIT 1 B. Utility Preliminary Bafety Analysis Report, amends

- 78:1240:189 Emergency Plan Unit 1 Final Safety Analysis Rept Append G. Amend 37 & Emergency Plan Unit 2 Final Safety Analysis Rept Append 12A. Anend 45. covering organizational control of emergencies.coordination w/off-aite groups & protec actions.

 * Northeast Utilities. 78/11/17. 100pp.
- F. Security, medical, emergency & fire protection plans
- 7811290148 Finds changes to Site Security Plan submitted 781004 do not decrease the effectivness of the Plan & are acceptable ZIEMANN.D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/15. 2pp. 94239 339
- Q. Adjudicatory correspondence
- 7811020325 Forwards recent memorands is certain problems experienced in connection w/pipe support base plate design. StePf is determining if these problems have generic implications for oper facils & will keep Lic Bd informed of any new info. ORAY.J.R. Office of the Executive Legal Director 78/10/19. lp. 94240.221
- --7811020332 Forwards 780628 memo to R Mattson.re (nho on failures of safety-related pipe supports at Millstone 1 & design deficiencies on similar equip on Shoreham 1. Memo gives Bd notification of pipe support base plate design.

 BTELLO, V Division of Operating Reactors 78/09/28. 2pp. 94240.222.
- --7811020343 Addresses pipe support base plate problem Discusses review of support redesigns & capability of the anchor bolts to withstand cyclic loadings.

 NORMAN.v S. Engineering Branch (Pre 791030), 78/06/02, 2pp. 94240
- H General correspondence
- 7810310037 Informs that for EEP normal channel of oral communication will be followed, but to expadite reviews direct train communication between subj facil staff b members of BEP branch is encouraged.

 ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/10/10 2pp. 94094-360.
- K. Utility Final Bafety Analysis Report (FBAR) & amends
- 7811240187 Forwards Append Q of Hillstone Unit 1 Final Safety Analysis Rept & Append 12A of Millstone Unit 2 Final Safety Analysis Rept covering site emergency plan. These have been designated Amendment Nos 37 and 45 respectively.

 COUNSIL, W. Q Northeast Utilities. 78/11/17. 2pp.
- P. Operating license stage documents & correspondence
- 7912050004 Forwards Licensee Performance Eval Questions for subj facils in response to 771123 request. Feels it is possible that dev of statistical methodology for such eval may not justify the effort. Qualitative eval may be as good. Urges I-year test. ORIER, B.H. Region I. Philadelphia. Office of the Director. 77/12/13. 12pp. 94200:114.
- 7811130088 Forwards initial eval of 8 complete 8EP topics & response to request for clarification of 8EP documentation procedures made at 780331 meeting. Requests response re facts used to define plants by NRC staff. (See AND#7811130337.) EISENHUT. D.Q. Assistant Director for Systems Engineering (Pre 791030). 78/08/17. 2pp 94076:334.
- 7810110070 Forwards Amend#83 to Facil Open Lic#DPR-21 revising Tech Bpers as requested in 780303 ltm u/Barety Evaluation & Notice of Issuance. ZIEMANN.D. L. Openating Reactors Branch 2 (Pre 790625). 78/09/26. 3pp. 94061:049.

- --7810110073 Agend #53 to Facil Oper Lic#DPR-21 revising Tech Specs re to require 3 operable fire pumps & add1 spray &/or sprinkler sys & fire hose stations to be operable in the turbine bidg. ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625). 78/09/26. 10pp. 94061.050
- --7810110074 Sefety Evaluation Rept supporting Amend#53 to Facil Oper Lic #DPR-21 concludes that the fire protec plan assures that 14 the public health & safety will be protected • Office of Nuclear Reactor Regulation, Director. 78/09/26. 33pp 94061.039
- --7810110075 Notice of Issuance of Amend#50 to Facil Oper Lic#DPR-21 on 780926 WAMBACH.T V Operating Reactors Branch 2 (Pre 790625). 78/09/26 3pp. 9406]:111
- --7810110076 Submits evaluation of SER. Recommends change in valve supervision HALL: R E Brookhaven National Laboratory 78/08/23. 2pp 94051:114
- 7810110140 Forwards rev plant unique assessment of multiple consecutive safety/relief valve actuations, but w/o using staggered & elevated SRV setpoints as originally submitted on 780731.

 CDUNGIL, W. C. Northeast Utilities. 78/10/04. 12pp. 94064:262.
- 7810110176 Responds to requirements re undetected single failure to adversally affect reactor protes was.
 COUNBILLY 0 Northeast Utilities 78/10/06. 2pp. 94069:100.
- 7910130139 Performance evaluation of process radiat monitoring sys red detecting fuel leakage. There have been no abnormal fuel related events resulting in sufficient coolant activity changes. Monitors very sensitive to pur level changes. CDUNSIL, N. Q. Northeast Utilities. 78/10/10. 2pp. 94003:045.
- 7810170140 Objects to request to follow Unit 2 re 740516 emergency plan as unwarrented & impractical Metter was discussed w/IE & NRR who agreed that Rev 4 of 770805 will remain in effect at this time Rev 5 should be issued by 781115.

 COUNSIL, N. O. Northeast Utilities. 78/10/10. 2pp. 94235:359.
- 7810240099 Rejterates that NRC Btaff concurrence will be obtained before new high density spent fuel racks are used in either the originally lic configuration or in less than optimum pattern.

 COUNSIL.W. O. Northeast Utilities. 78/10/13. 2pp.
- 7810270203 Forwards proposed rev to Environ Tech Spec & to Sefety Yech Spec for subj facil, permitting the STS & ET8 to become two independent documents.

 COUNBIL, H. O. Northeest Utilities. 78/10/20. 35pp. 94036:313.
- 7810310073 Informs of plans to resolve Staff concerns re seismic loads & Multiple Safety/Relief Value actuations. Util will reinforce outer torus support columns to meet short-term acceptance criteria w/o question by mid-Dec. 1978. COUNSIL, W. o. Northeast Utilities. 78/10/23. lp. 94094:312.
- 7811010166 Notifies that licenses intend to enter into certain sale & leaseback arrangements in order to finance constr of a refuel outage bldg at Millstone sits. Various aspects of financing are described.

 QARFIELD. 9. Day, Berry & Howard. 78/10/25, 5pp. 94391:239.
- 7811130335 Summary of 780914 meeting w/GE representatives & Mark 1 Owners Group re progress of Long Term Prog w/attendance list & agenda(RD-9-A-Merki, Standards.) GRIMES.C. Plant Systems Shanch (Pre 791030). 78/10/26. 67pp.
- 7811070288 Responds to 780928 FOIA request for documents submitted to EJ Brunner re a beseline eval for RFP. The NRC has located no documents subject to this request. FELTON.J.M. Division of Rules and Records. 78/10/31. 1p. 94040: 339.
- --7811070294 FDIA request for repts submitted to EJ Brunner re baseline eval for RIP. H/encl 780630 Brunner memo, JOHNSON: L. C. Affiliation Unknown, 78/09/28, 1p. 94040:340.
- 7811130193 Forwards "Boron Carbide" rept prepared by Carborundum Codescribing requal prog tests & results re subj facile.

 Answers to NRC queries & other analyses are also entires is non-proprietary version of Carborundum rept.

 COUNBIL, H. Q. Northeast Utilities. 78/11/03. 14pp.

- '811140153 Discusses Progress of NUSCO Nuc Records Prog for CN Yankee Atomic Pur & NE Nuc Energy Co Microfilming may not be completed by 790731 but hard copy will be evailable Asss whether projected 790731 date will be satisfactory CDUNBIL. W Q Northeast Utilities. 78/11/06 2pp 94383 304
- 911290288 Responds to 781104 request for info concerning licensee reg performance eval for Region 1 plants by NRC Provides
- ORIER, BH Region 1. Philadelphia. Office of the Director. 78/11/09. 9pp
- Bil2B0430 Forwards draft Bys Eval Prog Safety inputs re Topic VIII-3 A. Station Battery Test Red Requests they be transmitted to
- Bystematic Evaluation Programs Branch (Pre 790625) DAVIS.D K 78/11/14. 23pp
- Bi2150097 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73 Requests pre-workshop registration of attendees to facilitate sending out matl H/encl Registration Form & List of Locations MILLERJ R Assistant Director for Site & Safeguards (Pre 791030) 78/11/15 Spp. 94212:008.
- 312180253 Forwards RevMi "Draft Radiological Effluent Tech Space" for BUR's (NUREQ-0473) & "Preparation of Radiological Effluent Tech Space for Nuc Per Plants" (NUREQ-0133) ORIMES B. K. Assistant Director for Engineers & Projects (Pre 790625) 78/11/15 App 94369.290
- 112210056 Responds to 781116 telecon. Forwards copies of ANS meeting
- papers which demonstrate attention to ALARA per ROB. B. O'HARA). C. Ebasco Bervices, Inc. (subs. of Enserch Curp.). 78/11/17. 10
- 7812210070 "Experience in Decontamination & Repair of Radwaste Concentrator at Milistone Unit#1 "Describes procedures BUMMA-) Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 78/11/17. 19pp.
- 7812210074 "Peach Bottom 2 & 3 Regenerative Heat Exchangers Chem Contamination & Seel Ring Repairs." Describes work performed In 1977 & 1978.
- ROHNER, M. M. Philadelphia Electric Co. 78/05/06. 22pp.
- 7812210077 "Peach Bottom 2 & 3 Regenerative Heat Exchangers Chem Decontamination & Solidification. " Describes work performed in 1977 CABEY, Q. E. Dow Chemical Co. 78/02/16. 38pp.
- 11270183 Responds to 780817 request for comments on Systematic Eval Trof topic assessments into is substantively correct, but it is suggested that these & future assessments be written w/ specific ref to decuments used by NRC to form conclusions. COUNDIL, H 0. Northeast Utilities. 78/11/20 1p. 94272-081.
- .2070166 Notice of seminer on 781208 on new Model Redicingical iffluent Tech Specs for nuc pur plants. Requests edvance submission of seminer specific questions W/encl Seminer Info sheet. Proposed Agenda & maps.

 REER.B. H. Region i, Philadelphia. Office of the Director.

 18/11/21. 8pp. 03555:128.
- 2060303 Notification of 781207 meeting w/8EP Dwner's Group in sthesds: MD to discuss plans to address seismic input for se in SEP seismic review.

 EVIN.H A. Bystematic Evaluation Programs Granch (Pre 790625).

 B/11/24 2pp.
- 2140318 Amend#20 to Provisional Oper Lic#DPR-18 revising Tech Bpecs of define existing requirements for surveillance frequency. IEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/27. pp. 03556:353.
- B12140339 Notice of Issuance of Amend#20 to Provisional Oper Lic #DPR-18 revising Tech Specs to define existing requirements for surveillance fraquency.
 ILEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/2 Rpp. 03056:387. Operating Reactors Branch 2 (Pre 790625). 78/11/27.
- 2110019 Discusses possible dangers of LOCA in containment purging ring normal plant oper Requests either commitment to limit irging or justification for continuing. W/snc1 ANC: #812080207.

 **EMANN.D.L. Operating Reactors Branch C (Pre 790623) 7821 EMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/29. ip. 94339: 271.

- 7812110328 Approves proposed schedule for installing feedwater pump trip during refueling outage currently scheduled for 1979 ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/11/30 2pp 94204 280
- 7812140024 Forwards Amended4 to Provisional Open Lic#DPR-21 for subj facil as requested in 780320 ltr Wenci Bafety Eval & Notice of Issuence ZIEMANN.D L D 2pp. 94127 238 Operating Reactors Branch 2 (Pre 790625). 78/12/01
- ~-7812140027 Amend#34 to Provisional Open Lic#DPR-21. rev provision of Append A Tech Specs to allow in-place testing of Standby gas Treatment Sys at lower flow rates ZIEMANN.OL Operating Reactors Branch 2 (Pre 790625). 78/12/01. 7pp. 94:17 240
- ~~7812140030 Safety Evaluation Rept Bupporting Amend#54 to Provisional Open LiceBPR-21 concluding that proposed change is acceptable & safety of pub will not be endangered # Office of Nuclear Reactor Regulation. Director 78/12/01 2pp 94127.247
- --7812140034 Notice of Issuance of Amend#54 to Provisional Oper Lic #DPR-21 to allow in-place testing of Standby Cas Treatment Bys et lower rates. Bys et lower rates. ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625) 78/12/01 2pp 94127 249
- 7812080121 Forwards list showing clerical logistics & reasons for each change to Gafety Tach Boscs for subject1 List inadvertently omitted from util 781020 1th COUNSIL.M. Q Northeast Utilities. 78/12/04 9pp. 94106:326
- 7812130322 Forwards Tech Spec pages 3/4 2-6 & 2-7 omitted from Amend 34 due to clerical error ZIEMANN.D L. Dperati 4pp. 94307.038 Operating Reactors Branch 2 (Pre 790625). 78/12/04.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held & providing task-by-task activity surmary for the manth. BOBCN, L. J. General Electric Co. 78/12/04. 11pp
- 7812130072 Forwards Amend#55 to Provisional Oper Lic@DPR-21 & Amend 44 to Facil Oper Lic@DPR-65 & Notice of Issuence ZIEMANN-D L. Operating Reactors Branch 2 (Pre 790625). 78/12/04. Opp. 94210 292.
- --7812180077 Amend#55 to Provisional Open LicaDPR-21. Changes fach Specs re radioactive liquid sampling & analysis
 ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/04.
 2pp. 94210:295.
- -- 7812130082 Amend#44 to Facil Open LickOPR-65 Changes Tech Speck re REID.R H. Operating Reactors Branch 2 (Pre 790625). 78/12/04. 5pp. 94210: 297.
- --7812130086 Notice of Issuance of Amend#55 to Provisional Oper Lic #0PR-21 & Amend#44 to Facil Oper Lic#DPR-65 ISEMANN.D L. Operating Reactors Branch 2 (Pre 790685). 78/12/04.
- 7812190176 Responds to 780203 & 781020 itrs. Concludes, that since implementation of Append 1 Tech Space will cover items proposed by requests; plan to defer action on these requests so they are reviewed concurrent w/Append 1 implementation. IIEMANN.D.L. Operating Reattors Branth 2 (Fre 790625). 78/12/05. 2pp. 94340:055.
- 7817250012 Intende to apply quality assurance requirements 10CFR50 Append B & 10CFR71 to delivery of matly to a carrier for transport or such matls outside confines of site in Comm epproved package design. COUNSIL. H. C. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 78/12/05. ip. 94020:307
- 7812290135 Emphasizes importance of submitting accurate & complete info to NRC by licensee & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inecoracies or enforcement action will result DAVIB. J G. DEPice of Inspection & Enforcement, DPPice of the Director. 78/12/06. App. 9431:312.
- 7812150105 Requests add1 info from BEP licensees re elec penetrations of reactor containments in order to complete eval.
 ZIEMANN, D. L. Operating Reactors Branch 2 (Pre 790625). 78/12/08. ZIEMANN, D. L. Dp 4pp. 94212: 085.

- 7812180143 Informs that reinforcement of all outer torus columns 16 complete Short Term Program strength ratio is now 0 353. COUNTIL, M G Northeast Nuclear Energy Co. (subs. of Northeast Utilities), 78/12/08. ip 94365:278
- 7812210031 Forwards NUREO-085.Vol 1.No 2 "Status Summary Rept-Bys Eval Prog " W/o encl. ZIEMANN.D L Operating Reactors Branch 2 (Pre 790625) 78/12/08 2pp 94249.355.
- 7812260285 Forwards Amend#56 to Provisional Oper Lic OPR-21 & Amend#45 to Facil Oper Lic MOPR-65 revising Tech Specs as requested in 14 trs between 770221 & 780321 w/Safety Eval & Notice of Issuence.
 - REID.R.M. Operating Reactors Branch 4 (Pre 790625) 78/12/04. 4pp. 94155:280.
- --7812260289 Amend#56 to Provisional Oper Lic#DPR-21 revising Tech Specs re admin controls to reflect organizational struc & greater flexibility of entry into high radiat areas. ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625). 78/12/08. 20pp. 94155:284.
- --7812260299 Amend#49 to Facil Oper Lic#DPR-65 revising Tech Spacs re refueling water storage tank sump recirculation actuation satpoint-supp safety features response times incore detector operability, meteorological monitoring instru & admin REID.R M. Operating Reactors Brench 4 (Pre 790629), 78/12/08. 6200, 94160,030
- ---7812260301 Safety Eval Rept Supporting Amend#56 to Provisional Oper Lic #DPR-21 & Amend#45 to Facil Oper Lic#DPR-55 concluding that proposed changes are acceptable & safety of public will not be endangered by oper in proposed manner.

 **Dffice of Nuclear Reactor Regulation, Director, 78/12/08.
 15oc.
- --7812260306 Notice of Issuance of Amend#36 to Provisional Oper Lic #DPR-21 & Amend#45 to Fecil Oper Lic#DPR-65. REID.R. W. Operating Reactors Branch 4 (Pre 790625). 78/12/08. 3pp. 94135:020.
- 78121900B3 Internal "plant design change procedure" for the purpose of venting high density spent fuel racks has been processed & approved Change does not constitute an unreviewed sefety question.
 COUNSIL, N.O. Northeast Utilities. 78/12/12. 2pp. 94343:018.
- 7812050013 Requests views of Regional Directors on Licenses performance eval of subj facils. Forwards questions to be answered by 771209.

 YHORNBURG. H Division of Reactor Construction Inspection. 77/11/23.
- 7812270462 Notice of 790111 meeting to discuss Feedwater Sparger Prog incl review of Feedwater Notice Cladding, Sparger Design & Plans for Replacement. SHEA J. J. Operating Reactors Branch 2 (Pre 790625). 78/12/13. lp. 94015: 209.
- 7811210367 Forwards add1 info re multiple consecutive sefety/relief velve actuation of Mark I containment program. SOSON.L.J. General Electric Co. 78/11/13. 3pp. 94485:126.
- Q. Inspection reports. IE Bulletine & correspondence
- 7811060205 Forwards [E Circular#78-17. (See ANO: 7810230221: Docket #50-133, 781013.)
 GRIER, B. H. Region 1. Philadelphia: Office of the Director. 78/10/13. 1p. 94499: 210
- 7812010272 Forwards IE Inspec Repts#50-245/78-32 & 50-336/78-28 on 780814-15 during which no items of noncompliance were noted. GRIER, B. H. Region 1. Philadelphia. Office of the Director. 78/10/20. 2pp. 94417; 212.
- --7812010274 IE Inspec Repts#50-245/78-32 & #50-336/78-28 on 780814-15 during which no items of noncompliance were noted Major areas inspected incl. security ejen. security opparization access controls, response procedure to 780811 truck fire. SMITH, R. H. Region i. Philadelphia, Safeguards Branch. 78/10/20. 3pp. 94417: 214.
- 7812110314 Forwards IE Insp Rept 50-245/78-29 & 50-336/78-24 on 780723-28 & 780814-18 Na noncompliance noted.
 BRUNNER,E.J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/23. 3pp. 94204:117.

- --7812110316 IE Insp Repts 50-245/78-29 & 50-336/78-24 on 780723-28 a 780814-18 No noncompliance noted Major areas inspected: Unit 2 turbine bldg.auxiliary bldg.control room.portions of enclosure bldg & fire protection sys.

 SHEDLOSKY.J.T. Region 1. Philadelphia. Office of the Director MCCABE,E.C. Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch. 78/10/23 21pp. 94209.120.
- 7811020236 Responds to 780308 itr requesting NRC IE Repts#90-245/77-29 & 50-336/77-28 Portions of Appendix A not subj to 2.790 forwarded to recipient W/out encls. FELTON.J.M. Division of Rules and Records. 78/10/26. ip. 94247:071
- 7812110303 Forwards IE Insp Rept 50-245/78-34 on 781003-06 & notice of violation.

 BRUNNER, E. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Granch. 78/10/27. 3pp. 94204:079.
- ---7812110305 Notice of violation from insp on 781003-06. * Region i. Philadelphia. Office of the Director. 78/10/27 ip 94204.082
- --7812110310 IE Insp Rept 50-245/78-34 on 781003-06. Noncompliance noted failure to perform surveillance procedure per instructions.

 BAUNACK.H.H. Region 1, Philadelphia, Office of the Director.
 BETTENHAUSEN.L., KIBTER, H.B. Region 1, Philadelphia, Reactor
 Operations Nuclear Support Branch. 78/10/27. 7pp 94204:083.
- 7811160152 Forwards Inservice Inspec Class II Rept from examinations conducted from Feb-Bept 1978 re discrepancies in isometric drawings.LPC1 pipe weld indications structural defects in Low Pressure Coulant Bys.Core Spray, & Isolation Condenser. COUNSIL,N. 9. Northeast Utilities. 78/11/01. 28pp. 94135:297.
- 7812010345 Forwards licensee performance evaluation for Region 1.No operating reactor in Region 1 considered to have either abnormal or unusual safety concern GRIER.B.H. Region 1. Philadelphia. Office of the Director. 78/11/01. 4pp. 00002:259.
- 7812130214 Forwards IE Inspec Rept#50-245/78-33 & #50-336/78-29 on 780906-07 & 780919 during which no items of noncompliance were noted.

 MARTIN,M.Q. Region 1, Philadelphia, Bafeguards Branch. 78/11/01. 2pp. 94212:358.
- --7812150240 IE Inspec Rept#50-245/78-33 & #50-336/78-29 on 780906-07 & 780919 during which no items of noncompliance were noted. Hajor areas inspected incl:special security inspec of Interstate Security Svcs & watchman test of security sys. JONES.E. D. QALLINA.C.: DEVLIN.J.W. Region I, Philadelphia. Befeguards Branch. 78/10/24. 3pp. 94212:360.
- 78)1290164 Forwards IE Circular #78-18, "UL Fire Test. "W/encl ANO: 7811150002.

 ORIER.B.H. Region i- Philadelphia. Office of the Director. 78/11/06. 1p. 94238:058.
- 7812130130 Forwards 1E Bulletin#78-12A, suppl to 1E Bulletin#78-12. W/encl AND:7811300095. GRIEN, B. H. Region 1: Philadelphia, Office of the Director. 78/11/24. 1p. 94212:213.
- 78)2210053 Ack receipt of 781116 ltr informing NRC of steps taken to
- 781281053 Ack receipt of 78116 itt informing NRC of style carrect violations noted during inspect®0.245778-34.

 QRIER.B. H. Region 1. Philadelphia. Office of the Director.
 78/11/24. ip. 94269:034.
- --7812210056 Responds to 781027 NRC ltr re violations noted in Inspec Rept#50-245/78-34. Corrective actions: dissel generator data sheet rewritten & clarified, personnel re-instructed on Tech Spec & procedure compliance. COUNSIL-W.O. Northeast Nuclear Energy Co. (subs. of Northeast Utilities). 78/11/16. 2pp. 94269:035.
- R. Periodic operating reports & related correspondence
- 7810200087 Forwards Monthly Open Rept for Bept 1978.

 OPEKA J. F. Northeast Utilities. 78/10/13. ip. 94367:356.
- --7810200088 Monthly Oper Rept for Sept 1978. YOUNG, R. Northeast Utilities. 78/10/13. 6pp. 94367:357.
- 7811170104 Forwards Monthly Open Rept for Oct 1978. OPEKA, J. F. Northeast Utilities. 78/11/13. 1p. 02766:267.
- --7811170115 Monthly Oper Rept for Oct 1978. YOUNG.R. Northeast Utilities. 78/10/31. 6pp. 02766:268.

- ORIER B.H. Region 1. Philadelphia, Office of the Director 78/11/13 1p. 94239:243
- -7811290292 Forwards estimates of total errors in total quantities released which were not incl in 780101-780630 Semi-Annual Radioactive Effluent Release Repts
 OPEKALJ F Northeast Nucleer Energy Co. (aubs of Northeast Utilities) 78/09/15. 2pp. 94239:244
- 78:2290169 Forwards corrected Monthly Oper Rept for Nov 1978. OPEKA: J. F. Northeast Utilities. 78/12/20 1p 94190:312.
- --7812290173 Corrected Monthly Open Rept for Nov 1978 * Northeast Utilities. 78/12/06. 6pp. 94190:313
- a. Reportable occurrences, LERs & related correspondence
- 7810120089 Forwards LERW78-018/03L-0.

 OPERA: J. F. Northeast Utilities. 78/10/04. ip. 94473.352.
- --7810120096 LER#78-018/03L-0 on 780905:during surveillence on vessel level instructions found that 1 of the 4 reactor low-low water level switches was manfunctional.due to mech hangup caused by dry lubrication.

 YOUNG.R.H. Northeast Utilities. 78/10/04 3pp. 94473:353
- B10160117 Forwards LER#78-019/03L-0 - OPEKA.J.F. Northeast Utilities 78/10/10. 1p. 94007:127.
- -7810160123 LER478-019/03L-0 on 780912:during surveillence, setting of one of the four time delay turbine control fast. YOUNG.R.H. Northeast Utilities. 78/10/10. 2pp. 94007:128
- BiO200071 Forwards LER#78-021/03L-0.

 ** Northeast Utilities. 78/10/12 1p.
- -7810200072 Ler#78-021/03L-0 on 780914: Qas turbine tripped while output voltage was being adjusted. Caused by faulty gas generator speed switch 3A in electronic control. YUNG.R.H. Northest Utilities. 78/10/12. ip.
- B10230207 Forwards LERW78-022/03L-0. OPEKA, J. F. Northeast Utilities. 78/10/13. 1p. 94489:032.
- -7810230210 LER#78-022/03L-O on 780914: drywell vent bypess valve failed to fully close due to particle contamination in air operator-resulting in insufficient pressure. YOUNG.R.H. Northeast Utilities. 78/10/13. 2pp. 94489:033.
- 311140187 Forwards LERW78-023/03L-0.

 OPEKA: J. F. Northeast Utilities. 78/11/06. 1p. 94384:275.
- -7811140191 LER&78-023/03L-0 on 781011: feilure of pressure switch 2206-1621C to trip at proper point due to dry lubricant & setpoint drift. Switch was cleaned & readjusted. YOUNG.R.H. Northeast Utilities. 78/11/06. 2pp. 94384: 276.
- 111140167 Forwards LER#7B-024/031-0.

 OPEKA-J.F Northeast Utilities. 78/11/07. ip. 94383:320.
- :11160089 Forwards LERW78-024/03L-0.
 DPEKA-J.F. Northeast Utilities. 78/11/07. 1p. 94134:348.
- 7811160093 LER#78-024/03L-0 on 781011: while conducting drywell high pressure functional/calibr surveilance for ECCS, pressure switch was found to be tripping at 2.3 PBI, caused by setpoint drift.

 YOUNG.R. H. Northeast Utilities. 78/11/07. 2pp. 94134:390.
- 11210291 LERE78-025/03L-0 on 781019: Inadvertent initiation of isolation condenser resulted from satpoint drift & intermittent tripping of various logic channel switches. Buitches readjusted tested & returned to svc. YOUND.R.H. Northeast Utilities. 78/11/16. 3pp. 94495:198.
- 12070184 Responds to 780906 ltr re info on Control Rods failing to fully insert after screm. During 1977; eight different control rods did not insert seven rods were overhauled & one continued to function satisfactory.

 100MSIL.N. 9. Northeast Utilities. 78/11/28. 2pp. 94375:046.

- --7812090118 LER#7G-026/03L-0 on 781106 Barton 288 pressure indicating switch PS-2206-16210 was found to trip at 2 1 PSI due to setpoint drift. Switch was readjusted, tested & returned to svc YDUNG.R H Northeast Utilities. 78/11/30 2pp 94106 321.
- 7812080126 Forwards LERW78-027/03L-0 GPEKA, J.F. Northeast Utilities 78/12/01 tp 94106:343
- --7812080129 LERM78-027/03L-O on 781106 one of four level suitches (LTS-263-728)was tripping outside Tech Spec band Caused by instru drift YOUNG R H. Northeast Utilities. 78/12/01 2pp 94106-344.
- 7812260213 Forwards LER#78-028/03L-0 OPEKA, J. F. Northeast Utilities. 78/12/14 1p. 94160 183.
- --7812260219 LERM78-028/03L-0 on 781121 on two occasions defective car were used to ship radioactive waste to burial site.due to confusion between procedural controls & trial GA prog. YOUNG.R H. Northeast Utilities 78/12/05. 3pp 94160 184
- 7812290205 Forwards LER#78-029/03L-0

 @PEKA, J.F. Northeast Utilities. 78/12/22 1p 94190:341
- --7812270212 LERW78-029/03L-0 on 781122 while checking Energency Gas Turbine Demerator, burned out indicator bulb was found on lube oil pump circuit breaker Opening breaker resulted in gas turbine inoper Bulb & bulb socket replaced & tested. YGUN9-8 H Northeast Utilities. 78/12/22 2pp 94190:342.
- 7811210280 Forwards LER#78-025/03L-0 OPEKA, J. F. Northeast Utilities 78/11/16. ip 94485:197.
- U Congressional/Executive Correspondence
- 7810140036 Response to 780911 ltr for commants re individuals who are concerned over radioactive milk contemination in area near facil. Forwards NRC preliminary evaluation of Elefingless rept on Etrontium-90 levels in milk near subj facil
 DIRCKG.H.J. Office of the Executive Director for Operations 78/10/06. 2pp. 94329-073.
- --7810140039 Responds to 771115 ltr requesting NRC to evaluate Sterng rept re strontium-90 & Cesium-137 in milk from farms near sub; facil. Concludes no relationship between elevated redisactive milk level & sub; facil.

 HENDRIE, J. H. Commissioners 78/01/18. 2pg. 94329:075.
- --7810140043 Forwards add1 NRC comments by M Goldman re allegation raby Dr Sternglass concerning levels of strontium & Cesium near subj Paci). Concludes risks from exposure to low level radiat suposure small.

 DENION.H R. Office of Nuclear Reactor Regulation. Director. 78/07/27. ip. 94329:082
- --7810140045 Review & comment of rept by Dr Sterngless re redibactive health statistics around nuc facil in CT.Finds no support for contention that CT nuc plants have released sufficient radionuclides to cause significant radiat exposure. QLDMAN, h. California, Univ. of, Davis. 78/05/31. 4pp. 94329-083
- --7810140048 Review of Dr Sternglass rept Concludes data does not supcontention that nuc reactors have contributed to significent increases in Btrontium-90 & Costum-137 in milk Additionally, rept did not consider effluent monitoring from reactor, CUSTLE,D.M. Environmental Protection Agency, 78/08/09, 10pp-94329:087
- 7812050043 Responds to 781031 ltr. States that all present info is so limited that no meaningful comparisons can be made of the level of radioactivity in dairies near subj facils & dairies in other regions of the State.

 DIRCHS. H.J. Defice of the Executive Director for Operations. 78/11/27. 2pp. 94334:119.
- --7812050044 Ack receipt of eval of Sternglass rept. Requests any NRC Sternglass data indicating radioactivity concentrations of other areas of the State.
 DCDDr.C. J. House of Rep. 78/10/31. 2pp. 94334, 121.

- 7811200181 Forwards revs to Mod Amend Security Plan of subj facil & requests withholding from public disclosure IAW Section 2.790(d) CAHILL, M. J. Consolidated Edison Co. of New York 78/11/09. 1p. 94232:297.
- 7811070274 Responds to 780918 request for add1 info on admin control of fire protec prog. Forwards responses to NRC staff positions re Admin Controls. CAMILL.W J Consolidated Edison Co. of New York. 78/10/31. 23pp. 94040:300.
- 7811150249 Forwards request for add1 info re facil fire protec review. Request response by 781117. SCHMENGER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/02. 5pp. 94273:069.
- 7811200135 Responds to 781102 NRC request for info re subj facil fire protec prog. Forwards responses & rev to paragraph 8.40 of Apr 1977 Fire Protec Prog Rept. GAMILL.M.J. Consolidated Edison Co. of New York. 78/11/16.
- 7812190102 Forwards Buppl info re April 1977 Fire Protec Prog Rept Encl 1 mods paragraph B. 31 of Rept.Encl 2 contains sched for mods.Encl 3 & A contain addl info re staff positions. Details w/held from pub disclosure pursuant to 2.790 CAHILLIN.J. Consulidated Edison Co. of New York. 78/12/12. 12pp. 94376: 300.

G. Adjudicatory correspondence

Ì

- 7811090188 Forwards recent NRC menos he problems w/pipe support base plate design. Staff will inform Bd of conclusions after study of add info from licensee. (See AND: 7811020332, 7811020336, & 7811020343.)
 BMITH, B. H. Office of the Executive Legal Director. 78/10/24. 2pp. 94031-078
- 7810260201 Per 10CFR2, 772, time for NRC to review decision in ALAB-487 is extended until 781115.
 CHILK, S. J. Office of the Secretary of the Commission. 78/10/19.
 18. 94058:022
- 7812260307 Motion of the Utility Water Act Group et al.for Leave to File Brief as Amici Curiae.
 BMITH, T. T. Hunton & Williams. 78/11/13. 6pp. 94160:074,
- 7811290184 Notion by NRC Staff to w/draw its petition seeking review of decision ALAB-399 is granted. All parties now agree that ALAB-453 resolves pre-emption issue reised in ALAB-399; issue is now moot.
 CHILM. B. J. Diffice of the Secretary of the Commission. 78/11/15. 2pp. 94239:275.
- 7812010154 Comm will review decision of ABLB in ALAB-487. In particular issues stammined will be implication of "Besbrook" decision. CLI-77-8. SNRC003. 508; CLI-78-1. 7NRC1. 28-26. & to what extent lic conditions should reflect EPA's authority. CHILK. S. J. Office of the Secretary of the Commission. 78/11/15. 3pp. 94418-122.
- 7812070261 Order extending date to 790112 for NRC to elect whether to review ALAB-487 decision.
 CHILK, S. J. Office of the Secretary of the Commission. 78/11/29, 1s. 03555:010.
- 7812110224 Forwards NRC's 781115 Mamo & Order re subj facil inviting participation in review of ALAB-487. Also advises that time to receive reply briefs is extended to 790112. TRUBATCH. S. L. Office of the General Counsel. 78/11/29. ip. 94337:361.
- 7812110226 Forwards NRC's 781115 Memo & Order re subj facil inviting participation in review of ALAB-487. Also advises that time to receive reply briefs is extended to 790112.

 TRUBATCH.S.L. Diffice of the General Counsel. 78/11/29. ip. 94337:342.
- 78:21:10228 Forwards NRC's 78:11:5 Memo & Order re subj facil inviting participation in review of ALAB-487. Also advises that time to receive raply briefs is extended to 79:01:2.

 TRUBATCH. S. L. Office of the General Counsel. 78:11:29. ip. 94:338:029.

94312:331.

- --7812270430 Memorandum & Order inviting comments of EPA & PASNY redetermination of preferred alternative closed cycle cooling eys. Initial briefs shell be received by 781201. reply briefs by 781215. CHILK. 8. J. Office of the Becretery of the Commission. 78/11/15. 3pp. 94312:332.
- 7812210306 Forwards brief by Util Hater Act Group.Edison Elec Inst & Natl Rural Elec Coop Assoc re water quality regulation.
 8MITH.7 T Hunton & Hilliams. 78/12/15. 1p. 94407:255.
- --7812210311 Brief filed on behalf of Util Water Act Group, Edison Electinst & Natl Rurel Electoop Assoc re water quality regulation & jurisdiction under Clean Water Act section 511(c)(2) Cert of Svc encl.

 BMITH.T.T. Hunton & Williams. 78/12/15. 7pp. 94407:256.
- 7812260002 Response of Hudson River Fishermen's Assoc to NRC memo to order of 781115. Urges that NRC retain present NRC lic conditions req cessation of once-thru cooling at subj facil by 820501.
 CHABIS. 8. Natural Resources Defense Council. 78/12/15. 19pp. 94021:279.
- 7812270060 Brief submitted by CENY in response to 781115 Hemo & Order. Asserts that NRC must relinquish its regulation of water quality impacts of subj facil. Supporting documentation encl. BLOCK, U.D., SACK, E.J. Consolidated Edison Co. of New York, 78/12/15. 33pp. 94160:292.
- 7812280262 NRC Staff's Comments in response to 781115 NRC Order announcing Comm intention to review decision ALAB-487. 8taff claims that decision in CLI-78-1.7NRC1.does not req NRC to mod lies of subj facil. W/documentation & Cert of Svc. LEWIG.8 H., MULKEY.M.E. Office of the Executive Legal Director. 78/12/15. 39pp. 94374:260.
- 7812270138 Informs that US Court of Appeals for Becond Circuit denied petition for rehearing & rehearing on benc re closed-cycle cooling conditions.
 FIDELLER. LeBosuf, Lamb, Leiby & MacRee. 78/12/19. 2pp. 94161:144

P. Operating license stage documents & correspondence

- 7812190016 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PWR's (NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pwr Plants" (NUREO-0133).

 ORIHES. B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94214:286.
- 7812050004 Forwards Licenaee Performance Eval Questions for subj facilin response to 771123 request. Feels it is possible that dev of statistical methodology for such eval may not justify the effort. Qualitative eval may be as good. Urgss 1-year test. ORIER. B. H. Region i, Philadelphia, Office of the Director. 77/12/13. 12pp.
- 7810230057 Notice of issuance of Amend#41 to Facil Open Lic#DPR-26 which rev provisions in lic to conform to Order of ABLB dtd 780614 re receipt of govt approvals required to proceed w/constr of clased cycle cooling sys.

 3ALLARD.R.L. Environmental Projects Branch 1. 78/07/25. 2pp. 94199-199
- 7810110099 Notifies NRC that util expects to receive results of Westinghouse ECCS cooling performance reanalysis by 781130. CENV will submit its revised analysis by 781231. CAHILL, M. J. Consolidated Edison Co. of New York. 78/10/03. 1p. 94064: 350.
- 7810240108 Forwards data specified in Section 401 Certification for Bept. Includes species code list, greats slec output, circulating water temp.river water discharge, them discharges & daily fish counts.

 MONTIN.A. Consolidated Edison Co. of New York. 78/10/13. 17pp.
- 7810310240 Response to PABN 1tr of 780802; forwards denial of PABN's appl to extend period of interim oper using the installed once-thru cooling use at subjecti.

 DENTON.H.R. Diffice of Nuclear Reactor Regulation, Director. 78/10/13. 3pp. 94091:322.

- estuary which NRC is conducting or in which it is participating as per itr request of 780901

 LEMIS 8 H Office of the Esecutive Legal Director. 78/10/17 Jpp. 94034 004
- 7810310299 Forwards Amend#41 to Facil Oper Lic#DPR-26, changing Tech Bpec BCHLENCER A Operating Reactors Branch i (Pre 790625). 78/10/17. 269.
- --7810310304 Amend#41 to Facil Oper Lic#DPR-26.changing Tech Bpec reredioactive mati surveillance & sealed radioactive sources. SCHWENCER.A Operating Reactors Branch 1 (Pre 790625). 78/10/17. Boo
- --7810310305 Safety Eval Bupporting Amend#41 to Facil Oper Lic#DPR-26. Concludes that no harm will result. * Operating Reactors Branch 1 (Pre 790623). 78/10/17 2pp
- 'Bli01000| Summary of 781012 meeting w/util re steam generator progfor subj facil. OLSHANL Operating Reactors Branch 1 (Pre 790625). 78/10/18. 46pp. 94290-253
- 811070120 Informs NRC 1AH Tech Spec that Strawtown Dairy has ceased oper & therefore milk sample is unobtainable. Samples of leafy green vegetables & milk from Shenandosh Farm will be taken.

 CAHILL-H.J. Consolidated Edison Co of New York. 78/10/30 2pp.
- 811070157 Forwards Appl for Amend to Oper Lic#DPR-26 Proposed Tech Spec changes would establish LCO's & surveillance requirements for subj facil Overpressure Protec Bys. Cert of Svc encl.
 CAHILLIM. J. Consolidated Edison Co. of New York. 78/11/03 Spp. 94044:104.
- -7811070163 App1 for amend to Oper Lic DPR-26, requesting mod of Tech Spec 3 1.3.3 Table 3-3. Table4. 1-1 & 6.9.2 & addition of new Tech Spec 4.16 to establish limiting conditions of oper. Surveillance requirements for OPS detailed in encl. GNITLL.W.J. Consolidated Edison Co. of New York. 78/11/03. 22pp. 74044:107.
- 311150171 Forwards reissued 781017 Amend, renumbered as Amend#42, to Facil Oper LichtpRr-26 SCHHENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/06 2pp. 94242:329.
- -7811190175 Amend#42 to Facil Oper LicMDPR-26, changing Tech Spec re radioactive matl surveillance. SCHMENCER.A. Operating Reactors Branch 1 (Pre 7906P5). 78/10/17. Bpp. 94242:331.
- -7811150182 Safety Eval supporting Amend#42 to Facil Oper Lic#DPR-26. Concludes that no harm will ensue.

 Office of Nuclear Reactor Regulation, Director. 78/10/17. 2pp. 94242:339.
- H1200047 Status of IE outstanding review request:waiting for add1 info re requirements for pressurization of air lock door seats that support a proposed change to subj facil tech space.

 LAINAS.Q. Plant Systems Branch (Pre 791030). 78/11/09. 1p. 94215:330
- 11290288 Responds to 781106 request for info concerning licensee reg performance eval for Region i plants by NRC Provides details. RRIER.B.H. Region i, Philadelphia, Office of the Director. 78/11/09. 9pp.
- 11170160 Forwards data specified in Bection 401 Certification for the month of October, 1978.

 MONTI, W. A. Consolidated Edison Co. of New York, 78/11/10. 16pp. 94048:051.
- 11210274 Ack receipt of 781013 itr responding to request for extension of interim oper of subj facil using the installed once-thru cooling sys. Believes hearing would be premeture. EARLY.P.J. Power Authority of the State of New York. 78/11/13. 2pp. 94485:167.
- 12150088 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests ine-workshop registration of attenders to facilitate sending out math. W/encl Registration Form & List of Locations.

 ILLER-J.R. Assistant Director for Site & Safeguards (Pre 791030).

 **B/11/13. 3pp. 9421::343.

- BUR's (MUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pum Plants" (NUREO-0133) GRIMES B. Assistant Director for Engineers & Projects (Pre 790625). 78/11/13. 6pp 94365-334.
- 7812070193 Notice of seminar on 781208 on new Model Radiological Effluent Tech Specs for nuc pur plants Requests advance submission of seminar specific questions. W/encl Seminar Info Sheet, Proposed Agenda & maps ORIER, 8 H Region 1, Philadelphia, Office of the Director. 78/11/21 Bpp. 94375:192
- 7812190026 Discusses possible dangers of LOCA in containment purging during normal plant open. Requests either commitment to limit purging or justification for continuing Wienci ANOW 7812080207.

 SCHLENGER. A. Contains Reactors Branch I (Pre 790625) 78/11/28
- 7812150321 Responds to 781121 memo requesting mod to Environ Tech Specs to red continuous monitoring & recording of effluents from detergent Waste Collector tanks. Nemo has been forwarded to DBE.
 EIBENHUT.D.G Assistent Director for Systems Engineering (Pre 791030) 78/12/04 1p 94022-014
- 7812070180 Forwards application for anomal to OLs.
 ZARAKAB.P. Consolidated Edison Co. of New York. 78/12/05 ip
 98378 030
- --7812070182 Application for amend to QLs. Certificate of Evt encl CHILL, M. J. Consolidated Edison Co. of New York 78/12/05 12pp. 94378-031.
- 7812280126 Emphasizes importance of submitting accurate & complete info to NRC by licensess & applicants. Info submitted must be substantiated by data & calculations Licensee rust notify NRC of any inaccuractes or enforcement action will result DAVIS.J.O Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp 94310.262
- 7812190075 Forwards info re fracture toughness & potential for lampllar tearing of steam generator & reactor coolant purp support matls. Will forward addl info upon completion of record search. W/encl 4 oversized drawings available in CF. CRAHILL. W. U. Consolidated Edison Co. of New York 78/12/12. 14PP. 94215: 197.
- 7812050013 Requests views of Regional Directors on Licenses performance aval of subj facils Forwards questions to be answered by 771209. THORNBURG, H. Division of Reactor Construction Inspection 77/11/23.
- 7812190174 Forwards copies of "Appl for Amend to Oper Lic" which request emends to section 4 i. 2s of Environ Tech Spec Requirements for subj fecils. Amends would restructure present Aquatic Environ Monitoring Prog. Cert of Svc encl. CAHILLIM. J. Consolidated Edison Co. of New York 78/12/14. 3pp. 94340; OO2.
- --7812190180 Appl for amend to Licenses DPR-5, DPR-26 & DPR-64 requesting rev to Environ Tech Space. Rev Tech Space & proposed mode are designed to provide a monitoring prog for continuous assessment of Hudson River fish population. CAHILL.W.J., EARLY,P.J. Consolidated Edison Co. of New York. 78/12/14, 46pp. 94340-005.
- 7812260014 Comments of PABN re closed-cycle cooling conditions Asserts that lic condition should either be eliminated of delayed indefinitely. Cert of Evc encl.
 TROSTEN.L.M., FIDELL,E.R., ANCARROW,M.R., LeGoevé, Lamb, Leiby & MacRas. 78/12/15. 18pp. 94021:045.
- ---7B12260019 Forwards appl for extension of period of interim oper using installed once-thru cooling systeming final determination of permissibility of such systems.

 EARLY, P. J. Power Authority of the State of New York. 78/08/02.

 2pp. 94021:063.
- --7812260023 Appl for extension of period of interim oper using installs once-thru cooling sys. Appl contains motion for expedited relisef. Also encl is affidavit of PJ Early of PABN in support of extension.

 # Power Authority of the State of New York. 78/08/07. 58pp. 9402:065.

- 7811090016 Forwards IE Inspec Rept#50-247/78-28 on 780825 during which no items of noncompliance were noted.

 BRUNNER,E J. Region 1: Philadelphie: Reactor Construction & Engineering Support Branch. 78/09/25 Zpp. 94040:013.
- --7811090017 IE Inspec Rept#50-247/78-28 on 780825 during which no items of noncompliance were noted Major erest inspec incl: previously identified unresolved items w/respect to records. NAPUDA. G., BECKMAN.D., KISTER, H. B. Ragion 1, Philadelphia, Reactor Construction & Engineering Bugport Branch. 78/09/14, 4pp. 74040-015.
- 7810160246 Forwards IE Bulletin#78-12: "Atypical Hald Material in Reactor Pressure Vessel Helds" requesting action win 60 days & list of IE Bulletin Issued in 1978. (See ANO # 7810040253)

 ORIER.8. H. Region 1, Philadelphia, Office of the Director. 78/09/29. 6pp. 94003:308.
- 7811040201 Forwards IE Circular#78-17. (See ANG: 7810230221; Docket #50-133, 781013.)
 GRIGE, B.H. Region 1- Philadelphia, Office of the Director. 78/10/13. 1p. 94489: 200.
- 7811300337 Forwards IE Inspec Rept#50-247/78-30 on 780913-14 during which no items of noncompliance were noted.

 BRUNNER.E. J. Region 1, Philadelphia, Reactor Deprations Nuclear Support Branch, 78/10/19. 2pp. 94116:188.
- --7811300340 IE Inspec Rept#30-247/78-30 on 780913-14 during which no items of noncompliance were noted Major areas inspected incl:licensee response to IE Circular 78-08 "Environ Gual" of Safety Related Elec Equip."

 REBELDMSKI.T. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/19. 5pp. 94116:190.
- 78:10/60224 Ack receipt of 7808:8 ltr informing NRC of steps taken to correct violations noted during inspec#50-003/78-06 & #50-247/78-19.

 QRIER.8. H. Region 1, Philadelphia. Office of the Director. 78/10/20. 2pp. 94488:141.
- --78:1060238 Responds to 780712 NRC ltr re Violations noted in Inspec Repts#50-003/78-06 & #50-247/78-19. Corrective actions: Quality Assurance checklists modisenviron audit procedures & related environ procedures revised. ZARAKAB.P. Consolidated Edison Co. of New York. 78/08/18. 4pp. 74488:143.
- --7811060239 Forwards IE Inspec Repts#50-003/78-06 & #50-247/78-16 on 780516-18 & 780522-23 & Notice of Violation. ORIER, B. H. Region 1, Philadelphia, Dffice of the Director. 78/07/12. 3pp. 94488:147.
- --7811060244 Notice of Violation from inspec on 780316-18 % 780322-23, BTDHR, J. P. Region 1: Philadelphia: Office of the Director. 78/07/12. 3pp. 94488:130.
- --7811060247 IE Inspec Repts#30-003/78-06 & #50-247/78-19 on 780516-18 during which B times of noncompliance were noted: failure to monitor cooling water sys temp & approve procedured changes in accord w/EBTR: failure to submit timely measurement repts. BCRES,R. J. Region I, Philadelphia, Office of the Director. 78/07/07. 24pp. 94488:153.
- 7812010345 Forwards licenses performance evaluation for Region 1.No operating reactor in Region 1 considered to have either ebnormal or unusual safety concern.

 GRIER18.H. Region 1, Philadelphia, Office of the Director, 78/11/01. 4pp. 00002:257.
- 7811140202 Ack receipt of 781018 itr informing NRC of steps taken to correct violations noted during inspec#50-003/78-i1 & #50-247/78-29.

 BMTH. 0. H. Region 1. Philadelphia. Fuel Facility & Materials Bafety Brench. 78/11/03. ip. 94400:106.
- --7811140205 Responds to 780926 NRC itr re violation noted in Inspec Repta#50-003/78-11 & #50-247/78-29. Corrective actions: malfunctioning pan linkage mechanism in recorder of monitor CT-1014 repaired & monitor flushed. CAHILL. W. J. Consolidated Edison Co. of New York. 78/10/18. Ppp.

- ~-7911140262 IE Inspec Repts#50-003/78-11 & #50-247/78-29 on 780905-08 during which 1 item of noncompliance was noted: failure to continuously monitor & record liquid effluent discharges. THONUGL. Region 1, Philadelphia, Office of the Director. 78/09/26. app. 94400:112.
- 7812180057 Forwards IE Inspec Repts#50-003/78-12 & 50-247/78-33 on 781011-12 during which no items of noncompliance were noted. SHITH, 9. H. Region 1, Philadelphia, Fuel Facility & Materials Safesy Branch. 78/11/03. 2pp. 94133:092.
- ~~7812180058 IE Inspec Repts#50-003/78-12 & #50-247/78-33 on 781011-12 during which no items of noncompliance were noted Major areas inspected incl: observation of licenses conducted smargency drill & circulating cooling water temp monitor. BORES.R.J., BTOHR,J.P. Region 1. Philadelphia, Fuel Facility & Materials Bafety Branch. 78/11/02. App. 94133:094.
- 7811290214 Forwards IE Circular #78-18: "UL Fire Test, "W/encl AND: 7811350002.
 ORIER, B.H. Region i, Philadelphia, Office of the Director, 78/11/06. ip. 94237:329.
- 7812150133 Forwards IE Bulletin#78-12A. suppl to IE Bulletin#78-12. W/encl AND:7811300055. ORIER,B.H. Region 1, Philadelphia, Opplica of the Director. 78/11/24. 1p. 94212:174.

R. Periodic operating reports & related correspondence

- 7812010206 Forwards corrected copy of Chem Discharges sheet in Section 401 Cert Rept for Uct 1978.

 MONTS! M.A. Consolidated Edison Co. of New York. 78/11/15. 2pp. 94409: 265.
- 7810200064 Forwards tabulation of daily record of fish collections for Bept 1978 including breakdown & total weight. CAHILLIM. J. Consolidated Edison Co. of New York. 78/10/13. Spp. 94412:171.
- 7B10230149 Forwards Monthly Open Rept for Bept 1978. CAHLLU.J. Consolidated Edison Co. of New York. 78/10/16. ip. 94164:191.
- --7810230150 Monthly Oper Rept for Bept 1978. KANULA-L. Consolidated Edison Co. of New York. 78/10/16. App. 74144: 192.
- 7811210340 Forwards Monthly Open Rept for Oct 1978.
 CAHILLIM J. Consolidated Edison Co. of New York. 78/11/15. ip. 94494: 328.
- --7811210344 Monthly Open Rept for Oct 1978. KANULA, L., MAKEPEACE, J. Consolidated Edison Co., of New York, 78/11/08. 9pp. 94484:329.
- 7811220153 Forwards tabulation of daily record of fish collections for Oct 1978 w/deily species breakdown & total weight. CAHILL-W J. Consolidated Edison Co. of New York. 78/11/16, 4pp. 94074:277.
- 7812180182 Forwards data specified in Section 401 Certification for Nov 1978. MDNTI-M.A. Commonwealth Edison Co. 78/12/10. 17pp. 94366:036.
- 7812270188 Forwards rept of fish impingement & corrective action for Nov 1978. CAHILLIN.J. Consolidated Edison Co. of New York. 78/12/14. Spp. 94018: 007.
- 7812210207 Forwards Monthly Oper Rept for Nov 1978.
 CAHLLIM J. Consolidated Edison Co. of New York. 78/12/15. 1p. 94279:103.
- ---7812210211 Monthly Oper Rept for Nov 1978.
 KANULA,L. Consolidated Edison Co. of New York. 78/12/08. 79p. 94079:104.

- 8. Reportable occurrences. LERs & related correspondence
- 7810100067 Forwards LER#78-025/04L-0. CAHILL-W. U. Consolidated Edison Co. of New York, 78/09/27. 1p. 94033:063.
- --781010007: LER#78-025/04L-0 on 780628: w/Unite 2 & 3 oper at 100 & 90X pur-calculations performed utilizing equation prescribed by ETBR2.1.3.1, indicated heat rejection to river was in excess of BTU/HR maximum permitted by ETBR.
 * Consolidated Edison Co. of Neu York. 78/09/27. 2p. 94033:084.
- *810110153 Forwards LER #78-028-01T-0. CANILLIM.J. Consolidated Edison Co. of New York. 78/10/04. 1p. 94069:172.
- ~7810110155 LER #78-028/017-0 on 780920; At cold shutdown, leak discovered in albow connection between containment isolation valves in recirculation path from residual heat removal pumps. Affected section replaced & successfully hydro tested.

 MAKEPEACE, J. M. Consolidated Edison Co. of New York, 78/10/04.
- 810160105 Forwards LER#78-014/03X-1,78-019/03X-1,78-019/03X-1. CANILL-N.J. Consolidated Edison Co. of New York. 78/10/06. 1p. 74001:343.
- -7810160110 LER078-014/03X-1 on 780523: during low pur physics test of 1 high head 818 pump.leakage was confirmed past the seat of 1 swing check valve downstream of pump#22, caused by faulty valve disc mounting.

 HAKEPEACE, J. M. Consolidated Edison Co. of New York, 78/10/06, 2pp. 94001:344.
- ~7810160113 LERRYRE-019/03X-1 on 780629: during normel oper leskage was found at socket weld connection on seal injection header downstream of seal injection filters. due to pinhole lesk. MAKEPEACE. J. M. Consolidated Edison Co. of New York. 78/10/06. 2pp. 94001:345.
- -7810160168 LERR78-018/03K-1 on 780626: during normal open a slight leak was found at valve 1823D in a level instru line from boron injection tank due to crack in bonnet. MAKEPEACE.J.M. Consolidated Edison Co. of New York. 78/10/06. 2pp. 94001:348.
- 310160138 Forwards LER#78-027/03L-0. CAHILL-N.J. Consolidated Edison Co. of New York. 78/10/06. ip. 94005:304.
- -7810160141 LERW78-027/03L-0 on 780908: during normal oper the #21 Boric Acid Transfer Pump underwent mech seal feliums. Following repairs, pump returned to svc w/in time limit specified in Tech Spec 2.2.C.2.

 MAKEPACE.J.M. Consolidated Edison Co. of New York. 78/10/06.

 1p. 94005:305.
- ISIO7022: Forwards LER#78-029/03L-0. CAHILLH-J. Consolidated Edison Co. of New York. 78/11/01. 1p. 94039:138.
- 7811070230 LERM78-029/03L-0 on 781003: in hot shutdown condition the amount of water in condensate storage tank was reduced to below Tech Spec requirement to combet excessive charides in condensate & feedwater sys. Caused by bleed & feed oper. MAKEPEACE, J. M. Consolidated Edison Co. of New York. 78/11/01. Spp. 74039: 139.
- 11280260 Forwards LER878-030/03L-0 & LER878-031/03L-0. CAHILL-H.J. Consolidated Edison Co. of New York, 78/11/18. 1p. 94393; 200.
- 7811280263 LERB78-030/03L-0 on 781018; setting of bistable PC-439A found to be below Tech Spec minimum. Coused by instru drift. MAKEPEACE, J. M. Northern States Power Co. 78/11/17. ip. 94396; 201.
- 7811280270 LER#78-031/03L-0 on 781022: during normal oper.one instructionnel of containment pressure safeguards logic become deenergized. Caused by failure of static inverter associated withat channel.

 MAKEPEACE.J.M. Consolidated Edison Co. of New York. 78/11/17.

 19. 94395: 202.
- 12040229 Confirms 781127 verbal notification of reportable occurrence .CR-78-033/01. During cold shutdown outage, a blockage was liscovered in discharge line from boron injection tank. IDNT1-N, A. Consolidated Edison Co. of New York. 78/11/27. ip. 74439: 323.

94340:357.

--7812190131 LERM7B-033/01T-0 on 781126:blockage discovered in dischiline from boron injection tank caused by a defective heat trace circuit wire. Defective wire replaced & blockage cleared. Elec heat tracing test PT-07 rev.

CAHILL.W. J. Consolidated Edison Co. of New York. 78/12/08.

7812190121 Forwards LER#78-033/01T-0.

7812200193 Forwards LER678-032/03L-0. CANILL-N. J. Consolidated Edison Co. of New York. 78/12/13. lp. 94148:336.

MAKEPEACE, J. M. Consolidated Edison Co. of New York. 78/12/08. 1P. 94340:358.

- --7812200195 LERM78-032/03L-0 on 781116; during normal open-routine is revealed leak from socket weld connection of drain valve c-15 to seal injection header. When leak was 8.00PM, unit was ent down for repair. Leak caused by vibration.

 **Commonwealth Edison Co. 78/12/13. 1p. 94148:357.
- 7812200206 Forwards LER878-034/04L-0. CAHILL-N-J. Consolidated Edison Co. of New York. 78/12/13. 1p. 741621-279.
- ~~7812200208 LER#78~034/041~0 on 780705; heat rejection to river in earlies 16. 3x109 BTU/hr. Caused by method prescribed by ETBR for calculating heat rejected. More accurate method showed heat rejected to be less than ETBR maximum allowed.

 MMKEPEACE, J. M. Consolidated Edison Co. of New York, 78/12/13, 1p. 94162:279.
- DOCKET 50-249 DREBDEN NUCLEAR POWER STATION. UNIT 3

 F. Security, medical, emergency & fire protection plans
- 7810120080 Forwards analysis of Elec Cable Penetration Fire Barrier Test conducted on 780619 Also forwards 3rd party observer rept of test & 5 detailed drawings associated w/test. NAUGHTON,H.F. Commonwealth Edison Co. 78/09/29. 44p. 94049: 330.
- 7812070172 Forwards fire protect info incl hydraulic calculations & Automatic Sprinkler Co Drawing N26-1730, of aprinkler sys for fire pump in Crib House, Oversize drawings evailable in Central Files.

 NAUGHTON, M. F. Commonwealth Edison Co. 78/11/30. 6pp. 03555:144.
- 7812120195 Informs NRC name of fire protec consulting firm hired by CEIL to fulfill requirements of "Fire Protec Organization of Nuc Plant Fire Protec Functional Responsibilities Admin Control & QA" will be submitted 790201.

 NAUGHTON.H.F. Commonwealth Edison Co. 78/11/30. 2pp. 94277:099
- 9. Adjudicatory correspondence
- 7811090259 Bd grants request by Citizens for a Better Environ & Natu Resources Defense Council for permission to file response to answers opposing their patitions to intervene by 781103. MILHOLLIN. G.L. Atomic Safety and Licensing Board Panel. 78/11/01 1p. 02761:290.
- 7812110294 Cencels special prehearing conference scheduled for 78121 Conference shall be held on 790111 in Tex Courtnoom of US Courthouse & Fed Bldg. Chicago, IL. Parties & petitioners must rept to Board by 781215 re progress of negotiations.
 MILHOLLIN. 0.L. Atomic Safety and Licensing Board Panel. 78/12/01 2pp. 94203:243.
- 7810120112 Applicant's Answer to Petition for Leave to Intervene reproceeding filed 780908 by Attorney Gen of St of IL Includes notices of appearance for M.I. Miller. J. R. Rower & P. P. Steptos. Includes designation of person upon whom svc shall be made. BTEPTUE.P.P. 18ham, Lincoln & Basle. 78/09/18. 10pp. 94484:039
- 7810190131 Answer by CEIL to Petition to intervene filed by Atty Gen of IL on 780920. Agrees that Atty Gen has standing but asserts there are no genuine issues to be heard at hearing. Requests that Atty Gen request for EIB be denied. BTEPTOE.P. P. Isham, Lincoln & Beele. 78/10/02. 3pp.
- 7610300063 Natural Resources Defense Council Request for Leave to Fi a Response. Response is to applicant's contention re constitutionality of forced disclosure of group's members' names in order to open w/in state. ROIBMAN.A.2. Natural Resources Defense Council. 78/10/10. 4pp. 74037:177.

- 7810300324 NRC Staff Answers to Council for Citizens for Setter Environ & Natural Resources Defense Council's Petition for Leave to Intervene Staff opposes granting petition.w/Cert of Syc. QUDDARD, R. J. Office of the Executive Legal Director. 78/10/10. 3pp. 94253_37
- 7810230124 NRC Staff's Response to Petition of TEX-LA Cooperative. Inc for Leave to Intervene. Staff believes Petition should be granted.

 LEBSY.R.P., DLUME.M.B. Office of the Executive Legal Director 79/10/10. 9pp.
- 7811010063 Patition for leave to intervene & for hearing filed by citizens for Better Environ & Natural Resources Defense Gouncil. Request for leave to file response to answers opposing petition is granted. MIL-POLLIN. C.L. Atomic Befety and Licensing Board Panel. 78/10/13. 1p. 94302:360.
- 7811150223 "Netural Resources Defense Council Response to Commonwealth Edison's & Staff's Answers to Petition for Leave to Intervene. "Intervenor urges Bd to establish a schedule for briefing challenges to contentions.
 RUIGMAN. A Z Netural Resources Defense Council 78/10/23 16pp. 94270: 137
- 7811130216 NRC request to file response to NRDC response to Coam Ed & NRC answer to petition for leave to intervene dtd 781023 If granted. reply will be served by 781103. Cert of Svc enci. QCDDARD.R. J. QPPice of the Executive Legal Director. 78/10/26. 2pp. 03854:050.
- 7811200070 Request by Comm Ed for leave to file a response to NRDC brief which argues that organizations may show standing to participate in NRC proceedings merely by alleging that they represent anonymous members Cent of Svc encl.

 BTEPTOE, P. P. Isham, Lincoln & Beale. 78/10/30. 2pp. 94218:348.
- 7811220233 Forwards "Licensing Report Dresden Nuc Pur Plant Units 2 & 3-8pent Fuel Rack Modification," dated 780203.W/o encl rept. GDDARD.R. J. Office of the Executive Legal Director. 78/11/01. ip. 94289:3500.
- 7811140021 Grants request by licensee CELL to have until 781107 to respond to 781013 Order of ASLB permitting NRDC & Citizens for a Better Environ to file response to answers opposing their petitions to intervene in proceedings re-subj facils. HILPOLLIN.O.L. Atomic Safety and Licensing Board Panel. 78/11/03. 1p. 94317:090.
- 7811220010 NRC Staff's Response to NRDC's Response to Answers to latter's Patition for leave to intervene NRC asserts that NRDC has not demonstrated its standing to intervene as matter of right. Cent of Svc ancl. ODDDARD.R.J. Office of the Executive Legal Director. 78/11/03. Bpp. 94273:334.
- 7811200003 Special Prehearing Conference in proceedings re subj facils will be held on 781215 in Rock Island. L. All parties to proc & all petitioners to intervene must attend & should be prepared to discuss all issues.

 MILPOLLIN. Q.L. Atomic Sefety and Licensing Board Panel. 78/11/09. 2pp. 94215:221.
- 7812130122 Gives notice that A Bislaushi enters an appearance on behalf of applicant CEIL in proceedings re subj facils. Cert of Bvc encl.
 BISLAWSKI, A.P. Isham, Lincoln & Beale. 78/11/21. 2pp. 94307:188.
- 7812270230 Proposed stipulation to NRDC & CBE's representation of unnamed members in Dreaden-Guad Cities transchipment is not acceptable to NRC NRC position on NRDC's petition to intervene remains as stated in 781103 pleading.

 QDDDARD.R.J. Gffice of the Executive Legal Director. 78/12/06. 1p. 94017:138.
- 7612280271 Forwards"Stipulation" of NROC, CBE & Commonwealth Edison Core identification of members of NROC & CBE to prove they have interests that may be affected. No agreement w/Reg Staff has been reached.
 ROIEMAN. A. Z. Natural Resources Defense Council. 76/12/08. 1p. 94374: 334.
- --7812280280 Parties agree that NRDC & CBE have adequately indentified at least one member whose interest may be adversely affected by the proposed action. Auth to represent these interested members has not been agreed upon.
 ROIBMAN. A. Z. Natural Resources Defense Council. STEPTOE.P.P. Commonwealth Edison Co. 78/12/11. 3pp. 94374:335.

7812270133 Special Prehearing Conf Scheduled for 790111 is postponed until 790201. Parties & petitions are excused from requirement to rept to 8d by 781215 re negotiations progress.

MILHOLLIN B. Atomic Safety and Licensing Board Panel. 78/12/13. 2pp. 94161.142.

H General correspondence

7812080138 Forwards CEIL request for amend of DL to allow spent fuel transfer & storage between facils. H/o encl.

ODDARD.R. J. Office of the Executive Legal Director. 78/11/17. ip. 94107:356.

J. Insurance & indemnity information

- 7812190109 Requests refund of \$6 per mut in excess indemity fee paid for LiceDPR-2, WDPR-19, WDPR-25, WDPR-29, WDPR-30, WDPR-39, WDPR-39, WDPR-39, WDPR-48.
 - POOLE, R. D. Commonwealth Edison Co. 78/12/13. Lp. 94376:323.
- P. Operating license stage documents & correspondence
- 7811170287 Requests add1 info for review of proposed subj fecil Spent Fuel Pool Mod Guestion items include occupational exposure during BFP mod.effect on exposure level of cut up low density racks.BFP cooling sys.vol of contaminated matl. ZIEMANN.D L. Operating Reactors Branch 2 (Fre 770625). 78/11/08.7pp. 94045:179.
- 7812080026 FOIA request for all records incl:quantity of radioactive matl disposed of from former Manhatten proj in IL known as Chicago Pileswi-2 & 3. Matl disposed of in IL by Lindsay Cos at Morris facil & Dresden facil.

 HANEELL-D. Illinois, State of. 78/11/06. 2pp.
- 7812150228 Classifies lic amend for proposed fuel pool mod as Classes IV & I not Classes III & I. Requires add charge of 88300 for each of the two applito be paid w/in 15 days.
 MILLER.W.O. License Fee Management Branch. 78/12/11. Spp. 94213: 329.
- 7810230198 Notice of Proposed Issuance of Amends to Oper Lics.NRC is considering issuance of amends to Provisional Oper Lic SDPR-19 & Facil Oper Lic SDPR-23. Mould change provision in Tech Specs to allow more spent fuel to be stored at facil. ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/08/03. 4pp. 94392:220.
- 7810170185 Update & conclusion of diesel generator reliability study. Almost all corrective actions taken per investigation have been completed Results of study summarized in encl. HTEPHENSON.8.B. Commonwealth Edison Co. 78/09/28. 5pp. 94270:047.
- 7810100027 Forwards evaluation of reactor protect sys pur supplies to determine whether undetected failures adversely affect the RPS sys.
 TURBAKINS. Commonwealth Edison Co. 78/10/04. 5pp.
- 7810140112 Resvaluation of Lic amend fees for inter-station spent fuel transfer for subj facils as requested by 780817 ltr shows that the class i & 3 fees paid for each station are correct. HILLER.W.O. License Fee Management Branch. 78/10/10. ip. 94421:151.
- 7810270180 Responds to 781002 NRC ltr re requested Tech Spec change for reactor water cleanup sys return valve. Util accepts change as Class 2 & Class 1 amend. & remits appropriate fee.
 REED.C. Commonwealth Edison Co. 78/10/23. ip. 74037:081.
- 7811020322 Withdraws request to amend Tech Specs re reporting requirements for reactivity anomalies as Reg Guida "Interpretation" by NRC on 780701 does not require rept for reactivity increase of less than 5 sacs.

 REED.C. Commonwealth Edison Co. 78/10/26. 2pp. 94255:223.
- 781103016: Forwards proposed Amend changing Tech Specs w/regard to updating station organizational charts. Changes have received onsite & offsite approval.

 REED.C. Commonwealth Edison Co. 78/10/26. 9pg. 02724:009.
- 78:11:30335 Summary of 78:09:14 meeting w/gE representatives & Mark i Owners Group re progress of Long Term Prog w/attendance list & agenda(RD-9-A-Mark), Standards.) ORINES.C. Plant Systems Branch (Fre 79:1030). 78/10/26. 67pp.

hydrological features & discussing w/licensee hydrological design bases necessary to perform a detailed BEP review Addl hydrological info also requested.

8TALEY.0.B. Hydrology Meteorology Branch. 7B/10/31. 3pp. 74405:136

- 8:1100:31 Bummary of meeting w/CEIL on 78:023-24 to discuss questions re seismic design of subj facil & obtain seismic design info. Myancl list of attendees, meeting agende, charter of BRRT, floor response spectre, & design repts & tech paper. LEVIN.H A. Systematic Evaluation Programs Branch (Pre 790625). 78/11/02. 410pp. 9429:001.
- 311140105 Responds to 780516 NRC ltr requesting add1 info re reactor vessel metal surveillance specimen fluence valves at time of withdrawal.w/projections based on dosimetry results of previously tested capsules & 80% capacity factor; w/o sncl. TURBAK.M.B. Commonwealth Edison Co. 78/11/03. 2pp. 94425:125.
- 311140002 Notifies applicant of 781128 NRC-sponsered seminer re Model Radiological Effluent Tech Specs for Nuc Pur Plants w/enci Beminer Info Sheet(to be completed & returned by 781117) & Proposed Agenda.
 KEPPLER, J. 9. Region 3. Chicago, Office of the Director. 78/11/07.
 490. 94426:022.
- ii210257 Updates 770510 ltr info re control rod drive(CRD)uncoupling prog. Forwards historical data list of all CRD's occurring between 760522 & 771211. Improved Quality Control & filter installation procedures are adequate to prevent uncoupling. TURBAKIM 8. Commonwealth Edison Co. 78/11/13. 4pp. 74488:335.
- 1:300058 Forwards Amend#39,#37,#48 & #47 for Lics DPR-19,DPR-25,DPR-19 & DPR-30 respectively,Amends revise Tech Specs reoperating temp & pressure limits. Also forwards Safety Eval & Fed Register Notice.

 IPPCLITG.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/13.
- 7811300067 Amend#37 to the Operating Lic rev Tech Space re operating temp & pressure limits.

 IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/13.
 Bos.
- 7811300077 Safety Evel Rept in support of Amend#39,#37.#48 & #47 to Oper Lics DPR-19,DPR-25,DPR-29 & DPR-30,respectively. # Office of Nuclear Reactor Regulation, Director. 78/11/13. App.
- '811300085 Notice of Issuance of Amend#39,#37,#48 & #47 to Oper Lits DPR-19,DPR-25,DPR-29 & DPR-30,respectively.

 IPFOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/13.
- 2150071 Notification of workshops in Jen-May 1979 in Regions 1-5 to explain techniques of job analysis & parformance testing thow to relate such testing to qualification plan sevelopment & training. Designed for working level personnel, ILLER, J.R. Assistant Director for Site & Safeguards (Prs 791030). 18/11/15. 5pp. 94210:215.
- 2180248 Forwards Revel "Dreft Radiological Effluent Tech Specs" for WR's (NUREG-0473) & "Preparation of Radiological Effluent sich Specs for Nuc Pur Plants" (NUREG-0133). RIMES.B. K. Assistant Director for Engineers & Projects (Pre 90425), 78/11/15. App. 94366:125.
- 2050107 Forwards rev page to Topical Rept CE-1-A, "Guel Assurance rog, Rav 6." Rev reflects Reg Quidel, 28 & 1.33 rev. URBAK.M.S. Commonwealth Edison Co. 78/11/17, 2pp. 94335:334.
- 1280213 Forwards current lic status list for subj facile. EED.C. Commonwealth Edison Co. 78/11/20, 9pp. 94012:130.
- 1280246 Forwards "Projected Fluence Values at Withdrawal for the epsules Designated to Meet the Requirements of 10GFR50 ppend H." Teble 1 to be attached to 781103 itr to 1ppolito. JRBAK:M.S. Commonwealth Edison Co. 78/11/20. 2pp. 94012:162.
- 2140176 forwards Oct 1978 Prog Activity Review listing meetings hald providing task-by-task activity summary for the month. BEDN.L.J. General Electric Co. 78/12/04. 11pp.
- REMOIRY Emphasizes importance of submitting accurate & complete info info type by licensees & applicants. Info submitted must be instantisted by data & talculations, Licensee must notify IC of any inaccuracies or enforcement action will result. WIS.J.9. Office of Inspection & Enforcement, Office of the rector. 78/12/06. Rep. 94311:336.

- containment leak rate test procedure re temp & humidity measurement in subvol bounded by water level Requests exemption from IOCFR50 in order to eliminate subvol problem.

 TURBAKIN B. Commonwealth Edison Co. 78/12/12. 6pp. 94343: 334.
- 7812050013 Requests visws of Regional Directors on Licenses performance eval of subjectis.Forwards questions to be ensured by 771209.
 THORNBURGH Division of Reactor Construction Inspection. 77/11/23. 200.
- 7812190097 Accepts topical reptMCE-1-A RevM6, "Comm Edison Co Quality Assurance Prog for Nuc Generating Stations: " Requests submittal of 36 copies. HAA98, M P. Quality Assurance Brench. 78/12/13. 1p 94376:317.
- 7811210367 Forwards add1 into re-multiple consecutive sefety/relief valve accustion of Mark I containment program. SOBON.L.J. General Electric Co. 78/11/13. 3pp. 94485:126.
- Q. Inspection reports. IE Bulletins & correspondence
- 7810110052 Forwards IE Inep Repts 50-010/78-23.50-237/78-21 % 50-249/78-23 on 780807-10 % 16-18 % notice of deviation. DAVIB.A B. Region 3. Chicago, Office of the Director. 78/09/08. 2pp. 94080:049.
- --78:01:0054 Notice of Daviation from inspec on 780807-10 & 780816-18. * Region 3. Chicago: Fuel Facility & Materials Bafety Branch. 78/09/08. ip. 94063:226.
- --7810110062 IE Inspec Repts#50-010/78-23,#50-237/78-21 & #50-249/78-23 on 780807-10 & 16-18 during which I item of deviation was noted Failure to mast PEAR commitment for manitoring unit 2/3 liquid rad waste effluents.

 QRSQER,L.R., FIBHER,W.L. Region 3, Chicago, Office of the Director. 78/09706. ipp. 94063:227.
- 7811010018 Forwards IE Inspec Repts#50-10/78-25,#50-237/78-22 & 50-249/ 78-24 on 780705-06,11-12.19-20.780817.23-25,29-31 & 780901, during which no items of noncompliance were noted. FIDEELL/2. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/09/20. 2pp. 94290:141.
- ---7811010022 IE Inspec Repts#30-10/78-25,#50-237/78-22 & #50-249/78-24 o 780705-06,11-12:19-20.780817.23-25.29-31.780901.during which no items of noncompliance were noted Major areas inspect following of noncompliances & review of plant oper.

 BARKER, J. L. Region 3, Chicago, Office of the Director. KNOP.R. C. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/09/20. 7pp.
- 78:01:0277 Responds to 780708 NRC ltr rs deviation noted in Insp Repts 50-010/78-23,50-237/78-21,50-249/78-23. Corrective actions: liquid radwaste discharge monitor will be returned to svc & slarm will be made operable. REED.C. Commonwealth Edison Co. 78/09/22. Jpp. 94079:148.
- 7810200203 Ack receipt of 780922 ltr informing NRC of steps taken to correct item of noncompliance identified in ltr of 780908. DAVIS.A.B. Region 3. Chicago. Fuel Facility & Materials Bafety Branch. 78/10/12. p. 94367:089.
- 7B10300030 Forwards 1E Circuler#7B-17. (Bee AND: 7B10230221) KEPPLER, J. G. Region 3. Chicago. Office of the Director. 7B/10/13.
- 7811300261 Forwards IE Inspec Repts#50-010/78-26.50-237/78-23 & 50-249/78-25 on 780905-08.12-14.20-22. & 26-28 & Notice of Violation. FIORELLI & Region 3. Chicago, Reactor Operations Nuclear Support Brench. 78/10/25. 2pp. 94075: 233.
- ~-7811300264 Notice of Violation from inspec on 780905-08, 12-14, 20-22 & 26-28.

 Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/25. jp. 94075:061.
- --7811300268 IE Inspec Repts#50-010/78-26, 50-237/78-23 & 50-249/788-25 or 780905-08, 12-14, 20-22 & 26-28 during which I item of noncompliance was noted: failure to rept a 30 day reportable event in 30 days.

 ### RANKER, J. L., CHRIBBOTIMOS, N., HUGHES, J. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/25. 15pp. 94075:237.

- 7812050011 Forwards IE Inspec Repts#50-010/78-29.50-237.-254.-295.-304/ 78-25.50-249/78-27 & 50-265/78-26 on 781002 during which no items of noncompliance were noted.
 KEPPLER.J. Q. Region 3. Chicago, Office of the Director. 78/10/30. 2pp. 94200 183
- --7812050027 IE Inspec Repts for subj facils on 781002 during which no items of noncompliance were noted Major areas inspected inclidiscussion of actions being taken by util to improve its reg performance & tour of Zion station KNDP.R.C., FIDRELLI.O. Region 3, Chicago, Reactor Operations Nuclear Support Branch. KEPPLER.J.O. Region 3, Chicago, D
- 7811150063 Forwards IE Circular 78-18, "Underwriters Lab Fire Test " KEPPLER J G Region 3, Chicago, Office of the Director. 78/11/06. 94112.240
- 7811280486 Unresolved items noted in IE Inspec Repts#50~010/77~28. #50~237/77~25 & #50~249/77~25 have been reviewed & recommendations made Documentation of unresolved items withold per 10CFR2 790(d). HIND, J.A. Region 3, Chicago, Bafaguards Branch, 78/11/16 1p. 94381:358
- 7812050287 Forwards IE Bulletin 78-12A. "Atypical Weld Mati in Reactor Pressure Vessel Helds." KEPPLER, J.O. Region 3. Chicago, Office of the Director 78/11/24. 1p. 94202.332.
- 7812140081 Forwards IE Inspec ReptaM50-010/78-28.M50-237/78-24 & M50-249/78-26 on 781010-13.781016-19 & Notice of Violation. KEPPLER, J. G. Region 3. Chicago. Office of the Director. 78/12/01. 2pp 94128 227
- --7812140086 1E inspec Repts 50-010/78-28.50-237/78-24 & 50-249/78-26 on 781010-13 & 781016-19 Noncompliance noted: defective security organizationobserved including access controls & physical barriers into partially withheld (ref FOIA Examption 3). BELANGER, J.L., HOMELL, J.C., HIND, J.A. Region 3. Chicago, Bafeguards Branch 78/11/20 2pp. 94128: 229.
- 7812130330 Natification of Sits visit on 781206-07 to discuss operational considerations re insvc inspec prog. ZIEMANN.D L. Operating Reactors Branch 2 (Pre 790625). 78/12/05. 94307: 352.
- 78:2290026 Forwards IE Bullstin 78-14. "Deterioration of Buna-N Components in ASCO Solenoids." KEPPLER, J. Q. R. 1p. 94208; 009. Region 3. Chicago. Diffice of the Director. 78/12/19.
- R. Periodic operating reports & related correspondence
- 7811140119 Forwards monthly operating rept for Oct 1978. STEPHENSON.8 B. Commonwealth Edison Co. 78/11/08. 1p. 94425:184.
- S. Reportable occurrences. LERs & related correspondence
- 7810170195 Forwards LER#78-038/03L-0. STEPHENSON, B. B. Commonwealth Edison Co. 78/10/06. 1p. 94234:342.
- --7810170203 LER#78-038/03L-0 on 780916: inspec revealed that one hydraulic of 4 snubbers on valve had less than required amount of fluid. Subsequent test proved snubber inoperative. Caused by fluid leak resulting from loose hydraulic lines. HARRIB.8.W. Cammonwealth Edison Co. 78/10/06. 1p. 94234:343.
- 7810240100 Forwards LERN78-036/03L-0. 8YEPHENSON, B. B. Commonwealth Edison Co. 78/10/12. 1p.
- --7810240102 LER#78-036/03L-0 on 780917:While performing routine surveillance DIS 1300-2.0PIS-1349 tripped at 38.5 water DP. Caused by inetr drift. Isolation switch will continue to be tested monthly per DIS 1300-2.

 LINDSERO.C. Commonwealth Edison Co. 78/10/12. 1p.
- 7810240116 Forwards LER#78-040/03L-0. STEPHENSON, S. B. Commonweelth Edison Co. 78/10/12. 1p.

--7810240141 LER#78-037/03L-O on 780918. Leaks discerned in feed pump

STEPHENSON, B. B. Commonwealth Edison Co. 78/10/17. 1p

- minimum flow lines Caused by cracks & holes in piping due to excessive flow velocity

 JANBEN-T Commonwealth Edison Co 78/10/17. 2pp
- 7810270229 Forwards LERM78-039/03L-0. STEPHENSON, B. B. Commonwealth Edison Co. 78/10/17. 2pp. 94053: 247.
- ~-7810270231 LERW78-039/03L-0 on 780922 containment cooling Water Syc LPCI heat exchanger valve MO-3-1501-3A failed to open in automatic mode while attempting to start torus cooling, caused by motor oper values "chattering" ACHTERBERG. J. Commonwealth Edison Co. 78/10/17 1p. 94053. 248.
- 7810270302 Forwards LER#77-03B/01x-1. 8TEPHENSON, B. B. Commonwealth Edison Co. 78/10/17, 1p 06403; 358
- ~~7810270305 LER#77-038/01X-1 on 770914.D/G cooling water pump Pailure. due to excessive bearing wear, allowed rotor to contact canned motor windings & caused cooling water to short out CIESZKIEWICZ, S. Commonwealth Edison Co. 78/10/17. 2PP. 06403:359
- 7811090125 Forwards LERW78-041/03L-0.
 BTEPHENSON, B. B. Commonwealth Edison Co. 78/10/19. ip. 94042:301.
- ~~7611090126 LER#78-041/03L-0 on 780924: following unit startup while inerting containment the N2 level in storage tank drapped to less than 60 inches.Level in tank was below 60 inches for about 3 hours due to late N2 delivery. RALPH.R. Commonwealth Edison Co. 78/10/19. ip. 94042:302.
- 78]1030184 Forwards LER#78-043/03L-0.
 STEPHENSON, B. B. Commonwealth Edison Co. 78/10/27. 1p. 02724: 100.
- --78:1030:9: LER#78-043/03L-0 on 780929:contractor cut hole in HPCI ste line w/cutting torch while removing sleeve mat! from line restraint resulting in minor radioactive steam release to reactor bldg Contractor admonished hole welded over.
 JANSEN.T Commonwealth Edison Co. 78/10/27. 1p. 02724: 101.
- 7811060159 Forwards LER#78-044/03L-0.
 8TEPHENSON, B. B. Commonwealth Edison Co. 78/10/30. 1p. 94489:078.
- --7811060162 LER 78-044/03L-0 on 780930: indicated level increased on wi Range Monitor LI. 1602-8 while pumping down torus during normal oper Caused by stratic movement of cam resulting from binding of mechanical linkage connecting tube drive to cam. LINDBERG.C. Commonwealth Edison Co. 78/10/30. 2pp. 94489:079.
- 78:1140222 Forwards LER#78-048/03L-0. STEPHENSON, B. B. Commonwealth Edison Co. 78/11/01. 1p. 94400:054.
- --78:1140227 LER 78-048/03L-0: on 78:10:2. DIS 16:00-3, diff press sw isolation valve for DPIS 3-16:22A; was found closed, apparently since completion of previous quarterly survey on 78:07:11. Cause unknown. LINDBERG.C. Commonwealth Edison Co. 78/11/01. 2pp. 94400:055.
- 7811210333 Forwards LER#78-049/03L-0. STEPHENSON, B. B. Commonwealth Edison Co. 78/11/01, 1p. 94484; 322.
- --7B11210339 LERW7B-049/03L on 7B1014: while performing Turbine Stop Val Closure Bram Circuit Sensor Tests(DDS 500-10), #2 turbine stop valve 10% closure switch did not actuate until valve was 20% closed Valve was out of adjustment. KORCHYNBKY, M. Commonwealth Edison Co. 78/10/14, 1p. 94484:323.
- 7811280301 Forwards LER#78-050/03L-0. STEPHENSON. B. B. Commonwealth Edison Co. 78/11/13. 1p. 94395; 297.
- --7811280309 LERW78-050/03L-0 on 781021: during monthly survey D18 250-1 Main Stm Line Hi Flow Isol Sw. DP18 3-261-20 tripped at 120 PBID. Caused by Priction in switch mechanism. Bellows assembly will be replaced.

 LINDBERG.C. Commonwealth Edison Co. 78/11/13. ip. 94395: 298.

JANSEN, I Commonmearty Forson co

120130 Forwards LER 78-052/03L-0. EPHENSON, B.B. Commonwealth Edison Co. 78/11/30 ip 94276 188.

12120134 LER 78-052/03L-0. on 781104 during leak check of maisture

separator area steam was found blowing from bottom of an elbow gownstream of orifice RC 3-3041-09. Caused by erosion from high velocity steam/water mixture on albow. RM.PH, R Commonwealth Edison Co. 78/11/30. ip. 94276.159

210242 Forwards LER#78-053/03L-0 EPHENSON.B. G. Commonwealth Edison Co. 78/11/30. 1p. 94279 192

12210245 LER#78-053/03L-0 on 781104 during DCP 2700-11 (Offgas Radiat Monitor Calibr).3"A" monitor failed downscale.As req. inoperable monitor was then tripped in upscale position Cause was failed amplifier in 3"A" Offgas Log Rad Monitor. LINDBERO.C Commonwealth Edison Co 78/11/30 ip 94279 193

210244 Forwards LER#78-054/031-0. EPHENSON,B B Commonwealth Edison Co. 78/11/30 lp. 94279.197.

12210252 LERM78-054/031-0 on 781104 during normal surveillance, while testing MSIV closure time. MSIV 3-203-2A closed 2 8 seconds after initiation signal Caused by MSIV 3-203-2A valve timing which was out of adjustment RALPH.R Commonwealth Edison Co 78/11/30 1p 94279 198

180175 Forwards LER#78-055/03L-0. EPHENSON:B B. Commonwealth Edison Co. 78/12/07. lp. 94359-355

12180178 LER#78-055/03L-0 on 781116 small leak noted on recently installed drain attached to 3D2 Peedwater heater drain line Caused by lack of fusion & slag inclusion on socket welded drain line. Repaired by grinding defect & rewelding. JANSEN, T. Commonwealth Edison Co., 78/12/07, 1p., 94359: 356

180145 Farwerds LER#78-056/03L-0 EPMENSON, B. B. Commonweelth Edison Co. 78/12/08, 1p. 94365-261

12180148 LER#78-056/03L-0 on 781122 during routine inspec of containment spray interlocks, noted that face plate on Yarway model 4418C was broken, holding pointer set in fixed position above trip setpoint. Cause unknown LINDBERG. C. Commonwealth Edison Co. 78/12/08 ip. 94365.262.

270284 Forwards LER#78-097/03L-0. EPHENSON.B.B. Commonwealth Edison Co. 78/12/14. 1p. 94229.316

12270289 LER#78~057/03L-0 on 781130:during test on U3 D/G, the "D/G 3 Day Tank Level Hi/Lo" alarm sounded Caused by the solenoid valve which was stuck closed.

CHAN, J Commonwealth Edison Co. 78/12/14. 1p 94229 317

ET 50-250 TURKEY POINT PLANT, UNIT 3 ecurity, medical, emergency & fire protection plans

120075 Forwards copies of Rev 4 to subj facil Emergency Plan. RRG.R.E. Florida Power & Light Co. 78/09/27. 2pp. 94402:221.

:10120081 Rev 4 to State of FL Radiological Emergency Plan dtd May 1975 Ltr of support w/ERDA dtd 750410.FL Highway Patrol Order 32 dtd 760401 & Coast Guard 760426 ltr encl. * Florida Power & Light Co. 78/09/27 166pp. 94402:223.

300325 Ack reciept of 780623 ltr re position that 3-man fire igade is adequate to cope w/any fire at subj facil quests add1 info so NRC may evaulate proposal.

HKENCER A. Operating Reactors Branch 1 (Pre 790625). 78/10/16.
p. 94253:341.

310121 Forwards Rev O to security plan dtd 780526 Withheld ef 10CFR2, 790).
RIG.R.E. Florida Power & Light Co. 78/10/24. 111pp.

roull uper Lickupk-41 Amena lech Hapcs vor Fire protet His & Admin controls in Response to 771222 Appl(1-77-390) SCHWENCER, A. Operating Reactors Brench 1 (Pre 790625) 78/11/08. 94013 173. 5 p p

- --7811280172 Amend#42 to Lic#DPR-31 rev common station Tech Specs to incorp limiting conditions for open & surveillance requirements for existing fire protec sys SCHMENCER, A Operating Reactors Granch ((Pre 790623). 78/11/08 2pp 94013 178
- --7811280174 ArendWQ4 to Lic#BPR-41 rev common station Tech Space to incorp limiting conditions for oper & surveillance requirements for existing fire protec sys SCHMENCER. A Operating Reactors Branch 1 (Pre 790625) 78/11/08. 20pp. 94013 180
- --7811280178 Notice of Issuance of amend#34 & 42 to Facil Oper Lic# DPR-31 & DPR-41 Amend rev Tech Specs to incorp limiting conditions for oper & surveillance requirements for existing Fire protoc sys.

 SCHWENCER.A Operating Reactors Branch 1 (Pre 790623) 78/11/08.
- 7812080148 Licensee has been orally notified that Emergency Plan through Revision 4 dtd 780927 is acceptable based on 781025 memo Wenci AND 7811030177. SCHWENCER. A Operating Reactors Branch 1 (Pre 790625) 78/11/28 1p. 94104 349.
- 7812110010 Pending staff approval of Rev D requests util commit to prepare apecial security procedures applicable to the replacement of steam generators SCHMENCER. A Operating Reactors Branch 1 (Pre 290529) 78/12/01 2pp 94339 235
- 7812120119 Discusses fire protection in operating nuclear power stations in partitular providing analysis of facilities. BER Proposed fire protection mod increases level of protection against fire hazards. IALL-R E Brookhaven National Laboratory. 78/12/06 Spp 94275 340.
- --7812120125 Requests addl info re fire protec at subj facils. Info concerns water supply cable protecty and hydrants, smoke venting equip & smoke removal Documentation re info sought engl. RE Brookheven National Laboratory 78/09/21. 9pp. 94275-245.
- 7812270190 Responds to 781201 NRC request for special security procedures Agrees to prepare security procedures IAW Mod Amend Becurity Plan at least 90 days prior to commencing steam generactr repair activity.
 UHRIO,R.E Florida Power & Light Co 78/12/15. 1p. 94018:042

H General correspondence

78:2270168 Requests placement on distribution list for correspondence & repts dealing w/oper status for subj facils SHREVE J. Florida, State of 78/12/18 to 94018 C90

I Financial information

7811070144 Forwards req guarantees under Price-Anderson as amend 1978 under option 5 Encl provides into re 1977 annual rept. consolidated financial atetements cash flow projections. capital expenditure curtailments & cash flow sources UHRIG.R E. Florida Power & Light Co 78/10/30. 45pg. 94044: 022.

J. Insurance & indemnity information

7810230140 Forwards Endorsement#37 to Nuc Energy Liability Insurance #MF-S5 Also States that Endorsement#36 to Nuc Energy Liability Insurance#NF-185 was forwarded w/76061B FPL 1tr (L-76-228) UHRIG.R.E Florida Power & Light Co. 78/10/09. 2pp. 94164:203.

7810300107 Forwards Endorsement#36 to Policy#NF-185 & Endorsement#37 to policy#NF-55. UHRIG.R.E. Florida Power & Light Co 78/10/09. 1p. 94035:236



M. Antitrust correspondence

- 7811090144 "Notice of Appearance"re proceedings.Cert of Svc encl EVANS.D. J. Office of the Executive Legal Director. 78/10/30. Spp. 94399-361
- 7812270071 Provides notice that RC McDiarmid & DA Giacalone w/draw as Pepresentatives of FL Cities in proc re subj facile JABLDNR. A. Spiegel & McDiarmid. 78/12/13 4pp. 94161:011
- P. Operating license stage documents & correspondence
- 7812010382 Response to 780613 ltr re comments & corrective actions in 780404 NRC ltr re Diesel Generator Lockout. Ut[1's response is adequate.

 8CHMENCER. A Degrating Reactors Branch i (Pre 790625). 78/06/30.
- 7810230175 Notice of Proposed Issuance of Amends to Facil Oper Lics NRC is considering Issuance of Amends to Facil Oper Lics DPR-31 & DPR-41 Amends rev Tech Specs re transient & accident analysis.

 BCH-ENCER, A. Derating Reactors Branch 1 (Pre 790625). 78/08/04. 4pp. 94393.062.
- 7810200075 "Containment Structure Post"Tensioning Sys:Fifth-Year Surveillance Rept."

 SHAHL M.R. Sechtel Power Corp. (aubs. of Bechtel Corp.). 78/09/13.
 100pp. 94029:087.
- 7811210191 Notice of Issuence of Amends 38 & 31 to Facil Open LichDPR-31 & BDPR-41. Amends thangs Tech Space no neducting of Unit 4 Cycle 5 open. BCHMENCER, A. Openating Reactons Branch 1 (Pre 790625). 78/09/22. 3pp. 94488:003.
- 7810120022 Forwards test rept for 770701-780630 per 100FR50.596. UHRIQ.R.E. Florida Power & Light Co. 79/10/04 lp. 94330:174.
- ---7810120023 Test rept details plant change/mods.procedure changes/tests & expers. Major areas:cask-crane-add-limit suitthes/diesel emergency diesel surge tank.NDDT overpressure relief protection.reactor coolent pump seal mod/flamestic addition.
 Florida Power & Light Co. 78/10/04. 65pp. 94330:175.
- 7810110159 Responds to 780802 NRC ltr re meterological data. Forwards info tables re wind frequency. UHRIGA. E. Ploride Power & Light Co. 78/10/05. 9pp. 94069:226.
- 7810120028 Forwards check for \$4000 re lic amend request of 780926. UHRIG.R.E. Florida Power & Light Co. 78/10/06. 2pp. 94470:354.
- 7810170191 Forwards Fifth year Surveillance Rept re containment struc post-tensioning sys. Minor error in Third Year Surveillance Rept. submitted by 1tr of 730825.1-73-404.1s corrected.
 UMRIGR.E. Floride Power & Light Co. 78/10/10. 2.3pp. 94235:197.
- 7810200045 Forwards "Containment Structure Post-Tensioning Bys, Fifth-Year Surveillance Rept." UHRIG.R.E. Florida Power & Light Co. 78/10/16. Ip. 94029:086.
- ---7810170194 Fifth Year Surveillance Rept of containment struc post-tensioning sys. Concludes that sys is performing w/in limits set by design criteria & specs. Includes wire testing & analysis of sheath filler. ANDREWS, C. W. Bechtel Power Corp. (subs. of Bechtel Corp.). 78/07/21. 89p. 94239:200.
- 7810250252 Summary of Meeting held on 781002 to discuss an extension of oper interval for 4 add1 months in response to submittal of amend on 780926. Impact—related info presented included: remezosure from shutdown & replacement pur costs.

 ORDTENHUSS.M. Operating Reactors Brench 1 (Pre 790625). 78/10/16.
 3pp. 94392:343.
- 7811140030 Forwards Amend 39 to License DPR-31, safety evaluation & notice of issuance.

 8CHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/10/16.
 2pp. 94420:292.
- --7811140033 Amend#39 to facil Oper Lic#DPR-31 rev lic to reg gaging inspac of steam generator in case of 0.3gpm or greater leak or shutdown to repair leak due to denting k inspac of all 3 generators in event of 3nd leak w/in 20 days.

 BCHMENCER.A. Operating Reactors Brench 1 (Pre 770625), 78/10/16.3pp. 94420:294.

- --7811140036 Safety Eval Rept Bupporting Amend 39 to License DPR-31.

 * Operating Reactors Branch 1 (Pre 790625). 78/10/16. 5pp.
 94/20.297.
- --7811140039 Notice of Issuence of AamendW39 to Facil Oper Lic MDPR-31 of 781016 SCHWENCER.A Operating Reactors Brench 1 (Pre 790625). 78/10/16. 2pp. 94420-302.
- 7810270182 Ack receipt of 780719 ltr requesting proposed Tech Specs be submitted addressing overpressure protec. Will submit info by 781115.

 URRIO-R.E. Floride Power & Light Co. 78/10/19. pp. 94057:083.
- 7810300003 Requests add1 \$400 few to process 780809 appl for amend to Facil Lic #DPR-31 & DPR-41.
 MILLER, W. D. License Fee Management Branch. 78/10/19. 1p.
- 7811030177 Act review of Rev 1,2,3,4.Rev 1 & 2 found acceptable.Rev 3 & 4 update arrangements w/various radiol amergency support groups.Back-up hospital changed to Baptist Hosp.After review.3 & 4 found acceptable.

 KNICHTON, 0. Environmental Evaluation Branch (Pre 790625). 78/10/RS. 1p. 94104-330.
- 7811030203 Forwards corrected page#1 to Amend#30 to Lic#DPR-41 dtd 780721.

 8CH-ENCER.A Depreting Reactors Stanch 1 (Pre 790625). 78/10/25.
 2pp. 02724.139.
- 7811090015 Forwards Amend#40 & 32 to Fecil Oper Lic#DPR-31 & DPR-41, changing Tech Oper to reduce pressuriter heatup rate. BCHMENCER.A Operating Reactors Brench i (Pre 790625). 78/10/25. 2pp. 94040.001.
- --7811090018 Arend#40 to Facil Open Lic#DPR-31, changing Tech Spec to reduce pressurizer heatup rate. SCHMENCER.A. Operating Reactors Branch 1 (Fre 790625). 78/10/25. 2pp. 94040:003.
- --7811090021 Amend#32 to Fecil Oper Lic#DPR-41, changing Tech Spec to reduce pressurizer heatup rate. BCHWENCER.A. Operating Reactors Branch I (Prs 790625). 78/10/25. 4pp. 94040:006.
- --7811070024 Safety Eval Supporting Amend#40 & 32 to Lic#DPR-31 & DPR-41 Concludes that no adverse effects will result.

 Office of Nuclear Reactor Regulation, Director, 78/10/25. 3pp. 74040:010.
- 7811130075 Forwards reissued Amend#38 & #31 to Facil Lic#DPR-31 & #DPR-41 w/corrected amend numbers. BCHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/10/26. 2pp. 74478:329.
- --7811130080 Amend#38 to Facil Oper LiceDPR-31, changing Tech Spec to auth oper w/25% of tubes in plugged condition.
 EIBENNUT.D.O. Assistant Director for Systems Engineering (Pre 791030). 78/09/22. 2pp. 94076:314.
- --7811130083 Amend#31 to Facil Dper Lic#DPR-41, changing Tech Bpec re refueling of Cycle 5 open & auth open w/25 percent tubes in plugged condition. EIBENHUT, D. 9. Assistant Director for Systems Engineering (Pre 791030). 78/09/22. 13pp. 94076:344.
- --7811330170 Safety evaluation supporting Amend#38 & 31 to Lic#DPR-31 & #DPR-41. Concludes that no harm will ensue.

 # Office of Nuclear Reactor Regulation, Director, 78/09/22, 18pp. 94011:137.
- --7811130175 Notice of Issuance of Amend#38 & #31 to Facil Oper Lic#PPR-31 & #DPR-41, changing Tech Spec re Cycle 5 oper & oper w/ tubes in plugged condition. SCHWENCER,A. Operating Reactors Branch 1 (Pre 790625). 78/09/22. 3pp. 94011:155.
- 7811070180 Forwards check in response to 781019 request, UHRIG.R.E. Florida Power & Light Co. 78/10/30, ip. 94036:357.
- 7811290068 Amends#38 % #31 to Facil Oper Lic#DPR-31 % #DPR-41 for subj facils were completed on 780922. W/issuance of these two amends all prior NRC Orders are subj facils have been setisfied. Audit tabulation encl.

 8CHENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/08. 3pp. 94193:223.

- phantom on whole body counter Encl 1 contains actual amount of each radionuclide present encl 2 gives ratio of measurements to DOE values & encl 3 gives recommendations SUTHERLAND, J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 76/11/09. Spp. 94419.164.
- 7811210256 Notifies util of 781205 seminar in Atlanta to discuss new Model Rod Effluent Tech Specs & encl seminar info sheet, registration form. & proposed agenda O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 78/11/09. Sem. 9448R-330.
- #811160139 Forwards info in response to 780518 NRC request for info re steam generator & reactor coolant pump supports sufficient to show geometry of all principal elements Oversize drawings available in Central Files. UHRIG.R 6 Florida Power & Light Co. 78/11/10. 1p. 94135:249
- --7811160142 "Report on Fracture Toughness & Potential for Lamellar Tearing of Steam Generator & Reactor Coolant Pump Supports." w/29 oversize drawings showing geometry of all principal elements available in Central Files • Florida Power & Light Co 78/09/30. 40pp. 94135:250
- 7811300041 Forwards NRC staff paper.Policy Session Item(8ECY-78-554) re licenses reg performance evaluation Three methods for evaluation are statistical trend analysis & regional survey method W/o encl. D'REILLY.J.P. Region 2. Atlanta, Office of the Director. 78/11/15 2pp. 94071-035
- 7812180038 Notice of workshops re implementation of training & quel requirements contained in Append B of 10CFR73 Requests pre-workshop registration of attendees to facilitate sending out matl W/encl Registration Form & List of Locations. MILLER.J.R. Assistant Director for Site & Safeguards (Pre 791030). 78/11/15. Spp. 94133:031.
- 7812190036 Forwards Rev#i "Dreft Radiological Effluent Tech Specs" for PWR's(NURED-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pwr Plants" (NURED-0133) GRIMES, 8. K. Assistant Director for Engineers & Projects (Pre 790625), 78/11/15. 6pp. 94215:009.
- 7811270161 Forwards appl for Amend to Facil Operating Lics#DPR-31 & DPR-41 Proposed amend addresses Overpressure Miligating Sys (DMS) Discusses limiting conditions for oper of Reactor Coolant Sys UHRIG.R.E. Florida Power & Light Co. 78/11/20. 11pp. 94252:324
- 7811280228 In response to 780915 NRC itr submits suppl to 760604 itr to meet requirements of Bec V.B of Append I to 10CFR30 to operationally evaluate drein floor treatment sys which is suppl by a portable demineralizer.

 UHRIO.R E. Florida Power & Light Co. 78/11/20. Opp. 94012:047.
- 7812140357 Discusses possible dangers of LDCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. Wencl ANOW 7812080207.

 BCHMENCER: A Operating Reactors Branch 1 (Pre 790625). 78/11/28-6pp. 03557:223.
- 7812040336 Requests \$1.600 in lic fees since amend does not qualify for exemption under IOCFR170.22 footnots#2.
 MILLER.W.O. License Fee Management Branch. 78/11/29. ip.
- 7812280171 Emphasizes importance of submitting accurate & complete info to NRC by licensee & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inscrupacies or enforcement action will result. DAVIS. J. Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94375:011.
- 7812280019 Forwards copy of newly rev NPDES permit for subj fact1. No shviron impact will result from changes incorp into new permit.

 UHR10:R.E. Florida Power & Light Co. 78/12/07. 1p. 94131:036.
- --7812280026 Forwards NPDE8 permit for subj facil Permit to become effective on date noted provided no request for adjudicatory hearing is filed with EPA W/encl EPA Correspondence.

 TRAINA, P. J. Environmental Protection Agency. 78/06/14. ip. 94(3):037.

- facils to circulating water conling canel sys, to become effective 780701 TRAINAP J Environmental Protection Agency. 78/12/14 13pp. 94131 038
- 7812140150 Submits request to amend Append A of Facil Oper Lit&DPR-DPR-41.in response to 780719 NRC ltr. Amend concerns operability & surveillance of facil Overpressure Mitigating UHRIO.R.E. Florida Power & Light Co. 78/12/11. lipp. 94127-00
- 7812180378 Notice of 781218 meeting u/FL Light & Pur Co to discuss review of subj facil's Steam Generator Replacement Prog. GROTENHUIS.M Operating Reactors Granch 1 (Pre 790625). 78/12/12pp. 94358-215
- 7812270195 Forwards add1 info to suppl 780529 ltr in response to NF request for detailed schedule for providing eval of effects of esymmetric loss of coolant accident loads. UHRID.R E. Florida Power & Light Co. 78/12/19. 1p. 94010:087
- 7812270197 Forwards Matl Status Rept for period 771001 to 780331 fo LiceDPR-31.DPR-41.DPR-67 & SNM-1914 & Nuc Matl Transaction Rept for LiceDPR-31. DRPA-41
- Rept for LiceDPR-31 & DPR-41.
 UHRIG.R.E. Floride Power & Light Co. 78/12/20. 31pp. 94018: OC
- 7812270221 Forwards request to amend Append A of Facil Oper Lics OP & 41.8ub.j proposal requests changes in rod insertion limits for both units to allow more flexibility in long range reload planning W/encl sefety evaluation.
 UHRIG.R.E. Pennsylvania Power & Light Co. 78/12/22. 7pp. 94017-122.
- 7812280139 Informs of plans for next facil refueling & results of review of refueling analysis method Unit 3 is in oper cycle 5 & next refueling is sched for 791230. Westinghouse FLARE code will be used for reload design.

 UHRIO.R E Florida Power & Light Co 78/12/22 2pp. 94310:350
- 7811210338 Requests relief from ASME Code requirements re ultrasoni exeminations of piping welds. Recording & eval indications at 20% DAC is impractical Primary reference level(100% DAC) criteria for UT exam provides comparable sefety level UHRIG.R.E. Florida Power & Light Co. 78/11/15. 4pp. 94484:324
- G. Inspection reports, IE Bullatins & correspondence
- 7811130003 Forwards IE Inspec Repts#50-250/78-17 & #50-251/78-17 on 780718-19 during which no items of noncompliance were noted. KENNA-H. B. Region 2, Atlanta, Bafeguards Branch. 78/08/24. 2pp 94077:008.
- --7811130007 TE Inspec Repts#50-250/78-17 & #50-251/78-17 on 780718 during which no items of noncompliance were noted. Major areas inspected: special security inspec re discovery of a hoar bomb device MODRE, D.E. ollLEBPIE, P. Region 2, Atlanta, Office of the Director. 78/08/23, 5pp. 94077 013.
- 7811010407 Forwards IE Inspec Rept#50-250/78-16 & #50-251/78-16 on 780724-27 during which no items of noncompliance were noted. BUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Bef Branch. 78/09/21. 2pp. 94388.330.
- --7811010411 IE Inspec Rept#30-250/78-16 & #50-251/78-16 on 780724-during which no items of honcompliance were noted Major areas inspected included:rediological environ protec & emergency planning.

 91880N.0.T. Region 2, Atlanta, Office of the Director. 78/09/4pp. 949881332.
- 7810110247 Orants requests in 1tr of 780914 to w/hold proprietary in Inspec Repta#50-250/78-14 & 50-251/78-14.
 LDNG, F.J. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78/10/02. ip. 03555:230.
- --7810110251 Requests w/holding proprietary info in Inspec Repts #50-250/78-14 & 50-250/78-14. UHRIG.R.E. Florida Power & Light Co. 78/09/14. ip. 94068:20
- --7810110256 Forwards IE Inspec Repts#50-250/78-14 & #50-251/78-14 780717-21 during which no items of honcompliance were noted. LQNO,F.J. Region 2, Atlenta, Reactor Operations Nuclear Suppor Brench. 78/08/21. 2pp. 94068:203.

- --7810110262 IE Inspec Repts#50-250/78-14 & #50-251/78-14 on 780717-21 during which no items of noncompliance were noted Major areas inspected included: calibration, surveillance, & procurement.

 OUZTS, J. E. , KELLOGO, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/08/17. Spg. 94068:205.
- 7810200188 Ack receipt of IE Inspec Repts#50-250/78-15 & #50-251/78-15.

 Does not consider any info therein to be proprietary.

 UMRIG.R.E. Florida Power & Light Co. 78/10/03. 1p. 94366:319.
- 7810240067 Ack receipt of 780918 ltr informing NRC of steps taken to correct violations noted during inspec#50-250/76-12 & #50-251/78-12.
 LDNG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/10. ip.
- --7810240075 Responds to 780814 NRC itr re violations noted in Inspec Repte#50-250/78-12 2-251/78-12. Corrective actions: Ltr to be issued requiring operational release must be obtained prior to starting work on safety related equip. UHRIG.R. E. Fibrida Power & Light Co. 78/09/29, 2pp.
- --7810240071 Responds to 780814 NRC 1tr re violations noted inspec Repts #30-230/78-12 & #30-231/78-12. Corrective actions include: procedures inglemented to document signature of plant work orders documenting equip release UHR10.R.E. Florida Pawer & Light Co. 78/09/18. Spp.
- --7810240208 Forwards IE Inspec Repts#50-250/78-12 & #50-251/78-12 on 780626-29 & Notice of Violation.
 LUNG, J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/08/14. 2pp.
- --7810240211 Natice of Violation from inspec on 780626-29. LEMIB.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 72/08/14. 2pp.
- --7810240217 IE Inspec Repts#50-250/78-12 & #50-251/78-12 on 780626-29 during which 3 items of noncompilance were noted failure to document proper approval of plant work orders & operational release of safety related equip & control clearance of equip LEMIB.R.C. Region 2, Atlanta. Reactor Operations Nuclear Support Branch. 78/08/14. 13pp.
- 7810260004 Ack receipt of 780823 itr informing NRC of steps taken to correct violations noted in 16 Insp Repts 50-250/78-10 & 50-251/78-10.

 0'REILLY, J. P. Region 2. Atlanta. Office of the Director. 78/10/13. 3pp. 74404:216.
- --7810260007 Responds to 780717 NRC ltr re violations noted in Inspec Rept#850-250778-10 & 50-251778-10. Clerifies info re training of Fire Team members & requests change to unresolved item. Requests suspension of deviation to review NUREO 0041. UHRIG.R. E. Floride Power & Light Co. 78/08/23. 4pp. 94404:219.
- --7810260010 Forwards IE Inapec Rapt#80-250/78-10 & #50-251/78-10 on 780526-0602 & Notice of Violation & Notice of Deviation. BUTHERLAND, J.T. Region 2, Atlanta, Office of the Director. 78/07/17. 2pp. 94404; 223.
- --7810260064 Notice of Violetion From inspec on 780526-0602. * Region 2, Atlanta, Office of the Director. 78/07/06. ip. 94404:225.
- --7810260069 Notice of Daviation from Inspec on 780526-0602. Dn 780601, 52 of 57 fire brigade trained mambers were not certified as respiratory protection qual per NUREQ-0041. A Region 2, Atlanta, Office of the Director. 78/07/06, 1p. 94404:226.
- ---7810260073 IE Inspec Repts#50-250/78-10 & #50-251/78-10 on 780526-0602 during which I item of noncompliance & I item of deviation were noted training of fire team personnel & certification of fire team personnel in respiratory protec.

 91850N.0.T. Region 2. Atlanta, Office of the Director. 78/07/06. App. 94404:227.
- 7810300321 Forwards IE Circular 78-17.

 O'REILLY, J.P. Region 2, Atlanta, Office of the Director, 78/10/13.

 1p. 94253:227
- 7812010123 Ack receipt of 781031 ltr informing NRC of steps taken to

correct violations noted during inspects0-250/78-10 k

- --7812010128 Responds to 781013 NRC ltr re violations noted in Inspec Repts#30-230/78-10 & #50-231/78-10. Corrective actions: respiratory protec training will be introduced by 781101 for members of each shift.

 UHRIG.R.E. Florida Power & Light Co. 78/10/31. 1p. 94418:057.
- 7812120232 forwards IE Inspec Repts#50-250/78-20 \$#50-251/78-20 on 780905-08 & Notice of Violation. LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/17. 2pp. 94277:206
- --7812120235 Notice of Violation from inspec on 780905-08 * Region 2: Atlanta: Diffice of the Director: 78/10/17. \$p. 94277.208.
- --7812120237 IE Inspec Repts#50-250/78-20 & #50-251/78-20 on 780905-08 during which 2 Items of noncompliance were noted:use of or failure to rev obsolete procedure for maint or surveillance.

 MARTIN.R.D. Region 2. Atlants. Office of the Director.

 JOHNSON, A. H., WHITENER H. L. Region 2. Atlants. Reactor Operations
 Nuclear Support Branch. 78/10/17. 7pp. 94277:209.
- 7811070309 Ack receipt of IE Inspec Rept(e)#50-250/78-18,#50-251/78-18, on 780822-25, Does not consider any info therein to be proprietary.

 UHRIG.R.E. Florida Power & Light Co. 78/10/22. 1p. 94041: 146,
- --7811070314 Forwards IE Inspec Rept(e)850-250/78-18 & 50-251/78-18 on 780823-28 duplot which on these of noncompliance were noted
- 760822-25 during which no items of noncompliance were noted.
 LONG-F.J. Region 2. Atlanta, Reactor Operations Nuclear Support
 Branch. 78/09/29. 2pp. 94041:147.

 --7811070320 IE Inspec Rept(s)#50-250/78-18 & 50-251/78-18 on 780822-2
 during which no items of noncompliance were noted. Major
- --7811070320 IE Inspec Rept(s)#90-250/78-18 & 30-251/78-18 on 780822-25 during which no items of noncompliance were noted. Major areas inspected included: organization & admin, followup on noncompliance. IE Bulletins & circulars, reportable events. VENDERY, E. H., LEWIS.R. C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/09/29 7pp. 94041:149.
- 7811030003 Ack receipt of 780914 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/78-11. \$ 50-251/79-11. \$ UTHERLAND, J.T. Region 2. Atlants. Fuel Facility & Materials Bafety Branch. 78/10/24. 1p. 02720:221.
- --7811030168 Responds to 780811 NRC ltr re violations noted in Inspec Repts#30-250/78-11 & #80-251/78-11. Corrective actions: radiation controlled Area inspec every shifts sealed sources being tested contaminated respirators removed. UHRIG.R.E. Florida Power & Light Co. 78/09/14. 5pp. 02720: 222.
- --78:1030:7: Forwards IE Inspec Repts#50-250/78-:1 & #50-251/78-:1 on 780419-23 & Notice of Violation.

 BUTHERLAND.J.Y. Region 2. Atlenta. Fuel Facility & Meterials Safety Branch. 78/08/:1. 2pp. 02720:227.
- --7811030175 Notice of Violation from inspec on 780619-23. BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Befety Branch. 78/08/11. 3pp. 02720: 229.
- --7811030178 IE Inspec Repts#30-250/78-11 & #50-251/78-11 on 780619-23 during which 4 items of noncompliance were noted: control of high radiation areas/health physics procedures/periodic leak testihealth physics retraining program.

 * Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 78/10/24. 16pp. 02720: 232.
- 7812010043 Ack receipt of IE Inspec Repts#50-250/78-17 & #50-251/78-17.

 Does not consider any info therein to be proprietary.

 UHRIO.R.E. Florida Power & Light Co. 78/10/24. 1p. 94416:118.
- 78111000B2 Ack receipt of 781031 ltr informing NRC of steps taken to correct violations contained in IE Insp Repts 30-250/78-13 & #50-251/78-13. KENNA-M.S. Region 2. Atlanta, Safeguards Branch. 78/10/31, 1p. 94179: 332.
- --7811100083 Responds to 780915 NRC ltr re violations noted in Inspec Repts850-280/78-13 & 850-251/78-13 Corrective actions withheld (ref lOCFR2.790) URRIG.R.E. Florida Pawer & Light Co. 78/10/19. ip. 94179; 333.
- --7811100086 Forwards IE Insp Rept 50-250/78-13 & 50-251/78-13 on 780710-13.
 KENNAW, B. Region B. Atlants, Safepuards Branch 78/09/15

- 7811180103 Forwards IE Circular 78-18. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/06 1p. 94113:293
- 7811240025 Ack receipt of IE Inspec Repts#50-250/78-19 & #50-251/78-19 on 780828-31 Does not consider any info therein to be proprietary UHRIG.R.E. Floride Power & Light Co. 78/11/09. ip. 94457.326.
- --7811240027 Forwards IE Inspec Repts#50-250/78-19 & #50-251/78-19 on 760928-31 during which no items of noncompliance were noted. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Brench 78/10/17. 2pp. 94457:327.
- --7811240033 IE Inspec Repte#50-250/78-19 & #50-251/78-19 on 780828-31 during which no items of noncompliance were noted Major
- areas inspected included: insvc inspec activities & records & maint & mod welding & NDE Activities & Prog. BLAKE, J. , CONLON, T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/10/12. App. 94457:329
- 7812010100 Ack receipt of IE Inspec Rept#50-250/78-23 & #50-251/78-23. Does not consider any info therein to be proprietary. UHRIG.R.E. Florida Power & Light Co. 78/11/15. Bpp. 94417:082.
- --7812010104 Forwards IE Inspec Rept#50-250/78-23 & #50-251/78-23 on 780912-15 during which no items of noncompliance were noted. LONG-F. J. Region 2. Atlants. Resctor Operations Nuclear Support Branch. 78/10/20. 2pp. 94417:083.
- --7812010109 1E Inspec Rept 50-250/78-23 & 50-251/78-23 on 780912-15 during which no items of nationalisance were noted Major areas inspected incl:plent pper, following of rept events IE bulletins & circulers.

 WERDERY, E. H., LEWIS, R. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/23. Spp. 94417:085.
- 7812010116 Ack receipt of 781024 ltr informing NRC of steps taken to correct violations noted during inspec#50-250/78-16 to #50-251/38-16.
 BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Befaty Branch, 78/11/16. [p. 94418:021.
- ~-7812010119 Responds to 781016 NRC ltr re violations noted in Inspec Reptse50-250/78-16 & 850-251/78-16. Corrective actions: serial survey will be performed over subj fecil. procedural requirements will be established for Ci/sec rate. URRIG.R.E. Florida Power & Light Co. 78/10/24. 3pp. 94418:022.
- 7812050240 Ack receipt of IE Inspec Rept#50-250/78-22 & #50-251/78-22 on 780912-15. Does not consider any info therein to be proprietary.
 UHR19.R.E. Florida Power & Light Co. 78/11/16. 1p. 94202:046.
- --7812050242 Forwards IE Inspec Rept#50-250/78-22 & #50-251/78-22 on 780912-15 & Notice of Violation. BUTHERLAND,J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/11/03. 2pp. 94802:047.
- --7812050246 Notice of Violation from inepec on 780912-15. Region 2: Atlanta: Fuel Facility & Materials Safety Branch, 78/11/03.
 1p. 94202:049.
- --7812050249 IE Inspec Rept#50-250/78-22 & #50-251/78-22 on 780912-15 during which I them of noncompliance was noted: review of groundwater monitoring sched not done quarterly but semi-smously w/out benefit of req amend to lic.
 CUNNINOHAM,A.L. HUFHAM.J.W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/10/12. 6pp. 94202:050.
- 7812120057 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Bafaguards Newsletter.
 KENNA W.B. Region 2, Atlanta, Safeguards Branch. 78/11/17. 4PP. 94278: 092
- 7812040308 Forwards IE Bulletin#78-12A, suppl to IE Bulletin 78-12. W/encl AND: 7811300055. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/24. 1p. 94129: 160.
- 7812120236 Ack receipt of 781114 ltr informing NRC of steps teken to correct violations noted during inspec#50-250/78-20, #50-251/78-20. LONG, F. J. Region 2. Atlenta, Reactor Operations Nuclear Support Branch. 78/12/04, 1p. 94277:202.

7812190235 Ack receipt of IE Inspec Repts#30-230/78-25 & #50-251/78-2 on 781016-20 Does not consider any info therein to be

74277.20

UMRIG.R.E. Florida Power & Light Co. 78/12/04. 3pp.

- proprietary.
 UHRIQ.R.E. Florida Power & Light Co. 78/12/06. ip. 94376: QQL.
- --7812190238 Forwards IE Inspec Repts#50-250/78-25 2-251/78-29 on 781016-20 during which no items of noncompliance were noted. LONG.F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 70/11/17. 2pp. 94376
- --7812190243 IE Inspec Repts#50-250/78-25 & #50-251/78-25 on 781014-2 during which no items of noncompliance were noted. Major areas inspected incl:plant oper after refusing followups of noncompliance, oper items. IE publications, emergency drills.

VERDERY, E.H. Region 2, Atlanta, Reactor Operations Nuclear Suppo Brench. 78/11/17. 7pp. 94376:004.

- 78:2:80:38 Forwards facil Steam Generator Inspec Prog planned for Jam UHR19.R.E. Florida Power & Light Co. 78/12/11. 1p. 94345: 204.
- --7812180141 "Turkey Point Unit#3 Bleam Generator Inspec Prog Planned January 1979. # Florida Power & Light Co. 78/12/11. 2pp. 94365:285.
- 7812210068 Ack receipt of IE Inspec RepteMS0-230/78-24 & MS0-281/78-2 Does not consider any info therein to be proprietary. UHRIG-R.E. Florida Power & Light Co. 78/12/11. 1p. 94269: DSB.
- --7812210071 Forwards IE Inspec Repts#50--250/78-24 & 50-251/78--24 on 781018-19 during which no items of noncompliance were noted. BUTHERLAND, J. T. Ragion 2, Atlanta. Fuel Facility & Materials Befety Branch. 70/11/22, 2pp. 94269, 339.
- ~7812210076 1E Inspec Repts#50~250/78-24 % #50~251/78-24 on 781018-1 during which no items of noncompliance were noted. Major areas inspected incl: observation of annual Emergency exercise, jicenses fire drill & discussions w/personnel. HUFHAM.J.W., 01880N.Q.T. Region-2. Atlanta, Fuel Facility & Materials Bafety Granch. 78/11/22. 5pp. 94269:341.
- 7812280328 Ack receipt of 781201 ltr informing NRC of steps taken to correct violations noted during inspec#80-250/78-21 % #50-251/78-21, SUTHERLAND, J. T.
- SUTHERLAND, J. T. Region 2. Atlante. Fuel Facility & Materials Bafet Branch. 78/12/19. 2pp. 94082:155. --7812280339 Responds to 781106 NRC ltr re violations noted in Images Repts#50-250/78-21 & #50-251/78-21 Corrective actions: respiratory protec equip training classes & health physics
- training classes held. UHRIG.R.E. Florida Power & Light Co. 78/12/01. Spp. 94082:157 --7812280342 Forwards IE Inspec Repts#50-250/78-21 & #50-251/78-21 or 780911-15 & Notice of Violation. SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Matarials Bafety Branch. 78/11/06. 2pp. 94082:162.
- --7812280344 Notice of Violation from inspec on 780911-15. * Region 2, Atlanta, Office of the Director. 78/11/06. 2pp. 94082 1AA
- --7812280348 IE Inspec Repts#50-250/78-21 & #50-251/78-21 on 780911-Discounts it inspec ApprendU-290734-21 to #30-291778-21 to 7809 during which 3 items of noncompliance were noted issuence & use of respirators, preparation of shipments of radioactive math not in requirements & failure to lock high radiat areas CCLLINS, D.M., ZAVADDSKI, R.W., OISSON, A.F. Region 2, Atlanta, Office of the Director. 78/11/03. 13pp. 94082:166.
- 7812290087 Forwards IE Bulletin 78-14. O'REILLY, J.P. Region 2. Atlanta, Office of the Director, 78/12/19 2pp. 03669:338.
- S. Reportable occurrences, LERs & related correspondence
- 7811060142 Forwards LER#78-013/03L-0. BCHMIDT, A.D. Floride Power & Light Co. 78/10/27, 1p. 94424: 281.

--7811060152 LER078-013/03L-0 pn 780929 Unit 3 condensate storage tank contained less than 185.000 gallons for period of about 4 hours. Caused by unit 3 steam generator blowdown w/no demineralized water makeup.

BCH0PPMAN.M A Florida Power & Light Co. 78/10/27. 1p. 94424 2892

- 7811060144 Forwards LERR78-014/03L-O.

 BCHMIDT, A.D. Florida Power & Light Co. 78/10/27. 1p. 94489:059.
- --7811060148 LERN78-014/03L-0 on 780929:Comparator pur supply FC-3-484 melfunctioned due to faulty regulating oper amplifier in comparator's pur supply bd Amplifier was replaced & comparator tested satisfactorily.

 SCHOPPMAN, M.A. Florida Power & Light Co. 78/10/27. 1p. 94489 090
- 7811220201 Forwards LER#78-015/03L-0. SCHMIDT.A D. Florida Power & Light Co. 78/11/08. 1p 03695.278.
- --7811220203 LER#78-015/03L-0 on 781010, i9 accessible safety related shubbers were replaced one at a time w/methanical shubbers. SCHOPPMAN, M. A. Florida Power & Light Co. 78/11/08 lp. 03695.279
- 7812040187 Forwards LER#78-014/03L-0. SCHMIDT.A.D. Florida Power & Light Co. 78/11/24. 1p. 94457:106.
- --7812040189 LERW78-016/03L-0 on 781025 during pur oper-intake cooling water pumps were running when 3B pump motor failed. The 3B pump motor failed because of short circuit in the motor windings
 SCHOPPMAN.M.A. Floride Power & Light Co. 78/11/24. 1p. 94457-107
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4

 F. Becurity, medical, emergency & fire protection plans
- 78120B0148 Licensee has been orally notified that Emergency Plenthrough Revision 4 dtd 780927 is acceptable based on 781025 memo M/encl AND 7811020177.

 BCHMENCER A Operating Reactors Branch 1 (Pre 790625). 78/11/28.
 1p. 94104.349.
- 7812110010 Pending staff approval of Rey O, requests util commit to prepare special security procedures applicable to the replacement of steam generators.

 8CHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/12/01. 2pp. 94339:235.
- 7812120119 Discusses fire protection in operating nuclear power stations in particular providing analysis of facilities.' SER. Proposed fire protection mod increases level of protection against fire hazards. HALL-R.E. Brookhaven National Laboratory. 78/12/06. Spp. 94273-240.
- 7810120075 Forwards copies of Rev 4 to subj facil Emergency Plan.
 UHRIGAR E. Florida Power & Light Co. 78/09/27, 2gp. 94402:221.
- --7810120081 Rev 4 to State of FL Radiological Emergency Plan dtd May 1975.Ltr of support w/ERDA dtd 730410.FL Highway Patrol Order 32 dtd 760401 & Coast Guard 760426 ltr encl. • Florida Power & Light Co. 78/09/27. 166pp. 74402:223.
- 7810300325 Ack recipt of 780623 ltr re position that 3-man fire brigade is adequate to cope w/any fire at subj facil.
 Requests addl info so NRC may evaulate proposal.
 8CHNENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/10/16.
 3pp. 94253:341.
- 7810310121 Forwards Rev D to security plan dtd 780926 Withheld (ref 10CFR2.790).
 UHR10.R.E. Florida Power & Light Co. 78/10/24. 111pp.
- 7811130221 Forwards response to 781016 NRC ltr requesting info re availability of supplementary fire brigade support personnel actions req of personnel & training & squal of individual who established size of brigade & training prog.

 UHRIG.R.E. Florida Power & Light Co. 78/11/07. 5pp. 03554:109.
- 7811280170 Forwards Amend#42 to Facil Oper Lic@DPR-31 & Amend#34 to Facil Oper Lic@DPR-41. Amend Tech Specs for Fire Protec Sys & Admin controls in Response to 771222 Appl(1-77-390). SCHWENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/11/08. 5pp. 94013:173.

- --7811280172 Amend#42 to Lic#DPR-31 rev common station Tech Specs to incorp limiting conditions for oper & surveillance requirements for existing fire protec sys.

 6CHMENCER.A Operating Reactors Branch 1 (Pre 790625) 78/11/08.
 2pp. 94013-178
- --7811280174 Amend#34 to Lic#DPR-41 rev common station Tech Specs to incorp limiting conditions for oper & surveillance requirements for existing fire protec sys. SCHMENCER.A. Operating Reactors Branch i (Pre 790625). 78/11/08. 20pp. 94013:180.
- --7811280178 Notice of Issuance of amend#34 & 42 to Facil Oper Lic# PR-31 & DRR-41 Amend rev Tech Specs to incorp limiting conditions for oper & surveillance requirements for existing fire protec sys. SCHHENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/08. 2pp. 94013:200.
- 7812120125 Requests add1 info re fire protec at subj facils, info concerns water supply, cable protecty and hydrants, smoke venting equip & smoke removal Documentation re info acught encl.

 HALL R. E. Brockhaven National Laboratory. 78/09/21, 9pp 94275:345.
- 7812270190 Responds to 781201 NRC request for special security procedures. Agrees to prepare security procedures IAW Mod Amend Security Plan at least 90 days prior to commencing steam generactr repair activity.
 UHRIQ.R.E. Plorida Power & Light Co. 78/12/15. 1p. 94018:042

H. Geheral correspondence

- 7819270168 Requests placement on distribution list for correspondence & repts dealing w/oper status for subj facils. SHREVE.J. Florida, State of. 78/12/18. 1p.
- I. Financial information
- 7811070144 Forwards req guarantees under Price-Anderson as enend 1975 under option 5.Encl provides info re 1977 annual rept. consolidated financial statements.cash flow projections. capital expenditure curtailments & cash flow sources. UHRID: R.E. Florida Power & Light Co. 78/10/30. 45pp. 94044:022.
- J. Insurance & Indomnity information
- 7810230140 Forwards Endorsement#37 to Nuc Energy Liability Insurance #MF-35. Also States that Endorsement#36 to Nuc Energy Liability Insurance#MF-183 was forwarded w/760618 FPL 1tr (L-76-228). URIO.R. E. Florida Power & Light Co. 78/10/09. 2pp. 94164:203.
- 7810300107 Forwards Endorsement#36 to Policy#NF-105 & Endorsement#37 to policy#NF-55.
 UHR10.R.E. Floride Power & Light Co. 78/10/09. 1p. 94035:236.

M. Antitrust correspondence

- 7811080144 "Notice of Appearance"re proceedings.Cert of Svc encl. EVANS.D. U. Office of the Executive Legal Director. 78/10/30. 3pp. 94399:291.
- 781227007: Provides notice that RC McDiarmid & DA Quacalone w/draw as representatives of FL Cities in proc re subj facils.
 JABLON.R.A. Spiegel & McDiarmid. 78/12/13. 4pp. 94i61:01).
- P. Operating license stage documents & correspondence
- 78:01:01:23 Forwards "Rept of Abnormal Indications from Metal Impact Monitoring Bys," during 78:09:22-25 reactor coolant pump runs. UHR16.R.E. Florida Power & Light Co. 78/10/06. 2pp. 94067:349.
- 7812010382 Response to 780613 ltr re-comments & corrective actions in 780404 NRC ltr re-Diesel Generator Lockout.Util's response is adequate.

 8CHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/06/30. is.
- 7812180378 Notice of 781218 meeting w/FL Light & Pwr Co to discuss review of subj facil's Steam Generator Replacement Prog. OROTENHUIS.H. Operating Reactors Branch (Pre 790625). 78/12/14. 2pp. 94398:215.

- 7812190036 Forwards Rev#1 "Dreft Radiological Effluent Tech Specs" for PWR's(NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133).

 ORIMES-8 K. Assistant Director for Engineers & Projects (Pra 790625). 78/11/15. 6pp 94215.009
- 7812290026 Forwards NPDES permit for subj facil Permit to become effective on date noted provided no request for adjudicatory hearing is filled with EPA. W/encl EPA correspondence.
 TRAINA-P. J. Environmental Protection Agency. 78/06/14. ip 94131:037
- 7810250175 Notice of Proposed Issuence of Amends to Facil Oper Lics NRC is considering issuence of amends to Facil Oper Lics DPR-31 & DPR-41. Amends rev Tech Specs re transient & accident enalysts.

 8CH-ENCER, A Operating Reactors Brench 1 (Pre 790625) 78/08/04 4ps. 94393:062.
- 7811210191 Notice of Issuance of Amends 38 & 31 to Facil Oper Lic*DPR-31 & #DPR-41. Amends change Tech Specs re refueling of Unit 4 Cycle 5 oper.

 8CHJENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/09/22.
 3pp. 94488-003.
- 7810120022 Forwards test rept for 770701~780630 per 100FR50 596. UHRIO-R E. Florida Power & Light Co. 78/10/04. ip. 94330:174.
- --7810120023 Test rept details plant change/mods.procedure changes, tests & expers.Major areas:task-crane-add-limit switches.diesel emergency diesel surge tank.NDDT overpressure relief protection.reactor coalent pump seal mod.flamastic addition. * Florida Power & Light Co. 78/10/04. 65pp 94330:175
- 7810110139 Responds to 780802 NRC ltr re meterological data.Forwards info tables re wind frequency. UHR10.R.E. Florida Power & Light Co 78/10/05. 9pp. 94069-226
- 7810270182 Ack receipt of 780719 ltr requesting proposed Tech Specs be submitted addressing overpressure protec. Will submit info by 781115.

 UMRIO-R.E. Florida Power & Light Co. 78/10/19. 1p. 94057:083.
- 7810300003 Requests add: \$400 fee to process 780809 appl for emend to Facil Lic #DPR-31 & DPR-41. MILLER, W.D. Licensa Fee Management Branch. 78/10/19. ip. 94034:224.
- 7811030177 Ack review of Rev 1:2:3:4.Rev 1 & 2 found acceptable.Rev 3 & 4 update arrangements w/various radiol emergency support groups.Back-up hospital changed to Baptist Hoap.After review:3 & 4 found acceptable.

 KNIGHTON:0. Environmental Evaluation Branch (Pre 790625). 78/10/25.

 1p. 94104:350
- 7811030203 Forwards corrected page#1 to Amend#30 to Lic#DPR-41 dtd 780921.
 8CHWENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/10/25.
 2pp. 02724:137.
- 7811090015 Forwards AmendW40 t 32 to Facil Oper LicHDPR-31 t DPR-41, changing Tech Spec to reduce pressurfier heatup rate.

 8CHWENCER: A. Operating Reactors Branch 1 (Pra 790625). 78/10/25.
 2pp. 94040:001
- --7811090018 Amend#40 to Facil Oper LickDPR-31, changing Tech Spec to reduce pressurizer heatup rate.

 BCHWENCER.A. Operating Reactors Strench 1 (Pre 790623). 78/10/23.
 2pp. 94040:003.
- --7811090021 Amend#32 to Facil Oper Lic#DPR-41 changing Tech Bpec to reduce pressurizer heatup rate. 8CHMENCER.A. Operating Reactors Brench 1 (Pre 790625). 78/10/25. 4pp. 94040:006.
- --7811090024 Sefety Evel Supporting Amend#40 & 32 to Lic#DPR-31 & DPR-41. Concludes that no adverse effects will result.

 * Office of Nuclear Reactor Regulation, Director. 78/10/25. 3pp. 94040:010.
- 781i130075 Forwards reissued Amend#38 & #31 to Facil Lic#DPR-31 & #DPR-41 w/corrected amend numbers.

 SCHWENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/10/26.

 Spp. 94478:339.
- --7811130080 Amend#38 to Facil Oper Lic#DPR-31, changing Tech Spec to auth oper w/25% of tubes in plugged condition. EISE-MUT.D.O. Assistant Director for Systems Engineering (Pre 791030). 78/09/22. 2pp. 94072:314.

- ~-7811130083 Amend#31 to Facil Oper Lic#DPR-41.changing Tech Spec rerefueling of Cycle 5 oper & auth oper u/25 percent tubes in plugged condition EIBENHUT.0 9 Assistant Director for Systems Engineering (Pre 791030) 78/09/22 13pp 94076:344.
- --7811130170 Bafety evaluation supporting Arend#38 & 31 to Lic#DPR-31 #DPR-41 Concludes that no harm will ensue • Office of Nuclear Reactor Regulation. Director. 78/09/22. 18pp. 94011 137
- --7811130175 Notice of Issuance of Amend#38 & #31 to Fecil Oper Lic#DF 31 & #DPR-41, changing Tech Spec re Cycle 5 oper & oper w/tubes in plugged condition.

 BCHHENCER, A Operating Reactors Brench 1 (Pre 790625). 78/09/22 3pp. 94011:155
- 7811070180 Forwards check in response to 781019 request UHRIG.R E Florida Power & Light Co 78/10/30. Ip 94036:357.
- 7811290068 Amends#38 & #31 to Facil Oper Lic#DPR-31 & #DPR-41 for subjectile were completed on 780922 Wissuance of these two amends.ell prior NRC Orders re subj facils have been satisfied. Audit tabulation encl.
 BCHNENCER, A. Operating Reactors Branch 1 (Pre 790625) 78/11/08 369. 94193.223
- 7811200417 Forwards results of measurements of radioactive mat1 in NRC phantom on whole body counter Enc1 1 contains actual arount of sach radionuclida presentent1 2 gives ratio of measurements to DDE values & enc1 3 gives recommendations.

 BUTHERLAND, J T Region 2, Atlants, Fuel Facility & Materials Bafetty Branch. 78/11/09. 3pp 94419.164
- 7811210236 Notifies util of 781205 seminar in Atlanta to discuss new Model Rod Effluent Tech Specs & encl seminar Enfo sheet, registration form. & proposed agenda O'REILLY.J P. Region 2. Atlanta, Office of the Director. 78/11/09 5pp 94488 330
- 7811160139 Forwards info in response to 780318 NRC request for info resteam generator & reactor coolent pump supports sufficient to show geometry of all principal elements. Oversize drawings available in Central Files

 UHRIG-R & Florida Power & Light Co. 78/11/10 ip 94135: 249.
- ---7811160142 "Report on Fracture Toughness & Potential for Lamellar Tearing of Steam Generator & Reactor Coolent Pump Supports." w/27 oversize drawings showing geometry of all principal elements available in Central Files.

 * Florida Power & Light Co. 78/09/30. 40pp. 94135:250.
- 7811300041 Forwards NRC steff paper Policy Bession [ter(BECY-78-554)] 1 licensee reg performance evaluation. Three methods for evaluation are: statistical trend enalysis & regional survey method W/o encl.

 D'REILLY, J.P. Region 2, Atlante, Defice of the Director 78/11/15
 2pp. 94071-035.
- 7812180038 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73 Requests pre-workshop registration of attendees to facilitate sending out math. W/encl Registration Form & List of Locations.
 MILLER, J. R. Assistant Director for Bite & Bafeguards (Pre 791030). 78/11/15. 5pp. 94133:031.
- 7811270161 Forwards appl for Amend to Facil Operating Lics#DPR-31 & DPR-41. Proposed amend eddresses Overpressure Mitigating Sym (DMB). Discusses limiting conditions for oper of Reactor Coolant Sys.

 UMRIO-R.E. Florida Power & Light Co. 78/11/20. 11pp. 94252;324.
- 781128022B In response to 780915 NRC ltr. submits suppl to 760604 ltr meet requirements of Bec V. B of Append I to 10CFR30 to operationally evaluate drain floor treatment sys which is suppl by a portable demineralizer.

 UHRIG.R.E. Florida Power & Light Co. 78/11/20. 3pp. 94012:047.
- 7812140357 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wiencl ANDS 7812080207. SCHENCER, A. Operating Reactors Branch 1 (Fre 790625). 78/11/28. App. 03557:223.
- 7812040336 Requests \$1,600 in lic fees since amend does not qualify free exemption under 10CFR170. 92 footnote#2.
 MILLER.M.O. License Fee Management Branch. 78/11/29. ip. 94137: 356.

- 78:228017: Emphasizes importance of submitting accurate & complete info to NRC by licensee & applicants Info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result DAVIS.J G Office of Inspection & Enforcement, Office of the Director 78/12/05 2pp 94375 011
- 7812280019 Forwards copy of newly rev NPDES permit for subj facil No environ impact will result from changes incomp into new UHRIG.R E Florida Power & Light Co 78/12/07 ip 94131:036.
- --7812280040 Authorization to discharge under NPDES from FL Pur & Light facils to circulating water cooling canal sys. to become effective 780701
 - TRAINA.P.J. Environmental Protection Agency 78/12/14 13pp. 94131 038
- 7812140146 Forwards "Cycle S Startup Rept.
 UMRIO.R E Florida Power & Light Co 78/12/08 ip 94479.001.
- --7812140152 "Cycle 5 Startup Rept " Test began 780927 w/initial
 - Cycle 3 States Apple 1 Test began 78092/ W/Initial criticality & was completed 780930.

 MENDE.R. G. TOMONTO. J. R., KAMINSKAS, V. A. Florida Power & Light Co. 78/12/08 28pp 94479 002.
- 7812140150 Submits request to amend Append A of Facil Oper Lic#DPR-31 & DPR-41:in response to 780719 NRC ltr.Amend concerns operability & surveillance of facil Overpressure Mitigating. UHRIGR.E Florida Power & Light Co 78/12/11 11pp 94127.009.
- 7812210196 States acceptance criteria on rod worths is w/in 10% from design For Cycle 4 the difference from Westinghouse design was 7.8% Provides measured vs design values for rod worth in ppm boron concentrations. UHRIG.R E Florida Power & Light Co. 78/12/14, 1p. 94279:067.
- 7812270195 Forwards add1 info to suppl 780929 ltr in response to NGC request for detailed schedule for providing eval of effects of asymmetric loss of coalant accident loads. UHRIO.R E Florida Power & Light Co. 78/12/19 1p 94018:087.
- 7812270187 Forwards Matl Status Rept for period 771001 to 780331 for Lic#DPR-31, DPR-41, DPR-67 & 8NM-1514 & Nuc Metl Transaction Rept for LicaDPR-31 & DPR-41 UMRIG.R E Florida Power & Light Co. 78/12/20 31pg. 94018:006.
- 7812270221 Forwards request to amend Append A of Facil Oper Lics DPR-31 & 41 Buby proposal requests changes in rod insertion limits for both units to allow more flexibility in long range reload planning W/encl safety evaluation. UHR10-R.E. Pennsylvania Power & Light Co. 78/12/22 7pp 94017 122
- 7812280139 Informs of plans for next facil refueling & results of review of refueling analysis method Unit 3 is in oper cycle 5 & hext refueling is sched for 791230 Hestinghouse FLARE code will be used for reload design UHRIG.R.E. Florida Power & Light Co. 78/12/22 2pp. 94310:350.
- 7811210338 Requests relief from ASME Code requirements re ultrasonic examinations of piping welds. Recording & eval indications at 20% DAC is impractical. Primary reference level(100% DAC) criteria for UT exam provides comparable sefety level UHRIO.R E. Florida Power & Light Co. 78/11/15 4pp 94484:324
- Q. Inspection reports. IE Bulletins & correspondence
- 7811100082 Ack receipt of 781031 ltr informing NRC of steps taken to correct violations contained in IE Inap Repts 50-250/78-13 & #30-251/78-13 KENNA, W. B. Region 2: Atlanta, Safeguards Branch, 79/10/31. Ip 94179:332
- --7811100083 Responds to 780915 NRC ltr re violations noted in Inspec Repts#30-250/78-13 & #50-251/78-13. Corrective actions withheld (ref 10CFR2.790). URRIG.R.E. Florida Power & Light Co. 78/10/19. 1p. 94179: 333.
- --7811100086 Forwards IE Insp Rept 50-250/78-13 & 50-251/78-13 on 780710-13 KENNA, N. B. Region 2, Atlanta, Safeguarda Branch. 78/09/18. 2pp. 94179 335
- 7811130003 Forwards IE Inspec Repta#50-250/78-17 & #50-251/78-17 on 780718-19 during which no items of noncompliance were noted. KENNA. H. B. Region 2: Atlanta: Safeguards Branch. 78/08/24, 2pp. 94077: 008

- --7811130007 IE Inspec Repts#30-250/78-17 & #50-251/78-17 on 780718-19 during which no items of noncompliance were noted. Major areas inspected: special security inspec ne discovery of a hear bomb device MODRL D E . OILLESPIE.F.P Region 2. Atlanta. Dffice of the Director . 78/08/23 5pp. 94077 013
- 7812010043 Ack receipt of IE Inspec Repts#50-250/78-17 & #50-251/78-17. Does not consider any info therein to be proprietary. UHRIO.R E. Florida Power & Light Co 78/10/24. lp. 94416:118
- 7812010100 Act receipt of 1E Inspec Rept#50~290/78-23 & #50~251/78-23. Does not consider any info therein to be proprietary.

 UHRIO, R. E. Florida Power & Light Co. 78/11/15 8pp. 94417:082.
- --7812010104 Forwards IE Inspec Rept#50-250/78-23 & #50-251/78-23 on 780912-15 during which no items of noncompliance were noted. LONG.F. J. Region 2. Atlenta, Reactor Operations Nuclear Support Branch. 78/10/23. 2pp 94417:083
- --7812010109 IE Inspec Rept 50-250/78-23 & 50-251/78-23 on 780912-15 during which no items of noncompilance were noted. Major areas inspected inciplant open-following of rept events. IE bulleting & circulars. VERDERY, E. H., LEWIS, R. C. Region 2, Atlenta, Reactor Operations Nuclear Support Branch. 78/10/23, 5pp. 94417.085.
- 7812010116 Act receipt of 781024 ltr informing NRC of steps taken to correct violations noted during inspec#50-230/78-16 & #50-251/76-16 BUTHERLAND.J T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 78/11/16. 1p 94418:021.
- --7812010119 Responds to 781016 NRC ltr re violations noted in Inspec Repts#50-250/78-16 & #50-251/78-16. Corrective actions: serial survey will be performed over subj facil, procedural requirements will be established for Civec rate. URFIG.R.E. Florids Power & Light Co. 78/10/24. 3pp. 94418:022.
- 7812010125 Ack receipt of 781031 itr informing NRC of steps taken to correct violations noted during inspec#50-250/78-10 & #50-251/78-10
- #50-2517/8-10 BUTHERLAND.J T Region 2. Atlants, Fuel Facility & Materials Safety Branch 78/11/16. 1p. 94418:036.
- --7812010128 Responds to 781013 NRC itr re violations noted in inspec Repts#50-250/78-10 & #50-251/78-10. Corrective actions: respiratory protec training will be introduced by 781101 for members of each shift.
 UHRIG.R.E. Floride Power & Light Co. 78/10/31. ip. 94418:057.
- 7812120057 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Safeguards Newsletter KERNA, W.B. Region 2, Atlanta, Baleguarda Branch. 78/11/17. 4PP. 94279:092
- 7811010407 Forwards IE Inspec Rept#50-250/78-16 & #50-251/78-16 on 780724-27 during which no items of noncompliance were noted. SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Prench. 78/09/21, 2pp. 94388: 330:
- --7811010411 IE Inspec Rept#50-250/78-16 & #50-281/78-16 on 760724-27 during which no items of noncompliance were noted. Major areas inspected included: radiological environ protec & emergency planning. 0/880N.O.T. Region & Atlanta, Office of the Director. 78/09/11. 4pp. 94386:332.
- 7810110247 Orants requests in 1tr of 780914 to w/hold proprietary info in Inspec Repts#50-250/78-14 & 50-251/78-14. LONG.F. J. Region 2: Atlanta, Reactor Operations Nuclear Support
- --7810110251 Requests w/holding proprietary info in Inspec Repts #50-250/78-14 & 50-250/78-14. UHRIG.R.E. Florida Power & Light Co. 79/09/14, 1p. 94048:202.
- --7810110256 Forwards IE Inspec Repts#50-250/78-14 & #50-251/78-14 on 780717-21 during which no items of noncompliance were noted. LONG.F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/08/21. 2pp. 94068:203.
- --7810110262 IE Inspec Repts#50-250/78-14 & #50-251/78-14 on 780717-21 during which no items of noncompliance were noted Major areas inspected included: calibration, surveillance, & procurement.
 OUZTB, J. E., KELLDOG. P. J. Region 2. Atlanta, Reactor Operations
 Nuclear Support Branch. 78/08/17. Spp. 94068: 205.

- 7810240067 Ack receipt of 780918 ltr informing NRC of steps taken to correct violations noted during inspec#50-230/78-12 & #50-231/78-12. LDNo.F.J Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/10. 1p.
- --7910240075 Responds to 780814 NRC ltr re violations noted in Inspec Reptem50-250/78-12 &850-251/78-12. Corrective actions: Ltr to be issued requiring operational release must be obtained prior to starting work on safety related equip. UR10.R E. Florida Power & Light Co. 78/09/29. 2pp.
- --7810240071 Responds to 780814 NRC ltr re violations noted Inspec Repts 850-250/78-12 & 850-251/78-12. Corrective actions include: procedures implemented to document signature of plant work orders documenting equip release. URIOR E. Florida Power & Light Co. 78/09/18. 3pp.
- --7810240208 Forwards IE Inspec Repts#50-250/78-12 & #50-251/78-12 on 780826-29 & Notice of Violation LDNg.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/08/14. 2pp.
- --7810240211 Notice of Violation from inspec on 780626-29. LBHS.R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/08/14. 2pp.
- --7810240217 IE Inspec Repts#50-250/78-12 & #50-251/78-12 on 780626-29 during which 3 items of noncompliance were noted:failure to document proper approval of plent work orders & operational release of safety releted equip & control clearance of equip LEMIS.R. C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 78/08/14 13pp.
- 7810260004 Ack receipt of 780823 ltr informing NRC of steps taken to correct violations noted in IE Insp. Repts 30-230/78-10 & 50-231/78-10.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/10/13.
 3pp. 74404:216.
- --7810260007 Responds to 780717 NRC ltr re violations noted in Inspec Repts#50-25078-10 & 50-25178-10. Clarifies info re training of Fire Taum members & requests change to unresolved item. Requeste suspension of deviation to review NURGE 0041. UMRIG.R. E. Florida Power & Light Co. 78/08/23. App. 94404.219.
- --7810260010 Forwards IE Inspec Rept#50-250/78-10 & #50-25)/78-10 on 780326-0602 & Notice of Violation & Notice of Deviation. 8U/HERLAND.J.T Region 2. Atlanta, Defice of the Director. 78/07/17. 2pp. 94404-223.
- --7810260064 Notice of Violation from inspec on 780526-0600.

 * Region 2, Atlanta, Office of the Director. 78/07/06. ip 74404:225.
- --7810260069 Notice of Deviation from Inspec on 780526-0602. On 780601, 52 of 57 fire brigade trained members were not certified as respiratory protection qual per NUREO-0041.

 Region 2. Atlanta, Office of the Director. 78/07/06. 1p. 94404:226.
- --7810260073 IE Inspec Repts#50-250/78-10 & #50-251/78-10 on 780526-0602 during which I item of nanompliance & I item of deviation were noted training of fire team personnel & certification of fire team personnel in respiratory protec.
 01880N.G.T. Region 2. Atlanta, Office of the Director. 78/07/06. 6pp. 94404:227.
- 7810300321 Forwards IE Circuler 78-17.
 D'REILLY-U.P. Region 2. Atlanta, Office of the Director. 78/10/13.
 1p. 94253:329.
- 7812120232 Forwards IE Inspec Repts#50-250/78-20 & 950-251/78-20 on 780905-08 & Notice of Violation. LONG, F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/17. 2pp. 94277: 206.
- --7819120235 Notice of Violation from inspec on 780905-08.

 * Region 2. Atlanta, Office of the Director. 78/10/17. ip. 94277:208.
- ---7812120237 IE Inspec Repts#50-250/78-20 & #50-251/78-20 on 780905-08 during which 2 items of noncompliance were noted: use of an failure to rev obsolete procedure for maint or surveillance. MRTIN.R.D. Region 2. Atlanta. Office of the Director. UN-MBON.A.H., WHITENER,H.L. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/17. 7pp. 94277:209.

- 7611070309 Ack receipt of IE Inspec Rept(s)#30-250/78-18.#30-291/78-18.
 on 780922-25, Does not consider any info therein to be proprietery
 UMR10.R E. Florida Power & Light Co. 78/10/23. ip 94041-146.
- --7811070314 Forwards IE Inapec Rept(a)#50-250/78-18 & 50-251/78-18 on 760822-25 during which no items of noncompliance were noted. LDNo.F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 78/09/29. 2pp. 94041-147.
- --7811070320 IE Inspec Rept(s)#80-250/78-18 & 50-251/78-18 on 780822-85 during which no items of noncompliance were noted Major areas inspected included organization & admin.followup on noncompliance.IE Builetins & circulars.reportable events. VERDERY.E.H., LEHIB.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 78/09/29. 7pp. 94041:149.
- 7811030003 Ack receipt of 780914 itr informing NRC of steps taken to correct violations noted in 16 Insp Repts 50-250/78-11 & 50-251/78-11.

 BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Brench. 78/10/24. 1p. 02720:221.
- --7811030168 Responds to 780811 NRC ltr re violations noted in Inspec Repts#50-250/78-11 & #50-251/78-11. Corrective actions. radiation controlled Area inspec every shift sealed sources being tested conteminated respirators removed UHRIO.R.E. Floride Power & Light Co 78/09/14. 5pp 02720:222.
- --781103017: Forwards IE Inspec Repts#50-250/78-11 & #50-251/78-11 on 780519-23 & Notice of Violation BUTHERLAND.J. T. Region 2, Atlanta, Fuel Facility & Hatariala Bafety Branch. 78/08/11. 2pp. 02780:227.
- --7811030175 Notice of Violation from inspec on 780617-23
 BUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials
 Bafety Branch. 78/08/11. 3pp. 02720:229
- --7811030178 IE Inspec Repts#50-250/78-11 & #50-251/78-11 on 780619-23 during which 4 items of noncompliance were noted: control of high rediation areas health physics procedures; periodic leak testinealth physics retraining program Region 2, Atlanta, Fuel Facility & Meterials Bafety Branch 78/10/24, 16pp. 02720:232.
- 78ii210i88 Responds to NRC ltr re violations noted in Inspec Repts#50-250/77-28 & #50-25i/77-28. Corrective actions: 2 thermouslis & 2 couplings were replaced & welds liquid penetrant tested.
 UHRIO.R.E. Florids Power & Light Co. 78/10/31. 2pp. 9448B:039.
- 78:11:50:03 Forwards IE Circular 78-18.

 Q'REILLY, J. P. Region 2, Atlanta, Diffice of the Director. 78/11/06.
- 7811240025 Ack receipt of IE Inspec Repte#50-250/78-19 & #50-251/78-19 on 780928-31. Does not consider any info therein to be proprietary.
 URRIO-R.E. Florida Power & Light Co. 78/11/09. 1p. 94457: 326.
- --7811240027 Forwards 1E Inspec Repts#50-250/78-19 & #50-251/78-19 on 780828-31 during which no items of noncompliance were noted. HURPHY.C.E. Region 2, Atlanta Reactor Construction & Engineering Bupport Branch. 78/10/17.
- ---7811240033 IE Inspec Repts#50-250/78-19 & #50-251/78-19 on 780828-31 during which no items of noncompliance were noted. Major areas inspected included: insvc imapec activities & records & maint & mod welding & NDE Activities & Prog.
 BLAKE.J., CONLON.T.E. Region 2, Atlants, Reactor Construction & Engineering Support Branch. 78/10/12. 6pp. 94457-329.
- 7812050240 Ack receipt of IE Inspec Rept#50-250/78-22 & #50-251/78-22 on 780912-15. Does not consider any info therein to be proprietary.
 URRIO.R.E. Florida Power & Light Co. 78/11/16 ip. 94202:046.
- --7812050242 Forwards IE Inspec Rept#50-250/78-22 & #50-251/78-22 on
- ---7812030242 Forwards IE Inspec Rept#50-230/78-22 & #50-251/78-22 on 780912-15 & Notice of Violation.
 SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/11/03. 2pp. 94202:047.
- --7812050246 Notice of Violation from inspec on 780912-15.

 Region 2, Atlanta, Fuel Facility & Materials Bafety Branch.
 78/11/03: 1p. 94202:049.

- 7812040308 Forwards IE Bulletin#78-12A, suppl to IE Bulletin 78-12. W/encl AND 7811300055 D'REILLY,J.P. Region 2. Atlanta, Office of the Director. 78/11/24. ip. 94129:160.
- 7812120236 Ack receipt of 781114 ltr informing NRC of steps taken to correct violations noted during inspec#30-250/78-20. #50-251/78-20. LDNQ.F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/12/04 1p. 94277: 202.
- ---7812120239 Responds to 781017 NRC ltr re violations noted in Inspec Repta#50-250/78-20 & 50-291/78-20 Corrective actions: work packages w/most recent info will be made & released to field & review of new Tech Specs initiated. UHRIO.R.E. Florida Power & Light Co. 78/12/04. 3pp. 94277:203.
- 7812190235 Ack receipt of IE Inspec Repts#50-250/78-25 & #50-251/78-25 on 781016-20. Does not consider any info therein to be proprietary.
 UHRTO-R.E. Florida Power & Light Co. 78/12/06. ip. 94376:001.
- --7812190238 Forwards 1E Inspec Repts#50-250/78-25 t#50-251/78-25 on 781016-20 during which no items of noncompliance were noted. LCNG-F.J. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78/11/17 2pp. 94376:002.
- --7812190243 IE Inspec Repts#50-250/78-25 & #50-251/78-25 on 781016-20 during which no items of noncompliance were noted. Major area inspected incligiblent oper after refueling, followupe of noncompliance, oper items, IE publications, emergency drills. VERDERY, E.H. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 78/11/17, 7pp. 94276-004.
- 7812210068 Ack receipt of IE Inspec ReptsM50-250/78-24 & W50-251/78-24. Does not consider any info therein to be proprietary. UHRIGAR.E. Floride Power & Light Co. 78/12/11. ip. 94269:338.
- --7812210071 Forwards IE Inspec Repts#50-250/78-24 & 50-251/78-24 on 781018-19 during which no items of noncompliance were noted. SUTHERLAND.J.T. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/11/22. 2pp. 94269:339.
- --7612210076 IE Inspec Repts#50-250/78-24 & #50-251/78-24 on 781018-19 during which no items of noncompliance were noted. Major areas inspected incl: observation of annual Emergency exercise. licensee fire drill & discussions w/personnel. HUFHAM, J. M., 01880N. G. T. Region 2, Atlanta, Fuel Facility & Heterials Safety Branch. 78/11/22 pp. 94269:341.
- 7812280328 Ack receipt of 781201 itr informing NRC of steps taken to correct violations noted during inspec#30~250/78-21 & e50-251/78-21.

 8UTHERLAND.J. T. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 78/12/19. Spp. 94082:155.
- --7812280339 Responds to 781106 NRC itr re violations noted in Inspec Repts#50-250/78-21 & #50-251/78-21. Corrective actions: respiratory protec equip training classes & health physics training classes held. URRIG.R.E. Florida Power & Light Co. 78/18/01. Spp. 94082:157.
- --7812280342 Forwards IE Inspec ReptsW50-250/78-21 & w50-251/78-21 on 780711-15 & Notice of Violation.
 SUTHERAND, J. T. Region 2, Atlants, Fue) Facility & Materials Safety Branch. 78/11/06. 2pp. 94082:162.
- --7812280348 IE Inapec Repta#50-250/78-21 & #50-251/78-21 on 780911-15 during which 3 items of noncompliance were noted issuance & use of respirators, preparation of shipments of radioactive math not in requirements & failure to lock high radiat areas CCLLINS, D. M., ZAVADOBKIR, H., G. (BBGON, A. F. Region 2, Atlanta, Dffice of the Director. 78/11/03. i3pp. 94082:i&d.
- 7813290087 Forwards IE Sulletin 78-14.

 O'REILLY, J.P. Region 2: Atlants: Office of the Director. 79/12/19.
 3pp. 03669:358

- snubbers Pailed functional tests due to control block poppet valve & relief valve malfunctions & excessive main cylinder user. Hydraulic type replaced w/mechanical type snubbers BCHOPPHAN.M.A. Florida Power & Light Co. 78/09/30. ip. 94471: 447
- 7810200093 Forwards LER#78-010/03L-0.

 BCHMIDT,A. D. Florida Power & Light Co. 78/10/11. 1p. 94140:346.
- --7810200096 LERW78-010/03L-0 on 780911: Leakage of radioactively contaminated water to paved area outside of pump room for 30 minutes: caused by spent fuel pit cooling pump mech seal failure.

 BCHOPPMAN, M. A. Florida Power & Light Co. 78/10/11. ip. 94140/347.
- 7810200114 Forwards LER#78-012/017-0.

 SCHMIDT.A.D. Florida Power & Light Co. 78/10/11. 1p. 94401:215.
- --7810200117 LER#78-012/017-0 on 780927: No Adverse affact from substitute of fuel assembly N-07 for an N-04 in cors position F-14. Cycle 5 reload 8afety Eval remains valid. SCHOPPHAN, M. A. Florida Power & Light Co. 78/10/11. ip. 74401.216.
- 7810230250 Forwards LER#78-011/03L-0. 8CHMIDT, A. D. Florida Power & Light Co. 78/10/13. ip. 94052:280.
- --7810230253 LER#78-011/03L-0 on 780920: Preventive meintenance thecks of MBIV's solenoid valves revealed defective colls. Failure of coils caused by high temp & moisture in area. Preventive maintenance re solenoid coils is planned.

 BCHOPPHAN.M.A. Florida Power & Light Co. 78/10/13. Epp. 94052:281.
- 7811060157 Forwards LER#78-013/03L-0. 8CHM1DT.A.D. Florida Power & Light Co. 78/10/27. 1p. 94489:076.
- --7811060163 LER#78-013/03L-0 on 780729: condensate storage tank held less than 183.000 gellons for about 8 hours. Caused by leaks in condensar tubes, necessitating increased stam generator blowdown. Flow demand exceeded output of treatment plant. 8CHOPPHAN.M.A. Floride Power & Light Co. 78/10/27. ip. 94489-077
- 7811080148 Forwards LERM78-014/03L-0.
 8CHMIDT.A.D. Florids Power & Light Co. 78/11/01. ip. 94399:307.
- --7811080180 LERW78-014/03L-0 on 781002: tondensate storage TenkiCST)fell to 182,000 gallons because of water demand increase for steam generator blowdown resulting from cation resin bed regeneration. CST filled after resin bed regeneration. SCHOPPMAN.H. A. Florida Power & Light Co. 78/10/02. 1p. 94399:308.
- 7812040221 Forwards LERM78-015/01T-0. 9CHMIDT, A. D. Florida Power & Light Co. 78/11/20. Ip.
- --7812040222 LERM78-015/01Y-0 on 781106: Boron Injection Tank(BIT) semple showed low Boron level, Exact cause is unknown but it is suspected the actual BIT concentration was proper & the sample was diluted & invalid.

 8CH0PPHAN, M. A. Florida Power & Light Co. 78/11/20. 3pp. 94452: 309.
- 7812050176 Forwards LERM78-010/03L-1.
 BCHM1DT.A.D. Floride Power & Light Co. 78/11/27. ip. 94335:134.
- --7812090181 LER#78-010/03L-1 on 780911: Spent fuel pit cooling pumps sech seel failed causing 150 gallons of radioactively conteminated water to lesk to paved area outside pump room caused by inadequately lubricated pump bearing.

 BCHOPPHAN.M.A. Florida Power & Light Co. 78/11/27. 1p. 94395:135.
- 7812270307 Forwards LER678-016/03L-0.

 8CHMIDT.A.D. Florida Power & Light Co. 78/12/15, 1p. 94230:345.

--7812270312 LER#78-016/03L-0 on 781115: Crack in 4A charging pump discharge piping drain line developed due to crack in a 1 inch nipple (type 316 stainless steel), which was subsequently replaced SCHOPPMAN. M. A. Floride Power & Light Co. 78/12/15. 2pp. 94230, 346.

DOCKET 50-252 UNIV. OF NEW MEXICO RESEARCH REACTOR

J. Insurance & indemnity information

7812140153 Forwards Amend#9 to Indomnity Agreement#E-47. RICHARDS.B. New Mexica, Univ. of. 78/12/06 ip. 94133:344.

--7812140157 Amend49 to Indemnity Agreement#E-47. Article III, Paragraph 4(b)(2) amended by changing amount to \$140000000 SALTEMAN, J. Antitrust & Indemnity Group. 78/12/05. ip.

DOCKET 50-254 QUAD-CITIES STATION, UNIT 1

F. Security, medical, emergency & fire protection plans

78101200B0 Forwards analysis of Elec Cable Penetration Fire Barrier Test conducted on 780619. Also forwards 3rd party observer rept of test & 5 detailed drawings associated w/test. NAUGHTON. M. F. Commonwealth Edison Co. 78/09/29. 44p. 94049: 330.

7Bi1020349 Responds to 7B0929 ltr requesting NRC agreement to respond to requests in case of offsite emergency. Under Interagency Agreement DDG Chicago Oper Ofc coordinates requests in area. KEPPLER.J. 9. Region 3. Chicago, Office of the Director. 7B/10/25. 1p. 94241:087.

--7811020375 Requests NRC assistance in event of emergency at subj facil. KALIVIANAKIS, N. Commonwealth Edison Co. 78/09/29. ip. 9424: 088.

7812120195 Informs NRC name of fire protec consulting firm hired by CEIL to fulfill requirements of "Fire Protec Organization of Nuc Plant Fire Protec Functional Responsibilities Admin Controls & QA" will be submitted 790201.

NAUCHTON.W.F. Commonweelth Edison Co. 78/11/30. 2pp. 94277:099.

Q. Adjudicatory correspondence

7811090259 Bd grants request by Citizens for a Better Environ & Naturel Resources Defense Council for permission to file response to answers opposing their petitions to intervene by 781103. MILHOLLIN. G.L. Atomic Bafety and Licensing Board Panel. 78/11/01. ip. 02761:290.

7812110284 Cancels special prehearing conference scheduled for 781215. Conference shall be held on 790111 in Tax Courtroom of UB Courthouse & Fed Bldg. Chicago. IL. Parties & petitioners must rept to Board by 781215 re progress of negotiations. MILHOLLIN. O.L. Atomic Bafety and Licensing Board Panel. 78/12/01. 2pp. 94203:243.

7810190131 Answer by CEIL to Petition to intervone filed by Atty Gen of IL on 780920 Agrees that Atty Gen has standing but asserts there are no genuine issues to be heard at hearing. Requests that Atty Gen request for EIB be denied. SYEPTOE, P. P. Isham, Lincoln & Beals. 78/10/02. 3pp.

7810300063 Natural Resources Defense Council Request for Leave to File a Response. Response is to applicant's contention reconstitutionality of forced disclosure of group's members' names in order to oper w/in state.
RDIGNAN, A. Z. Natural Resources Defense Council. 78/10/10. 4pp. 94037:177.

7810300324 NRC Staff Answers to Council for Citizens for Better Environ & Natural Resources Defense Council's Petition for Lews to Intervene. Staff apposes granting petition, w/Cert of Byc.
QDDARD, R. J. Office of the Executive Legal Director. 78/10/10. 3pp. 94253:337.

7810230124 NRC Staff's Response to Petition of TEX-LA Cooperative Inc for Leave to Intervene Staff believes Petition should be granted, LESSY, R. P. , BLUME, M. B. Office of the Executive Legal Director. 78/10/10. 9pp. 7811010063 Petition for leave to intervene & for hearing filed by citizens for Better Environ & Natural Resources Defense Council Request for leave to file response to answers opposing petition is granted.
MILHOLLIN, O. L. Atomic Safety and Licensing Board Panel. 78/10/13 ip. 94302 360.

7811130223 "Natural Resources Defense Council Response to Commonwealth Edison's & Staff's Answers to Petition for Leave to Intervenor urges Bd to establish a schedule for briefing challenges to contentions.

RDIBMAN.A. 2 Natural Resources Defense Council 78/10/23 16pp 94270: 137.

7811130216 NRC request to file response to NRDC response to Comm Ed & NRC answer to petition for leeve to intervene dtd 781023 IP granted.reply will be served by 781103 Cert of Svc encl 9DDDARD,R J. Office of the Executive Legal Director. 78/10/26 Zpp. 03354-050.

7811200070 Request by Comm Ed for leave to file a response to NRDC brief which argues that organizations may show standing to perticipate in NRC proceedings merely by alleging that they represent anonymous members. Cert of Svc encl.

8769706.P.P. Isham, Lincoln & Beals. 78/10/30. 2pp. 94218:348.

7811160021 Grants request by licensee CEIL to have until 781107 to respond to 781013 Order of ABLB permitting NRDC & Citizens for a Setter Environ to file response to answers opposing their petitions to intervene in proceedings re aubj facile. MILHOLLIN.Q.L. Atomic Sefety and Licensing Board Panel. 78/11/03 1p. 94317:090.

7811220010 NRC Steff's Response to NRDC's Response to Answers to latter's Petition for leave to intervene. NRC asserts that NRDC has not demonstrated its standing to intervene as matter of right. Cert of Svc sncl.

9DDDARD.R.U. Office of the Executive Legal Director. 78/11/03. Spp. 94273:334.

7811200003 Special Prehearing Conference in proceedings re subj facils will be held on 781215 in Rock Island, IL.All parties to proc & all petitioners to intervene must attend & should be prepared to discuss all issues.

MILHOLLIN, O. L. Atomic Safety and Licensing Board Panel. 78/11/09.

2pp. 94215:221.

7812130122 Gives notice that A Bielawski enters an appearance on behalf of applicant CEIL in proceedings re subj facils. Cert of Svc encl.

BIELAWSKI, A.P. Isham, Lincoln & Beale. 78/11/21. 2pp. 94307:188.

7812270230 Proposed stipulation re NRDC & CGE's representation of unnamed members in Dreadon-Guad Cities transshipment is not acceptable to NRC. NRC position on NRDC's position to intervene remains as stated in 781103 pleading.

GDDDARD/R. J. Office of the Executive Legal Director. 78/12/06. ip.

7812280271 Forwards"Btipulation" of NRDC.CBE & Commonwealth Edison Core identification of members of NRDC & CBE to prove they have interests that may be affected. No agreement w/Reg Staff has been reached.

RDIBMAN.A. Z. Natural Resources Defense Council, 78/12/08. ip. 94374:334.

---7812260280 Parties agree that NRDC & CBE have adequately indentified a least one member whose interest may be adversely affected by the proposed action. Auth to represent these interested members has not been agreed upon.
RUSHAN.A.Z. Natural Resources Defense Council STEPTOE.P.P. Commonwealth Edison Co. 78/12/11. 3pp. 94374:335.

7812270133 Special Prehearing Conf Scheduled for 790111 is postponed until 790201. Parties & patitions are excused from requirement to rept to 8d by 781215 re negotiations progress.

MILHOLLIN. 0. B. Atomic Bafety and Licensing Board Panel. 78/12/13. 2pp. 94161:142.

H. General correspondence

7812080138 Forwards CEIL request for amend of GL to allow spent fuel transfer & storage between facils. W/o encl.

9000ARD, R. J. Office of the Executive Legal Director. 78/11/17. Ip. 94107:356.

J. Insurance & indemnity information

- 7812190109 Requests refund of \$6 per mwt in excess indem)ty fee paid for LiceDPR-2, #DPR-19, #DPR-25, #DPR-29, #DPR-30, #DPR-39, #DPR-48.
- POOLE, R.D. Communuealth Edison Co. 78/12/13. 1p.
- P. Operating license stage documents & correspondence
- 7812080026 POIA request for all records incliquentity of radioactive math disposed of from former Manhatten proj in it known as Chicago Pileswi, 2 & 3, Math disposed of in It by Lindsay Cos at Morris facti & Dreaden facti.
 HANSELLD. Illinois, State of. 78/11/06. 2pp.
- 7812150228 Classifies lic anend for proposed fuel pool mod as Classes IV & I not Classes III & I Requires add charge of \$8300 for each of the two applits be paid with 15 days.
 MILLER.M.O. License Fee Henagement Branch. 78/12/11. 2pp. 94211-339
- 7810110030 Requests add1 fee of \$2800 re appl for amend to Facil Dper LicMDPR-29 & DPR-30 since review involves Classes I & III. single safety issue w/total fee of \$4400. MILLER.W. D. License Fee Management Branch. 78/10/02. 1p. 94053:150.
- 7810100027 Forwards evaluation of reactor protect sys pur supplies to determine whether undetected failures adversely affect the RPB sys.

 TURBAK.M.S. Commonwealth Edison Co. 78/10/04. Spp.
- 7810140112 Reevaluation of Lic amend fees for inter-station spent fuel transfer for aubj facils as requested by 780817 ltr shows that the class i & 3 fees paid for each station are correct. MILLER.H. D. License Fee Management Branch. 78/10/10. 1p. 94421:151.
- 7811240237 Forwards LER#78-010/03L-1.
 KALIVIANAKIS.N. Commonwealth Edison Co. 78/10/25, Ip. 94458:227.
- 7811020322 Request to amend Baction 6.6.8.1.0 of Append A to Tech Bacs to facil oper lic re reparting req for reactivity anomalies is w/drawn.as Rep Quide"Interpretation"by NRC on 780701 does not req rept for reactivity increase of less than 5 secs.

 REED.C. Commonwealth Edison Co. 78/10/26. 2pp.
- 7811030161 Forwards proposed Amend changing Tech Specs w/regard to updating station organizational charts. Changes have received onsite & offsite approva).
 REGD.C. Commonwealth Edison Co. 78/10/26. 9pp.
- 7811120035 Summary of 780914 meeting w/GE representatives & Mark 1 Cunsts Group to propress of Long Term Prog w/attendance list & agenda(RD-9-A-Mark), Standards.) GRIPES.C. Plent Systems Branch (Pro 791030), 78/10/26, 67pp.
- 7811140105 Responds to 780516 NRC itr requesting addition or reactor vestel metal surveillance specimen fluence valves at time of withdrawal.w/projections based on dosimetry results of previously tested capacies & 80% capacity factor.w/o encl. TURBAK.M.8. Commonwealth Edison Co. 78/11/03. 2pp. 94425:125.
- 7811140002 Notifies applicant of 781128 NRC-sponsored seminar re Model Radiological Effluent Tech Specs for Nuc Pur Plents w/encl Beminar Info Sheet(to be completed & returned by 78117) & Proposed Agenda.

 KEPPLER. J. G. Region 3, Chicago, Office of the Director. 78/11/07.
- 7811300058 Forwards Amend#39:#37.#48 & #47 for Lics DPR~19.DPR~25. DPR-19 & DPR-30 respectively. Amends revise Tech Baccs reoperating temp & pressure limits. Also forwards Bafety Eval & Fed Register Natice. IPPQLITO.T. A. Operating Reactors Brench 3 (Pre 790625). 78/11/13.
- --7811300070 Amend#48 to the Operating Lic rev Tech Specs re operating temp & pressure limits.

 IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625), 78/11/13.
 Boo.
- --7811300077 Sefety Eval Rept in support of Amend#39,#37,#48 & #47 to Oper Lice DPR-19, DPR-20, DPR-29 & DPR-30, respectively.

 * Dffice of Nuclear Reactor Regulation, Director. 78/11/13. 4pp.

- --7811300085 Notice of Issuance of Amend#39.#37.#48 & #47 to Oper Lice DPR-19.DPR-25.DPR-27 & DPR-30.respectively. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/13. App.
- 7812180044 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate tending out math. Wencl Registration Form & List of Locations.
 MILLER-J.R. Assistant Director for Site & Safeguards (Pre 791030), 78/11/15. 5pp. 94133:049.
- 7812180266 Forwards Rev81 "Dreft Radiological Effluent Tech Space" for 8WR 's (NURE9-0473) & "Preparation of Radiological Effluent Tech Space for Nuc Pur Plants" (NURE9-0133).

 9RIMES B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94365:349.
- 7812080107 Forwards rev page to Topical Rept CE-1-A: "Qual Assurance Prog. Rev. 6." Rev reflects Reg Quidel, 28 & 1.33 rev.
 TURBAK.M.S. Commonwealth Edison Co. 78/11/17. 2pp.
- 7811270170 Lic#DPR-29 Appl for amended Tech Specs to support core reload#4. W/encl plant analysis on suppl reload lic submittal. Barrier Lead Test Assamblies. & LOCA Analysis Rept for Dresden Units 24:3 & Quad Cities Units 142.
 REED. C. Commonwealth Edison Co. 78/11/20. 109pp. 94199:001.
- 7811280213 Forwards current lic status list for subj facile. REED.C. Commonwealth Edison Co. 78/11/20. 9pp.
- 7811280246 Forwards "Projected Fluence Values at Withdrawal for the Capsules Designated to Neet the Requirements of 10CFR50 Append H." Table 1 to be attached to 781103 itr to Ippolito. TURBAK-M.8. Commonwealth Edison Co. 78/11/20. 2pp. 94012:162.
- 7812060166 Informs NRC that response to 781115 NRC 1tr re lic emend appl & ownership for sub, facil will be made by Commonwealth Edison.
 MILLER.R. B. Town-Illinois Oss & Electric. 78/11/24. 1p. 94371:260.
- 7812110001 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/enc1 ANO: W7812080207. IPPOLITO.T. Operating Reactors Branch 2 (Pre 790625). 78/11/29. Bpp. 94339:089.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held % providing task-by-task activity summary for the month. 8080N.L.J. Ganeral Electric Co. 78/12/04. Jipp.
- 7812080149 Requests add1 info within 60 days re 761106 & 780821 submittals on instru setpoints.

 1PPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/12/05.
 3pp. 94104:351.
- 7812280129 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & raiculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS. J. G. Office of Inspection & Enforcement. Office of the Director. 78/12/06. App.
- 7812190097 Accepts topical rept#CE-1-A Rev#A **Comm Edison Co Quality Assurance Prog for Nuc Generating Stations. " Requests submittel of 36 copies.

 HAASB.M.P. Quality Assurance Branch. 78/12/13. 1p.
- 7812270225 Provides add1 info re gassous releases described in 781030 itr.Cause of increase in off-gas activity is believed to be fuel leakers & corrective action for high gassous activity is to maintain minimum leakage by close surveillance.
 KALIVIANAKIS.N. Commonwealth Edison Co. 78/12/13. 2pp. 94017:139.
- 7812200219 Forwards add1 info re core loading pattern for reload#4. indicating that reactor shutdown margin, loading error, & rod withdrawal ware recalculated.
 TURBAK.M.S. Commonweelth Edison Co. 78/12/15. 9pp. 94162:293.
- 78:1210367 Forwards add1 info re multiple consecutive safety/relief valve actuation of Mark I containment program.
 8080N.L.J. General Electric Co. 78/11/13. 3pp.

repaction reports. IE Bullatins & correspondence

010067 Forwards IE Inspec Repts #50-254/78-19 & #50-265/78-20 on 0713-14,780719-20,760726-27,760802-03, & 780810-11,during ich no items of noncomplaince were noted.

MELLI, Q. Region 3, Chicago, Reactor Operations Nuclear Support ench. 78/09/19. 2pp. 94290:103.

11010076 IE Inspec Repts#50-254/78-19 & #50-265/78-20 on 780713-14 780719-20, 780725-27, 780802-03, & 780810-11, during which no items of noncompliance were noted. Major areas inspected included: plant oper & out-of-avc activities.

JACKIM, I. N., KNDP, R. C. Region 3, Chicago, Office of the Director. 78097/18, 6pp. 94290:105.

OB0077 Forwards IE Inspec Repts850-254/78-20 & 850-265/78-21 on OB02-25, 29,0901 during which no items of noncompliance re-noted.

VIS.A.B. Region 3. Chicago. Fuel Facility & Materials Sefety anch. 78/10/02. 2pp. 94271:124.

110293 Ach receipt of 780901 ltr informing NRC of steps taken to frect violations noted in 780810 NRC ltr. PfLER, J. Q. Region 3, Chicago, Office of the Director. 78/10/03. P. 03556:074.

0-60120 Presents control rad drive return nazzle & feedwater nazzle spec grags to be implemented during next refueling outage, was cheduled for Jan 1979. Justification for proga is evided & also plan for mod of feedwater nazzles. RBAK.M. 8. Commonwealth Edison Co. 78/10/27. Opp.

070002 Ack receipt of 781006 itr informing NRC of steps taken to rect violations noted in 780920 Notice of Violation. NO.J.A. Region 3. Chicago, Bafeguards Branch. 78/10/27. ip. 037:072.

030011 Forwards IE Inspec Repte850-010/78-29,50-237,-254,-295,-304/-25,50-249/78-27 & 50-245/78-26 on 781002 during which no +8ms on noncompliance were noted.

PFLER, J. Q. Region 3, Chicago, Office of the Director. 78/10/30.

040033 Forwards IE Inspec Repts#50-284/78-21 & #50-265/78-22 on OB21-25, 760831, 780901, 780906-07, 780913-14, 781003-04 & tite of Deviation.

ORELL1, 9. Region 3, Chicago, Reactor Operations Nuclear Support anch. 78/10/31. 2pp. 94129: 092.

11204003B Notice of Deviation from inspec on 780821-25. * Region 3. Chicago, Office of the Director. 78/10/31. ip. 94129:09-4.

112040046 IE Inspec Repts#50-2543/78-21 & #50-265/78-22 on 780821-25 dVring which I item of deviation was noted: excessive amounts of oil stored near vital cabling smoking in No Bmoking Area. JACKIM, I.N., BROWN, C. H., KNDP, R. C. Region 3, Chicago, Office of the Director. 78/10/30. 6pp.

*O&O225 Forwards IE Inspec Repts#50-254/78-24 & 50-265/78-23 on 11004-06 during which no items of noncompliance were ited.
ITBRIAN.R.F. Region 3, Chicago, Reactor Construction & Engineering ipport Branch. 78/10/31. 2pp. 94382:174.

#12060230 IE Inspec Repts#50-254/78-24 & #50-265/78-25 on 781004-06 during which no items of noncompliance were noted Major areas inspected incl: IE Bulletins & Circular followup relative to qual of elec equip.

#WOHES.J., SPESSARD.R.L. Region 3, Chicago, Défice of the Director, 78/10/31. 6pp. 94382:176.

150063 Forwards IE Circular 78-18. PPLER, J. G. Region 3, Chicago, Office of the Director. 78/11/06.

t040020 Responds to 7B1031 NRC itr re violations noted in Inspec pts#50-254/7B-21 & #50-265/7B-22. Corrective actions:areas

7812050287 Forwards IE Bulletin#78-12A, suppl to IE Bulletin 76-12. W/encl AND:7811300055 KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 78/11/24.

7812260292 Ack receipt of 781120 ltr informing NRC of steps taken to correct violations noted in 781031 NRC ltr FIDRELLI, Q. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/12/14. 1p. 94160:045.

7812290026 Forwards IE Bulletin 78-14.
KEPPLER, J. Q. Region 3. Chicago, Office of the Director 78/12/19.

R. Periodic operating reports & related correspondence

7810250111 Monthly performance rept for Bept 1978. Includes maint summary, average daily unit pur level-refueling info request & LEP's.

* Commonwealth Edison Co. * Inwa-Illinois Gas & Electric. 78/09/30. 25pp. 94268.332.

7811220031 Forwards Monthly Operating Rept for Oct 1978
KALIVIANANIS, N. Commonwealth Edison Co. 78/11/09. 1p. 94309:010.

--7811220033 Monthly Operating Rept for Oct 1978. # Commonwealth Edison Co. 78/10/30. 30pp. 94309:011.

7812200235 Forwards Monthly Oper Rept for Aug. Sept. Oct 1970. correcting mistakes made in Aug & Bept Average Daily Unit Pur Level Rept & in the Bept & Oct Operating Data Repts.
KALIVIANAKIB, N. Commonwealth Edison Co. 78/11/28. ip 94162:325

--7812200241 Monthly Oper Rept for Aug. Sept.Oct 1978. Corrections are circled in red.
HANNUM.D. Commonwealth Edison Co. 78/11/08. App. 94162: 326.

7812200188 Monthly Oper Rept for Nov 1978.

Towa-Illinois Gas & Electric. 78/11/30. 26pp. 94145:314.

S. Reportable occurrences, LERs & related correspondence

7810170232 Forwards LERW78-027/03L-0.
KALIVIANAKIB, N. Commonwealth Edison Co. 78/10/05. ip. 94236:312.

--7810170235 LERW78-027/03L-0 on 780928: Unit One dissel fuel transfer lines 1-3201 & 1-3204 were taken out of svc at 4:55s.m.
780928 to replace 2 sections of piping. Bys returned to svc same day.
VAHRENHALD, J. Commonwealth Edison Co. 78/10/05. 2pp. 94236:313.

7811240175 Forwards LER#78-026/03L-0.
KALIVIANAKIB.N. Commonwealth Edison Co. 78/10/19. ip. 94458:268.

--7811240177 LER#78-026/03L-0 on 780920: "A" RHR room watertight door found open. Caused by contractor personnel ignorance. . Personnel admonished to heed procedures at all 1 times. KCDI.M. Commonwealth Edison Co. 78/10/19. 2pp. 94458: 269.

7811240240 LER#78-010/03L-1 on 780420: during routine Hydraulic Shubber Surveillance Inspec, Shubber Mark 149 was found inoper due to empty fluid reservior & Mark 144 was found w/missing cotter pin.dus to component failure.

VANKENMALD.J. Commonwealth Edison Co. 78/10/25. 3pp. 94458.228.

7811240179 Forwards LER#78-020/03L-0.
KALIVIANAKIS.N. Commonwealth Edison Co. 78/10/27. 1p. 94458:275.

--7811240181 LERA78-028/03L-0 on 780929: the A BJAE off gas log radiat monitor failed downscale. Caused by component failure: the A radiat monitor high votage pur supply capacitors were not in proper contect w/monitor chassis.

MRRAY-R. Commonwealth Edison Co. 78/10/17. 2pp. 94458: 276.

781107011B Notifies NRC that average release rate for radioactive matls w/half-lives greater than B days between 780701 & 780930 was 2.03 times Tach Spec 3.8.9.3.C(l)design objective. Eval of elevated main chimney release rate has started.

KALIVIANAKIS.N. Commonwealth Edison Co. 78/10/30 2pp. 94043:319.

- 0- 2011148

7812110191 Forwards LER#78-029/03L-0.

- --7812110183 LER#78-029/03L-0 on 7B1025; smoke detectors were removed from svc in cable spreading room, elec equip room & control room for installation of new fire detection/suppression sys.
 REED.M. Commonwealth Edison Co. 78/11/15. 1p 94337:105.
- 7812110176 Forwards LER#78-030/03L-0.
 KALIVIANAKIS.N. Commonwealth Edison Co. 78/11/21. 1p. 94337:096.
- --7812110178 LER#78-030/03L-0 on 781026: dual position indication was received for supression chember to druwell vacuum breaker, valveH-1601-33E. Caused by position indication problem. CLARM.D. Commonwealth Edison Co. 78/11/20. 1p. 94337:097.
- DOCKET 50-255 PALISADES NUCLEAR PLANT
 F. Security, medical, emergency & fire protection plans
- 7812130161 Forwards new security plans for subj facils as requested by NRC.Plans withheld (ref 10CFR2.790).
 HOFFMAN, D. P. Consumers Power Co. 78/12/08. 1p. 94305:120.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7812270146 Forwards rev page 8-18 of Section8 of subj facil FBAR. Change consists of changing and supply from motor control centers it 2 to Motor Control Centers it 3 having only 1 MCC automatically supplied by emergency generator. FGOO.H.O. Consumers FDuer Co. 78/12/21. 2pp. 94139:148.
- P. Operating license stage documents & correspondence
- 7810110030 Requests addl fee of \$2800 re appl for ement to Facil Oper LiceDPR-29 & DPR-30 since review involves Classes I & III, single safety issue witotal fee of \$4400. MILLER.W. O. License Fee Management Branch. 78/10/02. 1p. 94063:150
- 7812110011 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purping or justification for continuing Wenc1 ANG: 47812080207.
 ZERMANN D. L. Operating Reactors Branch 2 (Pre 790625). 78/11/29. 8pp. 94339:237.
- 7810110111 Clarifies interpretation of Tech Byec 3.1.1a. stating that one primary coolant pump shall be in oper whenever a reduction in primary coolant sys boron concentration is being made.

 HOFFMAN, D. P. Consumers Power Co. 78/10/04, ip. 94066:357.
- 7810190218 Forwards electric diagrams umitted from 780808 package 8et of apartura cards advanced directly to R Silver. HOFFMAN. D. P. Consumers Power Co. 78/10/10. 1p. 94415:191.
- 7810310027 Informs that for SEP normal channel of oral communication will be followed, but to expedite reviews direct oral communication between subj facil staff & members of BEP branch is encouraged.

 ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/10.

 ZPP. 94094:347.
- 7810160097 Informs of delay in providing NRC w/info re anviron qualification of safety-related equip due to slow review of tables presented.

 BIXEL.D.A Consumers Power Co. 78/10/11, ip. 94004:221.
- 7810270278 Forwards Amend #44 to Provisional Operating Lic #DPR-20. Amend auth deletion of requirement to perform washly monitoring of fish impingment on intake braveling screens. 21EFANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/16. 3pp. 94030:287.
- --7810270286 Amend #44 to Provisional Lic #DPR-20, deleting requirement to perform weekly monitoring of fish impingement on intake traveling screens.

 ZIEMANN, D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/16. 4pp. 94030;290.
- --7810270293 Notice of Issuance of Amend #44 to Provisional Oper Lic #DPR-20, suth deletion of requirement to perform weekly monitoring of fish impingement on intake traveling screens ILEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/16. 28p. 94030:294
- 7810270075 Responds to 780817 NRC ltr requesting review of initial eval

- 7811130047 Requests add1 info re ESF switchover from impetion to recirculation mode.isolation of reactor safety protec sys from non-safety sys & engr safety features. (EBF) sys logic & design.

 ZIEMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/10/26.
 3pp. 94010:231.
- 7811130167 Notifies applicant of 781128 NRC-sponsored seminer re Hodel Radiological Effluent Tech Specs for Nuc Pur Plants. Encl w/Beniner Info Sheet(to be completed & returned by 781117) & Proposed Agenda.

 KEPPLER, J. O. Ragion 3, Chicago, Office of the Director. 78/11/07. dpp. 03353:215.
- 7812180035 Notice of workshops re implementation of training & qual requirements contained in Append 8 of IOCPR73. Requests pre-workshop registration of attendes to facilitate sending out math. Wiencl Registration Form & List of Locations.

 MILLER. J. R. Assistant Director for Bite & Sefeguards (Pre 791030). 78/11/15. 5pp. 94133:024.
- 7812190017 Forwards Rev#1 "Dreft Radiological Effluent Tech Specs" for PWR's (NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133).

 GRIMES, B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94214:292.
- 7812050303 Notification of 761207 meeting w/BEP Owner's Group in Bethesda, HD to discuss plans to address seismic input for use in BEP seismic review. LEVIN.H.A. Bystematic Evaluation Programs Branch (Pre 790525). 78/11/24. 2pp.
- 7812040164 Forwards 781026 Notice of Noncompliance & Order to comply from HI Water Resources Comm. & 781116 util reply. Effluent in violation: oil & grease.
 HOFFHAN, D. P. Consumers Power Co. 78/11/27. 5pp. 94456:164.
- 7812030119 Porwards completed tabulation of environ qual of safetyrelated elec equip requested by NRC on 780906. Btates that equip addressed must ensure safe shutdown of plant during LOCA & main steam line break. HOFFNAN.D.P. Consumers Power Cq. 78/11/30. 97pp. 94930:291.
- 7812120100 Presents justification for installation & use of high density spent fuel storage racks. Includes responses to 780613 NRC request for addl info. Concludes that tests demonstrate structure adequacy of 84C met1.

 HDFFMAN, D. P. Consumers Power Co. 78/12/04. 19pp. 94275:001.
- 78:2140343 Determines that 78:002 emergency pur sys mods will req staff review & approval. Since review involves a single safety issue it is subj to a 64,000 Class III fee.
 MILLER.M. O. License Fee Management Branch. 78/12/04. ip. 03557:167.
- 7812280118 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J. 0. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94310:213.
- 7812120182 Informs NRC of filter testing condition in respiratory protect equip which is different from regulation in Reg Guide 8.15. but which meets the regulatory requirements.

 BIXELID.A. Consumers Power Co. 78/12/08. ip. 94277:082.
- 7812150085 Requests add1 info from SEP licensess re electrical penetrations of reactor containments to complete evaluation. ZIEMANN,D.L. Operating Reactors Branch R (Pre 790625). 78/12/08. 4pp. 94211:339.
- 7812210091 Forwards NURE9-0485, Vol 1.No 2 "Status Summary Rept-Sys Eval Prog." W/o sncl. ZIEMANN, D. L. Operating Reactors Brench 2 (Pre 790625). 78/12/08. 2pp. 94269:134.
- 7812050013 Requests views of Regional Directors on Licenses performance eval of subj facils Forwards questions to be answered by 771209.

 THORNBURG. H. Division of Reactor Construction Inspection. 77/11/23.
- 7819270147 Requests info re positive displacement charging pump vibration levels & discharge pressure pulsations to complete review.
 21EMANN.D.L. Operating Reactors Branch 2 (Pre 790625). 78/12/14.
 3pp. 94018:053.

- tee. Changes involve nuc steam supply sys & Puel assembly lesign.
 IDEPMAN D. P. Consumers Power Co. 78/12/18. 33pp. 94160:140.
- (2270174 Clarifies Tech Spec 3.1.14 re boron dilution in order to take it consistent w/subj Facil Standard Tech Specs. (OFFMAN, D. P. Consumers Power Co. 78/12/21. 1p. 94018:095.
- 12280134 Responds to 781208 request for add1 info re 86P Topic VIII-4 'Electrical Penetrations of Reactor Containments." Requires :abulation of info selected by NRC in docket search by early Jan to prepare reply within schedule.
 31XEL, D.A. Consumers Power Co. 78/12/22. ip. 94310:339.
- Inspection reports. IE Bulletins & correspondence
- 12120212 Forwards IE Inspec Rept#50-255/78-05 on 780111-13.18-20, 24-27.31 t 780201-03.16-17 during which 5 items of Toncorpliance were noted. Inspec Rept withheld [ref 100FR2.790].

 **EPPLER.J. 0. Region 3. Chicago, Office of the Director. 78/04/27. 3pp. 94276:067.
- 12040172 Ack receipt of 780512 ltr informing NRC of steps taken to correct violations noted during inspec450-255/78-05. **EPPLER, J. Q. Region 3. Chicago, Office of the Director. 78/06/12. **2pp. 94456: 228.
- 7812040174 Responds to 780421 NRC ltr & submits attachment w/ request that it be withheld pursuant to 2.790. YGUNDOAML.R. C. Consumers Power Co. 78/05/12. 1p. 94456:230.
- 7812040178 Responds to 780421 NRC ltr re violations noted in Inspec Repte30-235/78-05. Attachment withheld from pub disclosure pursuant to 2.790. BIXELD.A. Consumers Pawer Co. 78/05/12. ip. 94456:231.
- 11300314 Forwards IE Inspec Rept#50-255/78-17 on 780724-28.780730. 780801-03 & 780814-18 during which no Items of noncompliance were noted. FIORELLI.9. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/09/29. 2pp. 94136:358.
- 7811300318 IE Inspec Rept #50-255/78-17 on 780724-28,780730,780801-03 & 780814-18 during which no itmss of noncompilance were noted. Major areas inspected inclingar, reportable events, records, review & audit procedures & safety injection sys oper. HANTER, D. R., JORGENSEN, B. L. Region 3, Chicago, Office of the Director, 78/09/29, 17pp. 94137:001
- 110110186 Ack receipt of 780908 ltr informing NRC of steps taken to correct violations noted in 780818 NRC ltr.
 MIND.J.A. Region 3, Chicago, Bafeguards Branch. 78/10/02. ip. 94087:130.
- 110130195 Ack receipt of 780905 ltr in response to Inspec Rept#50-255/ 76-16. Clarifies NRC position on 5 items of noncompliance objected to by licensee. Also requests that mgt control of radiat sefety prop be addressed by future response. KEPPLERIJ. 0. Region 3. Chicago. Office of the Director. 78/10/05. 4ms. 94002:130.
- 11 1090298 Forwards IE Inspec Repts#50-255/78-20 on 780828-31 & 780907-08 during which no items of noncompliance were noted. DAVIS.4.8. Region 3. Chicago. Fuel Facility & Materials Sefety Branch. 78/10/05. 2pp. 02762:345.
- -7811090303 IE Inspec Repte50-255/78-20 on 780828-31 % 780907-08 during which no items of noncompliance were noted Major areas inspected incl:Emergency Plan procedure, examination of facil & samples, OREER, V. Region 3, Chicago, Office of the Director, 78/10/05, Bpp. 02762; 347.
- 911900225 Forwards IE Inspec Rept#50-255/76-05 during Jan-Feb 1976 & Notice of Violation. W/encl ANGE7811300177.
 KEPPLER, J. G. Region J. Chicago. Office of the Director. 78/10/06.
 2ps. 94027:124.
- 910230334 Forwards 1E Circular#78-17. (See AND: 7810030221, Docket 50-313,781013)
 MEPPLER, J. G. Region 3, Chicago, Office of the Director. 78/10/13.
 1p. 94194:305.

- Qen Office Health Physice group in procedure dev & training. ALARA review group. HDFFMAN.D.P. Consumers Power Co. 78/10/27 2pp. 94218.355.
- 7811300349 Forwards IE Inspec Rept#50-255/78-22 on 780925 & Notice of Violation. FIORELLI, 9 Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/27. 2pp. 94116:219
- --7811300350 Notice of Violation from inspec on 780925-29.

 * Region 3, Chicago, Office of the Director. 78/10/27. 1p.
- --7811300354 IE Inspec Rept#50-255/78-22 on 780925-29 during which i ite of noncompliance was noted: feilure to complete appropriete admin review. Noncompliance w/Tech Specs 6 8.1.
 HUNTER, D. R., JORGENBEN, B. L. Region 3, Chicago, Office of the Director. 78/10/26. Spp. 94116:222.
- 7812010124 Farwards IE Inspec Rept#50-255/78-23 on 781002-04 & Natice of Violation.
 FIORELITY. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/27. 2pp. 94418-048.
- --7812010126 Notice of Violation from inspec on 781002-06. * Region 3, Chicago: Office of the Director. 78/10/27 ip. 74418:030.
- --7812010129 IE Inspec Rept#50-255/78-23 on 781002-06 during which 2 items of noncomliance were noted: Pailure to follow procedures & Failure to implement an acceptable insectesting prog for pumps.

 REYES.L.A., STREETER-U.F. Region 3- Chicago, Opplies of the Director. 78/10/27. Spp. 94418:051.
- 7811150051 Forwards IE Circular 78-18.
 KEPPLER.J. G. Region 3. Chicago, Dépice of the Director. 78/11/06
 1p. 94112 163.
- 7811210437 Ack receipt of 781027 ltr responding to item of concern in 781005 ltr Will examine action during future inspec.

 KEPPLER, J. Q. Region 3. Chicago. Office of the Director. 78/11/14 ip. 03538:362.
- 7B12060022 Notifies that installation of evacuation sirens in new svc bldg addition per IE Inspec#50-255/7B-20 req more work than anticipated & will be completed by 790115 HOFFMAN,D.P. Consumers Power Co. 78/11/14. 1p. 94415:335.
- 7819200299 Forwards IE Inspec Rept#50-255/78-21 on 780921-22 & 0926-29 & Notice of Violation. DAVIB.A.B. Region 3. Chicago. Fuel Facility & Materials Bafety Brench. 78/11/15. Spp. 94206:307.
- --7812200302 IE Inspec Rept#30-255/78-21 on 780721-22 during which 2 items of noncompliance were noted: Failure of seffluent control instrumentation to reported oversiposure of employee. HUETER.L.J., FIGHER.W.L. Region 3. Chicago. Office of the Director. 78/11/14. 11pp. 94206:310.
- 7812060024 Responds to 781027 NRC itr re violation noted in Inspec Rept#50-253/78-22. Check w/personnel showed maint activity had been correctly done. Admin procedures will be rev. HOFFMAN. D. P. Consumers Power Co. 78/11/16. 2pp. 94415: 337.
- 7812060361 Responds to 780521 NRC 1tr re violations noted in inspec Rep #850-235/78-23. Corrective actions: flow transmitter repaired & recalibrated tagging proc rev to repair instru prior to testing. HOFFMAN.D.P. Consumers Power Co. 78/11/16. 3pp. 94382:317.
- 7811300114 Forwards IE Inspec Rept#50-255/78-05 on 780111-13, 18-20-24-27, 780131-780203 & 780216-17.
 KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/11/20.
 1p. 94078: 324.
- --7811300117 IE Inspec Rept#50-255/78-05 on 780111-13,780118-20,780124-27.780131-780203 & 780216-17 during which 5 items of noncompliance were nuted; physical security organization, access requirements, access controls & testing & maint. CARLBON, D. M., MADEDA, T. J., NDRELIUB, C. E. Region 3, Chicago, Office of the Director. 78/11/20. 17pp. 74072:325.

- 7812290059 Forwards IE Inspec Rept #50-255/78-24 on 781016-18 during which no items of moncompliance were noted DAVIS.A B Region D. Chicego. Fuel Facility & Materials Safety Branch. 78/11/21 2pp. 94190.033
- 7812290063 IE Inspec Rept #30-255/78-24 on 781016-18 during which no item of noncompliance were noted Major areas inspected incl confirmatory measurements prog.

 OREER. J. JANUSKA.A. G. ESSIO.T. H. Region D. Chicago, Fuel Facility & Materials Safety Branch 78/11/21 3pp 94190:035
- 7812050314 Forwards IE Builetin#78-12A.suppl to IE Builetin 78-12 W/encl AND.7811300055 KEPPLER.J G Region 3. Chicago. Diffice of the Director. 78/11/24. 1p 94393 195
- 7812290017 Forwards IE Inspec Rept#50-255/78-26 on 781024-25 & Notice of Violation FioRELLI, G. Region G. Chicago, Reactor Operations Nuclear Support Branch. 78/11/24 2pp. 94207.341
- --7812270020 Notice of Violation from inspec on 781024-25.

 * Region 3. Chicago, Diffice of the Director. 78/11/24. Ip 9407.343
- --7812290025 IE Inspec Rept#50-253/78-26 on 781024-25 during which I item of noncompliance was noted: failure to adhere to procedures for training & documentation LITTLE.W.S., SWANSON.E.R. Region 3, Chicago, Reactor Operations Nuclear Support Branch 78/11/20 4pp. 94207.344
- 7812150202 Notification of meeting w/CPC on 781220 in Jackson MI to discuss recent inspec conducted by Performance Appraisal Team at Corp Office & nuc plant.
 KEPPLEN, J G Region 3, Chicago, Office of the Director. 78/12/07.
 1p. 94212 323
- 7812260293 Ack receipt of 781116 itr informing NRC of steps taken to correct violations noted in 781027 NRC ltr. FIDRELLI, G Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/12/14 ip 94160:048.
- 7812260314 Act receipt of 781114 ltr re 2 month delay in installation of evacuation sirens in the new svc bldg.Compliance u/this commitment will be reviewed during future inspec DAVIS.A B Region 3. Chicago, Fuel Facility & Materials Befety Branch. 78/12/14 ip. 94160.097
- 7812280059 Forwards IE Bulletin 78-14 KEPPLER.J. O. Region J. Chicago. Office of the Director 78/12/19. 1P. 03554 348
- R. Periodic operating reports & related correspondence
- 7810110119 Forwards Monthly Open Rept for Sept 1978 ADAMS.W E Consumers Power Co 78/10/04, 1p 94067:336.
- --7810110122 Monthly Oper Rept for Sept 1978.
 BCLLNOW, D. T. Consumers Power Co. 78/10/04. 4pp. 94067:337.
- 7810190203 Forwards annual NPDES compliance eval inspec rept 6td 780912.
 MDFFMAN.D.P. Consumers Power Co. 78/10/04. ip. 94168:173.
- --7810190237 Forwards compliance eval rept conducted 780817 Found subj facil to be in compliance u/conditions of NPDE9 Permit MI 0001457. PRZYBYSZ-R. Michigan, State of. 78/09/12. lp. 94414:215
- --7810190240 Annual NPDE8 compliance evaluation insp rept Facil found to be in compliance PRZYBY9Z.R Michigan, State of. 78/08/23. 9pp. 94168:175.
- 7810130137 Furnishes long term cooling equip mod & bimonthly status rept.

 HOFFPIAN D. P. Consumers Power Co. 78/10/10. 1p. 94003:168.
- 7811140147 Forwards Monthly Open Rept for Oct 1978, ADAMS: W.E. Consumers Power Co. 78/11/08, 1p. 94383: 269.
- --7811140148 Monthly Oper Rept for Oct 1978. BOLLNOW, D. I. Consumers Power Co. 78/11/03. 4pp. 94382:270.
- 7811800112 Long Term Equip Mod Bimonthly Status Rept for Sept-Oct 1978. M/encl. MGFTMAN.D.P. Consumers Power Co. 78/11/15. 1p. 94220:230.

- 7812110122 Forwards Montly Open Rept for Nov 1978 ADAMS, N.E. Consumers Power Co. 78/12/04 1p 94339 313
- --7812110125 Monthly Oper Rept for Nov 1978 BOLLNOW, D. I. Consumers Power Co. 78/12/04 4pp. 94339.314
- 8 Reportable occurrences. LERs & related correspondence
- 7810170244 Forwards LER#77-045/01X-2 HOFFMAN, D.P. Consumers Power Co 78/09/29 1p 94236 329.
- --7B10170248 LERW77-045/01X-2 on 780916 initial valve design did not consider failure of T-ring air supplies, which could result in loss of containment integrity. Backup air supplies were installed & retested Aug '78 & are now acceptable e Consumers Power Co. 7B/09/29. ip. 94236:330.
- 7810100015 Forwards LERM78-031/01T-0 HOFFMAN.D P Consumers Power Co. 78/10/02 Ip 94415 171.
- --7810100019 LERM78-031/01T-0 on 780917: During routine plant oper CRDM-could not be withdrawn In order to prevent rod misalignment rod insertion was blocked by removing CRDM control fuses Caused by shorting of motor windings from water * Cansumers Power Co. 78/10/02 Ip.
- 7811210353 Confirms reportable occurrence. Chemistry samples taken from safety injection tanks 8 % D on 781015 % 781019 respectively showed boron concentration of each tank to be below Toch Spec limits
 LEWIS, J. O., PETITJEAN, H. R. Consumers Power Co. 78/10/25 1p 94484: 341
- 7811210418 Reportable Occurrence:on 781025-26, during Tech Spec Test, enubbers 5 & 28 of Tech Spec Table 3.20.1 were found inoper. LEWIS.J.Q., PETITJEAN, H.R. Consumers Power Co. 78/10/27 1p. 94482:150.
- 7811070210 Forwards LERM78-032/01T-0. HOFFMAN, D.P. Consumers Power Co. 78/11/02. tp. 94039.112.
- --7811070218 LERN78-032/017-0 on 781019 during monthly sampling of 81 tanks the boron concentrations in tanks 0 & D were 1703 & 1655 ppm, respectively, Caused by dilution of 81 tank contents from water left in shutdown cooling lines after shutdown & Consumers Power Co. 78/11/02. 1p. 94039 113
- 7811070183 Forward's LERM78-033/011-0.
 HOFFMAN, D. P. Consumers Power Co. 78/11/03 lp. 94044.185
- --7811070206 LERM78-033/01T-0 on 781025: leakage of waste gas decay tank
 T-688.w/xe-133 the predominant nuclide thru leaking tank
 relief valve from elevated pressure. Caused by faulty
 pressure instru.
 * Consumers Power Co. 78/11/03 1p. 94044:186
- 7811140223 Forwards LERM78-034/01T-0 HDFFMAN, D. P.—Consumers Power Cd. 78/11/09. 1p. 94400.057.
- --7811140228 LERW7B-034/01T-0 on 781026 during surveillance of safetyrelated shock suppressors, enubbers 85 & 828 found inoper. Caused by oil leakage past failed O-ring in both snubbers. O-ring failure due to age & high temp conditions. * Consumers Power Co. 78/11/09. ip. 94400.058.
- 7811210330 Forwards LERM78-035/03L-0 & #78-036/03L-0. HDFFMAN,D P. Consumers Power Co. 78/11/16 1p. 94484.316.
- --7811210335 LER#78-035/03L-0 on 781020: channel D pressure instrupt-0102D found to be out of calibr Caused by zero shift. Calibr frequency changed from annually to semi-annually.
 * Consumers Power Co. 78/11/16 jp. 94489
- --7811210337 LERM78-036/03L-0 on 781021: during monthly surveillance, ho station found to have 50 foot hose rather than req 75 foot hose. Hose normally stored in that station had apparently been replaced.

 * Consumers Power Co. 78/11/16. 1p. 94489-312.
- 7812050167 Forwards LER#78-037/03L-0. HDFPMAN.D.P Consumers Power Co. 78/11/30. 1p. 94335:118.
- --7812050175 LER#78-037/03L-0 on 781031: during oper, deisal generator#iwas taken out of svc for repair of pre-lube oil pump, during which time charging pump P-55c was also taken out of svc. due to leaking seals. Event is under review. # Consumers Pawer Co. 78/11/30 lp. 94335:119.

7812110206 Forwards LERH78-038/03L-0 HOFFMAN, D.P. Consumers Power Co. 78/12/06 1p. 94337:331

--7812110210 LER#78-038/03L-0 on 781106 during constr activities,2 elec penetration fire barriers opened to permit cable routing w/o fire tour being established Caused by failure of contractor personnel to comply w/plant procedures * Consumers Power Co 78/12/06 ip. 94337 332

7812120095 Forwards LER 78-039/03L-0 HOFFMAN, D. P. Consumers Power Co. 78/12/07 1p. 94274.225.

--7812120097 LER 78-039/03L-0 on 781110 during normal operation steam generator pH & conductivity exceeded Tech Spec steady-state limits Caused by inadvertent addition of morpholine to condensate sys thru leaking drain valve.

• Consumers Power Co. 78/12/07. 1p. 94274:226

7812150261 Forwards LERW78-040/01T-0 HOFFMAN, D. P. Consumers Power Co. 78/12/12 1p. 74213-057.

--7812:30265 [ERM78-040/01T-0 on 78112B volume control tank venting to leating waste gas surge tank resulted in gaseous release Cause under investigation.

+ Consumers Power Co. 78/12/12 1p. 94213.058.

7812220106 Forwards LER#78-037/03X-1 HUFFMAN. D. P. Consumers Power Co. 78/12/14. 1p. 74343-358

--7812220107 LER#78-037/03X-1 on 781031: with diesel generator#1-2 out of syc.pur supply for alternate changing pumps was shifted to D/0 1-1 before charging pump P-55c was removed from syc. Caused by personnel error.

* Consumers Power Co. 78/12/14. ip. 94343:359.

7612210230 Forwards LER#78-040/01X-1. KOFPMAN.D.P Consumers Power Co. 78/12/18. 1p. 94279.161.

--7812210232 LER#78-040/01X-1 on 781128:during venting of control tank.

leakage from surge tank resulted in gaseous release w/out 15
day holdup time required by Tech Specs Cause is still under

eram updated rept will be submitted by 790105

Consumers Pawer Co 78/12/18 ip. 94279:162.

7812290202 Forwards LER#78-041/01T-01.
HDFFMAN.D P Consumers Power Co. 78/12/26 1p 94190.338.

--7812290207 LER #78-041/017-01 on 781214: insufficient HP91 flow would reach core during postulated LOCA due to redundant HP91 header being valved out of svc because of HP91 pump NP9H considerations. Mod is being considered.

* Consumers Power Co. 78/12/26. 2pp. 94190:339.

BOCKET 50-259 BROWNS FERRY NUCLEAR POWER STATION. UNIT 1

7811280187 Forwards LER878-033/03L-0. F0%:H. 8 Tennessee Vallay Authority, 78/11/21. 1p. 94013:224.

F. Beturity, medical, emergency & fire protection plans

7810310074 Forwards rev to copies 5 thru 10 of subj facil security plan std 780926. Revs reflect latest changes in proposed security sys & procedures. Revs are proprietery (ref 100FR2. 790). QILLELAND, J.E. Tennessee Valley Authority. 78/10/25. 79pp. 94094:315.

7811200200 Forwards reva to Physical Security Plan of subj facils re installation of emergency lighting fixtures Requests withholding from pub disclosure per 100FR2 790. GILLELAND, J. E. Tennessee Valley Authority. 78/11/15. ip. 94232:036

G. Adjudicatory correspondence

7812260057 Motion of MN Pollution Control Agency is granted & licensee is ordered to ceese & desist from further installation of any spent fuel storage rack at subj facil pending further order.

order.

* Atomic Safety and Licensing Board Panel. 78/12/15. Opp.

H. General correspondence

7812210336 Comments on 780927 constituent ltr to Legomarsino revalidity of the Reactor Bafety Study, the subject of fire, & the Operating performance of commercial nucleur plants ODSBICK, L V Office of the Executive Director for Operations 78/12/12 13pp 94014, 305.

J Insurance & indemnity information

7811090096 Advance premium & standard premium endorsement for 1978 BARDES.C R Nuclear Energy Liability Insurance Association 78/10/11 ip. 94042 | 141.

7812010236 Forwards PolicyMMF-66. Endorsement#37 for subj facil States advance premium \$94768.89, reserve premium \$71349.36 & return premium \$3123 17.
F16DLER.J Nuclear Insurance Consultants. 78/11/28. 2pp.

K Utility Final Safety Analysis Report (FBAR) & amends

7812200244 Forwards Amend#67 which rev FBAR to reflect current plant configuration Amend does not req review & is available in PDR OLLELAND, J.E. Tennessee Valley Authority. 78/11/30 2pp. 94159: 001

--7812200246 Amend#67 to F8AR, Vols 1-7. This amend does not req review it merely rev F8AR to reflect current plant configuration Tennessee Valley Authority 78/11/30. 2900pp.

P Operating license stage documents & correspondence

7811200080 Requests add1 info for review of recirculation pump trip for the to mitigate Anticipated Transient w/o Screen Info due w/in 60 days
LEAR. 0 Operating Reactors Branch 3 (Pre 790623) 78/05/13 3pp. 94217: 360.

7812110245 Responds to 780928 request for amend to License DPR-33 to permit operation at greater power levels. Class III fee is applicable & should be submitted MILLER.W D. License Fee Management Branch. 78/11/30. 1p. 94337-248

7810200131 Notice of issuance of Amend#40 to Facil Operating Lic# DPR-33.Amend#38 to Facil Operating Lic#DPR-32 & Amend#14 to Facil Operating Lic#DPR-40.rev Tech Bpaces for ager of subj facils.Amends lower low water level satpoint IPPQLITO.T A. Operating Reactors Branch 3 (Pre 790625). 78/08/02. 2pp. 94411-287.

7810130200 Forwards Amend#43 to DPR-33 Bafety Evaluation Rept & Notic of Issuence IPPOLITO.T.A Operating Reactors Branch 3 (Pre 790625) 78/09/29. 2pp. 94079:261

--7810130202 Amend#43 to Lic#DPR-33imod conditions for open & surveillance equip.
IPPOLITO.T.A. Openating Reactors Branch 3 (Pre 790625) 78/09/2
2pp. 94079-263.

--7810130203 Safety Evaluation Rept supporting Amend#43 to Lic#DPR-93 covering pump seizure accident.inadvertent Cold Loop Startup Transiant & monitoring of safety margins for 1 loop oper.

* Operating Reactors Branch 3 (Pre 790623). 78/09/29. 4pp. 94079.268.

--7810130210 Notice of Issuance of Amend to Facil Oper Lic*DPR-33 to permit oper at maximum of 50% lic pur level w/i recirculation loop isolated.

IPPOLITG.T A. Operating Reactors Branch 3 (Pre 790625). 78/09/2 2pp. 94079:272

7810140035 Notice of Issuence of Amend#43 to Facil Oper Lic# DPR-33 on 780929 re 82% lic pur level w/ one recirculation loop isolated.

IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790425). 78/09/29.

2pp. 94329:063.
7810110107 Responds to 780829 ltr indicating there have been no

incidents of control rods failing to fully insert on demand at sub; facils. GILLELAND, J.E. Tennessee Valley Authority. 78/10/05. Ip. 94066:353

- 7810120065 Forwards replacement pages of proposed Tech Bpec changes & of justification for the proposed changes. NEDO-24136. correcting typographical arrors of amend request submitted 780908 OILLELAND, J.E. Tennessee Valley Authority. 78/10/05. 9pp.
- 94421.184.
- 7810200244 Forwards responses to verbal questions re proposed changes to Tech Specs of subj facil as submitted 780322.

 OILLELAND. J E Tennessee Valley Authority. 78/10/10. 699. 94170 242
- 7810240153 Forwards add1 info re proposed differential pressure control & torus water level Yech Specs for subj facils.
 OILLELAND, J. E. Yennesses Velley Authority 78/10/18. 3pp.
- 7810240144 In response to 780807 ltr to N.B. Hughes, the recommended surveillance of reactor protec sqs will continue Request response date extension to 781219.
 GILLELAND, J. E. Tennessee Valley Authority. 78/10/19. ip.
- 7811130335 Summary of 780914 meeting w/GE representatives & Mark I Owners Oroup re progress of Long Term Prog w/attendance list & agenda(RD-9-A-Markl.Standards.) ORIMES.C. Plant Systems Branch (Pre 791030). 78/10/26. 67pp.
- 7811200406 Forwards results of measurements of radioactive mat1 in NRC phentom on whole body counter Enci I contains actual amount of each radionuclide present enci 2 gives ratio of measurements to DOE values & enci 2 gives recommendations. SUTHERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/11/09. Spp. 94419:305.
- 7811210288 Notifies util of 781205 seminar in Atlanta to discuss new Madel Rod Effluent Tech Spece & encl seminar info sheet, registration form & proposed agenda O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/09. 5pp. 94485:212.
- 7811170113 Reports that NRC will assist Los Alamos Scientific Lab team in performing vitel area enalysis at subj facil during the week of 781126.

 GILLELAND, J. E. Tennessee Valley Authority. 78/11/13. 1p. OTLLELAND, J. E. 94047: 145
- 7811170175 Requests that NRC review indemnity fee invoice#23-79 & #27-79.dtd 781024.which appears to be incorrect & rebill GILLELAND, J. E. Tennessee Velley Authority. 78/11/13. 1p. 94136:029
- 7811170215 Responds to NRC questions prompted by Gilleland's 780811 1tr requesting Tech Spec changes. Change ensures reconfiguration of SRM's & IRM's & will be placed in non-coincidence trip onde HILLS.L. M. Tennessee Valley Authority. 78/11/13. 1p. 94136:122.
- 7811280361 Licensee's supporting documentation for approval of Recirculation Pump Trip(RPT) for reactor protec sys fails to address most criteria of IEEE 279 or equip qual & edequate surveillance testing Tech Specs. Addl info requested.

 LAINAB.O. Plant Systems Branch (Pre 791030). 78/11/14. 2pp. 94397: 224.
- 7811300049 Forwards NRC staff paper, Policy Bession Item(BECY-78-554) re-licenses reg performance evaluation. Three methods for evaluation are:statistic), trend analysis & regional survey method. M/o sect. 0'REILLY.J.P. Region 2. Atlanta, Office of the Director. 78/11/15. 2pp. 94071:051.
- 781213014B Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attenders to facilitate sending out math. W/encl. Registration Form & List of Lotations. MILLER. J. R. Assistant Director for Bite & Befeguards (Pre 791030). HILLER, J. R. As 78/11/15. 5pp.
- 7612180273 Forwards Rev#i "Draft Radiological Effluent Tech Specs" for BUR's(NUREQ-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Per Plants" (NUREQ-0133). GRIMES, B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94356:340.
- 7812050003 Forwards Amends#44.40 & 17 to Lic#DPR-33,DPR-52 & DPR-68 IPPOLITO.T. A. Operating Reactors Branch 3 (Pre 790625), 78/11/16. 3Pp. 94200:021.

- --7812050009 Amend#44 to Oper Lic Permits everage pur range monitor sys to be inoperable in refuel modespermits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clarifies Tech Byers he rod block monitor. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16 29pp. 94200:024.
- --7812050017 Amend#40 to Oper Lic.Permits average pur range monitor sys-to be inoperable in refuel mode:permits less than 3 intermediate range monitors par trip channel to be oper in shutdown mode & clarifies Tach Space resmod block monitor. IPPOLITO. T.A. Operating Reactors Branch 3 (Pre 790685). 78/11/16. 27pp. 94200: 055.
- --7812050022 Amend#17 to Oper Lic Permits everage pur range monitor sys to be operable in refuel mode.permits lass than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clarifies Tech Space recrod block monitor. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 16pp. 94200:084
- --7812050023 Concludes amends do not involve significant hazards, health & safety of public will not be endangered by oper in proposed memore & activities in compliance w/regs. Office of Nuclear Reactor Regulation, Director. 78/11/16. 9pp. 94200: 102.
- --7812050026 Notice of Issuance of Amend#44 to Lic#DPR-33 emend#40 to Lic #DPR-52 & amend#17 to Lic#DPR-68 which revise Tech Beecs. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 3pp 94200:111.
- 7812050012 Forwards Amend#45.41 & 18 to Facil Open Lic#DPR-33.DPR-52 & DPR-68 rev Tech Specs as requested in 780803 ltr w/Bafety Evaluation & Notice of Issuence IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/18. 2pp. 94200:188.
- --7812050016 Amend#45.41 & 18 to Facil Open LicHDPR-33.DPR-52 & DPR-68 rev Tech Boecs to incorp minor changes for leak testing containment isolation & check valves. Amendel8 changes limit of 2000 MHD/t fuel exposure.

 IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/18.

 60pp. 94200:190.
- --7812050019 Befaty Evaluation Rept supporting Amend445.41 & 18 to Facil Oper LiceDPR-33.DPR-52 & DPR-68 concluding that proposed changes are acceptable & safety of pub will not be endangered by oper in proposed manner.

 # Office of Nuclear Reactor Regulation, Director. 78/11/18.
 18pp. 94200: 250.
- --7812050020 Notice of Issuance of Amend#45:41 & 18 to Facil Oper Lic #DPR-33/DPR-52 & DPR-68.
 IPPOLITO,T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/18. IPPOLITO, T. A. Op 2pp. 94200: 268.
- 7812060062 Requests add1 info re reload analysis for open of subj facil
- in third fuel cycle incorporating prompt recirculation pump trip feature. IPPOLITO,T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/02. IPPOLITO, T. A.
- 5pp. 94234: 126.
- 7812110029 Discusses possible dangers of LDCA in containment purging during normal plant open Requests either commitment to limit purging or justification for continuing W/encl ANO: e7812080207.

 IPPOLITO.T. Openating Reactors Branch 2 (Pre 790625). 78/11/29.
- 7812050243 Forwards results of MCPR analysis to aid NRC in review of amend request & corrections to smend request Also forwards QE rept "Suppl Reload Lic Bubmittal for Browns Ferry Nuc Plent unit 1. Reload 2." GILLELAND. J. E. Tennessee Valley Authority. 78/11/30. 11pp. 94202:056.
- --7812030251 "Buppl Reload Licensing Submittel for Browns Ferry Unit 1, Reload 2," Revision 1, FREEMON, A.M. General Electric Co. NEDO-24136 RO1, 78/11/30. 33pp. 94432; 198.
- 7812050189 Informs that due to delays, complete response to suppression pool temp transients will be submitted by 780315.

 QLLELAND, J.E. Tennessee Valley Authority. 78/12/01. 1p.
- 7819140176 Forwards Oct 1978 Prog Activity Review listing meetings held

1070170 Forwards add1 info re cycle 3 reload analysis equested in 781122 NRC 1tr. Transient analysis in 1-1 submittal has been performed w/REDV Code LLELAND, J. E. Tennessee Valley Authority. 78/12/05. 7pp. 1555: 136

1280141 Emphasizes importance of submitting accurate & complete info RC by licensees & applicants. Info submitted must be ibstantiated by data & calculations. Licensee must notify IC of any inaccuraties or enforcement action will result. WIS.J.O. Office of Inspection & Enforcement, Office of the rector, 78/12/06. 2pp. 94310:354.

2200154 Provides details of mod motor~generator set characteristics 'postulated M-0 set oper modes for low-pressure coolant sjection valve pur supply. Installation will be delayed still end of 2nd refueling outage of Unit 3 LLELAND, J. E. Tennessee Valley Authority. 78/12/13. 4pp. 1420:271.

2200256 Responds to NRC ltm of 780807 me reactor protect sys purpply at subj facil. TVA does not believe that concerns spressed by NRC are a problem Further surveillance of the factor protect sys supplies is unwarranted. ILLELAND, J.E. Tennessee Valley Authority, 78/12/13, 1p. 1206:00f.

2260163 Response to 781122 request for add1 info needed for reload halysis for cycle 3 oper of facil. LLELAND, J.E. Tennessee Valley Authority. 78/12/14. 4pp. 4159:232.

2220175 Due to incomplete resolution of insvc prog for Unit 1. ubsittel of rev Tech Specs has been postponed until after stails of Unit 3 insvc inspecc prog ere resolved.

TLIELAND, J.E. Tennessee Valley Authority. 78/12/19. 1p.

2290217 Responds to 781129 NRC ltr re containment purging during creal plant oper & request for info re design of ell safety ctuation signal circuits which incorp a manual feature esponses will be submitted by 790301.
ILLELAND. J. E. Tennassee Velley Authority. 78/12/21. 2pp. 4191:188.

1210367 Forwards add1 info re multiple consecutive safety/relief alve actuation of Mark I containment program.

OBON-L. J. General Electric Co. 78/11/13. 3pp.

Inspection reports. IE Bulletins & correspondence

0310060 Ack receipt of 780127 ltr informing NRC of steps taken to orrect violations noted during Inspec #50-259/77-26. 50-260/77-26 & #50-296/77-26. DNG.F.J. Region 2: Atlanta: Reactor Operations Nuclear Support ranch. 78/03/01. ip. 94094:129.

810310064 Responds to 780103 NRC ltr re violations noted in Inspec Repts #30-259/77-26, #30-260/77-26 & 50-296/77-26. Corrective actions are exampt from disclosure due to security info contained in response. GILLELAND, U.E. Tennessee Valley Authority. 78/01/27. ip. 94074:130.

'810310059 Forwards IE Inspec Repts #30-259/77-26, #30-260/77-26 & #30-296/77-26 on 771213-16 & w/o Notice of Violation, w/weld pursuant to 2.790. LCNO;F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/01/03. 2pp. 94094:131.

'B10010074 IE Inspec Repts #50-259/77-26, #50-260/77-26, #50-296/77-26, on 771213-16 during which I item of noncompliance was noted: vital green area gate was open & unattended. BRADFORD.M.H. Region 2, Atlanta, Office of the Director. ALDERBON,C.E. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/01/03. Spp. 94094:133.

.0110265 Forwards IE Inspec Repts#50-259/78-15, #50-260/78-16, & #50-196/78-14 on 780626 during which no items of noncompliance sere noted.

1UTHERLAND, J. T. Region 2, Atlants, Fuel Facility & Materials Bafety Franch. 78/08/31. 2pp. 94079:142.

/810120004 IE Inspec Repts#50-259/78-15,#50-260/78-16, t #50-296/78-14, on 780626, during which no items of noncompliance were noted. Hajor area inspected: whole body counting practices to procedures to test count of NRC phantom.

MILLBAP, M. J. Region 2, Atlanta, Fuel Pacility & Materials Safety Branch. 78/08/30. 4pp.

7810110283 Forwards IE Inspec Repts#50-259/78-19.#50-260/78-20 & #50-26/78-18 on 780720-21 during which no items of noncompliance were noted.

8UTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 78/09/01. 2pp. 03556:076.

- --7810110286 IE Inspec Rapts#50-259/78-192-260/78-20.#50-296/78-18. on 780720-21 during which no items of noncompliance were noted Major areas inspected included: emergency planning & simulated emergency conditions.

 PEROTTI.D.J. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 78/08/31. 4pp. 94079:144.
- 7811010269 Forwards IE Inspec Repts#50-259/78-20.#50-260/78-21 & #50-296/78-19 on 780807-10.during which no items of noncompliance were noted.

 LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/13. 2pp. 94392:160.
- ~~7811010280 IE Insp Repts 50~259/78~20.50~260/78~21 & 50~296/78~19 on 780807~10.during which no items of noncompliance were noted Major areas inspected:plant operations.reportable occurrences & electrical mods.

 BULLIVAN.R.F. Region 2, Atlanta, Office of the Director. 78/09/12. Spp.
- 7810110056 Forwards IE Inspec Rept 30-259/78-24.50-260/78-27 & 50-276/78-23. 0'REILLY.J.P. Region 2. Atlanta. Office of the Director. 78/09/26. 2pp. 74063:246.
- --7810110059 IE Inspec Rept 50-259/78-24.50-260/78-27 & 50-296/78-23 on 780915. Meeting held re TVA security program & managerial changes being implemented.

 GILLESPIE.F. P. Region 2. Atlanta. Safeguards Branch. 78/09/82. 3pp. 94063:248.
- 7810230226 Ack receipt of 780922 ltr re corrective steps taken on items of noncompliance found in inspec as notified by NRC ltr of 780825.

 O'REILLYJ, P. Region 2, Atlanta, Office of the Director. 78/10/06.

 Ip. 94165:093.
- --7810230227 Responds to 780825 NRC ltr re violations noted in Inspec Repts#50-239/78-16, #50-260/78-19, #50-296/78-17, GILLELAND, J. E. Tannessee Vallay Authority. 78/09/22 ip. 74165: 094.
- --7810230230 Forwards IE Inspec Repts#50-259/78-18.#50-260/78-19.#50-276 78-17 on 780726-28. O'REILLY, J. P. Region 2. Atlants. Office of the Director. 78/08/25. 3p. 94165:095.
- 7810230300 Forwards IE Circular#78-17. (See AND: 7810230221, Docket 50-313, 781013)

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/10/13.
 1p. 94164:183.
- 7811090198 Act receipt of 781016 ltr informing NRC of steps taken to correct violations noted during inspec#50-259/78-18, #50-260/78-19 & #50-296/78-17. KENNA, M.B. Region 2, Atlanta, Office of the Director. 78/10/26. ip. 94038: 260.
- --7811090204 Responds to 780825 NRC 1tm re violations noted in Inspet Repts#50-259/78-18,#50-260/78-19 & #50-296/78-17. Corrective actions are exempt from disclosure IAH 100FR2.790. GILLELAND.J. E. Tennessee Valley Authority. 78/10/16. 1p. 74038:261.
- 7812030053 Forwards IE Inspec Repts#50-259/78-21,#50-260/78-23 & #50-294/78-20 on 780828-0901 during which no items of noncompliance were noted.

 LONG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/27. 2pp. 94334:R18.
- --7812050057 IE Inspec Repts#50-259/78-21,#50-260/78-23 & #50-296/78-20 on 780828-0901 during which no items of noncompliance were noted Major areas inspected intl:reportable occurrences & followup on IE bulletins & circulers.
 SULIVAN.R.F., OUZTB.J.E. Region 2, Atlanta, Office of the Director. 78/10/26, 10pp. 94034:220.
- 7811130006 Ack receipt of 701010 ltr informing NRC of steps taken to correct violations noted during inspec#50-259/78-17, 50-260/78-18 & 50-296/78-16. SUTHERLAND.J.T. Region 2, Atlanta, Fuel Facility & Materials Bafety Br

- --781130013 Responds to 780915 NRC ltr to violations nated in Inspec Repta#50-259778-17, #50-260778-18 2-296778-16 Corrective actions: 18 & DA RHR heat exchanges inspected & task test initiated 9ILLELAND J. E. Tennessee Valley Authority. 78/10/10 2pp. 94077; 012.
- --7811130018 Forwards IE Inspec Repts#90-259/78-17.#50-260/78-18 & #850-299/78-16 on 780725-28 & Notice of Violation.

 BUTHERLAND.J.T. Region 2. Atlanta, Fuel Facklity & Materials

 Barety Branch. 78/09/15. 2pp. 94073:278.
- --7811130022 Notice of Violation from inspec on 780725-28. • Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 78709715. 1p. 94076:280.
- --7811130022 Notice of Violation from inspec on 780725-28.

 * Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 78/09/15. 1p.
- --7811130049 IE Inspec Repts#30-259/78-17.#30-260/78-18 & #30-296/78-16 on 780725-28 during which I item of noncompliance was noted: release of radioactive effluents above limits. TRGUP, O. L. . 91880N, A. F. Repion 2, Atlanta, Fue) Facility & Materials Safety Branch. 78/09/15. Spp. 94075:282.
- 78iii50073 Forwards IE Circular 78-18. O'REILLY, J.P. Region 2: Atlante, Office of the Director. 78/11/06. 1p. 94ii2.288.
- 7812210355 Forwards IE Inspec Repts#50-259/78-26.#50-260/78-29 & #50-296/78-25 during which no items of noncompliance were noted.

 KENNA: H B. Region 2. Atlanta. Bafeguards Branch. 78/11/09. Spp. 94014:353.
- --7812210363 IE Inepec Repts#50-239/78-26.#30-260/78-29 & #30-296/78-25 during which no items of noncompliance were noted Major areas inspected incliphysical security requirements previous items: alarm. access. communications.
 BEBECKER.K. H. A. GILLEBPIEF.F. P. Region 2. Atlanta. Befeguards
 Branch. 78/11/08. 4pp. 94014:355
- 7812180320 Forwards IE Inspec Repts#50-259/78-25.#50-260/78-28 & #80-296/78-24 on 780925-27 during which no items of moncompliance were noted. LDNG.F.J. Region 2. Atlenta, Reactor Operations Nuclear Support Branch. 78/11/09, 2pp. 94356-285.
- --7812180325 IE Inspec Repts#50-259/78-25,#50-260/78-28 & #50-296/78-24 on 780925-27 during which no items of noncompliance were noted, Major areas inspected incl:refueling plant oper & LER & IE Circulars/Bulletins review.

 SULLIVAN.R.F., DANCE.H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 78/11/09, 6pp. 94356:287.
- 7812130372 Forwards ampided response to IE Bullstin#78-09, describing steps taken to effect a good seal between drywell head & contestiment flenge.

 OILLELAND.J.E. Tennesse Valley Authority. 78/11/13. 2pp. 04399.15%
- 7812120051 Forwards reproductions of articles that appeared in June & Aug 1978 aditions of Nuc Security Safeguards Newsletter. KENNA, M. B. Region 2, Atlanta, Safeguards Branch. 78/11/17. 4PP. 94278:068
- 7812040369 Forwards IE Bulletin#78-12A, suppl to 1E Bulletin 78-12. W/encl AND:7811300055. OFFILEY, J.P., Region 2, Atlanta, Office of the Director. 78/11/24. 1p. 94187:177.
- 7812060015 Ack receipt of 781122 ltr informing NRC of steps taken to correct violations noted during inspec#50-259/78-22, #50-260/78-25 & #50-296/78-21.

 8UTHERLANO.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 78/11/28. [p. 94418:338.
- --7812060021 Responds to 781027 NRC ltr re violations noted in Inspec Rept850-239778-22.880-260778-25 t 850-296778-22.Corrective actions: survaillance instruc sched change to reflect 18 month testing req. GillElaNo.J.E. Tennessee Valley Authority. 78/11/22. 3pp. 94418-339.
- --7812060026 Forwards IE Inspec Rept#50-259/78-22,#50-260/78-25 & #50-296/78-21 on 780911-14 & Notice of Violation.

 BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials
 Befety Branch. 78/10/27. 2pp. 94415:312.

- --7812060030 Notice of Violation from inspec on 780911-14.

 Region 2: Atlanta: Office of the Director. 78/10/27. ip. 94415:314.
- --7812060033 IE Inspec Rept#50-259/78-22,#50-260/78-25 & #50-296/78-21 on 780911-14 during which I item of noncompliance was noted: surveillance teating of air cleaning sys.
 TROUP.9 L. JACKBON.L.L., 91880N.A.F. Region 2, Atlanta, Office of the Director. 78/10/27. 9pp. 94415:315.
- 7812280014 Forwards IE Bulletin 78-14. O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 78/12/19. 2PP. 94131:032
- R. Periodic operating reports & related correspondence
- 7810160106 Forwards Monthly Oper Rept for Bept 1978.
 DEWEABE, J. G. Tennessee Valley Authority. 78/10/10. ip. 94004:281.
- --7B10160109 Monthly Oper Rept for Sept 1978. DEMEASE, J. G. Tennessee Valley Authority. 78/09/30. 34pp. 94002 087
- 7810170161 Monthly Oper Rept for Bept 1978.
 DEMEASE, 0.9. Tennessee Valley Authority. 78/10/31. 31pp. 94236:097.
- 7810300103 Files fish impingement rept for subj facil for 3rd quarter 1978 01LLELAND, J. E. Tennessee Valley Authority. 78/10/19. 14pp. 94078: 048.
- 7811140137 Forwards Monthly Oper Rept for Oct 1978.

 DEWEASE J. Q. Tennessee Valley Authority. 78/11/09. 1p. 94425.275.
- --7811140140 Monthly Oper Rept for Gct 1978.

 OREEN, D. Tennesses Valley Authority. 78/11/02. 33pp. 94425.276.
- 7812190161 Forwards Monthly Open Rept for Nov 1978.
 DEWEASE, J. Q. Tannesses Vallay Authority. 78/12/02. 1p. 94340/180.
- --7812190162 Monthly Oper Rept for Nov 1978.

 DEMEAGE, J. G. Tennesses Valley Authority, 78/12/02. 29ep.
 9210-181
- B. Reportable occurrences, LERs & related correspondence
- 7811020362 ROM50-289/7827: on 780913"A" recirculation loop flow decreased from 41,000 to 33,000 cpm w/corresponding increase in pump delta F.caused by valve satem separating from valve disc.

 DEWEASE, J. D. Tennessee Valley Authority. 78/09/14. 1p. 94241:136.
- 7810100036 Forwards LERM78-028/01T. FDX.H.B. Tennesse Valley Authority. 78/10/02. 1p. 94033:028.
- --7810100040 LER#78-028/01T-0 on 780919:Foxboro Model 510 per supplies provided under TVA contact 75Kii-8580 were not seismically qualified, Qualified per supplies have been provided & will be installed.

 * Tennesses Valley Authority. 78/10/02. 2pp. 94033:029.
- 7810310183 Forwards LERW78-029/017-0. FDX:H.B. Tennessee Valley Authority. 78/10/25. 1p. 94090:239.
- --7810310186 LER#78-029/03L-0 on 781012: cable raceway between Diesel Qenerator Bldg & Standby Oss Treatment Bldg appeared to have sattled 2 inches at Diesel Generator Bldg & expension joint. Cause unknown but new supports will be installed on raceway. w Tennessee Valley Authority. 78/10/24. 3pp. 94090:240.
- 7811140217 Forwards LERW78-030/03L-0. FDX.H.S. Tennesses Valley Authority. 78/11/08. 1p. 94400:046.
- --7811140221 LER 78-030/03L-0: on 781013, four heat detectors found to be connected to incorrect spray zones. Elec panel 1-23-281A was wired incorrectly causing improper sequencing. Detectors were rewired & returned to oper per Tech Bases.

 W Tennessee Valley Authority. 78/11/06. 2pp. 94400:047.
- 7811140240 Forwards LERN78-031/03L-0. FDX.H.S. Tennessee Valley Authority. 78/11/08. 1p. 94400:096-

- 78:1280214 Suppl to 780331 ltr re Reportable Occurrence 50-259/288 & interia measures taken to alleviate potential adverse implant voltage conditions on Unit 3:4-WV unit boards, the 161-KV sys. & the 4-KV shutdown boards.

 FOX.H. 8. Tennesses Valley Authority. 78/11/20. Rpp. 02785:338.
- 7811280171 LERM78-033/03L-0 on 781025: redwater airborne effluent monitor recorder RM-90-252 failed to open resulting in loss of cartinuous effluent monitoring. Caused by broken input eignel lead.

 Tennessee Valley Authority. 78/11/15. 2pp. 94013:225.
- 7811280205 Forwards LER#78-032/03L-0, FOX.H. 8. Tennesse Valley Authority. 78/11/22. 1p. 94013:265.
- --7811280207 LERM78-032/03L-0 on 781022: offgas sampling Pump A malfunctioned & pump B motor would not start. Caused by vanes sticking on pump A-model MBRI Mfg by Metal Bellows Corp. Bearings & centrifugal switch failed on pump B motor.

 * Tennesses Valley Authority. 78/11/15. 2pp. 94013: 266.
- 7812270265 Forwards LERN78-034/017-0. FGX:H. 8. Tennessee Valley Authority. 78/12/19. 1p. 94232:036.
- ---7812270269 LER#78-034/01T-0 on 781205:during refueling outage 6 M81V's exceeded leakage limits. Caused by degradation of valve seating surfaces thru normal oper.

 * Tennessee Valley Authority. 78/12/18. 2pp. 94232:037.
- DOCKET 80-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- 7810310075 Forwards rev to copies 5 thru 10 of subj facil security plan dtd 780926. Revs reflect latest changes in proposed security sys & procedures. Revs are proprietary (ref 100FR2.790). 9LLELAND. J.E. Tennessee Valley Authority. 78/10/25. 79pp. 94094: 315.
- 7811200200 Forwards revs to Physical Security Plan of subj facils reinstallation of emergency lighting fixtures. Requests withholding from pub disclosurs per 10CFR2.790.
 91LELAND: J. E. Tennesses Valley Authority. 78/11/15. ip. 94292;036.

H. Gameral correspondence

- 7812210336 Comments on 780927 constituent ltr to Lagomarsino revalidity of the Reactor Bafety Study, the subj facil fire, & the operating performance of commercial nuc pur plants. OCSSICK.L. V. Defice of the Executive Director for Operations. 78/19/12. 13pp. 94014:308.
- J. Insurance & indemnity information
- 7819010256 Forwards PolicyMMF-66.Endorssment#37 for subj facil, States Advance premium #94768.B9, reserve premium #71049.36 & return premium #3125.17.
 FIEDLERIJ, Nuclear Insurance Consultants. 78/11/28. 2pp.
- 78:1090096 Advance premium & standard premium endorsement for 1978. SARDES.C.R. Nuclear Energy Liebility Insurance Association. 78/10/11. 1p. 94042:141.
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 7812200244 Forwards Amend#67 which rev FBAR to reflect current plant configuration. Amend does not req review & is available in PDR.
 9ILLELAND, J. E. Tennessee Valley Authority. 78/11/30. 2pp. 94169:001.
- --7819200246 Amenda67 to FBAR, Vols 1-7. This amend does not req review, as it merely rev FBAR to reflect current plant configuration. * Tennessee Valley Authority. 78/11/30. 2900pt.

- GILLELAND, J. E. Tennessee Valley Authority. 78/11/19. 1p. 94047:145.
- 7811170175 Requests that NRC review indomnity fee invoice#23-79 & #27-79.dtd 781024 which appears to be incorrect & rebill util.

 OILUELAND. J. E. Tennessee Vellay Authority. 78/11/12. lp. 94134:029
- 7811170215 Responds to NRC questions prompted by Oilleland's 780811 lt requesting Tech Spec changes. Change ensures reconfiguration of ERM's & Will be placed in non-coincidence trip mode.

 MILLE, L.M. Tennesses Valley Authority. 78/11/13. 1p. 74136: 122.
- 7811200080 Requests add1 info for review of recirculation pump trip for use to mitigate Anticipated Transient w/o Boram Info due w/in 60 days.

 LEAR.9. Operating Reactors Branch 3 (Pre 790625). 78/05/10. Opp. 94217:360.
- 7810200131 Notice of issuence of Amend#40 to Facil Operating Lic# DPR-03.Amend#38 to Facil Operating Lic#DPR-52 & Amend#14 to Facil Operating Lic#DPR-56, rev Tech Space for oper of subjectis.Amends lower low water level setpoint.

 IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/08/02.

 2pp. 94411:287.
- 7810110107 Responds to 780829 itr indicating there have been no incidents of control rods failing to fully insert on demand at subj facils.
 OILLELAND. J. E. Tennessee Valley Authority. 78/10/05. ip. DANAA-353
- 7810230244 Forwards responses to verbal questions re-proposed changes to Tech Brecs of subj facil as submitted 780322.

 QILLELAND, J.E. Tennessee Valley Authority. 78/10/10. App. 74170: 242.
- 7810240153 Forwards add1 info re proposed differential pressure control torus water level Tech Specs for subj facils.
 OILLELAND, J. E. Tennessee Valley Authority. 78/10/18. 3pp.
- 7810240144 In response to 780807 itr to N.B. Hughes, the recommended surveillance of reactor protec sys will continue. Request response date extension to 781215.

 GILLELAND, J. S. Tennesses Valley Authonity. 78/10/19. ip.
- 7810250082 Forwards summary rapt of refueling test proy conducted after subj facil spring 1978 outage.
 GILLELAND, J. E. Tennassee Valley Authority. 78/10/19. ip.
- --7810250085 "Bummary Rept:Refueling Test Program." Bummarizes tests performed as of 780816.

 DEMEASE, J. Q. Tennessee Valley Authority. 78/10/19. Spp.
- 7811130335 Summary of 780914 meeting w/OE representatives & Mark 1 Owners Group re-progress of Long Term Prog w/attendence list & agenda (RD-9-A-Mark), Btandards.)
 GRIMES. C. Plant Systems Brench (Pre 791030). 78/10/26.
- 7811130128 Forwards "Reactor Containment Bldg Integrated Leak Rate Test."
 GILLELAND, J. R. Tennessee Velley Authority. 78/11/07. 1p. 94242:362.
- --7811150129 "Reactor Bldg Containment Integrated Leak Rate Test" on 780513-15. Dutlines objectives, principal syents & special equip used in the CIRT. Concludes that accurate results can be obtained while significantly reducing test time. GILLELAND, J. E. Tennessee Velley Authority, 78/11/07. 71pp. 74206-318.
- 7811200406 Forwards results of measurements of radioactive metl in NR phantom on whole body counter. Entl i contains actual amount of sech radionucide presents entl 2 gives ratio of measurements to DOE values & entl 3 gives recommendations. SUTHERLAND.J.T. Region 2, Atlanta, Fuel Facility & Materials Bafet Branch, 78/11/09. Spp. 94419:305.
- 7811210202 Notifies will of 781205 seminar in Atlanta to discuss new Model Rod Effluent Tech Specis & encl seminar info sheet, registration form & proposed agenda. O'REILLY, J. P. Ragion P. Atlanta, Diffice of the Director, 78/11/09. 5pp. 94485:212.

≥pp. 74071.051

7812150148 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out matl. W/encl Registration Form & List of Locations. MILLER.J. R. Assistant Director for Site & Safeguerds (Pre 791030). 79/11/15. Spp.

- 7812180273 Forwards RevMi "Draft Rediological Effluent Tech Specs" for BMR's(NNREQ-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Per Plants" (NUREQ-0133). ORINGES.B.W. Assistant Director for Engineers & Projecte (Pre 790625). 78/11/15 App. 94356:340.
- 7812050003 Forwards Arends#44,40 & 17 to Lic#DPR-33.DPR-52 & DPR-68 safety eval & Notice of Issuance.

 IPPOLITO.T.A Operating Reactors Branch 3 (Pre 790625) 78/11/16.

 3PP. 94200:021.
- ~-7812050009 Amend#44 to Oper Lic.Permits average pur range monitor systobe inoperable in refuel moderpermits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clarifies Tech Specs re.rod block monitor. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 29pp. 94200:024.
- --78)2050017 AmendW40 to Oper Lic.Permits average pur range monitor systobe incaperable in refuel modelpermits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clarifies Tech Specs rs:rod block monitor. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 270625). 78/11/16. 229p. 94200.055
- --7812030022 Amend#17 to Oper Lic.Permits average pur range monitor systoble operable in refuel modelpermits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clarifies Tech Specs reirod block monitor.

 * Operating Reactors Branch 3 (Pre 790625). 78/11/16. 16pp. 94205:034.
- --7812050023 Concludes amends do not involve significant hezards health & safety of public will not be endangered by oper in proposed menner & activities in compliance w/regs.

 Office of Nuclear Reactor Regulation. Director. 78/11/16. 9pp. 94200:102
- --7812050026 Notice of Issuance of Amend#44 to Lic#DPR-33 amand#40 to Lic #DPR-52 & amend#17 to Lic#DPR-68 which revise Tech Specs. SPPOLITO.1.A. Operating Reacture Branch 3 (Pre 790625). 78/11/16. 3pp. 94200 111.
- 7812030012 Forwards Amend#45.41 & 18 to Facil Oper Lic#DPR-33.DPR-52 & DPR-68 rev Tech Specs as requested in 780803 ltr u/8afety Evaluation & Notice of Issuance.
 IPPQ_ITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/18.
 2pp. 94200-180.
- --7812050016 Amend#49.41 & 18 to Fecil Oper Lic@DPR-33.DPR-52 & DPR-68 rev Tech Specs to incorp minor changes for leak testing containment isolation & check valves Amend#18 changes limit of 2000 MHD/t fuel exposure.

 IPPOLITO.T A. Operating Reactors Branch 3 (Pre 790625). 78/11/18. 60pp. 94200.190.
- --7812050019 Bafety Evaluation Rept supporting Amend#45,41 & 18 to Facil Oper Lic WDR-33, DRR-52 & DRR-68 concluding that proposed changes are acceptable & sefety of pub will not be endangered by oper in proposed manner.

 **A Office of Nuclear Reactor Regulation, Director 78/11/18 18pp. 94200:250.
- --7812030020 Notice of Issuance of Amend#45.41 & 18 to Facil Oper Lic #DPR-33.DPR-52 & DPR-68. IPPDL1T0.1.A. Operating Reactors Branch 3 (Pre 790625). 78/11/18. 2pp. 94200:268.
- 7812110029 Discusses possible dangers of LOCA in containment purging during normal plant open. Requests either commitment to limit purging or justification for continuing Wienci AND: 87812080207 IPPOLITO. T. Openating Reactors Branch 2 (Pre 790625). 78/11/29. 8pp. 94408:101.

- 78:2030189 Informs that due to delays complete response re suppression pool temp transients will be submitted by 780315.

 OILLELAND, J. E. Tennessee Valley Authority. 78/12/01 ip.
- 7812140176 Forwards Dct 1978 Prog Activity Review listing meetings held & providing task-by-task activity summary for the month. 8080N.L.J. General Electric Co. 78/12/04 11pp.
- 7819280141 Emphasizes importance of submitting accurate & complete info to NRC by licensess & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J. G. Office of Inspection & Enforcement, Office of the Director. 78712706. 2pp 94310:354.
- 7812200154 Provides details of mod motor-generator set characteristics w/postulated M-O set oper modes for low-pressure coolent injection valve pur supply. Installation will be delayed until end of 2nd refueling outage of Unit 3. GILLELAND, J.E. Tennessee Valley Authority. 78/12/19. 4pp. 94420.271.
- 7812200256 Responds to NRC 1tr of 780807 re reactor protec sys pur supply et subj facil. TVA does not believe that concerns expressed by NRC are a problem. Further surveillance of the reactor protec sys supplies is unwarranted. 07LLELAND. J.E. Tennessee Valley Authority. 78/12/13. ip. 94206:001.
- 7812290217 Responds to 781129 NRC ltr re containment purging during normal plant oper & request for info re design of all safety actuation signal circuits which incorp a manual feature. Responses will be submitted by 790301.
 01LLELAND, J.E. Tennessae Valley Authority. 78/12/21. 2pp. 94191.188.
- 7811210367 Forwards add1 info re multiple consecutive safety/relief valve actuation of Mark I containment program. BOBONL J. General Electric Co. 78/11/13. 3pp.
- G. Inspection reports. IE Bulletins & correspondence
- 7811090198 Ack receipt of 781016 ltr informing NRC of steps taken to correct violations noted during inspec#50-259/78-18: #50-260/78-19 & #50-296/78-17. KENNA, M.B. Region 2. Atlanta, Office of the Director. 78/10/26. io. 94038:260.
- --7811090204 Responds to 780825 NRC ltr re violations noted in Inspec Rept#850-239/78-18, #50-260/78-19 & #50-296/78-17. Corrective actions are exempt from disclosure IAW 10CFR2. 790. GILLELAND, J. E. Tennessee Valley Authority. 78/10/16. lp. 94038:261.
- 78:11:30006 Ack receipt of 78:10:10 ltr informing NRC of steps taken to correct violations noted during inspece30-259/78-17, 50-260/78-18 & 30-296/78-16.
 SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Befety Branch, 78/10/31. 1p. 94075:275.
- --7811130013 Responds to 780915 NRC ltr re violations noted in Inspec Repts#30-259/78-17, #80-260/78-18 P-296/78-16. Corrective actions: 18 & 3A RHR heat exchanges inspected & task test initiated. O'LLELAND.J.E. Tennessee Valley Authority, 78/10/10. 2pp. 94077-012.
- --7811130018 Forwards IE Inspec Repts#50-259/78-17,#50-260/78-18 & #80-276/78-16 on 780725-28 & Notice of Violation. SUTHERLAND.J.T. Region 2: Atlants, Fuel Facility & Materials Safety Branch. 78/09/15. 2pp. 94075:278.
- --7811130022 Notice of Violation from inspec on 780725-28.

 * Region 2: Atlanta: Fuel Facility & Materials Bafety Branch.
 78/09/15. jp. 94075:280.
- --7811130049 IE Inspec Repts#50-259/78-17.#50-260/78-18 & #50-296/78-16 on 780725-28 during which I item of noncompliance was noted: release of radioactive effluents above limits. TRDMy.G.L., 201880N.A.F. Region 2, Atlants, Fuel Facility & Materials Safety Branch. 78/09/15. Spp. 94075:282.

1 1978 editions of Nuc Becurity Safeguards Newsletter.

WHAN B. Ragion 2, Atlanta, Safeguards Branch. 78/11/17. 4PP.
278:040

310060 Ack receipt of 780127 itr informing NRC of steps taken to rect violations noted during Inspec #50-259/77-26. >-260/77-26 & #50-296/77-26. |
49.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Inch. 78/03/01. | 1p. 94094:129.

-Q310064 Responds to 780103 NRC 1tr re violations noted in Inspectants 850-259/77-26, 850-260/77-26 & 500-296/77-26 contained in response.

FillELAND, J. E. Tennessee Valley Authority 78/01/27, ip. 78/09/4-130.

Q310069 Forwards IE Inspec Repts #50-259/77-26, #50-260/77-26 \$ 150-296/77-26 on 771213-16 & w/o Notice of Violation, //hels pursuent to 2,790 QNG/F.J. Region 2, Atlanta, Reactor Operations Nuclear Support tranck. 76/01/03 2pp 94094:131.

OGIO074 IE Inspec Repts #30-259/77-26, #50-260/77-26, #50-296/77-26, 771213-16 during which I item of noncompliance was noted; itel green area gate was open & unattended. RADFORD, H. H. Region 2, Atlanta, Office of the Director. LDERSON, C. E. Region 2, Atlanta, Reactor Operations Nuclear Upport Branch. 78/01/03 5pp. 74094:133

O120004 IE Inspec Repts#50-259/78-15, #50-260/78-16, & #50-296/78-14, n 780626, during which no items of noncompliance were noted. sjor area inspected: whole body counting practices & rocedures & test count of NRC phantom.

ILLEMP. W. ... Region 2. Atlanta. Fuel Facility & Materials Befety ranch. 78/08/20 4pp.

10283 Forwards IE Inspec Reptem50-259/78-19, #50-260/78-20 & #50-26 -18 on 780720-21 during which no items of noncompliance e noted, -ERLAND. J. T. Region 2. Atlants. Fuel Facility & Materials Bafety nch. 78/09/01. 2pp. 03556:076.

Di 10286 IE Inspec Repts#50-259/78-192-260/78-20,#50-296/78-18n 790720-21 during which no items of noncompliance were sted. Major areas inspected included: emergency planning &

implated amergency conditions. BRROTTI.O.J. Region 2: Atlanta, Fuel Facility & Materials Safety ranch. 78/08/31. 4pp. 94079:144.

10267 Forwards IE Inspec Repts#50-259/78-20, #50-260/78-21 & -296/78-19 on 780807-10, during which no items of compliance were noted. A.F.J. Region 2, Atlenta, Reactor Operations Nuclear Support sch. 78/09/13. 2pp. 94392:160.

1010280 IE inap Repta 50-259/78-20, 50-260/78-21 & 50-296/78-19 t 780807-10, during which no items of noncompliance were sted. Major areas inspected: plant operations, reportable :currences & electrical mods.

&LIIVAN,R.F. Region 2: Atlanta, Office of the Director. WO9/12. 5pp.

0056 Forwards IE Inspec Rept 50-259/78-24,50-260/78-27 & 96/78-23.

ILLLYJ.P. Region 2, Atlanta, Office of the Director. 78/09/26.
94063:246.

110059 IE Inspec Rept 80-259/78-24,50-260/78-27 & 50-296/78-23 on 0915. Heeting held re TVA security program & managerial anges being implemented. LLESPIE,F.P. Region 2, Atlanta, Bafaguerds Branch. 78/09/22. p. 94063: 248.

0226 Act receipt of 780922 itr re corrective steps taken on a of noncompliance found in inspec as notified by NRC of 780825.
ILLY,J.P. Region 2, Atlanta, Office of the Director, 78/10/06. 94165:093.

230227 Responds to 780826 NRC ltr re violations noted in Inspec :te#80-259/78-18.#50-260/78-19.#50-296/78-17. LLELAND, J. E. Tennessee Valley Authority. 78/09/22. ip. 160:094. 7810230300 Forwards IE Circuler#78-17 (See ANO 7810230221.Doctet 50-313.781013) O'REILLY.J P Region 2. Atlanta. Office of the Director. 78/10/13. ip. 94164 183

D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 78/08/25 3p 94165 095

78-17 on 780726-28

AICERONRY FOLMELOR IE TURBEC MABERNON-MOANNEHH MON-MONNEH MACHEN

- 7812040322 Forwards IE Inspec Rept#50-260/78-24 on 78091-22 during which no items of noncompliance were noted.
 KENNA, H. D. Region 2, Atlanta, Safeguards Branch, 78/10/23, 2pp.
- --7812040325 IE Inspec Rept#50-260/78-24 on 780920-92 during which no items of noncompliance were noted. Major areas inspected inclifacti organization, shipping & receiving, storage & internal control, inventory, records & repts.

 HDD0ES, J. W. Region 2- Atlanta, Safeguards Branch. 78/10/23. 3pp. 94121 349
- 7812050053 Forwards IE [napec Repts#50-259/78-21.#50-260/78-23 & #50-296/78-20 on 780828-0901 during which no items of noncompliance were noted LONG, F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/10/27. 2pp. 94334.218.
- --7812050057 IE Inspec Repts#50-259/78-21.#50-260/78-23 & #50-296/78-20 on 780828-0901 during which no items of moncompliance were noted Hajor areas inspected inclineportable occurrences & followup on IE builetins & circulars.

 SULLIVAN, R.F. . OUZTB, J. E. Region 2. Atlanta, Office of the Director. 78/10/26 10pp 94334:220.
- 78:11:50073 Forwards IE Circular 78-18.

 D'REILLY, J.P. Region 2, Atlanta, Office of the Director. 78/11/06.
 10.
- 7812210355 Forwards IE Inspec Repte#50-259/78-26.850-260/78-29 & #50-296/78-25 during which no items of noncompliance were noted.

 KENNA, H. B. Region 2. Atlante, Sefequends Branch. 78/11/08. 2pp. 94014.353.
- --7812210363 IE Inspec Repts#50-259/78-26,#50-260/78-29 & #50-296/78-25 during which no items of noncompliance were noted Major areas inspected incl:physical security requirements previous items:alerm.access.communications.
 BERECKER.K. H., OILLESPIE.F.P. Region 2: Atlanta. Sefeguerds Branch. 78/11/08. 4pp. 94014:355.
- 7812180325 IE Inspec Repts#50-259/78-25.#50-260/78-28 & #50-296/78-24 on 780925-27 during which no items of noncompliance were noted. Major areas inspected incl.refueling plant oper & LER & IE Circulars/Bulletins review BULLIVAN.R F., DANCE,H.C. Region P. Atlante, Reactor Operations Nuclear Bupport Branch. 78/11/09. opp. 94356:287.
- 7812130372 Forwards amended response to IE BulletinW78-09, describing steps taken to effect a good seal between drywell head & containment flange.

 9TLLELAND, J.E. Tennessae Valley Authority. 78/11/13. 2pp. 94292: 125.
- 7811220087 Act receipt of 781102 ltr informing NRC of steps taken to correct violations noted during inspec#50-260/78-22.
 LONG, F. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/15 p. 94270:269.
- ---7811220091 Responds to 781010 NRC ltr re violation noted in Inspec Rept #80-260/78-22. Corrective actions: Tech Spec change to be requested re-calibr requirement & all changes for refueling test instr to be properly documented. QILLELAND, J. E. Tennassee Valley Authority. 78/11/02. 1p. 94273: 270.
- --7811220093 Forwards IE Inspec Rept#50-260/78-22 on 780815-18 & Notice of Violation.
 LCNO.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/10. 2pp. 94273:271.
- --7811220095 Notice of Violation from inspec on 780915-18.

 Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/10. 19. 94273:275.

- --7811220099 IE Inspec Rept#90-260/78-22 on 780815-18 during which 2 items of noncompliance were noted failure to adhere to all qual requirements for 94 records & to all requirements for surveillance instru content VOOT-LOWELL, R. MARTIN, D. Region 2. Atlanta, Reactor Operations Nuclear Support Granch 78/10/10. App. 94273:276
- 7812040369 Forwards IE Bulletin#78-12A.suppl to 16 8ulletin 78-12. W/encl AND.7811300055. D'REILLY, J. P. Region 2. Atlanta. Diffice of the Director. 78/11/24 1p. 94127-177.
- 7812060015 Ack receipt of 781122 ltr informing NRC of steps taken to correct violations noted during inspec#50-259/78-22, #50-260/78-25 & #50-296/78-21 SUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Gafety Branch. 78/11/28, 1p 94418-338.
- --7812060021 Responds to 781027 NRC ltr re violations noted in Inspec Rept#90--2597/B-22.450-260/78-25 & #30-296/78-22 Corrective actions, surveillance instruc sched change to reflect 18 month testing req. OllLELAND.J.E. Tennessee Valley Authority, 78/11/22. 3pp.
- --7812060026 Forwards IE Inapec Rept#50-259/78-22.#50-260/78-25 & #50-296/78-21 on 780911-14 & Notice of Violation. SUTHERLAND.J T. Region 2, Atlante, Fuel Facility & Materials Safety Branch. 78/10/27. 2pp. 94415 312
- --7812060030 Notice of Violation from insper on 780911-14.

 Region 2. Atlanta. Office of the Director. 78/10/27. ip 74415:314.
- --7812050033 IE Inspec Rept#50-259/78-22,#50-260/78-25 & #50-296/78-21 on 780911-14 during which 1 item of noncompliance was noted: surveillance testing of air cleaning sys. TROUP, 0 L., JACKBON, L., 61880N.A.F. Region 2, Atlanta, Office of the Director. 70/10/27 9pp. 94415:315.
- 7812280014 Forwards IE Bulletin 78-14. O'RBILLY, J.P. Region 2. Atlanta, Office of the Director. 78/12/19. 2PP. 94131.032.
- R. Periodic operating reports & related correspondence
- 7810160106 Forwards Monthly Open Rept for Bept 1978.
 DEMEASE, J. G. Tennessee Valley Authority, 78/10/10. 1p. 94004:281.
- ~-7810160109 Monthly Oper Rept for Sept 1978.
 DENEASE, J. G. Tennesses Valley Authority. 78/09/30. 34pp. 94002:087.
- 7810170161 Monthly Oper Rept for Sept 1978. DEMEASE J. 0 Tennessee Valley Authority. 78/10/31. 31pp. 94236:097.
- 7B10300103 Files fish impingement rept for subj facil for 3rd quarter 1978 OlLELAND, J.E. Tennesses Valley Authority. 7B/10/19 14pp. 94033-048
- 7811140137 Farwards Monthly Oper Rept for Oct 1978.
 DEWEASE, J. O. Tennesses Valley Authority. 78/11/09. 1p. 94425:275.
- --7811140140 Monthly Oper Rept for Oct 1978. GREEN, D. Tennesses Valley Authority, 78/11/02, 33pp. 94425: 276.
- 7812190161 Forwards Monthly Oper Rept for Nov 1978.
 DEWEASE, J. G. Tennessee Valley Authority, 78/12/02. ip. 94340:180.
- --7812190162 Monthly Oper Rept for Nov 1978.
 DEMEASE, J. Q. Tennessee Valley Authority, 78/12/02, 29pp. 94340, 181.
- S. Reportable occurrences, LERs & related correspondence
- 7810250035 Repartable Occurrence #50-260/7816 on 780930: During rautine inspec of drywell several pipe cracks were found, probably caused by vibration. (Revisional) DEMEABE, J. G. Tennassee Valley Authority. 78/10/05. 2pp.
- 7810180138 Forwards LER#78-016/01T-0.

- --7810180142 LER#78-016/01T-0 on 780930; discovered 1 inch instru line to Pdt-68-82 & a 3/4 inch bonnet vent line on FCV-68-1 were cracked & leaking Exact cause unknown.

 Tennessee Valley Authority. 78/10/13. 1p. 94368:314.
- 7810300168 Forwards LER#78-017/03L-0. FOX:H S Tennessee Valley Authority. 78/10/25. ip. 94034:131.
- --7810300171 LER 78-017/03L-0 on 781004: drywell orygan concentration was not reduced to 4% w/in 24-hour pariod after placing reactor in run mode due to personnel safety considerations during rapair of inner drywell air lock repairs.
 Tennessee Valley Authority. 78/10/25. 2pp. 94034:132.
- 7812070264 Notification of 7B1316 abnormal occurrence. Betpoint on main steam line radiation monitor nonconservative. Caused by reduced radiation level background in main steam line tunnel due to Cycle 2 reload.

 DEHEABS, J. G. Tennessee Valley Authority. 78/11/17. 1p. 03555:018.
- 7811280201 Forwards LERW78-019/017-0 FOX:H \$ Tennessee Valley Authority. 78/11/24. 1p. 94013:259.
- --7811280203 LERM78-019/017-0 on 781114: during normal open main steed line radiat monitors RM-90-135,-136,-137 & -138 were found less conservative than allowed by T.S. 3. i. A. Caused by decrease in background from cycle 1 to cycle 2 fuel.

 F. Tennessee Vallay Authority. 78/11/24. 2pp. 94013:260.
- 7812080101 Farwards LER#78-018/03L-0. FDX.H.S. Tennessee Valley Authority. 78/12/04. 1p 94107;289.
- --7812080103 LERW78-018/03L-0 on 781103: reactor pressure switch P8-68-96, switch i failed to operate during surveillance testing. Switch exercised & edjusted.

 * Tennesses Valley Authority. 78/12/04. 2pp. 94107: 290.
- 7812120174 Forwards LER 78-020/03L-0. FDX:H. 9. Tennesses Valley Authority. 78/12/07. 1p. 94276:009.
- --7812120177 LER#78-020/03L-0 on 781110; during normal pur oper.Reactor & Turbine Bldg & Refueling Zone Ventilation Exhaust Monitor, RM-90-230 became inoperable instr & its sensing line dried out & returned to evc.

 * Tennesses Valley Authority. 78/12/07. 2pp. 94276:010.
- 7812290221 Forwards LERRY8-021/031-0. FDX:H 8. Tennesse Valley Authority. 78/12/21. 1p. 94191:190.
- --7812290224 LERW78-021/03L-0 on 781201: suppression chamber hydrogen monitoring sys failed to meet Tech Spec requirements, Caused by low signal output of torus hydrogen sensor.

 * Tennesse Valley Authority. 78/12/20. 2pp. 94191:191.

DOCKET 50-261 H. B. ROBINSON PLANT, UNIT 2

- F. Security, medical, emergency & fire protection plans
- 7810270147 Responds to 780313 request for add1 info on Fire Protect. Requests delay in responding to Item 8(Lube 0il 8pil) Control 89s for Reactor Coolant Pumpsjuntil 781201 due to late arrival of design info.
 UTLEY.E.E. Carolina Power & Light Co. 78/10/20. lp. 94037:007.
- 7811270136 Forwards NRC staff position & request for add1 info re subj facil Emergency Plan.Requests submission of rev plan w/in 90 days. BCH-ENCER, A. Decreting Reactors Branch 1 (Pre 790625). 78/11/09. 5pp. 94271:309.
- 7812110133 Forwards add1 info re fire protec prog for subj facil in response to Items#8,#12 of NRC 780313 itr. Info covers lube oil spiil control sys for reactor coolent pumps & flame reterdent coatings.

 UTLEY.E.E. Caroline Power & Light Co. 78/12/05. 4pp. 94339:357.
- Q. Adjudicatory correspondence
- 7812140061 NRC Staff is directed to Furnish ABLE & Other parties in proc w/current status of final suppl to SER Staff is also directed to furnish Bd & all parties w/detailed status rept of enu devs in case once each month.

 MOLF, J.F. Atomic Safety and Licensing Board Panel. 78/12/05. 299-74127:326.

J Insurance & indomnity information

- 7812190118 Forwards ltr of 781214 to NRC advising that funds have been transferred to NRC in amount of \$25.400 to cover indemnity fee for Lic#DPR-23 Requests refund resulting from reduction of indemnity fee.

 LANCASTER. J L. Carolina Power & Light Co 78/12/14 ip. 94374 280
- --7812190123 Advises that funds have been transferred to NRC in amount of \$25,400 to cover indemnity fee for Lic#DPR-23 NRC invoice not enc1 LANCASTER, J. L. Carolina Power & Light Co 78/12/14 IP.

P Operating license stage documents & correspondance

- 7810110108 Requests submittal data for Flume Retardant Coetings be extended to 781201 in reply to 780313 ltr UTLEY.E.E. Carolina Power & Light Co. 78/10/05. ip. 94066:354.
- 7810310233 Forwards Amend 34 to License DPR-23 safety evaluation & notice of issuance.
 BCHMENCER.A. Operating Reactors Branch (Pre 790625). 78/10/06.
 2p. 74091 001.
- --7810310237 Amend#34 to Liz WDPR-23 changing Tech Spec re containment spray additive valves & refueling water storage tenk outlet valve test requirements.

 SCHMENCER.A. Operating Reactors Branch i (Pre 790629) 78/10/06.

 4pp. 94091:003.
- --7Biddio24: Safety Evaluation supporting Amend 84 to License DPR-23

 * Operating Reactors Branch (Pre 790625) 78/10/06 Opp.
 94091:007
- ~-7810310246 Notice of Issuence of Amend 04 to Litense DPR-23. SCHWENCER.A. Operating Reactors Branch i (Pre 790625) 78/10/06 3pp. 94091:010
- 7810200196 Forwards Amend#33 to Facil Open Lic#DPR-23 for subj Pacil revising tech specs as requested in 780813 ltr.w/Notice of Issuence.

 8CHERCER, A. Openating Resctore Brench i (Pre 790628): #8/10/10.
 388.
- --7810200199 Amend #33 to Facil Open LichDPR-R3 revising tack space ra CFI organizational changes. Wencl release of tack space. BCHWENCER, A Departing Reactors Branch 1 (Pre 790625). 78/10/10. 247pp.
- --7Bi0200201 Notice of Issuence of Amend#33 to Fatil Oper Lit#DPR-23. BCHMENCER.A. Operating Reactors Branch i (Pre 790625). 7B/10/10. Spp.
- 7811210273 Nutifies util of 781205 seminar in Atlants to discuss new Model Rod Effluent Tach Space & encl seminar info sheet, registration form, & proposed agends.

 0'REILLY, J. P. Region 2, Atlants, Office of the Director 78/11/09.
 5pp. 94485:162.
- 7811290406 Forwards NRC staff paper policy session item (SECY-78-854) relicenses reg performance eval. Three methods for eval are: statistical, trend analysis & regional survey method. W/o encl. O'REILLY.J.P. Region 2. Atlanta. Office of the Director. 78/11/18. App. 94180:099.
- 7812180033 Notice of workshops re implementation of training & qual requirements contained in Append B of lOCFR73 Requests pre-workshop registration of attendees to facilitate sending out math W/encl Registration Form & List of Locations.
 MILLER, J. R. Assistant Director for Bite & Bafeguards (Pre 791030).
 78/11/15. 5pp. 94133:014.
- 7812190023 Forwards Rev#i "Draft Radiological Effluent Tach Space" for PHR's(MUREO-0473) & "Preparation of Radiological Effluent Tach Space for Nuc Pur Plants" (NUREO-0133).

 0RINES.B.M. Assistant Director for Engineers & Projects (Pre 790625). 78/(1/15. App. 94214:306.
- 7812150064 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/encl ANO: 7812080207. SCHMENCER. A. Operating Reactors Brench 1 (Pre 790625). 78/11/28.6pp. 94210:145.

- 7812290114 Emphasizes importance of submitting accurate & complete infeto NRC by licensees & applicants life submitted must be substantiated by date & calculations Licensee must notify NRC of any inaccuracies or sufferement action will result DAVIS.J G. Office of Inspection & Enforcement. Office of the Director 78/12/06 2pp 94133 228
- G. Inspection reports. IE Bulletins & correspondence
- 7810260063 Forwards IE Inspec Rept#50-261/78-20 on 780807-10 during which no items of noncompliance were noted BUTHERLAND. J T Region 2. Atlanta. Fuel Facility & Materials Safety Branch 78/09/15 2pp. 94392 320
- 7810260067 iE Insper Rept#50-261/78-20 on 780807-10 during which ho items of noncompliance were noted Major areas inspected included radiological environ monitoring prop.mgt controls & inspec of environ monitoring stations.
 PEERY, W W , HUFHAN, J. W. Region 2, Atlanta. Fuel Facility & Materials Safety Branch 78/09/12 4pp 94392:316
- 7810310138 Forwards IE Inspec Rept#50-261/78-19 on 780807-10 during which no items of noncompliance were noted LONG-F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 78/09/19. 2ps. 94090 160
- --7810310144 iE Inspet Rept#50-261/78-19 on 780807-10 during which no items of noncompliance were noted Major areas inspected included, training progs for nonlicensed personnel & operator requel prog KELLOQG, P.J., BRADFORD, M.H. Region Q. Atlanta, Reactor Operations Nuclear Support Branch, 78/09/19, 3pp. 94090-162
- 9811080288 Forwards IE Inspec Rept#80-261/78-21 on 780822-25 during which no items of homompliance were noted.
 LONG-FO. Region 2. Atlanta. Resider Operations Nuclear Support Branch 78/09/27. Epp. 94406 189.
- --7811080289 IE Inspec Rept#50-261/78-21 on 780822-23 during which no items of noncompliance where noted. MCHENRY:T.J. Region 2. Atlanta Reactor Operations Nuclear Support Branch. 78/09/26 App. 94406 191
- 7810110226 Ack receipt of 780713 ltr informing NRC of steps taken to correct violations noted during imspec#50-261778-15.
 LCNO.F.J. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch. 78/09/28 ip 03555.287
- --7810110227 Responds to 780817 NRC itr re violation noted in Inspec Repts#80-261/78-15 Corrective actions Interlock sys tested when modification completed. Checkout procedure to be implemented. FURR.B.J. Carolina Power & Light Co. 78/09/13 2pp. 94062:169.
- --7810110231 Forwards IE Inspet Repts#50-261/78-15 on 780705-07 & Notice of Violation LCN9.F.J. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch 78/08/17 2pp. 94062:171.
- --7810110233 Notice of Violation from inspec on 780705-07 + Region 2: Atlanta, Reactor Operations Nuclear Support Branch, 78/08/17 ip. 94062:173
- --7810110236 IE Inspet Rept(\$1850-261/78-15 on 780705-07 during which item of noncompliance was noted no tests of interlock systimate mod MARTIN.R.D., BURNETI.P.T. Region R. Atlanta, Reactor Operations Nuclear Bupport Branch. 78/00/15 4pp. 94062:174.
- 7810230013 Act receipt of 781002 itr informing NRC of steps taken to correct violations noted during Inspect90-261/78-17. LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/11. ip. 94169:193.
- --7810230020 Responds to 780908 NRC ltr re violations noted in Inspec Rept#50-261/78-17. Corrective actions, review of periodic tests & operating procedure checklists & grag to insure compliance w/latest rev will be dev by 781231. BANKS, H.R. Caroline Power & Light Co 78/10/11 2pp. 94169: 194
- --7810230023 Forwards IE Inspec Rept#50-261/78-17 on 780801-04 & assoc Notice of Violation. LCNO.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/08. 2pp. 94169.196.
- --7810230025 Notice of Violation from Inspec on 780801-04.

 * Region 2. Atlanta: Office of the Director. 78/09/08. lp. 94169:198.

- --7810230027 IE Inapec Rept#50-261/78-17 on 780801-04 during which I item of noncompliance was noted failure to dist &/or use current revs of plant procedures

 * Region 2: Atlanta: Office of the Director: 78/09/08. Spp. 94169:199
- 7810230366 Forwards I& Circular#78-17. (See ANO.7810230221, Docket 50-133, 7810431 DCREILLY, J.P. Region 2. Atlanta, Office of the Director. 78/10/13. ip. 94169-165.
- 7811220254 Forwards IE Inspec Rept#50-261/78-22 on 780912-15 during which no items of noncompliance were noted LONG,F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/10/16. 2pp. 94379-318
- --7811220286 IE Inspec Rept#30-261/78-22 on 780912-15 during which no items of noncompliance were noted Major areas inspected into: inspec of followups of licenses event.noncompliance, headquarters request IE Circulars MCHENRY, T. J., DANCE, H. C. Region 2. Atlanta, Office of the Director 78/10/16 5pp. 94379.320.
- 7810310122 Transmite inservice inspec prog for pump & valve testing & weld inspec progs. Also transmite 3 copies of remaining rev sys drawlings not submitted during 780822 & 23 meetings. Encl available in CF only.

 UTLEY/E E Carolina Power & Light Co. 78/10/25 2pp. 94090:027.
- 7812070301 Forwards IE Inspec Rept#50-261/78-23 on 781002-06 & Notice of Violation.
 SUTHERLAND.J.T. Region 2. Atlents. Fuel Facility & Materials Bafety Branch. 78/10/30. 2pp. 94355:329.
- --7812070309 Natice of Violation from Inspec on 781002-06. * Region 2, Atlanta: Fuel Facility & Materials Safety Branch. 78/10/20 ip. 94355:331.
- 7812060288 Forwards IE Inspec Rept#30-261/78-25 on 781017-19 during which no items of noncompliance were noted. KENNA-H.B. Region 2. Atlanta. Safeguards Branch. 78/11/01. 2pp. 94372:307.
- --7812060293 IE Inspec Rept#50-161/78-25 on 781017-19 during which no items of noncompliance were noted. Major areas inspected incl:lic's physical protec prog as implemented by approved security plan.

 DAVIS.C.L. Region 2. Atlanta. Safeguards Branch. 78/11/01. 3pp. 94372:309.
- 7811130087 Forwards IE Circular 78-18.
 D'RELLLY, J.P. Region 2. Atlanta, Dffice of the Director, 78/11/96.
 1p. 94113:197
- 7B12150057 Forwards IE Inspec Rept#50-261/78-24 on 781003-06 during which no items of noncompliance were noted.

 LONG F.J. Region 2. Atlants. Reactor Operations Nuclear Bupport Branch. 78/11/07. 2pp. 94210:255.
- --7812180063 IE Inepec Rept#50-261/78-24 on 781003-06 during which no items of noncompliants were noted Major areas inspected inclineviews audite. IE Bulletin & licensee event followup & licensee action on previous inspec repts.

 MCHENRY, T. J., BELISLE, Q. A., DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/07. 7pp. 94210:257.
- 7811170127 Refers to 780912 CPL ltr re review of valves for pressure isolation function:concludes that all sgs w/high to low pressure interface have enough overpressurization protects that valves do not need to be recategorized & leek test.

 UTLEY.E.E. Carolina Power & Light Co. 78/11/09. 1p. 94048:290.
- 7812120185 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Bafeguards Newsletter. KENNA, H. B. Region 2. Atlanta. Bafeguards Branch. 78/11/17. 4PP. 94277:083.
- 7812040359 Forwards IE Bulletin#78-12A suppl to IE Bulletin 78-12. W/encl AND:7811300055. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/94, 5pp. 94127:143.

- 7812070039 Ack receipt of 781106 ltr informing NRC of steps taken to correct violations noted during inspec#50-261/78-18
 SUTHERLAND.J.T. Region 2. Attenta, Fuel Facility & Materials Sefety Branch 78/11/28, ip. 94344.303
- --TB12070065 Responds to NRC 781011 ltr re violation noted in lingua Rept #30-261778-18 Corrective actions batteries were removed from instruments & parper number of respirators were restored. FURRIB J. Carolina Power & Light Co. 78/11/06. 2pp. 94344:304
- --7812070069 Forwards IE Inspec Rept#50-261/78-1B on 780807-11 & Notice of Violation.

 BUTHERLAND.J T. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 78/10/11 2pp. 94344 306
- --7812070071 Notice of Violation from inspec on 780807-ii. 4 Region 2. Atlanta, Office of the Director. 78/10/ii. ip. 94344:308.
- --7812070075 IE inspet Rept#50-261/78-18 on 780807-11 during which I lee of noncompliance was noted plant access emergency it had survey instrument w/batteries left in & had the wrong number of respirators. PERROTTI, D.J., HUFHAM, J.W. Region 2. Atlanta, Fuel Facility & Materials Sefety Branch. 78/10/11. 19pp. 94344:309
- 7812130241 Ack receipt of 781127 ltr informing NRC of steps taken to correct violations noted during inspec#30-261/78-23.

 8UTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Sefety Branch. 78/12/07 lp. 94336-098.
- --7812130251 Responds to NRC 781030 ltr re violation noted in Insp Rept 50-261/78-23 Corrective actions: radioactive control personnel instructed in drum exterior smear procedure on 781005. BANGS, H. R. Carolina Power & Light Co. 78/11/27. 2pp 94336:099
- 781229008: Forwards IE Bulletin 78-14.

 O'REILLY, J. P. Region 2: Atlanta: Office of the Director. 78/12/19.

 Zpp. 02693:204
- R. Periodic operating reports & related correspondence
- 7810190270 RD: on 781003; both containment spray pumps were inoper due to air binding Event placed containment spray sys in condition less conservative than least conservative aspects of section 3.3.2.1 b of Tech Specs.

 8TARKEY, R. B. Carolina Power & Light Co. 78/10/04. ip. 94052:013.
- 7810160147 Forwards Monthly Oper Rept for Bept 1978.
 BANKS, H. R. Carolina Power & Light Co. 78/10/10. 1g. 94001:350.
- --7810160149 Monthly Open Rept for Bept 1978. WATFORD M.L. Caroline Power & Light Co. 78/10/03 4pp. 94001;351.
- 7811160119 Forwards Monthly Oper Rept for Oct 1978.
 BANKS, H.R. Carolina Power & Light Co. 78/11/09. 1p. 94135:174.
- --7811160120 Monthly Open Rept for Oct 1978. WATFORD M.L. Caroline Power & Light Co. 78/11/02. 4pp. 94135-175
- 7812010232 Forwards corrected pages#12 & 14 to Semi-annual Effluent & Waste Disposal Rept for 780101-780630.
 BANKS, H. R. Ceroline Power & Light Co. 78/11/21. 4pp. 74409: 339.
- 7812130348 Forwards Monthly Oper Rept for Nov 1978.

 8ANKS, H. R. Caroline Power & Light Co. 78/12/11. 1p. 94418: 132
- --7812150351 Monthly Oper Rept for Nov 1978. WATFORD: M.L. Carolina Power & Light Co. 78/12/06. Spp. 74418: 133.
- 9. Reportable occurrences, LERs & related correspondence
- 7810100048 LERM78-022/03L+0 on 780901: momentary loss of 480 volt 3 phase AC pur to MCC-5 occurred due to decreasing spring tension in knife blade contact of safety switch. Switch to be replaced by 2 ciruict breakers. BYARKEY,R.B. Carolina Power & Light Co. 78/10/02. 3pp. 94032:183.
- 7810100043 Forwards LER#78-021/03L-0. BANKS,H.R. Carolina Power & Light Co. 78/10/02. 1p. 94032:162.

- 7610270215 Forwards LER#78-026/01T-0.
 BANKS-H.R. Carolina Power & Light Co. 78/10/16. 2pp. 94053:229.
- --7810270226 LER#78-026/017-0 on 781003 During normal oper "A" & "B" containment spray pumps failed to meet the Delta P requirement due to air bining Pumps vented at 2150 making them oper.

 STARKEY.R.B. Carolina Power & Light Co. 78/10/16 lp. 94053:230.
- 7910310123 Forwards LERM78-022/03L-0. FURR, 8.J. Carolina Power & Light Co. 78/10/20. 1p. 94090:126
- --7810310127 LER 78-022/00L-0 on 780921 during full pur oper a primary to secondary leak was detected in A Steam Generator of 0.620PM. Caused by failure of 2 steam generator tubes. BTARKEY, R. B. Carolina Power & Light Co. 78/10/20. 2pp. 94090:127.
- 7810310143 Forwards LER#78-023/03L-0.

 BANKS-H R. Carolina Power & Light Co. 78/10/23. ip. 94090:171.
- --7810310133 LERR78-023/03L-0 on 780722. While proceeding from hot to cold shutdown the concentration of boric acid storage tank 8 was 22796PPM, due to insufficient sampling during betching & tank A level was low as result of borating the RCS.
 STARKEY, R. B. Carolina Power & Light Co. 78/10/23. 2pp. 94090 172.
- 7810310219 LER #78-024/03L-0 on 781001: engine-driven firs water pump failed to start due to moisture in distributor cap. Caused by heavy rains & access door being left open. Moisture removed & engine test started w/satisfactory results on 781006.

 BTARKEY,R.B. Carolina Power & Light Co. 78/10/25. 2pp. 94090: 324.
- 7811090186 Forwards LERW78-025/03L-0.

 BANKS, H. R. Carolina Power & Light Co. 78/11/01. 1p. 94038: 233.
- --7811090191 LER#78-025/03L-0 on 781003: during normal oper PPS leakage past Containment Purge Outlat isolation valve 30-FR was in excess of Tech Spec limits due to normal wear of Nordel rubber seat.

 81ARKEY.R.B. Cerolina Power & Light Co. 78/11/01. 2pp. 94038:234.
- 7812140163 Forwards LERW78-027/03L-0.
 BANKS,H.R. Carolina Power & Light Co. 78/11/11. lp. 94133:306.
- --7812140165 LERW78-027/03L-0 on 781109: w/reactor at full pwr,instr air supplies to RHR flow controls valves RHR-605 &RHR-788 were not isolated as require to deficiency in procedure OP-38-C & misunderstanding by operator signing off procedure. BTARKEY.R.B. Caroline Power & Light Co. 78/12/11. Spp. 9413:307.
- 7812270257 Forwards LER#78-027/01T-0.
 8ANKS, H.R. Carolina Power & Light Co. 78/12/19. 1p. 94168:059.
- --7812270263 LER#78-029/017-0 on 781205; determined that 781128 Reactor Protec Bys relay failure was potential generic problem. Relay was stuck in energized position due to thermal deterioration of epoxy adhesive used in manufacture. STARKEY, R.B. Carolina Power & Light Co. 78/12/19. 3pp. 94169:060.
- 7810310210 Forwards LER W78-024/03L-0.

 BANKS, H. R. Carolina Power & Light Co. 78/10/25. 1p. 94090:323.

V. Operator Examinations

- 7810170110 Senior Operator Lic#80P-1426-4 for R.E.Morgan to direct the lic activities of lic operators & to manipulate all controls of subj facil, Lic#0PR-23.

 CQLLINB, P. F. Operator Licensing Branch. 78/11/16. 1p.
- 7810180170 Operator LicMOP-2866-4 for James I Murray to manipulate all controls of subj facil.LicMDPR-23 COLLING.P.F. Operator Licensing Branch. 78/11/16. ip. 94317:099.

- DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT
 F. Security, medical, mergency & fire protection plans
- 7810160122 Describes plan for isolation of reactor bldg fire suppression water for installation of new hose stations. Details corpensatory protec measures for the 10 hours the sys will be disabled MAYER.L.O. Northern States Power Co. 78/10/10. 1p. 94005:172
- 7811140194 Forwards responses to NRC Staff recommendations re-subjfacil fire protec prog resulting from NRC inspec during week of 780731 & contained in NRC ltr of 780905 NBP intends to resolve all NRC concerns by 781231. MAYER, L.O. Northern States Power Co. 78/11/07 10pp 94384:205
- 7812050045 Forwards fire protectinfo from 780731-780804 meeting, Incl
 list ofattendees summary Items NSP agreed to complete in
 response to NRC steff concerns; concerns discussed at meeting
 but not resolved & open items
 IPPCL ITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/24
 26pp. 94334:122

Q. Adjudicatory correspondence

- 7810230337 Requests briefs from all parties re issuance of a full-to like for subj facil pending resolution of anticipated transients w/out scram(ATMB) design Briefs must be filed w/in 30 days of svc of this Order. LAZO.R.M. Atomic Bafety and Licensing Board Panel. 78/10/13. 5p 94167:043.
- 7811070284 Forwards memoa re recent problems in pipe support base pldesign. (AND 7811020332, 7811020336, & 7811020343) LEWIS,8.H. Office of the Executive Legal Director. 78/10/24. ip 94040: 326
- 7811130002 Forwards 780929 memo re results of recent fire protec ret test conducted at Underwriters Lab (See AND: #7810050339, #7810050373.) LEWIB.E.H. Office of the Executive Legal Director. 78/10/24
- 7812050050 NRC Steff request for extension of time re preparation of rept of staff views on implications of & requirements for protec against ATMS for operating nuc pur plants.

 KARMAN.M. Office of the General Counsel. 78/11/09. 3pp. 94334:211.
- 7812130149 Forwards 781017 memo re post-LOCA hydrogen production from the inside containment.
 KARMANIM. Office of the Executive Legal Director. 78/11/22. 1p. 94299:063.
- 7812260044 Request & Motion for Order Prohibiting the Installation Defective Spent Fuel Storage Racks in Violation of Provisional Oper Lic.Request to Institute a proc & Petition for Leves to Intervens. Cert of Svc encl. STENSVAAQ. J. M. OLSON, J. F. Minnesota Pollution Control Agency. 78/12/08. 3ipp. 94021:001.
- --7812260037 Motion of MN Pollution Control Agency is granted & lic is ordered to cease & desist from further installation of any spent fuel storage rack at subj facil pending further order. • Atomic Safety and Licensing Board Panel. 78/12/15. 3pp.

H. General correspondence

- 7812270018 Responds to 781109 ltr expressing concern re fuel rack swelling at subj Pacil. Forwards OE Topical Rept NEDD-24076. w/o encl. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/12/0
- --7812270023 Expresses concern over fuel rack swelling at sub; fact Requests OE Rept NEDO-24076 & NAC BER.
 GARDEBRING, S. B. Affiliation Unknown, 78/12/09, ip. 94159: 15

I. Financial information

7810300156 Forwards 1977 Annual Rept & schedule showing 1977 actual Cash Flow to comply with Reg Guide 9.4. Net income by dividence declared instead of dividends paid has been reduced to get retained earnings figure.

CARLEON, L. R. Northern States Power Co. 78/10/23. 2pp. 94034: 1

- 7810170099 Responds to 780807 NRC request for surveillance & info re Reactor Protec Bys Pur Supply Design Final details on any facil or spec mod will be submitted by 790201 when studies MAYER, L. D. Northern States Power Co. 78/10/12, 3pp. 94270:089.
- --7810170262 States that 781012 util response to NRC re Reactor Protec Bys Pur Supply contains no restricted or defense info. WACHTER, L. J. Northern States Power Co. 78/10/12. 1p. 94270:092.
- 7810250076 Notifies that starting about 781201 Co will begin to use shipping cask CNST 14-175H(UBA/7094/A) MAYER. L. O. Northern States Power Co. 78/10/12. 1p.
- 7910200078 Mark I Containment Prog--Gen Elec Rept "NEDE-21685-P.Mark I Downcomer Reduced Bubmergence-Functional Assessment Rept" has been transmitted to NRC by Gen Elec via L.U. Sobon's ltr to V. Stello 700802. Rept deals w/tech bases re use 3 ft min. MAYER.L. D. Northern Stotes Power Co. 70/10/13, jp. 94366:341.
- --7810200080 Forwards ltr which covers submitted of info requested by NRC re-containment design of Mark 1. Request contains no restricted or other defense info.

 WACHTER, L. J. Narthern States Power Co. 78/10/13. 19. 94366:342.
- 7810300145 Notifies NRC of high leakage rates for reactor water cleanup sys isolation valves during local leak rate testing on 781020.781021, & 781022 cause for which is under investigation. ELIABON, L. R. Northern States Power Co. 78/10/23. 1p. 94035:126.
- 7811130335 Summary of 780914 meeting w/GE representatives & Mark 1 Owners Group re progress of Long Term Prog w/attendance list & agenda(RD-9-A-Mark), Standards.) QRIMES.C. Plant Bystems Branch (Pre 791030), 78/10/26. 67pp.
- 78:1220138 Forwards Amend#36 to Provisional Operating Lic#OPR-22. which changes Tech Space re limiting conditions for oper & surveillance req for suppression pool water laval. IPPOLITO, T.A. Operating Reactors Branch 3 (Fre 790623). 78/10/30. 2pp. 94074: 225.
- ---7811920140 Amend#36 to Provisional Operating Lic#DPR-22, which changes Tech Specs re limiting conditions for oper a surveillance req for suppression pool water level. W/encl rev Tech Spec. IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/30. 94074: 227. lBpp.
- ---7811220143 Safety Eyal Rept Supporting Amend#36 to LiceDPR-22. States that issuance of emend will not be inimical to the common defence & security or to pub health & eafety.

 # Office of Nuclear Reactor Regulation, Director, 78/10/30. 4pp. 94074: 245.
- --->7811220144 Notice of Issuance of Amend#36 to Provisional Operating Lic Operating Reactors Branch 3 (Fre 790625). 78/10/30. IPPOLITO, T. A. 2pp. 94074:249.
- 78:1270:00 Forwards Amend#37 to Provisional Lic#DPR-92.changing Tech 8pec to improve simmer margin of safety/relief valves. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/06. 94260: 339.
- --7811270103 Amend#37 to Provisional Oper Lic#DPR-92, changing Tech Spec to improve simmer margin of safety/relief valves. ORIMES. B. K. Assistant Director for Engineers & Projects (Pre 790628). 78/11/06. 33pp. 942R3: 249.
- --7811270106 Sefety Evel supporting Amend#37 to Provisional Oper Lic #DPR-22. Concludes issuence of amend will not be inimical to nation or people. * Office of Nuclear Reactor Regulation, Director. 78/11/06. 10pp. 94223: 202.
- --7811270110 Notice of Issuance of Amend#37 to Provisional Open Lic #EDR-22 changing Tech Spec to improve simmer margin of questy/relief valves.

 IMPOLITO, I.A. Operating Reactors Branch 3 (Pre 790625). 78/11/06.

 2pp. 94223:292.

- 7811210307 States that Bechts! has discovered a problem in the s analysis computer prog that analysed subj facil piping sys. Recommends adding one & modifying two restraints on the RHR suction piping.
 - Northern States Power Co. 78/11/13. Ip. 94488
- 7812130135 Notice of workshops re implementation of training & q requirements contained in Append B of IOCFR73 Requests pre-workshop registration of attendees to facilitate sending out met). Wence registration or attenders to racilitate sending out met). Wence Registration Form & List of Locations. HILLER.J. R. Assistant Director for Site & Safeguards (Pre 79)-78/11/15. 5pp. 94212:179.
- 7812180275 Forwards Revel "Dreft Radiological Effluent Tach Spec-BWR's (NUREG-0473) & "Preparation of Rediological Effluent Tech Specs for Nuc Pur Plants" (NUREG-0133). GRIMES.B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. App. 94336:332.
- 7811210334 Notifies that 780707 Itr schedule can not be met. Antithat field verification & insurance review of completed design for turbine lube oil reservoir deluge sys extension will be completed by 790:31.

 NAVER.L.D. Northern States Power Co. 78/11/16. 1p. 94484:3)
- 7811280338 Completion of replacement of existing CR 120A contact retainers will be finished by 790131. Also, replacement of snubber aprings will be decided upon after discussions w/ vendorioriginal replacement springs found defective. HACHTER, L. J. Northern States Power Co. 78/11/16. ip. 94395:
- 7811290367 Requests addl info on 780315 util proposal re Inevo It Testing Prog. Questions cover pump testing prog.valve testing prog & reactor recirculation sys.

 IPPCLITO.T.A. Deersting Reactors Branch 3 (Pre 790625). 78/11 6pp. 94180:029.
- 7812010215 Announces installation of 1 addi restraint & mod of 2 suction piping restraints. Because analysis indicates RHR suction line & supports would have functioned during design basis earthquake, the prob is not an RO.RO hereby retracted. ELIABON.L.R. Northern States Power Co. 78/11/22. 1p. 94409:
- 7812130200 Concludes that the effects evaluated re post-LOCA game of hydrogen in both BWR & PWR pressure suppression type containments do not leed to new significant safety concerns w/encl supporting conclusion. MATTBON, R. J. Division of Bystems Safety. 78/10/17. 48pp. 94289: 042
- 7812050371 Forwards corrected replacement page#157A for subj faci Opec re downcomers to suppression pool. IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/11 3pp. 94408: 896.
- 7812110021 Discusses possible dangers of LOCA in containment purg during normal plant oper Requests either commitment to limit purging or justification for continuing M/encl ANO: 87812090207.
 87812090207.
 1890. 1990: 290.
 1890. 94039: 290.
- 7612070221 Forwards appl for change of Tech Space. Append A. of Ope MAYER, L. D. Northern States Power Co. 78/12/01. 1p. 03555: 0f
- -- 7812070222 Appl for change of Tech Spece, Append A. of Open Little re reduction of minimum specified Low Pressure Coolant Injection delivery capability by 10% to provide reasonable margin between performance & minimum.Watt Ethibits A.B & C. WACHTER, L. J. Northern States Power Co. 78/12/01. 03555: OB3.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meeting & providing task-by-task activity summary for the month. BDBON.L.J. General Electric Co. 78/12/04. 11pp.
- 7812280017 Emphasizes importance of sumbitting accurate & complat to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations.Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS. J. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94131:034.

ressel mat) surveillance prog. Due to a delay by Gen Elec in essembling this info.ukil requests extension of time to irrovide info.

AAYER.L.O. Northern States Power Co. 78/12/11. ip 94133:341.

.2260323 Forwards 781204 NRC itr re mod & installation of defective spent fuel racks at facil pleeding aprived on the Comm by the Nh Pollution Control Agency re this issue Cert of Byc enci. ITEMSVA40. J. Minnesota. Btate of. 78/12/13. 2pp. 94160:114.

'812240328 Responds to 781109 ltr re fuel rack swelling.Forwards QE Topical Rest.NEDG-2407.W/o encl rest.W/encl Cert of Bvc. GARDEBRING.S. Minnesote, State of. 78/12/04. 4pp.

2210190 During surveillance test on 781214 one of four ATMB-Recirc ump Trip reactor high pressure intestru channel sensor elays(Agastat Model#0PBC 750 w/#CF0095 societ)failed to nergize due to societ contact being disengaged.

LIAGON,L. R. Northern States Power Co. 78/12/15. ip. 94279:025.

2060318 Notifies NRC that co will use model CNB-1600 shipping cask o transport redioactive math. Also confirms understanding of A requirements of 10CFR71 governing shipments.

AVEN.L.O. Northern States Power Co. 77/12/27. ip. 94332:039.

1210367 Forwards add1 into re-multiple consecutive safety/relief alve actuation of Mark I containment program.
0BON. L. J. General Electric Co. 72/11/13. 3pp.

Imprection reports, IE Bulletins & correspondence

1300398 Forwards IE Inspec Rept#50-263/78-12 on 780828-30 during hich no items of noncompliance were noted. AVIB.A B. Region 3. Chicago, Fuel Facility & Meterials Safety ranch. 78/09/29. Spp. 94136:324.

311300401 IE Inspec Répt#80-263/78-12 on 780928-30 during which no items of noncompliance were noted. Major areas inspected inclianviron protects confirmatory measurements. JANUBNA. A. A., OBETHANN, M. J. Region 3. Chicago, Office of the Diryctor. 78/09/26. Spp. 94136:326.

1230338 Forwards IE Circular#78-17. (80e ANO:7810230221:Docket 1-313.781013) PPLER.J. Q. Region 3. Chicago, Bffice of the Director. 78/10/13. . 94167:041.

1070074 Forwards IE Inspec Rept#50-263/78-14 on 781012-13 during ith no items of noncompliance were noted. ORELLI.0. Region 3. Chicago. Reactor Operations Nuclear Support ench. 78/10/30. 2pp. 94347:343.

112070078 IE Inspec Rept#50-263/78-14 on 781012-13 during which no items of noncompliance were noted Major areas inspected inclinitial training, replacement training & retraining of licensed & nonlicensed personnel & operators.

HRIGHT.9.C., LITTLE.W.S. Region 3, Chicago, Office of the Director. 78/10/30. 3pp. 94047:345.

140010 Forwards IE Inspec Rept#80-263/78-13 on 780925-29 & Notice Violation.
ORELLI-9. Region 3, Chicago, Reactor Operations Nuclear Support anch. 78/10/31. 2pp. 94119:337.

12140012 Notice of Violation from inspec on 780925-29. R Region 3. Chicago, Dffice of the Director. 78/10/31. 1p.

12140016 IE Inepec Rept#80-263/78-13 on 780925-29 during which i item of noncompliance was noted quality engr did not review & approve the resolution of discrepancies identified during receipt of purchase orders.

4ARPSTER.T. L. MARNICK.R.F. Region 3, Chicago, Office of the Director. 78/10/30. 7pp. 94119:340

.50064 Forwards IE Circular 78-18.

*PLER.J. 9. Region 3. Chicago, Office of the Director. 78/11/06.

94112:183.

incl:preparation for refueling outage prefuel handling activities & fuel handling activities.
WRIGHT,0 C., LITTLE.M.B. Region 3, Chicago, Office of the Director. 78/11/15. Spp. 94159.034.

- 7812050278 Forwards IE Bulletin#78-12A. suppl to IE Bulletin 78-12. M/encl ANO: 7811300055 MEPPLER.J. 9. Region 3, Chicago, Office of the Director. 78/11/24 ip. 94202:165
- 7812260308 Ack receipt of 781121 ltr informing NRC of steps taken to correct violations noted in 781031 NRC ltr. FIORELLIQ. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/12/14. ip. 74160:080
- 7812280065 Forwards IE Bulletin 78-14. KEPPLER.J.O. Region 3. Chicago. Office of the Director. 78/12/19. 19. 03534:354.
- A Pariodic operating reports & related correspondence
- 7810120030 Forwards monthly Open Rept for Bept 1978.
 MAYER, L. D. Northern States Power Co. 78/10/09. 1p. 94471: 335.
- --7810120032 Monthly Oper Rept for Bept 1978. MYRABO.A.L. Northern States Power Co. 78/10/05. App. 94471:3.
- 7811160116 Forwards Monthly Open Rept for Oct 1978.
 MAYER, L. D. Northern States Power Co. 78/11/13. 1p. 94135:166.
- --7811160117 Monthly Open Rept for Oct 1978. MYRABO A.L. Northern States Pawer Co. 78/11/03. 5pp. 94135:1
- 7812110136 Forwards Monthly Oper Rept for Nov 1978, MAYER, L. C. Northern States Power Co. 78/12/08. ip. 94393: 237.
- --7812110140 Monthly Oper Rept for Nov 1978 MWRABO.A.L. Northern States Pawer Co. 78/12/06. 4pp. 94393: 2
- 8. Reportable occurrences, LERs & related correspondence
- 7810110100 Forwards LERWY8-016/03L-0.
 MAYER, L. D. Northern States Power Co. 78/10/06. 1p. 94069:115.
- --7810110183 LER#78-016/03L-0 on 780908: trip of essential MCC 833A s breaker 52-304 resulted in oper in degraded mode permitted by verious limiting conditions for oper Cause unknown.
 SMITH. G.R. Northern States Power Co. 78/10/06. ip. 94413:336
- 7810240117 Notifies NRC that 2 valves leaked in excess of criteria f local leak tests established in Tach Specs. ELIABON:L.R. Northern States Power Co. 78/10/16, Ip.
- 7811240162 LER978-018/03L-0 on 781002: during routine sorveillance to HPCI isolation temp switch Model 17023-6 failed to trip, due to loace wire inside switch. Redundant switches tested satisfatorily.

 HILL-W. J. Northern States Power Co. 78/10/19. 1p. 94456: 301.
- 7810300191 Forwards LERW78-018 03L-0.
 MAYER, L. G. Northern States Power Co. 78/10/25. 1p. 94033:351.
- --7810300195 LER#78-018/03L-0 on 781002:2 primary containment isolat valves.1 in RCIC sys & 1 in RMCU sys.were made inoper dus to personnel error. PEARSON.8.L. Northern States Power Co. 78/10/19. 1p. 94033:3
- 7811240124 Forwards LER#78-017/03L-0.
 MAYER, L. D. Northern States Power Co. 78/10/25. 1p. 94478: 282,
- --7811240126 LERM78-017/03L-0 on 781001: two primary containment isol valves(RCIC & RMCU Bys)were rendered inoperable for 2 minutes due to control document identification error. Isolation valve Tech Bjec requirement amphasized. PEARBON.B.L. Northern States Power Co. 78/10/23, 1p. 94478;2

DOCKETED ITEMS

- 7811280234 Forwards LERB78-019/011-0.878-023/011-0.878-024/011-0.878-025/011-0. 878-025/011-0. 878-025/011-0. 878-025/011-0. 878-026/011-0. 878-026/011-0. 878-026/011-0.
- --7811280239 LERB78-019/01T-0 on 781014: while performing local leak rate tast. "D" outboard MSIV.AO-2-86D was leaking in excess of Tach Spec 4, 7 A. 2. f. Caused by scratch on main seet Seats lapped & valve retested satisfactory TOSIN.P. A. Northern States Power Co. 78/11/22 ip. 6. 94012.147.
- --7811260244 LERF/8-023/017-0 on 781014 while performing local teak rate test "A" outboard MBIV.AD-2-86A was leaking in ercess of T.S. 4.7. A.2.f. Caused by bent value sten & worn lower guide rib Valve stem replaced & lower guide rib rebuilt TOBLN.P.A. Northern States Power Co. 781/1/22 pp. 94012-148
- --7811280249 LER#78-024/017-0 on 781020:during local lest rate test HPCI-9.turbine exhaust line check valve was leading in excess of T.B. 4 T.A. 2. Caused by accumulated dirt on seating surfaces Seats cleaned lapped & retested satisfactorily PEDERBEN, D.E. Northern States Power Co. 78/11/22 1p. 94012 149
- --TB11280253 LERM78-025/OLT-0 on 781021: during local leak rate test.RCIC-9.RCIC turbine exhaust line check valve was leaking in excess of T S. 4. 7. A 2. f. Caused by accumulated dirt on seating surfaces. Seats cleaned & retested satisfactorily.
 HAMMER.S. J. Northern States Power Co. 78/11/22. ip. 94012:150.
- --7811280256 LER#78-026/OiT-0 on 781022: during local leak rate teet.MD-2397 & MO-2398, reactor cleanup isolation valves were leaking in excess of T.S. 4.7. A. 2.4. Coursed by excessive packing gland leakage & improper torque/limit switch settings.

 NOLANJL L. Northern States Power Co. 78/11/22 tp. 94012:151.
- 7812200283 Forwards LER#70-021/03L-0.
 MAYER-L, O. Northern States Power Co. 78/12/14. 1p. 94207:180.
- --7812200287 LER878-021/03L-0 on 781114: during refueling outage while testing RHR SH sys, a pinhole leak was discovered in CV-1729. RHR SH differential pressure control valve. Caused by corrosion & erosion of upper valve body OVERLID. T. H. Northern States Power Co. 78/12/14. 1p.
- 7812200211 Forwards LER #78-022/03L-0.
 MAYER, L. 0 Northern States Fower Co. 78/12/15. 1p. 94162:289.
- --7812200215 LER878-032/03L-0 on 781117: steam leak was discovered in A 1" WYE Strainer, VS-4002, on the main steam equalizer drain line. Leak caused by a defective casting & dev after two days of svc.
 TOBIN.P. A. Northern States Power Co. 78/12/15. jp. 94162:286.
- 7812260193 Reportable occurrence on 781218:MD-2-54A recirc discharge bypass valve would not close, recirc eye mod Valve to be repeired. ELIAGON, L. R. Northern States Power Co. 78/12/19. ip. 94159:196.
- 7612260256 Forwards LERW78-028/03L-0.
 MAYER-L G. Northern States Power Co. 78/12/19, 1p. 94159:356.
- ---7812260258 LER#78-028/03L-0 on 781124: during normal open small steam
 last was discovered in weld of 45 dagree elbow on HPCI steam
 supply line I inch drein line to main condenser due to
 corrrosion Weld repair made at leak Awaiting parts.
 PEDERBERIO E. Northern States Power Co. 78/12/19. 1p.
 94159:337.
- 7612270232 Forwards LER878-029/01T-0.
 MAYER, L. D. Northern States Power Co. 78/12/21. 1p. 94017:141.
- --7812270237 LER#78-029/01T-0 on 781214: High pressure instrument channel relay failed to energize due to disengaged AOASTAT#CR0095 relay socket contact that failed to make contact w/AOASTAT #FP8750 relay contact. Contacts were reengaged. HAMMER.M.E. Northern Beates Power Co. 78/12/21. 1p.
- 7819270241 Forwards LER#78-020/03L-0.
 MAYER, L. O. Northern States Fower Co. 78/12/21. 1p. 94017:150.
- --7812270245 LERW78-020/03L-0 on 781121: during normal pur increase, both indicating lights for MG-2014, LPCI A loop admission valve were out due to blown control pur fuse. Fuse had opened on alight over load for extended time period & was replaced. OVERLID. T. W. Northern States Power Co. 78/12/21. 1p. 94017:151.

- --7812270251 LER#78-027/03L-0 on 781121: during normal oper a ston was found in tee downstream of MD-1197 on the 2" HP Turbing "U" bend drain line to condensar, grobably due to flow of steam & water from restricting orifice into tee TILLY, D. D. Northern States Power Co. 78/12/21. ip. 94017
- DOCKET 50-264 DOW CHEMICAL CO.
- F. Security, medical, emergency & fire protection plans
- 7810300037 Forwards Dow's rev "Security Plan for Subj Facil" Documentable in Central Files only.
 LANOMER.R.R. MCOHANNY, O.L. Dow Chemical Co. 78/10/20. ip-
- J. Insurance & indemnity information
- 7810110098 Forwards signed copy of Amend #9 to Indemnity Agreement #8-34 COALMELL, T. N. Dow Chemical Co. 78/10/05. 1p. 94066:347.
- --7810110101 Amend #9 to Indomnity Apresment #8-34, adding Article payment of premiums.

 SALTZMAN, J. Antitrust & Indomnity Group. 78/10/05. 2pp. 74066: 348.
- DOCKET 50-265 QUAD-CITIEB STATION, UNIT 2
- A. Application/construction stage documents & correspondence
- 7812150228 Classifies lic amend for proposed fuel pool mod as Clas
 IV & I not Classes III & I.Requires addl charge of \$8300 for
 each of the two applite be paid w/in 15 days.
 MILLER.W.D. License Fee Hanagement Branch. 78/12/11. 2pp.
- F. Beturity, medical, emergency & fire protection plans
- 7810120080 Forwards analysis of Electrical Cable Penetration Fire Barrier Test conducted on 780619. Also forwards 3rd party observer rept of test & 5 detailed drawings associated w/test.

 NAUGHTON, W. F. Commonwealth Edison Co. 78/09/29. 44p.
- 7811020349 Responds to 780929 ltr requesting NRC agreement to resp to requests in case of offsite emergency. Under Interagency Agreement DE Chicago Oper Ofc coordinates requests in area. KEPPLER. J. G. Region 3. Chicago. Office of the Director. 78/10/ip. 94241:087.
- --7811020275 Requests NRC assistance in event of emergency at subj KALIVIANAKIS:N. Commonwealth Edison Co. 78/09/29: ip. 94241:088.
- 7812120195 Informs NRC name of fire protec consulting firm hired to CEIL to fulfill requirements of "Fire Protec Organization of Nuc Plant Fire Protec Functional Responsibilities Admin Controls & GA" will be submitted 790201.

 NAUGHTON, M. F. Commonwealth Edison Co. 78/11/30. 2pp.
- Adjudicatory correspondence
- 7811090259 Bd grants request by Citizens for a Better Environ & Na Resources Defense Council for permission to file response to answers opposing their petitions to intervene by 781103. MILHOLLIN. Q. L. Atomic Safety and Licensing Board Penel. 78/11/1p.
- 78iii6002i Grants request by licensee CEIL to have until 78ii07 to respond to 78i0i3 Order of ABLB permitting NROC & Citizens for a Better Environ to file response to answers opposing their petitions to intervene in proceedings re sub; facils. MILHOLLIN, Q.L. Atomic Befety and Licensing Board Penel. 78/11/1 jp.
- 7812110284 Cantels special prehearing conference scheduled for 781; Conference shall be held on 790111 in Tax Courtroom of US Courthouse & Fed Bldg, Chicago, IL. Parties & petitioner must rept to Board by 781215 re progress of negotiations.

 MILHDULIN, Q. L. Atomic Safety and Licensing Board Panel. 78/12/(2nn.
- 7810190131 Answer by CEIL to Petition to intervene filed by Atty of af IL on 780920. Agrees that Atty Gen has standing, but asserts there are no genuine issues to be heard at hearing. Requests that Atty Gen request for EIS be denied.

IBSAN, A. Z. Natural Resources Defense Council. 78/10/10 4pp.

300324 NRC Staff Answers to Council for Citizens for Setter From & Natural Resources Defense Council's Petition for the to Intervene Staff opposes granting petition. W/Cert SMC.

DARD, R. J. Diffice of the Executive Legal Director. 78/10/10

310223 Staff Answer to State of IL petition for Leave to Intervens off does not oppose admission of IL as party to proc. DDARD.R.J. Diffice of the Executive Legal Director 78/10/10.

010063 Petition for leave to intervene & for hearing filed by titens for Better Environ & Natural Resources Defense uncl. Request for leave to file response to answers osing petition is granted. LHOLLIN.G.L. Atomic Bafety and Licensing Board Panel. 78/10/13.

130223 "Natural Resources Defense Council Response to Commenwealth son's & Staff's Answers to Petition for Leave to tervene. "Intervenor urges Bd to establish a schedule for isfing challenges to contentions. IBMAN.A. 2. Natural Resources Defense Council 78/10/23. 16pp.

130214 NRC request to file response to NRDC response to Comm Ed & Canswers to patition for leave to intervene dat 781023. grented, reply will be served by 781103. Cent of Svc encl. DDARD.R. J. Office of the Executive Legal Director. 78/10/24

200070 Request by Comm Ed for leave to file a response to NRDC ief which argues that organizations may show standing to rticipate in NRC proceedings merely by alleging that they present anonymous members Cert of Bvc encl.

220010 NRC Staff's Response to NRDC's Response to Answers to tter's Petition for leave to intervene.NRC asserts that DC has not demonstrated its standing to intervene as

tter of right.Cert of Svc encl. DDARD,R. J. - Office of the Executive Legal Director. - 78/11/03.

200003 Special Prehearing Conference in proceedings re subj facils

li be held on 781215 in Rock Island. N. All parties to oc & all petitioners to intervene must attend & ould be prepared to discuss all issues. LFOLLIN. G. L. Atomic Bafaty and Licensing Board Panel. 78/11/09.

130122 Gives notice that A Bielawski enters an appearance on behalf applicant CEIL in proceedings re subj facils. Cert of Svc cl.

ELAWSKI, A. P. Isham, Lincoln & Beale. 78/11/21. 2pp.

270230 Proposed stigulation re NRDC & CBE's representation of named members in Dresden-Quad Cities transshipment is not ceptable to NRC.NRC position on NRDC's petition to tervens remains as stated in 78:103 pleading.
DDARD,R. J. Office of the Executive Legal Director. 70/12/06. 1p.

28027: Porwards"Btipulation" of NRDC.CBE & Commonwealth Edison Co-identification of members of NRDC & CBE to prove they we interests that may be affected.No agreement w/Reg Staff s been reached.

194AN.A. Z. Natural Resources Defense Council. 78/12/08. 1p.

12280280 Parties agree that NRDC & CBE have adequately indentified at least one member whose interest may be adversely effected by the proposed action. Auth to represent these interested members has not been agreed upon. ROIBMAN. A. Z. Natural Resources Defense Council. 78/12/11. 3pp.

270133 Special Prehearing Conf Scheduled for 790111 is postponed til 790201. Parties & petitions are excused from quirement to rept to Bd by 781215 re negotiations ogrese. bildLIN, Q. B. Atomic Safety and Licensing Board Panel. 78/12/13.

transfer & storage between facils. W/o encl.
GODDBARD, R. J. Office of the Elecutive Legal Director 78/11/17. 1p.

J. Insurance & indemnity information

7812190109 Requests refund of \$6 per mut in sicess indemity fee paid for LiceDPR-2. #DPR-19. #DPR-25. #DPR-29. #DPR-30. MDPR-39. #DPR-39. PDOLE, R. D. Commonwealth Edison Co. 78/12/13. 1p

P. Operating license stage documents & correspondence

7812080026 FOIA request for all records incl:quantity of radioactive matl disposed of from former Manhatten proj in IL known as Chicago Piles#1.2 & 3 Matl disposed of in IL by Lindsay Cos at Morris Pacil & Drasden Pacil. HANSELL.D Illinois, State of. 78/11/06 2pp.

7812080149 Requests add) info within 60 days re 761106 & 780221 submittals on instru setpoints.

IPPCLITO T. A. Operating Reactors Branch 3 (Pre 790625). 78/12/05 Эрр. 94104: 351.

7812110001 Discusses possible dangers of LOCA in containment purging during normal plant open. Requests either commitment to limit purging or justification for continuing. W/ancl ANG: #7812080207.

IPPOLITG. T. Descript Reactors Branch 2 (Pre 790625). 78/11/29. 1PPOLITO T. Ope 8pp. 94339:089.

7810100027 Forwards evaluation of reactor protect sys pur supplies proposing over-voltage alarm in control room of subj facils. TURBAK.M.8. Commonwealth Edison Co. 78/10/04. Spp.

7BiOl40112 Resvalustion of Lic amend fees for inter-station spent fuel transfer for sub, facils as requested by 780817 its shows that the class 1 & 3 fees path for each station are correct.
MILLER.M.O. License Fee Management Branch. 78/10/10. 1p.

7811130335 Summary of 780914 meeting w/GE representatives & Mark 1 Owners Group re-progress of Long Term Prog w/ettendance list & agenda(RD-9-A-Markl).Standards.) GRIMES.C. Plant Systems Branch (Pre 791030), 78/10/26 67pp.

7811020322 Request to amend Bection 6. 6. 8. 1. 0 of Append A to Tech Brece Discussional Request to ameno Dection G.O. 5.10 or Append A to to facily open its re-reporting req for reactivity anomalies is w/drawn.as Reg Guide"Interpretation"by ARC on 780701 does not req rept for reactivity increase of less than 5 secs. REED.C. Commonwealth Edison Co. 78/10/26. Spp.

7811030161 Forwards proposed Amend changing Tech Spece w/regard to updating station organizational charts. Changes have received onsite & offsite approval. REED C. Commonwealth Edison Co. 78/10/26 9pp.

7811140105 Responds to 780516 NRC ltr requesting addl info re reactor vessel metal survaillance specimen fluence values at time of withdrawal, w/projections based on dosimetry results of praviously tested capsules & BOX capacity factor. W/a encl. TURBAK.M.S. Commonwealth Edison Co. 78/11/03. 2pp.

7811140002 Notifies applicant of 781128 NRC-sponsered Seminar re Model Radiologicsl Effluent Tach Space for Nuc Pur Plants w/encl Seminar Info Sheetito be completed & returned by 78117) & Proposed Agenda. KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 78/11/07. Брр.

7811300038 Forwards Amend#39.#37.#48 & #47 for Lics DPR-19.DPR-25. OPR-19 to DPR-30 respectively, Amends revise Tech Spect re operating temp to pressure limits. Also forwards Bafety Eval & Fed Register Notice. IPPOLITOIT, A. Operating Reactors Branch 3 (Pre 790625). 78/11/13.

~~7811300073 Amend#47 to the Operating Lic rev Tech Space re operating teng & pressure | finite.
IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/13. Вор.

--7811300077 Safety Eval Rept in support of Amend#39, #37, #48 & #47 to Oper Lics DPR-19, DPR-25, DPR-27 & DPR-30, respectively. # Office of Nuclear Reactor Regulation, Director 78/11/13. App.



- --7811300085 Notice of Issuance of Amend#39, #37, #48 & #47 to Oper Lics DPR-19, DPR-25, DPR-29 & DPR-30, respectively. IPPOLITO, T.A. Operating Reactors Granch 3 (Pre 790625) 78/11/13 2pp
- 7812180044 Notice of wortshops re implementation of training & qual requirements contained in Append B of 10CFR73 Requests pre-workshop registration of attendees to facilitate sending out matl M/enc) Registration Form & List of Locations.
 MILLER. J. R. Assistant Director for Site & Safeguards (Pre 791030) 78/11/13 5pp 94133 049
- 7812180266 Forwards Rev81 "Draft Radiological Effluent Tech Specs" for 8LR's(NURE0-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NURE0-0133) ORINES.8 M. Assistant Director for Engineers & Projects (Pre 790625) 78/11/15 6pp. 94365:349
- 7812050107 Forwards rev page to Topical Rept CE-1-A: "Qual Assurance Prog. Rev 6: " Rev mellects Reg Quidel 28 & 1 31 rev TURBAK-M B Commonwealth Edison Co 78/11/17 2pp
- 7811280213 Forwards current lic status list for subj facils REED.C Commonwealth Edison Co 78/11/20 9pp
- 7811280246 Forwards "Projected Fluence Values at Withdrawal for the Capsules Designated to Meet the Requirements of 10CFR30 Append H " Table I to be attached to 781103 ltr to Ippolito TURBAK-M B Commonwealth Edison Co 78/11/20. 2pp
- 7812050166 Informs NRC that response to 781118 NRC ltr relic amend appl & numership for subj facil will be made by Commonwealth Edison
 MILLER, R U. lowe-lilinois Oas & Electric 78/11/24 lp 94371, 260.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held & providing tast-by-task activity summery for the month BDBON-L J Comeral Electric Co 78/12/04 11pp
- 7812280129 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants Info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB.J.Q. Optice of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp.
- 7812190097 Accepts topical reptMCE-1-A RevM6."Comm Ediath Co Quality Assurance Prog for Nuc Generating Stations." Requests submittal of 36 copies. HAA88.W.P. Quality Assurance Branch. 78/12/13. 1p.
- 7812270225 Provides addi info re gasedus releases described in 781030 ltr.Cause of increase in off-gas activity is believed to be fuel leasers & corrective action for high gaseous activity is to maintain minimum leakage by close surveillance.
 KALIVIANAKIS.N. Commonwealth Edison Co. 78712/13. 2pp 74017:139.
- G. Inspection reports. IE Bulletins & correspondence
- 7812040033 Forwards 1E Inaper Repts#50-254/78-21 & #50-265/78-22 on 780821-25, 780831, 780905, 780906-07, 780913-14, 781003-04 & Notice of Deviation. FIDRELLI, G. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/31, 2pp. 94129:092
- --7812040038 Notice of Deviation from inspec on 760821-25.

 Region 3. Chicago, Office of the Director. 78/10/31. ip. 74127:074.
- --7812040046 IE Inspec Repts#30-2543/78-21 & #50-265/78-22 on 780821-25 during which i item of deviation was noted excessive amounts of oil stored near vital cabling smoking in No Smoking Area. JACKIM. I. N. BROWN. C. H., KNOP. R. C. Region 3, Chicago, Office of the Director, 78/10/30. App.
- 7811010067 Fdrwards 1E Inspec Repts M50-254/78-19 & M50-265/78-20 on 780713-14, 780719-20, 780726-27, 780802-03, & 780810-11, during which no items of noncomplaince were noted, F1D%ELLI.9. Region 3. Chicago, Reactor Operations Nuclear Support Branch, 78/09/19, 2pp. 94270:103.
- --7811010076 IE Inspec Repts#50-254/78-19 & #50-265/78-20 on 780713-14 780719-20.780726-27.780802-03. & 780810-11.during which no items of noncompliance were noted Major areas inspected included plant oper & out-of-svc activities.

 JACKIN-I.N. NOP.R.C. Region 3. Chicago. Office of the Director. 78/09/18. App. 94290:105.

- 7811080077 Forwards IE Inspec Repts#50-254/78-20 & #50-265/78-21 on 780622-25, 29,0901 during which no items of noncompliance were noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch, 78/10/02 2pp. 94271 124
- --78i1080080 IE Inspec Repts#50-254/78-20 & #30-265/78-21 on 780822-25.
 29.0901 during which no items of noncompliance were noted
 Major areas inspected included radioactive waste sys.
 effluent releases & effluent control instru

 HUETER, L. J. FISHER, W. L. Region 3. Chicago, Fuel Facility &
 Materials Safety Branch 78/10/02 lipp
- 7810110293 Act receipt of 780901 ltr informing NRC of steps taken to correct violations noted in 780810 NRC ltr KEPPLER, J G Region 3. Chicago. Office of the Director 78/10/03 2pp 03956 074
- 7811070002 Ack receipt of 781006 ltr informing NRC of steps taken to correct violations noted in 780920 Notice of Violation.
 H1ND J A Region 3, Chicago. Safeguards Branch 78/10/27 ip 94037-072
- 7812050011 Forwards IE Inspec Repts#50-010/78-29.50-237.-254.-295.-304/78-25.50-249/78-27 & 50-265/78-26 on 781002 during which no items on noncompliance were noted REPFLER.J Q Region 3. Chicago. Office of the Director. 78/10/30 2pp.
- 7812060225 Forwards IE Inspec Repts#50-254/78-24 & 50-265/78-23 on 781004-06 during which no items of noncompliance were noted HEISHMAN.R F Region 3, Chicago. Reactor Construction & Engineering Support Branch 78/10/31. 2pp 94382:174.
- --7812060230 IE Inspec Repts#B0-254/78-24 & #B0-265/78-25 on 781004-05 during which no items of noncompliance were noted Major areas inspected incl: IE Bulletins & Circular followup relative to qual of elec equip.
 HU0HES, J. SPESSARD, R. L. Region 3, Chicago, Défice of the Director. 78/10/31. 6pp 94582:176.
- 7811190063 Forwards IE Circular 78-18
 KEPPLER J O. Region 3. Chicago, Office of the Director. 78/11/06.
 ip.
- 7812060020 Responds to 781031 NRC itr re violations noted in Inspec Repts#30-254/78-21 & #50-265/78-22 Corrective ections eress reg housekeeping were cleaned no smoking rules enforced, procedure GAP 200-13 is being rev. REED.C. Commonwealth Edison Co. 78/11/20 2pp. 94415:333.
- 7812050287 Forwards IE Bulletin#78-12A.suppl to IE Bulletin 78-12 W/encl AND: 7811300055 KEPPLER. J. G. Region 3. Chicago. Office of the Director 78/11/24 lp.
- 7812260292 Ack receipt of 781120 ltr informing NRC of steps telen to correct violations noted in 781031 NRC ltr.
 FIORELLIQ Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/12/14 ip. 94160:045.
- 7812290026 Forwards IE Bulletin 78-14.
 KEPPLER.J O Region 3. Chicago. Office of the Director. 78/12/19.
 in.
- R. Periodic operating reports & related correspondence
- 7810250111 Monthly performance rept for Bept 1978 Includes maint summary, everage daily unit pur level, refueling info request & LER's.

 ** Commonwealth Edison Co. ** Towa-Illinois Gas & Electric.
 78/09/30. 25pp. 94368:332.
- 7811220031 Forwards Monthly Operating Rept for Oct 1978 KALIVIANAKIS.N. Commonwealth Edison Co. 78/11/09. 1p. 94309:010
- --7811220033 Monthly Operating Rept for Oct 1978, # Commonwealth Edison Co. 78/10/30. 30pp. 94309:011.
- 7812200235 Forwards Monthly Open Rept for Aug. Sept. Oct 1978, correcting mistakes made in Aug & Sept Average Datily Unit Pur Level Rept & in the Sept & Oct Operating Data Repts.

 KALIVIANAKIS.N. Commonwealth Edison Co. 78/11/28. 1p. 94162:325.
- --7812200241 Monthly Open Rept for Aug. Bept. Oct 1978. Corrections 4F6 circled in red. HANNUM.D. Commonwealth Edison Co. 78/11/08. App. 94162: 326

7812200188 Monthly Open Rept for Nov 1978
• Towa-Illinois Gas & Electric 78/11/30 26pp 94149.314.

8 Reportable occurrences. LERs & related correspondence

7810170198 Forwards LER#78-030/03L-0
KALIVIANAKIS.N Commonwealth Edison Co 78/09/26. ip 94411 258

- --7810170202 LER#78-030/031-0 on 780831 Main Steam Line Rediat Monitor 2-1705-2D, failed in a downscale condition. Caused by instrudrift enhanced by an elevated chassis ambient oper temp a Commonwealth Edison Co 78/09/26 3pp 94411 259
- 7810170172 Forwards LER#78-031/03L-0 NALIVIANANIB.N Commonwealth Edison Co. 78/09/29 ip 94270 032
- --7810170180 LER#78-031/03L-0 on 780910 during test the 2-203-3rM91V failed to give a half erram in reactor protec sys channel "B" due to equip failure Inspec & adjusted actuator arm CLARK, D. Commonwealth Edison Co 78/09/29. 3pp 94270.033
- 7811240222 Forwards LERW78-002/03L~0 KALIVIANAKIB,N Commonwealth Ediaon Co 78/10/20 ip 9445B 219
- --7811240224 LER#78-032/03L-0 on 780927 Unit 2 Main Steam Target Rock Pressure Relief Valve#2-203-3A failed to open while performing test Caused by broken air line to valve's manual air operator REED M Commonwealth Editor Co 78/10/20 3pp 94458:220
- 7811240192 Forwards LER#78-033/03L-0 KALIVIANAKIS.N. Commonwealth Edison Co. 78/10/26 1p. 94458 312.
- --7811240193 LER#78-033/03L-0 on 780930 during routine snubber surveillance inspec.2 enubbers were found to be inoperable. Both Mark 183 & Mark 175 snubbers failed due to hydraults Heakage thru hardened O-rings. KOPACZ Commonwealth Edison Co. 78/10/26. 2pp. 94458:313
- 781107011B Notifies NRC that average release rate for radioactive matls w/half-lives greater than B days between 780701 & 780930 was 2 03 times Tech Spec 3.8.B.3 ((1)design objective Gval of elevated mein chimney release rate has started KALIVIANAKIB.N Commonwealth Edison Co 78/10/20 2pp. 94043 319
- 7811240203 Forwards LER#78-034/03L-0 KALIVIANAKIB, N. Commonwealth Edison Co. 78/10/30 1p. 9445B:346
- --7811240204 LER#78-034/03L-0 on 781002 while performing procedure GT8 130-4. Control Rod Drive Scam Timing control rod N-10(50-39) failed to screm upon receiving a test signal from panel 902-16 Caused by Patiture of 118 scram sciencid valve TIETZ.O Commonwealth Edison Co 78/10/30. 2pp. 94458-347
- 7811240239 Forwards LER#78-038/03L-0. KALIVIANAKIB, N. Commonwealth Edison Co. 78/11/01 lp 94458.246.
- --7811240241 LERW78-039/03L-0 on 781004.Unit 2A reactor vent radiat monitor & 2A refueling floor radiat monitor started spuriously spiking. Caused by faulty pur supply common to both 2A monitors. Pur supply replaced w/spare monitor. HILLEMSEN. B. Commonwealth Edison Co 78/11/01. 3pp. 94458:247.
- 7811240153 Forwards LER#78-036/03L-0. KALIVIANAKIB.N. Commonwealth Edison Co. 78/11/03 1p. 94436.205
- --7811240156 LER#78-036/03L-0 on 781016:#1 core spray low-low level initation switch failed to trip at proper setpoint, caused by instru drift. BWALES, J. Commonwealth Edison Co. 78/11/03 3pp. 94466-286
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1 F. Becurity, medical, emergency & fire protection plans
- 7811120167 Forwards copies of RevMB to Emergency Plan Menual BURBICIN.B. Historian Electric Power Co. 78/11/06. Spp.
- --7811150173 Rev#8 to Emergency Plan Manual covering reporting of radiat incidents & emergancies to Reg agencies, med assistance. minor redist incidents, major radiat emergencies & gan health physics procedures. Wisconsin Electric Power Co. 78/09/15. 222pp. 94223:003.

- 7812260169 Forwards Raymo to Emergency Plan Manual For to replace outdated pages of Manual BURBTEIN. B Wisconsin Electric Power Co 78/12/14 Ppp
- --7812260172 Rev#9 to Emergency Plan Manual for Aubj facil replacing outdated pages of Manual
 - Wisconsin Electric Power Co. 78/12/14 9np 94159 296
- O Adjudicatory correspondence
- 7810110017 Interrogatories propounded to Applicant re environ & safety espects of proposed facil
 * Affiliation Uninown 78/09/27 12pp
- 7810110018 NRC Staff first set of interrogatories to & Request for the production of documents from St of WI Case involves arend to LiceDPR-24 & 27 re increased sport fuel storage capacity BERBON, B. A. Office of the Executive Legal Director 1300
- 7BIO110023 NRC Interrogatories to & request for production of documents from intervenor Lakeshore Citizens for Bafe Energy Admitted contentions also submitted.
 BERBON.B A Office of the Executive Legal Director 76/09/29 BERBON, B A 39pp 940h3 091
- 7810110072 NRC Staff Interrogatories to & request for the production of documents from applicant per iOCFR2 7406 re amend to lic HDPR-24 & DPR-27 Admitted contentions also submitted. BERSON, D. A. Office of the Elecutive Legal Director 79/09/29 14pp 94061,116
- 7810130223 Submission of interrogatories by applicant WIEP to intervenor Lakeshore Citizens for Bafe Energy Interrogatories addressed to contentions contained in intervenor's amended contentions
 TROMBRIDGE.Q F Dhew, Pittmen, Patts & Trombridge 78/10/02. App 24001 345
- 7010190083 Interrogs asked of NRC Staff by St of HI Interrogs partain to staff's position re tech merit of each intervenor Lakeshore Citizens for Safe Energy's admitted contentions LAFOLLETTE. B. C. WALSH. P. Wisconsin, State of 78/10/02 3pp 94006-319
- --7810190000 Interrops asked of applicant WMPC by Sit of HI pertaining t maint of spent fuel pool, in particular, danger from rediat emission & exposure WALSHLP Wisconsin, State of 78/10/02 10pp
- 7810230326 Applicant. WI Elec Pur. objections to interrogs submitted by Intervenor Lalesbore citizens for safe energy, are stated.

 Objections based on interrog's reliance on contentions that were rejected by ABLS or ere still being argued.

 TROMURIDOE OF Shaw, Pittman, Potts & Trowbridge 70/10/12. App 94195 179
- 7BIO260222 NRC advises NABLB that issuance of BER & environ assessment will be delayed until Dec 1978 due to reordering of NRC tech staff's priorities w/respect to review afforts on pending apple Delay has been discussed w/applicant's representative.

 BERSON B. A. Office of the Executive Lagai Director 78/10/17. 1p 74058:185
- 7811200275 "Lakeshore Citizens for Hafe Energy Responses to the NRC Btaff's First Bet of Interrops " Urges evaluation of airborns amissions which add to existing background radiat Cert of Svc encl. BCHAEFER, H. Lateshore Citizens for Bafe Energy. 78/10/25 22pp. 94250 288
- 7811200268 "Labeshore Citizens for Bafe Energy Responses to the WI Ele Pur Co's First Set of Interrogs." Defines "increased worker activity" re-spent fuel pool activities ESIED. J. Lakeshore Citizens for Bafe Energy. 78/10/86 App 94280.271
- 7811180260 "Applicant's Answers to Interrogs Propounded by Intervenor on 780927." Cort of Suc encl.
 NEWTON:8. A. Wisconsin Electric Power Co. 78/10/27. Alpe. 94273: 167
- 7811150089 Answer by NAC Staff to Interrogs of St of WI re contentions of Lakeshore Citiens for Bare Energy who oppose amends to lics for sub; facil concerning increase in spant fuel storage capacity. Affidavits & Cart of Byc ancl. BERBONS.A. Office of the Executive Lagal Director 78/11/01. 55pp. 94113: 208.

- on 781002 re emend to lics for subj facils to increase spent fuel storage capacity Supporting documentation & Cert of Svc encl.
 NEWTON.R.A. Wisconsin Electric Power Co. 78/11/01. 39pp. 9449: 201.
- 7812040344 Forwards Affidevite of CM Trammell & FM Altmeter of NRC Staff.
 BEREON, B.A. Diffice of the Executive Legal Director. 78/11/08. 4pp. 94131:011.
- 7812050049 Applicant's answers to 780929 NRC interrogs re amend to LicsOPR-24 & WDPR-27. Increasing Spant Fuel Storage Capacity. W/list of names, beckground & professional quals of witnesses & answers re-potential incremental airborne releases. NEWTUN, R. A. Wisconsin Electric Power Co. 78/11/08. 23pp. 94334:168
- 7812140359 Buears that listed persons have been authorized by intervenors LACSE to respond to intervenes submitted by NRC Staff & applicant WIEP re LACSE contentions.

 BASIS A Lakesbore Citizens for Safe Energy. 78/11/13. 1p. 03557: 233.
- 7812270050 St of WI's Answers to NRC Staff's first set of interrogs & request for production of documents. Bt has not yet located qualified witnesses re admitted contentions. Cart of Svc and l. MALBH.P. Wisconsin, State of. 78/11/14. 3pp. 94ie0.26i.
- 78:2040:83 Dismisses Contention#4 of Intervenors; sustains objections raised by applicant MIEP to intervenors; Contention#0 & intervenors; interrogs re their Contention#9. Contentions concern security plans & health care plans.
 HILLER.M.E. Atomic Bafety and Licensing Board Panel. 78/11/17.
 4pp. 94457-081.
- 7812080175 Gives notice that effective 781122.8 Berson withdraws as NRC representative in proceeding re-subj facil Certificate of Bvc encl.

 BEREON.B.A. Office of the Executive Legal Director. 78/11/17. 3pp. 94107:255.
- 7812270452 Intervenors request NASLS for leave to w/draw Intervenors
 HEPCO.NRC staff & St of WI move NASLS to enter order to
 approve w/drawal of Intervenor as party & enter Order
 dismissing proc. Agreement & Cert of Svc encl.
 BAST.S.A. Lakeshore Citizens for Safe Energy. BARTH.C.A. Office of
 the Executive Legal Director. CHURCHILL.S.W. Hisconsin Electric
 Power Co. 78/12/13. 9pp. 94016:008

H. General correspondence

- 781214036B Requests copies of NUREQ-0410 & NUREQ-0471. BUBT.B.A. Lakeshore Citizens for Bafe Energy. 78/11/13. 1p. 03537:234.
- P. Operating license stage documents & correspondence
- 7810280016 Request for add1 info re expansion of spent fuel pool storage capacity, which will req on-site neutron attenuation testing of boron plates that are to be in pool, removal of which will req special rept to NRC.

 BCHMENCER, A. Operating Resctors Branch i (Pre 790625). 78/10/03.
 300.
- 7810170133 Responds to 780913 ltr requesting sched for submittal of rev ECCS cooling performance analysis. Submittal of completed ECCS analysis to NRC will be on an before 790112. Analysis will use new Westinghouse ECCS eval model.

 BURSTEIN'S. Wisconsin Electric Power Co. 78/10/10. 1p. 94236:088.
- 7810230272 Forwards responses to requests for add1 info re spent fuel storage expansion plans for subj facil. Discusses fuel loading limit, radiat dose in Soraflex plate, thickness of stainless steel inner can-fuel region dimension.

 8URSTSIN.8. Wisconsin Electric Power Co. 78/10/10. 44pp.
 94167-136.
- 78:0190130 Forwards copy of 7803:0 ltr from subj facil to Univ of Wi. COLLINS, P. F. Operator Licensing Branch. 78/10/11. 1p. 94414:027.
- --78:0190193 Requests copy of 780510 ltr be sent to Univ of HJ. Ack 780609 ltr to WI Elec has been placed in Univ of HJ. JACOBBON, N. Affiliation Unknown. 78/09/25, ip. 94414:028.

- Requal Prog. Nine exeminations were regraded IAM conversations of 780420 & 21. Results of the regrading are attached Regraded acores will be used as record acores REED, 2. A. Wisconsin Electric Power Co. 78/05/10 opp. 74414:029.
- 7810190101 Dutlines agreement reached re proposed use of rad banks swap measurement technique to confirm adequate reactor shutdown capability. Technique to be used for subj facil only; further use must obtain NRC generic approval.

 ECHMENCER: A. Operating Reactors Branch 1 (Pre 790625). 78/10/12.

 4pp. 94413:272
- 7810310016 Summarizes meeting on 780929 re Westinghouse rod bank swap measurement prog. RosenthAL.J.E. Reactor Safety Branch (Pre 791030). 78/10/13. 4pp. 94094:326.
- 7811170297 Forwards rough draft workingpapers on subj facil amended Becurity Plan, intended solely for use of JR Barggren. Comments withheld from public disclosure pursuant to 2.790. RDSE.D.O. Los Alamos Scientific Laboratory. 78/11/01. 3pp. 02765:220.
- 7811130203 Forwards Tech Spec change Request 56 to DPR-24 & DPR-27, Tech Spec 15 3.15 "Goverpressure Mitigating Sys Oper." encl outlining functional requirements & limiting conditions for oper re-pressurizer pur operated relief valve.
 BURSTEIN, 9. Wisconsin Electric Power Co. 78/11/02. 16pp.
 03554:001.
- 78:11:40:124 Forwards reactor matts surveillance capsule test repts for subj facils. Conservation in the curves used to predict the change in transition temp as a function of fluence is clearly demonstrated by the results.

 BURSTEIN, B. Wisconsin Electric Power Co. 78/11/08. 3pp. 94380:113
- --78:1140:31 "Analysis of Capsule T from WI Elec Pur Co Facility Reactor Vascel Radiation Surveillance Program." DAVIDBON.J.A., ANDERBON.S.L., SHOGAN.R.P. Westinghouse Electric Corp. WCAP-9331. 78/08/31. 57pp. 94383:117.
- --7811140133 "Analysis of Capsule R from WI Elec Per Co Facility Reactor Vessel Radiation Burveillance Program." YANLOHKO, B. E., ANDERSON, B. L., Hestinghouse Electric Corp. NCAP-9387, 78/08/31, 62pp. 94383:176.
- 7819150203 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73 Requests pre-workshop registration of attendess to facilitate sending out math Wiencl Registration Form & List of Locations. MILLER, J.R. Assistant Director for Bite & Bafeguards (Pre 791030). 78/11/15. Spp.
- 7812190060 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PWR's(NUREQ-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pwr Plants" (NURED-0133). GRIMES. K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94215:095.
- 7812010225 Requests amend to Facil Oper Lic to Incorp changes to Tech Space. Changes consist of rev to reactor coolant sys heatup & cooldown limitation curves for oper of subj facil. W/check for \$4.400.00. BURSTEIN.9. Hisconsin Electric Power Co. 78/11/16. 6PP. 94409:326.
- 7611280229 Withdraws unnecessary requests for relief re Residual Heet Removal Pumps. Containment Spray Fumps. Turbine Driven Auxiliary Feedwater Pumps. Elec Auxiliary Feedwater Pumps. Forwards rev pages of periodic pump & valve test plan. BURSTEIN, S. Wisconsin Electric Power Co. 78/11/20. 9pp. 94012:050.
- 7812130008 Discusses possible dangers of LDCA in containment purging during normal plant open. Requests either commitment to limit purging or justification for continuing. W/encl ANO e7812080207. SCHENCER: A. Operating Reactors Branch 1 (Pre 790623). 78/11/28. App. 94209:230.
- 7812000101 Forwards results of startup physics testing at subj facil, in particular rod worth data. Data shows that the acceptance criterion was met. Preliminary repts indicating that R review criteria were exceeded are incorract.

 MILEON.T.R. Misconsin Electric Power Co. 78/11/30. 19pp. 94335.288.

- 7812210320 Forwards request for add1 info re subj Facil expansion of Spent Fuel Storage capacity SCHNENCER. A Operating Reactors Branch i (Pre 790625). 78/12/06. 5pp. 03556.104
- 7812270389 Responds to 781113 request & encl "Generic Task Problem Descriptions"(NUREO-0471)& "NRC Prog for Resolution of Generic Issues Related to Nuc Pur Plants"(NUREO-0410).

 W/o encl.
 BARTH.C A. Office of the Executive Legal Director 78/12/06 ip. 94229:286
- 7812280060 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB. J 0. Defice of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp 94085.360.
- 7812290110 Ack receipt of 781116 appl for smend to Lics#DPR-24 & 27 Requests eddl %3600 lic fee DIQGS:R M License Fee Management Branch. 78/12/20 Ip 94191.358.
- G. Inspection reports, 1E Bulletine & correspondence
- 7810130054 Ack receipt of 780911 ltr informing NRC of steps taken to correct violations noted in ltr of 780822 re noncompliance & rev of adequacy of the weld repair KEPPLER.J. G. Region 3. Chicago, Office of the Director 78/10/05. ip. 94421.026
- 7810190079 Forwards IE Inspec Repts #50-266/78-14 % #50-301/78-18 on 780822-25. Notice of Violation w/held pursuant to 100FR2-790 HIND J.A. Region 3, Chicago, Safeguards Branch. 78/10/10. 2pp. 94007-023
- 7810220232 Forwards IE Circular#78-17. (See AND: 7810230221, Docket 50-313, 781013)
 KEPRLER.J. Q. Region 3, Chicago, Office of the Director. 78/10/13.
 19. 94181-355.
- 7811210415 Forwards IE Inspec Repts#50-266/78-15,#50-301/78-20 on 780911-15 during which no items of noncompliance were noted FIORELLI.G. Region 3, Chicago. Reactor Operations Nuclear Support Branch. 78/10/16 2pp. 94483:132.
- --7811210436 IE Inspec Repts#30-266/78-13,#30-301/78-20 on 780911-15 during which no items of noncompliance were noted Major area inspected included plant oper-procurement nonroutine event & safety injection reset procedures CHOULER N.C., HUOMEB.J., WARNICK.R.F. Region 3. Chicago, Office of the Director. 78/10/16 11pp. 94482:134.
- 7811290333 Forwards IE Inspec Rept#50-266/78-17 on 781003-05 during which no items of noncompliance were noted. FIDRELLI.O. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/25. 2p. 94193:324.
- --7811290336 IE Inspec Rept#50-266/78-17 on 781003-05 during which no items of noncompliance were noted. Major areas inspected inclipreparation for refueling outage, prefuel handling activities, fuel handling activities.

 MENNING. J.E. Region 3. Chicago, Office of the Director. 78/10/23 496, 94193:326.
- 7811070374 Responds to IE Bulletine78-12 dtd 780929 re atypical weld matl in Reactor Pressure Vessel welds. Vessels in subj facil antedate the etypical matl. on the matter does not apply. BURBTEIN 8. Wisconsin Electric Power Co. 78/10/26. App. 94043.265
- 7811060072 Notice of Violation-failure to rept a significant fish killappended to 780612 itr is retracted. Thirty six fish killed is not significant to warrant a rept. KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 78/10/31. ip. 94422:334
- 7812060174 Forwards IE Inspec Rept#50-266/78-19 on 781002-04 during which no items of noncompliance were noted.
 HEIBHMAN.R.F. Region J. Chicago, Reactor Construction & Engineering Support Brench. 78/10/21. 2pp. 94382:085.
- --7812040178 IE Inspec Rept#50-244/78-19 on 781002-04 during which no items of noncomplience were noted Hajor areas inspected incl: GA/GC prog.implementing procedures: work activities & records relative to steam generator tube inspec.

 WARD, K.D., DAHELBON, D.H. Region 3. Chicago, Dffice of the Director. 78/10/31. 9pp. 94382:087.

- 7811150071 Forwards IE Circular 78-18 KEPPLER. J & Region 3. Chicago. Office of the Director 78/11/06 1p 94112 272
- 78:2140141 Forwards IG Inspec Rept#50-266/78-20 on 78:013-14 during which no items of noncompliance were noted FIDRELLI, O Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/11/13. 2pp. 94:103-105.
- --7812140147 IE Inspet Rept#50-266/78-20 on 781013-14 during which no items of noncompliance were noted Major areas inspected inclineasurement of control abank worth by boron dilution & of control & shutdown bank worths.

 KOHLER, J. E. CHOW, E. T. . GIREETER, J. F. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/11/13. 3pp. 94103:107.
- 7812210120 Forwards IE Inspec ReptM50-266/78-16 on 781012-13 during which no items of noncompliance were noted HEIGHMAN,R F. Region 3. Chicago. Reactor Construction & Engineering Bupport Branch 78/11/17. 2pp. 94269.302.
- --7B12210131 IE Inspec Rept#50-266/78-16 on 7B1012-13 during which no items of noncompliance were noted Major areas inspected incl:safety related pipe anubers incl review of prog & procedures
 YIN.I.T., DANIELBON.D.H. Region 3, Chicago. Dffice of the Director 7B/11/16. App. 94269.304
- 7812290068 Forwards IE Inspec Repts #50-266/78-22 & #50-301/78-23 on 781017-20 during which no items of noncompliance were noted FIDRELLI, 9. Region 3. Chicago, Reactor Operations Nuclear Bupport Branch 78/11/22 2pp 94190:047.
- 7812290074 IE Inspec Repts #30-266/78-22 & #50-301/78-23 on 781017-20 during which no items of noncompliance were noted. Hajor areas inspected incl: calibr & surveillance of safety related components and equip.
 BYREXIEN.J. F., SMITH.J.D. Region 3. Chicago. Reactor Operations Nuclear Bupport Branch. 78/11/20. Spp. 94190:049.
- 7B12050271 Forwards IE BulletinW7B-12A, suppl to IE Bulletin 7B-12 M/encl AND 7B11000055. KEPPLER.J O Region 3, Chicago, Defice of the Director. 7B/11/24. Ip. 94202 21B.
- 7B12290022 Forwards 1E Inspet Rept#30-266/7B-21 & #50-301/7G-22 on 7B1023-26 during which no items of noncompliance were noted. FIORELLI, 0 Region 3, Chicago, Reactor Operations Nuclear Bupport Branch. 7B/11/24. 2pp. 94207:352.
- --7812270032 IE Inspec Repts#50-266/78-21 & #50-301/78-22 on 781023-26 during which no items of noncompliance were noted. Major areas inspected incliquality assurance progresords, nonroutine event followup & noncompliance followup. CHOULES.N.C., WARNICK,R.P., Region 3, Chicago, Reactor Operations. Nuclear Support Branch. 78/11/21. 4pp. 94207:354.
- 7B12130101 Requests add1 info for review of 770520 request relating to insvc inspec prog. Requests response w/in 45 days BCHHENCER, A Deprating Reactors Branch 1 (Pre 790625) 78/12/04. 4pp. 94294: 329.
- 7B122B0036 Forwards IE Bullstin 7B-14. KEPPLER, J. O. Region 3. Chicago, Office of the Director. 7D/12/19. 1P. 94133:216
- R. Periodic operating reports & related correspondence
- 7810170171 Forwards Monthly Oper Rapt for Bapt 1978 BURETEIN, B. Hisconsin Electric Power Co. 78/10/09. Ip. 94970.036
- --7810170173 Monthly Open Rept for Bapt 1978 • Wicconsin Electric Power Co. 78/10/05. 9pp. 94870:007.
- 7811140174 Forwards Monthly Open Rept for Oct 1978.
 BURSTEIN.9 Wisconsin Electric Power Co. 78/11/08. ip. 94384:234.
- --7811140178 Monthly Oper Rept for Oct 1978. * Wisconsin Electric Power Co. 78/11/03. 10pp. 94384: 235.
- 7812120083 Forwards Monthly Oper Rept for Nov 1978.

 BURETEIN, S. Misconsin Electric Power Co. 78/12/08. Ip. 94074:181.
- --7812120087 Monthly Open Rept for Nov 1978.

 * Hisconsin Electric Power Co. 78/12/05. 9pp. 94274:182.

- Reportable occurrences, LERs & related correspondence
- 7810180043 Forwards LER#78-012/01X-0. Hisconsin Electric Power Co. 78/09/12, 1p. 94422:056. BURBTE IN. B.
- --7810180044 LER#78-012/01X-0 on 780627:during visual inspec of fire barrier penetration seals,horizontal seals found to be constructed differently than specified Error due to change in constr drawings No reportable item exists. BURSTEIN. S. Hisconsin Electric Power Co. 78/09/07. 1p. 94422: 057.
- 7810180038 Forwards LERA78-014/017-0.
 BURSTEIN, 8. Wiecpneim Electric Power Co. 78/10/04. 1p 94422:050.
- ~~7810180040 LER#78~014/01T-0 on 780920:primary-to-secondary leakage noted ouring normal oper. Causab by 2 leaking tubes & 1 leaking plug on inlet side of the Amsteam generator Tubes will be plugged & plug will be weld repaired.

 BURBTEIN, B. Hisconsin Electric Power Co. 78/10/04. 2pp. 94422 051.
- 7811240149 LERe78-010/017-1 on 780528: Indication of primary-to-secondary leak of 145 GPD in the "A" 80 was noted on 780324. Bource of leak due to failure of tube at position R44033. Tube plugged & unit returned to svc. BURBIEIN.8. Misconsin Electric Power Co. 78/10/23. 2pp. 94456 250
- 7811240135 Forwards LER#78-015/017-0 BURSTEIN, B. Wisconsin Electric Power Co. 78/10/23. ip. 94456:270.
- -- 7811240158 LERM78-015/01T-0 on 781009: snubber on pressurizer relief line was found inoperable. Orinnel Model#H9-17, 21/2 inch x Sinch bore & stroke snubbar feiled for undetermined cause. Snubber replaced & surveillance prog expanded. BURSTEIN. S. Hisconsin Electric Power Co. 78/10/23. 2pp. 94456: 271
- 7812110189 LER#78-016/01T-0 on 781106: turbine runback resulted from safeguards bus tim broaker trip. Westinghouse Model CV-7 undervoltage relay on the breaker tripped causing breaker to open. No line voltage surges detected. BURSTEIN, B. Wisconsin Electric Power Co. 78/11/17. 2pp. 94408:040
- 7812180217 LERB78-073/03L on 781121: failure to submit RO 30-366/78-55 w/in 30 days. Caused by Deviation Rept 2-78-79 not received by responsible dept head nor superintendent of Plant Engr Sycs Personnel were reminded of procedures. OREENE, T. V. Georgia Power Co. 78/12/11. 2pp. 94365:076.
- 78:12:0393 LER#78-0:3/0:17-0 on 78:009: snubber #322: inoperable caused by Grinnell model #H8-17 bare & stroke snubber not locking when specified load rate was applied. Snubber replaced & surveillance prog expanded. GREENWOOD, J. Wiscomsin Electric Power Co. 78/10/10. 1p. 94486: 049.
- DOCKET 50-267 FORT ST. VRAIN NUCLEAR GENERATING STATION B. Utility Preliminary Bafety Analysis Report, amends
- 78i1240234 BAR re use of U Carbide (UC2) Fuel Particles in Fort St Vrain Fuel Elements Topical rept re future reload fuel General Atomic Co. (subs. of Gulf Dil Co.). 78/09/30. 29pp.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 7811240226 Forwards Safety Rept for instru control rad drive & orifice assemblies. MILLEN, C.K. Public Service Co. of Catarado. 78/11/17. 3pp. 94458: 178.
- --7811240228 Safety analysis rept for installation of instru control rod drive & orfice assemblies during fuel outage in 790101.
 remaining in core until second refueling. Oversize drawings available in Central Files. Public Bervice Co. of Colorado. 78/11/17, 22pp. 94459:181.
- F. Security, medical, emergency & fire protection plans
- 7810170174 Fire protec prog rev in response to branch tech position FULLER, J. K. Public Service Co. of Colorado. 78/10/13. 1p. 94226: 022

Prog Review for Nuc Generating Station in Response to Branch Position 9 5-1, " dtd 781013. FULLER, J. K. Public Service Co of Colorado. 78/11/13 BSpp 94135:001

7011160096 Forwards tay pages & Hec 4 for rept entitled "Fire Protec

- 7812220062 Forwards Appl for Amend to Append A of Facil Oper LiceOPR-34 changing Tech Specs for Fire Protec in areas of Halon Fire Suppression Sys for Control Room Smoke Detectors & Alarms & Fixed Water Sprey Sye.
 MILLEN.C.K. Public Service Co. of Colorado. 78/12/11. 2pp. 94342: 265.
- -- 7812220069 Appl for amend to Append A of Facil Open LickDPR-34, changin Tech Specs for Fire Protec Sys re Halan Fire Suppression Sys & Smoke Detectors & alarme for control room & cable areas & fixed water apray sys for auxiliary elec room.
 MILLEN.C.K. Public Service Co. of Colorado. 78/12/11. 6pp. 94342 267

H. General correspondence

- 7812280274 Forwards info re reactor & HTOR concept in gen requested for high school debating purposes in 781128 ltr.W/encl summary of 781103-04 meetings re subj facil.HTOR lic criteria.& postulated accidents & safety res needs.

 DENTON.H.R. Office of Nuclear Reactor Regulation. Director.
 78/12/18. 100pp. 94347:207.
- ~-7812280277 Requests info on subj facil & HTQR concept in gen for high school debate topic re energy independence. GERLACH, D. Affiliation Unknown 78/11/28. 1p. 94347, 209.
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7811240232 Forwards copy of "Bafety Analysis Rep:Use of UC2 Fissle Fuel Particles in Fort Bt Vrain Fuel Elements."
 Requests review be completed by 790215.
 WEBBHAN.O.L. General Atomic Co. (subs. of Gulf Dil Co.). 78/11/17. 2pp. 94461: 360.
- D. Advisory Committee on Reactor Safeguards reports & correspondence
- 7810230382 Comments on 780804 NRC Staff presentation re facil core PMR oscillations. Surprised to find that little more is known on the matter now then was known in Nov 1977. LIPINBK1, H. C. Argonne National Laboratory. 78/08/14. 2pp. 94195: 172.
- P. Operating license stage documents & correspondence
- 7810100005 Describes Post frradiation Surveillance Prog for proposed test & standard fuel elements of subj facil reactor. FULLER, J. K. Public Service Co. of Colorado. 78/06/20. 2pp. 94033: 026
- 7810100012 Statement that "gamma scan to determine distribution of fission product & core power"was included by mistake in on-site examination description for PIE Prog. The gamma scan will be conducted on a splective basis. FULLER, J. K. Public Service Co. of Colorado. 78/06/R3. 1p. 94033: 020.
- 7810110136 Advises PBC wishes to discuss improving NRC response to matters re subjectil & proposed open mesting re lic matters in Denver area at 781011 meeting Watt listing of correspondence re proposed mode to subjectil Tech Books. FULLERLY. Public Bervice Co. of Colorado. 78/10/03. App. 94064: 353.
- 7810120063 Forwards Appl for Amend to Appendix A of Facil Oper LiceDPR-34. MILLEN.C.K. Public Service Co. of Colorado. 78/10/05. 1p.
- --7810120064 Appl for amend to Appendix A of Facil Oper LiceDPR-34, changing Tach Spec to incorporate new fire water booster pumps installed to meet requirements of Sec 14.4.2.1 of FBAR. MILLEN, C. K. Public Service Co. of Colorado. 78/10/05. App. 94418: 354.
- 7Bi0iB0i4i Seeks to indirectly implement limiting steam generator module helium inlet temp variation by limiting allowable steam generator module outlet steam temp variations. Concerns fluctuation test at 70% of rated thermal pur. FULLER, J. K. Public Bervice Co. of Colorado. 7B/10/05. 2pp. 94316: 338.

- acceptable & does not require Tech Spec change or involve unreviewed safety question per 10CPR30.59.
 FULLER.J.K. Public Service Co. of Coloredo. 78/10/09. 3pp. 94236:011.
- 7810190014 Summary of meeting on 780929 w/Oen Atomic Co to discuss use of H-451 graphite in subj facil reactor/OAC's questions were resolved/validation of computer codes used in analysis of stress or chem reactions not required for review.

 WILLIAMS.P.M. Advanced Reactors Branch. 78/10/10. 4pp. 94322:356.
- 7810230165 In response to concerns re precautions which will be taken when primary sys is pressurized & reactor open, util forwards prerequisites to surveillance test.
 WARDHBURG.D. Public Service Co. of Colorado. 78/10/12. 1p. 94164: 263.
- 7810310094 Response to 780828 NRC ltr.PSC will not propose any mode of current prog at subj facil since plant oper thru Dec 1978 has not provided basis for determining mode. Asserts that use of ABME Section XI Braft 2 rules would not be practical. FULLER.J.K. Public Service Co. of Colorado. 78/10/19. 3pp. 94091:898.
- 7811010207 Notice of Meeting on 781103 & 04 w/Pub Svc Co of Coloredo to discuss subj facil fluctuations oper & testing above 70% pur & related items.

 MUZHYCZIQ. Division of Project Management. 78/10/19. 2pp. 94391:348.
- 7810230067 Submits responses to 8 NRC questions of 780818. This completes response to all NRC questione re reactor fluctuation testing at pur levels above to below 70% rated thermal pur. Requests release for oper by 781118.

 FULLER, J. K. Public Service Co. of Colorado. 78/10/20. 42pp.
- 7810260205 Per request in NRC ltr of 781004 forwards comments re BNL POX graphits test results Concludes that results verify data base presently used to analyze extent & consequences of exidation of core support blocks.
 FULLER-J. K. Public Service Co. of Coloredo. 78/10/20. 9pp. 94036-078.
- 7810319085 Forwards response to questions contained in 780922 NRC ltr re core inlet helium temp vs time transients generated by TAP code.
 FULLER.J. N. Public Service Co. of Coloredo. 78/10/85. 82pp. 94091-045.
- 7811130200 Forwards first part of QA's response to 780919 NRC questions re add1 info on H-451 graphits. Responses to remaining questions will be submitted 781124. MESEMAN.Q.L. Qaneral Atomic Co. (subs. of Quif Cil Co.). 78/10/30. 56pp. 94077:001.
- 7811130001 Calibr & testing for all Class A.O & C instru has been completed. Instruments to be calibr &/or functionally tested prior to resuming oper after early Jan 1979 refueling outage.
 BEYRIT.K. V. Region 4. Dellas. Office of the Director. 78/11/01.
 299. 74077:008.
- 7811160071 Forwards preliminary rept of sacillation testing at subj facil, On 781104 during testing mode under auspices of RT-500A limit(+/-305/40r steam generator module main steam temp was exceeded. Sequence of events encl.
 MARCHBURG, D. Public Service Co. of Calorado. 78/11/09. 4pp.
- 7811270211 Responds to 781025 ltr re review sched of H-451 graphite & thorium oxide fuel. Graphite review will be completed in Jan 1979, subj to acceptable responses by 781101 to add inforequest. Thorium review is in acceptance phase, to end 781131. OAMHLLL, P. Assistant Director for Standard & Advanced Reactors, 78/11/13. 1p. 94272:170.
- 7811270154 Forwards Startup Rept#8 for subj Facil covering the period 780522 to 780822. MAREMBOURG, D. Public Service Co. of Coloredo. 78/11/21. 1p. 94199:214.
- ~-7811270156 Startup Rept#8 covering period 780522 to 780822 re Feedwater Flow Control.circulator speed control.main stream desuperheaters.load change response & control rod celibr.

 Public Service Co. of Colorado. 78/08/22. 104pp. 94199: 215.

- opportunity to observe tech discussions & discuss PBC plans for fluctuation testing above 70% pur Hymni agenda KUZMYC2.0. Advanced Reactors Branch. 78/11/21 92pp 94390.162
- 7812070186 Presents revised schedule to 781104 reactor refueling region outlet temp fluctuations. & reflecting 781116 discussions w/NRC Region restraint device installation delay BAR should be ready by Jan 1979.
 FULLER.J K. Public Service Co. of Colorado. 78/11/27 3pp. 94375:048.
- 7B120B0021 Notice of meeting w/PSC on 7B1214 to discuss data & conclusions re fluctuation test where steam temp limits were exceeded KUZMYCZ.Q. Advanced Reactors Branch 7B/11/30. 2pp. 94103:361.
- 7812110242 Summary of a 781116 meeting re fluctuations at facility. Description of sequence of events during fluctuations a preliminary data from 781104 events enci. KUZMYCZ.O. Advanced Reactors Branch. 78/11/30 Sapp 74337:156.
- 7812110292 Responds to 780411 request for exemption to 100FR21 requirements. Suggests that 781019 commission amend to 100FR21 may eliminate need for such exemption. DENTON.H.R. Dffice of Nuclear Reactor Regulation, Director. 78/12/01. 1p. 74204:030.
- 78:2130164 Establishes new sched for action plan for identifying the instru trip settings & the absolute limiting values originally set out in litr to NRC of 770920. Also details present status of prog.
 MILLENC. M. Public Bervice Co. of Colorado. 78/12/05. 10pp. 94303:122.
- 7812280090 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracias or enforcement action will result. DAVIB.J.Q. Defice of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 03555:305.
- 7812180321 Responds to FOIA request re environ impact statements submitted by Atlas Minerals Uranium Mill & addl records of subj facil. Copies will be placed in PDR in Greeley.Co. FELTON.J. M. Division of Rules and Records. 78/12/ii. 2pp. 94/356: 293.
- --7812180323 Requests add1 info re draft & final environ impact statems for Atlas Minerals Uranium Mills & worker health & safety info Also requests info re control of reactor temp oscillations & mech vibrations.

 PULB.M. Affiliation Unknown. 78/11/12 2pp. 94356:295.
- 7812200164 Forwards corrected pages to Bth startup rept intl Module Main Steam Temp Trim Control.Load Change Response.Feedwater Flow Control & Deserator Level Control. MARE/BDURG.D. Public Service Co. of Colorado. 78/12/15. Spp. 94157:342
- 7812270177 Forwards responses to questions raised at 781104 meeting & description of Firewater Booster Pump installation, design & results of functional tests after installation. FULLER.J.K. Public Service Co. of Colorado. 78/12/18. 65pp. 01791:057.
- 78:12270182 Summary of 78:12:15 meeting of Tech Review Comm for Review of Temp Fluctuations in subj facil. Topics discussed incl comparison of displacement probe & nuc detector signals & info on core status. FRY.D. N. Dak Ridge National Laboratory. 78/12/19. 17pp. 94017:342.
- G. Inspection reports, IE Bulletins & correspondence
- 7810110304 Forwards 1E Inspec Rept #50-267/78-13 on 780807 & Notice of Violation.
 MADEEN, 9. L. Region 4, Dallas, Office of the Director. 78/08/18.
 2pp. 94061:001.
- --7810110306 Notice of Viplation from insper on 780807-11. * Region 4. Dallas, Office of the Director. 78/08/18. ip. 94061:003.
- ---7810110308 IE inspec Rept#50-267/78-13 on 780807-11 during which I is of noncompliance was noted: failure to follow procedures red dispasal of combustible & maint of recording equip.
 DICKERBON, M. H. Region 4, Dallas, Office of the Director.
 78/08/18. 8pp. 94061:004.

- Correct violations noted during inspec#50-267/78-13.

 MADBEN. O. L. Region 4. Dellas. Reactor Operations Nuclear Support Branch. 78/09/19. 1p. 94068.244.
- --7810110264 Responds to 780818 NRC Itr re violation noted in Inspec Rept#50-267/78-13 Corrective actions: continuous monitoring of Admin Procedure requirements. HILLEN.C K. Public Bervice Co. of Colorado. 78/09/ii. ip. 94322.361.
- 7810230360 Forwards 1E Circular#78-17. (See AND: 7810230221 Docket 50-133.781013)
 SEYFRIT, K. V. Region 4. Dellas, Office of the Director. 78/10/13 1p. 94169:189.
- 7812180328 Forwards IE Inspec ReptM50-267/78-16 on 781016-20 during which no items of honcompliance were noted. MADEEN.Q.L. Region 4. Dallas, Resctor Operations Nuclear Support Branch. 78/11/03. 2pp. 94357:320
- --7812180331 IE Inspec Rept#50-267/78-16 on 781016-20 during which no items of noncompliance were noted Major areas inspected inclingualization & admin.04 progression.70X pur level data review & review of startup rept & LER's
 DICKERBON,M. H., CUPP,E.A. Region 4, Dallas, Reactor Operations
 Nuclear Support Branch, 78/11/03, 7pp. 94357:322
- 7B11920121 Forwards IE Circular#7B-18, "UL Fire Test." H/encl ANG:7811150002. BEYFRIT,K.V. Region 4, Dallas, Office of the Director. 78/11/06. is. 94074-208.
- 7812190187 Forwards IE Inspec Rept#30~267/78-15 on 781016-19 during which no items of noncompliance were noted. MADEEN, G.L., Region 4, Dalles, Reactor Operations Nuclear Support Branch. 78/11/08. 2pp. 94414:297.
- --7812190193 IE Inspec Rept#50-267/78-15 on 781016-19 during which no items of noncompliance were noted Major areas inspected incl:radwaste says incl liquid & gaseous radioactive effluent releases & record repts of effluents.

 HURRAY, B. Region 4, Dallas, Office of the Director, 78/11/06, 7pp.
- 7812290239 Forwards IE Inspec Rept#50-267/78-18 on 781103007 during which no items of noncompliance were noted. MADGEN.O.L. Region 4, Dellas Reactor Operations Nuclear Support Brench. 78/11/28. 2pp. 94191:239.
- --7812240244 IE Inspec Rept#50-267/78-18 on 781105-07 during which no items of noncompliance were noted Major areas impacted incl: Emergency Planning Prog incl coordination w/offsite support agencies. HARRISON,H.G., DROWN,G.D. Region 4, Delles, Reactor Operations Nuclear Support Branch. 78/11/28. 6pp. 94191:241.
- R. Periodic operating reports & related correspondence
- 7812180243 Forwards Monthly Open Rept for July 1978. 8MART, F. E. Public Service Co. of Colorado. 78/08/23. 1p. 94358:354.
- --7812180245 Honthly Oper Rept for July 1978. HILLYARD, H. H. Public Service Co. of Colorado. 78/07/31. Spp. 94398:335.
- 7810160103 Monthly Open Rept for Sept 1978.

 QAHM J.W. Public Bervice Co. of Colorado. 78/10/01. Spp.
- 7810160100 Forwards Honthly Oper Rept for Sept 1978.
 WAREHSOUNG.D. Public Service Co. of Colorado. 78/10/09. 2pp.
 94001:336.
- 7811070234 Forwards Monthly Open Rept for Oct 1978.

 WAREHBOURG, D. Public Bervice Co. of Colorado. 78/11/02. 1p.
 94039: 181
- --7811070238 Monthly Oper Rept for Oct 1978.

 9AHM, J. W. Public Bervice Co. of Coloredo. 78/11/02. 5pp.
 94039:182.
- 7812130163 Forwards Monthly Open Rept for Nov 1978. WAREMBOURG, D. Public Service Co. of Colorado. 78/12/04. ip. 94305: i38.

- OAHN-J.W. Public Service Co. of Colorado. 78/12/01. 5pp. 94305.139.
- 8 Reportable occurrences. LERs & related correspondence
- 7810300164 Forwards LER#78-029/03L-0 WAREMSDURQ, D. Public Service Co. of Colorado. 78/09/27. 1p 94004:134.
- --7810300166 LERB78-029/03L-0 on 780829 during routine check of LCD compliance, i emergency generator diesel oil day tank was found to be below the 500 gallon level Cause was fuel oil pump transfer which does not start until 350 gallon level 84Hth.J.M. Public Bervice Co. of Calorada. 78/99/27. 339 94034: 135.
- 78]0300189 Forwards LER#78-018/03X-2.
 WARDMOURG, D. Public Service Co. of Colorado 78/09/27. 1p. 94033-339
- --7810300194 LERW78-018/03X-2 on 780713:during period 780713-780908.1 primery coolant exidents exceeded 10 0 vpm w/core average outlet temp greater than 1,200 degrees F. Source of moisture ingress is undertermined Reactor shut down.

 GAHM.J.H. Public Bervice Co. of Colorado. 78/09/27. 10pp.
- 78101&0131 Forwards LERW78-30/03L-0. WAREMBOURG, D. Public Service Co. of Colorado 78/10/09. 1p. 94005:306.
- 7810300179 Forwards LER#78-030/03L-0. WAREHBUNG, D Public Service Co. of Coloredo. 78/10/05. lp. 94024:225.
- --7810300180 LERM78-030/03L-0 on 780912:5 hydraulic anubbers were for imper due to empty oil reservoirs. Reservoirs were refilled & surveillance interval adjusted.

 QAHM.J.H. Public Service Co. of Colorado. 78/10/05. 4pp. 94034: 226.
- 7810300309 Forwards LER#77-036/03L-1.
 HAREMSOURG, D. Public Service Co. of Coloredo. 78/10/03. ip. 94271:115.
- --7810300313 LERW77-036/03L-1 ON 771115 during normal open the react was open w/average core outlet temp greater than 12000 F k w/ the sum of water.CO & CO2 primery coolant impurities in excess of 10ppm/val.caused by operator error. GAHH.J.M. Public Service Co. of Colorado. 78/10/05. SPP. 94871:116.
- 7810270928 Forwards LER#78-031/03L-0.
 WAREMSURG, D. Public Service Co. of Colorado. 78/10/24. 1p. 94032:242
- --7810270232 LER#78-031/03L-0 an 780925 during routine testing, I of heating ventilation & air conditioning sys isolation dempers for 480 volt switchgeer room would not shut due to faulty O-ring in demper jamming open actuating sheft. OAHN J.W. Public Service Co. of Colorado. 78/10/24. 4pp. 94053:243.
- 7810270276 Forwards LER#78-025/01-X-1.
 WARDMBOURG, D. Public Service Co. of Colorado. 78/10/24. ip. 94027-327
- --7810270283 LERB78-025/01X-1 on 780703:w/loss of pur to one of two redundant pps logic sys.circulator seal malfunction (buffer-mid-bufsr)trip of a helium circulator was inhibited.caused by logic design problem.

 OAHM.J.H., REED.A. Public Bervice Co. of Colorado. 78/10/24.

 10pp. 94027:328.
- 7810310225 Forwards LER #78-032/03L-0. MARCHBOURG.D. Public Service Co. of Colorado. 78/10/27. 1p.
- --7810310230 LER #78-032/03L-0: on 780928, surveillance check of fixed flow alarm bistables for primary collect dew point moisture monitors not performed. Later less that acceptable alarm setpoints discerned. Cause: requirements misinterpreted. QAPM.J. M. Public Service Co. of Colorado. 78/10/27. 4pp. 94090: 248.
- 7811280285 Forwards LER#78-016/03X-1.
 WAREHBOURD, D. Public Service Co. of Colorado. 78/11/22. 1p. 94795: 22A

- --78/1280289 LER#78-018/03x-1 on /80510 while oper at 40x pwr.moisture concentrations in PCRV exceeded limits of 4.2.11 Moisture was introduced during previous Loop 1 shutdown & collected in PCRV insulation.

 OAHM, J. H. Public Bervice Co. of Colorado. 78/11/22. 4pp. 94395:227.
- 7811280312 Forwards LER#78-033/03L-0
 WAREBOURG, D. Public Bervice Co. of Colorado. 78/11/22. lp.
- --78)1280318 LER#78-033/03L-0 on 781027: during routing surveillence of steam pipe rupture detection systems one of three bistables for high temperature under PCRV did not trip, due to carroded cable terminal board at junction box. QAHM.J.W. Public Service Co. of Colorado. 78/11/22: 4pp. 94393-311.
- 7812120089 On 781129 at 4:00 pm.due to problem in heluim circulatory systhems was a minute release of radioactivity in reactor bldg. No heierd to public.

 OASCHLER, J. A. Public Service Co. of Coloredo. 78/12/05 lp. 94274:192
- 7812130273 Discusses minor release of activity at aubj facil on 781127. Breach in aftercooler of "B" helium buffer compressor let water enter gas side & circulate through buffer systmich ultimately opened relief valves letting 1 curie gas escape. KUZMYCZ, Q. Advanced Reactors Brench. 78/12/05. 3pp. 94291:324.
- 7812130135 Forwards LER678-034/03L-0.
 WARDHBOURG, D. Public Service Co. of Colorado. 78/12/06. 1p.
 04307-043
- --7812130141 LER878-034/03L-0 on 781107: during normal open a release of reactor bidg sump effluent req cooling tower blouddown flow to increase above normant rate to 4.39 million gallons for the day due to need to dilute sump effluent discharge. OAMN.J. H. Public Service Co. of Colorado. 76/12/06. 3PP. 94307: 064.
- 7812130190 Forwards LERM78-018/03X-3.

 WARDHOUNG, D. Public Service Co. of Colorado. 78/12/06. 1p. 94306:024.
- --7812130192 LER878-018/03X-3 on 781009.primary content oxidant concentration exceeded 10vpm w/core everage outlet temp preater than 1200 degrees F. Caused by accumulation of water in PCRV insulation.

 OAMM.J.W. Public Service Co. of Colorado. 78/12/04. Spp. 94305:025.
- 7812130172 LERW78-014/03L-0 on 781007: Control Rods 3 & 8 of Group 6 dropped at 0405 t 0413 respectively due to faulty normal pur supply fuse. Faulty fuse has been replaced.
 WILBON-K.R. Duke Power Co. 78/12/07. 2pp. 94294: 353.
- 7812130176 Forwards LER#78-005/03X-1.
 WARCHSUMO,D. Public Service Co. of Colorado. 78/12/07. ip. 94305:171
- ---TBi2l30179 Suppl info to RD#50-267/78-05/03-X-1 on 781107:during oper at 13% thermal & O elec pur one of three IA circulator speed indication channels was at 0.4ue to bridge unbalance. Similar problem occurred 7 times since 780425. FERIS.M.J., GAHN.J.M., MAREMBOURG, D. Public Service Co. of Colorado. 78/12/07. 6pp. 94305:172.
- --7812130185 LERE78-005/03X-1 on 781107: melfunctions in IA.1C & 1D circulator speed measurement caused loss of high speed circulator signals on different dates due to blec circulat unbalance & signal cable resistance change in modifiers. OMM.J. W. Public Service Co. of Colorado. 78/12/07. 7pp. 94305: 178.
- 7812200209 Forwards LERW78-035/03L-0. WARDHBOURG, D. Public Service Co. of Colorado. 78/12/14. 1p. 94162/880.
- --7812200210 LER678-035/03L-0 on 781114:4 of 6 high pur Rod M/drawel Prohibit trip points were set too high Accepted test procedure voltage range permitted RHP to be set higher than Tech Specs allow. QAHM, J. W. Public Service Co. of Colorado. 78/12/14. 4PP. 94162:201.
- 7812270201 Forwards LER#78-027/03X-1. WARDMBDURG, D. Public Service Co. of Coloredo. 78/12/20. 1p. 94017:213.

- -7812270206 LGR#78-027/03X-1 on 781204: ITT Barton Model 289 hellum circulation seal melfunction pressure differential suithches failed to activate at trippoint due to dirt accumulation in switches. Trip sattings being thetaed on monthly basis. 9AHM.J.H. Public Service Co. of Colorado. 78/12/20 App. 94017-214
- U. Congressional/Executive Correspondence
- 7811220132 FOIA request for encl list of communications pertaining to subj facil.
 HASMELL, F. M. Benete. 78/11/01. 3pp. 94074-260
- 7811220128 Responds to 781101 FDIA request Forwards list of 23 documents related to subj facil. FELTON.J.M. Division of Rules and Records 78/11/15 3pp 94074:184
- DOCKET 30-269 DODNEE NUCLEAR STATION: UNIT |
- A. Application/construction stage documents & correspondence
- 78iii30i33 Notice of exemption from provisions of 10CFR30.46 for License OPR-38. Although ferflitty does not comply w/ requirements for ECCS, Tech Specs will provide protec against small break LOCA 81ELLO.V. Division of Operating Reactors 78/10/23. Spp 94272:272.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 7811020014 Supplements 780811 Safety Eval of subj facil Found LPSN sysping arrangement acceptable. Deletes requirement to provide spars dedicated cables for LPSN syspump motors.

 REID.R.H. Operating Reactors Stanch 4 (Pre 790625) 78/10/05. 2pp 94351:247.
- F. Security, medical, emergency & fire protection plans
- 7810180126 Forwards proprietary info consisting of Change#8 to Rev#5 o subj facil security plan.W/o proprietary info. PARKER, U. Duke Power Co. 74/10/06. 3200
- 7810310008 Forwards Revision 2 of modified emended security plan (MASP).Enc1 withheld (ref 10CFR2.790). PARKER.W.O. Duke Power Co. 78/10/19. 2pp. 94093:360.
- 7811210032 Bummary of 781025 meeting to discuss qual of Station Health Physics at subj facil.NRC requested util to submit ray Tech Spec. FAIRTILE, M. Operating Reactors Brench 4 (Pre 790625). 78/11/02. 2800. 94482:338.
- 7812060019 Bunmary of a 781025 meeting re sub; facil Station Health Physicist. FAIRTILE.M. Operating Reactors Branch 4 (Pre 790625). 78/11/02. 3pp. 94415:330.
- Q. Adjudicatory correspondence
- 7819080225 Ack receipt of 781018 ltr re util proposal to transport sut facil spent nuc fusl. Ltr will be forwarded to ABLB in order to be considered as a written limited appearance statement. Wencl ANO: 7811130267 KETCHEN,E. O. Office of the Executive Legal Director. 78/11/20. 3pp. 94137:114.
- P. Operating license stage documents & correspondence
- 7810110025 Request for all info re radiat leakage & safety problems a subj facila.
 QRRDON,M.J. Gordon, Walter J. 78/09/08. ip. 94063:131.
- 7810230158 Forwards check for \$8300 to cover add1 lic fees for NRC review of Cycle 5 released amend for subj facil. PARKER: N. O. Duke Fower Co. 78/10/03. 2pp. 94164:260.
- 7B10130136 Requests return to 1 gpm ellowable leakage rate for subjfacil because 0.3 gpm leak rate results in severe hardship in leak detection resulting in extresive loss of elecgenerating capacity, Summary of impre

PARKER. W D. Duke Power Co. 78/10/06 1p. 94003:081.

- 78:0260149 Notification of forthcoming meeting with Duke Pur Co on 781025 to discuss goals of Radiat Protec Manager
 FAIRTILE: N B. Operating Reactors Branch 4 (Pre 790625) 78/10/17.
 Ip 94055: 336
- 78:1080107 Responds to 78:012 NRC request for info re amend to lic MENNH-1773 for spent fuel shipment to McGuire Finds that remarking Oconee spent fuel pool is tech feasible as a possible future action but requests processing of appl now PARKER. W.O. Dute Power Co. 78/10/18 opp. 94399 141.
- 7810240147 Due to inaction on subj Facil 781007 proposal for Yach Spec new to incorporate staff position for voltage monitors the proposal is rescinded PARKER-H.O Duke Power Co. 78/10/19. Ip
- 7810250153 Repts 2 steam generator tube plugs which were being installed during current refueling outage have not been tocated Startup with plugs unrecovered presents no significant safety herard
 PARKER.H D. Dute Power Co. 78/10/19 4pp
- 7910300182 Responds to 781010 NRC ltr & remits fee for review of cycle 4 reload amend PARKER: H D. Duke Power Co. 78/10/20 2pp 94030.159
- 7810250062 Confirms conversation w/M Fairtile re advice that DOE funding of extended fuel burnup irradiat at subj facil does not commit DOE to fund any future such irradiats or restrict future alternatives for LMR fuel tycle

 LANG.P M. Energy. Dept of 78/10/23 ip.
- 7810270129 Provides info re effects of heat in a dry environ on en unerploded steam generator plug in response to question re BAR based test results Concludes that possibility of detonation of unexploded plug in dry environ is negligible PARKER. H. D. Dute Power Co. 78/10/23 ip. 94057:110.
- 7811070013 Forwards Amends 65.65 % 62 to Licenses DPR-38.DPR-47 & DRA-95.respectively changing Tech Spec re full rated pur Cycle 5 open after core reload removal orifice rod massmobiles from core & High Pressure Injection Pump open. REID.R.H. Operating Reactors Branch 4 (Pre 790625) 787: 94006:290 78/10/23. 309.
- --7811070055 Amend#65 to Facil Open Lic#DPR-38.changing Tech Specs REID.R. W. Operating Reactors Branch 4 (Pre 790625) 78/10/23 2pp. 94036:293.
- --7811070057 Amend465 to Facil Open LicMDPR-47 changing Tech Specs. REID-R.W. Openating Reactors Branch 4 (Pre 790625). 78/10/23 94036: 295
- --7811070060 Amend#62 to Facil Oper Lic#DPR-55.changing Tech Specs. REID-R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/23. 25pp. 94036:297.
- --7811070063 Exempts subj facil from 10CFR80.46(a)re reactor cooling until mod is complete or until next refueling shubdown.

 8TELLO-V. Division of Operating Reactors. 78/10/23. Bpp. 94036:322.
- --78:1070068 Safety evaluation & EIA supporting Amend 65 to Lic DPR-3B.
 Amend 65 to Lic DPR-47 & Amend 62 to Lic DPR-55. Concludes
 that it is acceptable for Cycle 5 open to proceed & that ElA not req. e. Diffice of Nuclear Reactor Regulation, Director. 78/10/23. 17ps. 94036:330.
- --7811070071 Notice of Issuance of Amend#68 & 62 to Facil Open Lic#DPR-38. DPR-47 & DPR-55, respectively, rev lack Space to support full rated pur oper during Cycle S after one reload adding High Pressure Injection Pump reqs & fuel demonstration prog. REID,R.W. Operating Reactors Branch 4 (Pre 790628). 78/10/20. 200. 94034: 349.
- 7811170324 Notice of Issuance of Amend#62 & 63 to Open Lic#DPR-38.47 & 95. Amend rev Tech Opecs allowing full rated pur during Cycle 5 after core reload & permits use of 5 previously burned fuel assemblies. REID R.W. Operating Reactors Branch 4 (Prs 790625). 78/10/23, 268. 02766:243.

7811020255 Notice of rev to Tech Spec 3.7 re Auxiliary Elac Sye Spec 3.7.1 is rev to clearly define onstite emergency transitistion paths in 12500C Instr Control Sys.& rev 3.7.2 re siec sys degraded mode oper. Duke Power Cp. 78/10/31. 6pp. -94247:138.

PARKER, W.O. Duke Power Co. 78/10/26. 200

PARKER, W. D.

- 7811170029 Requests additinfo in order to complete review of submittels dtd 780714 & 781006 ne permenent mode to High Pressure Coolant Injection Bys at subj facil Requests info in 20 days. REID.R W Decrating Reactors Branch 4 (Pre 790628). 78/10/31. 3₈₉.
- 7811140114 Responds to 781031 request for edd1 info re mod of high pressure injection sys. specifically, small break ECC8 mod. PARKER, NO Duke Power Co. 78/11/Ob. 4pp. 94425:135.
- 7811160065 Confirms conversations re 780705 proposed open lic change re possible receipt of 4 fuel assemblies from FL Pur Corp. Requests withdrawal of proposed lic amend & indemnity agreement(B-44) & refund of lic fee. PARKER, H O Duke Power Co. 78/11/07. ip. 94133; 121.
- 7811160079 Rescinds 780523 request for NRC concurrence re proposed Change to respiratory protec sys.
 PARKER, W. D. Duke Power Co. 78/11/07. ip. 94133:175.
- 78:11:60:34 Responds to 78:011 NRC comments on minimum qualifications of ANBI/ANB-3. 1-1978 to be appropriate.

 PARKER: W. O. Duke Pawer Co. 78/11/07. 1p. 94135: 235.
- 7811270118 Forwards 3 previously omitted Tech Spec pages (2.3-1.2.3-3 t 2.3-11) for Lic Amend#65.65 & 62.covering limiting eafety systettings & protect instru.
 REID.R.M. Operating Reactors Branch 4 (Prs 790625). 78/11/08 5pp 94271:266.
- 7811200421 Forwards results of measurements of radioactive mat1 in NRC phantom on whole body counter Encl 1 contains actual amount phanisum on Mnoie body counter-ents; i contains actual amount of each radionuclide present, ent? 2 gives retio of measurements to DDE values & ent? 3 gives recommendations.

 BUTHERLAND.J.T. Region 2. Atlanta. Fuel Facility & Materials Sefety Branch. 78/11/09. 5pp. 94419:175.
- 7811210298 Notifies util of 781205 seminar in Atlanta to discuss new Model Rod Effluent Tech Space & encl seminar info sheet. registration form. & proposed agenda. Region 2: Atlanta, Office of the Director. 78/11/09. D'REILLY, J.P. R 5pp. 94488: 126.
- 7811210306 Notifies util of 781805 seminar in Atlanta to discuse new Model Rod Effluent Tach Space & encl seminar into sheat, registration form, & proposed agenda. D'REILLY.J.P. Region 2, Atlanta, Office of the Director. 78/11/05 Spp. 94488: 091. Region 2, Atlanta, Office of the Director. 78/11/09.
- 781:300035 Forwards NRC staff paper,Policy Bession Item(SECY-78-554) re licensee reg performance evaluation. Three methods for evaluation are: statistical trans analysis & regional survey method.W/o encl. D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/15. 94070: 351
- 7812150123 Notice of workshops re implementation of training & qual DIKELOVIES NOTICE OF WORKSHOPS TO IMPLEMENTATION OF TRAINING & QUAIT requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out matl. W/encl Registration Form & List of Locations. MILLER.JR. Assistant Director for Site & Bafeguards (Fra 791030). 78/11/13. Spp.
- 7812190031 Forwards Ray#1 "Draft Radiological Effluent Tech Specs" for PWR's(NUMED-0473) & "Preparation of Radiological Effluent Tech Space for Nuc Per Plants" (NUMEG-0133). W/o ensl ANG: 7811270173 & 781127018. ORIMES, B. K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/18 6pp. 94814:833.
- 7811300379 Informs DPC that NRC has contracted w/Mountain Heat Res Inc to undertake a series of post-licensing studies of nur part stations. Studies will analyse socioecon impacts which occurred during constr & post-constr periods of each plant. DEYOUNG. C. Division of Site Sefety & Environmental Analysis. 78/11/20. App. 74186: 252.

- THI PURCHE OF IT reg of #10CFR part B1 Rule emanded 781019 & provided relief requested. DENTON H. R. Office of Nuclear Reactor Regulation, Director. 78/11/24. 200
- 7812060260 Response to 780905 itr requesting exemptions from certain reg of 810CFR Part 21 Rule amended 781019 & provided relief DENTON H. R. Office of Nuclear Reactor Regulation, Director. 78/11/24. 2pp. 94371:337.
- --7812060272 Requests exemption from 10CFR21 re procurement of various standard stock items from Cutler Hammer, Inc. Procurement delays will affect constr sched. PARKER, W. O. Duke Power Co. 78/09/05. 3pp. 94371: 339.
- 7812060272 Requests exemption from IOCFR21 re procurement of various standard stock items from Cutter Hammer, Inc. Procurement delays will affect constr sched.
 PARKER.H.O. Dube Power Co. 78/09/05. 3pp.
- 7812040231 Requests relief from reg of ASME Code Section XI.Article IMC 500 Request concerns sys pressure test found to be PARKER, M. D. Duke Power Co. 78/11/28. 7pp. 94325:348.
- 7812150083 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purping or justification for continuing Wencl AND. 7812080207. Operating Reactors Branch 4 (Pre 790625). 78/11/29. App. REID, R. W. 94210:330.
- 7812180131 Expects that mod of high pressure injection sys at subj facils can be implemented for each unit during first available outage of sched duration sufficient to install PARKER, N. O. Duke Power Co. 78/12/04. 1p. 94364:278.
- 7812280173 Emphasizes importance of aubmitting accurate & complate info to NRC by licensee & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB.U.Q. Office of Inspection & Enforcement, Dffice of the Director. 78/12/06. 2pp. 94375:015.
- 78:2:30:78 Provides preliminary results of recent refueling outage of subj facil: Some evidence of erosion or corrosion defect growth was present & is currently being evaluated. A final rept will be provided by 790124.

 PARKER, M. D. Duke Power Co. 78/12/07. 1p. 94305:170.
- 7812250001 Accepts proposed design mod to High Pressure Injection (HPI) sys consisting of installing cross-current lines between discharge lines of HPI sys. W/Bafety Eval. LAINAG. 6 Plant Bystems Branch (Pre 791030). 78/12/07. 6p. 34030:371.
- 7812260062 Forwards Befety Eval Rept for subj facil re mpd to high pressure injection sys. REIO.R.W. Operating Reactors Branch 4 (Pre 790AR5). 78/12/13. 2pp. 94021:271.
- --7812260064 SER "Mod to High Pressure Injection Bys."Concludes design mod to HPIS will ensure that for all postulated single failure conditions, HPIS will be capable of supplying HPI flow by 2 HPI pumps through 2 injection paths.

 4 Operating Reactors Branch 4 (Pre 790625), 78/12/13. App. 94021: 273.
- 7812280238 Forwards Amend#66.66 % 63 revising Tech Specs re subj facils control rad operability.Forwards Bafety Eval.Notice of Trauance, & Notice of Exemption.
 REID.R.M. Districting Reacture Branch 4 (Pre 790625). 78/12/18. 3pp. 94355;258.
- --7812280247 LiceDPR-38, DPR-47, & DPR-35 for Amenda 66, 66, & 63: Tech Speca Proposed changes re control rod operability & support of United full rated pur during Cycle 4 after core reload & removal of prifice rod assemblies from core.

 REID.R. W. Departing Reactors Branch 4 (Pre 790625). 78/12/18. REID, R. W. Operat Sepp. 94385: 261.
- --7812280261 Notice of Exemption of DPR-47 from 10CFR50.46(a)(i) requirement that ECCB performance be calculated in accordance w/celculation models per 10CFR80, App N. BIELLD, V. Division of Operating Reactors. 78/12/15. 9ap. 94195: 286.

Operating Reactors Branch 4 (Pre 790625). 78/12/15. 13pp. 94355, 306.

Amend 63 to DPR-55 Concludes that proposed Tech Spec changes do not involve a significant hazard health or safety

- --7812280267 Notice of Issuance of Amend 66 to DPR-38.Amend 66 to DPR-& Amend 63 to DPR-35 revising common Tech Specs to support the oper of Unit82 full rated pur during Cycle 4. ZMETZIO, 0. D. Operating Reactors Branch 4 (Pre 790625). 78/12/15.
- 7812270244 Forwards proposed rev to subj facil Tech Specs Proposed exception: 3.3.6(f):would allow insperability of one Reactor Bldg Spray Pump for up to 72 hours provided all Reactor Oldg Cooling Units are operable Wiettach affidavit. PARKER: 0. Duke Power Co. 78/12/22. 4pp 94017.155.
- Q. Inspection reports, IE Bulletins & correspondence

consideration.

- 7810130056 Ack receipt of IE Imap Repts 50-269/78-17.50-270/78-17 & 50-287/78-18 on 780807. No proprietary info. PARKER.W. D. Duke Power Co. 78/09/27 ip 94079 185.
- --7810130060 Forwards IE Insp Rept 50-269/78-17.50-270/78-17 & 50-287/78-17 on 780807. No noncompliance noted.

 SUTHERLAND.J T. Region 2. Atlanta. Fuel Facility & Materials Branch. 78/09/20. 2pp. 94079 IB6
- --7810130064 lE lnsp Repts 50-269/78-17, 50-270/78-17 & 50-287/78-18 or 780807. No noncompliants noted Hajor areas inspected: whole body counting practices & test count of NRC phantom OIBSON, A. F. Region 2. Atlante. Fuel Facility & Materials Safety Branch. 78/09/20. 4pp. 94079:188.
- 7811030221 States that grow has been established to address IE Circula 78-08 Review of adequaty of qualifications of each piece of equip will be completed by 790416.

 PARKER, W. Q. Duke Power Co. 78/09/29. 1p. 02/24-250.
- 50-313.781013)
 50-313.781013)
 0'REILLY,J. P. Region P. Atlanta, Office of the Director. 78/10/13.
 1p. 94165:005

7810230287 Forwards IE Circular#78-17. (See AND 7810230221.Docket

- 7811100103 Ack receipt of 781016 ltr informing NRC of steps taken to correct violations noted during inspece50-269/78-18, #80-270/78-18 & #80-287/78-19. KENNA, H. B. Region 2, Atlanta, Safeguards Branch. 78/10/26. 94173: 356.
- -- 7811100110 States info contained in 781016 ltr is proprietary pursu to Bection 2.770 & is to be withheld. PARKER, M. D. Duke Power Co. 78/10/16 1p. 94173:357.
- --7811100115 Responds to 780919 NRC ltr re violation noted in Inspec Rept#850-269/78-18,#80-270/78-18 & #80-287/78-19. Corrective action withheld (ref 10CFR2.790). PARKER, W. D. Duke Power Co. 78/10/06. 1p. 94173: 358.
- --7811100124 Forwards summary of 1E Inspec Repts#30-269/78-18, #30-270/78-18 % #50-287/78-19 on 780815-17. Notice of Violation withheld pursuent to 2.790. KENNA.W. B. Region 2. Atlanta, Office of the Director. 78/09/19, 2pp. 94173:359.
- --7811100130 IE Inspec Repts#50-249/78-18.#50-270/78-18 & #50-287/78on 760815-17 during which I item of noncompliance was noted testing of alarms.
 BEBECKER, K. H., GILLESPIE, F. P. Region 2. Atlanta, Office of the Director. 78/09/18. 1p. 94173:361.
- 781:180085 Forwards IE Circular 78-18.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/06
 1p. 941:13:183.
- 7811280378 Ack receipt of IE Inspec Repts#50-269/78-22, #50-270/78-22, #50-287/78-23 on 780918-22 Does not consider any info therein to be proprietary. PARKER, N. O. Duke Power Co. 78/11/09. 1p. 94397:251.
- --7811280390 Forwards IE Inspec Repts#50-269/78-22,#50-270/78-22 & #80-297/78-23 on 780918-22 during which no items of noncoapliance were noted. LONG.F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/10/18. 2pp. 94397:252.

- --7811280398 IE Inspec Repts#50-269/78-22.#50-270/78-22 & #50-287/78-23 on 780918-22 during which no litens of noncompilance were noted Major areas inspected included unresolved items, special repts.action on IEC 78-08 LEMIS.R. C. Region 2. Atlanta, Resctor Operations Nuclear Support Branch, 78/10/18. 6pp. 94397:254.
- 7812180320 Forwards IE Inspec Repts#50-259/78-25.#50-260/78-28 & #50-296/78-24 on 780925-27 during which no items of noncompliance were noted. LONG, F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/09, 2pp. 94356:285.
- 7911220110 Inspec Rept 50-269/78-23 inadvertently named Oconee Unit 3. should be Doonee Unit 1. LONG.F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/11/13. ip.
- 7812120033 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Bafeguards Newsletter. KENNA, H.B. Region 2, Atlanta, Bafeguards Branch. 78/11/17. 4pp. 94278: 072.
- 7812050021 Ack recaipt of 781120 ltr informing NRC of steps taken to correct violations nated during inspecs#30-269/78-15, #50-207/78-15 & #50-207/78-16.

 BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/11/20 1p. 94200:270.
- --- 7812050025 Responds to 780929 NRC ltr re violations noted in Inspec Repts#50-269/78-15, #50-270/78-15 & #50-287/78-16. Carrective actions: entrances to interim wasts facil posted w/redist signs & spent fuel cask rebolted & retorqued for shipment. PARKER, W.D. Duke Fower Co. 78/10/25. 4pp. 94200:271.
- --7812050029 Forwards IE Inspec Repte#50-269/78-15.#50-270/78-15 & #50-287/78-16 on 780726-28 & 780801-04 & Notice of Violation.

 UREILLY.J.P. Region 2. Atlanta. Office of the Director. 78/09/29. 2pp. 94200:275.
- --7812050030 Notice of Violation from Inspec on 780726-29 k 780901-04. * Region 2. Atlanta. Office of the Director. 78/09/29. ip. 94200.277.
- --7812050031 IE Inspec Repts#50-269/78-15.#50-270/78-15 & #50-287/78-16 on 780726-28 & 780801-04 during which 2 items of noncompliance were noted: failure to properly pack cask for shipment & to perform radiat surveys in interim waste bldg. HDBEY.C. M., JENKINB.G. R., OIBBIN.A.F. Region 2, Atlants, Fuel Facility & Materials Bafety Branch. 78/09/28. 11pp. 94200:278.
- 7812060320 Ack receipt of IE Inspec Rept#30-269/78-23 on 780926-29.

 Does not consider any info therein to be proprietary.

 PARKER, U. D. Duke Power Co. 78/11/21. ip. 94332.040.
- --7812040329 Forwards IE Inspec Rept#50-269/78-23 on 780926-29 during which no items of poncompliance were noted. LCNQ.F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/11/21. 2pp. 94332:041.
- --78:2060333 IE Inspec Rept#50-269/78-23 on 780926-29 during which no items of noncompliance were noted Major areas inspected inclineduating maintenance accomplished on safety-related equip incl procedures & plant work requests.

 JCHNEON, A.H. Region 2, Atlanta, Office of the Director. 78/11/21. 6pp. 94332:043.
- 7812040324 Ack receipt of 781106-ltr informing NRC of steps taken to correct violations noted during inspec#50-269/78-20, #80-287/78-21.
 #30-270/78-20, #80-287/78-21.
 BUTHERLAND, J. T. Region 2. Atlants, Fuel Facility & Materials Safety Branch. 78/11/22. 1p. 94130:353.
- --7912040328 Responds to 781018 NRC itr re violations noted in Inspac Repts#30-249/78-20, #50-270/78-20, #50-287/78-21, Corrective actions: door lock mod to prevent unlocking w/o key. PARKER W, O. Duke Power Co. 78/11/06. 2pp. 74130:354.
- --7812040332 Forwards IE Ineps: Repts#50-269/78-20,#50-270/78-20,#50-287/ 78-21 & Notice of Violation. SUTHERLAND.J.T. Repion 2. Atlanta, Fuel Facility & Materials 8efety Branch. 78/10/18. 2pp. 94130:356.
- --7812040335 Notice of Violation from Inspec on 780911-15.

 * Region 2. Atlanta. Fuel Facility & Materials Sefety Branch.
 78/10/16. ip. 94130:358.

- --7812040339 IE Inspec Repts#50-269/78-20,#50-270/78-20,#50-287/78-21 on 780911-15 during which 1 item of noncompliance was noted: fallure to keep entrance to high radiat area locked.
 HOSEY, C. M., OIBBON, A. F. Region 2, Atlanta, Fuel Factlity & Materials Sefety Brench. 78/10/18. App. 94130:359.
- 7812040363 Forwards IE Bulletin#78-12A, suppl to IE Bulletin 78-12.

 M/encl ANO:7811300055.

 D'REILLY, J.P. Region 2. Atlanta, Office of the Director. 78/11/24
 1p. 94127:166.
- 7812070317 Ack receipt of IE Insp Repts 50-269/78-21 & 50-287/78-22 on
- 7812070317 Ack receipt of IE Insp Repts 50-269/78-21 & 50-287/78-22 on on 780919-21 Does not consider any info therein to be proprietary.
 PARKER M. O. Duke Power Co. 78/11/28. ip. 94084:339.
- --7812070319 Forwards 1E lnsp Repts 50-269/78-21 t 50-287/78-22 on 780919-21 during which no items of noncompliance were noted. MURPHY.C.E. Region 2, Atlants, Reactor Construction & Engineering Support Branch. 78/11/02. 2pp 94084:340.
- --7812070320 IE Insp Repts 50-269/78-21 & 50-267-32 on 780919-21 during which no items of noncompliance were noted Major areas inspected incl: Cornective action on previously identified infraction #287/78-14-01.
 CCMLON.T.E. ECONOMOS.N. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 78/11/01. 7pp. 94084:342.
- 7812130306 Ack receipt of IE Inspec Repts#50-269/78-26.#50-270/78-25 & #50-287/78-26 on 781023-27. Does not consider any info therein to be proprietary.
 PARKER. M. O. Duke Power Co. 78/12/05. 1p. 94159:278.
- --7812130311 Forwards IE Inspec Repts#30-269/78-26. #50-270/78-25 the #50-287/78-26 on 781023-27 during which no items of noncompliance were noted.

 LONG:F.J. Region 2: Atlanta, Reactor Operations Nuclear Support Branch. 78/11/21, 2pp. 94159:279.
- --7812130317 IE Inapec Repte#50-269/78-26,#50-270/78-25 & #50-267/78-26 on 781023-27 during which no items of noncompliance were noted. Major areas inspected inclineview of past flow.pur & pur distrib anomalies.

 BURNETI, P.T. Region 2, Atlanta, Office of the Director.

 JULIAN, C.A. Region 2, Atlanta, Reactor Operations Nuclear Support Branch.

 BETTENHAUBEN, L. Region 1, Philadelphia. Office of the Director. 78/11/20. 3pp. 74137:281.
- 7812140041 Ack receipt of IE Inspec Repts#50-269/78-29,#50-270/78-21 & #50-287/78-29 on 781106-08. Does not consider any Info to be proprietery.
 PARKER.W.D. Duke Power Co. 78/12/05. ip. 94127:267.
- ---7812140046 Forwards IE Inspec Repts#50-269/78-29, #50-270/78-21 \$
 #50-287/78-29 on 781104-08 during which no items of noncompliance were noted.
 LCNO/F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/22. 2pp. 94127:268.
- --7812140048 IE Inspec Repts#50-249/78-29, #50-270/78-21 & #50-287/78-29 on 781106-08 during which no items of noncoepiiance were noted Major areas inspected inclipiant oper & restoration of sys following refueling outage.

 JAPE,F., LEWIS,R.C. Region 2, Atlanta, Reactor Operations Nuclear Bupport Branch, 78/11/22, 6pp. 94127:270.
- 7812140033 Ack receipt of IE Inspec Repts#80-269/78-24,#50-270/78-23 & #80-287/78-24 on 781017-20 & 781101-03. Does not consider any info therein to be proprietary. PARKERIN D. Duke Power Co. 78/12/05. 1p. 94126:330.
- --7812140055 Forwards IE Inspec Repts#50-269/78-24, #50-270/78-23 & #50-287/78-24 on 781017-20 & 781101-03 during which no items of noncompliance were noted.

 KENNA, W. B. Region 2, Atlanta, Safeguards Branch. 78/11/29. 20p. PAIGA. 201
- --7812140039 IE Inspec Repts#50-249/78-24,#50-270/78-23 & #50-287/78-24 on 781017-20 & 1101-03 during which no items of noncompliance were nated. Major areas inspected incl:fecil organization, shipping & receiving & storage. HDDGEB,J.W., CLAY,E.L., WILLIAMS,G.H. Region 2, Atlante, Bafeguards Branch. 78/11/24. App. 94126:333.
- 7812290072 Forwards IE Sulletin 78-14. O'REILLY.J.F. Region 2. Atlanta. Office of the Director. 78/12/19. Rpp. 03695:189.

74.IAA .54.3

--78102000B3 Monthly Oper Rept for Sept 1978 REAVIS, J. E. Duke Power Co 78/10/16 16pp. 94366-344.

PARKER, W. O. Duke Power Co. /8/10/16

- 7810240002 Forwards Quarterly 780601-780831 rept on Jocasses Area 8elsmic Activity. PARKER,M.D. Dute Power Co 78/10/16 ip
- --7810240077 Quarterly Seismic Activity Rept. (6-1-78 to 8-31-78)
 Decreased Seismicity in Jocassee erea represents diminishing site and no of joints at greater depths.
 TALMANI, P., STEVENSON, D., BAUBER, J. South Carolina, Univ. of 78/10/16. 19pp.
- 7812210157 Forwards Monthly Open Rept for Nov 1978.
 PARKER, M. D. Duke Power Co. 78/12/15 1p. 94278:185
- --7812210160 Monthly Open Rept for Nov 1978 REAVIS, J. Duke Power Co. 78/12/15 16pp. 94278.186
- B. Reportable occurrences, LERs & related correspondence
- 7810200162 Forwards LER#78-023/01T-0 PARKER, M. D. Duke Power Co. 78/10/04. 1p. 94412.008
- --7810200170 LERM78-023/01T-0 on 780919: during annual check on borated water storage tank level instr one channel was found out of calibration due to error in differential pressure transmitter. Components were recalibrated.
 MILSON.K.R. Duke Power Co. 78/10/04. 2pp. 94412:010
- 7811020359 RO 269/78-24: on 781012, during refueling shutdown DT36 tube was found to be plugged at one end only Cause unknown.
 VELO D. J. Duke Power Co. 78/10/12. ip. 94253.351
- 7811220185 Forwards LER#78-024/01T-0.
 PARKER-H. D. Duke Power Co. 78/11/15. 3pp. 94074.817
- --7811220188 LER#78-024/017-0 on 781012 during refueling outage noted that 7 0780 tubes which should have been plugged during seriism outages were not plugged. Caused by placement of pluge in wrong tubes due to personnel errore.

 MILBON.K.R. Dute Power Co. 78/11/15. 1p. 94074.220.
- 7812010244 Forwards LERM78-025/03L-0. PARKER-N. D. Duke Power Co. 78/11/27 1p. 94390:153.
- ~-7810210245 LER#78-025/03L-O on 781026: during annual RPS recalibr the RPS trip setpoint was found to be less conservative than allowed by Tech Spec limits. Caused by effect of temp? humidity changes from May 1978 pressure switch failure. HILSON M. R. Duke Power Co. 78/11/27. 2pp. 94390:154.
- 7812190127 Forwards LER#78-026/03L-0. PARKER:H.D. Duke Power Co. 78/12/11. 1p. 94340:334.
- ~-7812190130 LER#78-026/03L-0 on 781110:while attempting to put RBCU "c" fam into svc.damper-open indication not recieved in control room. Caused by blown fuse in demper motor circuit.
 WILSON.K.R. Duke Power Co. 78/12/11, 2pp. 94340:356.
- DOCKET 50-270 DODNEE NUCLEAR STATION, UNIT 2

 E. NRC Befety Evaluation Report (BER), supple & correspondence
- 7811020014 Supplements 780811 Safety Eval of subj facil Found LPSW sysplping arrangement acceptable. Deletes requirement to provide spare dedicated cables for LPSW syspump motors.
 REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/05. 2pp. 94391:247.
- F. Security, medical, emergency & fire protection plans
- 7810180126 Forwards proprietary info consisting of Change#B to Rev#5 of subj facil security plan W/o proprietary info. PARKER.W.O. Duke Power Co. 78/10/06. 32pp.
- 7810310008 Forwards Revision 2 of modified amended security plan (MASP). Enc.) withheld (ref. 10CFR2.790).
 PARKER, M. O. Duke Power Co. 78/10/19. 2pp. 94093:360.

- 7Bi2060019 Summary of a 7Bi025 meeting re sub; facil Station Health Physicist. FAIRTILE.M. Operating Reactors Branch 4 (Pre 790625) 7B/11/02 3pp. 94415.330
- O Adjudicatory correspondence

94482 338

- 7812080225 Ack receipt of 781018 ltr re util proposal to transport subfacil spent nuc fuel Ltr will be forwarded to ABLB in order to be considered as a written limited appearance statement.

 W/encl ANO.781130267

 KETCHEN.E 0. Office of the Executive Legal Director 78/11/20.

 3pp. 94137:114
- P. Operating license stage documents & correspondence
- 7811170029 Requests add1 info in order to complete revises of submittal dtd 780714 & 781006 re-permanent mode to High Pressure Coolant Injection Sys at subj facil. Requests info in 20 days REID.R W. Deerating Reactors Branch 4 (Pre 790625). 78/10/31 3pp 94048:182.
- 7Bi0fi0025 Request for all info re radiat leakage & saPoty problems at subj facils DORDON,W J. Gordon, Walter J. 7B/09/08 lp. 94063:331.
- 7810200102 Ack receipt of 780825 response to 780801 NRC request for add1 info re substitute surveillance tendon Requests add1 info re solution to stress corrosion surveillance & lift-off test problem w/in 30 days.
 REID.R.W. Deprating Reactors Branch 4 (Pre 790625). 78/10/02 ip. 94367-333
- 7810230158 Forwards check for \$8300 to cover addl lic fees for NRC review of Cycle 5 released amend for subj facil, PARKER, N.O. Duke Power Co. 78/10/03. 2pp. 94164:260.
- 7B10130174 Analysis of small break LOCA dtd 7B0515 & the proposed mod which requires an oper to position switches to open 2 electmotor-open valves. Actions are consistent wistaff position on this matter.

 PARKER, H. O. Duke Power Co. 7B/10/06. ip 94003-051
- 7810260149 Notification of Porthcoming meeting with Duke Pur Co on 781025 to discuss goals of Radist Protec Manager. FAIRTILE.N.B. Operating Reactors Branch 4 (Pre 790625). 78/10/17. ip. 94055:336.
- 7811080107 Responds to 781012 NRC request for info re amend to lic #BNM-1773 for spent fuel shipment to McGuire Finds that reracking Donnee spent fuel pool is tech feasible as a possible future action,but requests processing of appl now PARKER-N.O. Duke Power Co. 78/10/18. 6pp. 94399.141.
- 7810240147 Due to inaction on subj Facil 781007 proposal for Yeth Sperey to incorporate staff position for valtage monitors, the proposal is rescinded.
 PARKER, M. D. Duke Power Co. 78/10/19. 1p
- 7811070013 Forwards Amends 63.63 % 62 to Licenses DPR-3B, DPR-47 & DPR-35.respectively, changing Tech Specs re full rated pur Cycle 5 open after core reload.removal orifice rod assemblies from core & High Pressure Injection Pump open. REID.R.H. Operating Reactors Branth 4 (Pre 790625). 78/10/23. 3p:94036:290.
- --78i1070055 Amend#65 to Facil Oper Lic#DPR-38.changing Tech Specs. REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/10/23 2pp. 94036:293.
- --7811070057 Amend#65 to Facil Oper Lic*DPR-47-changing Tech Specs. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/23. 20p. 94034:295.
- ---7811070060 Amend#62 to Facil Oper Lic#DPR-55.changing Tech Specs REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/10/23 25pp. 94036:297.
- --7811070063 Exempts subj facil from 10CFR50.46(a) re reactor cooling until mod is complete or until next refueling shutfown.

 STELLD.V. Division of Operating Reactors. 78/10/23 Bpp. 94036:392.

- --7811070068 Befety evaluation & EIA supporting Amend 65 to Lic DPR-38. Aband 68 to Lic DPR-47 & Amend 62 to Lic DPR-55 Concludes that it is acceptable for Cycle 5 oper to proceed & that EIA not req. e Office of Nuclear Reactor Regulation, Director. 78/10/23. 179p. 94036:330.
- --7811070071 Notice of Issuance of Amend#65 & 62 to Facil Oper Lic#DPR-38. DPR-47 & DPR-55, respectively, rev Tech Specs to support full reted pur oper during Cycle 5 after core reload, adding High Pressure Injection Pump reqs & fuel demonstration prog. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/23. 2pg. 94036: 349.
- 7811170324 Notice of Issuence of Amend#62 & 65 to Oper Lic*DPR-38.47 & 55. Amend rev Tech Specs allowing full rated pur during Cycle 5 effect core reload & permits use of 5 previously burned fuel assamblies.
 REID.R.U. Operating Reactors Branch 4 (Pre 790626). 78/10/23. 2pp 02766:243.
- 7811010104 Requests rapid NRC approval of Standby Shutdown Sys concept proposed ra station security & fire protect of sub, facil. Must have NRC assurance that BES concept meets NRC requirement before committing to these mods.

 PARKER.W.O. Dute Power Co. 78/10/26. 2pp.
- 78i1020235 Notice of rev to Tech Spec 3.7 re Auxiliary Elec Sys. Spec 3.7.1 is rev to clearly define onsite energency transmission paths in 125000 Instr Control Sys.& rev 3.7.2 re elec sys degraded mode oper.
 PARKER, W. O. Duke Power Co. 78/10/31. 6pp. 94247:138.
- 7811070214 Ack receipt of NRC info to staff reviewing 780918 submittel of lic amend supporting subj facil through Cycle 4. Confirms 780922 & 780926 ltr to NRC responding to staff questions reproposed physics testing of cycle 5.
 PARKER.W. D. Duke Power Co. 78/11/01. 1p. 94039:121.
- 7811140114 Responds to 781031 request for add1 info re mod of high pressure injection sys-specifically, small breal ECCS mod. PARKER N. O. Duke Power Co. 78/11/06. App. 94425:155.
- 78iii80i79 Responds to 78i002 NRC ltr re total # surveillance tendons prescribed & substitution of surveillance tendon for tendon 2D28 Believes tendon 2D28 need not be replaced or tensioned & should be available for math degradation test.

 PARKER.W. O. Duke Power Co. 78/11/06. 2pp. 94242:359.
- 78i1160065 Confirms conversations to 780705 proposed oper lic change repossible receipt of 4 fuel assemblies from FL Pur Corp.
 Requests withdrawal of proposed lic amend & indemnity agreement(8-44) & refund of lic fee.
 PARKER, M. D. Dute Power Co. 79/11/07. ip. 94193:121.
- 7Biii60079 Rescinds 780523 request for NRC concurrence re proposed change to respiratory protoc sys.

 PARKER.M.D. Duke Power Co. 78/11/07. ip. 94133:175.
- 78i1160134 Responds to 78i01i NRC comments on minimum qualifications of station Health Physicist Considers requirements in ANBI/ANS-3.1-1978 to be appropriate. PARKER: M. D. Dute Power Co. 78/11/07. ip. 94135:235.
- 7811270118 Forwards 3 previously smitted Tech Spec pages(2.3-1,2.3-3 & 2.3-11)for Lic Amend&53.65 & 62.covering limiting safety systettings & protect instru.

 REID. R. N. Dereting Reactors Branch 4 (Pre 790625). 78/11/08. Spp. 9471:266.
- 7811200421 Forwards results of measurements of radioactive mat1 in NRC phantom on whole body counter. Encl I contains actual amount of each radionuclide present encl 2 gives ratio of measurements to DDE values & encl 3 gives recommendations. BUTHERLAND.J.T. Region 2. Atlants. Fuel Facility & Materials Bafety Brench, 78/11/09. Spp. 94419:175.
- 7811210298 Notifies util of 781205 seminar in Atlanta to discuss new Model Rad Effluent Tech Specs & ancl seminar info sheet, registration form, & proposed agenda.

 O'REILLY, J.P. Region 2. Atlanta, Office of the Director, 78/11/09. 5pp. 94488:126.
- 7811210306 Notifies util of 781205 seminer in Atlanta to discuss new Model Rod Effluent Tech Specs & encl seminer info sheet, registration form. & proposed agenda. D'REILLYJ.P. Region 2. Atlanta, Office of the Director. 78/11/09. Spp. 94488:091.

- 7811300035 Forwards NRC staff paper.Policy Bession Item(8ECY-78-554) r licensee reg performance evaluation. Three methods for evaluation are: statistical, trend analysis & regional survey method. H/o encl. O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 78/11/15.
- 78:2150123 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73 Requests pre-workshop registration of attenders to facilitate sending out math Wencl Registration Form & List of Locations.
 MILLER, J. R. Assistant Director for Bite & Bafeguards (Pre 79:030), 78/11/15. Spp.
- 7812190031 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PWR's (NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pwr Plants" (NUREO-0133), U/o encl ANO: 7811270173 & 781127018.

 GRIMES-8.K. Assistant Director for Engineers & Projects (Pre 790425), 78/11/15. 6pp. 94214:333.
- 7811300379 Informs DPC that NRC has contracted w/Mountain Heat Res Inc to undertake a series of post-licensing studies of nuc per stations. Studies will analyze socioscon impacts which occurred during constr & post-constr periods of each plant, DEYOUNG.R.C. Division of Site Befsty & Environmental Analysis, 78/11/20, 2pp. 94136:252.
- 7812060260 Response to 780905 ltr requesting exemptions from certain reg of 810CFR Part 21. Rule amended 781019 & provided relief requested.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director.

 78/11/24. 2pp. 94371:337.
- --7812060272 Requests etemption from 10CFR21 re procurement of various standard stock items from Cutler Hammer, Inc. Procurement delays will affect constructed.
 PARKER, M. D. Duke Power Co. 78/09/05. 3pp. 94371: 339.
- 7812040231 Requests relief from rsg of ASME Code Section XI, Article 14 300. Request concerns sys pressure test found to be impractical. PARKER, N. O. Duke Power Co. 78/11/28. 7pp. 94325: 348.
- 78:2130083 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing, W/encl ANO: 78:2080207.
 REID.R.M. Operating Reactors Branch 4 (Prs 790625). 78/11/29. 6pp 742:0:330.
- 7812180131 Expects that mod of high pressure injection sys at subj facils can be implemented for each unit during first available outage of school duration sufficient to install mod. PARKER.N.O. Duke Power Co. 78/12/04. 1p. 94364:278.
- 7812280173 Emphasizes importance of submitting accurate & complete ind to NRC by licensee & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB, J. G. Office of Inspection & Enforcement, Office of the Director, 78/12/06. 2pp. 94376:015.
- 7812260001 Accepts proposed design mod to High Pressure Injection (HPI sys consisting of installing cross-current lines between discharge lines of HPI sys. W/Bafety Eval.
 LAINAB. 0. Plent Systems Branch (Pre 791030). 78/12/07. 6p. 94020:271.
- 7812260062 Forwards Safety Eval Rept for subj facil re mod to high pressure injection sys.
 REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/12/13. 2pl 94021:271.
- --7812260064 SER "Mod to High Pressure Injection Sys. "Concludes designed to HPIS will ensure that for all postulated single failure conditions. HPIS will be capable of supplying HPI flow by 2 HPI pumps through 2 injection paths.

 Operating Reactors Branch 4 (Pre 790625). 78/12/13. 4pp. 94021:273.
- 7812280238 Forwards Amend#66.66 & 63 revising Tech Speca re subj fact: control rod operability. Forwards Safety Eval. Notice of Issuance. & Notice of Exemption. REID. R. W. Operating Reactors Branch 4 (Pre 790625). 78/12/18. 3pt 94355: 288.

- REID.R. W. Operating Reactors Branch 4 (Pre 790625). 78/12/18. 36pp. 94335:261.
- --7812280261 Notice of Exemption of DPR-47 from 10CFR50 46(a)(1) requirement that ECCB performance be calculated in accordance w/celculation models per 10CFR50 App K. BTELLDLV. Division of Operating Reactors. 78/12/13 9pp. 94195.286.
- --7812280264 SER supporting Amend 66 to DPR-3B. Amend 66 to DPR-47, & Amend 63 to DPR-55. Concludes that proposed Tech Spec changes do not involve a significant hazard, health or safety consideration.

 Operating Reactors Branch 4 (Pre 790625). 78/12/15. 13pp. 94335:306.
- --7812280267 Notice of Issuance of Amend && to DPR-30.Amend && to DPR-47. A Amend &3 to DPR-55 revising common Tuch Boecs to support the open of Unitse? Full reted pur during Cycle 4. ZMETIIG. G. B. Operating Reactors Branch 4 (Pre 790&25) 78/12/15. 250
- 7812270244 Forwards proposed rev to subj facil Tech Spece.Proposed exception: 3-3 6(f), would allow inoperability of one Reactor Bldg Spray Pump for up to 72 hours provided all Reactor Bldg Cooling Units are operable.H/attach affidavit.
 PARKER.W O. Duke Power Co. 78/12/22 App. 94017:155
- 7810300182 Responds to 781010 NRC ltr & remits fee for review of cycle 4 reload amend. PARKER, H. O. Dyke Power Co. 78/10/20 2pp. 94030:159.
- Q. Inspection reports, IE Bulletine & correspondence
- 7811100103 Ack receipt of 781016 ltr informing NRC of steps taken to correct violations noted during inspec#30-269/78-18, #50-270/78-18 #850-287/78-19. KENNA W. B. Region 2. Atlanta. Gafeguards Oranch. 78/10/26. lp. 94173
- --7811100110 States info contained in 781016 ltr is proprietary pursuant to Section 2,790 & is to be withheld. PANER, M. C. Dute Power Co. 78/10/16 ip. 94173:337
- --78[11001]5 Responds to 780919 NRC ltr re violation noted in Inspec Repts#50-269/78-18, #50-270/78-18 t #50-287/78-19. Corrective action withheld (ref 10CFR2. 790). PARKER, M. D. Duke Power Co. 78/10/06. 1p. 74173:358.
- --7811100124 Forwards summary of IE Inspec Repts#80-269/78-18, #30-270/78-18 & #50-287/78-19 on 780815-17. Notice of Violation withheld pursuant to 2.790. KENNA, U.B. Region 2, Atlanta, Office of the Director. 78/09/19. 2
- --7811100130 IE Inspec Repts#30-269/78-18.#50-270/78-18 & #50-287/78-19 on 780815-17 during which 1 Item of noncompliance was noted testing of alarms.

 BEBECKER,K. H., OILLEBPIE,F. P. Region 2, Atlanta, Office of the Director. 78/09/18. 1p. 94173:361.
- 7810130056 Ack receipt of I6 Insp Repts 50-269/78-17,50-270/78-17 & 50-297/78-18 on 780807 No proprietery info.
 PARKER.M.O. Duke Power Co. 78/09/27. 1p. 94079:185.
- --7810130060 Forwards IE Insp Rept 50-269/78-17, 50-270/78-17 & 50-287/78-17 on 780807. No noncompliance noted. SUMERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 78/09/20. 2pp. 94079:186.
- ~~7810130064 IE Insp Repts 80-269/78-17, 50-270/78-17 & 50-287/78-18 on 780807. No noncompliance noted, Major areas inspected; whole body counting practices & test count of NRC phantom. 91850N.A.F. Region 2, Atlanta, Fuel Facility & Meterials Bafety Branch. 78/09/20. 4pp. 94079:188.
- 7811030221 States that prog has been established to address IE Circular 78-08 Review of adequacy of qualifications of each piece of equip will be completed by 790416.

 PARKER.W.O. Duke Power Co. 78/09/29. 1p. 02724:250.
- 7810220287 Forwards IE Circular#78-17. (See ANG: 7810230221. Docket 50-313.781013)
 D'REILLY, J. P. Region 2. Atlanta. Office of the Director. 78/10/13. 1p. 94165: 005.

- 7811280378 Ack receipt of IE Inspec Repts#50-269/78-22, #50-270/78-22, & #50-287/78-23 on 780918-22 Dose not consider any info therein to be proprietery PARKER.W. 0 Dose Power Co. 78/11/09. Ip. 94397-251
- --7811280390 Forwards IE Inspec Repts#50-269/78-22, #50-270/78-22 & #50-287/78-23 on 780918-22 during which no items of noncompliance were noted LDN3.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/18 2pp 94397-252
- --7811280398 IE Inspec Repts#50-269/78-22.#50-270/78-22 & #50-287/78-23 on 780718-22 during which no items of noncompliance were noted Major areas inspected included unresolved items, special repts.action on IEC 78-0B LEMIS.R. C. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch 78/10/18 &pp. 94397 294.
- 7812120053 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Bafeguards Noweletter KENNA,H B. Region 2, Atlanta, Bafeguards Branch 78/11/17 4pp 94278:072
- 7812030021 Ack receipt of 781120 ltr informing NRC of steps taken to correct violations noted during inspecs#30-269/78-15. #50-270/78-15 & #50-287/78-16 BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/11/20 1p. 94200:270
- --7812050025 Responds to 780929 NRC ltr re violations noted in Inspec Repts#50-269/78-15,#50-270/78-15 & #50-287/78-16. Corrective actions: entrances to interin weets Pacil posted w/radiat signs & spent fuel cask rebolted & retorqued for shipment. PARKER.W. O. Duke Power Co. 78/10/25 App 94200:271.
- --7812050029 Forwards IE Inapec Repts#50-269/78-15.#50-270/78-15 & #50-287/78-16 on 780726-28 & 780801-04 & Notice of Violation.
 D'REILLY, J. P. Region 2, Atlanta, Office of the Director 78/09/29. 2pp. 94200:275.
- --7B12050030 Notice of Violation from Inspec on 780726-28 & 780901-04. * Region 2. Atlanta, Diffice of the Director, 78/09/29 ip. 94200.277.
- --7812050031 IE Inspec Repts#90-269/78-13,#50-270/78-15 & #50-287/78-16 on 780726-28 & 780801-04 during which 2 items of noncompliance were noted: failure to properly pack cask for shipment & to perform radiat surveys in interim waste bldg. HDBEY, C. M., JENMINB, O. R., OIDSON, A. F. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/07/28. 11pp 94200:278.
- 7812040326 Ack recaipt of 781106 ltr informing NRC of steps taken to correct violations noted during inspec#50-269/78-20. #50-270/78-20. #50-287/78-21. BUTHERLAND.J. T. Region 2. Atlents, Fuel Facility & Materials Bafety Branch. 78/11/22. ip. 94130:353.
- --7812040328 Responds to 781018 NRC ltr re violations noted in Inspec Repts#30-269/78-20, #30-270/78-20, #30-287/78-21. Corrective actions: door lock mod to prevent unlocking w/o key. PARKER.W. O. Duke Power Co. 78/11/06 2pp. 94130: 334.
- --7812040332 Forwards IE Inspec Repts#50-26978-20,#50-27078-20,#50-27 78-21 & Notice of Violation. BUTHERLAND, J. T. Region 2. Atlenta, Fuel Facility & Materials Bafety Branch. 78/10/18. 2pp. 94130-356
- --7812040335 Notice of Violation from Inspec on 780911-15. # Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 78/10718. ip. 94130:358.
- --7812040339 IE Inspet Repts#50-269/78-20,#50-270/78-20,#50-287/78-21 (780911-15 during which 1 item of noncompliance was noted: failure to keep entrence to high radiat area locked. HOSEY, C. M., 91880N.A.F. Region 2, Atlanta, Fuel Facility & Materiale Bafety Branch. 78/10/18. App. 94130:359.
- 7812040363 Forwards IE Bulletin#78-12A. suppl to IE Bulletin 78-12. W/encl AND:7811300055. D'REILLY-J.P. Region 2. Atlants. Office of the Director. 78/11/24. lp. 94127:166.

- 7812130306 Ack receipt of IE Inspec Repts#50-269/78-26,#30-270/78-25 & #50-287/78-26 on 78:023-27 Does not consider any info therein to be proprietary PARKER. W D Duke Power C Duke Power Co 78/12/05 to 74159 278
- --7812130311 Forwards IE Inspec Repts#50-269/78-26,#50-270/78-25 & #50-289/78-26 on 781023-27 during which no items of Nuncampliance were noted. LCNO.F. J Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/21. 2pp. 94139:279
- --7812130317 1E Inspec Repts#50-269/78-26,#50-270/78-25 t #50-287/78-26 on 781023-27 during which no items of noncompliance were noted Major areas inspected incl. review of past flow.pur t nated Major areas inspected incl.review or year trumpe, a pur distrib anomaliss.

 BURNETT, P.T. Region 2. Atlanta, Office of the Director JULIAN, C.A. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. BETTENHAUSEN, L. Region 1. Philadelphia, Office of the Director 78/11/20. 5pp 94159:201.
- 7812140041 Ack receipt of IE Inspec Repts#50-269/78-29,#50-270/78-21 & #50-287/78-29 on 781106-08 Does not consider any info to be proprietary. PARKER: H. O. Duke Power Co. 78/12/05. ip. 94127; 267.
- --7812140046 Forwards IE Inspec Repts#50-269/78-29,#80-270/78-21 & #50-287/78-29 on 781106-08 during which no items of noncompliance were noted. LING.F. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/22 2pp. 94127:268.
- --781214004B IE Inspec ReptsH50-269/78-29, #50-270/78-21 & #50-287/78-29 on 781106-08 during which no items of noncompliance were noted Major areas inspected incliplant open & restoration of Ays following refuelting outage.

 JAPE, F., LEWIS, R.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/22 6pp. 94127:270.
- 7812140033 Ack receipt of 1E Inspec Repts#30-269/78-24,#50-270/78-23 & #50-287/78-24 on 781017-20 & 781101-03 Does not consider any info therein to be proprietary PARKER. W. O Duke Power Co 7 78/12/05 1p. 94126:330.
- --7812140055 Forwards IE Inspec Repts#50-269/78-24,#50-270/78-23 & #50-287/78-24 on 781017-20 & 781101-03 during which no items of noncompliance were noted. KENNA.H. B. Region 2. Atlanta. Safeguards Branch 78/11/29. 2pp. 74126: 331
- --7812140059 IE Inspec Repts#30-269/78-24,#30-270/78-23 & #50-287/78-24 on 781017-20 & 1101-03 during which no items of noncompliance were noted Major areas inspected inclifacil organization, thisping & receiving & storage HONGES, J. W. CLAY, E. L., WILLIAMS, O. H. Region 2, Atlanta, Bafeguards Branch, 78/11/24, 4pp. 94126:333.
- 7812290092 Forwards IE Bulletin 78-14.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/12/19.

 2pp. 03695; 189.
- R. Periodic operating reports & related correspondence
- 7810200082 Forwards Monthly Open Rept for Sept 1978. PARKER, W. O. Duke Power Co. 78/10/16. Ip. 94366:343.
- --7810200083 Monthly Open Rept for Sept 1978. REAVIS.J E. Buke Power Co. 78/10/16. 16pp. 94366:344.
- 7810240002 Forwards Quarterly 780601-780831 rept on Jocessee Area Seismic Activity.
 PARKER, W. D. Duke Power Co. 78/10/16. ip.
- --7810240077 Quarterly Seismic Activity Rept. (6-1-78 to 8-31-78).
 Decreased Seismicity in Jocasses area represents diminishing TALMANI, P., BTEVENSON, D., SAUBER, J. South Carolina, Univ. of. 78/10/16. 19pp.
- 7812210157 Forwards Monthly Open Rept for Nov 1978.
 PARMER: W. D. Duke Power Co. 78/12/15. 1p. 94278: 185.
- --7812210160 Monthly Oper Rept For Nov 1978. REAVIB. J. Duke Power Co. 78/12/15. 16pp. 94278:186.

- --7811080141 LER#78-010/03L-0 on 781004: control rod 7 g to be inoper due to short in CRD stator Short cause moisture-induced corrosion. Will replace shorted sta during upcoming refueling outage.
 WILSON, K.R. Duke Power Co. 78/11/01. 3pp.
- 7811300172 Forwards LERM78-011/03L-0. PARKER-W.O. Duke Power Co. 78/11/22 lp 94073 10
- ---7811300174 LER#78-011/03L-0 on 781023:E8 Analog Chann Range Pressure Transmitter found to be out-of-calib **C#4sive temp/humidity in penetration room. Actions minimize effects of excessive conditions. WILSON, K. R. Duke Power Co 78/11/22 2pp. 94073
- 7812180188 Forwards LERW78-012/01T-0. PARKER-W D. Dute Power Co. 78/12/05. 1p. 94366:08
- --7812180196 LER#78-012/01T-0 on 781105: valve 2HP-127,R theck valve was in closed position during HPI cher functional test. Caused by personnel error. HILSON, K. R. Duke Power Co. 78/12/05 2PP. 94366
- DOCKET 50-271 VERMONT YANKEE NUCLEAR POWER STATION E. NRC Safety Evaluation Report (SER). supple & corresp
- 7811290392 Responds to 781018 request for copies of ref from Safety Eval to Amend#47 for Subj facil lic & req for info re posible fuel loading error.Forwards refe NRC found no loading error.W/encl ANO:7810240145. STELLO.V. Division of Operating Reactors. 78/11/16. 94181:178.
- F. Security, medical, emergency & fire protection plans
- 7810200090 Proposes to provide 2 fire drills per year f operating shift fire brigads. Asserts that NRC insists 4 drills for each brigade year per year is arbitrary unnecessary Vermont Yankee Nuclear Power Corp. 78/10 94367: 092
- 7812050130 Forwards latest rev of mod amend security pl facil to meet 780621 NRC comments Encl w/held from pu disclosure pursuant to 2.790. QROCE.R.H. Vermont Yankse Nuclear Power Corp. 78/12 94335: 051.
- 7812270276 Forwards addl info re fire protec sys hose s
- design. Vermont Yankse Nuclear Power Corp. 78/12 94229: 207
- H. General correspondence
- 7811090166 Requests change of address for correspondent ORDCE, R. H. Vermont Yankee Nuclear Power Corp. 78/11 94038: 14R
- K. Utility Final Bafety Analysis Report (FSAR) & amends
- 7810240008 Ack receipt of rev Emergency Plan as Amend 8 Requests submission of rev emergency plan IAW Reg Gui 1.101. IPPOLITO, T. A. Operating Resctors Branch 3 (Pre 79062
- P. Operating license stage documents & correspondence
- 7810200151 Notice of Issuance of Amend to Facil Oper Li Declaration. NRC has issued Amend 46 to Facil Oper Lic which revises Tach Space for oper of Subj Facil Amend increase in pH of water discharged from cooling tower IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 79062 2pp. 94401:189.
- 7810190043 Reload 5 Licensing submitted for subj facil dtd 780621 is being reviewed Requests addl info telec to YAE on 780927. IPPCLITO.T.A. Operating Reactors Branch 3 (Pre 79062
- 3pp. 94325: 355.

DOCKETED ITEMS

- --7810230043 Amend #47 to Facil Oper Lic#DPR-28, changing Tech Spec re Cycle 6 oper. 1970L1TQ.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/10 32pp. 94414:227.
- --78:0230044 Bafety Evaluation supporting Amend#47 to Fecil Oper Lic #DPR-28. Concludes that amend does not decrease safety margin. • Operating Reactors Branch 3 (Pre 790625). 78/10/10. Spp. 94414:259.
- --7810230048 Notice of Issuance of Amend#47 to Facil Oper Lic#DPR-28, changing Tech spec re Cycle & oper. IPPOLITO,T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/10. 2pp. 94414:267.
- 7810160135 Comments on Reactor Protec Bys pur supply Ref is made to LiceOPR-28 for subj facil & NRC 780807 ltr to subj facil. Combinetion of events as described has low probability of occurring & does not present need for sys mod. VANDENBURGH.D. Vermont Vantes Nuclear Power Corp. 78/10/11. 2pp. 94005:164.
- 7811020066 Forwards Amend 48 to License DPR-28.safety evaluation & notice of issuence.
 1PPELITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/13.
 4pp. 94351:264.
- --7811020071 Amend#48 to Facil Oper Lic#DPR-28 rev Tech Specs re:oper plant during Oct 15-May 15 in the helper-cycle mode w/discharge temp restrictions & oper in closed-cycle during May 16-Oct 14. Also removes limit on thermal plume.

 1PPDL1TD.T. A. Operating Reactors Branch 3 (Pre 790525). 78/10/13. 50p. 94351; 268.
- --7811020081 Environ Impact Appraisal supporting Amend#48 to Facil Oper Lic#DPR-28 concluding that there will be no significant environ impact attributable to proposed action other than what has been described in FES. • Office of Nuclear Reactor Regulation, Director. 78/10/13. 3pp. 94351:273.
- --7811020086 Notice of Issuance of Amend#48 to Facil Oper Lic#DPR-28 on 781013. IPPOLITO,T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/13. Typ. 94351:276.
- 7811130335 Bummary of 780914 meeting w/OE representatives & Mark 1 Owners Group re progress of Long Term Prog w/attendance list & agenda (RD-9-A-Marki, Standards.) ORIMEG.C. Plant Bustoms Brench (Pre 791030). 78/10/26. 67pp.
- 7810240143 Requests copies of ref#8 & #7 to Amend#47 which provide plant-specific deta used in transient & accident analysis. Asks if NRC Felt sub; facil commutated fuel load error during previous refueling.

 8COTT, D. M. Vermont, State of, 78/10/18, ip.
- 7811010104 Requests rapid NRC approval of Standby Shutdown Bys concept proposed relatation security & fire protect of subjects. Hust have NRC assurance that SSS concept meets NRC requirement before committing to these mods. PARKER M.O. Duke Power Co. 78/10/28. 200.
- 7811140324 States 781016 NRC 1tr requests rewriting of met1 sent for infe purposes only. Suggests need may exist for review of staff activities to confirm they are consistent w/priorities established by senior mgt.
 VANDEMBURGH.D. Vermont Yankee Nuclear Power Corp. 78/11/07. 3pp. 94400: 059.
- 7812130167 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out meth. M/ench Registration Form & List of Locations. HILLER-J.R. Assistant Director for Site & Bafeguards (Pre 791030). 78/11/15. 3pp.
- 7812180262 Forwards Rev#1 "Draft Radiological Effluent Teth Specs" for BMR's(MUREG-0473) & "Preparation of Radiological Effluent Teth Specs for Nuc Pwr Flants" (NUREG-0133). GRIMES N. Assistant Director for Engineers & Projects (Pre 790625), 78/11/15. bpp. 94365.328.
- 7811270130 Forwards rept re"Primary Containment Leak Rate Testing, 1974-1978."
 9ROCE, R. H. Vermont Yankee Nuclear Power Corp. 78/11/17. 1p. 94224: 221.

- ~-7811270134 "Vermont Yankee Primary Containment Leakage Rate Testing 1974-1978. "Describes all reactor containment testing performed subsequent to the Oct 1974 Type A test & Up to & incl a Type A test performed in Aug 1978 EICHENHOLZ, H. Vermont Yankee Nuclear Power Corp. 78/11/17. 45p 94224:222.
- 7812070141 Notice of seminar on 781208 on new Model Radiological Effluent Tech Specs for nuc pur plants. Requests advance submission of seminar specific questions. Wencl Seminar Info Bhaet, Proposed Agenda & maps.
 ORIER. B.H. Region 1. Philadelphia, Office of the Director. 78/11/21. Spp. 94375:284.
- 7812110002 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing, W/ancl ANO: #7812080207.

 IPPOLITO.T. Operating Reactors Branch 2 (Pre 790625). 78/11/29. Bpp. 74339:139.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings he & providing task-by-task activity summary for the month. BOBCN-L.J. General Electric Co. 78/12/04. 11pp.
- 7812280121 Emphasizes importance of submitting accurate & complete in to NRC by licensees & applicants. Indo submitted must be substantiated by data & talculations. Licensee must notify NRC of any inaccuracies or sneorcement action will result DAVIS. J. O. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94310:249.
- 7811210367 Forwards add) info re multiple consecutive safety/relief valve actuation of Merk I containment program.
 8080N-L-J. General Electric Co. 78/11/13. 3pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7811080236 Forwards IE Inspec Rept#90-271/78-19 on 780822-24 during which no items of noncompliance were noted. HARTIN.H.Q. Region 1. Philadelphie. Safeguards Branch. 78/09/23. 2pp. 94406:064.
- --7811080245 IE Inspec Rept#80-271/78-19 on 780822-24 during which no items of noncompliance were noted Major areas inspected included physical security, access contrals, detection Aids. 10CFR2, 790 info available in Central Files.

 ROBERS, M., MCKEOWNIL. Region 1. Philadelphia, Safeguards Branch. 78/09/25. 1p. 94406;066.
- 7810170023 Forwards IE Bulletin#78-12: "Atypical Held Material in Reactor Pressure Vessel Helde" requesting action w/in 60 days & list of IE Bulletins issued in 1978. (see AND 7810040293) ORIER, B. H. Ragion i, Philadelphia, Office of the Director. 78/07/29. App. 94241:334.
- 7811020170 Ack receipt of 780928 ltr informing NRC of steps taken to correct violations noted during inspec 30-271/78-18.

 8MITH. Q. H. Region I. Philadelphia, Reactor Operations Nuclear Support Brench. 78/10/13. ip. 94355:108.
- --7811020175 Responds to 780911 NRC ltr re violation noted in Inspec Rept#90-271/78-18. Corrective actions: personnel reminded to perform preliminary survey of subj samples, follow handling red & written plant procedures. MCDDY, D. E. Vermont Yankee Nuclear Power Corp. 78/09/28 2pg. 94035: 109.
- --7811020179 Forwards IE Inspec Rept#50-271/78-18 dtd 780901 \$ Notice Violation.
 - CROCKER, H. W. Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/09/05. 2pp. 94355:113.
- --7811020183 Notice of Violation from Inspec on 780815-17. CROCKER, H. W. Region I, Philadelphia, Office of the Director. 78/09/01. [p.
- --7811020188 IE Inspec Rept 50-271/78-18 on 780815-17 during which 2 items of noncompliance were noted: Disregard of Procedure DP O&GO. Mater Chemistry: Procedure DP O&GO. Hater Chemistry: Procedure DP O&GO. Hater Chemistry: Procedure DP 2611. Gassous Radwasts.
 BTDHR.J.P. Region 1, Philadelphie, Office of the Director.
 KOTTAN.J.J. NRC Regional Offices: 78/09/01. 9p. 94355:114.
- 7811040178 Forwards 1E Circular#78-17. (See AND: 7810230221, Docket #50-133, 781013.)

- 7812060344 Forwards IE Inspec Repts#50-271/78-21 on 780919-22 & 1005-06 during which no items of noncompliance were noted. CARLSONR T Region I. Philadelphie. Reactor Construction & Engineering Support Branch. 78/10/23 2pp 94382 257.
- --7812060346 IE inspec Rept#30-271/78-21 on 780919-22 & 1005-06 during which no items of noncompliance were noted. Major areas inspected incl. insvc inspec prog & implementation during current refueling outage SANDERS. W F. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 78/10/19 4pp. 94392 259
- 7811290145 Forwards IE Circular #78-18. "UL Fire Test. "H/encl AND 7811150002 ORIER. B R Region 1. Philadelphia. Office of the Director. 78/11/06. 1p 94239: 323.
- 7812290051 Forwards IE Inspec Rept#50-271/78-24 on 781025-26 during which no items of moncompliance were noted.
 BRUNNER E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/11/09. 2pp. 94190-005
- --7812270053 IE Inspec Rept#50-271/78-24 on 781025-26 during which no items of noncompliance were noted Major areas inspected intl: status of previously indentified items NAPUDA. 0. KIBTER. H. Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch 78/11/09. 3pp. 94170 007.
- 7812180030 Forwards IE Bulletin#78-12A.Buppl to IE Bulletin 78-12 W/snc1 AND 7811300005 ORIEN.B H. Region 1. Philadelphia. Office of the Director. 78/11/24 pp. 94133:004
- R Periodic operating reports & related correspondence
- 7810170192 Forwards Monthly Open Rept for Sept 1978 MODDY, D. E. Vermont Yankee Nuclear Power Corp. 78/10/10 | Ip 94235:289.
- --7810170193 Monthly Oper Rept for Bept 1978 B.DOREN.R M Vernant Yenkee Nuclear Pawer Corp. 78/10/12. App. 94235.290
- 7811140125 Forwards Monthly Oper Rept for Oct 1978.
 MOODY DE Vermont Yankee Nuclear Fower Corp 78/11/10 1p.
- --7811140127 Monthly Oper Rept for Oct 1978. S.OOREN. R M. Vermont Yankes Nuclear Power Corp. 78/11/10. Bpp. 74425-225.
- 7812190290 Forwards Monthly Oper Rept for Nov 1978.
 MODDY.D.E. Verront Yantes Nuclear Power Corp. 78/12/11. is.
- --7812150292 Monthly Oper Rept for Nov 1978. BJOOREN, R H. Vermont Yankee Nuclear Power Corp. 78/12/11. App.
- 94409: 207.
- 9. Reportable occurrences. LERs & related correspondence

94409: 206

- 7812180173 Forwards LER878-021/03L-0. CONMAY, M. F. Vermont Yantes Nuclear Power Corp. 78/07/24. ip. 74399: 357.
- --7812180176 LERW78-021/03L-0 on 780612 during steady state oper-noted bhat drywell atmospheric temp recorder TR-1-149 was inoperable Recorder feiled due to failed idler assembly. CDWAY, W.F. Vermont Yankee Nuclear Power Corp. 78/07/24. 2pp. 94399.338.
- 7812180193 Forwards LER878-017/03L-0. CDNMAY.W.F. Vermont Yankee Nuclear Power Corp. 78/07/24. 1p. 94366:097.
- --7812180197 LERW78-017/03L-0 on 780626: during reactor pur increase noted that local critical pur ratio in 4 symmetrically located fuel bundles was lower than Tach Spec levels. Caused by pur increasing amon transient.

 CINHAY.M.F. Vermont Yankes Nuclear Power Corp. 78/07/24. 2pp. 94366:098
- 7812180213 Forwards LER#78-016/03L-0. CONNAY, N.F. Vermont Yantee Nuclear Power Corp. 78/07/24, 1p. 94365: 072.

- --7812180216 LER#78-016/03L-0 on 780625: during steady state oper, hoted that druwell atmospheric temp recorder IR-1-149 was inoperable. Caused by recorder Pailurs due to broken cord on chart drive mechanism

 CONHAY,N F Vermont Vantee Nuclear Power Corp 78/07/24. 2pp 94365 073
- 7812180190 Forwards LER#78-019/03L-0 CONHAY.W F Vermont Yanker Nuclear Power Corp 78/07/25. 1p. 94366:090
- --7812180194 LERW78-019/03L-O on 780629 during steady state oper Motor Control Ctr 893 lost voltage because "D" Uninterruptible Pur Supply (UP3) tripped due to blown inverter leg flues Failed components replaced & operablisty test performed.

 CDNMAY.M.F. Vermont Vankes Nuclear Power Corp. 78/07/25. 2pp 94366 091
- 7812180237 Forwards LER#78-017/03L-1 CONHAY,W F Vermont Yankee Nuclear Power Corp. 78/08/10. 1p. 94359:332
- --7812180241 LERW78-017/03L-1 on 780626. during increase of reactor for noted that critical pur ratio in 4 symmetrically lideated fuel bundles was below Tech Spec values Caused by pwr increasing renon transient CONMAY.H F. Vermont Yankse Nuclear Power Corp. 78/08/10. 2pp. 94359, 333
- 7810310244 Forwards LER#78-030/03L-0 CONMAY, N. F. Vermont Yankee Nuclear Power Corp. 78/10/26. 1p. 94091.328
- --7810310248 LER#78-030/03L-0 on 780926 small amount of radiolodine we released during third quarter, exceeding Tech Spec level, due to faulty fuel cladding, Amount released is small fraction of maximum release allowed. & there was no hazard to pub. CONMAY, H. F. Vermont Yankee Nuclear Power Corp. 78/10/26. Rgp. 94091.329
- 7811160102 Forwards LER#78-031/03L-0. CONHAY-H.F. Vermont Yankes Nuclear Power Corp. 78/11/13. 1p. 94135:102.
- --7811160103 LERW78-031/03L-0 on 781016.weekly review of completed surveillance test following plant startup noted that monthly hydrogen detector functional test was not performed due to personnel error.

 COMMAY.M.F. Vermont Yankee Nuclear Power Corp. 78/11/13. Rpp 74135.103
- 7011160128 Forwards LER#78-032/03L-0 CONMAY.H F. Vermont Yankee Nuclear Power Corp. 78/11/13. 1p. 94135:226.
- --7811160130 LER678-032/03L-O on 781014: during surveillance test of Ma eteam Isolution Valves V2-86C closed in 2.6 seconds rather than 3-5 seconds reg in Tach Spec 4.7. D. 1. a.1. Caused by closing speed control valve coming loose from actuator CONMAY.H.F. Varmont Yankee Nuclear Power Corp. 78/11/13. 2pp. 94135-227
- 7812180219 Forwards LERW78-033/03L-0.
 CONMY: W.F. Vermont Yankse Nuclear Power Corp. 78/12/13. 1p. 94338:339.
- --7812180222 LER478-033/03L-0 on 781113: during weekly surveillance re radiological environ prog.air pump motor was found inoper. Time meter indicated pump had operated only 0.4 hours. Air pump replaced & new weekly air sample initiated. CCNNAY.N.F. Varmont Yankee Nuclear Power Corp. 78/12/13. 2pp. 94358-340
- DOCKET 50-272 SALEM NUCLEAR GENERATING STATION, UNIT \$
 F. Security, medical, emergency & fire protection plans
- 7811300022 Forwards findings of steff review of subj facil 780803 security plan. Enciwl lists areas NRC considers unresolved, w/held from pub disclosure IAN 10CFR2.790 Enciw2 is Review Guideline re plant protec from sabotage by insiders. BCHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/16.4pp. 94070:337.
- 7812040224 Requests add1 info re subj facil Security Plan Forwards list of Unresolved issues (withheld from disclosure) & Review Outdeline "Protec of Nuc Pur Plants Against Industrial Sabotage by the Insider."

 SCHWENCER.A. Operating Reactors Stanch 1 (Pre 7906R5), 78/11/16.

2040225 Review Guideline#23 "Protec of Nuc Pwr Plants Against adustrial Sabotage by the Insider " Refers to security secures that place controls on access to vital areas ARK.R. A Rea 3/11/06. 3pp. Reactor Bafeguards Licensing Branch (Pre 791030).

.0206 Responds to 7Bill6 request for info on security plan ments incl detailed study to determine Type I & ll vital so is unnecessary & requests response to issues raised in ltr re "insider" control procedures IIZZI.F P. Public Service Electric & Gas Co. of New Jersey 2714. 2pp. 94279 096

210210 Appraises Reactor sefeguards Licensing Branch Review ideline#23 "Protec of Nuc Per Plants Against Industrial bodage by the Insider" re-compartmentalization, two-man descensional reliability.

EWEN.J.E. KMC. Inc. 78/11/28 Spp. 94279:098

udicatory correspondence

0322 NRC Staff requested to inform ASI.B & concerned parties of date upon which Staff will complete safety eval & ron analysis re subj facil OLLIN, G. L. Atomic Safety and Licensing Board Panel 78/10/12, 94195:185.

DLLIN, Q. L.

0337 NRC Steff response to AGLB Order of 781012 requesting infoublication of Steff documents NRC Steff asserts that it not be able to publish these documents before Jan 1979 to unavailability of key tech reviewer.

H-B.H Office of the Executive Legal Director. 78/10/24 App.

3259 Notion by Pub Advocate of St of NJ on behalf of intervenors ed & Eleanor Coleman to convene ARLB to receive pub imony. Motion based on principles reflected in R2.715. Cert of Svc encl. ER.R. H. New Jersey, State of 78/11/09. Bpp 94417-129

3351 Licensee's opposition to motion of intervenors A & E Coleman onvene the Bd to receive pub testimony. Urges denial of ests.Feels Pub Advocate is invoking nanexistent liege & should become a Pull party if truly interested. IRHAHN.M J. Conner, Noore & Corber. 78/11/22. Bpp. 94131-014

1227 NRC Btaff's response in apposition to Motion by Intervenors I Coleman to convene ABLB to receive pub testimony Staff ses taking of evidence from persons making a limited scance Cert of Svc enci 1. B. H. Office of the Executive Legal Director. 78/11/29. Bpp. I · 348

3027 Forwards 780523 Itr For File & requests ack of receipt. isses concern re pending appl to modify existing permits suc fuel storage at subj site.
NRT.H.D. New Jersey, State of 78/12/08. 1p. 94159:2: 78/12/09. 1p. 94159: 240

>301 Licenses's Objections to certain of Mr & Mrs AC Coleman, Jrs' . Set of Interrog to the Licenses Licenses moves for corder that objectionable discovery not be had Wyencl cive order contentions & Cart of Svc.
RHAHN.M.J. Conner. Moore & Corber. 78/12/11. 18pp. s: 157.

·O46 Response by licensee PSEO to intervenors A & E Colemans' set of interrogs dated 781121. Interrogs concern, inter-spent fuel reprocessing & radiat levels in spent fuel Cert of Byc encl. NO.R. Public Bervice Electric & Gas Co. of New Jersey. /11. 32pp. 74082:321.

rence & indemnity information

159 Forwards 8 certified copies of captioned endorsement for f 1978 premium Advanced premiums & standard premium sement encl.
EY-T.F. Nuclear Insurance Consultants 78/11/02. 2pp. : 130

275 Forwards Amend#5 to Indemnity Agreement#8-74. Copy has been d by all licenses. JTH9.R. Public Bervice Electric & Gas Co. of New Jersey. /21. 1p. 94399:214.

BO276 Amend#5 to Indemnity Agreement#8-74.effective 781004. **etituting replacement lic numbers.

IZMAN, J. Antitrust & Indemnity Group. 78/11/21. lp.

7812040223 Forwards insurance Endorsement #24 to MAELU Policy #MF90 fo rev of 1978 premium HARTLEY, T F Nuclear Insurance Consultants 28/11/28 2pp

- P. Operating license stage documents & correspondence
- 7812050004 Forwards Licensee Performance Eval Questions for subj facilin response to 771123 request Feels it is possible that dev of statistical methodology for such eval may not justify the effort Qualitative eval may be as good Unges 1-year test QRIER.B H Region I, Philadelphia, Office of the Director. 77/12/13 12pp
- 7810110091 Responds to 780913 NRC request for schedule for submittel o rev ECCB analysis w/corrected sirconium-water heat gandration calculations Results will be available by November 1978
 LIBRIZZI,F P. Public Service Electric & Gas Co. of New Jersey
 78/09/26 1p. 94065-349
- 7810180092 Forwards tables re total amount of water diverted from well each month & chioride analysis of water from Wells #1, 2, 3, & 5 for 780701-780930 MIDURA-H J. Public Service Electric & Gas Co. of New Jersey. 78/10/10 | 3pp. 94401-025
- 7810170132 Forwards Amend#44 to Lic Appl for subj facil.consisting of addl financial info as requested by 780417 NRC ltr MITTL-R L. Public Service Electric & Qas Co. of New Jersey 78/10/11. ip
- -- 7810170133 Forward: Amend#44 to Lic Appl for subj facil.pertaining t
- --7810170135 Amend#44 to Lic Appl for subj facil Contains addl financi * Public Bervice Electric & Gas Co. of New Jersey. 78/10/11. 1764pp.
- 7810250118 Add1 info submitted in support of appl to increase spent fuel storage capacity Covers procedures used to insure fuel storage racks are last tight & surmary of matl properties used in reck. LIBRIZZI.F P Public Bervice Electric & Gas Co. of New Jersey. 78/10/13. iipp 94392:265
- 7810240083 Forwards request for amend to Facil Open LickDPR-70 re change in reporting responds bility of Station GA Engineer.
 Librizzi, F.P. Public Service Electric & Gas Co. of New Jersey.
 78/10/17. 9pp
- 781:270006 Discusses daily staff notes for 781023 re CEIL's intention to replace recirculation inlet notice safe ends failure of Reactor Coolant Pump at PBEQ facil & 15,000 gal of water leaking into containment & inventory at Nuc Fuel Bycs.

 # Office of the Executive Director for Operations 78/10/24. ip. 94272: 261.
- 7811060089 Responds to 780831 ltr requesting info re pulsation damper & other mech devices utilized to eliminate excessive positive displacement changing pump vibration. Repts no pulsation dampers used at positive displacement pump. LIBRIZZI.F.P. Public Bervice Electric & Gas Co of New Jersey. 78/10/27. 3pp. 94424 102.
- 7811060091 Submits add1 info to support appl to increase agent fuel storage capacity at subj fecti: Neutron Absorber Spent Fuel Cell Corrosion Swelling Test, Fuel Bundle Recovery from Buiged Fuel Cell, Fuel Storage Rack Inspec. Test Surveillance LIBRIZZI.F.P. Public Service Electric & Oas Co. of New Jersey. 78/10/71. 24pp. 94424:118.
- 7811220259 Summary of 781003 meeting re PSEE0's proposed spent fuel pool mod Items discussed incl: 2.05 linear elastic limit for faulted condition.ability of new racks to withstand accidental grop & rack struc analyses.

 ZECH.0.0. Depreting Reactors Branch I (Pre 7906R5). 78/11/07. 7p 94379:335.
- 7811290288 Responds to 781106 request for info concerning licensee re-performance eval for Region 1 plents by NRC. Provides details. QRIEN, B. H. Region 1, Philadelphia, Office of the Director. 78/11/09. 9pp.

- 7812150212 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out matt. W/encl Registration Form & List of Locations MILLER-J R Assistant Director for Site & Safeguards (Pre 791030). 78/11/15. 3pp.
- 7812180283 Forwards Revai "Draft Radiological Effluent Tech Specs" Por PHR's (NNREG-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133).

 GRIMES.8 K Assistant Director for Engineers & Projects (Pre 790625) 78/11/15 4pp 94365-117.
- 7811240219 Forwards addl info in support of subj util's appl to increase the spent fuel storage capacity at subj facil LIBRIZIJ.F P Public Bervice Electric & Gas Co. of New Jersey, 78/11/20 3pp. 94458-214.
- 7812070191 Notice of seminar on 781208 on new model Reciological Effluent Tech Specs for nuc pur plants Requests advance submission of seminar specific questions Wiencl Geminar Info Sheet Proposed Agenda & maps.

 ORIER.8 H Region I. Philadelphia. Office of the Director 78/11/21. 8pp. 94375.057
- 7812140332 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing Wienci AND 47812080207.

 8CH-ENCER. A Operating Reactors Branch 1 (Pre 790525). 78/11/28. 6pp. 03537:045
- 7812080039 Forwards proprietary & non-proprietary rept*Dynamic Analysis of the Reactor Coolant Bys for Loss of Coolant Accidents: Balem Nuc Generating Stations 1 & 11, " affidavit for Withholding & Appl for Withholding ANDERSON.T.M. Hestinghouse Electric Corp. 78/12/01 2pp.
- --7812080043 "Dynamic Analysis of the Reactor Coolent Bys for LUCAs."

 Westinghouse Electric Corp. 78/12/01. 160pp.
- 7812260045 Emphasizes importance of submitting accurate & complete info to NRC by livensee & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J O. Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94133:220.
- 7812050013 Requests views of Regional Directors on Licensee performance eval of subj facils.Forwards questions to be answered by 771209.
 THORNBURG. H. Division of Reactor Construction Inspection. 77/11/23. 200.
- 7812290240 Requests that PBEO reexamine 780628 & 780731 itr requests after review of enclosed NRC Amend to 10CFR21 that was issued on 781019.

 DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 78/12/18 4pp. 94191:247.
- 7812270181 Responds to 781128 it & requests extension to 790201 to complete review of containment purging during normal plant oper. Extension will not adversely affect plant safety. LIBRIZZII.F. P. Public Bervice Electric & Oes Co. of New Jerssy. 787/82/21. ip. 94190:333.
- G. Inspection reports, IE Bulletins & correspondence
- 7811300293 Forwards IE Inspec Repts#30-272/78-23,50-311/78-27 on 780912-0916 during which no itams of noncompliance were noted.

 BRUNNER,E. J. Region I, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/10/10. 2pp. 94075:149.
- --7811300298 1E Inspec Repts#80-272/78-23.#50-311/78-27 on 780812-0916 during which no items of noncompliance were noted Major ereas inspected incl:routine inspec of oper & construc. NORHOLM, L. J. Region 1: Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/10. 13pp. 94075:151.
- 7811290397 Forwards IE Inspec Rept#50-272/78-24 on 781012-15 during which no litems of noncompliance were noted.

 8RUNNER.E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/12. 2pp. 94181:159.
- 78i1040173 Forwards IE Circular#78-17 (See AND:7810230221, Docket #30-133/781013.)
 ORIER.8.H. Region I, Philadelphia, Office of the Director. 78/10/13. ip. 94489:103.

- 78:1290389 IE Inspec Rept#50-272/78-24 on 78:1012-15 during which no items of noncompliance were noted Major areas inspected incl:survvillance calibr of safety related components. CONTE.R.J. ZIMMERMAN.R.P. Region i. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/13: 12pp. 94:81:161.
- 7811130115 Ack receipt of 780928 ltr in response to 780906 & 780612 NRC ltr informing NRC of steps taken to correct deviations noted in Inspec Rept#80-272/78-18 & 50-311/78-13. GRIER, B.H. Region 1. Philadelphia. Office of the Director. 78/10/30. 1p. 94076:090.
- --781130119 Responds to 780906 NRC ltr re deviation noted in Inspec R e80-272/78-18. Util claims alleged violetion was not & did not represent noncompliance w/100FR90.99 since subteired procedures are controlled by QA Prog to comply w/FBAR. BCHMEIDER, W.F. Public Bervice Electric & Qas Co. of New Jersey. 78/09/29 2pp. 94076: 091.
- 7812010345 Forwards licensee performance evaluation for Region 1.No operating reactor in Region 1 considered to have either abnormal or unusual safety concern.

 GRIER, B. H. Ragion 1. Philadelphia, Office of the Director.

 78/11/01. 4pp. 00002:259.
- 7811290193 Forwards IE Circuler #78-18, "UL Fire Test. "W/encl AND: 7811150002.

 GRIER.B. H. Region 1. Philadelphia. Office of the Director. 78/11/06 1p. 94239:284.
- 7812270417 Forwards 12 Inspec Repts#50-311/78-35 & 50-272/78-25 on 780917-1014 during which no items of noncompliance were noted.

 BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/13. 2pp. 94312:308.
- ~~7812270423 IE Inspec Repts#50-272/78-25 & 50-311/78-35 on 780917-101 during which no items of noncompliance were noted Major areas inspected inclutest prog controls log & record review. Emergency Drill, preoper plant personnel training. NORRHOUN,L. J., KEIMIG.R.R. Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/11/06. 15pp. 94312:310.
- 7B122B0009 Forwards IE Inspec Rept#50-272/7B-25 & #50-311/7B-35 on 7B0917-1014 during which no litems of noncompliance were noted.

 BRUNNER, E. J. Region 1: Philadelphia: Reactor Operations Nuclear Support Branch. 78/11/13. 2p. 74130:149.
- ~-7812280012 IE Inspec Repts#50-272/78-25 & #50-311/78-35 on 780917-16 during which no items of noncompliance were noted Major areas inspected inclitours of faciling & record reviews, observation of swergency drill & review of recent LERS. NORRHOLM, L. J., KEIMIO, R. R. Region i. Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/06. 15pp. 94130:151.
- 7812180022 Forwards IE Bulletin#78-12A. Suppl to IE Bulletin 78-12. W/encl ANO:7811300055. QRIER.B.H. Region I. Philadelphia, Office of the Director. 78/11/24. [p. 94133:286.
- 7812110100 Cladding Flaws detected May 1976 in Unit 1 Steam Generator 614 have been inspec w/ultrasound & TV. Interprets Tach Specs as limiting TV inspecs to areas where results can be correlated w/ultrasound inspecs.
 LIBRIZZI.F. P. Public Service Electric & Ges Co. of New Jersey.
 78/11/27. 2pp. 94393:274.

R. Periodic operating reports & related correspondence

- 7810160084 Forwards Monthly Open Rept for Bept 1978.
 MIDURA-H. J. Public Service Electric & Oss Co. of New Jersey.
 78/10/10. 1p.
- --78/0160090 Manthly Oper Rept for Sept 1978.
 MILLER,L. K. Public Bervice Electric & Ges Co. of New Jersey.
 78/10/10. 15pp.
- 78:10:180:128 Forwards Westewater Treatment Rept for Sept 1978 for sewag treatment plant at subj facil.
 MIDURAN. J. Public Bervice Electric & Cas Co. of New Jersey.
 78/10/10. 2pp. 94:195:296.
- 7810180144 Forwards Discharging Monitoring Repts for sub; fecil for Bept 1978. MIDMA.H.J. Public Service Electric & Gas Co. of New Jersey. 78/10/10. 19pp. 94316:388.

- 7810250103 Forwards "Impingement Monitoring Prog Rept #18" for Sept 1978 LIBRIZZI.F P Public Service Electric & Oas Co. of New Jersey 78110718 ip 94392 276
- --7810250104 "Impingement Monitoring Prog Rept #18 for September,1978" Impingement rate of weakfish is declining steadily • Public Service Electric & Oas Co of New Jersey 78/10/18 63pp 94370-268.
- 7812080113 Forwards tech rept "Summary Assessment of Weakfish Ispingement Summer 1978" SHIBIAS, J.A. Public Service Electric & Gas Co. of New Jersey. 78/11/06 2pp. 94108:123
- --7812080115 "Summary Assessment of Weakfish Impingement Summer 1978" Concludes available data on population size number impinged to survival indicate that impingement did not significantly impact on 1978 year-class of weakfish Public Service Electric & Oas Co of New Jersey 78/11/30. 19699 94108.125.
- 78:11:60074 Forwards Monthly Open Rept for Oct 1978. MIOURA:H J. Public Service Electric & Qas Co. of New Jersey. 78/11/09 ip 94133-147.
- --7811160075 Monthly Oper Rept for Oct 1978. MILLER, L. K. Public Bervice Electric & Gas Co. of New Jersey. 70/11/09 17pp. 94133-148.
- 7812120151 Honthly rept Oct 1978. HILLERLL X. Public Bervice Electric & Gas Co. of New Jerssy. 78/11/09. 2pp 94276:284.
- 7811210323 Forwards Hastewater Treatment Rept for Oct 1970. MIDURAH J. Public Bervice Electric & Oas Co. of New Jersey. 78/11/10 2pp 94485.267.
- 78:2080134 Forwards Rept #19 on "Impingement Monitoring Prog" for Oct 1978 LIBRIZZI,F P. Public Service Electric & Gas Co. of New Jersey 78/11/20. ip 94:08-308.
- ---7812080136 "Impingement Montoring Prog. Oct 1978," Rept#19. On 781012 reactor was taken out of svc for month & only 1 pump was in svc resulting in low impingement rates Before shutdown fish not found in all samples, showing they are leaving area * Public Bervice Electric & Gas Co. of New Jersey. P77-54-19. 78/11/20. App. 94108:309
- 7812190242 Forwards Monthly Oper Rept for Nov 1978. MIDURAM J. Public Service Electric & Qas Co. of New Jersey. 78/12/11 ip. 94213.274
- --7812150244 Monthly Oper Rept for Nov 1978.
 MILLER,L K. Public Service Electric & Gas Co. of New Jersey.
 78/12/11 13pp. 94213:275
- 7811210343 Forwards Discharge Monitoring Repts for Oct 1978. MIDURA: H J. Public Service Electric & Gas Co. of New Jersey. 78/11/17. 10pp. 94484: 342.
- B. Reportable accurrences, LERs & related correspondence
- 7810100028 Forwards LER#78-062/03L LibelZII,F P. Public Service Electric & Ges Co. of New Jersey. 78/10/03. 1p. 94033:039.
- --7810100033 LER#78-062/03L-0 on 780913:during normal open the #12 Reactor Coolant Flow Channel 2 was not indicating due to failure of a Hagen Controls Bignal Isolator.

 KAPPLE.A. U Public Bervice Electric & Gas Co. of New Jersey. 78/10/03. 3pp.
- F310100037 Forwards LERW78-063/03L-0. LIBRIZZI.F.P. Public Service Electric & Gas Co. of New Jersey. 78/10/03. 1p. 94039:074.
- --7810100041 LERW78-053/03L-D on 780910:during normal oper the fan coil water flow trouble alarm sounded for W13 Containment Fan Coil Unit Unit was declared inoper due to slit buildup in low pressure sensing line.
 KAPPLE:A. H. Public Service Electric & Gas Co. of New Jersey. 78/10/03. 3pp. 94039:075.
- 'SIO100087 Forwards LERB78-064/03L-0. LIBRIZZI,F.P. Public Service Electric & Qas Co. of New Jersey. 78/10/03. ip. 94033:174.

- --7810100089 LERW78-064/03L-0 on 780912 reactor trip setpoint greate than 1/8 limit during check of presours protec channel 2 Caused by unstable quiput from comparator feeding trip bistable Comparator replaced KAPPLE.A W Public Bervice Electric & Gas Co of New Jersey 78/10/03. 3pp 94033.177
- 7810200119 Forwards LER#78-061/01X-1.
 L1BR1221.F P Public Service Electric & Gas Co of New Jersey.
 78/10/16 1p 94401 205
- 7810230243 Forwards LER#78-065/03L-0 LIBRIZZI.F.P. Public Service Electric & Oas Co. of New Jersey. 78/10/18 1p. 94052 283.
- --7810230249 LERM78-065/03L-0 on 780924 containment isolation valve to be electrically inoperable in closed direction. Normally closed auxiliary contacts in opening main contactor found to be open. Auxiliary contact assembly replaced KAPPLE.A. W. Public Service Electric & Gas Co. of New Jersey 78/10/18 3pp. 94052/284
- --7810230255 LERW78-066/03L-0 on 780929 inner door of 100 foot eleval air lock inner door ecceded maximum leak rate Caused by improper latch adjustment due to normal oper & maintenance wear Door latch readjusted.

 KAPPLE.A.W. Public Service Electric & Oas Co. of Nou Jersey 78/10/18 | p. 94165 100
- 7810230295 Forwards LER#78-068/03L-0 LIBRIZZLF.P. Public Service Electric & Gas Co. of New Jersey. 78/10/18. 1p. 94164:188.
- --7810230304 LERW78-068/03L-0 on 781004 Personnel air lock inner doc exceeded maximum leak rate Causa was improper latch adjustment caused by usar Roller latch readjusted & test reperformed to confirm operability. KAPPLE, A W Public Service Electric & Gas Co. of New Jorsey 78/10/18. 2pp. 94164-189.
- 78:03:10:137 Reportable Occurrence 78-70/01P: on 78:10:21. failure of #13 reactor coolant pump shaft seals resulted in excessive leakage of primary coolant into containment Detailed rept will follow MIDURA: M.J. Public Bervice Electric & Gas Co. of New Jersey 78/10/23. pp. 94090: 159.
- 7811130266 RD 78-70/Q1P:on 781021.W13 Reactor coolant gump shaft see failed resulting in excessive leakage of primary coolant into container. Detailed RO Rept will be submitted MIDURA.H J. Public Service Electric & Gas Co. of New Jersey. 78/10/23 ip. 94011:210.
- 7810310180 Confirms 781024 verbal rept of RO.Low pressure in contro air age caused operation of air operated deluge valves, necessitating operation of fire pumps in manual mode LER will follow. MIDURALM.J. Public Service Electric & Gas Co. of New Jersey 78/10/24. 1p. 94090:238.
- 78:11:00263 Ack 78:024 verbal rept to L Norrholm advising of reportal occurence re oper of fire pumps in manual mode resulting from low presure in the control air sys & caused by operation of deluge valves. R0 rept will be submitted MIDMA.H.J. Public Bervice Electric & Gas Co. of New Jorsey. 78/10/24. 1p. 9401:208.
- 7810310254 Forwards LER#78-067/03L-0 LIBRIZZI,F. P. Public Service Electric & Qas Co. of New Jersey. 78/10/20. jp. 94094:284.
- --7810310260 LERW70-067/03L-0 on 780929: missing fire berrier in ceb penetration identified. Caused by failure of admin controls to pinsure fire berrier installation. Cable penetration was immediately properly sealed. Others to be inspec by 781101 KAPPLE.A.W. Public Service Electric & Qas Co. of New Jersey. 78/10/26. 3pp. 94094: 285.

KAPPLE, A.W. Public Service Electric & Cas Co. of New Jersey. 78/11/01 3pp 94040:185.

7811070178 Forwards LER#78-070/01T-0 LIBRIZZI.F.P Public Service Electric & Gas Co. of New Jersey. 78/11/02 lp 94044-181.

--78110701B1 LER#78-070/01T-0 on 781021: during Mode 4 open, while heating up to enter Mode 3.high flow thru #13 RCP seals & other alarms indicating RCS leakage observed. Cause unknown: suppl rept to be submitted when cause discerned.

KAPPLE: A.W. Public Service Electric & Oas Co. of New Jersey. 78/11/02. 3pp 94044:182.

7811070266 Forwards LER#78-069/031-0. LIBRIZZI.F.P. Public Service Electric & Gas Co. of New Jersey. 78/11/02. 1p. 94040:193.

--78:1070268 LER878-069/03L-0 on 78:01]: while investigating 18 Diesel Alarm.heater leaking chromated water into pre-lube pump motor was discerned Lesk caused by carrysion of element sheath of 2 of the 3 heater elements.

KAPPLE.A.W. Public Bervice Electric & Gas Co. of New Jersey.
78/11/02. 3pp. 74040:194.

7811170181 Reportable OccurrenceM78-72/OIP: high external radiat levels in fan coil unit detector location would result in isolation of svc water to fan coil units, would render them inoperable. Detailed rept to follow.

MIDURA, H. J. Public Barvice Electric & Gas Co. of New Jersey.
78/11/07. ip. 94048.138

7811280460 Reportable Occurrence 78-72/01P on 781106: design deficiency re high rediat levels in gen area of containment fen coil unit would be sufficient to cause monitors to alorm & perform isolation function. Engr dept to change design MIDURA;H. J. Public Bervice Electric & Gas Co. of New Jersey. 78/11/07. ip. 94376:327.

7811220107 Forwards comments in the form of redraft of Commission paper re-proposed Fed Register Notice "Abnormal Occurrence Event, Loss of Containment Integrity" W/encl draft notice of issuence.

DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 78/11/11. 15pp. 94273:306.

7811200201 Forwards LER678-043/03L-1.
L1881271:F P Public Service Electric & Gas Co of New Jarsey.
78/11/14. 3pp. 44232:037.

--7811200203 LER#78-043/03L-1 on 780B0B: as reactor pur was increased a deviation alarm would not clear & a GPT celculation showed a GPTB of 1.03%. Due to large load reduction Design change will delete tha less than 50% pur alarm KAPPLE. A. W. Public Bervice Electric & Gas Co of New Jersey. 78/11/14. 1p. 94292:040. (

7811240132 Forwards LER#78-072/01T-0. LIBRIZZI.F.P. Public Bervice Electric & Gas Co. of New Jersey. 78/11/20. ip. 94437:001.

--7811240137 LER#7B-072/01T-0 on 781106: during Mode 5 oper, all containment fan coil units were found inoper due to tripped svc water valves, caused by design deficiency in detector installation. KAPPLE.A.W. Public Service Electric & Ges Co. of New Jersey, 78/11/20. 3pp. 94457:002

7811280304 Forwards LER078-043/03L-0. L188121.F.P. Public Service Electric & Que Co. of New Jersey. 78/11/52. ip. 94395:302.

--7811280313 LER#78-043/03L-0 on 780808:during normal oper.after 45% pur reduction to less them 30% for maint-reactor pur increased to 51%. Deviation alarm would not clear & OPTR was 1.03%.0PTR was not discovered sooner because of alarm indications. KAPPLE.A.W. Public Bervice Electric & Gas Co. of New Jersey, 78/11/22, 1p. 94395:303 LIBRIZZI, F. P. Public Bervice Electric & Gas Co. of New Jersey, 78/12/11. 1p. 9408B:142

--7812140169 LER#78-073/01T-0 on 781127:18 Vital Instru Bus was lost causing reactor trip Bafety injection followed & 18 Dissel #11 Charging & #12 RHR pumps failed to start. Caused by bad output transformer in supply inverter.

KAPPLE, A. W. Public Bervice Electric & Gas Co. of New Jartsy. 78/12/11 4pp. 94088:143

7812220085 Forwards LERM78-075/03L-0.

LIBRIZZI,F. P. Public Bervice Electric & Gas Co. of New Jersey. 78/12/18. 1p. 94343:331.

--7812220086 LERM78-075/03L on 781130: during open w/containment entry in progress, inner door of eir lock 130 would not fully open-caused by feiled cam roller on inner door operating mechanism. Air lock repaired, tested, returned to svc. KAPPLE, A. M. Public Service Electric & Gas Co. of New Jersey. 78/12/18. 2pp. 94343:332.

DOCKET 90-274 U B. GEOLOGICAL SURVEY RESEARCH REACTOR

H. General correspondence

7812200238 Effective 770101. Administrator of the geological survey TRISA reactor will be AP Marranisms. CLESSCH.A. Interior, Dept. of, Geological Survey. 78/12/14. 19. 94162: 337.

P. Operating license stage documents & correspondence

7810230134 Repts slow droptime for transient rod in subj reactor.dup to faulty cylinder & seel. Repair completed by 780927. CLESSCH.A. Interior.Dept. of. 78/09/27. 2pp. 94271:180.

7811090063 Requests change to paragraph 2.8 of lic to read "to receive possess & use up to 5 kg U-235 for use in connection w/oper of reactor."
CLESSCH.A. Interior.Dept. of. 78/10/11. 2pp. 94040:122.

DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

A. Application/construction stage documents & correspondence

7810140114 Forwards matl in support of oper lic appl re environ qualification of equip. Requests ack of receipt of Matl. CRANE.P.A. Pacific Que & Electric Co. 78/09/21. lopp. 94421:081.

7810120058 Forwards responses to informal questions posed by 780804 MRC memo on selemic quelifications. Submission is nonproprietery version.

CRANE. P. A. Pacific Gas & Electric Co. 78/09/22. 44pp. 94081:184.

7810190071 In response to 780321 NRC request for add1 info on containment purging forwards ensuers to questions, draft Tech Specs & rept on "Analysis of Off-Site Exposures due to LOCA coincident w/Containment Purging."

CRANE,P.A. Pacific Oss & Electric Co. 78/09/27. 106pp. 94323:001.

78:0170179 Forwards response to 780728 ltr re reactor vessel matl properties noncompliance w/10CFR50. Appendix 9. fracture toughness requirements. & 10CFR50. Appendix H. reactor vessel matl surveillance prog requirements. CRAME, P. A. Pacific Gas & Electric Co. 78/10/02. Spp. 94270:073.

7810310226 Forwards responses to 780728 NRC ltr re reactor vessel mati properties noncompliance w/1007880 toughness & surveillance requirements. Requests ack of receipt.
CRANE, P. A. Pacific Oas & Electric Co. 78/10/02. 8pp. 94090:339.

7810170221 Bubmits info re "degraded grid voltage" as result of discussions w/Instrumentation & Control Bys Branch reviewer on 780929 as suppl to previous submittals on second level under/over voltage protec. Design is acceptable by ICSB rev. CRANE, P. A. Pacific Gas & Electric Co. 78/10/04. ip. 94234: 165.

- 730038 Ack receipt of 780906 ltr re subj facil Provides info on sale assessment of site decomm astimate & waste mgt. ICKS-M. J. Office of the Esscutive Director for Operations. 10706. 3pp. 94032:333.
- GG30042 Requests add) info re issuence of constr permit. URTON, P. House of Rep. 78/09/06: ip. 94052:338.
- 90294 Trip reptiplant visit & mesting w/applicant on 780905 to cuss remaining Open issues re aubj facil.W/aummery of sining unresolved issues.
- .P.T. Structural Engineering Branch. 78/10/06. 4cp. 94R39:247.
- 70205 Attached Table 6.3-10, which appeared in Amend 67, has been nged as indicated to reflect Staff's concerns re added was position & function. Change to be documented in ure amend Five copies of submittal sent to D. Allison. NE.P.A. Pacific Gas & Electric Co. 78/10/10. 2pp. 94935:337.
- 60118 Forwards amend fee per 780811 & 23 requests for extension of st completion dates of CPPR~69 & CPPR~39.

 NB.P.A. Pacific Gas & Electric Co. 78/10/11. 2pp. 94005:162.
- 70227 Summarizes discussion w/NRC,POE, & OE on 780830 in Bethesda, re-electrical penetration qualification.
 4E.P.A. Pacific Oss & Electric Co. 78/10/11. 4pp. 94236:173.
- 50206 Responds to requests of 780811 & 780823 by issuing Order inding construction dates for subj facil. 2.J.F. Light Water Reactors Branch 1. 78710713. 3pp. 823.
- 250212 Order extending constr completion dates for subj facil to 70430 for Unit 1 & 781031 for Unit 2.Eval of Request for tension of Constr Permit entl. FD.R.B. Division of Project Management. 78/10/13, 2pp. 1372:336.
- Q219 Forwards seismic design audits & lists equip qualified for te environ.

 BDM.D.P. Light Water Reactors Branch 1. 78/10/16. 34pp.

 8:112
- 260225 Rept of seismic analysis & struc design eval used in viewing turine padestale for response to postulated 7.5M sgri earthquake.

 DOM.J.A. Pacific Gas & Electric Co. 78/09/15. 38pp.
- 0257 Forwards gen repair prog for arc strikes & wald spatter on Code Class 1,2 & 3 pressure boundaries in accordance w/ irements of ABME Code section XI, summer 1978 addendum. serci.
 5, P.A. Pacific Gas & Electric Co. 78/10/16. 2pp.
- 3099 Bummery of 781012 meeting re-smissic qual of elec equip. awad test results of elec equip. Did not discuss review sch aspects of test involving type & severity of Ing. W/encl list of attendees & results of discussion.
 30M.D.P. Light Weter Reactors Branch 1. 78/10/18. 13pp. 7:309.
- 2381 Bunmarizes 781005 meeting re sub; facil review ached. Object reting: to discuss status of numerous specific items review & to identify items of most concern re meeting ichedule. List of attendees encl.
 LON. D. P. Light Water Reactors Branch 1. 78/10/18. 15pp. 1:149
- 1029 Bummary of 7B1020 meeting re seismic qual of subj facil equip. 15 items found acceptable & 8 items needed mod. tems pertain to Instru/Control Bys. W/encl Branch Review BS scope equip w/in Westinghouse qual prog. ON. D. P. Light Water Reactors Branch 1, 78/10/25, 9pp. ;117.
- O21 References comments in matter of cross-examination of Itants to ACRS at licensing proc be decided as soon as ble. Comm will consider the matter on a generic basis Ed agreet that it is a top-level policy question. B.E. B. Atomic Safety and Licensing Board Panel. 78/10/27. ip. 8:319.
- 040 Ack receipt of 781020 NRC ltr. Repeats opposition to cross-nation procedures of AGRS consultants in licensing
- P.A. Pacific Gas & Electric Co. 78/10/27. 10. 94398:116.

- 7811060005 Forwards 781026 Gen Elec response to 780830 NRC questions reeuby facil elec penetrations qual Bone info is new. ALLIBON,D. Light Water Reactors Branch 1 79/10/30. 3pp. 94397:343.
- --7811080008 Responds to questions raised at 780830 meeting w/NRC raqualification of elec panetration assemblies for subj facil Addresses justification of qual by similarity, verification of repaired assemblies & QE knowledge of repair.

 CLEVELAND, J. W. General Electric Co. 78/10/16 14pp. 94397: 346.
- 7811070271 Advises that cannister-type penetrations meet environ qual requirements consistent w/those found acceptable for Three Mile Island. Also supplies date re rain line steam breek analysis & use of diesel generator under test.

 CRANE.P. A. Patific Gas & Electric Co. 78/11/02 2pp. 94040-284
- 7811200366 Forwards QE draft ltr re testing of penetrations-adequacy of repair. QE tested a leaking-unrepaired penetration to test epoxy seal & concluded that a repaired penetration should not act differently.

 LAINAB.G. Plant Systems Branch (Pre 791030). 78/11/09 lp 94419:211.
- --7811200384 Responds to 780830 NRC ltr questioning qual of elec penetration assemblies supplied to subj facil incl attachment on "Comparison of Cannister & 100 Series Fanetration Designs". CLEVELAND, J. W. General Electric Co. 78/10/26 13pp 94419:212
- --7811200392 Final protatupe test rept "Millstone 2 Elec Penetration Post-LDCA Prototype Test".Low voltage pur & control modules were subjected to 1635 dayres.5 psig.100% RH environ for 52 weeks.Leakage rate was less than 1s10 to 8 pur cc He/6sc. LURIA.N. Q. General Electric Co. 78/11/09. 4pp
- 7811210234 Forwards seismic qual summary forms for all WE valves identified in Tables 7-7 & 7-7A of "Hosgri Rept." ANDERSON, T.M. Westinghouse Electric Corp. 78/11/10. 33pp 94497:149.
- 7811210318 Presente ACRS conclusion from 781102-04 meeting that Dr Luto's concerns re seismic eval bases for sub; facila were considered in findings & recommendations in 780714 ACRB rapt. LAHROSKI, B. ACRB - Advisory Committee on Reactor Safeguards. 78/11/07. ip. 94482:175
- 78:2050083 Forwards RevM1 Draft Radioligical Effluent Tech Spec for Pur's(NUREG-0472) & "Praparation of Radiological Effluent Tech Bpsc for Nuc Pur Plants"(NUREG-0133). W/o encl ANC: 76:1270:173 & 76:1270:180. VABBALLO, D. B. Assistant Director for Light Water Reactors, 78/11/16. 6pp. 94336:184.
- 78:122018: Forwards Amend#78 & Amend#73 to Oper Lic appl. CRANE, P. A. Pacific Gas & Electric Co. 78/11/20. 3pp. 94387:001.
- --7811220182 Amend#72 & Amend#73 to Oper Lic appl u/addl matl for Hosgri Baismic Syal & FBAR: respectively. BCHACKLEFORD, B. Pacific Gas & Electric Co. 78/11/15. 286pp. 94397:004.
- 7811300364 Informs PQE that NRC hass contracted w/Mountain West Res Inc to undertake a series of post-licensing studies of our purstations. Studies will analyse sociasion impacts which occurred during constr & post-constr periods of each plant. DEYGUNG. R.C. Division of Site Sefety & Environmental Analysis. 78/11/20, 2pp. 94116:299.
- 7811300079 Forwards log of contacts from 780419-780305 by resident PQ&E engr in Bethesda for liaison w/NRC.
 ALLIBON, D. P. Light Water Reactors Branch 1. 78/11/21. 12pp.
- 7812010010 Forwards staff eval of probabilistic seismic risk assessment covering: POE studies on probabilities of earthquakes & resulting ground acceleration at site. & probabilities of various consequences.

 BTOLZ, J. F. Light Water Reactors Branch 1, 78/J1/21, 3pp. 94409: 128.
- --7812010014 Discusses PSE studies in 1977-78 on probabilistic evel of sarthquaks hazard. Various assumptions are questioned. 8TEPP, JrC. Qeosciences Branch. 78/05/08. 400. 94409:131.
- --7812010013 Forwards staff eyal of Amend 92 to lic appl re Risk to Pub

- --7912010019 Clarifies certain points of eval of analysis of risk to pub from seismic events contained in 780908 memo. Covers probability of Core meltdown, & earthquake probabilities BUHL.A.R. Probabilistic Analysis Branch (Pre 791030). 78/11/06. 29p. 94409-144
- 7812210229 Forwards seismic test procedure for subj facil 4160V Class IE Buitchgear Bus Undervoltage Relays. CRANE, P. A. Pacific Qos & Electric Co. 78/11/28. 1p. 74279:129.
- --7912210235 Beismic test procedure for 4160V Class IE Switchgear. Undervoltage Rolays demonstrates relays performance while being switniched on & off during the shake. HERBST.J.E. NIELSEN.D. COLHELL.J.H. Pacific Qas & Electric Co. 78/11/27. 31pp. 94279:130
- 781212020B Requests add1 info re meens of accomplishing quality inspectat subj facil. 8TOLZ-J.F. Light Water Reactors Branch 1. 78/11/30. 3pp. 94276:061.
- 7812210197 Forwards seismot test procedure for subj facil diesel generator control cabinet. CRANE.P.A. Pacific Gas & Electric Co. 78/11/30. ip. 94279:068.
- --7812210209 Seismic test procedure for diesel generator control cabinet.
 Tests will demonstrate that relays are capable of changing
 state during a seismic event if necessary.
 HERBST-J E , NIELBEN.D., COLWELL.J.W. Pacific Gas & Electric Co
 78/11/30. 9pp. 94279:069.
- 7812210223 Forwards seismic test procedure for subj facil local starter LPF36. CRANE-P.A. Pacific Oas & Electric Co. 78/12/01. 1p. 94279:121.
- --7812210225 Seismic test procedure for local starter LPP36. Tests will
- determine if LPF36 motor contacts main pur contacts change state during a seismic event.
 YCUNO.R.A., NIEL8EN.D.; COLHELL.J.W. Pecific Ges & Electric Co. 78/12/O1. 3PP. 94279:122.
- 7812120161 Forwards 8 requests for exemption from ASME Code Section 11 pump & valve testing requirements. Requests 1 thru 4 are continuations of attachments 7 & 9 to 771010 PGE 1tr recompliance u/Bection 50.534(g), 10CFR50.

 CRANE.P. A Pacific Oas & Electric Co. 78/12/06. 10pp. 94276:343.
- 7812130389 Forwards 781101 ltr from Hilsy Labs re test mounting configurations for selemic qual testing of elec equip. This memo places matt in file to the PDR to informs parties of info availability.

 ALLISON. D. P. Light Water Reactors Branch 1. 78/12/06. 3pp. 94292:231
- --7812130390 Clarifies questions raised at 781020 maeting re test prog for elec equip. SHIPHAY, O. D. Affiliation Unknown. 78/11/01. 2pp. 74292:234.
- 7812150033 Forwards informal info "Investigation of A Seiche due to Design Spectre at Raw Mater Storage Reservoir. Subj Fecil Nuc Proj" by CE Cecilio discussing potential for seiching in raw water reservoirs.

 ALLIBON D. P. Light Water Reactors Sranch 1. 78/12/06. 20pp. 02016-020
- 78:22:0193 Forwards seismic test procedure for 125 VDC switchgear, distribution panel & mold case circuit breakers & test rept entitled "Beismic Testing of Bafety-Related Elec Equip for PGE."

 CRANE: P. A. Pacific Ges & Electric Co. 78/12/06. 4pp. 94279:027.
- --7812210200 Seismic test procedure for 125 volt DC switchgear, distribution panel & mold case circuit breakers. PATTERBON.H., GOAD, L.F., BHIPHAY, G.D., Pacific Gas & Electric Co. 78/11/28. 34pp. 94279:031.
- 7812280095 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS. J. Q. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 03555:311.
- 7812190143 Forwards rept presenting results of a large-break loss-of-coolant(LDCA)accident. New analysis incorp a correction to clad-water heat of reaction calculation & recent ECCS eval model improvements.

 CRANE, P. A. Pacific Gas & Electric Co. 78/12/07. 78pp. 94376:031.

- 7812180374 Forwards request for add1 info re boilted connections in linear supports of subj facil support base plates Requests response sched. STOL2.J.F. Light Water Reactors Branch 1. 78/12/08 Spp. 94357-275
- 7812260217 Requests add1 time to dev draft Appendix ! Tech Specs.
 Proposes submittal by 790216.
 CRANE,P. A. Pacific Oas & Electric Co. 78/12/14. 1p. 94162.098
- 7B11R10113 Forwards 7B1107 ltr to Chairman Hendrie re ACRB review of appl for permits to open subj facil.
 BTOLZ/J.F. Light Water Reactors Branch 1. 7B/11/14 3pp 74482:172.
- E. NRC Safety Evaluation Report (SER), suppls & correspondence
- 7812070056 Forwards Suppl 8 to SER for subj facil. VASBALLO.D.B. Assistant Director for Light Hater Reactors. 78/11/10. ip 94462.032
- --7812070063 Forwards Supple8 to SER for subj facil. BTDL7.J.F. Light Water Reactors Branch 1. 78/11/14. 3pp. 94462:033.
- --7812070067 Suppl 8 to facility BER. a Division of Project Management. 78/11/15. 110pp. 94462:001
- 7812050155 Forwards add1 info to address Section7. B. open item 3 of SER Suppl 7. re environ qual of Fen Cooler Pur Cables. Attachment #1 on Specs. Tests & Installation of Wires & Cables at subj facil is not enci.

 CRANE.P. A. Pacific Ges & Electric Co. 78/11/27. 12pp. 94335:074.
- F. Security, medical, emergency & fire protection plans
- 7811290307 Summary of 780214-15 meeting w/util re subj facil fire protec prog. All mods will be made prior to fuel loading. HEARN, P. C. Auxiliary Systems Branch. 78/03/29. 33pp. 94181:306.
- 7811210164 Forwards rev responses to NRC fire Protec Review questions 5.8.9.21.23.24, 26-29, 45, 46 & 49-51 & rev rept "Supplementary Info for Fire Protec Review." Review question items incliconstr design, fire protec valves & automatic sprintlers, CRANE.P.A. Pacific Gas & Electric Co. 78/11/13. 54pp. 94485-294.
- --7811210169 "Buppl Info for Fire Protection Review." # Pacific Gas & Electric Co. 78/11/13. 138pp. 94486:001.
- 7811290400 Forwards suppl detailed info related to subj facils seisaic design audits & the fire protection review. W/31 drawings available in Central Files.

 ALLIBON, D. P. Light Water Reactors Branch 1. 78/11/21. 1029pp. 94182:001.
- 7812290102 Review of Fire Protec safety evel rept for subj facil has been completed. Concurs in NRC findings & in NRC conclusion that upon implementation of mode listed in rept, fire protec prog will be acceptable.

 BEHN J.D. Oags-Babcock Associates, Inc. 78/11/29. 1p. 94190:116.

9. Adjudicatory correspondence

- 78:0160155 Requests by intervenors for production of documents by NRC staff & applicants & enlargement of time to file interrogs. Also submits interrogs to appl & requests that attached documents be explained.
 FLEISCHAKER, D., PHILLIPG, J. Center for Law in the Public Interest. 78/09/27. 19pp. 94005:143.
- 78:0190207 Forwards various pleadings of Intervenors(Scenic Shoreline Preservation Conference Sen Luis Obispo Mothers for Peace: Ecology Action Club, S. A. Silver, & J. J. Forster) re oper lic. FLEISCHAKER, D. Fleischeker, D. B. 78/09/28. 3pp. 94032:017
- --7810190262 Intervenors(Scenic Shoreline Preservation Conference,etc), request for oral argument.
 FLEISCHAKER, D. Fleischeker, D. S. PHILLIPB, J. P., KRISTOVICH, B. Center for Law in the Public Interest. 78/09/28. 3pp. 94052:020.
- --7810190267 Intervenors(Scenic Shoreline Preservation Conference,ett)
 request to reply to NRC & applicant response to intervenors
 request for issuance of ASLB subposenas.
 FELISCHAMER, D. Fleischaker, D. B. PHILLIPB, J. P., RISTOVICH, B.
 Center for Law in the Public Interest. 78/09/28. Spp. 94052:023.

190269 Intervenors(Scenic Shoreline Preservation Conference, stc) quest to reply to NRC & applicant response to intervenors quest for issuence of AGLS subpones.
EISCHAKER,D. Fleischaker, D. B. PHILLIPB,J.P., KRISTOVICH,S. nter for Law in the Public Interest. 78/09/28 32pp. 052:025

Olog Notice of reconstitution of ASLAB re CL proceeding.

liman, A Rosenthal & W Johnson will serve on board.

O.M.S. Atomic Gafety and Licensing Appeal Panel. 78/10/03. ip.

O324 Suppl Memo in support of intervenor SLDM appeal from 780511 O703 Orders re qual of security experts SLDM now seeks of certification & qual only of D Comey as security rt for discovery purposes.

8, Y. 1. VALENTINE.P. C. San Luis Obispo Mothers for Peace.

0/06. 22pp. 94389:275.

Oi26 Grents request by intervenor for extension to 781006 to ond to PGE motion to diamiss security contention.NAC f is also granted extension to 781006,per their request. RS E.S. Atomic Sefety and Licensing Board Panel 78/10/10. 94414:025.

O182 Denies request by Intervenors that Bd subpoens 13 persons as eases in evidentiary hearing. Denied because Bd remains nvinced that circumstances are exceptional & warrant ting the request.

RB:E.B. Atomic Safety and Licensing Board Panel 78/10/10.
94392:254.

O-OOB Requests 8d stay issuance of any order on Applicants motion ismiss security contention until Appeals 8d issues its rng in repsonse to Intervenors motion for direct ification, M/encl cert of svc.
NTINE.P.C. Ban Luis Obispo Mothers for Peace. 78/10/10. 4pp. 4: 216.

OBSO PORE response to intervenor BLOM's Petition for direct ification & BLOM's appeal from ABLB Order of 780905. PORE rts that certification is not appropriate. Supporting mentation & Cert of Bvc encl.
ON.B., MDRRIBBEV., C., CRANE, P. A. Pacific Qas & Electric Co. O/13. 35pp. 94253:279.

O294 Intervenor's Request to Subposes Dr S Graham to testify restrions that Applicant has failed to conduct thorough stigations of Hospri fault sys. Cert of Svc encl. SCHAKER.D. Flaischaker, D. S. PHILLIPS, J. P., KRIBTOVICH, S. 11ation Unknown. 78/10/16. 11pp. 94025:347.

O128 Advises Lic 8d of status of 6 independent experts subpossed equest of Intervenors.

8CHMARR, D. Fleischeker, D. 8. 78/10/16. 2pp. 94035:143.

OB18 NRC Staff Answer to Appl Motion to Dismiss Security ention. Staff suggests the Ed defer on a ruling while revenue Sen Luis Obispo Mothers for Peace awaits ruling heir appeal re the security issue.

NBERO, M. R. Office of the Executive Legal Director. 78/10/16. 74389: 265.

OO82 Informs Bd that Staff will comply w/Intervenor's request documents & interrogs to the Staff no later than 781025 to error in mails. There will be the same answering time inally anticipated by parties.
TELLOTTE, J. Hearings Division. 78/10/17. 2pp. 94035:096.

OO39 Replies of Subj Util to Intervenors' Interrage dtd 780927. mes of Qual for Safety Hearings & Cert of Svc encl. E-P.A. , NORTON.8. FURBUSH.M. H. Pacific Gas & Electric Co. O/17. 95pp. 94290:008.

O314 Forwards subposes for signature of E Bowers.One will be ed upon Dr Stephen Orahem; the other E copies are for reference.

BCHAMER.D. Fleischaker, D. B. 78/10/23. 1p. 94087:042.

OOSS Notice of addition of E J Bullivan to list of staff sease provided in Sept 1978 Davis live re radiological th & safety hearings.
TELLDITE.J. Office of the Executive Legal Director. 78/10/25. 94423: 325.

0199 "NRC Staff Response to Intervenor's San Luis Obisso Mothers Peats Patition for Directed Cent & Appeal from Licensing rder of 780905." Urges Intervenors petition be denied. of Svc encl. NBERG, M. R. Office of the Executive Legal Director. 78/10/26. . 03593:348. 7811080185 Hemoremoum & Order granting the petition for directed certification vacating Bd's 780905 order & remending the cause for immediate further consideration consistent withis opinion in the oper licensing proc.

DUFLO.H. E. Atomic Befety and Licensing Appeal Panel. 70/10/27, 12pp. 74405:115.

7811100014 No objection to Intervenor's request of 781016 to subpoens Dr Grehm for the upcoming evidentiary hearing TOURTELLOTTE.J. Office of the Executive Legal Director. 78/16/27. ip. 94175:351.

7811080029 Forwards "Staff Comments on Generic Hetter of Cross"
Elanthation of ACRE Consultants in NRC Licensing
Proceedings", W/encl Cert of Svc.
TREBYS A. Office of the Executive Legal Director 20/10/30. 10pp.
94398:047.

7811280498 Notice that PQE will take depositions of F 811ver.J Brune & R Hubbard. Also encl is response of PQE to intervenors' request of 780927 for production of documents. Documents sought are now available for inspec. Cert of 8vc encl CRANE.P. A. Pacific Gas & Electric Co 78/10/30. App 94414: 269

7811070338 Urges ACRB permit cross-exemination of consultants. Cross-exemination is essential to accurate interpretation of opinion & determination of factual bases of assumption. VALENTINE, P. C. Valentine, P. C. 78/10/31

78:1170007 "Reconsideration of Bd's Order of 780905." Petition of Dan Luis Objego Mothers for Peace to establish David Comey as an expert witness is denied.
BOWERS.E. 8. Atomic Safety and Licensing Board Panel. 78/11/03.
37pp. 94:14:104.

78:1200042 Evidentiary hearing on 78:204 will be held in Avila Beach. CA.First 2 days of hearing will be set aside for limited appearance atatements of no longer than 5 minutes each. Written statements of any length may be submitted. 80WERS.E. S. Atomic Sefety and Licensing Board Panel. 70/11/07. 2pp. 942:5:324.

7812010198 Attorney RK Hosfling enters appearance in captioned matter. Cert of Syc enci. HDEFLING.R.M. Office of the Executive Legal Director. 78/11/09. 3pp. 94409:205.

7812010048 Expresses view on gen policy question of subpoening ACNB consultants to require their attendance at evidentiary hearings before ABLB. Exceptional Licrometances standard should not be limited to direct knowledge witnesses.
FLEIBCHAKER, D. Center for Lew in the Public Interest. 78/11/14, 3pp. 94416:133.

7812040321 Testimony of Newmerk re earthquake resistance design criteria utilized in constrof subj facils. "Rationale for Development of Design Spectra for Disblo Canyon Reactor Facil" & Cert of Svc encl.
NEWMARK, M. N. M. Newmark Consulting Engineering Services.
78/11/15, 73pp. 94128:001.

--7812040324 Testimony of CJ Stepp re subj facil seismic concerns addressed during construering the Oper Lic review. STEPP, J. C. Geosciences Branch. 78/11/15. 41pp. 94122:076.

--7812040327 "Diablo Canyon Testimony of J Knox & F Rosa re Beismic Or of Class IE Equip," discussion of saismic qual eval with criteria in Befsty Eval Rept 3.10 & suppls.
ROBA:F. Power Systems Brench. 78/11/15. 12pp. 94122:117.

--7B12040D3D "Testimony of RB Hofmann" re conservative value for groun acceleration from a 7.50 sertiquese on the Hospri fault. HOMANN, R. B. Office of Standards Development, Director. 7G/11/10 22pp. 94122:129

--78120403' for Un (1967meet HALL

--78120405 (defir struct KNIGHT 94122:

7812130006 Reque... TURNERIA. J. Aff.

- 7812110219 Asks whether seismic hearings will begin 781204 Believes facil should not be allowed to open for love of humanity in general.
 ROSENBERG, H. Affiliation Unknown 78/11/17. ip. 94337:353
- 7812180324 Forwards testimony on behalf of Intervenors re Contention 1. Geology & sets forth conclusions re through-poing continuity of the Sam Gregerio-Hosgri fault zone. Resume. Study results & Cert of Bvc encl GRAMAM.8. A. Affiliation Uninown. 78/11/17. 19pp. 94356:299.
- 7812180309 Petition for directed certification for review of "Reconsideration of Bd's Order of 780905" relating to quel of security expert Forwards Cert of Svc. VALENTINE, P.C. San Luis Obiepo Mothers for Peace. 78/11/20. 40pp. 94336:190.
- 7812040179 Applicant ODE has until 781205 & NRC Staff until 781211 to respond to intervenor's Patition for directed certification to review ASLS's rejection of DD Comey as an expert witness on security matters.

 DUFILIM E. Atomic Bafety and Licensing Appeal Panel. 78/11/21.

 2pp 94457-073
- 7B12080191 Memorandum act receipt of intervenor's Patition for Birected Certification. Applicant's response is due 7B1205: Staff's 7B1211. Bd will not favor requests to extend time.

 DUFLO, M E. Atomic Safety and Licensing Appeal Panel. 7B/11/21.

 2pp. 943B2 122.
- 7812130146 Forwards list of publications & rev qualifications sheet omitted from 780927 Steff's response to intervenor's interven. KETCHEN.E. Q. Office of the Esecutive Legal Director 78/11/21, 22pp. 94289:064.
- 7B120B0004 Order granting permission to make opening statements prior to limited appearances. Each statement limited to RO minutes. No change will be made from stated location. BOHERS.E. 8. Atomic Safety and Licensing Board Panel. 7B/ii/27. 2pp. 94103:314.
- 7812080024 Requests to make appearance statement at 781204 hearing in Ban Luis Obispo County.CA. RICE-L. Affilietion Unknown. 78/11/27. ip. 94104:002.
- 7812140346 Forwards list of publications of JF Devine & resume of FA McKesom. KETCHEN,E Q. Office of the Executive Legal Director. 78/11/27. 10pp. 03957:175
- 7812140085 Suppl reply of PGE to intervenors' interrogs of 780927. Forestds names & quals of 4 add1 witnesses PGE intends to call in the licensing hearing re subj facils. Cert of Svc encl.
 CRAME.P.A., NORTON.B., MORRISBEY, J. C. Pacific Gas & Electric Co. 78/11/28. 10pp. 94128:231.

ı

- 7812140344 Gives notice that E Ketchen enters an appearance on behalf of NRC in proc re subj facils. Cert of Svc encl. KETCHEN.E. G. Office of the Executive Legal Director. 78/11/28. 3pp. 03857:168.
- 7812140373 Confirms 781192 conversation re-status of 2 U808 witnesses apparing for NRC 8oth witnesses wrote U808 rept which is append 0 to 8uppl 4 of SER & will be at hearing to answer questions.

 TGURTELLOTTE, J. Hearings Division. 78/11/29. | 1p. 03558: 118.
- 7812180027 Forwards memo to subpoens to ACRS consultants entitled "Interpretive Comm Statement on Amenability to Subpoens of Consultants to ACRS under 100FRS, 720," SUMERSE, B. Atomic Bafety and Licensing Board Panel. 78/11/30. App. 94130:340.
- --7812180037 Forwards "Interpretive Comm Statement on Amenability to Bubpoens of Consultants to ACRB under IOCFR2.720," which now represents the Comm's views & which will be presented for formal vote at next Comm Affirmative Session. KELLEY.J.L. Office of the Executive Legal Director. 78/11/29, 19. 94130:341.
- 7812180416 NRC Staff's Response to Petition submitted by intervenor San Luis Obispo Mothers for Peace seeking review & reversal of ABLB's upholding of denial of D Comey's quals. NRC urges that intervenor's petition be denied. Cert of Svc encl. STAENBERG, M R. Office of the Executive Legal Director. 78/12/01. 5pp. 74336:358.

- 7812210521 "Buppl Reply of Jt Intervenors' to Applicant's It 780727." Cart of Bvc encl. HUBBARD.R. B. MHB Technical Associates. 78/12/01. 4pp.
- 7812270025 Urges approval of plant uper as soon as posetble; elec puris vitally needed. RUSBELLHLM, Affiliation Unknown. 78/12/05. ip. 94159:
- 7812140273 Forwards AmendWi to Constr Permit#CPPR-39 & Amend Constr Permit#CPPR-69 w/related correspondence. ODLOBERG.J.R. Office of the Executive Legal Director. 78 ip. 03357.289.
- -- 78:2:40278 Forwards Amend#1 to constr permit#CPPR-39 & Ameconstr permit#CPPR-59 & Fed Register Notice.
 BCVD.R.B. Division of Project Management. 78/12/06. 4
 0357:290
- --7Bi2(4027B Amenum) to Constr PermitMCPPR-39, adding antitrute Paragraph 2. D. BOYD. R. B. Division of Project Management. 78/12/06. 1 03537. 294.
- --TB12140279 Amend#4 to Conett Petmit#CPPR-69 adding antitru to Paregraph 2.D. BCPD-8.B. Division of Project Management. 78/12/06. 1 03997:304.
- --7812140283 Notice of lesuance of Amendéi to Constr Permité Amendé4 to PermitéCPPR-49. M/encl Eval of Amend by LWRéi. STDL7.J.F. Light Water Reactors Branch L. 78/12/06. 8 03387-344

H. Obharai correspondance

- 7811180130 Expresses concern dwar role of nur energy in UB of suggests more rea be directed towards solar energy. Deplores Liquid Metal Breeder Reactor & the idea of eiting plant on the James River near her home.
 NELBON.E.B. Affiliation Unknown. 78/10/23. 3pp. 94272:
- 7811210312 Act receipt of 780918 ltr & environ impact statem date & location of public hearing on subj facil & submits questions of concern re subj facil.
 MURRHYLE. Affiliation Unknown. 78/10/30. ip. 94488:098
- 7812180289 Forwards for Dept of Energy Response, a welld re ab G Burns into who inspects the structural steel of the subj factl. LAGUMARBINO,R. J House of Rep. 78/11/22. Spp. 94365:142
- 7812110040 Responds to 781030 ltr re seismic design; conservé w/regerd to elec losd projections & notice of hearing. BALLARO,R. L. Environmental Projects Branch I. 78/11/30, 94408:169.
- 7812270057 Strongly recommends putting subj ferti into oper possible since the energy is necessary. OEDRGE.J. Affiliation Unknown. 78/12/07. lp. 94160:291
- 7811210413 Balleves nuc pur cennot be mede sere & that const facil should be stopped. STANLR.F. Affiliation Unknown. 78/11/15. ip. 74485:12
- K. Utility Final Safety Analysis Report (FSAR) & amends
- 7811140126 Forwards copy of Amends 70 & 71 to open lic app1 facils. Amends incl add1 mat1 for Hosgri eval & FSAR. Cent of Bvc enci.
 CRANE, P. A. Pacific Gas & Electric Co. 78/11/09. 2pp.
- --7811140145 Amende 70 & 71 to Oper Lic appl for subj facils addl mat! for Hosgri Eval & FBAR. SHACKLEFORD.B. Pacific Gas & Electric Co. 78/11/09. 4
- D. Advisory Committee on Reactor Safeguards reports & corres
- 7812150050 Comments transmitted in 780922 ltf from ACRS cons Luco re seismic eval bases were discussed at 781102-04 ACR meeting. These comments were considered in the findings & recommendations in ACRS rept of 780714. LAMROSKI, 8. ACRS - Advisory Committee on Reactor Safeguar 78/11/07. ip. 94210:253.

3DN.D P. Light Water Reactors Branch i 78/10/24. 3pp. 3: 164

310384 Forwards comments by Dr Luco re seismic derign basis for ij facil. (CINLEY, J. C. ACRS — Advisory Committee on Reactor Bafeguerds '10/13. to 94388-167.

>10388 Comments on 780614 & 780707 acre meetings re use of lective peak acceleration & underestimation of subj facil sponse to offshore fault resulting from use of lerge luction for teu-effect & small torsion excitation.

10, J.E. California, Univ. of. San Diego. 78/09/22. Spp 188:168.

ection reports. IE Bulletine & correspondence

1316 Forwards IE Circular#78-17. (See ANO: 7810230221, Docket 3-781013) KEN.R H Region 5. San Francisco. Office of the Director 1/13 ip 94166:347.

263 Forwards IE Inspec Repts#50-275/78-14 & #50-323/78-14 on 1-30 during which he items of noncompliance were noted.

J.L. Region 5. Ban Francisco, Reactor Operations Nuclear of Branch. 78/10/17. 2pp. 94273:355

20267 IE Inspec Repts#50-275/78-14 & #50-323/78-14 on 780901-30 ing which no items of noncompliance were noted. Major as inspected included; preoper testing, fuel storage, lawup on licensee event & IE Bulletin-Circuler, testing. RNBERG.D. M. Region 5, San Francisco, Reactor Operations Nuclear port Branch. YOUNG.T., STERNBERG.D.H. Region 2, Atlanta, ctor Operations Nuclear Support Branch. 78/10/16. 5pp. 73:357

131 Responds to 701006 NRC itr re-violation noted in inspective actions: circuitry is bring placed in conformance R paragraph 3.3. & implementing instruc will be issued 1115.
-P.A. Pacific Que & Electric Co. 78/11/02. 2pp. 94043:348

DO7 Forwards 1E Circular 78-18. 4EN.R.H. Region 5. San Francisco, Défice of the Director 706. 1p. 94112-301.

JO1 Forwards IE inspec Reptemb0-279/78-17 & 50-323/78-16 on I-31 during which no items of moncompliance were noted. J.L. Region 5. Ban Francisco, Reactor Operations Nuclear of Branch. 78/11/16. 2pp. 94209:190.

50004 16 Inspec Repte#50-275/78-17 & 50-323/78-16 on 761001-31 ing which no items of noncompliance were noted Major see inapected incl:preoper testing, fire protec.plant tour.) has repts. 16 bulletin followup & design thanges. 4G-T. 8TERNBERO.D.M. Region 5. Ban Francisco. Reactor sations Nuclear Support Branch. 78/11/15. 4pp. 94209:192.

PO1 Forwards IE Inspec Rept#50-275/78-16 on 781030-31 & 1101 | which no items of noncompliance were noted. U.L. Region 5, San Francisco, Reactor Operations Nuclear to Branch. 78/11/17. 2pp. 94706:328.

IOG14 IE Inspec Rept#50-275/78-16 on 781030-31 k 1101 during which tems of noncompliance were noted. Hajor ereas inspected : Containment Integrated Leak Test.

KENBERRY, B. Region 5. San Francisco, Office of the Director.

TER.H.L., MILLER, L.P. Region 5. Ban Prancisco, Reactor ations Nuclear Support Branch. 78/11/15. 3pp. 94306:330.

98 Forwards 1E Bulletin978-12A-suppl to 1E Bulletin 78-12. ANO.7811300055. EN.R.H. Region 5. San Francisco. Office of the Director. 24. 1p.

33 Forwards IE Bulletin 78-14. EN.R.H. Region 3, Sen Francisco, Diffice of the Director. 19. ip. 06911:001.

table occurrences. LERs & related correspondence

86 Forwards add1 info to RO: defect in Unit 2 NEMA size#2 motor liers. Unit 1 inspec complete; inapec & replacement of ut springs for Unit 2 will be completed prior to onal test.

4670N, J. D. Pecific Gas & Electric Co. 78/12/07. 1p. 254.

- 7812070227 Transcript of PQ&E testimony on 781204 Testimony of RV Bettinger. PH Hamilton. RH Jehns & 8W Bmith encl.

 Atomic Befety and Licensing Board Panel. 78/11/20 239pp. 94188: 016.
- --7812070237 Testimony of PQEE on 781204.

 * Atomic Safety and Licensing Board Panel. 78/11/20. 200pp 74188.278.
- --7812070242 Testimony of POSE on 781204.

 Atomic Safety and Licensing Board Panel 78/11/20. 107pp. 94187-162.
- 7812130036 Transcripts of 781204 hearings re subj Facils.Pp 3758-3997. BDWERB.E., MARTIN.W.E., BRIGHT.Q.O. Atomic Safety and Licensing Board Panel. 78/12/04. 239pp. 94211:030.
- 7812130064 Transcript of 781205 hearing re-subj faciliLimited Appearance Statements In Avile Beach.CA.PP 3398-4249. BOMERS.E., MARTIN.W E. BRIGHT.G.O. Atomic Bafety and Licensing Board Panel. 78/12/05. 251pp. 94296:012
- 7812200344 Transcript of hearing in Avila Beach.CA on 781207.
 Appearances on behalf of applicant B Norton,MH Furbush, &
 P. Cranes on behalf of joint intervenors: 198 Fleishaker, S
 Kristovitch & for NRC E Wetchen Pp 4486-4679.
 BDUERS.E., MARTIN,W.E., BRIGHT, O D Atomic Safety and Licensing
 Board Panel 78/12/07 193pp 94124-188.
- 7812200338 Transcript of hearing in Avila Beach.CA on 781208 Appearance on behalf of Pacific Ges & Elec: B Norton,MH Furbush,P Crane. on behalf of joint intervenors: OS Fleischater.S Kristovich & for NRC: M Staenberg Pp. 4679-4652
 BOWERS,E., MARTIN,W. E., BRIGHT,G.O. Atomic Sefety and Licensing Board Panel. 78/12/08. 183pp. 94124: 003.
- 7812270346 Transcript of hearing re-subj facil at Avila Deach.CA on 781213.9p 5309-5806 BOWER8.£. Atomic Befety and Licensing Board Panel. 78/12/13. 197pp. 94229:024.
- 7812220014 Transcript of 781214 hearing in Avila Beach, CA re subjecti. Pp 5307-3706
 BOMERS-E., MARTIN.H.E., BRIGHT.G.O. Atomic Safety and Licensing Board Panel. 78/12/14. 199pp. 94248:024.
- 7812290002 Transcript of a 781218 hearing in Avila Beach CA re subj facil.Pp 6102-6359. BOMERS.E., MARTIN.W.E., BRIGHT.@ O. Atomic GaPaty and Licensing Board Panel. 78/12/18. 237pp. 94208:050
- 7812290279 Transcript of a morning 781214 hearing at Avile Beech, CA resubj facil. Pp 6360-6471.
 BOWERS, E., MARTIN, W.E., BRIGHT, Q.O. Atomic Safety and Licensing Board Penel 78/12/19. 1119p. 94192:001.
- 7812290280 Transcript of 781229 hearing on 781220 at Avila Beach.Ca. Pp6472-6688. BOWERSE, MARTIN.W.E., BRIGHT.G.O. Atomic Safety and Licensing Board Panel. 78/12/20. 216pp. 94193:001.
- 7812290282 Transcript of 781221 hearing in Avila Beach.CA re subj facil.Pp 6689-6862 BOMERS.E., MARTIN.H.E., BRIGHT.O.D. Atomic Sefety and Licensing Board Panel. 78/12/21. 173pp. 94194:001.
- 7812290283 Transcript of a morning 781222 hearing in Avila Seach CA resubj facil.Pp6863-6949.
 BOMERS.E., MARTIN.M.E., BRIGHT.Q.O. Atomic Safety and Licensing Board Panel, 78/12/22. 86pp. 94195:001.

U. Congressional/Executive Correspondence

7811080032 Responds to encl 780831 & 780925 congressional correspondence w/DDE requesting info to ensuer constituent's charges re not waste storage & location of subj fecil near geologic fault.

DIRCKS. W.J. Office of the Executive Director for Operations. 78/10/30. 10pp. 94398:089.

- Q. Inspection reports, IE Sulletine & correspondence
- 7812010175 Forwards 1E Inspec Repts#50-160/78-04.#50-276/78-02. #70-297/78-04 & #70-386/78-04 on 780926-27 during which no items of noncompliance were noted. KENNA, M. B. Region 2. Atlanta, Safeguards Branch. 78/10/20. 2pp. 94409: 221.
- --7812010182 IE Inspec Repts#50-160/78-04.#50-276/78-02.#50-297/78-04 & #70-0386/78-04 on 780926-27 during which no items of noncompliance were noted Major areas inepec incl nuc matl control & accounting procedures review.
 TODD-0. A. WILLIAMS.O.H. Region 2. Atlanta, Befoguards Branch.
 78/10/20. 3pp. 94409.223.
- 7812210281 Forwards IE Inspec Rept#50-276/78-03 on 781121 during which no Items of noncompliance were noted. KENNA, M.B. Region 2. Atlanta, Bafaguards Branch. 78/12/13. Spp. 94167: 298.
- --7812210287 IE Inspec Rept#50-276/78-03 on 781121 during which no items of noncompliance were noted. Areas inspected; physical security protec prog. Details of inspec w/held pursuent to MOORE, D.E. - GILLESPIE, F. P. Region 2, Atlanta, Safeguarda Branch. 76/12/13. 1p. 94167:300.
- DOCKET 50-277 PEACH BOITOM ATOMIC POWER STATION, UNIT 2 F. Becurity, medical, emergency & fire protection plans
- 7811290078 Forwards request for add1 info re fire protec at subj facil. Beveral NRC staff positions are encl re concern on this aub I. Operating Reactors Branch 3 (Pre 790625). 78/11/17. IPPOLITO T.A 46pp. 94192:209.
- 7812260192 Responds to 781117 request for eddi info re Fire Protec Prog. Remainder of questions will be addressed w/in 90 days. Bubj covered incl: cables above control room ceiling enclosed rooms win control room complex & seal qual prog.

 DALTROFF, S. L. Philadelphia Electric Co. 78/12/20. 33pp. 74159: 163.
- Q. Adjudicatory correspondence
- 7812130217 Memo & order re ALAB-509. Any party who disagrees w/ABLAB approach re radon emissions should file brise within 45 Atomic Safety and Licensing Appeal Panel. 78/19/01. DUFLO M E 11pp. 94306: 087.
- P. Operating license stage documents & correspondence
- 78:0300169 Forwards analysis of Gen Elec turbine trip transient tests performed during Apr 1977. ROSZTDCZY, Z.R. Analysis Branch, 77/11/02. 1p. 94034:114.
- --7810300174 "Safety Eval Rept on OE Transient Analysis Method in View of Peach Bottom Yests". Repts velidity of OE transient analysis methods k verifles plant transient behavior Four possible interim positions are presented. ROBZTOCZY, Z. R. Analysis Branch. 77/04/11. 16pp. 74034:115.
- 7812050004 Forwards Licenses Performance Eval Questions for subj facils in response to 77:123 request. Peels it is possible that dev of statistical methodology for such eval may not justify the affort Qualitative eval may be as good. Urges i-year teet. GRIER, B. H. Region i. Philadelphia, Office of the Director. 77/12/13. 12pp.
- 7812130198 Ack receipt of 760604.70930.761130, & 761203 submittals. Forwards request for addl info to be provided w/in 34 days for cost-benefit analysis. LEAR. Q. Operating Reactors Branch 3 (Pre 790625). 77/02/16. 3pp. 74306: 054.
- 7810230035 Notice of Issuance of Amends #44 & #44 to Facil Oper Lics #DPR-44 & DPR-56, Amends delete Environ Tech Specs Sections 6.1.5.6.1.c & 6.1.6.re special study prog related to impingement entrainment & thermal tolerance of organisms.

 LEAR. 9. Operating Reactors Branch 3 (Pre 790625). 78/07/86. 2pp. 94052: 319.

- Amends rev Tech Specs to mod rectar coolant Sys thermal & pressurization limitations.

 1PPD_170.T A. Operating Reactors Branch 3 (Pre 790ADS) issued Amends#45 & #46 to Facil Oper Lics#DPR-44 & DPR-56. Operating Reactors Branch 3 (Pre 790525). 78/08/04
- 200. 94392:234.
- 7811010390 Forwards Amends#46 & 46 to Fatil Oper Lit#DPR-44 & DPR-56 rev Tech Specs as requested in 780711 ltr w/Bafety Evaluation & Notice of Issuance. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790 Operating Reactors Branch 3 (Pre 790625). 78/10/03

2pp. 94388:281

2pp. 94169:200.

- ~~7811010393 Amend#46 to Facil Open Lic#DPR-44 rev Tech Specs re. surveillance of suppression pool temp logging, controlled bypass heatup line on HPCI steam supply & identification of valves to reflect plant unique designation. 1PPOLITO.T. A Op 9pp. 94388:283. Operating Reactors Branch 3 (Pre 790625). 78/10/03
- --7811010400 Amend#46 to Facil Open LiceDPR-56 rev Tech Specs re: surveillance of suppression pool temp logging, controlled bypass heatup line on HPCI steam supply & identification of values to reflect plant unique designation.

 1PPDL1TD, T. A. Operating Reactors Branch 3 (Pre 790625). 78/10/02. Spp.
- --7811010405 Safety Eval Rept supporting Amends#46 & 46 to Facil Oper Lic#DPR-44 & DPR-56 concluding that proposed mode & assoc Tech Spec changes have no eafety or environ significance & are therefore acceptable. * Operating Reactors Branch 3 (Pre 790625), 78/10/03. 3pp. DANGED DA. 94388: 301
- --7810130232 Notice of Issuance of Amend#46 & 46 to Facil Open Lic#DPR-44 & DPR-36 on 781003.
 IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/03
 2pp. 94081: 340.
- 7BiOli0105 Responds to 780807 itr requesting evaluation of sub; facil Protec Sys pur supply to determine whether there is potential for undetected single failures to adversely effect Reactor Protec Sys.

 DALTROFF, S. L. Philadelphia Electric Co. 78/10/05. 2pp. 94066:391
- 7810230011 Forwards Amend#47 to LiceDPR-44 % #47 to LiceDPR-36 for subj facil, changing Tech Spec in response to 780526 & 780905 ltrs. Operating Reactors Branch 3 (Pre 790625). 78/10/10. IPPOLITO T. A.
- --7810230016 Amend#47 to Fecil Open Lic#DPR-44, changing Tech Spec re instrumentation that initiates or controls core & containment cooling systadmin controls & safety-related snubbers Operating Reactors Branch 3 (Prs 790625). 78/10/10. IPPOLITO, T. A. 21pp. 94169: 210.
- --7810230019 Amend#47 to Facil Oper Lic#DPR-56, changing Tech Spec re fire protec & admin controls.

 1POLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/10.

 24pp. 94169:231.
- --7810230024 Bafety Evaluation Supporting Amend#47 to Fecil Lic#DPR-44 & Amend 47 to Lic#DPR-56. Concludes that amend will not decrease safety margin. Operating Reactors Branch 3 (Pre 790625). 78/10/10. 8pp. 94169: 255.
- --7810230028 Notice of Issuance of Amend#47 to Facil Oper LiceOPR-44 & Amend #47 to DPR # 56 rev Tech Spec re containment cooling sys controls admin controls & snubbers. IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/10. 2pp. 94169: 263. Operating Reactors Branch 3 (Pre 790625). 78/10/10.
- 7811040124 Forwards Amend#48 to Facil Oper LiceDPR-44 revising Tech Specs as requested in 781004 ltr w/Bafety Evaluation & Notice of Issuence. IPPGLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/16. 2pp. 94424:146.
- --7811060125 Amend#48 to Facil Oper Lic#DPR-44 revising Tech Spec re oper of subj facil w/new type reload fuel(8x8R)for cycle 4. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/16. 36pp. 94424:148.
- --78110601R8 Safety evaluation supporting Amend %48 to Facil Oper Lic&DPR-44 concluding that design of SizER fuel, thermal-hydraulic stability of subj facil & proposed oper limit are acceptable & safety of pub will not be endangered. a Office of Nuclear Reactor Regulation, Director. 78/10/16. 10pp. 94424:184.

DOCKETED ITEMS

- 16.0130 Notice of Issuance of Amend#48 to Facil Oper Lic#DPR-44 on iO 16.

 **ONLITO.T.A Operating Reactors Branch 3 (Pre 790625). 78/10/16.

 **P. 94424:194.
- 1272 Provides results of test on facility at end of cycle 2 tions using proposed licensing basis ODYN Model.
 K. W. General Electric Co. 78/10/17. 20pp. 94203:174.
- i O274 Transmits calculational results & data related to staff's 'i qu of ODYN transient model. Info incl calculations formed to quanify effects of stuck rod on scram c tivity & series of figures as delta K versus X voids. 床。k.w. General Electric Co. 78/10/17. 27pp. 94203:195.
- 10277 Forwards results of studies carried out in effort to Prmine reason behind apparent discrepancy between BNL & Wold reactivity feedback models.

 **Kok.M. General Electric Co. 78/10/17. 7pp. 94203:222.
- 1 OB Response to 780927 NRC ltr re benchmarking Enc's PTSBWR/2 against present data & verifying transient & stability.

 Data to be supplied in Dat 1979 will settisfy requests twin GE proprietary info must be provided.

 Y+Q.F. Exxon Nuclear Co., Inc. (subs. of Exxon Corp.).

 / 19. 2pp. 94059:300.
- 186 Forwards "Postoperational Rept#10 on the Ecology of 1 ngo Pond for the Period of 7801-7805" EV-M. 8. Philadelphia Electric Co. 78/10/24. 1p. 94054:073.
- 70188 "Postoperational Reptw10 on the Ecology of Conowingo Pond Period Jan-June 1978". Philadelphia Electric Co. 78/10/31. 161pp. 94054:074.
- GGS Surmary of 780914 meeting w/GE representatives & Mark 1 & Group re progress of Long Term Prog w/attendance & agenda (RD-9-A-Mark1, Standards.)

 8. C. Plant Systems Branch (Pre 791030). 78/10/26. 67pp.
- 288 Responds to 781106 request for info concerning licensee reg remance eval for Region 1 plants by NRC. Provides 1 to . 18. H. Region 1, Philadelphia, Office of the Director. 709. 9pp. 94239:230.
- 130 Notice of workshops re implementation of training & qual rements contained in Append B of 10CFR73. Requests 3rkshop registration of attendess to facilitate sending sti.Wencl Registration Form & List of Locations. 3. J. R. Assistant Director for Bite & Bafeguards (Pre 791030). 415. 3pp.
- 268 Forwards Rev#i "Draft Radiological Effluent Tech Specs" for (NAUREO-0473) & "Preparation of Radiological Effluent Specs for Nuc Pur Plants" (NOREO-0133).
 3. B.K. Assistant Director for Engineers & Projects (Pre 53. 76/11/15. 6pp. 94364:324.
-)&& Responds to 781116 telecon. Forwards copies of ANB meeting s which demonstrate attention to ALARA per RQB. 9. s. J. C. Ebasco Services, Inc. (subs. of Enserch Corp.). $^{\prime}$ 17. 1p.
- .0070 "Experience in Decontamination & Repair of Radwasta: matrator at Millatone Unit#1." Describes procedures. 14. J. Northeast Nuclear Energy Co. (subs. of Northeast .1 ties). 78/11/17. 19pp.
- .0074 "Peach Sottom 2 & 3.Regenerative Heat Exchangers Cham :eminetion & Seel Ring Repairs." Describes work performed 977 & 1978. MER.H.M. Philadelphia Electric Co. 78/06/06. 22pp.
- OC77 "Peach Bottom 2 & 3 Regenerative Heat Exchangers Chem ntamination & Bolidiffication." Describes work performed 977.
 [Y. 9 E. Dow Chemical Co. 78/02/16. 38pp.
- IBS Informs PECO that NRC has contracted w/Mountain Hest Res Inc. dantake a series of post-licensing studies of nuc pur res. Studies will analyze socioecon impacts which ed during constr & post-constr periods of each plant.

 G. R. C. Division of Site Safety & Environmental Analysis.

- 7812070205 Notice of seminar on 781208 on new Model Radiological Effluent Tech Space for nuc pur plants. Requests advance submission of seminar spacific quastions. W/encl Seminar Info Sheet. Proposed Agenda & maps ORIER. B. H. Region 1. Philadelphia. Office of the Director. 78/11/21. 8pp. 79375:152.
- 7812180104 Forwards Amends#49 & #48 to Licenses DPR-44 & DPR-55, respectively. Tech 8pecs by increasing total storage capacity of spent fuel pools from 2220 to 5632 fuel assemblies. Forwards BER, EIA & notice of issuance IPPCLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/30. 2pp. 94130:233.
- --7812180103 AmendsW49 & W48 to Lic DPR-44 & DPR-55, respectively, espension of spent fuel pool storage capacity & related Tech Spece. Forwards supporting SER & EIA. GRIMES, B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/30 12pp. 94130:255.
- --7812180107 Safety Evel supporting Amends#49 & 48 to Lice DPR-44 & DPR-56-respectively.

 Assistant Director for Engineers & Projects (Pre 790625).
 78/16/20. 11pp. 94130:267.
- --7812180112 Notice of Issuance of Amende#49 & #48 to Facils Operating Lic #DPR-44 & DPR-56.respectively, & Negative Declaration. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/30. 3pp. 94130:300.
- --7812180108 EIA supporting Amends#49 & #48 to Lice #DPR-44 & DPR-56-respectively.

 # Assistant Director for Engineers & Projects (Pre 790625).
 78/11/30. 22pp. 94130:278
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held & providing tesk-by-task activity summary for the month. BUBDN:L.J. General Electric Co. 78/12/04. 11pp.
- 7812280033 Emphasizes importance of submniting accurate & complete info to NRC by licenses & applicants. Info submitted must be substantiated by date & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS, J. G. Office of inspection & Enforcement, Office of the Director. 78/12/06 2pp. 94133:214.
- 7612050013 Requests views of Regional Directors on Licenses performance eval of subj facils Forwards questions to be answered by 771209.

 THORNBURG, H. Division of Reactor Construction Inspection. 77/11/23 2pp.
- 78i1210367 Forwards add1 info re multiple consecutive safety/relief valve actuation of Mark I containment program SOBON, L. J. General Electric Co. 78/i1/13. 3pp.
- Q. Inspection reports: IE Bulletins & correspondence
- 7811090053 Forwards IE Inspec Rept#50-277/78-23 & #50-278/78-28 on 780823 during which no items of noncompliance were noted. BRUNNER, E. J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/21. 2pp. 94040:099.
- ~-7811090058 IE Inspec Rept#50-277/78-23 & #50-278/78-28 on 780823 durin which no items of noncompliance were noted Hajor areas inspected included review of Licenses's response to IE Circular 78-8 dtd 780531.

 OREENMAN.E.Q., MCCABE.E.C. Region 1, Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/18. 6pp. 94040:101.
- 7810160238 Forwards IE Bulletin#78-12: "Atypical Weld Meterial in Reactor Pressure Vessel Welds" requesting action w/in 60 days. & list of IE Bulletins Issued in 1978. (see AND#7810040253)
 GRIER, B.H. Region 1. Philadelphia, Office of the Director. 78/09/29. 49p. 94006:353.
- 2011010006 Act account of 201000 the informing NPC of Stens taken to

- REVIOUS IS PULLABORIONIAS DAPENDUATUS DIANCES. 2pp. 94381; 300
- --7811010093 Notice of Violation from inspec on 780814-16. * Region 1, Philadelphia, Office of the Director, 78/09/14. 1p. 94381:302
- --7811010099 IE Inspec Repts#30-277/78-21 t#50-278/78-26 on 780914-16 during which I item of noncompliance was noted: Amount of radioactive decay of Pu-241 during periods ending 770331. 770930 & 780331 not reported on Form-742-Paragraph 7.
 BIBBETT, P. H. Region 1, Philadelphie, Dffice of the Director.
 BHAUB.E. T., JOYNER, J. H. Region 1, Philadelphia, Bafeguerde B
 78/09/14 10pp. 94381:303. Region 1. Philadelphia, Safeguarde Branch.
- 78:0200094 Second Inspec prog was conducted during recent subj facil refueling outage. All 25 channels were classified acceptable for reuse in any reactor core location during subsequent oper cycles. COONEY, M. J. Philadelphia Electric Co. 78/10/13. 1p. 94401:220.
- 7811060203 Forwards IE Circular#78-17. (8se AND: 7810230221, Docket #50-133, 7B 1013.) ORIER, 8. H. Region 1, Philadelphia, Office of the Director. 79/10/13. ip. 94489: 203.
- 78:20:0345 Forwards licensee performance evaluation for Region 1.No operating reactor in Region 1 considered to have either abnormal or unusual safety concern. QRIER.B.H. Region I, Philadelphia, Office of the Director. 75/11/01. App. 00002:259.
- 7811290160 Forwards IE Circular #79-18, "UL Fire Test, "W/encl AND: 7811150002. ORIEN, 8. H. Region 1, Philadelphia, Office of the Director. 78/11/06. 1p. 94238:052.
- 7812010008 Ack receipt of 781103 ltr informing NRC of steps taken to correct violations noted during Inspeces0-277/78-26.

 BRUNNER,E. J. Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch. 78/11/15. 1p. 94409:114.
- --7812010012 Responds to 781020 NRC itr re violations noted in Inspec Rept#50-277/78-26. Corrective actions: procedure req constant monitoring of fuel element is being rev to allow oper to observe all aspects. DALTROFF, S.L. Philadelphia Electric Co. 78/11/03. Spp. 94409: 115.
- --7812010016 Forwards IE Inspec Rept#50-277/78-26 on 780919-22 & Notice of Violation. BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/10/20, 2pp. 94409:118.
- --7812010025 Notice of Violation from inspec on 780919-22. # Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/20, 1p. 74409:120.
- --7812010031 IE Inspec Rept#50-277/78-26 on 780919-22 during which 2 items of noncompliance were noted; failure to complete procedure prerequisites prior to performing procedure & failure to observe fuel bundle during movement. KALMAN. G., OREENMAN. E., CAPHTON. D. L. Region 1, Philadelphia, Office of the Director. 78/10/02. 7pp. 94409:121.
- 7811300217 Forwards rev Insvc Inspec Prog in response to 780910 NRC ltr. Table 5.4-1 of ISI prog has been rev to require leak rate testing of valves needed to perform pressure isolation function. List of alternate valves is in Att A.

 DALTROFF, S.L. Philadelphia Electric Co. 78/11/22, 3pp. 94070:001.
- --7811300220 Insvc Inspec Prog for subj facil. Rev prog is IAM 1974 ed of Bection XI of ABME Code & upgrades prog for subj facil. New prog establishes rev requirements for Class 1.2 & 3 components of boiling water reactors. # Philadelphia Electric Ca. 78/11/30. 65pp. 94070:004.
- 781218022: Responds to 780929 NRC ltr forwarding IE Bulletin 78-12 to requests add info re reactor vessel weld math a reactor vessel february which which will be forwarded to NRC at a later date.

 DALTROFF, B. L. Philadelphia Electric Co. 78/11/22, upp. 94058:335.

COONEY, M. J. Philadelphia Electric Co. 78/10/15. ip. 94169:293

• -

UDER HED!

mmrnin

- --7810230167 Monthly Oper Rept for Bept 1978.
 ALDEN.W.M. Philadelphia Electric Co. 78/10/15. 9pp. 94169:294.
- 78i1140142 Forwards Monthly Open Rept for Oct 1978.
 COUNEY, M. J. Philadelphia Electric Co. 78/11/09, ip. 94383:240.
- --7811140144 Monthly Oper Rept for Oct 1978.
 ALDEN, M. Philadelphia Electric Co. 78/11/15. 9pp. 94383:241.
- 78111600B4 Forwards Monthly Open Rept for Oct 1978. CODNEY, M. J. Philadelphia Electric Co. 78/11/09. 1p. 94134:273.
- --7811160086 Monthly Oper Rept for Oct 1978.
 ALDEN, H. M. Philadelphia Electric Co. 78/11/15, 9pp. 94134:274.
- 7811170130 Forwards Thermal & Biological Monitoring Rept#60.covering period 780601 thru 780630.for subj facil. WILLBEY, W. B. Philadelphia Electric Co. 78/11/09. 1p. 94469:034.
- -- 7811170131 Thermal & Bilogical Monitoring Rept#60, covering period 760501 thru 780630.for subj facils.
 * Philadelphia Electric Co. 78/11/09. 37pp. 94469:035.
- 7812080109 Forwards Thermal Monitoring Repts #61 & #62.
 WillSEY,W. B. Philadelphia Electric Co. 78/12/05. ip. 94246:238.
- --7812080111 "Thermal & Biological Monitoring Prog for Unit #2 &3." & Monthly Rept #61 for Jul 1978, Presents daily summary of air temp data: daily generation at PBAPB in thermal megawatts hourly Conowingo Pond temps & impact hours above July limit.

 Philadelphia Electric Co. 78/07/31. 12pp. 94248:239.
- --7812080112 "Thermal & Biological Monitoring Prog for Unit 2 & 3."
 Monthly Rept #62 for August 1978 Presents daily generation
 at PBAPS hourly Conowingo Fond & impact hours above August
 confidence limits. * Philadelphia Electric Co. 78/08/31. 18pp. 94846:850.
- 781R180134 Forwards Sept Thermal Monitoring Rept#63.
 WILLSEY, M. B. Philadelphia Electric Co. 78/12/12. ip. 94366:008.
- --7812180157 "Thermal & Biological Monitoring Prog#63 for Sept 1978." Oper w/in applicable thermal criteria w/monthly mean delta tamp 1.41F higher than mean of preoper experience.

 * Philadelphia Electric Co. 78/09/30. 11pp. 94366:009.
- 7812220043 Forwards Monthly Oper Rept for Nov 1978. CDDNEY,M.J. Philadelphia Electric Co. 78/12/14. 1p. 94248:300.
- --7812220064 Monthly Oper Rept for Nov 1978. ALDEN,W. M. Philadelphia Electric Co. 78/12/12. 9pp. 94248:302.
- S. Reportable occurrences, LERs & related correspondence
- 7810100082 LER#78-037/03L-0 on 780901: while testing ADS subsys, timers on both loops were found outside the 115-126 second limit of tech specs due to setpoint drift of time delay relays. Timera were calibrated, reteated & returned to svc. COONEY, M. J. Philadelphia Electric Co. 78/09/26. 1p. 94032:191.
- 7810100101 LERWYB-036/03L-0 on 780901: failure of auxiliary mil pump to start due to a ground in motor Motor Baidor Tupe 10400, 7 1/2 H.P., 250V.D.C. was replaced & HPCI was tested satisfectorily w/in 36 hours ADB timers not w/in Tech Bpecs. COONEY.H.J. Philadelphia Electric Co. 78/09/26. ip. 9403 94033: 155.
- 7810100038 LERM78-035/031-0 on 780830:E-3 dissel start time to reach rated voltage & frequency did not meet surveillance test requirement, probably caused by leaking check valve in the hydraulic sus assoc withe air bootter relay.

 CDONEY.M.J. Philadelphia Electric Co. 78/09/29. 1p.
- 7810130185 Forwards LERW78-039/03L-0. CDONEY,M.J. Philadelphia Electric Co. 78/10/04. 3pp. 94009:356.

"I 30163 LERW78-039/03L-0 on 780904; backflow of radioactive liquid om radwaste demineralizers to evo air sys discovered on 0904 & 780921; Caused by leaking process valves & sociated check vlaves due to dirt deposite

ONEY, H. J. Philadelphia Electric Co. 78/10/04. 1p. 94002:359.

OO94 Rept Occurrence#2-78-41/1P: on 781010 during routine e 11ance text of Unit 2 4kV undervoltage relays setpoint us sequence loading relays E-32 t E-42 were out of broduc to engr error.
ICH,N.T. Philadelphia Electric Co. 78/10/11 2pp. 94399 079.

OSSA LERBYB-040/ORL-0 on 780918: While testing stroking control endted that when control rod was selected previously cited rod did not deselect. Caused by defective relay however subsequently replaced.

EV.M.J. Philadelphia Electric Co. 78/10/17. 1p.

O137 Forwards LER878-041/01T-0 EY-M.J. Philadelphia Electric Co. 78/10/24. 2pp. 94042:316.

OPO141 LERB78-041/01T-0 on 781010:2 4KV emergency bus sequential adding releys found outside Tech Spec limits. Caused by ror in determining setgoint & calibr span of relays. Relays calib & testing procedures revised.

3NEY, M. J. Philadelphia Electric Co. 78/10/24. ip. 94042; 318.

0146 Forwards LER#78-020/017-0.
EY.M.J. Philadelphia Electric Co. 78/11/01. 2pp. 94043:001.

OPO152 LERM78-020/017-0 on 781019: unit 3 combainment oxygen nc entration had increased to 0.1% above 4 percent limit of ch Spsc 3.7.A.5. Caused by open air back-up valves in operable instru nitrogen compressor.
DNNEY.M.J. Philadelphia Electric Co. 78/11/01. ip. 94043:014.

OOPS LERB78-042/O3L-0 on 781019: during start-up, inboard main m. line drain isolation valve MO-2-74 would not close in ones to hand switth in control room, due to defective torque switch on the valve.

EY, M.J. Philadelphia Electric Co. 78/11/08. Ip. 94334:361.

D225 LER#78-044/03L-0 on 7810R1: during startup, excessive open of gland seal condensate pump was noted. Check valve—8.31 was leaking which let condensate return to gland—condenser. Valves were blocked to facilitate repair.
EV.M.J. Philadelphia Electric Co. 78/11/20. 1p. 94474: 239.

D210 Forwards revised util 781024 ltr containing LER 78-041/17-0. attative description, "Reted pur" was inapproprietally tituted for "reted voltage" in 2 instances. Revision rate & consistent w/Tech Specs.
EY-M.U. Philadelphia Electric Co. 78/11/29. lp. 03555:117.

OFFICE OF PROPERTY OF THE PROP

D173 LERW78-045/03L-0 on 781031: axygen analyzer sys isolation b BV-25710 was inoperable due to operating plunger king k dirty seating surface. Plunger k valve replaced at any surface cleaned.
EV: M. J. Philadalphia Electric Co. 78/11/30. 1p.

D162 LER#78-047/03L-0 on 781102:during third refueling outage, and to remove neutron flux samples from reactor vessel.

ed by administrative oversight. Eval of sample removal
is in progress.

EV.M.J. Philadelphia Electric Co. 78/12/04. ip. 94305:121.

01:30 LER#78-046/03L-0 on 781117; output demand signal from RCIC Controller (Inst#HC8213-115) read down scale, Caused by circuit in controller demand current loop.
EV.M.J. Philadelphia Electric Co. 78/12/06. 1p. 94307; 213.

50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3 prity, medical, margency & fire protection plane

3078 Forwards request for add1 info re fire protec at sub; facil. •m1 NRC staff positions are encl re concern on this

ETD.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/17. 94192:209.

7812260192 Responds to 781117 request for add1 info ra Fire Protec Prog. Remainder of questions will be addressed win 90 days. Subj covered incl: cables above control room citing, enclosed rooms w/in control room complex & seal quel prog. DALTROFF, S. L. Philadelphia Electric Co. 78/12/20. 33pp.

Q. Adjudicatory correspondence

7812130217 Mema & order to ALAB-509. Any party who disagrees w/ABLAB approach to radon emissions should file brief within 45 days.

DUFLOFM. E. Atomic Bafety and Licensing Appeal Panel. 78/12/01.

DUPLOFM.E. Atomic Bafety and Licensing Appeal Panel. 78718701.

P. Operating license stage documents & correspondence

7812110052 Discusses possible dangers of LOCA in containment purging during normal plant oper.Requests either commitment to limit purging or justification for continuing.W/smc1 ANO: e7812080207.

1PPOLITO T. Operating Reactors Branch 3 (Pre 790625), 78/11/29. Bpp. 94408:227.

7812180104 Forwards Amenda#49 & #48 to Licenses DPR-44 & DPR-55, respectively. Tech Bace by increasing total storage capecity of spent fuel pages from 2220 to 5502 fuel assemblies. Forwards BER, EIA & notice of issuence. IPPOLITO.T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/30. 2pp. 94130:233.

--7812180107 Befety Evel supporting Amende#49 & 48 to Lice DPR-44 & DPR-56.respectively.

* Assistant Director for Engineers & Projects (Pre 790625).
78/11/30. https://dx.doi.org/10.267.

--7812180108 EIA supporting Amends#49 & #48 to Lics #DPR-44 & DPR-56, respectively.

Assistant Director for Engineers & Projects (Pre 790625). 78/11/30, 22pp. 94130: 278.

7812080004 Forwards Licensee Parformance Eval Questions for sub; facils in response to 771123 request Feels it is possible that day of statistical methodology for such eval may not justify the effort Qualitative eval may be as good Urges 1-year test. ORIER. B. M. Region I. Philadelphia. Office of the Director. 77/12/13. 12pp.

7812130198 Ack receipt of 760604,70930.761130, & 761203 submittels. Forwards request for addl info to be provided w/in 34 days for cost-benefit analysis. LEAR.9. Operating Reactors Branch 3 (Pre 790685). 77/02/16. 3pp. 94306:054.

7810230035 Notice of Issuance of Amends #44 & #44 to Facil Oper Lics #0PR-44 & DPR-56. Amends delete Environ Tech Spece Bactions 6.1.b.6.1.c & 6.1.d.re special study prog related to impingement, entrainment & thermal tolerance of organisms LEAR.9. Operating Reactors Branch 3 (Pre 790625). 78/07/26. 2pp. 94078:319.

7810250191 Notice of Issuance of Amends to Facil Oper Lics.NRC has issued Amends #45 & #46 to Facil Oper Lics#DPR-44 & DPR-96. Amends rev Tech Byees to mod reactor coolant Bys thermal & pressurization limitations.

1PPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/08/04. 2pp. 74392:234

7811010390 Forwards Amends#46 & 46 to Facil Oper LicHDPR-44 & DPR-56 ray Tech Bjecs as requested in 780711 ltr w/8afety Evaluation & Notice of Issuence. IPPCLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/10/03.

IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/03. 2pp. 94388:281.

--78:1010393 Amend#46 to Facil Oper Lic#DPR-44 rev Tech Specs re: surveillance of suppression pool temp logging.controlled bypess heatup line on HPCI steem supply & identification of valves to reflect plant unique designation. SPPOLITG.T.A. Deprating Reactors Branch 3 (Pre 790625). 78/10/03. 79p. 94388:283.

--78:1010400 Amend#46 to Facil Oper Lic#DPR-56 rev Tech Specs re: surveillance of suppression pool temp logging.controlled bypaes heatup line on HPCI steem supply & identification of valves to reflect plant unique designation. IPPOLITO.T.A. Operating Reacture Branch 3 (Pre 790623). 78/10/03. 9ao.

- --7811010403 Safety Eval Rept supporting Amends#46 & 46 to Fecil Oper Lic#DPR-46 & DPR-56 concluding that proposed mode & assoc Toch Spec changes have no safety or environ significance & are therefore acceptable * Operating Reactors Branch 3 (Pre 790625). 78/10/03 3pp 94308 301.
- --7810130232 Notice of Issuance of Amend#46 & 46 to Facil Oper Lic#DPR-44 t DPR-36 on 781003.

 IPPOLITO,I A Operating Reactors Branch 3 (Pre 790623) 78/10/03

 2pp. 94001.340.
- 78:01:01:05 Responds to 78:08:07 ltr requesting evaluation of subj facil Protec Sys pur supply to determine whether there is potential for undetected single failures to adversely affect Reactor Protec Sys DALTROFF, St., Philadelphia Electric Co. 78:10:705. 2pp. 94064: 351.
- 7010200011 Forwards Amend#47 to LicMDPR-44 & #47 to LicMDPR-56 for subj fecil.changing Tech Spec in response to 780526 & 780905 ltrs.

 IPPOLITO: T A Operating Reactors Branch 3 (Pre 790625). 78/10/10 2pp. 94169:208
- --7810230019 AmendW47 to Fac)1 Oper LicMDPR-36, changing Tech Spec refire protec & admin controls IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625) 78/10/10. 24pp 94169-231
- --7810230024 Safety Evaluation Supporting Amend#47 to Fac() Lic#0PR-44 & Amend #47 to Lic#0PR-56 Concludes that amend will not decrease safety wargin.

 # Operating Reactors Branch 3 (Pre 790525) 78/10/10. Bpp 94169: 255
- ~~7810230028 Notice of Issuance of Amend#47 to Facil Oper Lic#DPR-44 & Amend #47 to DPR # 54, rev Tech Spac re containment cooling sys controls.admin controls & snubbers.

 IPPOLITO,T. A. Operating Reactors Branch 3 (Pre 750625) 78/10/10.

 Zpp. 94169:263.
- 7810270108 Response to 780927 NRC itr re benchmarking Enc's PTBBWR/2 code against present data & verifying transient & stability tests. Data to be supplied in Oct 1979 uitl satisfy requests & certain GE proprietery info must be provided. OWSLEY.0. F Exon Nuclear Co. Inc. (subs. of Exxon Corp.). 78/10/19. 2pg. 94039-300.
- 7810270186 Forwards "Postoperational Reptwi0 on the Ecology of Conowingo Pond for the Period of 7801-7806". WILLSEY,W. B. Philadelphia Electric Co. 78/10/24. Ip. 94054-073
- --781027018B "Postoparational Rept#10 on the Ecology of Conceinge Pend for Period Jen-June 1978".

 Philadelphia Electric Co. 78/10/31. 1619p. 94034:074.
- 7811100335 Burmary of 780914 mesting w/05 representatives & Mark 1 Duners Group re progress of Long Term Prog w/attendance list & agenda(RD-9-A-Marki, Standards) GRIFEB.C. Plant Systems Branch (Pre 791030). 78/10/26 67pp.
- 7811290288 Responds to 781106 request for info concerning licenses reg performance eval for Region I plants by NRC Provides details. GRIBR.B.H. Region i. Philadelphia. Office of the Director 78/11/09. 9pp. 94239:230.
- 7812130130 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out math. Whenci Registration Form & List of Locations. MILLER. J. R. Assistant Director for Site & Safeguards (Pre 791030). 78/11/15. 5pp.
- 7812180268 Forwards Rev#1 "Oraft Radiological Effluent Tech Brecs" for BuR's(NUREG-0473) & "Preparation of Radiological Effluent Tech Spece for Nuc Pur Plants" (NUREQ-0133). GRIMES, B. K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94364:324.
- 7812210066 Responds to 781116 telecon Forwards copies of ANS mueting papers which demonstrate attention to ALARA per RGB. B. D'HARA, J. C. Ebasco Services, Inc. (subs. of Enserch Corp.). 78/11/17. ip.
- --7812210070 "Experience in Decontamination & Repair of Radwaste Concentrator at Hillstons Unit#1." Describes procedures. SUMMA.J. Northeast Nuclear Energy Co. (subs. of Northeast Utilities) 78/11/17. 19pp.

- --7812210074 "Peach Bottom 2 & 3 Regenerative Heat Eichangers Chem Contamination & Spal Ring Repairs " Describes work performed in 1977 & 1978 ROINCR.M M Philadelphia Electric Co 78/06/06. 22pp.
- --78;2210077 "Peach Bottom 2 & 3 Regenerative Heat Exchangers Chem Becontamination & Solidification " Describes work performed in 1977 CASEY, O. E. Dow Chemical Co 78/02/14 38pp
- 7811300383 Informs PECO that NRC has contracted u/Mountain West Res Inc to undertake a series of post-licensing studies of nuc pur stations Studies will analyse succioecon impacts which occurred during constr & post-constr periods of each plant. DEVOUND: R. C. Division of Sito Bafoty & Environmental Analysis 78/11/20 2pp 94136-264.
- 7812070205 Notice of seminer on 781208 on new Model Radiological Effluent Tech Specs for nuc pur plants Requests advance submission of seminar specific questions Wencl Beminar Info Sheet-Proposed Agenda & maps GRIER-8 H. Region 1. Philadelphia. Office of the Director. 78/11/21. Dpp. 94375-152.
- 7812180105 Amends#49 & #48 to Lic DPR-44 & DPR-56, respectively, expansion of spent fuel pool storage capacity & related Tech Specs. Forwards supporting SER & EIA GRIMES B. K. Assistant Director for Engineers & Projects (Pre 790425). 78/11/30. 12pp 94130:255
- --7812180112 Notice of Issuance of Amends#49 & #48 to Facila Operating Lic WDPR-44 & DPR-36.respectively, & Negative Declaration. IPPDLITD.T A. Operating Reactors Branch 3 (Pre 790625) 78/11/30 3pp. 94130-300
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held & providing task-by-task activity summary for the month. 8080N.b. J Operal Electric Co. 78/12/04 lipp.
- 7812280035 Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccurates or enforcement action will result. DAVIG.J Q. Office of Inspection & Enforcement. Office of the Director. 78/12/06 2pp. 94133:214.
- 7812030013 Requests views of Regional Directors on Licenses performance eval of subj facile. Forwards questions to be answered by 771209.
 THORNGURG. H. Division of Reactor Construction Inspection. 77/11/23
- 7812180160 Forwards Appl for Amend of Facil Operating Lic in order to temporerily modify subj Facil Tech Specs relating to the Reactor Core Isolation Cooling Sys. Forwards \$4,000 appl

Filing Fee BRADLEY, E. J. Philadelphia Electric Co. 78/12/14. Bpp. 94356.021

- 7811210367 Forwards add1 info re multiple consecutive safety/relief velve actuation of Mark 1 containment program SOBCN, L. J. General Electric Co. 78/11/13. 3pp.
- G. Inspection reports, IE Bulletins & correspondence

20p.

- 7811090053 Forwards IE Inspec Rept#50-277/78-23 & #50-278/78-28 on 780623 during which no items of noncompliance were noted. SRUNNER: J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/21. 2pp. 94040:099.
- --7811090058 IE Inspec Rept#50-277/78-23 & #50-278/78-28 on 780823 during which no items of noncompliance were noted Major areas inspected included review of Licensee's response to IE Circular 78-8 dtd 780531.

 QREPMAN, E. Q., MCCABE, E. C. Region 1, Philadelphie, Reactor Operations Nuclear Support Branch. 78/09/18. App. 94040:101.
- 7810160238 Forwards IE BullstinW7B-12: "Atypical Weld Material in Reactor Pressure Vessel Welds" requesting action w/in 60 days. & list of 1E Bullstine issued in 1978. (see ANOW7810040253) ORIER, 8.H. Region 1, Philadelphia. Office of the Director. 78/09/29. 6pp. 94006:353.
- 7811010085 Ack receipt of 781002 ltr informing NRC of Steps taken to correct violations noted during inspec #50-277/78-21 & #50-278/78-26.
 #ARTIN.N.G. Region 1. Philadelphia. Safeguards Branch. 78/10/10.
 1p. 74381:277.

0089 Responds to 780918 NRC ltr re-violations noted in Inspec #850-277/78-21 & #50-278/78-26 Corrective actions:mod user analysis method to calculate incremental Pu-241. ROFF_8.L. Philadelphia Electric Co 78/10/02 2pp. 1 · 298.

0093 Forwards IE Inspec Repts#50-277/78-21 & #50-278/78-26 on 14-16 & Notice of Violation. IN.H.O. Region 1. Philadelphia, Bafeguards Branch. 78/09/18.

94381:300.

0095 Notice of Violation from inspec on 780814-16.
sgion 1, Philadelphia, Office of the Director 78/09/14. ip.
1,302.

0099 IE Inspec Repts#50-277/78-21 2-278/78-26 on 780914-16 ng which i itam of noncompliance was noted: Amount of oactive decay of Pu-281 during periods ending 770331.
30 & 780331 not reported on Form-742-Paragraph 7.
ETT.P.H. Region I. Philadelphia. Office of the Director.
8.E.T., JOYNER.J.H. Region 1. Philadelphia. Sefeguards Brench.
09/14. 10pp. 94381.303.

03 Forwards IE Circulare78-17. (See ANO: 7810230221, Docket 3.781013.) B.M. Region 1, Philadelphia, Office of the Director.

H3 Forwards licensee performence evaluation for Region 1.No. ing reactor in Region 1 considered to have either al or unusual safety concern B.H. Region 1. Philadelphia, Dffice of the Director. 01. 4pp. 00002:259.

60 Forwards IE Circular #78-18, "UL Fire Test. "H/encl AND: 0002. B.H. Region 1. Philadelphia. Office of the Director 06. 1p. 94238-052.

21 Responds to 780929 NRC ltr forwarding IE Bulletin 78-12 lests addi info re reactor vessel weld math & reactor Pabrication.gen Elec Co is providing this into which e forwarded to NRC at a later date. FF.B.L. Philadelphia Electric Co. 78/11/22. 2pp. 94358:335.

55 Forwards IE Bullstin#78-12A, suppl to IE Bullstin#78-12. ANO:7811300055. 8 H. Region I. Philadelphia. Office of the Director. 24. 1p. 94212:220.

dic operating reports & related correspondence

30 Forwards Thermal & Biological Monitoring Rept#60.covering 7804601 thru 7806430 for subj facil. Y.W.B. Philadelphia Electric Co. 78/11/09. ip. 94469:034.

0131 Thermal & Bilogical Monitoring Rept#60.covering period 01 thru 780630,for aubj facils. hiladelphia Electric Co. 78/11/09. 37pp. 94469:035.

.09 Forwards Thermal Monitoring Repts W61 & W62. IY.W.B. Philadelphia Electric Co. 78/12/05. 1p. 94246:238.

10:11 "Thermal & Biological Monitoring Prog for Unit #2 \$3." & hly Rept #61 for Jul 1978 Presents daily summery of temp date: daily generation at PBAPS in thermal magawatts Hy. Conowingo Pond temps & impact hours above July limit. hiladelphia Electric Co. 78/07/31. 12pp. 94246:239.

0112 "Thermal & Biological Monitoring Prog for Unit 2 & 3." hly Rept Wa2 for August 1978.Presents daily generation BAPS hourly Conowingo Pond & impact hours above August idence limits. hiladelphia Electric Co. 78/08/31. 12pp. 94246:250.

064 Monthly Oper Rept for Nov 1978. W.M. Philadelphia Electric Co. 78/12/12. 9pp. 94248:302.

84 Forwards Monthly Oper Rept for Oct 1978. 'M.J. Philadelphia Electric Co. 78/11/09. 1p. 94134:273.

0086 Monthly Oper Rept for Oct 1978. N.W.M. Philede)phie Electric Co. 78/11/15. 9pp. 94134:274.

34 Forwards Sept Thermal Monitoring Rept#63. Y/W.S. Philadelphia Electric Co. 78/12/12, ip. 94366:008. YeW. B. Philadelphia Electric Co.

--7812180157 "Thermal & Biological Monitoring Prog#63 for Sept 1978." Oper w/in applicable thermal criteria w/monthly mean delta temp I 41F higher than mean of preoper experience. ** Philadelphia Electric Co. 78/09/30. Ilps 94366:009.

7812220063 Forwards Monthly Oper Rept for Nov 1978. COONEY, M. J. Philadelphia Electric Co. 78/12/14, 1p. 94248: 300.

B. Reportable occurrences, LERs & related correspondence

7810100096 LERW78-016/03L-0 on 780904 during surveillance test Unit 3 "D"main steam radiat monitor failed to cause e half scram due to defective transistor Transitor was replaced & monitor returned to svc in 6 hours. COONEY, M. J. Philadelphia Electric Co. 78/09/26. 1p. 94033:159.

7810130155 Forwards LER#78-039/03L-0. COONEY.M. J. Philadelphia Electric Co. 78/10/04. 3pp. 94002:354.

--7810130163 LERM78-039/03L-0 on 780904: backflow of radioactive liquid from reducate demineralizers to svc air sys discovered on 760904 & 760921 Caused by leaking process valves & esectated check vieves due to dirt deposits. COONEY, H. J. Philadelphia Electric Co. 78/10/04. 1p. 94002: 359.

7811080094 Rept Occurrence#2-78-41/1P.on 781010 during routine surveillence test of Unit 2 4KV undervoltage relays, setpoint of bus sequence loading relays E-32 & E-42 were out of calibridue to engr error.
ULLRICH.W. T. Philadelphia Electric Co. 78/10/11. 2pp. 94399:079.

7810270261 Forwards LERW78-019/01T-0. COUNEY, M. J. Philadelphia Electric Co. 78/10/16. 2pp. 94029; 200.

--7810270270 LERB78-019/017-0 on 780929: underestimated amount of activity in purps stream of off-gas sample, resulting in 3 peaks exceeding Tech Spac limits. Purging of off-gas directly to vent sys during off-gas process has been stopped. CODNEY.M. J. Philadelphia Electric Co. 78/10/16, 1P. 94029: 202.

78:114008a Reportable Occurrence#3-78-20/1P on 78:1019:while Unit 2 was being inerted.Unit 3 drywell oxygen concentration exceeded Tech Spec limit by 0.1%. Drywell was depressurized & purged to bring oxygen concentration with limit.

ULLRICH.N.T. Philadelphia Electric Co. 78/10/19. 2pp. 94425:059.

7811280470 Reportable Occurence#3-78-21/1P on 781106: HPCI tripped after delivering erratic flow to reactor vessel following a reactor scram. No cause determined & investigation continues. ULLRICH, W. T. Philadelphia Electric Co. 78/11/07. 2pp. 94376: 361.

7811280227 Forwards LERW78-021/017-0. COONEY, M. J. Philadelphia Electric Co. 78/11/20 2pp. 94012: 045.

--7811280230 LERW78-021/01T-0 on 781106: while at pur feedwater control sys failure resulted in reactor low level transient & scram HPCI initiated but delivered unstable flow & soon tripped on overspand. Cause was HPC1 governor being but of calibr. CODNEY, M. J. Philadelphia Electric Co. 78/11/20. 1p.

7812210165 LERM78-022/03L-0 on 781116: during performance of RHR surveillance test, motor operated valveMHD-1348 was closed from control room & failed to reopen. B LCPI sys was declared inoper. Cause: loose drive sleave locknut on operator RHB-5. COONEY, M. J. Philadelphia Electric Co. 78/12/15. 1p. 06911:001.

7812290198 LERM7B-023/03L-0 on 781127: "D" Reactor Bldg Area Ethaust Radiat Monitor indicated downscale & was determined to be inoperable. Caused by defective lener diode in emplifier of QE sensor-converter unit.model#1948927011.

COONEY.M. J. Philadelphia Electric Co. 78/12/20. pp. 94190: 334.

DOCKET 50-279 BANTA MARIA DE GARONA NUCLEAR POWER PLANT H. General correspondence

7811210413 Believes nuc pur cannot be made safe & that constr of gubj facil should be stopped. STAHL, R. F. Affiliation Unknown. 78/11/13. 1p. 94483:126.

- DOCKET 50-280 SURRY POWER STATION, UNII 1
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 7812140180 "NRC draft SER re Surry steam generator repair program, for use by ACRS Surry Subcommittee at 781028 meeting "
 SCHLENGER, A Operating Reactors Branch 1 (Pre 790625). 78/10/27.
- 7812280284 Forwards Bafety Eval by NRR dtd 781215 8CH-ENCER.A Operating Reactors Branch 1 (Pre 790625). 78/12/15. 2pp. 94083.053
- --7812280291 Sapety Evaluation Rept supporting Steam Generator Repair Prog of sub; facil.concluding that health & safety of pub will not be andangered by the proposed steam generator repair prog.

 * Office of Nuclear Reactor Regulation, Director. 78/12/15.
 55pp 94083:055
- F Becurity, medical, emergency & fire protection plans
- 7810300022 Forwards "Chapter 10-Special Security Measures During Constr Open" which is to be incorp as part of mod amended security plan for sub; facils Document available in Central Files only BTALLINOS.C M Virginia Electric & Power Co 78/10/25 fp 94031 052
- 7812120137 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuclear Security Safeguards Newsletter. KENNA, W.B. Region 2. Atlanta, Safeguards Branch. 78/11/17. 4pp 94276; 329
- M Antitrust correspondence
- 7810310360 Ack receipt of add1 antitrust info on Old Dominion Elec Cooperative transmitted by owner of subj facils. PARR.O.D. Light Water Reactors Branch 3 78/10/23. 7pp
- O. Advisory Committee on Reactor Safaguards reports & correspondence
- 7812040389 Notice of ACRB Bubcommittee on Burry Power Plant 781028 open meeting at 8:30 am to discuss steam generator repair program HOYLE, J. C. | Office of the Becretary of the Commission 78/10/10. 2pp. 94382-342
- 7812200296 Forwards 781214 memo containing info on condenser tube matl requested by ACRS during 223d ACRS meeting. CROCKER.L.P. Division of Project Management. 78/12/15 ip 94205:348.
- --7812200307 Forwards list of condenser matl for operating PWR's as requested by ACRS NOONAN, V. 8 Engineering Branch (Pre 791030) 78/12/14. App. 94205: 349
- P Operating license stage documents & correspondence
- 7810230154 Order amending Facil Operating Lics*DPR-32 & DPR-37 Rev 770824 Order for Mod of Lic.
 STELLO, V. Division of Operating Reactors. 78/06/29 4pp. 94194: 351.
- 78:0250232 Supplements 780817 response to IE Bulletin#78-01, "Bergen-Paterson Hydraulic Snubbers". Corrects typographical error. BTALL INGS C. M. Virginia Electric & Power Co. 78/08/30. 1p. 94372 223.
- 7810120034 Forwards add1 info in response to 780612 NRC ltr re movement of heavy loads near spent fuel. Includes diagrams illustrating physical relationship between reactor core, fuel transfer canal-spent fuel storage pool & movement of loads STALLINGS, C.M. Virginia Electric & Power Co. 78/10/09. 3Bpp. 94332:252.
- 7BiOidO139 Responds to NRC itr of 780913 & states plans to comply with conditions of recently issued Exemption & Order for Mod of Lic for subj facil by Jen 1979. Also plans to submit sufficient analysis plus Tech Spec changes in compliance.

 BTALLINGS.C.M. Virginia Electric & Power Co. 78/10/11. ip.

- 7810160198 Forwards amend to Oper Lic for subj facil's proposed Tech Spec Change No 72 Amend is in response to Schwencer's 780828 ltr requesting dev of Tech Specs to ensure operability of the overpressure protoc sys STALLINGS.C.M. Virginia Electric & Power Co 78/10/12 14pp. 94032, 355
- 7810250215 Ack receipt of 1th dtd 780929 stating intention to perfore environ qual test Test prog found acceptable except for acceptance criterion "short term for safety sys initiation following accident "
 SCHMENCER: A Operating Reactors Branch 1 (Pre 790623) 78/10/12
 3pp 94370 038
- 7910190119 Forwards "Subj Faci) Cycle 3 Startup Physics Test Rept-THOMAS W. N. Virginia Electric & Power Co 78/10/13 ip 94368-338
- --7810180121 "Subj Facil Cycle 5 Startup Physics Test Rept"
 KUNBIT18.T J. LEBERBTEIN.J.H. Virginia Electric & Power Co.
 78/09/30 78pp. 94368 212
- 7810270380 Based on clarification of environ testing on Continental cable contained in 780929 ltr testing prog is now acceptable.

 8CHMENCER. A. Operating Reactors Branch 1 (Pre 790825) 78/10/18
 - SCHEENCER.A. Operating Reactors Branch 1 (Pre 790625) 78/10/18 2pp. 94030:162
- 7810300331 Ack recipt of 780726 Itr re inspec & maint of outside recirculation spray pumps & low head safety injection pump. Does not agree that condition of pumps after 30 hours of oper is a sufficient test to assure long term oper EISENHUT, D. C. Assistant Director for Systems Engineering (Pre 791030). 78/10/19. 3pp 94233 348
- 7810270174 Forwards copies of "Steam Generator Repair Prog" for subj facil Rev contains supplemental info requested by staff. BTALLINGS.C.M. Virginia Electric & Power Co 78/10/29 2pp. 94055:288
- --7810270223 "Steam Generator Repair Prog" for subj facil Rev contains supplemental info requested by NRC Staff. * Virginia Electric & Power Co. 78/10/25 9pp. 94036:290.
- 7811060060 Forwards draft safety evaluation re-steam generator prog-(AND:7812140180). & copy of "Radiological Assessment of Steam Generator Removal & Replacement (AND:7812140185) BCH-ENCER, A. Operating Reactors Branch 1 (Pre-790625). 78/10/27. 1p. 94423-328.
- 7811070130 Forwards new sched for submission of radiological effluent Tech Specs as requested in 780710 ltr by B D Vessello Delay has been caused by changes in Model Tech Spec & NUREO 0133 STALLINGS.C.M. Virginia Electric & Power Co. 78/11/03. 1p. 94038:355.
- 7811070190 Responds to 781019 ltr on IRS pumps ORS pumps & LHSI pumps. Btales respective pumps will perform satisfactorily under accident conditions & encls design info & inspec & test results.

 8TALL INOS.C. M. Virginia Electric & Power Co 78/11/03 App. 94036:331.
- 7811170082 Forwards rev page T80.4-7a of Tech Spec amend#44 & 43 transmitted in 780927 ltr. Due to administrative error.an incorrect copy of page was sent. BCHLENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/11/06
- 7811290152 Forwards Amend#45 & #45 to Facil Oper Lic#DPR-32 & #DPR-37 rev Tech Specs requested in 770516 appl w/Environ Impact Appraisal & Notice of Issuance/Negative Declaration.

 8CHHENCER, A Operating Reactors Branch 1 (Pre 790625). 78/11/06 3pp. 94240-001.
- --7811290166 Amend#45 to Fecil Oper Lic#DPR-32 rev Tech Spec re: deleting biological monitoring prog except for low-intensity fish sampling prog.

 8CHHENCER: A Operating Reactors Brench 1 (Pre 790625). 78/11/06 2pp. 94240:004.
- --7811290168 Amend#45 to Facil Oper Lic#DPR-37 rev Tech Spec to reduce prog for temp.selinity & impingement monitoring u/Tech Specs encl.

 BCHMENCER.A. Operating Reactors Branch 1 (Fre 790625). 78/11/05.

- --7811290172 Environ Impact Appraisal supporting Amend#49 & #45 to Facil Oper Lic#DPR-32 & #DPR-37--concluding that there will be no environ impact from proposed action # Operating Reactors Branch I (Pre 790625) 78/11/06 10pp 94240 017
- --7811290175 Notice of Issuance of Amend #45 & #45 to Facil Oper Lic #DPR-32 & #DPR-37 & Negative Declaration on 781106 SCHWENCER.A Operating Reactors Branch I (Pre 790625) 78/11/06 3pp 94240 027
- 7811240021 Notifies util of 781205 seminar in Atlanta to discuss hew Model Rad Effluent Tech Bpcc & encl seminar info sheet. registration form & proposed agenda O'REILLY, J.P. Region 2. Atlanta, Office of the Director. 78/11/09 3pp. 74458-162
- 7811140128 Forwards Rev B replacement pages to document entitled "Steam Generator Repair Prog. Surry Pur Station Units #1 & #2 "
 STALLINGS C.M. Virginia Electric & Power Co. 78/11/10. Spp. 94422-233.
- 7811300097 Forwards NRC staff paper Policy Bession Item(BECY-78-954) re licensee reg performance evaluation. Three methods for evaluation are statistical trend analysis & regional survey method Wout encl D'REILLY.J. P. Region 2. Atlanta, Office of the Director 78/11/15 2pp. 94071.309.
- 7BIR150205 Notice of workshops re implementation of training & qual requirements contained in Append 0 of 10CFR73 Requests pre-workshop registration of attendees to facilitate sending out matl H/encl Registration Form & List of Locations. MILLER.J. R Assistant Director for Bite & Bakeguards (Pre 791030). 78/11/15 Spp.
- 7811300036 Informs VEPC that NRC has contracted w/Mountain Hest Res Inc to undertake a series of post-licensing studies of nuc pur stations. Brudies will analyze socioecon impacts which occurred during constr & post-constr periods of each plant. DEYOUNOR C Division of Site Befety & Environmental Analysis 78/11/20. 2pp. 94070: 353.
- 7811280247 Forwards title page of "Steam Generator Repair Prog" for subj facil, which was forwarded on 780817. Page had been inadvertantly pmitted.

 10 Stall INGS, C. M. Virginia Electric & Power Co. 78/11/22 2pp. 94012:164.
- 7811300222 Forwards responses to NRC questions re permanent solution of low head safety injection & spray pump net positive suction head problems in response to 780131 NRC ltr requesting additinfo BTALLINOS. C. M. Virginia Electric & Power Co. 78/11/22. 34pp. 94070:075.
- 7812150057 Discusses possible dangers of LDCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/encl AND: 7812080207.

 8CHHENCER: A. Operating Reactors Branch 1 (Pre 790625). 78/11/28. 6pp. 49210:099.
- 7812110063 Responds to 780922 ltr requesting comments on Tech Spec charges to Sec4.4 Containment tests. Disapproves proposal that air locks be tested at 4 mo intervals w/o intermediate test should air locks be opened during such interval. STELLO,V. Division of Operating Reactors. 78/11/29. 4pp. 94339:179
- 7812200169 Notifies NRC that for 30 min on 781118, condenser cooling water outlet temp decreased by 3.5 degrees F with both units at steady pur Cooling water through condensers was increased to temp dropped 3.5degrees F.Mc detriment to blota was found. 8TALLINGS, C.M. Virginia Electric & Power Co. 78/11/29. 1p. 74157-359.
- 7812110087 Responds to 780726 request for exemption from 10CFR21.Comm amend to 10CFR21 dtd 781019 might eliminate need for such examption. W/encl FR notice of amend to 10CFR21. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 78/11/30. 4pp. 94338.305.
- 7812120054 Responds to 781103 ltr providing eddl info re low head safety injection pumps, butside plans for inspec & test & schod for providing addl info.
 EISENHUT.D. 0. Assistant Director for Systems Engineering (Pre 791030), 78/12/01. 3pp. 94278:076.

- 7812120059 Ack receipt of 780919 rept VEP-FRD-23, "Reactor Core Thermal Hydraulic Analysis Model Using LYNX | & LYNX 2 Computer Codes." Requests submitted of references 9 & 12.which are omitted SCHMENCER. A Operating Reactors Branch | (Pre 790625) 78/12/04 2pp 94278-096
- 7812180433 Requests registration as user of CNSI-I.L-37-65.CNSI-LL-50-100.CNSI-14-193H, CNSI-LL-28-4.CNSI-4-45.CNSI-AL-33-90. & CNSI-8C-48-220.
 STALLINGS.C M Virginia Electric & Power Co 78/12/04. 1p

94357.029

- 78]2280]3] Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J 0 Office of Inspection & Enforcement, Office of the Director 78/12/06 2pp. 94310-283.
- 7812220006 Forwards repts on subj Facil net positive section head(NP6H) concerns on containment recirculation spray pumps & low head safety (njection pumps Requests an eval by 790101 of the repts re adequacy of available NPSH for subj pumps BUCKLEY, B. C. Plant Systems Brench (Pre. 791030) 78/12/11. 2pp. 94248; 283
- 7812150282 Forwards proposed Amend to Oper Lic DPR-32 Proposed change is to extend oper for add1 nine months from completion of upcoming steam generator inspec Wycheck for \$4,000.00 STALLINOS.C M Virginia Electric & Power Co. 78/12/12 2pp 94409-136
- 7812190079 Forwards proposed Tech Spec to replace those submitted 781012. Proposed changes set reactor coolant sys temp limit of 330 degrees below which the sys must be snabled. Less dependence is put on operator surveillance STALLINGS.C.M. Virginia Electric & Power Co. 78/12/14 10pp 94342: 337
- 7B121900BB Responds to 7B1201 ltr re low head safety injection pumps & outside & inside recirculation spray pumps Will forward conclusions re extension of interval between IRB pump tests following inspec BTALLINGS. CM Virginia Electric & Power Co 7B/12/13 2pp 94343:027.
- 7812190090 Forwards proposed changes in form of an amend to Tech Specs of Oper Lics DPR-32 & DPR-37. Request does not involve any unrevisued safety question Check for payment of amend fees encl.

 8TALLINGS.C.M. Virginia Electric & Power Co 78/12/15. 19pp. 94341:001.
- 7812190148 Forwards results of environ qual testing on the Continental Instrument Cable in use at subj facil Cable performance was w/in acceptance criteria for both the simulated loss of coolant & steam break accident conditions.

 8TALLINGS. C.M. Virginia Electric & Power Co. 78/12/15 ip. 94340: 079.
- --7812190149 Environ testing of instr cable was conducted to conform w/requirements established by subjutil Cable subjected to thermal aging & radiat byposure prior to test simulating LOCA & MBLB accident conditions. Cables function as intended.

 * Virginia Electric & Power Co. 78/11/29. 64pp. 94240-080.
- 7812220032 Forwards suppl repts on guby facil containment recirculation spray pumps & low head safety injection pumps. Requests essistance in reviewing & providing a safety eval of mass & energy release date submitted in early Jan 1979.
 8TELLO,V. Division of Operating Reactors 78/12/16, 2pp. 94248:360.
- 7812260252 Suppl to 781212 VEPC ltr requesting emend to Oper Lic #DPR-32 Provides clarification of inspec programmary of initial inspec results & defines areas of additinspec identified to date. BTALLINGS.C.M. Virginia Electric & Power Co. 78/12/20. App. 94159: 351.
- 7812280132 Raquests an amend to Oper Lic in form of changes to Tech Bpecs re Emergency Core Cooling Bys & Loss of Coolant Accident. Forwards check for \$4,400. 8TALLINGS.C.M. Virginia Electric & Power Co. 78/12/26. 55pp. 94310:285

- Q. Imspection reports: IE Bulletins & correspondence
- 7811010414 Ack receipt of 771207 ltr informing NRC of steps taken to correct violations noted during inspec#50-280/77-30 & #50-281/77-30.

 LDNG.F.J Region 2. Atlanta, Office of the Director. 77/12/16 1p. 94388:342
- --7811010415 Responds to 771114 NRC ltr re violation noted in Inspec Rept #50-280/77-30 & #50-281/77-30. BTALLINGS.C.M. Virginia Electric & Power Co. 77/12/07. lp. 74388:343
- --7811010423 Forwards IE Inspec Rept#50-280/77-30 & #50-281/77-30 on 771004-07 & Notice of Violation Notice of Violation is w/held from disclosure per 10CFR2: 790 LONG,F. J. Region 2, Atlanta, Office of the Director. 77/11/14. 2pp. 74:388: 344.
- --7811010428 IE Inspec Rept#30-280/77-30 & #30-281/77-30 on 771004-07 during which i item of noncompliance was noted improper security bedging Details w/held from disclosure per 10CFR2 790 ROCERS, R.F. & WHITENER, H. L. Region 2. Atlanta, Office of the Director 777/11/09. Bpp.
- 7810230139 Forwards IE Inspec Repts#50-280/78-19 & #50-281/78-19 on 780802-04 during which no items of noncompliance were noted. CONG.F. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 78/09/14. 2pp.
- --7810230140 IE Inspec Repts#50-280/78-19 & #50-281/78-19 on 780802-04 during which no items of noncompliance were noted Major areas inspected included quality assurence records, procurement & follow-up to LER. BYOLDB, J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/709/14. App.
- 7810310048 Forwards IE Inspec Repts #50-280/78-20 & 50-281/78-20 on 780911 during which no items of noncompliance were noted. BUTHERLAND, J. T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 78/09/21. 2pp. 94094:119.
- --78103J0054 IE Inspec Repts #50-280/78-20 & #50-281/78-20 on 780811 during which no items of noncompliance were noted. Major areas inspected included:whole body counting practices & procedures: test count on NRC phantom on whole body counter. GIBSON, A. F. Region 2. Atlenta, Office of the Director. 78/09/21. App. 94094:121.
- 7810250015 Forwards IE Inspec Repts#50-280/78-23 & #50-281/78-23 on 780905-08 during which no items on noncompliance were noted. Inspec Rept w/held from pub disclosure pursuant to 2,790 KENNA-W.B. Region 2, Atlanta, Bafeguards Branch. 78/10/13. Epp. 94410:053.
- 7812060258 Forwards lE Inspec Repts#50-280/78-24 & 50-281/78-24 on 780912-15 during which no items of noncompliance were noted. LONG.F.J. Region P. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/23. 2pp. 94071:328.
- --7812060262 IE Inspec Repts#50-280/78-24 & #50-281/78-24 on 780912-15 during which no items of noncompliance were noted. Major areas inspected incl:plant open-lic event repts. safety injection sys features & IE Circular followup.

 BURKE, D. J., SKOLDS. J. L., LEMIS, R. C. Region 2, Atlanta. Office of the Director. 78/10/23. 7p. 94071:330.
- 7812110222 Forwards IE Inspec Repts#50-280/78-27 & 50-281/78-27 on 780925-29 during which no items of noncompliance were noted. BUTLERLAND, J.T. Region 2, Atlanta, Fuel Facility & Materiale Bafety Branch. 78/11/02. 2pp. 94338:013.
- ~~7812110225 IE Inspec Repte#50-280/78-27 & 50-281/78-27 on 780925-29 during which no items of noncompliance were noted. Hajor areas inspected incliprevious items, reactor coolent chem control, solid radwaste control & gaseous effluents.
 QIBBON.A.F., EMALD.8.C., JACKBON.L.L. Region 2, Atlanta, Fuel Fecility & Materials Safety Branch. 78/11/02. 13pp. 94338:015.
- 7812080006 Forwards IE Inspec Repts#50-280/78-25 & 50-281/78-25 on 780918-22 during which no items of noncompliance were noted. BUTHERLAND, J. T. Region 2. Atlanta Fuel Facility & Materials Safety Branch. 78/11/03. 2pp. 94109:069.
- ---7812080010 16 Inep Regts 50-280/78-25 & #50-281/78-25 on 780918-22.
 No items of noncompliance were noted Major areas inspected: radiological environ monitoring program inclingt control &

- 7811130110 Forwards IE Circular 78-18.
 D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/06
 10. 94113 311
- 7811200335 Forwards IE Inspec Repts#50-280/78-26 & #50-281/78-26 on 780924-29 & Notice of Violation which is withheld from public disclosure.
 KENNA.W.B. Region 2. Atlanta. Safeguards Branch. 78/11/07. 2pp. 9449-332
- 7812140151 Forwards IE Inspec ReptsW50-280/78-29 & 50-281/78-29 on 781002-06 during which no items of noncompliance were noted. LONG, F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/07. 2pp. 94478
- --7812140136 IE Inspec Repts#50-280/78-29 & 50-281/78-29 on 781002-06 during which no items of noncompliance were noted Major areas inspected incl'procedures.LER follow-up & action on previous inspec findings
 OUZTS, J. E., KELLOG9, P. J. Region 2. Atlanta. Reactor Operations
 Nuclear Support Branch 78/11/03. 5pp 94478 352
- 7811130237 Ack receipt of 781026 ltr informing NRC of Steps taken to correct violations noted during inspec#50-280/78-22 & #50-281/78-22 LDN0,F.J Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/08 1p. 03554:318.
- --7811130238 Responds to 781003 NRC ltr re violations noted in Inspec Rept#850-280/78-22 & #50-281/78-22 Corrective actions:
- special requal training course re startup procedures & theory. Emphasis on SRO & RO retraining STALLINOS.C M. Virginia Electric & Power Co. 78/10/26. 3pp. 03554:319.
- --7811130239 Forwards IE Inspec Repts#50-280/78-22 & #50-281/78-22 on 780821-24 & Notice of Violation LOW-F J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/03. 2pp 03554:322.
- --7811130240 Notice of Violation from inspec on 780821-24. * Region 2, Atlanta, Office of the Director. 78/10/03. ip. 03584.324.
- --7811130241 IE Inapec ReptaM50-280/78-22 & #50-281/78-22 on 780821-24 during which 2 items of noncompliance were noted failure to follow procedures paragraphs & deficiency LER's not submitted to NRC w/in req time.

 BURKE, D. J., DRADFORD, H. & BUZY, J. J. Region 2, Atlanta, Office of the Director. 78/10/03. 11pp. 03554:325.
- 7811200127 Ack receipt of 781018 ltr informing NRC of steps taken to correct violations noted during Inspect50-280/78-21 No violations noted during inspect50-281/78-21. LONG.F.J. Region 2. Atlants. Reactor Operations Nuclear Bupport Branch. 78/11/08. 1p 94220:347.
- --7811200133 Responds to 780927 NRC itr to violation noted in Inspec Rept#50-280778-21. Corrective actions: procedures mod to include specific guidance on High Flux Trip Betpoint Reduction. BTALLINGB.C.M. Virginia Electric & Power Co. 78/10/18. 2pp. 94220:348.
- --7811200140 Forwards IE Inspec Repts#50-280/78-21 & #50-281/78-21 on 780815-19 & Notice of Violation re #50-280/78-21. LDNG.F.J. Region 2. Atlants. Reactor Operations Nuclear Support Branch. 78/09/27. 2pp. 94220-350.
- --7811200210 Notice of Violation from inaper on 760815-18. LCNO.F.J. Region 2: Atlanta: Reactor Operations Nuclear Support Branch. 78/09/27. 1p. 94220:352.
- ~7811200214 IE Inspec Repts#50-280/78-21.#50-281/78-21 on 780815-18 during which 1 item of honcompliance was noted: trip syssetting was higher than the limiting sefety sys setting. BURNETT.P.T. MARTIN.R.D. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch. 78/09/26. Spp. 94220:353.
- 7812210108 Forwards IE Inspec Repts#50-280/78-30 & 50-281/78-30 on 781010-13 during which no items of noncompliance were noted.
 LONG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/13. 2pp. 94269:276.
- --7812210113 IE Inspec Repts#50-280/78-30 & 50-281/78-30 on 781010-13 during which no items of noncompliance were noted Major ereas inspected incliplant open plant cleanliness control IE

CONCIED ILEIMO

- 7812290082 Forwards IE Inspec Repts#50-280/78-28 & #50-281/78-28 on 781002-06 during which no items of noncompliance were noted 8UTHERLAND, J.T. Region 2, Atlenta, Fuel Facility & Materials Safety Branch 78/11/17 2pp 94190.089
- --7812290088 [E Inspec Repts#50-280/78-28 & #50-281/78-28 on 781002-06 during which no items of noncompliance were noted Major areas inspected incl.emergenty facils.equip.procedures.toats & drills.gnviron sys & fire brigade topics PEROTTI.D. J. HUFHAM.J W Region 2. Atlanta. Fuel Facility & Materials Safety Branch 78/11/17. 15pp 94190 091.
- 78:201026: Forwards results of staff measurements of radioactive matl in an NRC phantom on the whole body counter taken during inspec on 7809:: SUTHERLAND.J T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 78/11/20 Spp. 94417-145.
- 7812040220 Forwards IE Bulletin#78-12A suppl to IE Bulletin 78-12. H/emri AND 7811200055. D'REILLY, J. P. Region 2. Atlenta. Diffice of the Director. 70/11/24 ip 94121 341
- 7812130381 Responds to IE Bulletin#78-12 re reactor pressure vessel weld meth Will give NRC sched of info availability as soon as arrangements w/vendor are finalized.
 STALLINGS.C.M. Virginia Electric & Power Co. 78/11/28 lp. 94292 217
- 7812180332 Ack recipt of 781201 ltr informing NRC of stops taken to correct violations noted during inspec#50-280/78-26 & #50-281/78-26 KENNA, N B Region 2. Atlanta, Bafaguards Branch 78/12/11 lp. 94356;062.
- --7812180338 Responds to 781107 NRC its re-violations noted in Inspec Repts#50-280/78-26 & #50-201/78j-26 Corrective actions withheld from pub disclosure pursuant to 2 790. STALLINGS, C. H. Virginia Electric & Power Co. 78/11/20 ip 94356-043.
- 7812290040 Farwards IE Bulletin 78-14
 D'REILLY.J. P. Region 2. Atlanta. Office of the Director 79/12/19
 2pp. 94189-336
- R Periodic operating reports & related correspondence
- 7810230184 Forwards Monthly Oper Rept for Sept 1978 BTALLINGS.C M Virginia Electric & Power Co 78/10/13. Ip 94170-193
- --7810230187 Manthly Oper Rept for Bept 1978. BTEMARI, D.L. Virginia Electric & Power Co. 78/10/13 44pp. 94170-194
- 7811170192 Monthly Oper Rept for Oct 1978 BTEHART, D. L. Virginia Electric & Power Co. 78/10/31 43pp
- 7811200194 Forwards Monthly Oper Rept for Oct 1978 BTALLINGS, C.M. Virginia Electric & Power Co. 78/11/14. ip 94283,001.
- --7811200198 Monthly Oper Rept for Oct 1978. STEWHARD, D. L. Virginia Electric & Power Co. 78/11/14. 43pp. 94253-002
- 7812200262 Monthly Oper Rept for Nov 1978 KANE 0 Virginia Electric & Power Co. 78/12/01. 38pp. 94206.242
- 7812200260 Forwards Monthly Oper Rept Por Nov 1978. 81ALLINOS.C.M. Vitginia Electric & Power Co 78/12/12. ip. 94206.261.
- 8. Reportable occurrences, LERs & related correspondence
- 7810100074 Forwards LER#78-004/03x-1 BTALLINGS.C M. Virginia Electric & Power Co. 78/10/03 1p 94032:241.
- --7810100079 LER#78-004/03X-1 on 780303.loss of avc water flow through charging pump intermediate seal cooler was caused by corrosion of atem of discharge gate valve; corrosion was galvanic(brass touching bronse); problem will be studied. 8AUCOM, T. L. Virginia Electric & Power Co. 78/10/03. 3pp. 74032:242.

- 7810110127 Forwards LERM78-028/032-0 BTALLINGS C M Virginia Electric & Puwer Co 78/10/06 1p 74068 266
- --7810110132 LER#78-028/05L-0 on 780716, snubber not meeting inspec criteria caused by low oil level due to leakage at mating surface between body & end plate Holding boits were tightened & snubber was refilled BADCON, I L. Virginia Electric & Power Co. 78/10/09 2pp 94068:267
- 7B10200110 Forwards LER87B-029/03L-0 BTALLINGS.C M Virginie Electric & Power Co 7B/10/17 ip 94164-002
- --TBI02001IB LER#78-029/03L-0 on 780927 failure of Channel II Pressur Pressure(Protec)P-436 failed high due to failure of oscillator amplifier module of the trainmitter Amplifier replaced, tested & Channel II was returned to evo BAUCOM.T L. Virginia Electric & Power Co. 78/10/17 2pp 94140 4003
- 7811090177 Forwards LER#78-030/03L-0, #78-031/03L-0, #78-032/03L-0, #78-033/03L-0
 STALLINGS,C. M Virginia Electric & Power Co 78/11/06. 1p
 94028 184
- --7811090210 LERM78-030/03L-0 on 781009 w/unit at rated pwr.Charging Component Cooling Mater Pump "B'tripped Pump tripped on overcurrent Caused by correction damage to motor bearings Pump & motor rebuilt & reinstalled DAUCON.T L Virginia Electric & Power Co 78/11/09 2pp 94038, 185
- --7811090213 LERA78-031/O3L-O on 781011 Channel I Pressurizer Level (Protec).L-1-459. drifted high Event caused by drift of electronic zero adjustment in conjunction w/leakage thru transmitter's bypass/equaliting valve Valve tightoned BAUCON.T L Virginia Electric & Power Co 78/11/06 2pp. 94038.107
- --7811090217 LERA78-002/03L-O on 781011 heat tracing circuit faults occurred as a result of boric acid incuration faults regained & circuit current verified BAUCOM.T i. Virginia Electric & Power Co 70/11/06. Upp 94038 189
- --7811070219 LERB78-033/03L-0 on 781015 heat tracing circuit failed Caused by old boric acid buildup & penetration of heat leakage BAJCOM.T L. Virginia Electric & Power Co. 78/11/06 2pp
- 94038-192.

7811170183 Forwards LER#78-034/017-0.

- BTALLINGS.C M. Virginia Electric & Power Co. 78/11/14 to 94136 048 -- 78/11/70185 LER#78-034/01T-O on 78/101. during routine inspec on 78
- it was noted that 17 spare process piping containment penetrations on Unit 1 & 23 on Unit 2 were not capped but inside ands sealed in Auxiliary Ridg, due to constructor BAUCOM, T L. Virginia Electric & Power Co. 78/11/14. 2pp. 94136 049
- 7811280236 Forwards LERN78-035/017-0. BTALLINGS.C M Virginia Electric & Power Co. 78/11/21 1p. 94012 156
- --7811280238 LER#78-035/01T-0 on 781109 study of calibr techniques that B1 Accumulators indicated level would be lower than actual level Discovered after rigorous review of factors affecting instru
 BAUCOM T L Virginia Electric & Power Co 78/11/20 3pp.
 94012.157
- 7812040230 Forwards LERW78-040/03L-0 BTALLINOS.C M Virginia Electric & Power Co. 78/11/27 lp 74329:207
- --7812040233 i.ER#78-040/03L-O on 781031 periodic test to inspec ENO during a repueling outage had not been completed for ED9's 1 & 3 Caused by admin error Admin guidelines have been rev BAUCON, T L. Virginia Electric & Power Co. 78/11/29. 2pp. 94025-288.
- 7012050208 Forwards LERM78-036/03L-0.#70-037/03L-0 & #78-038/03L-0. 8TALLINGS, C. M. Virginia Electric & Power Co. 78/11/30. p. 94331:209.

- -7812050209 LER#78-036/03L-0 on 781107:failure of heat tracing circuit 24D. Unital, due to boric acid damage Heat tracing tape replaced BAUCOM, T. L. Virginja Electric & Power Co 78/11/29. 2pp.
- --7812050211 LER#78-037/03L-0 on 781107 procedure deviation found re Filling & venting Reactor Coolant Sys on 770105 Procedure deviation was misrouted to records vault w/o review by BNSOC Deviation has now been submitted to SNSOC for review BAUCOM:T L Virginia Electric & Power Co. 78/11/29. 2pp. 94331:212
- --7812050214 LER#78-038/03L-0 on 781108: quarterly calibr of Nuc Pur Range Instr not performed due to sched error Reactor pur reduced as required & calibr completed IAH existing procedures.

 BAUCON.T.L. Virginia Electric & Power Co 78/11/29. 2pp. 94331: 214.
- 7812140125 Forwards LER#78-039/03L-0.#78-041/03L-0 & #78-042/03L-0. BTAULINGS, C. M. Virginia Electric & Power Co 78/12/12 1p.
- --7812140126 LER#78-039/03L-0 on 781115:during normal oper Channel I of Pressuriter Level Instrumentation LI-1-459 drifted low Cause unknown at this time Transmittor recalibr SAUCOM.T.L Virginia Electric & Power Co 78/12/11 2pp 94127.002
- --7812140129 LER#78-041/03L-0 on 781121.snubber 1-WAPD-HSS-1418 observed ₩/zero fluid level in reservoir Caused by leakage thru Paulty reservoir seals.
 BAUCOM, T. L. Virginia Electric & Power Co. 78/12/11. Rpp. 94127:004.
- --7812140131 LER#78-042/03L-D on 781117:during normal pur oper.manual valves i-BD-B.iB & 20 closed in attempt to stop leak in syr water line, resulting in termination of Plow thru blowdown radiat manitors Caused by operator error. BAUCOM, T. L. Virginia Electric & Power Co. 78/12/11. 2pp. 94127:006.
- 7812200204 Forwards LER #78-034/01X-1.
 BTALLINGS, C.M. Virginia Electric & Power Co. 78/12/13 ip. 94142: 274.
- --7812200207 LER 478-034/01X-1 on 781101 noted that 17 spare process piping penetrations on Unit #1 & 23 on Unit #2 were hot capped in Auxiliary Bidg. Caused by failure to properly complete capping at end of constr.

 BAUCOM.T. L. Virginia Electric & Power Co. 78/12/13. 3pp. 94162: 275.
- 7812270290 Forwards LER#78-022/03X-1.

 BTALLINGS, C. M. Virginia Electric & Power Co. 78/12/20. 1p.

;

- --7812270294 LERB78-022/03X-1 on 780726:Hydro Test Pump failed to build up pressure during attempt to fill Safety Injection Accumulators due to lifting of its relief valve Valve replaced & checked. Accumulator refilled BAUCOM.T.L. Virginia Electric & Power Co. 78/12/18. 2pp. 94229 342
- 7912270320 Forwards LER878-044/03L-0.

 8TALLINOS C M. Virginia Electric & Power Co 78/12/20. 1p. 94230: 360.
- --7812270324 LER#78-044/03L-0 on 781204 during normal full pur oper, loss of flow was detected in charging pump intermediate seal cooler i-SW-E-IB Caused by failure of cooler intake gate valve becoming corroded. BAUCOM, T. L. Virginia Electric & Power Co 78/12/18. 2pg. 94230:361.
- T. Hearing transcripts on non-antitrust matters
- 7811100051 Transcript of 781028 subcomm meeting in Hashington, DC resubj facil steam generator repair prog & whether ACRB should review the prog.
 CARBON, M., MDELLER, D., ETHERINGTON, H. ACRB Advisory Committee on Reactor Bafeguards. 78/10/28. 191pp. 94175:245.

- DOCKET 50-281 SURRY POWER STATION, UNIT 2
- E. NRC Bafety Evaluation Report (BER1: supple & correspondence
- 7812140180 "NRC draft SER re Surry steam generator repair program use by ACRS Surry Subcommittee at 781028 meeting." SCHLENCER, A Operating Reactors Branch 1 (Pre 790625) 78/10/
- 7812280284 Forwards SaPety Evel by NRR dtd 781215 SCHUENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/12/ 2pp 94083:053.
- --7812280291 Safety Evaluation Rept supporting Steam Cenerator Re Prog of subj facil, concluding that health & safety of pub will not be endangered by the proposed steam generator
 - repair prog. 9 Office of Nuclear Reactor Regulation, Director 78/12/15 37pp. 94083:035.
- F. Security, medical, emergency & fire protection plans
- 7812120157 Forwards reproductions of articles that appeared in Ju Aug 1978 editions of Nuclear Security Safeguerds Newsletter KENNA-H B. Region 2. Atlanta, Bafeguards Branch. 78/11/17. 4 94276: 329.
- 7810300022 Forwards "Chapter 10-Special Security Measures During Open" which is to be incorp as part of mod amended security plan for subj facils. Document available in Central Files only STALLINGS, C. M. Virginia Electric & Power Co. 78/10/25. ip. 94031:052
- Q. Adjudicatory correspondence
- 7810110043 Amend 44 to Facil Oper Lit DPR-37 revising Tech Spets Changing date of next inspec of steam generator tubes. BTELLO:V. Division of Operating Reactors. 78/10/03. 3pp. 94062:186.
- M. Antitrust correspondence
- 7810310360 Ack receipt of add1 antitrust info on Old Dominion Ele Cooperative transmitted by owner of subj facils. PARR.O.D. Light Water Reactors Branch 3. 78/10/23. 7pp.
- O. Advisory Committee on Reactor Bafeguards reports & corresponde
- 7812060389 Notice of ACRS Subcommittee on Surry Power Plant 78102 open meeting at 8:30 am to discuss steam generator repair
 - program HOYLE, J.C. Opfi 2pp. 94382:342. Office of the Secretary of the Commission 78/10/1
- 7812200296 Forwards 781214 memo containing info on condensar tube requested by ACRB during 223d ACRS meeting.
 CROCKER.L. P. Division of Project Management. 78/12/15. 19. CROCKER, L. P. 94205: 348.
- --7812200307 Forwards list of condenser matt for operating PWR's requested by ACRB.
 NCONAN.V. S. Engineering Branch (Pre 791030). 78/12/14. 4pp 74205: 349.
- P. Operating license stage documents & correspondence
- 7811170082 Forwards rev page TSQ.4-7a of Tech Spec amend#44 & 43 transmitted in 780927 ltr. Due to administrative error an incorrect copy of page was sent.

 BCHMENCER.A. Operating Reactors Branch 1 IPre 790625). 78/11/ 3pp. 02766: 281.
- 7812110063 Responds to 780922 ltr requesting comments on Tech Spechanges to Sec4, 4 Containment tests. Disapproves proposal that air locks be tasted at 4 mo intervals w/o intermediate test should air locks be opened during such interval. STELLO.V. Division of Operating Reactors. 78/11/29. 4pp. 94338:179.
- 7812110087 Responds to 780726 request for exemption from 10CFR21. amend to 10CFR21 dad 781019 might eliminate need for such exemption. W/encl FR nobice of amend to 10CFR21.

 DENTIN.H.R. Office of Nuclear Reactor Regulation. Director. DENTON: H. R. Office of Nucl. 78/11/30, 4pp. 94338: 305.

ノいしんにょさわ ここにいり

- 78:2:20054 Responds to 78:103 ltr providing addl info re low head safety injection pumps, outside plans for inspec & test & sched for providing add1 info. EIBENHUT.D.Q. Assistant Director for Systems Engineering (Pre 791030) 78/12/01. 3pp 94278:076
- 7812120057 Ack receipt of 780919 rept VEP-FRD-23, "Reactor Core Thernal Hydraulic Analysis Model Using LYNX 1 & LYNX 2 Computer Codes." Requests submittal of references 9 & 12, which are omitted.
- Operating Reactors Branch 1 (Pre 790625) 78/12/04 BCHLENCER, A. 2pp. 94278.096
- 7810230154 Order amending Facil Operating Lics#DPR-32 & DPR-37 Rev 770824 Order for Mod of Lic. STELLO.V. Division of Operating Reactors. 78/06/89 4pp 94194:351.
- 7810250232 Supplements 780817 response to IR Bulletin#78-01, "Bergen-Paterson Hydraulic Snubbers". Corrects typographical error STALL INOS. C. M. Virginia Electric & Power Co. 78/08/30. 1p.
- 94372: 223 7810110041 Forwards Amend 44 to License DPR-37. safety evaluation &
- notice of issuance & availability. SCHLENCER, A. Operating Reactors Branch 1 (Pre 790625) 70/10/03. SCHWENCER, A. 2pp. 94063:184
- --7810110044 Notice of Issuance of Amend#44 to Facil Oper Lic#OPR-37 8CHHENGER,A. Operating Reactors Branch 1 (Pre 790625) 78/10/00 3pp. 94063:189.
- --7810110048 Bafety evaluation supporting Amend 44 to License DPR-37.
 Plent may be operated for another six months & then shut
 down so steam generators can be reprobed to assess extent
 of tube denting. Office of Nuclear Reactor Regulation, Director 78/10/03 Spp. 94063:192.
- 78:01:01:07 Responds to NRC ltr of 78:09:3 & states plans to comply with conditions of recently issued Exemption & Order for Mod of Lic for subj facil by Jan 1979. Also plans to submit sufficient analysis plus Tech Spec changes in compliance STALLINGS. C. M. Virginia Electric & Power Co. 78/10/11. 1p. 2000/8-10.
- 94005: 311.
- 7810160198 Forwards amend to Oper Lic for subj facil's proposed Tech Bpec Change No. 72 Amend is in response to Schwencer's 780828 ltr requesting dev of Tech Specs to ensure operability of the averpressure protecting and the protection of the Power Co. 78/10/12. 14pp. 94052: 355.
- 7810250215 Ack receipt of 1tr dtd 780929 stating intention to perform anviron qual test Tost prog found acceptable except for acceptance criterion "short term for safety sys initiation following accident."

 BCHMENCER.A. Operating Reactors Branch i (Pro 790625). 78/10/12.

 3pp. 94370:038.
- 7810180119 Forwards "Subj Facil Cycle S Startup Physics Test Rept". THOMAS.W.N. Virginia Electric & Power Co. 78/10/13. 1p. 94348: 35B.
- --7810180121 "Bubj Fecil Cycle 5 Stertup Physics Test Rept". KUNSITIS.T.J., LEBERSTEIN.J.H. Virginia Electric & Power Co 78/09/30 78pp 94368:212.
- 7810270380 Based on clarification of environ testing on Continental cable contained in 780929 itr testing prog is now acceptable. SCHWENCER, A Operating Reactors Branch (Pre 790625). 78/10/19. 2pp. 94030: 162.
- 7810300331 Ack reciept of 780726 ltr re inspec & maint of outside recirculation apray pumps & low head safety injection pump.

 Does not agree that condition of pumps after 50 hours of oper is a sufficient test to assure long term oper. Oper 19 d to 20 central ent test to assure for Byetems Engineering (Pre 791030). 78/10/19. 3pp. 94253:348.
- 7810270174 Forwards copies of "Steam Generator Repair Prog" for subj facil Rev contains supplemental info requested by staff. BTALLINGS. C.M. Virginia Electric & Power Co. 78/10/25. 2pp. 94056: 288.
- --7810270223 "Steam Generator Repair Prog" for subj facil Rev contains supplemental info requested by NRC Staff.

 * Virginia Electric & Pawer Co. 78/10/25. 9pp. 94056:290.

- 7811060060 Forwards draft safety evaluation re steam generator prog (ANO 7812140180), & copy of "Radiological Assessment of Bteam Generator Removal & Replacement (ANO: 7812140185) BCHWENCER. A Operating Reactors Branch 1 (Pre 790525). 79/10/27 1p. 94423.328
- 7811070130 Forwards new sched for submission of radiological effluent Tech Specs as requested in 780710 ltr by B D Vassallo Delay has been caused by changes in Model Tech Spec & NUREQ 0133 BTALLINGS.C.M Virginia Electric & Power Co. 78/11/03. ip. 74038:355
- 7811070190 Responds to 781019 ltr on 188 pumps, ORS pumps & LHSI pumps. States respective pumps will perform satisfactorily under accident conditions & encls design info & inspec & test results. STALLINGS, C.M. Virginia Electric & Power Co. 78/11/03. App. 94036: 351.
- 7811290192 Forwards Amend#49 & #49 to Facil Oper LicMDPR-32 & #DPR-37 rev Tech Specs requested in 770516 appl w/Environ Impact Appraisal & Notice of Issuance/Negative Declaration Operating Reactors Branch 1 (Pre 790625) 78/11/06. 300 94240.001
- --7811290166 Amend#45 to Facil Oper Lic#DPR-32 ray Tech Spec re deleting biological monitoring prog except for low-intensity fish sampling prog. BCHHENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/06. BCHWENCER, A. OF 2pp 94240: 004.
- --7811290168 Amend#45 to Facil Open Lic#DPR-37 rev Tech Spec to reduce prog for temp, ealinity & impingement monitoring w/Tech Specs
- SCHWENCER. A Operating Reactors Branch | (Pre 790625) 78/11/06 2pp. 94240:006 --7811290172 Environ Impact Appraisal supporting Amend#45 t #45 to Faci Oper Lic#DPR-32 t #DPR-37--concluding that there will be no
- environ impact from proposed action. * Operating Reacture Branch 1 (Pre 790628). 78/11/06. 10pp. 74240:017.
- --7811290175 Notice of Issuence of Amend #45 & #45 to Facil Oper Lic WDPR-32 & WDPR-37 & Negative Declaration on 781106 SCHUENCER. A. Operating Reactors Branch 1 (Pre 790625) 78/11/06 3pp. 94240:027.
- 7811240021 Notifies util of 781205 seminar in Atlanta to discuss new Model Red Effluent Tech Bpecs & encl seminar in Actanta to discuss new Model Red Effluent Tech Bpecs & encl seminar info sheet, registration form & proposed agenda.

 D'RELLLY, J. P. Region 2, Atlanta, Défice of the Director 7B/11/09.
- 3pp. 94458:162. 7811;40128 Forwards Rev 8 replacement pages to document entitled "Steam Oenerator Repair Prog. Surry Pur Station.Units #1 & #2." BTALLINGS.C.M. Virginia Electric & Power Co 78/11/10. Spp.
- 94425: 233. 7811300057 Forwards NRC staff paper. Policy Session Item(SECY-78-554) re
- licensee reg performance evaluation. Three methods for evaluation are: statistical, trend analysis & regional survey method.W/out enci. G*REILLY.JP Region 2, Atlanta, Gffice of the Director. 78/11/15. 2pp. 94071:309.
- 7812130205 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attenders to facilitate sending out meth. W/encl Registration Form & List of Locations MILLER.J.R. Assistant Director for Site & Bafeguards (Pre 791030), 78/11/15. Spp.
- 7812180288 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PHR's (NUREO-0473) & "Preparation of Radiological Effluent Tech Spers for Nuc Pur Plants" (NUREO-0133). ORIMES.B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. Opp. 94363:136.
- 7811300036 Informs VEPC that NRC has contracted w/Mountain West Res Inc to undertake a series of past-licensing studies of nur pur stations. Studies will analyze socioecon impacts which occurred during constr & post-constr periods of each plant. DEYOUNG, R. C. Pivision of Site Bafety & Environmental Analysis. 78/11/20. 2pp. 94070:353
- 7811280247 Forwards title page of "Steam Generator Repair Prog" for sub; facil.which was forwarded on 780817.Page had been inadvertantly omitted. STALLINGS.C.M. Virginia Electric & Power Co. 78/11/22. 2pp.

- 7811300222 Forwards responses to NRC questions re permanent solution of low head safety injection & spray pump net positive suction head problems in response to 780131 NRC ltr requesting additing STALLINGS. C. M. Virginia Electric & Power Co. 78/11/22 3App 94070 075
- 7812150059 Discusses possible dangers of LOCA in containment purging during normal plant open Requests either commitment to limit purging or justification for continuing Wienci ANO 7812080207
 BCHNENCER A Operating Reactors Branch I (Pre 790625) 78/11/28. bpp 94210 099
- 7812200169 Notifies NRC that for 30 min on 781118, condenser cooling water dutilet terp decreased by 3.5 degrees F with both units at steady pur Cooling water through condensers was increased a temp dropped 3.5degrees F No detrinent to biota was found STALLINOS, C.M. Virginia Electric & Power Co. 78/11/29 1p. 94157 359.
- 7812180433 Requests registration as user of CNSI-LL-57-65. CNBI-LL-50-100. CNSI-14-195%. CNBI-LL-28-4. CNBI-4-45. CNBI-AL-33-90. & CNSI-8C-48-220 STALL INOS. C M Virginia Electric & Power Co. 78/12/04 19 94-357-009
- 7812280131 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants, info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuraties or enforcement action will result. DAVIS. J Q Office of Inspection & Enforcement. Office of the Director. 78/12/06 2pp. 94310.283
- 7812220006 Forwards repts on subj Facil net positive section head(NPSH) concerns on containment recirculation spray pumps & low head safety injection pumps Requests an eval by 790101 of the repts re adequacy of available NPSH for subj pumps BUCKLEY.B C Plant Systems Branch (Fre 791030) 78/12/11. 2pp. 94248; 293
- 7812190079 Forwards proposed Tech Spec to replace those submitted 781012. Proposed changes set reactor coolant systemp limit of 390 degrees below which the sys must be enabled. Less dependence is put on operator surveillance STALL INGS, C.M. Virginia Electric & Power Co. 78/12/14. 10pp. 94349-357.
- 781219008B Responds to 781201 ltr re low head safety injection pumps & outside & inside recirculation spray pumps Will forward tonchusions re extension of Interval between IRB pump tests following inspec.

 STALLINGS C M Virginia Electric & Power Co. 78/12/15 2pp 94342:007
- 7812190090 Forwards proposed changes in form of an amend to Tech Specs of Oper Lics DPR-32 & DPR-37 Request does not involve any unreviewed safety question. Check for payment of amend fees encl
 STALLINGS. C M. Virginia Electric & Power Co 78/12/15. 19pp. 94341.001
- 7812190148 Forwards results of environ qual testing on the Continental Instrument Cable in use at subj facil. Cable performance was w/in acceptance criteria for both the simulated loss of coelant & steam break accident conditions
 STALL INOS. C. M. Virginia Electric & Power Co. 78/12/15. Ip. 94340, 079
- --TB12190149 Environ testing of instricable was conducted to conform w/requirements established by subjutil. Cable subjected to thermal aging & radiat exposure prior to test simulating LOCA & MSLB accident conditions. Cables function as intended. 9 Virginia Electric & Power Co. 78/11/29, 64pp. 94340:080.
- 7812220032 Forwards suppl repts on subj Pacil containment recirculation spray pumps & low head saPaty injection pumps. Requests assistance in reviewing & providing a safety eval of mass & energy release data submitted in early Jan 1979.
 BTELLGI.V. Division of Operating Reactors. 78/12/16. 2pp. 94248:360
- 7812280132 Requests an amend to Oper Lic in form of changes to Tech Specs re Emergency Core Cooling Bys & Loss of Coolent Accident Forwards check for \$4,400.

 87ALLINGS.C.M. Virginia Electric & Power Co. 78/12/26. 55pp. 94310:285.

- Q Inspection reports. IE Bulletine & correspondence
- 7812010261 Forwards results of staff measurements of radioactive matina NRC phantom on the whole body counter taken during inspec on 780911
 8UTHERLAND.J T Region 2. Atlante, Fuel Facility & Materials Safety Branch. 78/11/20 3pp. 94417:143
- 7812080010 IE Insp Repts 50-280/78-25 & #50-201/78-25 on 780918-22 No items of noncompliance were noted Major areas inspected radiological environ monitoring program inclingt control & implementation of monitoring programs
 PERRYLM M., MACARTHUR, T. C., HUFMAN, J. W. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 78/11/03 4pp. 74109.071
- 7812110222 Forwards IE Inspec Repts#50-280/78-27 & 50-281/78-27 on 780925-29 during which no items of noncompliance were noted SUTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Sefety Branch. 78/11/02. 2pp. 94338-013
- --7812110225 IE Inspec Repts#50-280/78-27 & 50-281/78-27 on 780925-29 during which no items of noncompliance were noted Major areas inspected incl-previous items.reactor coolant chem control.solid radwaste control & gaseous effluents.

 QIBSON.A.F., EMALD.S.C., JACKSON.L.L. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 78/11/02 13pp. 94338 015
- 7812140156 IE Inspec Repts#50-280/78-29 & 50-281/78-29 on 781002-06 during which no items of noncompliance were noted Major areas inspected incl.procedures.LER follow-up & action on previous inspec findings.

 OUZTB. J E., KELLOGO.P. J. Region 2. Atlanta. Reactor Operations, Nuclear Support Branch. 78/11/03. Spp. 94478-352
- 781229040 Forwards IE Bulletin 78-14 D'RRILLY, J.P. Region 2, Atlante, Office of the Director. 78/12/19 2pp 94189, 334.
- 7811010414 Ack receipt of 771207 ltr informing NRC of steps taken to correct violations noted during inspecMS0-280777-30 & MS0-281777-30.

 LOND.F.J. Region 2- Atlanta. Diffice of the Director 77/12/16 ip 94388: 342
- --7811010415 Responds to 771114 NRC ltr re violation nated in Inspec Rest #50-280/77-30 & #50-281/77-30. 87ALLINOS.C.M. Virginia Electric & Power Co. 77/12/07. ip 94388:343.
- --7811010423 Forwards IE Inspec Rept#50-280/77-30 & #50-281/77-30 on 771004-07 & Notice of Violation Notice of Violation is wheld from disclosure per 10CFR2.790 LONG.F. J. Region 2. Atlanta, Office of the Director. 77/11/14 2pp. 94388:344.
- --7811010428 IE Inspec Rept#50-280/77-30 & #50-281/77-30 on 771004-07 during which I item of nuncompliance was noted: improper security badging. Details w/held from disclosure per 100FRZ 790.
 ROSERS.R.F., WHITENER.H.L. Region 2, Atlanta, Office of the Director. 77/11/09. Spp.
- 7810250139 Forwards IE Inspec Repts#50-280/78-19 & #50-281/78-19 on 780802-04 during which no items of noncompliance were noted. LONG-F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/14. 2pp.
- ---7810250140 JE Inspec Repts#50-280/78-19 & #50-281/78-19 on 780802-04 during which no items of noncompliance were noted Major areas inspected included; quelity assurance records, procurement & follow-up to LER.
 SWOLDB.J.L. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/09/14. dpp.
- 7810310048 Forwards IE Inspec Repts #30-280/78-20 \$ 50-281/78-20 on 780811 during which no items of noncompliance were noted. SUTHERLAND, J. T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 78/09/21. 2pp. 94094:119.
- --7810310054 IE Inspec Repts #30-280/78-20 & #30-281/78-20 on 780811 during which no Items of noncompliance were noted. Major erass inspected included: whole body counting practices & procedures; test count on NRC phantom on whole body counter. Q1880N.A.F. Region 2, Atlanta, Office of the Director. 78/09/21. 4pp. 94094:121.
- 7810260015 Forwards IE Inspec Repts#50-280/78-23 & #50-281/78-23 on 780905-08 during which no items on noncompliance were noted. Inspec Rept w/held from pub disclosure pursuant to 2,790. KENNA,M.B. Region 2, Atlante, Safaguards Branch. 78/10/13. 29p. 94910:093.

001(#12101110

- 7812060258 Forwards IE Inspec Repts#50-280/78-24 & 50-281/78-24 on 780912-15 during which no items of noncompliance were noted. LONO,F.J. Region 2, Atlanta. Reactor Operations Nuclear Support Branch. 78/10/23. 2pp. 94371:328
- --7812060262 IE Inspec Repts850-280/78-24 & #50-281/78-24 on 780912-15 during which no items of noncarpliance were noted Major areas inspected incliplant oper-lic avent repts.safety injection sys features & IE Circular followup BURKE, D. J. 8KOLDS, J. L. LEWIS, R. C. Region 2, Atlanta, Office of the Director, 78/10/23 7pp. 94371-330
- 7812080006 Forwards IE Inspec Repts#50-280/78-25 & 50-281/78-25 on 780918-22 during which no items of noncompliance were noted. 8UTHERLAND.J.T. Region 2. Atlants. Fuel Facility & Materials Safety Branch. 78/11/03 2pp. 94109:069.
- 7811150110 Forwards IE Circular 78-18.

 O'REILLY J.P. Region 2. Atlanta. Defice of the Director 78/11/06
- 7811200335 Forwards 1E Inspec Repts#30-280/78-26 & #50-281/78-26 on 780924-29 & Notice of Violation which is withheld from public disclosure.
 KENNAN B. Region 2, Atlanta, Bafeguards Branch. 78/11/07. 2pp. 94419:332.
- 7812140151 Forwards IE Inspec Repts#50-280/78-29 & 50-281/78-29 on 781002-06 during which no items of noncompliance were noted LDNO.F. J Region 2, Atlenta: Reactor Operations Nuclear Support Branch. 78/11/07. 2pp. 94478:350.
- 7811130237 Ack receipt of 781026 ltr informing NRC of Steps taken to correct violations noted during inspec#50-280/78-22 % #30-281/78-22. CONG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/08.
- --78iii30238 Responds to 78i003 NRC ltr re violations noted in Inspec Repta#50-280/78-22 & #50-28i/78-22 Corrective actions: special requal training course re startup procedures & theory. Emphasis on SRO & RO retraining. BTALLINOB.C.M. Virginis Electric & Power Co. 78/10/26. 3pp. 0354: 319.
- --7811130239 Forwards Id Inspec Repts#50~280/78-22 & #50~281/78-22 on 780821-24 & Notice of Violation.
 LDNO.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/03. Rep. 03554:322
- --7811130240 Notice of Violetion from inspec on 780821-24.
 Region 2: Atlanta: Office of the Director: 78/10/03. 1p. 0354-324
- --7811130241 IE Inspec Repts#50-280/78-22 & #50-281/78-22 on 780821-24 during which 2 items of noncompliance were noted failure to follow procedures paragraphs & deficiency LER's not submitted to NRC w/in req time.

 BURKE, D. J. BRADFORD H. H. BUZY, J. D. Region 2: Atlanta, Office of the Director, 78/10/03. 11pp. 03854:325.
- 7811200127 Ack receipt of 781018 ltr informing NRC of steps taken to correct violations noted during Inspec#30-280/78-21. No violations noted during inspec#30-281/78-21. LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/08. 1p. 94220:347.
- --7811200133 Responds to 780927 NRC ltr re violation noted in Inspec Rept#80-280778-21. Corrective actions: procedures mod to include specific guidance on High Flux Trip Setpoint Reduction. BTALLINOS.C.M. Virginia Electric & Power Co. 78/10/18. 2pp. 9422: 348.
- --7811200140 Forwards IE Inspec Repts#50-280/78-21 & #50-281/78-21 on 780815-18 & Notice of Violation re #50-280/78-21. LUMG.F.J. Repion 2, Atlants, Reactor Operations Nuclear Support Brench, 78/09/27. 2pp. 94220:050.
- --7811200210 Notice of Violation from inspec on 780015-18. LONG,F. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/09/27, ip. 94220:352.
- --7811200214 IE Inspec Repts#50-280/78-21.#50-281/78-21 on 760815-18 during which i item of noncompliance was noted trip sys setting was higher than the limiting safety sys setting. BURNETT.P.T., MARTIN.R.D. Region 2, Atlanta. Reactor Operations Nuclear Support Branch. 78/09/26. 5pp. 94220:353.

- 7812210108 Forwards IE Inspec Repts#50-280/78-30 & 50-281/78-30 on 781010-13 during which no items of noncompliance were noted. LONG F.J. Region 2. Atlants, Reactor Operations Nuclear Support
 - LONG.F.J. Region 2: Atlanta. Reactor Operations Nuclear Support Branch 78/11/13 2pp. 94269.276
- 7812290082 Forwards IE Inspec Repts#50-280/78-28 & #50-281/78-28 on 781002-06 during which no items of noncompliance were noted. BUTHERLAND.J T Region 2. Atlants, Fuel Facility & Materials Safety Branch. 78/11/17 2pp. 94190 089
- 7812040320 Forwards IE Bulletine78-12A suppl to IE Bulletin 78-12. H/encl AND 7811300055 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/24, 1p. 94121: 341
- 78:2130381 Responds to 1E Bulletin#78-12 re reactor pressure vessel weld math Will give NRC sched of info availability as soon as arrangements wivendor are finalized.
 BTALLINGS, C. M. Virginia Electric & Power Co. 78/11/28, ip. 94272:217.
- 7812180352 Act recipt of 781201 ltr informing NRC of steps taken to correct violations noted during inspec#50-280/78-26 t #50-281/78-26 KENNA, M.B. Region 2, Atlanta, Bafeguards Branch. 78/12/11. 1p. 94354:062.
- --7812180358 Responds to 781107 NRC ltr re violations noted in Inspec Repts#50-280/78-26 & #50-281/78j-26. Corrective actions withheld from pub disclosure pursuant to 2.790. STALLINGS.C.M. Virginia Electric & Power Co. 78/11/28. lp. 94336:063
- R. Periodic operating reports & related correspondence
- 7811170192 Monthly Open Rept for Oct 1978. STEWART, D. L. Virginia Electric & Power Co. 78/10/31. 43pp.
- 7810230184 Forwards Monthly Oper Rept for Sept 1978. 8TALL NOS.C.M. Virginia Electric & Power Co. 78/10/13 ip. 94170:193.
- --7810230187 Monthly Oper Rept for Sept 1978. BIEHART.D.L. Virginia Electric & Power Co. 78/10/13. 44pp. 94170:194.
- 7811200194 Forwards Monthly Open Rept for Oct 1978. BTALLINGS, C.M. Virginia Electric & Power Co. 78/11/19. ip. 94281 001.
- --7811200198 Monthly Oper Rept for Dct 1978. BIEWHARD.D.L. Virginia Electric & Power Co. 78/11/14. 43pp. 94282:002
- 7812200262 Manthly Oper Rept for Nov 1978.
 KANE.G. Virginia Electric & Power Co. 78/12/01. 38pp. 94206:262.
- 7812200260 Forwards Monthly Oper Rept for Nov 1978. STALLINBS.C.M. Virginia Electric & Power Co. 78/12/12. 1p. 94206:261
- 8. Reportable occurrences. LERs & related correspondence
- 7911170183 Forwards LER#78-034/01T-0. BTALLINGS,C.M. Virginia Electric & Power Co. 78/11/14. ip. 94136:048.
- --7811170185 LER#78-034/01T-0 on 781101: during routine inspec on 78102 it was noted that 17 spars process piping containment penetrations on Unit 1 & 23 on Unit 2 were not capped, but inside ands sealed in Auxiliary Bidg, due to constructor.

 BAUCOM.T. L. Virginia Electric & Power Co. 78/11/14. 2pp. 94134-049
- 7810100057 Forwards LER878-011/03x-1. STALLINBS.C.M. Virginia Electric & Power Co. 78/10/03. 1p. 94033:094.

- --7810)00065 LERM78-011/03x-1 on 780305 During normal full pur aper there
 was no see water flow thru charging pump intermediate seal
 cooler 2-SW-E-18, due to failure of the cooler's discharge
 gate value
 * Virginia Electric & Power Co 78/10/03 3pp 94033 095
- 7810230257 Forwards LEH#78-032/03L-0 STALLINGS.C M. Virginia Electric & Power Co 78/10/12 1p 94181.351
- --7B10230262 LERW78-032/03...-O on 78092) heat tracing circuit manual boration/boric acid-to-blender failed Failure caused by boric acid penetration of the heat tracing tape circuits Heat tracing tape replaced BAUCOM.T L Virginia Electric & Power Co 78/10/12 3pp. 94181-352
- 7810200109 Forwards LER#78-033/00L-0 BTALLINGS, C.M. Virginia Electric & Power Co. 78/10/17. 1p. 94401-217
- --7810200112 LERW78-033/03L-0 on 780926 Circulating water outlet valve MCV-GW-2000 failed to close when operated elec Actuator cam for shut "tengue switch became wedged against a tongue switch Buitch mod by hold down screw locking hardware BAUCOM I L. Virginia Electric & Power Co. 78/10/17 2pp. 74401 219.
- 7811060211 Forwards LER#78-034/03L-0 & #78-035/03L-0 87ALLINOS, C M Virginia Electric & Power Co 78/11/01. 1p. 94489-229
- --781060213 LER#78-034/03L-0 on 781006 w/unit at cold shutdown, snubbers 2-8H-H38-20 & 2-HFPD-H88-9 found inoper due to low fillid level. Defective snubbers were dry because of leaking rad seals. Leak due to mech damage to seal. Snubbers replaced GAUCON.T. L. virginia Electric & Power Co. 78/10/31 2pp. 74487:230
- --7811060217 LER#78-035/03L-0 on 781007: during cold shutdown-valve pit was flooded while draining circulating water bo: D Motor oper valve damaged by flood & could not accept vol of water being pumped from water bo: D. RAUCOM.T i... Virginia Electric & Power Co. 78/10/31 2pp 94489-232
- 7811090236 Forwards LER#78-036/03L-0 BTALLINGS, C M Virginia Electric & Power Co. 78/11/06 ip. 94042:083
- --7811090240 LERBY8-036/03L-0 on 781015 compensatory surveillance on RCP "c"atator & hearing temp had not been performed Caused by failure of operating personnel to restore process computer trand block following computer reinitialization.

 BAUCOM J. L. Virginia Electric & Power Co 78/11/03. 2pp. 74042:084.
- 7811210259 Forwards LER#78-037/03L-0. STALLINGS.C M. Virginia Electric & Power Co. 78/11/14. 1p.
- --7811210266 LERB78-007/03L-0 on 781022 with unit at rated pur.panel indicator for Radiat Monitor RM-213 monitoring "A" steam generator bluwdown read "O". Caused by loose connector joining detector cable to electronic chassis BAUCON.T.L. Virginia Electric & Power Cd. 78/11/14. 1p 03557:020.
- 7811280286 Forwards LER878-038/03L-0 8TALLINGS.C.M. Virginia Electric & Pauer Co. 78/11/20 1p. 94399:241.
- --7811280292 LERW78-038/03L-D on 781030.boric acid flow from boric acid tenks to blender was interrupted due to crystallized boron blockage at albow in line 1"-CH-336-132 Obstruction was removed & pipe flow returned to normal.

 BAUCOM.T. L. Virginia Electric & Pawer Co. 78/11/17. 2pp. 74395:242.
- 7812140224 Forwards LER878-039/03L-0 & \$78-040/03L-0 STALLINOS.C.M Virginia Electric & Power Co. 78/12/12 1p. 94204:341.
- --7812140229 LER#78-039/03L-O on 781115 during normal oper it was noted that "B" loop hot leg bemp sensing element TI-2-422A was drifting low. Caused by packing leak which reduced resistance of the sensing element.

 BAUCOM-T. L. Virginia Electric & Power Co. 78/12/11. 2pp. 94204:342.

- --7B12140234 LERM78-040703L-U dn /B1116. Fourtine testing revealed failure of heat tracing circuit 4C Unit#2 Boron Injection Tank Top recirculation return Caused by boric acid damage to the heat tracing circuit BAUCOM.T L Virginia Electric & Power Co 7B/12/ll 2pp 94204:343
- 7812200204 Forwards LER #78-034/01X-1 BTALLINGS: C M Virginia Electric & Power Co. 78/12/13. 1p 94182 274.
- ---7812200207 LER W78-034/01X-1 on 781101 noted that 17 spare process piping penetrations on Unit W1 & 23 on Unit W2 were not capped in Auxiliary Bldg Caused by Failure to properly complete capping at end of constr.

 BAUCOM.T L Virginia Electric & Power Co. 78/12/13 3pp. 94182:275
- 7812270270 Forwards LER#70-041/03L-0. BTALLINOS,C M Virginia Electric & Power Co 78/12/20 ip. 94272-039
- --7812270281 LERM78-041/031 on 781201 feilure of heat tracing circuit 5a (panel 10)Unit#2 Blender to charging pump suction due to water damage of Heat Tracing Circuit Heat tracing tape replaced.

 BAUCOM, T L. Virginia Electric & Power Co. 78/12/18. 2pp. 94232.040.

T. Hearing transcripts on non-entitrust matters

- 7811100051 Transcript of 781028 subcomm meeting in Heehington DC resubj facil steam generator repair prog & whether ACR8 should review the prog. CARBON.M. MCRELLER, D., ETHERINGTON.H ACR8 Advisory Committee on Reactor Sefeguards. 78/10/28. 191pp. 94175.245.
- DOCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT I
- 7811140143 Forwards responses to 780913 &19 NRC ltrs re addl info on fire protec prog equip.
 MAYER.L D. Northern States Power Co. 78/11/08. 10pp. 94383:250.
- 7811290076 Summarizes progress of Fire Protec Review W/encl request for add1 info. staff positions. & evals. Requests meeting w/licenses 1 weak after receipt of responses to latest staff positions.

 LAIN/81.0. Plant Systems Branch (Pre 791030). 78/11/16. 27pp. 94192.182
- 7811290365 Requests add1 info re fire protec prog & forwards NRC staff proposal & recommendations. Areas needing info include: equip req for achieving hot shutdown & fire brigade training. SCHMENCER, A. Operating Reactors Brench I (Pre 790625). 78/11/21. 28pp. 94180:001.

I. Financial information

- 7Bi0300136 Forwards 1977 Annuel Rept & schedule showing 1977 actual Cash Flow to comply with Reg Quide 9.4. Net income by dividends declared instead of dividends paid has been reduced to get retained earnings figure.
 CARLBON.L.R. Northern Btates Power Co. 78/10/23 2pp. 94034:143.
- P. Operating license stage documents & correspondence
- 7810170220 Outlines schedules for correction of Zirconium-Water reaction inconsistency & dev of Upper Plenum Injection model & plant specific calculations. Tentative completion date is April 1979.

 MAYER, L. O. Northern States Power Co. 78/10/12. 2pp. 94236:163
- 7810300100 Notice of 781026 meeting w/ util to discuss bases for reactor coolant Tech spec in 780907 NRC ltr to util. GROTENHUIS.M. Operating Reactors Branch 1 (Pre 790625). 78/10/12. 2pp. 94035:066.
- 7810300237 Evaluation of Overall Asymmetric LDCA Loads Notifies of decision to discontinue participation in utility task group's activities. Subj. util's plan is practical because of relatively recent design of resector coolant sys piping.
 MAYER.L.D. Northern States Power Co. 78/10/25, 4p. 94034:034.

- SCHMENCER, A Operating Reactors Branch 1 (Pre 790623) 78/11/01. IBpp 94049.037.
- --7811170265 GER for Amende#26 & 32 to subj facil oper lic.Concludes that Tech Spec changes related to heatup rate-reactor vessel pressure-temp oper limits. & part length rods does not involve a major hazards consideration.

 GCHMENCER.A. Operating Reactors Brench 1 (Pre 790625). 78/11/01. 5pp. 94049.055.
- --7B]117026B Notice of leauence of Amend#32 & 26 to subj fecil oper lic BCHMENCER, A Operating Reactors Branch 1 (Pre 790625). 7B/11/01. 2pp. 94049:060.
- 7811130338 Confirms upcoming 781116 meeting to discuss NRC's reg prog for protecting pub health & sefety. A tentative meeting agenda is enclosed KEPPLER. J. G. Region 3. Chicago. Defice of the Director. 78/11/02. 3pp. 94007.305
- 7811140022 Confirms upcoming 781116 meeting to discuss NRC's reg program for protecting pub health & safety, A tentative meeting agenda is enclosed.

 KEPPLER.J. Q. Region 3. Chicago. Office of the Director. 78/11/02.

 2pp. 94419:024.
- 78iii60i9i Confirms talephone plans to meet & discuss pub health & safety protec grog as it relates to subj facil Tentative agenda for 78iii6 meeting encl KEPPLER.J G Region 3. Chicago. Office of the Director. 78/11/02. 3pp. 94i36:059.
- 78[1150115 Requests lic amend no later than 78:215 rs Deletion of Reactor Trip on Turbine Trip Below 50% pur & encl requests for Tech Spec changes & safety evaluation supporting changes.

 MAYER.L.D. Northern States Power Co. 78/11/03 34pp. 94113:340.
- 78iii30i47 Lic Amend request proposing change to reactor trip on turbine trip setpoint. Rev setpoint is justified on basis of NRC approved transient analysis methods employed by Westinghouse Corp.

 a License Fee Management Branch. 78/11/03. 1p. 94272:360.
- 7811130157 Notifies applicant of 781128 NRC-sponsored seminer re Model Radiological Effluent Tach Speca for Nuc Pur Plants. Encl w/Seminer Info Sheet(to be completed & returned by 781117) & Proposed Agenda.

 KEPPLER, J. O. Region 3, Chicago, Office of the Director. 78/11/07.

 App. 03593:293.
- 7811210452 Confirms plans for 781116 meeting concerning reg prog for protec of pub health & safety re subj facil. Tentative agenda encl.
 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 78/11/08.
 399. 94480:327.
- 7812010083 Confirms telephone discussion on 781107 re 781116 meeting for local pub officials in vicinity of subj facil. Forwards tentative agends.
 KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 78/11/08.
 3pp. 94417:137.
- 7811280403 Notice of Proposed Issuance of Amend to Facil Oper Lic #OPR-42 & DPR-60, rev Tech Bpec re use of Exxon fuel in Cycles 5 thru 8. BCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/09. 4pp. 74397-317.
- 7811290010 Forwards "Notice of Proposed Issuance of Amendments to Fecil Oper Lic." in response to 780708 amend appl re refueling of facil WExron Nuc Co Fuel for oper Cycles 5 thru B at each unit W/enci AND: 7811280403.

 BCHMENCER.A. Operating Reactore Branch 1 (Pre 790625). 78/11/09.
 29p. 94179:112.
- 78:2180050 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out math. W/encl Registration Form & List of Locations. MILLER.J.R. Assistant Director for Site & Bafeguards (Pre 79:1030), 78/:11/15. 5pp. 94:133:070.

- 7811280279 Request for amend to oper lic#DPR-42 & DPR-60 to change Tech Specs re secondary coolant chemistry monitoring requirements Incl safety evel & minimum frequencies for sampling tests. Hycheck for \$4,400. MAYER.L D. Northern States Power Co. 78/15/22. 5pp. 94395: 222.
- 7812150061 Discusses possible dangers of LDCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wiencl ANO: 7812080207

 8CH-ENCER A Operating Reactors Branch 1 (Pre 790625). 78/11/20 609. 94210:122
- 7912060141 Forwards Environ Event Rept 78-11 on Cooling Towar Oper for Nov 1978. Slightly elevated blowdown flow req for 3 days, during month to accomodate cooling sys preventative maint work.

 HARD.E.C. Northern States Power Co. 78/12/01. ip 94372:251.
- 7812280017 Emphasizes importance of sumbitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result DAVIB.J.O. Office of Inspection & Enforcement, Office of the Director. 78/12/06 2pp. 94131:034.
- 7812130215 Requests util help w/vital area analysis re sub; Pacil. Informs of site visit on 790109-11 by Los Alamos Scien Lab representatives SCHENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/12/08. 2pp. 94306:085.
- 7812190154 Bummary of 781026 meeting to discuss tech specs for secondary water chem.reactor coolant activity & secondary coolant activity.

 ORDTENHUS.M. Operating Reactors Branch I (Pre 790625). 78/12/12 Spp. 94340:150.
- 7812290236 Forwards request for add1 info re Topical Rept XN-NF-78-30 in order to complete review of reload conditions. Req info should be submitted w/in 45 days.

 1PPDLITO, T.A. Operating Reactors Branch 3 (Pre 790623). 78/12/19.

 6pp. 94191: 232.
- O. Inspection reports. IE Bulletine & correspondence
- 7810110199 Ack receipt of 780918 ltr informing NRC of steps taken to correct violations noted in 780829 NRC ltr. FIORELLI, O. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/10/04. 1p. 94068.336.
- 7810230338 Forwards IE Circular#78-17. (See ANC.7810230221.Docket 50-413.781013)
 KEPPLER, J. C. Region 3: Chicego: Office of the Director. 78/10/13
 19. 94147:041.
- 7811130054 Forwards IE Circular 78-18.

 KEPPLER.J.G. Region 3, Chicago, Office of the Director. 78/11/06.

 1p. 74112-183.
- 7812200091 Forwards IE Inspec Repts#30-282/78-12 & #50-305/78-13 on 780903-0B, 11-14,20-92 & 25-29 & Notice of Violation FIDRELLIQ. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/11/09. 2pp. 94156:335.
- --7812200095 Notice of Violation from inspec on 780905-08,11-14,20-22 & 25-29.

 * Region 3, Chicago, Office of the Director 78/11/09. 1p 94154:337.
- --7812200099 IE Inspec Repts#50-282/78-12 & #50-306/78-13 on 780905-08, 11-14, 20-22 & 25-29 during which 1 item of noncompliance was noted: feilure to follow an implementing procedure for approved GA prog.
 FRIERABEND.C.D., WARNICK, R.F. Region 3, Chicago, Office of the Director. 78/11/06. 5pp. 94136:338.

- --7812210054 IE Inspec Repts#50-282/78-14 & #50-306/78-15 on 781016-20 during which 1 item of noncompliance was noted an employee was not wearing proper protective equipment. RIDEN.H D. LITTLE.H S. Region 3. Chicago. Reactor Operations Nuclear Bupport Grench. 78/11/14 4pp 94269.338
- 7812050278 Forwards IE Bulletin#78-12A.suppl to IE Bulletin 78-12. W/encl A-D: 7811300055. KEPPLER.J.O. Region 3. Chicago, Office of the Director 78/11/24. lp. 94202 165.
- 7812210036 Responds to 781107 NRC itr re-violations noted in Inspec Repts#30-282/78-12 & #50-306/78-13 Corrective actions Design Charge Index Form(A)PINQP#340 rev to include of completion of installation MACHTER: L. J. Northern States Power Co. 78/11/30 Ip. 94267 362
- 7812270028 Ack receipt of 781130 ltr informing NRC of steps taken to correct violations noted in 781109 NRC ltr. FIDRELLI, G. Region 3: Chicago. Reactor Operations Nuclear Support Branch. 78712714 lp. 94159-242.
- 78:1220062 Forwards 16 Dulletin 78-14.
 KEPPLER.J.G. Region 3. Chicago: Office of the Director. 78/12/19.
 1P. 03554:350
- R. Periodic operating reports & related correspondence
- 7810120029 Forwards Monthly Oper Rept for Sept 1978.
 MAYER, L. O. Northern States Power Co. 78/10/09. 1p. 94421:174.
- --78:0120031 Monthly Oper Rept For Sept 1978. HUNBTAD, A. A. Northern States Power Co. 78/09/30. 4pp. 94421:175.
- --7810120033 Monthly Open Rept for Sept 1978 HUNSTAD, A. A. Northern States Power Co. 78/09/30 App. 94081:305.
- 7811140115 Forwards Monthly Open Rept for Oct 1978. HAYER.L. O Northern States Fower Co. 78/11/09. 1g. 94425:159
- --7811140117 Monthly Oper Rept for Oct 1978. HUNSTAD.A.A. Northern States Power Co. 78/11/01. Bpp 94425:1.69
- 7812120071 Forwards Monthly Oper Rept for Nov 1978.
 MAYER.L.O. Northern States Fower Co. 78/12/08. ip. 94274:195.
- --7812120094 Monthly Open Rept for Nov 1978 HUNBTAD, A. A. Northern States Power Co. 78/12/01. Bpp. 94274:196.
- 8 Reportable occurrences. LERs & related correspondence
- 7810180012 Forwards LER#78-018/017-0.
 MAYER, L. O. Northern States Power Co. 78/09/26, 1p. 94422:014.
- --7B10180013 LERB78-018/01T-0 on 780912 Lightning strike on transmission line caused breaker 6H5 to open resulting in loss of 2 of the 3 sources of offsite pur Design change in transformer protect relaying is being pursued. HUNSTAD. A.A. Northern States Power Co. 78/09/26 ip. 94422:015.
- 78:0170224 Environ Event Rept 78-09 re open of plant circulating water sus in partial recycle made for Bept Except for 780921, excess bloudown flow was needed. For the month, average daily blowdown flow rate was about 480cfs.

 WARD, E. C. Northern Btates Power Co. 78/10/02. 1p. 94236:166.
- 78:1070215 Environ Event Rept 78-10 covering open of Plant circulating water sys in partial recycle mode w/daily everage blowdown flow in excess of 130 cfs.

 WARD.E.C. Northern Status Power Co. 78/11/01, ip. 94039:122.
- 7811070247 Forwards LERM78-020/03L-0.
 MAYER: L. D. Northern States Pawer Co. 78/11/01. 1p. 94039: 203.

- --7812260209 LERW78-023/03L-0 on 781130 during pur oper & relay test at refueling, Safeguards Bus 14 inadvertently was locked out of svc for about 2 minutes, caused by appl of elec jumper w/o groper review & approval.

 HUNSTAD-A A Northern States Power Co 78/12/20 Ip. 94160.174
- DOCKET 50-284 1DAHD STATE UNIV. RESEARCH REACTOR
 P. Operating license stage documents & correspondence
- 7811080035 Forwards "Notice of Proposed Issuance of Amend to Facil Lice for AQN-201 res reactor. Amend appl of 780810 requested increase of maximum pur lavel from 100 MW to 3M. REID.R. N. Operating Reactors Branch 4 (Pre 790625) 78/10/10 2pp. 94398:106
- --781108003B Notice of Proposed Issuance of Amend to Facil Oper LiceR-11on 781010 REID.R H. Operating Reactors Branch 4 (Pre 790625) 78/10/10 App. 94398:108
- 7811130330 Finds facil Tech Spec not IAH current practice Requests recipient to Mpd AGN-201 TS & resubmit ABAP H/encl Tech Spec.
 REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/10/24, 53pp. 94087 156.
- --7811130333 Proposed "Standard for Admin Controls for Res Reactors."

 American Nuclear Society, 78/01/31, 15pp. 94087:211.
- 7812070202 Request an amend to 780810 ltr to incorporate Tech Specs. Amend forwarded 781024 per NRC request RAMEEY.O.F. Idaho State Univ. 78/11/21. ip. 94375:101.
- --7812070204 Tech Specs of mods to ANSI N378-1974 & Reg Guide 2.2 guidence Tech Specs incl definitions safety systoperation operation design features & admin contols. % Idaho State Univ. 78/11/15. 29pp. 94375:102.
- DOCKET 50-285 FDRT CALHDUN STATION, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 7B10230197 NRC of controller has been given such to refund Class II amend fee of \$1.200 which was sent w/7B0713 appl. Waiver of fee for fire protec amend deemed appropriate.
 MILLER, W. D. License Fee Management Branch. 78/10/10. 1p.
- 7810250079 Informs NRC of criteria for installation & testing of fire detectors in safety related portions of facil. Air flow patterns will be determined combustibles will be verified, struc considerations will be made.

 8HORT, T.E. Omaha Public Power District. 78/10/18. 2pp.
- 7810250101 Info re penetration seals is provided. Penetration seal ausuitilizing silicone foam.silicone elastomers to other related matte is currently being installed at sub; facil. Guide specs prepared by Chemtrol Corp on genetration seals encl. BHORT, T. E. Omahe Public Power District. 78/10/18. 92pp. 94367:095.
- 7812030193 Submits rept pursuant to Tech Specs 2.19.4.e(ii) \$ 5.9.3.i re 781016 removal from svc of Elec Fire Pump FP-1A for "A" cell suction screening maint & circulating water pump maint. Fire protect prog now fully operational.

 SHORTITE Omaha Public Power District. 78/11/14. 2pp. 94317:272.
- H. General correspondence
- 7811280280 Requeste all future correspondence re subj facil be addressed to: TE Short. Assistant General Manager. Omaha Public Pur District. 1623 Harney Street. Omaha. Nebraske 68102. SHORT, T. E. Omaha Public Power District. 78/11/20. ip. 94395:227.

7810130151 Informs of planned action to support lit for Gytle 5 open. Will supply documentation describing mech. thermal & nut characteristics of the fuel & will describe fuel design Also plans to apply for increased plant pur level to 1500 SHORT.TE Omaha Public Power District 78/10/04 2pp 94003.036

- 7811290390 Informs NRC that OPPD has been unable to procure a proper temp detector sys, but will relocate radiat monitor RN-059 to compensate Gives reasons RM-0568 should be left as is, u/o replacement or mod. SHORT. T E Omaha Public Power District 78/10/16 2pp. 94181 175
- 7810250060 Forwards Appl for Amend of Oper Lic to permit test of shock suppressors during oper 6 LeBourf. Lemb. Leiby & MacRae. 78/10/24 2pp
- ---7810250063 Appl for amend to oper lic DPR-40.changing Tech Specs to parmit test of shock suppressors during oper SHDRT.T.E. Omaha Public Power District 78/10/24 App
- 7810300378 Notifies that oft of controller has been auth to refund Class II amend fee for subj facilisent W/ appl dtd. MILLER,W O. License Fee Management Branch 78/10/24. 1p. 94197:358.
- 7811050079 Requests w/drawel of 771019 Appl for Amend for Operating Lic of subj facil The Cycle 4 operation has ended & peaking in fuel pins adjacent to flooded guide tubes was considered in Cycle 5 Core Reload Appl.

 SHORT.T.E. Omaha Public Power District 78/10/29. 1p. 94424 027
- 7811060099 Requests w/drawal of Request for Exemption Filed by applicant. Omaha Pub Pur District on 780714 Request is no longer necessary since recent amend to 10CFR21 Cert of svc enc.
 - LeBoruf, Lamb, Leiby & MacRae 70/10/30 2pp 94424:294.
- 7811070099 Forwards responses to Pirst round of questions re subj facil Cycle 5 Reload Appl dtd 780801 from Comm on 781009 SHDRT.T.E. Dmaha Public Power District 78/10/31 3pp. 94038:288.
- 7811090180 Forwards responses to second round questions re Cycle 5 Reload Appl of subj facil. BHORT.T.E. Omeha Public Power District 78/11/07. 10pp 94038:197.
- 7811140197 Forwards responses to questions posed in NRC ltr of 770919 Responses qualitatively describe mods to be performed by DPPD to ensure that long term core cooling can be performed w/out boron precipitation difficulties SHORT.7.E. Omeha Public Power District 78/11/08. 9pp. 94384:313
- 7811150132 Forwards addl fee for amend to provide for Cycle 5 open of facility after core reload. SHORT.T.E. Omaha Public Power District. 78/11/09. 2pp. 94272:265-
- 7811170193 Forwards add1 justification for OPPD request for amend of Facil Oper Lic for subj plant. Also forwards complete set of proposed Tech Specs reflecting past amends.
 SHORT.T.E. Dmaha Public Power District. 78/11/09. 83pp. 94047:270
- 7811240087 Ack receipt of 781083 appl for amend to operating lit to permit testing of shock suppressors. Because requested action is a Class 3 action, an add fee of 82.800 should be sent in addition to the \$1.200 already received MILLER, W.O. License Fee Hanagement Branch. 78/11/13. 1p. 94458:074.
- 7812190051 Forwards Rev#1 "Praft Radiological Effluent Tech Bpecs" for PWR's(NUREC-0473) & "Preparation of Radiological Effluent Tech Bpecs for Nuc Pur Plants" (NUREC-0133). GRITEBLB K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94215:057.
- 7812040161 Forwards responses to 780803 staff round 3 questions refacil Cycle 5 reload submittal.
 SHORT.T.E. Omaka Public Power District. 78/11/27. 7pp 94436:135.
- 7812180072 Forwards Amend#41 to Facil Oper Lic#DPR-40, changing Tech Bost for embrgency pur sye. REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/11/27. 2pp 94131:366

--7812180081 Safety Eval supporting Amend#41 to Facil Oper Lic#DPR-40 Finds hazards will not increase significantly.
* Office of Nuclear Reactor Regulation. Director 78/11/27 hps

1100 74131 262

94131-273

- --7B12180083 Notice of Issuance of Amend#41 to Facil L(c#DPR-40. REID-R.W. Operating Reactors Branch 4 (Pra 790625) 70/11/27 2pp. 94131 279.
- 7812150076 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Myenci AND. 7812080207

 REID.R W Decrating Reactors Branch 4 (Pre 790625). 78/11/29 bp

REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/29 bpp 94210:352.

- 7812180376 Issues Amend 42 to Facil Operating Lic#PIR-40 incorp site security plan info effective 790223 Forwards Amend 42 & Notice of Issuence.
 REID.R H. Operating Reactors Branch 4 (Pre 790623), 78/11/30 3ps
- --7812180380 Amend 42 to Fecil Operating LiceDPR-40 re-physical socuring plan Becomes effective 790223.
 REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/30.
 200 94358 209.
- --7812180390 Notice of Issuance of Oper LiceDPR-40 Amend 42 adding lic condition to incl Comm approved physical security plan. REID.R.W. Operating Reactors Brench 4 (Pre 770625). 78/11/33 2pp. 94398 211
- 7812130107 Forwards Amend#43 to Facil Oper LicMDPR-40. REID.R.W Operating Reactors Branch 4 (Pre 790629) 78/12/05. 2pp 94212:089.
- ---7812150114 Amend#43 to Facil Oper LicMDR-40.chenging Tech Spec IAM Gule 5 reload analysis & deleting Tech Specs permitting partial insertion of Control Element Assemblies REID.R.W. Operating Reactors Branch 4 (Pre 770625). 78/12/05. 255p. 94212:091.
- --7812150117 Safety Eval supporting Amend#43 to Facil Oper Lic#OPR-40. Concludes public will not be endangered + Office of Nuclear Reactor Regulation, Director 78/12/05. 19pp. 94212:116
- --7812150119 Notice of Issuance of Amend#43 to Lic#DPR-40. REID,R. W. Operating Reactors Branch 4 (Pre 790625) 78/12/05. 200. 94212-135.
- 7812280098 Emphasizes importance of submitting acturate & complete in to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS. J Q. Dffice of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 03555:315
- 7812260203 Responds to 781113 itr & encloses \$2800 Check covering add amend fee for application for amend dtd 781023. Applicant teeks permit to test shock suppressors during open of subjecti.
 8HORT.T.E. Omahe Public Power District. 78/12/12 ip. 94160.138
- 7812290176 Provides info re insvc inspec & test of check valves 91-17 & 81-176 in containment spray sys. Valves will be added to inspec plan under Category C. Requests exemption from stroking requirements, since vessel must be sprayed down.

 BHORT.T.E. Dmahe Public Power District. 78/13/22 4pp. 94190 32
- G. Inspection reports, IE Bulletins & correspondence
- 7811030034 Forwards IE Inspec Rept#50-285/78-11 on 780821-25 during which no item of ngncompliance was noted MADEEN.0.L. Region 4. Dallas. Reactor Operations Nuclear Support Branch. 7g/09/11. 2pp. 02720.341.
- ---7811030036 IE Inspec Rept#50-283/78-11 on 780821-25 during which no item of noncompliance was noted Major dreas inspected included procurement, prep for refueling plant oper. safety injection sys reset proc & elec equip. JCHN80N. W. D. Region 4, Dallas, Reactor Operations Nuclear Suppor Branch. BOYTER, N. C., MADSEN, O. L. Region 4, Dallas, Reactor Construction & Engineering Support Branch. 78/09/07. 7pp. 02720.343.

- 7810110219 Ack receipt of 780918 ltm informing NRC of steps taken to correct violations noted during inspec#30-285/78-10.
 MADSEN/G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 78/09/27. ip. 94062-164
- --7810110223 Responds to 780830 ARC ltm re violation noted in Inspec Rept #50-285/78-10. Corrective actions: integrity of wall strengthened by covering transom u/metal grating. Investigation of similar areas performed SHCRT.T.E. Chake Public Power District. 78/09/18. 2pp. 94062:165
- 7610160215 Forwards IE BulletinM78-12 (8ss ANO:7810040253)
 BEVFRIT.K. V Region 4. Dallas, Office of the Director. 78/09/29.
 1p. 94005.317.
- 7811220119 Forwards IE Circuler#78-18, "UL Fire Test," W/encl AND:7611150002. 8EYFRIT.K V. Region 4. Delies, Office of the Director. 78/11/06 1p. 94074-194.
- 7811280058 Forwards 1E Inspec Rept#50-285/78-12 on 780917-20 & Notice of Violation MADEEN-0.L. Region 4- Dalles, Reactor Operations Nuclear Bupport Branch. 78/10/12 2pp. 94013 289.
- --7811280060 Notice of Violation from inspec on 780917-20 • Region 4, Dallas, Office of the Director. 78/10/12 ip. 94013:290.
- --7811280052 IE Inspec Rept#50-285/78-12 on 780917-20 during which 2 items of noncompilance were noted: failure to follow procedures re-records audits & failure to follow tech speca re-personnel qual audits. Uninson, W.D., BOYTER, N.C., MADSEN, O.L. Region 4, Dellas, Reactor Operations Nuclear Bupport Branch. 78/10/12, 7pp. 94013:291.
- 7810230278 Forwards IE Circular#78-17. (Bee AND: 7810230221, Docket 80-133/781013)
 BEYFRIT, K. V. Region 4, Dallas, Office of the Director. 78/10/13. 1p. 94179: 355.
- 7812060348 Forwards IE Inspec Rept#50-285/78-13 on 781010-13 & Notice of Violation.
 MADEEN, Q.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch, 78/10/31, 2pp. 94382:264.
- --7818060349 Notice of Violation from inspec on 781010-13. • Region 4. Dallas Office of the Director. 78/10/31. ip. 94382:266.
- --7812060351 IE Inspec Repts#90-285/78-13 on 781010-13 during which I item of noncompliance was noted: failure to adhere to plant procedures in response to Tech Spec & Dealgn changes. JCHNBON, H. D. Region 4. Dallas. Office of the Director. 78/10/31. App. 940802:267.
- 7811130184 Response to requests for info rm insvc testing & inspec of check valves in the safety injection recirculation lines at subj facil.

 8HORT-T.E. Dambe Public Power District. 78/11/03. 5pp. 03553:320.
- 78i 1280257 Discovered that certain hydrotest requirement for Class 2 piping in ASPE XI. Burmer of 1975 Addenda le impractical w/in meaning of 10CFR50.35(a). Thus, rev to "Inseve Inspec Prog Plan for the 1976-1980 period" for subj facil is ancl. BHORT: T.E. Onaha Public Power District, 78/11/20. 3pp. 02725:348.
- 7812050044 Ack receipt of 781106 ltr informing NRC of steps taken to correct violations noted during inspec#30-283/78-12.

 MADSEN.O.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 78/11/21. ip. 94234:035.
- ~~781206004B Responds to 781112 NRC ltr rs violations noted in Inspec Rept%50-285/78-12.Corrective actions:approved sched of Internal & External Audite will be published at beginning of each year. BHDRT.T.E. Omaha Public Power District. 78/11/06. 3pp. 94234-057.
- 7812060264 Forwards IE Bullstin#78-12A. suppl to IE Bullstin#78-12. w/spc1 AND.7811300055. BEYFRIT.K. V. Region 4. Dalles. D#fice of the Director. 78/11/24. lp. 94371:348.
- 7812060278 Ack receipt of 781121 ltr informing NRC of steps taken to correct violations noted during Inapac#50-285/78-13. MADEEN O. L. Region 4. Delles. Reactor Operations Nuclear Support Branch. 78/11/27. 1p. 94372:283.

- --7812060282 Responds to 781031 NRC ltr re violation noted in Inspec Re. #50-285/78-13. Corrective actions. all 1977 Fuel Mpt & Hamdling Records were examined in Oct & Nov 1977 & inventories made of fuel assemblies SHORLT.E. Onsha Public Power District. 78/11/21. 3pp. 94372: 284.
- 7812130111 Provides into re inspec of check valves 91-159 & 91-160. Beliavas test for valves is unnecessary & impractical but during next refueling outage a flow test or removal & test will be performed. BHORT.T.E. Dmaha Public Power District 78/12/08. 2p. 94294:343.
- R. Periodic operating reports & related correspondence
- 7810110189 Forwards Section IV of "Somi-Annual Rept for Tech Spec 5, 9, 4 & Append B 780101-780630 Inclusive." 8H0R7.T.E. Omaha Public Power District. 78/10/03 ip. 94068:043
- --7810110193 "Semi-Annuel Rept for Tech Spec 5. 9. 4 & Append B. Jan-June 1978."
 - * Omaha Public Power District. 78/10/03. 105pp. 94068:044,
- 7810130125 Forwards Monthly Open Rept for Bept 1978. 8HORT.T.E. Omene Public Power District. 78/10/09. ip. 94003:094.
- --78i0130186 Monthly Oper Rept for Bept 1978. HICKLE.B.J. Omahe Public Power District. 78/10/09. 9pp. 94003-099.
- 7811140107 Forwards Monthly Open Rept for Oct 1978. SHURT.T.E. Omeha Public Power District. 78/11/08. lp. 94425:127.
- --7811140161 Monthly Open Rept for Oct 1978. HICKLE B.J. Omene Public Power District. 78/10/31. Spp. 94425:128.
- 7812130178 Forwards Monthly Open Rept For Nov 1978. 8HORT: T.E. Dmaha Public Power District. 78/12/08. 1p. 94305:344.
- --7812130181 Monthly Open Rept for Nov 1978. HICKLE B.J. Omaha Public Power District. 78/12/08. 14pp. 9430:348.
- 8. Reportable occurrences. LERs & related correspondence
- 7810110113 Forwards LERW78-026/03L-1. ANDEELG:R.L. Omeha Public Power District. 78/09/21. 1p. 74068:149.
- --7810110117 LER#78-026/03L-1 on 780830: "8"chennel RP8 variable dverpur trip reset damand elarm actuated & would not reset. Then, Hi pur & thermal margin/low pressure trip units failed, both due to failure of Davar19-601A, 18volt pur supply. CCNNOLLEY, J. Dmahe Public Power District. 78/09/15. 3pp. 94066: 190.
- 7810110100 Forwards LER#78-028/03L-0. ANDREWS R. L. Omaha Public Power District. 78/09/29. 1p. 94066:340.
- --7810110103 LER#78-028/03L-0 on 780831: failure of Tri-: weather towar 100 mater Dalta-T sensor sys to rapt stability class info. Calibrations revised to ensure instruments detect subsequent sensor sys failures.

 OTTERBER80, J., PETERBON, G. Omaha Public Power District. 78/09/27. 3pp. 74066:341.
- 7810100010 Forwards LER#78-030/01T-0. ANDREMB.R. L. Omeha Public Power District. 78/10/03. ip. 74418:1&6.
- --7810100014 LER#78-030/01T-0 on 781003:During oper check on auxiliary steam driven feed pump, the steam inlet valve YCV-1045 did not open due to closed air supply.

 GATES, G. Omaha Public Power District. 78/10/03. 4pp. 94415:167.
- 7810110112 Forwards LER#78-029/03L=0.
 ANDREWS, R. L. Dmaha Public Power District. 78/10/06. 1p. 94053;019.
- ~-7810110114 LERG78-029/03L-0 on 780908: Inseventent radioactive ges release to atmosphere caused by leakage past check valve CH-284. HQ-100 & relief valve HQ-105. Valves will be inspected & replaced or repaired during next refusing outegs.

 9ATES, Q. Dmaha Public Power District. 78/10/06. 4pp. 94053:080

180159 Forwards LER#78-031/03L-0. DRENS.R.L Omaha Public Power District. 78/10/11 1p. 317: 017.

NOT80162 LER#78-031/03L-0 on 780918 during normal steady state puroper the hot leg temp indicator for D'channel went to full scale, due to unknown cause.
CONNOLLER, J. PETERBON, O. Omeha Public Power District, 78/10/11.
3pp. 94317:018.

060200 Forwards LER#78-032/03L-0. OREWS.R.L Gmake Public Power District. 78/10/31 1p. 489: 196

11060204 LER#78-032/03L-0 on 781002 during performance of BT-EBF-5. DIVOUZUA LEMPTB-USE/OSL-O on 781002 during performance of 8 timere 81-19 & CH-18 on sequence 82-2 Pailed to time out win prescribed limit due to a stuck oper mechanism. Timere were exercised to Pres mechanism. AMDREMS R. L. Dmaha Public Power District. 78/10/31. 3pp. 94487.197.

210368 Forwards LER#78-033/03L-0. DREMS.R.L. Omaha Public Power District. 78/11/08 Ip 484 129

H1210371 LER#78-033/03L-0 on 781014 Reactor coolant cold leg temp indicator B/122C failed high off scale because of an open circuited Rosemount Model 104VC RTD The RTD will be replaced during present refueling outage.
PETERBON.G., CONNOLLEY.J. Omene Public Power District. 78/11/02. 3pp. 94485:130.

010238 Forwards LERW78-034/03L-0. DREW8.A.L. Omaha Public Power District. 78/11/25. ip. 407: 333

012010240 LER#78-034/03L-0 on 781026:repeated tripping of Stack particulate process monitor. Caused by trip set in accordance which Bpecs Table 2-1 at 9, 6x10-2; rather than more conservative release rates 2x10-3.

KUSEN.L. T. Omeha Public Power District. 78/11/25. 2pp. 94409-744 94409: 354.

2050173 Forwards LERW78-036/03L-0. WREWS.R.L. Omaha Public Power District. 78/11/30. 1p. 335: 126

312050179 LER#78-036/03L-0 on 781101:auxiliary feedwater check valve PM-164 found to be oriented in wrong position. Caused by missing value disk plate which was subsequently located & ratovered. KUSEK, L. T. Omaha Public Power District. 78/11/27. App. 94335: 129.

2200264 Forwards LER#78-037/03L-0. DREWS.R.L. Omaha Public Power District. 78/12/08. 1p. 1207: 103.

312200272 LERR#78-037/03L-0 on 781116: during refueling, all Limitorque Valves were inspec for proper staking of the lock nut on the motor operator. 30 of 65 valves exhibited unstaked lock nuts. Lock nuts uper staked IAN manufacturer's instruc. JONES. D., ANOREWS, R. Omsha Public Power District. 78/12/05. 9pp. 94207: 104,

2200267 LER#78-038/DIT-0 on 781127: Diesel generator#2 failed to auto lose onto the busibreaker mode switch contracts 27-27c siled to make contact. Caused by contact failure. DRE.M., PETERBON.O. Omeha Public Power District. 78/12/08. 3pp. 1207: 114

2200227 Forwards LER#78-035/03L-0. NDREWS, R. L. Omaha Public Power District. 78/12/12. 1p. 4162:313.

B12200231 LERATE-035/03L-0 on 781113: during test of Ventilation Isolation Actuation Bignal lockout 8881/VIA8 did not trip. Cause unidentified, since relay retested & found to be operating normally, Relays will continue to be tested. CORE.M., PETERSON.O. Omaha Public Power District. 78/12/12. 3p. 94162;314.

2270213 Forwards LER#78-039/03L-0. NDREHB,R.L. Omaha Public Power District. 78/12/22. 1p.

-7812270217 LEA#78-039/03L-0 on 781122 noted that level transmiter for "C" channel (C/LT-901) for ateam generator RC-2A level Instrumentation not w/in specs Caused by caller oright of GE/MAC Hodel 355 transmitter CONNOLLEY, J., PETERBON, G. Onaha Public Power District. 78/12/20 3pp 94168:097

7812270219 Forwards LER#78-031/03X-1 ANDRENS.R L. Omaha Public Power District 78/12/22 1p.

--7812270224 LER678-031/03x-1 on 780918 during refueling outage. "D" channel hot leg temp indication was investigated to determine cause of 780918 failure. Failure caused by Rosemount Model 104VC RTD having water in the pothead CONNOLLEY. J. PETERSON. G. Omaha Public Power District. 78/12/21. 38p. 94015:359.

7812270258 Forwards LERB78-043/03L-0
ANDREWB.R. L. Omena Public Power District. 78/12/22. 1p. 94168: 063

--7812270262 LER878-043/03L-0 on 781204 during inspec of discharged fuel assemblies, a single fuel pin was observed to have failed, assoc w/menufacture & exposure of present day nuc fuel.

DU90ER.L.J. Omaha Public Power District 78/12/22 3pp
94168-064.

7812270332 Forwards LERW78-044/03t-0.
ANDREWS, R. L. | Omaha Public Power District | 78/12/22 | 1p. 94232: 028

--7812270333 LERM78-044/03L-0 on 781214 during 1978 refueling outage. certain surveillance tests req by Tech Spece could not be performed bacases of shutdown condition. Facil Lit Change #77-11 submitted to NRC on 781109 to delete requirements. KUSEK.L.T. Oneha Public Power District. 78/12/19. 7pp. 94232:029

7812290225 Forward: LER#78-042/03L-0. ANDREWB, R. L. Omaha Public Power District. 78/12/22 ip. 94191: 197

--7812290228 LERW78-042/03L-0 on 781124: during shutdown cooling interlock test noted that PC-109D was not operating. Caused by valve closing relay 74-347/J48 not being wired to PC-1098 inadvertently disconnected in 1977.

MEMAFFEY, R. PETERBON, O. Omaha Public Power District. 78/12/22. 4pp. 94191:198.

7812200265 Forwards LER#78-038/017-0. ANDREWS, R. L. Omaha Public Power District. 78/12/08. 1p. 94207:113

DOCKET 90-286 INDIAN POINT STATION, UNIT 3 F. Becurity, medical, emergency & Pire protection plans

7810260109 Responds to 780929 NRC 1tr requesting addl info on Fire Protec Prog for subj facilit23 oversize drawings & inventory enciri copy drawings recd & sent to Br Chief. Orewings available in Central Files only.

EARLY.P. J. Power Authority of the State of New York 78/10/23.

7812270486 Requests addl info on admin controls of fire protec prog by BCHNENCER, A. Operating Reactors Granch 1 (Pre 790625). 78/12/12. 7pp. 94015; 299.

G. Adjudicatory correspondence

7Bi1090198 Forwards recent NRC memos re problems w/pipe support base plate design. Staff will inform Bd of conclusions after study of addl into from licenses. (See AND: 7811020332, 7811020336, & 7811020343.) BMITH, B. H. Office of the Executive Legal Director. 78/10/24. Rpp. 94031:078

H. General correspondence

7812060113 Requests changes in distrib list for subj facil.Replace Trotsen w/Bennett.
EARLY.P. J. Power Authority of the State of New York. 78/10/24 lp. 94332: 199

- 7812190015 Forwards Rev#l "Draft Radiological Effluent Tech Specs" for PWR's(NUREC-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NURS-0100). GRIMES.O.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/19 6pp. 94214 286
- 7812050004 Forwards Licensee Performance Eval Questions for subj facils in response to 771123 request Feels it is possible that dev of statistical methodology for such eval may not justify the effort. Qualitative eval may be as good. Urges 1-year test QRIEN. B. H. Region 1. Philadelphia. Office of the Director. 77/12/13 12pp.
- 7810110085 Responds to 780830 NRC itr u/questions on Diesel Generator Alarm & Control Circuitry, Blesel control switch presently brings up safeguards equip locked open alarm when not in auto position Circuit will be modified further. BERRY, Q T. Power Authority of the Blate of New York 78/09/29. 2pp. 94063.35B.
- 7810110094 In response to 780913 NGC ltr.states that util submitted rev Emergency Core Cooling Bye calculation for subj facil on EARLY, P. J. Power Authority of the State of New York. 78/10/02. 1p. 94065:359.
- 7810110160 Informs that info re lamellar tearing of steam generator & reactor coolant pump supports requested on 770914 & 771027 will be submitted by 781030. EARLY,P.J. Power Authority of the State of New York. 78/10/02.
- 7810300061 Surmary of 781004 mosting to Environ Toch Spec on continuous monitoring of liquid effluent releases. Util was found to be in honcompliance w/ETS 2.4 i.a & remedial action was recommended pending util appeal.W/encl list of attenders. DLSHAN-L Operating Reactors Branch i (Pre 790625). 78/10/12. App. 74034:286.
- 7810230191 Response to 780713 ACR8 1tr to NRC w/Items of Concern re subj facil & to Auth's discussion w/NRC on 780915; discusses items re sys interaction regulatory criteria & backfitting, instrumentation, shutdown & heat removal & eafety update. EARLY.P.J. Power Authority of the State of New York. 78/10/13. 2pp. 94052-275.
- 7810240108 Forwards data specified in Section 401 Cartification for Bept Includes species code list.grass elec output, circulating water temp.river water discharge.chem discharges & daily Pish counts HONTI, W. A. Consolidated Edison Co. of New York, 78/10/13 17pp
- 7810310240 Response to PASN 1tr of 780802; forwards denial of PASN's appl to ortend period of interim oper using the installed once-thru cooling sys at subj fecil.

 DENTON.H.R. Defice of Nuclear Reactor Regulation, Director.
 78/10/13 3pp. 94091:322.
- --7B10310243 Denial of PABN's appl for extension of period of interim open using the installed once-thru cooling eys Denial besed on NRC deference to EPA decision & NRC desire to evaluate that decision before taking action. BALLARO, R. L. Environmental Projects Branch 1. 78/10/13. 3pp. 94091: 325.
- 7811030182 Notice of denial of amend appl for lic#DPR-64, "Appl for an Extension of Period of Interim Oper Using Installed Oncerthrough Cooling Sys & Motion for Expedited Commiscretain 780807". Commust req compliance to EPA sched.

 BALLARD.R.L Environmental Projects Branch 1. 78/10/13. 3pp. 02724: 087.
- 7010300240 Forwards list of projects adddressed to the Hudson River estuary which NRC is conducting or in which it is participating as per lit request of 709001.

 LEMIS B.H. Office of the Executive Legal Director. 78/10/17. Spp. 94034:004
- 7811080078 Responds to 780802 1tr which included \$1,200 for extension of period of interim oper of facil using installed once-thru cooling eys. \$1,200 is being refunded pending legal settlement of request. MILLER, W. D. License Fee Management Branch, 78/10/23, 10. 94271: 137.

- oper & therefore milk sample is unobtainable. Samples of leafy graen vegetables & milk from Shenandoah Farm will be taken. CAHILLIN J. Consolidated Edison Co. of New York. 78/10/30. 2pp.
- 74038: 270.
- 7811070253 Forwards "Cycle 2. Startup Physics Test Rept."
 BAYNE, J. P. Power Authority of the State of New York. 78/10/31. Ip. 9403B:00A
- --7811070256 "Cycle 2.Startup Physics Test Rept". * Power Authority of the State of New York. 78/10/31. 380pp 94038 007
- 7811080110 Forwards Summary Analysis of Periodic Type B & Type C Reactor Containment Bldg Leek Rate Test for subj facil. Leakage during test occurred thru improperly positioned valve on \$13 & 34 Containment Recirculation Fan EARLY.P. J Power Authority of the Blate of New York. 78/11/02. 3pp 94399-149.
- --7811080111 "Reactor Containment Bldg Integrated Loak Test, Summary Tech Rept" Describes summer 1978 Periodic Type "B" & "C" tests at sub; facil Measured leakage of all ays well within tech spec.

 4 Power Authority of the State of New York. 78/11/02. 62pg. 94399: 152.
- 7811080183 Forwards"Appl for Amend to Oper Lic", \$1200 check for Class II fee not received. EARLY.P.J. Power Authority of the State of New York. 78/11/02. Rpp. 9405:103.
- -- 7811080184 "Appl for Amend to Oper Lic". Three attachments incl Sefety Evel Environ Impact Assessment & proposed changes to Environ Tech Space. EARLY, P. J. Powe Bpp. 94405: 105. Power Authority of the State of New York. 78/11/02.
- 7811080123 Responds to 780828 Itr & forwards "Appl for Amend to Operating Lic on Overpressure Protec Sys". Amend is class 11 since it involves single safety issue. EARLY,P.J. Power Authority of the State of New York. 78/11/03. Rpp. 94399:231.
- --7811080127 Appl to amend operating lic+DPR-64 Tech Spec contained in Appendix A.Proposed changes are intended to assure safe oper of Overpressure Protec Bys EARLY.P. J. Power Authority of the State of New York. 78/11/03. 26pp. 94299:233.
- --7811080129 Bafety eval of proposed Overpressure Protec Bys. Proposes to mod Tech Spec Section 3.1 to establish Limiting Conditions for Oper(LCO's) on Oper Components of OPS. Changes will not increase accident probability. EARLY, P. J. Power Authority of the State of New York. 78/11/03. EARLY, P. J. Powe 2pp. 74379: 261.
- 7811210200 Forwards Amende18 to Facil Open LiceOPR-64 for subj facil. Amend consists of changes to Tech Boocs per 771102 appl. Also forwards Bafety Eval & Notice of Issuance. SCHLENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/06. 2pp. 94488:021.
- --7811210205 Amend to Facil Oper Lic#DPR-64. Areas amended incl quadrant pur tilt ratio, heatup & cooldown & chem & volume control BCHHENCER A. Operating Reactors Branch 1 (Pre 790625). 78/11/06 36PP 94488:023.
- --7811210209 Safety Eval supporting Amend#18 to Facil Oper Lic#DPR-64 for subj facil Changes incl reduction in maximum pressurizer heatup rate & change in definition of quadrant pur tilt ratio Office of Nuclear Reactor Regulation, Director. 78/11/06. 309. 94498: 034.
- --7811210213 Notice of Issuance of Amend#18 to Facil Oper Lic#DPR-64 for oper of subj facil Areas changed incl Tech Specs re pressurizer heatup & choldown rates & repting procedures re steam generator tube insvc inspecs. BOWENCER,A. Operating Reactors Branch ! (Pre 790625). 78/11/06. 37pp. 94488: 037.
- 7811290208 Responds to 781106 request for info concerning licenses reg performance eval for Region i plants by NRC. Provides details. ORIEM.B.H. Region 1. Philadelphia, Office of the Director. 78/11/09. 9pp.

- 7811170160 Forwards data specified in Bection 401 Certification for the month of October, 1978 HONTI-M.A. Consolidated Edison Co. of New York. 78/11/10. 16pp. 94048: 051
- 7811210274 Ack receipt of 781013 ltr responding to request for extension of interim oper of subj facil using the installed once-thru cooling sys Believes hearing would be premature. EARLY.P. J. Power Authority of the State of New York. 78/11/13. 200. 94485 167.
- 7812150098 Natice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73 Requests pre-workshop registration of attendees to facilitate sending out mat] W/ent] Registration Form & List of Locations. HILLER, J. R. Assistant Director for Bite & Befeguerds (Pre 771030). 78/11/10. 5pp 94211:343.
- 7812190048 Forwards Rev#1 "Braft Radiological Effluent Tech Space" for PHR's (NUREO-0473) & "Preparation of Radiological Effluent rem simurated to the control of the
- 7811290182 Forwards rept prepared by Wastinghouse in response to 771004 MRC itr re-fracture toughness & potential for lemellar tearing of steem generator & reactor coolent pump support mati.Rept contains proprietary info.
 EARLY.P. J. Power Authority of the State of New York. 78/11/21. 2pp.
- 7812070200 Notice of seminar on 781208 on new Model Radiological Effluent Tach Space for nuc pur plants Requests advance submission of seminer specific questions. W/encl Seminer Info Sheek-Proposed Agenda & maps.

 ORIER. B.M. Region i. Philadelphia, Office of the Director.
 78/11/21. Spp. 94375:093
- 7812140331 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wienci ANOS 7818080207.

 8CHENCER, A. Operating Reactors Branch 1 (Pre 790623). 78/11/28.6pp. 03357:212.
- 7812070180 Forwards application for amend to OLs.
 IARMAS.P. Consolidated Edison Co. of New York. 78/12/05. ip. IARAKAB.P. 94375: 030.
- --7812070182 Application for amend to OLs. Certificate of Svc encl. CHILL, H. J. Consolidated Edison Co. of New York. 78/12/05. 12pp. 94375: 031
- 7819280076 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NAC of any inaccuracies or enforcement action will result. DAVIS.J. G. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 20p. 03035:31
- 7812050013 Requests views of Regional Directors on Licenses performance eval of subj facils. Forwards questions to be answered by 771209. THORNBURG, H. Division of Reactor Construction Inspection. 77/11/23.
- 7812190182 Notice of 781218 meeting w/util to discuss NUREO-0133. "Preparation of Rediological Effluent Tech Spec Por Nuc Pur Plants" as it applies to subj facil. OLBHAN.L. Operating Reactors Branch 1 (Pre 790625). 78/12/13. 2pp. 94381:207.
- 7812190174 Forwards copies of "Appl for Amend to Oper Lic" which request amends to section 4.1.2a of Environ Tech Spec Requirements for subj facils. Amends would restructure present Aquetic Environ Monitoring Prog. Cert of Buc encl. CAMILL-W. J. Consolidated Edison Co. of New York. 78/12/14. 3pp. 94340-000 94340: 002.
- --7812190180 Appl for amend to Licenses DPR-5, DPR-26 & DPR-64 requesting ray to Environ Tech Specs Rev Tech Specs & Proposed mode are designed to provide a monitoring prog for continuous assessment of Hudeon River fish population. CMTLL, M. J., EARLY, P. J., Consolidated Edison Co. of New York, 78/12/14, 46pp. 94340:005.
- 7812260014 Comments of PABN re closed-cycle cooling conditions Asserts that lic condition should either be eliminated of delayed indefinitely. Cart of Bvc encl.
 TROSTEN, L. M., FIDELL, E. R., ANCARROW, M. R. LeBoeuf, Lemb, Leiby & MacRae. 78/12/15, 18pp. 94021:045.

installed once-thru cooling systemding final determination of permissibility of such systems. EARLY, P J Power Authority of the State of New York 78/08/02.

--/812260014 Forwards appl for extension of period of sinering

- --7812260023 Appl for extension of period of interim oper using install once-thru cooling sys. Appl contains motion for expected relief. Also encl is affidavit of PJ Early of PASN in support of extension Power Authority of the State of New York 78/08/07 58pp 94021 065
- -- 7812280039 Notice of denial of amend appl seeking extension of period of interim oper using installed once-thru cooling sys Denial based on NRC legal reliance on EPA proc & decisions BALLARD, R. L. Environmental Projects Branch 1 78/10/13 Opp. 94021 126
- 7812290170 Repts on Steam Generator Tube Plugging Plant was placed to cold shutdown condition on 781207 as result of tube look in Steam Generator#33 Leaking tube was plugged explosively & secondary side hydrostatic test was performed BAYNE.J.P. Power Authority of the State of New York 78/12/20 2pp 94190 319.
- G. Inspection reports. 1E Bulletins & correspondence
- 7811080244 Forwards IE Inspec Rept#50-286/78-25 on 780815-17 during which no stems of noncompliance were noted BRUNNER.E. J. Region i. Philadelphia. Reactor Operations Nuclear Bupport Branch 78/09/19 2pp. 94405 349
- --7811080248 IE Inspet Rept#50-286/78-25 on 780815-17 during which no them of previous inspec findings oper actions on SIS reset features.CORE II startup preparations. REBELDWBKI.T Region L. Philadelphia. Reactor Operations Nuclear Support Branch. 78/09/18. 7pp 94405-351.
- 781014024; Forwards IE Bullatin#78-12: "Atypical Wold Material in Reactor Pressure Vessel Helds" requesting action win 60 days & list of 1E Bulletins issued in 1978 (See AND 87810040253)

 GRIER, B H. Region 1. Philadelphia, Office of the Director. 78/09/29. 6pp. 94007:007.
- 7810230134 Ack receipt of 780928 itr informing NRC of steps taken to correct violations noted during inspec#30-286/78-22.

 BMITH, O. H. Region 1, Philadelphia, Fuel Fecility & Materials Safety Branch 78/10/12 1p
- --7810250135 Responds to 780906 NRC itr ra violation noted in Inspec R #50-286/78-22. Corrective actions: establishment of inventory list for all health physics instru & control of human espoure to radiat.

 BAYNE, J. P. Power Authority of the State of New York 78/09/20.
- --7810250136 Forwards IE Inspec Rept#50-286/78-22 on 780717-21 & 780801-04 & Notice of Violation. CROCKER.H.H. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. 78/09/06. 2pp.
- --7810250137 Notice of Violation from inspec on 780717-21 & 780801-04. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 78/09/06 2pp.
- --7810230138 IE Inspec Rept#50-286/78-R2 on 780717-21 & 780801-04 duri to radiat protec procedures & failure to control exposure w/in 10CFR20 101 limits. NEELY.D.R., HIGGINS.J.C. Region 1, Philadelphia, Fuel Facility & Materials Sacety Branch. 78/09/06. 1700
- 7811060184 Forwards IE Circular#78-17. (See AND. 7810230221, Docket #50-133,781013.) QRIER/B.H. Region 1, Philadelphia, Office of the Director 78/10/13. ip. 94489:147.
- 7811100120 Ack receipt of 781005 ltr informing NRC of steps taken to errect violations noted during inspec#50-286/78-13 errect violations noted during inspec#50-286/78-13 errector. 78/10/20. ip. 94047:239.
- --7811100129 Responds to 780712 NRC ltr re violation noted in Inspec Rept850-286/78-13 Repts current ltr supersedes 780918 & 780921 ltrs re resolution of items from subj inspec. BAVNE.J.P. Power Authority of the State of New York. 78/10/05.

- --/BlilOdian Hebts Con Edison's corrective actions in response to requests by PABN re violations of ETS
 BAYNE, J P. Power Authority of the State of New York. 78/09/18
- ~-7811100158 Responds to 780712 NRC ltr re violetions noted in Inspec Rept#850-286/78-12 Rept# Con Edition conducts environ monitoring for PABN Corrective actions will be supplied subsequent to rely from Con Edition BAYNE.J P Power Authority of the State of New York 78/08/04. 2pp 94047 201
- --7811100165 Forwards 1E Inspec Rept#50-286/78-13 on 780516-18 & 22-23 & notice of violation CROCKER.H W. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. 78/07/12 Spp. 94046-335
- --7811100172 Notice of Violation from inspec on 780514-18 & 22-23. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch. 78/07/10 3pp 94046-338
- --7811100181 1E Inspec Rept#50-286/78-13 on 780516-18 & 22-23 during which of tems of noncompliance noted failure to submit anomalous measurements rept.failure to approve temp procedure changes in accord w/ETSR & other deficiencies. BRESS. J. STOHR.J.P. Region i. Philadelphia. Fuel Facility & Materials Bafety Granch. 78/07/10. 24pp. 94046.34i.
- 7812010047 Forwards IE Inspec Repts#50-286/78-27 on 780911-13 during which no items of noncompliance were noted. BRUN√ER,E J Region 1. Philadelphia, Reactor Operations Nuclear Bupport Branch 78/10/23 2pp 94416.125
- --7812010062 IE Inspec Rept#50-286/78-27 on 780911-13 during which no tem of noncompliance was noted Major areas inspected incl: response to IE Circular 78-08 "Environ Gualification of Safety Related Elec Equip" REDELOWSKI. 1, KEIMIO.R. Region I, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/20 6pp. 94416:186.
- 7811080082 Ack receipt of 781010 ltr informing NRC of steps taken to GRUNNER.E J. Region i. Philadelphia. Reactor Operations Nuclear Buggort Branch. 78/10/27. ip. 94399.037.
- --7811080086 Responds to 780921 NRC 1tr re violation noted in Inspec Rept #50-286/78-26 Corrective actions: procedures written describing admin of training w/documentation for Maintenance & I & C Dept personnel. BAYNE, J. P. Power Autho Power Authority of the State of New York. 78/10/10. 10. 94399 038
- --7811080090 Forwards IE Inspec Rept#50-286/78-26 on 780822-24 & Notice of Violation. BRUNNER: E.J. Region I: Philadelphia: Reactor Operations Nuclear Support Branch. 78/09/18. 2pp. 94399:039.
- --7811080092 Notice of Violation from inspec on 780822-24.
 BRUNNER,E.J. Region J. Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/18. 1p. 94399:041.
- --7811080097 IE Inspec Rept #50-286/78-26 on 780822-24 during which 1 item of noncompliance was noted: Feilure to establish documented retraining prog for craft & tech personnel. BECKMAN. D. A., RUHLMAN. W. A., KISTER, H. B., Region I, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/07. Bpp. 94399:042
- 7812010345 Forwards licenses performance evaluation for Region 1. No operating reactor in Region 1 considered to have either abnormal or unusual safety concern.
 ORIER: BH. Region 1, Philadelphia, Office of the Director.
 78/11/01. 4pp. 00002:259.
- 7811290158 Forwards IE Circular #78-18, "UL Fire Test. "W/encl AND:
- 7812010033 Ack receipt of 781027 ltr informing NRC of steps taken to correct violations noted during inspec450-284/78-21.

 SMITH.0. H. Region i. Philadelphia. Fuel Facility & Materials Safety Branch. 78/11/09. ip. 94416:055.

actions which have been taken in light of inspec. steps tak to avoid further items of noncompliance & date when compliance will be achieved BMITH.G H Region 1. Philadelphia. Fuel Facility & Materi Bafety Branch 78/10/05 2pp 94416:097.

--7812010081 Request written statement of explanation incl cor-

- --7812010085 Responds to 780816 NRC ltr & Notice of Violation. permissible discharge concentration should be everaged over a one year period in compliance w/ETS section 2 4 1.a. therefore they are not in violation of Tech Specs BAYNE. J. P. Power Authority of the State of New York. 94416 059
- --78:20:0089 Forwards IE Inspec Rept#50-286/78-21 on 7807:2-14 & Notice of Violation. CROCKER.н и Region 1. Philadelphia, Fuel Facility & Mater Bafety Branch 78/08/16 2pp 94416 061.
- --7812010092 Notice of Violation from inspec on 780712-14 & 24 Region 1. Philadelphia. Fuel Facility & Materials Gafet 78/08/14 1p 94416-063
- --7812010096 IE Inspec Rept#50-286/78-21 on 780712-14 & 24-28 which 02 items of noncompliance were noted: failure to calibr liquid radwaste monitor & improper setpoint on liquid radwaste monitor THONUS.L.H. KNAPP.P.J. Region 1, Philadelphia, Fuel Paci Materials Bafety Branch. 78/08/14. bpp. 94416-064
- 7812150198 Forwards IE Bullstin#78-12A, suppl to IE Bullstin#78-W/encl AND 7811300055. ORIER B H Region i, Philadelphia, Office of the Director. 78/11/24. pp. 94212:225
- 7812130168 Forwards "Insvc Inspec NIS-1 Data Rept & Summary" re from summer 1978 refueling outage including a summary rept of the Steam Generator Channel Mead visual & ultrasonic inspec EARLY, P. J. Power Authority of the State of New York. 78/12. 94294 111.
- --7812130171 "Insec Inspec Rept for Summer 1978 Refueling Duta inexc examination of Class 1 piping & components & Class 2 steam generator items & reactor coolant pump flywheels * Power Authority of the State of New York. 78/09/30. 9/94294:112
- 7812260130 Forwards info re insvc inspec on steam generators#3:
 Tubes inspec by sddy current method of exam. Exam incl inspec
 for tube wall degradation on outside surface of tubes &
 denting at tube sheet & tube support plates.
 BAYNE.J.P. Power Authority of the State of New York. 78/12. BOpp 94027 216.
- R. Periodic operating reports & related correspondence
- 7812010206 Forwards corrected copy of Chem Discharges sheet in 401 Cert Rept for Oct 1978.
 MONTI, M.A. Consolidated Edison Co., of New York. 78/11/15. 94409: 265.
- 7810130180 Monthly Oper Rept for Sept 1978.
 TAGLIAMONTE, M. Power Authority of the State of New York. 78 6PP 94003: 039.
- 7810130167 Forwards Monthly Open Rept for Sept 1978.

 BAYNE, J.P. Power Authority of the State of New York. 78/10. 94003:038
- 7810200064 Forwards tabulation of daily record of fish collect: Bept 1978 including breakdown & total weight, CAHILLIH.J. Consolidated Edison Co. of New York, 78/10/13. 94412: 171.
- 7811140106 Monthly Oper Rept for Oct 1978.
 TAQLIAMONTE,M. Power Authority of the State of New York. 71
 6pp. 94425:119
- 7811140104 Forwards Monthly Open Rept for Oct 1978.

 BAYNE, J. P. Power Authority of the State of New York. 78/11.

 94425:118.

- 7811220153 Forwards tabulation of daily record of fish collections for Oct 1978 w/daily species breakdown & total weight CAHILL-H J Consolidated Edison Co. of New York 78/11/16 App 94074-277.
- 7812180152 Forwards data specified in Section 401 Certification for Nov 1978 MONTLIA Commonwealth Edison Co. 78/12/10 17pp. 94366-056
- 7812150237 Forwards Monthly Open Rept for Nov 1978

 8AYNE.J P Power Authority of the State of New York 78/12/11 ip
 94213.161
- --7812150241 Monthly Oper Rept for Nov 1978 ZULLA, B. B Power Authority of the Blate of New York 78/11/30. 6pp 94213-268
- 7812270188 Forwards rept of fish impingement & corrective action for Nov 1978 CAHILL, N J Consolidated Edison Co. of New York 78/12/14. Spp. 94018 037.
- B Reportable occurrences. LERs & related correspondence
- 7810100098 Forwards LER#78-031/03L-0 BANE.J P Power Authority of the State of New York. 78/10/03 lp 94033.156
- --7810100100 LER#78-031/03L-0 on 780912 failure of hot leg RTD TE-410A Manifold stop valve 561A found to be leaking borated water onto cabling 8 junction but of RTD Leak diverted by wrapping valve w/insulating cloth/RTD cable & box rinaed.

 QMBLE, F. W. Pager Authority of the State of New York. 78/10/02 2pp. 94033, 157.
- 7810120038 Forwards LERM78-030/O3L-0 8AYNE.J.P. Power Authority of the State of New York. 78/10/03 1p. 74471-359.
- --7810120060 LERW78-030/03L-0 on 780908: during 99% plant oper the React Oper noted RCB laskage of 2.37ppm due to packing lasks on RTD manifold hat leg isolation valves W561A & 561B for loops W31 & 32, respectively. Leak insignificant & oper continued. OUMBLE.F.W. Power Authority of the State of New York. 78/10/03. 2pp. 94471; 360
- 7811060210 Forwards LER#78-032/03L-0.
 BAYNEL-J.P. Power Authority of the State of New York 78/10/30 ip 74489:226.
- --7811060215 LER#78-032/03L-0 on 781004 water coming out of ground at N and of Turbine Bidg caused by ruptured FM-I valve located in fire protec loop. Ruptured valve replaced & sys returned to Teth Spec limits.

 GMBLE.F.M. Power Authority of the State of New York. 78/10/30. 2pp. 94489:227.
- 7811140247 Forwards LER#78-033/03L-0 BAYNE.J.P. Power Authority of the State of New York. 78/11/09. 1p. 94400:103.
- --7811140250 LER#78-033/03L-0 on 781014: radial tilt occurred caused by injection of boric acid when the arial offset was approaching its most negative value High flux aetpoint was reduced & tilt condition eliminated.

 Power Authority of the State of New York. 78/11/09. 2pp. 94400:104.
- 7811220189 Forwards LER#78-034/03L-0.

 BAYNE.J P. Power Authority of the State of New York 78/11/17. 1p. 94071:299.
- --7811220192 LER#78-034/03L-0 on 781027 at 100X purson increase in plant vent radio gas was monitored, due to leakage of #31 charging pump plunger. Plunger & packing for Union Pump GX-300 Guintuples were replaced.

 QMBLE.F. M. Power Authority of the State of New York. 78/11/17.
 2Pp. 94071:300.
- 7812220095 Forwards LER#78-037/03L-0.
 BAYNE, J.P. Power Authority of the State of New York. 78/12/18. 1p 94943:340.
- --7812220098 LER#78-037/03L-0 on 781121: While open at 100% pur in steady state.channel 3 pressurizer level indicator(LT-461)showed fressurizer level failing. Caused by leakage of Edwards-Rockwell blowdown valva(G/A*globs).

 OUBLE, F. W. Power Authority of the State of New York. 78/12/18.

 10. 94340:344.

- DOCKET 50-287 GCONEE NUCLEAR STATION, UNIT 3

 E NRC Safety Evaluation Report (SER), suppls & correspondence
- 7811020014 Supplements 780811 Safety Eval of subj facil Found LPSW syspiping arrangement acceptable Deletes requirement to provide spare dedicated cables for LPSW syspump motors REID.R.W. Operating Reactors Branch 4 (Pre 790625) 78/10/05 2pp 94351 247
- F Security, medical, emergency & fire protection plans
- 7810180126 Forwards proprietary info consisting of Change#8 to Rev#3 of subj facil security plan W/o proprietary info PARKER: H O. Duke Power Co 78/10/06 32pp
- 7810310008 Forwards Revision 2 of modified arended security plan (MASP) Encl utthheld (ref 10CFR2 790). PARKER: W D Duke Power Co 78(10/19, 2pp. 9409.3:360
- 7811210032 Summary of 781025 meeting to discuss qual of Station Health Physics at subj facil NRC requested util to submit rev Tech Spec FAIRTILE.H. Operating Reactors Branch 4 (Pre 790625). 78/11/02 28pp 94482:358
- 7812050019 Summary of a 781029 meeting re-subj facil Station Health Physicist FAIRTILE, M. Operating Reactors Granch 4 (Pro 790529) 78/11/02 3pp 94415-330
- P. Operating license stage documents & correspondence
- 78iii70029 Requests addi info in order to complete review of submittals dtd 780714 & 78i006 he permanent mods to High Pressure Coulant Injection Sys at subj facil Requests info in 20 days REID.R W Operating Reactors Branch 4 (Pre 790625). 78/10/31. 3pp 94048-182
- 7Bi0110025 Request for all info re radiat leakage & safety problems at subj facils.
 ODRONN J. Gordon, Halter J 78/09/08 1p. 94063:131
- 7B10110090 Forwards "Integrated Leak Rate Test of Reactor Containment Bldg." PARKER-N D. Duke Power Co 7B/09/29. 1p. 94066:289
- --7810110092 "Integrated Leek Rate Test of Reactor Containment Bldg." ROGERG,R., DAVENPORT.G.Q. Dute Power Co. 78/09/29 30pp 94066:290.
- 7810230158 Forwards check for \$8300 to cover add1 lic fees for NRC review of Cycle 5 released amend for subj facil.
 PARKER:N 0 Duke Power Co. 78/10/03. 2pp. 94164: 260
- 7810260149 Notification of forthcoming meeting with Duke Per Co on 781025 to discuss goals of Radiet Protec Manager. FAIRTILE.N 8. Operating Reactors Branch 4 (Pre 790625). 78/10/17. ip. 94055.336.
- 7810270072 Forwards Startup Rept for subj facil 781031 PARKER.W O. Duke Power Co 78/10/17. 1p. 94039:149.
- --7810270076 Startup Testing Summary for 781031. Bummarites the zero pur pur escalation tests, & includes comparisons of measured & predicted valves of important core paremeters. * Duke Pawar Co 78/10/17. 13pp. 94039 130
- 7810240147 Due to inaction on subj Facil 781007 proposal for Yech Specrey to incorporate staff position for voltage monitors, the proposal is rescinded.
 PARKER.W.O. Duke Power Co. 78/10/19. ip.
- 7810300182 Responds to 781010 NRC 1tr & remits fee for review of cycle 4 reload emend. PARKER, U.O. Dute Power Co. 78/10/20. 2pp. 94030:159.

DOCKETED ITEMS

- 7811070013 Forwards Amends 65,63 % 62 to Licenses DPR-38,DPR-47 % DPR-55, respectively, changing Tech Specs re full reted pur Cycle 3 oper after core reload removal orifics rod assemblios from core % High Pressure Injection Pump oper. REID.R.W. Operating Reactors Branch 4 (Pre 790623). 78/10/23 3pp. 94006: 290
- ~-7811070035 Amend#65 to Facil Oper LiceDPR-38 changing Tech Specs. REID:R W Operating Reactors Branch 4 (Pre 770625). 78/10/23. 2pp. 94036:293
- --7811070057 Amend#65 to Facil Oper LickDPR-47, changing Tech Specs, REID-R. M. Operating Reactors Branch 4 (Pre 7706251, 78/10/23, 2pp. 94036-295
- --7811070060 Amond#62 to Fecil Oper LickDPR-95, changing Tech Spece. REID:R W. Operating Reactors Brench 4 (Pre 790625). 78/10/23, 25pp. 94036:297.
- --7811070063 Exempts subj facil from 100FR50 46(a)re reactor cooling until mod is complete or until mert refueling shutdoun. STELLO.V. Division of Operating Reactors. 78/10/23. 8pp. 94036-322.
- --78:1070068 Bafety evaluation & EIA supporting Amend 65 to Lic DPR-38, Amend 65 to Lic DPR-47 & Amend 62 to Lic DPR-55. Concludes that it is acceptable for Cycle 5 oper to proceed & that EIA not req e Office of Nuclear Reactor Regulation, Director. 78/10/23 19pp. 94036. 330.
- --7811070071 Notice of issuence of Amend#65 & 62 to Facil Oper LicHDPR-3B.DPR-47 & DPR-55, respectively, rev Tech Bosce to support Pull rated pur oper during Cycle 5 after core reload adding High Pressure Injection Pump reqs & fuel demonstration prog. REID.R.M. Operating Reactors Brench 4 (Pre 790625). 78/10/23, 2pp 74036-1349.
- 7811170324 Notice of Issuance of Amend#62 & 65 to Oper Lic#DPR-38.47 & 55. Amend rev Tech Specs allowing full rated per during Cycle 5 efter corp reload & permits use of 5 previously burned fuel assemblies.

 REID.R.M. Operating Reactors Branch 4 (Pre 790625). 78/10/R3. 2pp. 02765:243.
- 7811020255 Notice of rev to Tach Spec 3.7 re Auxiliary Elec Sys. Spec 3.7.1 is rev to clearly define oneite emergency transmission paths in 125VDC Instr Control Sys.& rev 3.7.2 re alec sys degraded mode oper.
 PARKER, W. O. Duke Power Co. 78/10/31. 6pp. 94247:138.
- 7811140114 Responds to 781031 request for add1 info re mod of high pressure injection sys.specifically.small break ECC8 mod. PARKER, N. O. Duke Power Co. 78/11/06. App. 94485:155.
- 7811160065 Confirms conversations or 780705 proposed open lic change of possible receipt of 4 Puel assemblies from FL Pur Corp. Requests withdrawal of proposed lic amend & indemnity agreement(8-44) & refund of lic fee.
 PARKER.W.O. Duke Power Co. 78/11/07. 1p. 94133:121.
- 7811160079 Rescinds 780322 request for NRC concurrence re proposed change to respiratory protecting.
 PARKER, N.O. Duke Power Co. 78/11/07. ip. 94133:175.
- 7811160134 Responds to 781011 NRC comments on minimum quelifications of station Health Physicist. Considers requirements in ANBI/ANS-3. 1-1978 to be appropriate. PARKER-W. O. Duke Power Co. 78/11/07. 1p. 94135:235.
- 7811270118 Forwards 3 previously omitted Tech Spec pages(2.3-1,2.3-3 & 2.3-11)for Lic Amend#65.65 & 62.covering limiting safety systettings & protect inetru.
 REID.R.H. Operating Reactors Branch 4 (Pre 790625), 78/11/08, 5pp. 94271:266.
- 7811200421 Forwards results of measurements of radioactive meth in NRC phantom on whole body counter. Encl i contains actual amount of each radionuclide present encl 2 gives ratio of measurements to DDE values & encl 3 gives recommendations. SUT-FER_AND_J.T. Region 0. Atlanta, Fuel Facility & Materials Safety Branch, 78/11/09. 3pp. 94419:175.
- 7811210279 Nobifies util of 781205 seminar in Atlanta to discuss naw Model Rod Effluent Tach Specs & encl seminar info sheet, registration form. & proposed agenda. O'REILLY,J.P. Region 2, Atlanta. Office of the Director. 78/11/09. 3pp. 94488:126

- 7811210306 Notifies util of 781203 seminar in Atlanta to discuss new Model Rod Effluent Tech 8pecs & encl seminar info sheet, registration form, & proposed agenda.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/09.
 3pp. 94488:091
- 7811300035 Forwards NRC steff paper.Policy Session Item(SECY-78-554) re licensee reg performance evalution. Three methods for evaluation are; statistical, trend analysis & regional survey method.W/o encl. O'REILLY,J.P. Region 2, Atlanta, Office of the Director. 78/11/15. 2pp. 94070:351.
- 7812150123 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out matl. Went? Registration Form & List of Locations. MILLER.J.R. Assistant Director for Site & Safeguards (Pre 791030), 78/11/15. Opp.
- 7812190031 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PHR's (NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plents" (NUREO-0133). W/o encl ANG: 7811270173 & 781127018.

 ORIFES.B.K. Assistant Director for Engineers & Projects (Pre 770623). 78/11/15. 6pp. 94214:333.
- 7811300379 Informs DPC that NRC has contracted w/Mountain West Res Inc to undertake a series of post-licensing studies of nuc pur stations Studies will analyze socioecon impacts which occurred during constr & post-constr periods of each plant. DEYOUNG, R. C. Division of Site Befety & Environmental Analysis. 78/11/20. 2pp. 94136:252.
- 7812060260 Response to 780905 ltr requesting exemptions from certain reg of WiOCFR Part 21. Rule amended 781019 & provided relief requested.

 DENTON:H.R. Office of Nuclear Reactor Regulation, Director. 78/11/24. 2pp. 94371:337.
- --7818060272 Requests exemption from 10CFR21 re procurement of various standard stock items from Cutler Hammer, Inc. Procurement delays will affect constructed the PARKER, N. O. Duke Power Co. 78/09/05. 3pp. 94371:339.
- 7812040147 Forwards updated replacement for 780216 copy of steam generator oper history. Includes all activities thru June 1978 refueling & insuc inspec.
 PARKER.W. D. Dute Power Co. 78/11/28. 11pp. 94456:098.
- 7812;50083 Discusses possible dangers of LDCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Myencl AND: 7812080207.
 - 7812080207. REID.R.W. Operating Reactors Smanch 4 (Pre 790625). 78/11/29. 6pp. 94210:330.
- 7812180131 Expects that mod of high pressure injection sys at subj facils can be implemented for each unit during first available outage of sched duration sufficient to install mod.

 PARKER.W.O. Duke Power Co. 78/12/04. 1p. 94364:278.
- 7812280173 Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIB.J.O. Director. 78/12/06. 2pp. 94375:015.
- 7812260001 Accepts proposed design mod to High Pressure Injection (HP1) sys consisting of installing cross-current lines between discharge lines of HP1 sys.W/Befety Eval. LAINMs.9. Plant Systems Branch (Pre 791030), 78/12/07. 6p. 94020:271.
- 7812260042 Forwards Bafety Eval Rept for subj facil re mod to high pressure injection eys.
 REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/18/13. Spp. 94021:271.
- --7812260064 BER "Mod to High Pressure Injection Sys."Concludes design mod to HPIS will ensure that for all postulated single failure conditions.HPIS will be capable of supplying HPI flow by 2 HPI pumps through 2 injection paths.

 * Operating Reactors Branch 4 (Pre 790625). 78/12/13. App. 74021:273.

- --7812280247 Lic#DPR-38.DPR-47.& DPR-55 for Amends 66.66.& 63:Tech Specs proposed changes re control rod operablity & support of Unite2 full rated pur during Cycle 4 after core reload & removal of orifice rod assemblies from core REID.R W. Operating Reactors Granch 4 (Pre 790623) Operating Reactors Granch 4 (Pre 790625). 78/12/19 94355: 261 Збрр.
- --7812280254 SER supporting Amend 65 to DPR-38. Amend 65 to DPR-47.& Amend 63 to DPR-55 Concludes that proposed Tech Spec changes do not involve a significant hazard health or safety consideration. e Operating Reactors Branch 4 (Pre 790625). 78/12/15. 13pp. 94355: 306
- --7812280267 Notice of Issuance of Amend 66 to DPR-38, Amend 66 to DPR-47. & Amend 63 to DPR-55 revising common Tech Bpecs to support the oper of Unit#2 full rated pur during Cycle 4, ZMETZIO, G B. Operating Reactors Branch 4 (Pre 790625). 78/12/15.
- 7812270244 Forwards proposed rev to subj facil Tech Specs Proposed exception 3 3.6(f) would allow inoperability of one Reactor Bidg Spray Pump for up to 72 hours provided all Reactor Bidg Cooling Units are operable Wattach affidavit. PARKER, M. D. Dute Power Co. 78/12/22. 4pp. 94017.155.
- Q. Inspection reports. IE Bulletine & correspondence
- 7811100103 Ack receipt of 781016 ltr informing NRC of steps taken to correct violations noted during inspec#50-269/78-18. #50-2270/78-19. KENNA. H.B. Region 2. Atlanta, Safeguards Branch. 78/10/26. 1p. 94173: 356
- ---78ii100ii0 States info contained in 781016 ltr is proprietary pursuant to Section 2.790 & is to be withheld.

 PARKER. H. O. Duke Power Co. 78/10/16. lp. 94173:357.
- --7811100115 Responds to 780919 NRC ltr re violation noted in inspec Repts#50-269/78-18,#50-270/78-18 & #50-287/78-19. Corrective action withheld (ref 10CFR2.790). PARKER, W. D. Duke Power Co. 78/10/06. 1p. 94173:358.
- --7811100124 Forwards summary of 1E Inspec Repts#80-269/78-18, #50-270/78-18 & #50-287/78-19 on 780815-17. Notice of Violation withheld pursuant to 2.790. #ENNA.W. 8. Region 2, Atlanta, Office of the Director. 78/09/19, 2pp. 94173:359.
- --7811100130 IE Inspec Repts#50-269/78-18.#50-270/78-18 & #50-287/78-19 on 780815-17 during which I item of noncompliance was noted to sting of alarms.
 BEBECKER.K.H., OILLEBPIE,F.P. Region
 Director. 78/09/18. 1p. 94173:361. Region 2. Atlanta, Office of the
- 7810130056 Ack receipt of IE lnsp Repts 30-249/78-17,50-270/78-17 & 50-287/78-18 on 780807. No proprietary info. PARKER, H. O. Duke Power Co. 78/09/27, ip. 94079:185.
- --7810130060 Forwards IE Insp Rept 50-269/78-17.50-270/78-17 & 30-287/78-17 on 760807. No npncompliance noted. SUTHERLAND. J. T. Region 2. Atlanta. Fuel Facility & Materials Barety Branch. 78/09/20. 2pp. 94079:186.
- --7810130064 IE Insp Repts 50-269/78-17, 50-270/78-17 & 50-287/78-18 on 780807. No noncompliance noted Major areas inspected: whole body counting practices & test count of NRC phantom. OIBSON, A. F. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/09/20. 4pp. 94079:18B.
- 7811030221 States that prog has been established to address IE Circular 7B-08 Review of adequacy of qualifications of each piece of equip will be completed by 790416.
 PARKER, M. D. Duke Pawer Co. 78/09/29. ip. 02724:280.
- 7810230287 Forwards IE Circuler#78-17, (See ANO: 7810230221, Docket 50-313, 781013) O'REILLY, J. P. 1p. 94145: 005. Region 2, Atlanta, Office of the Director. 78/10/13.
- 7811190085 Forwards IE Circular 78-18. D'REILLY, J.P. Region 2, Atlanta, Opfice of the Director. 78/31/06. 1p. 94113:183.

- #50-287/78-23 on 780918-22 during which no items of noncompliance were noted
 - LCNO.F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 78/10/18. 2pp. 94397:252.
- --7811280398 IE Inspec Repts#50-249/78-22.#50-270/78-22 & #50-287/70-23 on 780918-22 during which no items of noncompliance were noted Major areas inspected included: unresolved items. special repts.ection on IEC 78-08. LENIB.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Brench. 78/10/18. Spp. 94397: 254.
- 7812120053 Forwards reproductions of entitles that a peared in June & Aug 1978 editions of Nuc Security Bafeguards Newsletter KENNA. W. B. Region 2. Atlanta. Bafeguards Branch. 78/11/17. 94278:072
- 7812050021 Ack receipt of 781120 | tr informing NRC of steps taken to correct violations noted during inspecs#50-269/78-15. #50-270/18-13 & #50-287/78-16 BUTHERLAND, J T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 78/11/20. 1p. 94200:270
- --7812030025 Responds to 780929 NRC 1tr re violations noted in Inspet Repts#50-269/78-15,#50-270/78-15 & #50-287/78-15. Carrective actions: entrances to interim weste facil posted Wradist signs & spent fuel cask rebolted & retorqued for shipment PARKER,H. D. Duke Pawer Co. 78/10/25. 4pp 94200:271.
- --7812050029 Forwards IE Inspec Repts#50-269/78-15.#50-270/78-15 & #50-287/78-16 on 780726-28 & 780801-04 & Notice of Violation O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/09/29. 2pp. 94200:275.
- --7812050030 Notice of Violation from Inspec on 780726-28 & 780901-04, * Region 2, Atlenta, Office of the Director. 78/09/29. ip.
- --7812050031 IE Inspec Repts450-269/78-15, #50-270/78-15 & #50-287/78-16 on 780726-29 & 780801-04 during which 2 items of noncompliance were noted: failure to properly pack cask for shipment & to perform radiat surveys in interim waste bldg. HOBEY, C.M., JENKINS, Q.R., 21880N.A.F. Region 2. Atlanta, Fuel Facility & Materials Safety Brench. 78/09/28. 11pp. 94200:278.
- 7812040326 Ack receipt of 781106 ltr informing NRC of steps taken to correct violations noted during inspec#50-269/78-20. #50-270/78-20. #50-287/78-21. ButherLand.J.T. Region 2. Atlanta, Fuel Facility & Materials Safety Branch. 78/11/22. Ip. 94130:353
- --7812040328 Responds to 781018 NRC itr re violations noted in inspec Repts#50-269/78-20,#50-270/78-20,#50-287/76-21 Corrective actions: door lock mod to prevent unlocking w/o key. PANKER,M. O. Duke Power Co. 78/11/06. 2pp. 94130:354.
- --7812040332 Forwards IE Inspec Repts#50-269/78-20:#50-270/78-20:#50-287 78-21 & Notice of Violetion. SUTHERLAND, 1 T. Region 2. Atlants, Fuel Factlity & Materiels Sefety Branch. 78/10/10. 2pp. 94130:336.
- --7812040335 Notice of Violation from Inspec on 780911-15.
 * Region 2, Atlanta, Fuel Facility & Materials Safety Branch.
 78/10/18. 1p. 94130:358.
- --7812040339 IE Inspec Repts#50-269/78-20, #50-270/78-20, #50-287/78-21 or 780911-13 during which I itsm of noncompliance was noted: failure to keep entrance to high radiat area locked HOSEY.C.M., QIBSON,A.F. Region 2. Atlanta, Fuel Facility & Materials Barety Branch. 78/10/18. App. 94130: 359.
- 7812040363 Forwards IE Bulletin#78-12A. suppl to IE Bulletin 78-12. W/encl AND: 7811300055.

 O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/24.

 1p. 94127:166.
- 7812070317 Ack receipt of IE Insp Repts 50-269/78-21 & 50-287/78-22 on on 780919-21. Does not consider any info therein to be proprietary.
 PARKER:N.O. Duke Power Co. 78/11/28. 1p. 94084:339.

- --7812070319 Forwards IE Insp Repts 50-269/78-21 & 50-287/78-22 on 780919-21 during which no items of noncompliance were noted MURPHY.C E Region 2, Atlanta. Reactor Construction & Engineering Bupport Branch 78/11/02. 2pp 94084:340.
- --7812070320 IE Inap Repts 30-269/78-21 & 30-287-22 on 780919-21 during which no items of noncompliance were noted Major areas inspected incl. Cornective action on previously identified infraction #237/78-14-01.
 CCNLON-T.E., ECONOMOB, N. Region 2. Atlants. Reactor Construction & Engineering Guppart Branch 78/11/01. 7pp 94084:342.
- 7812130306 Ack receipt of IE Inspec Repts#50-269/78-26,#50-270/78-25 & #50-267/78-26 on 781023-27. Does not consider any info therein to be proprietary PARKELM, 0 Duke Power Co. 78/12/05. 1p 94159-278
- --7812130311 Forwards IE Inspec Repts#50-269/78-26, #50-270/78-25 & #50-207/78-26 on 781023-27 during which no items of noncompliance were noted.

 LONG.F. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/21 2pp. 94159 279.
- --7812130317 IE Inspec Repts#50-269/78-26.#50-270/78-25 & #50-287/78-26 on 781023-27 during which no items of noncompliance were noted. Major areas inspected inclination of past flow.pur & pur distrib anomalies.

 BURNETT.P T. Region 2. Atlanta. Office of the Director. JULIAN.C A. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. BETTENHAUSEN.L Region i. Philadelphia. Office of the Director 78/11/20. 5pp. 94159.281.
- 781214004) Act receipt of IE Insper Repts#50-269/78-29, #50-270/78-21 & #50-287/78-29 on 781104-08. Does not consider any info to be proprietary.
 PARKER, W. O. Duke Power Co. 78/12/05. ip. 94127-267.
- --7812140046 Forwards IE Inspec Repts#30-269/78-29,#30-270/78-21 & #50-287/78-29 un 781106-08 during which no items of moncompliance were noted.
 - LONG,F. J. Region 2: Atlanta, Reactor Operations Nuclear Support Branch, 78/11/22, 2pp. 94127:268
- --7812140048 IE Inspec Repts#30-269/78-29,#50-270/78-21 & #50-287/78-29 on 781106-08 during which no items of noncompliance were noted Major areas inapacted incliplant open & restoration of sys following refueling outage.

 JAPE.F., LEMIS.R.C. Region 2, Atlante, Reactor Operations Nuclear Bupport Branch. 78/11/22 opp. 94127:270.
- 7812140053 Ack receipt of 1E Inspec Repts#50-267/78-24,#50-270/78-23 & #50-287/78-24 on 781017-20 & 781101-03 Data not consider any info therein to be proprietary.
 PARKER. M. O. Duke Power Co. 78/12/05. 1p. 94126:330.
- --7812140053 Forwards IE Inspec Repts#50-269/78-24, #50-270/78-23 k #50-287/78-24 on 781017-20 & 781101-03 during which no items of noncompliance were noted.

 KENNA, W B. Region 2, Atlanta, Befaguards Branch. 78/11/29. 2pp. 94126.331.
- --7812140039 IE Inspec Repts#30-269/78-24,#50-270/78-23 & #50-287/78-24 on 781017-20 & 1101-03 during which no items of noncompliance were noted. Major areas inspected incl: facil organization. shipping & receiving & storage.
 HODOES, J. M., CLAY, E. L., WILLIAMES, O.H. Region 2, Atlanta, Bafeguards Branch 78/11/24, 4pp. 94126:333.
- 7812290092 Forwards IE Bulletin 78-14.

 O'REILLY.J.P. Region 2, Atlanta, Office of the Director. 78/12/19.
 2pp. 03495:189.
- R. Periodic operating reports & related correspondence
- 7610200082 Forwards Monthly Oper Rept for Bept 1978 PARKER, M. O. Duke Power Co. 78/10/16. ip. 94366:343.
- +-7810200083 Monthly Oper Rept for Sept 1978. REAVIS. J. E. Duke Power Co. 78/10/16. 16pp. 94366:344.
- 7810240002 Forwards Quarterly 780601-780831 rept on Jocessee Area Selsmic Activity. PARKER, M. D. Duke Power Co. 78/10/16. 1p.
- --7810240077 Guarterly Beismic Activity Rept, (6-1-78 to 8-31-78). Decreased Baismicity in Jocasses area represents diminishing site and no. of joints at greater depths.
 TX-HAMI.P., BIEVENSON.D., BAUSER.J. Bouth Caroline, Univ., of. 78/10/16. 19pp.

- 7812210157 Forwards Monthly Open Rept for Nov 1978. PARKER, H. D. Duke Power Co. 78/12/15. 1p. 94278: 185.
- --7812210160 Monthly Oper Rept for Nov 1978. REAVIS, J. Dute Power Co. 78/12/15 16pp. 94278 186.
- 8. Reportable occurrences, LERs & related correspondence
- 7812130169 Forwards LERH7B-014/03L-0.
 PARKER, M. O. Duke Power Co. 78/12/07 1p. 94294:352.
- 7812190153 Forwards LER#78-015/03L-0.
 PARKER, W. D. Duke Power Co. 78/12/08. 1p. 94340: 138
- --7812170156 LER878-015/03L-0 pn 780731:RPS Channel A.RC flow indication began reading high on 780729 & was valued out-of-avc on 780731 caused by lesk in pressure transmitter impulse line. Leaking fittings were repaired.

 WILBON,X.R. Duta Fower Co. 78/12/08 2pp. 94340:159.
- 7812290209 Forwards LER#78-016/03L-0. PARKER, H. D. Duke Power Co. 78/12/22. 1p. 94190: 344.
- ---7012290214 ROW207/78-16 on 701123:88 Channel A Wide-range pressure indication drifted high & was manually tripped due to excessive moisture in panatration caused by leaking roof.

 * Duke Power Co. 78/12/22. 2pp. 94190:345.
- --7812290218 LER#78-016/03L-0 on 781123:E8 Channel A wide-range pressure indication drifted high & was menually tripped due to excessive moisture in penstration caused by leaking roof. WIL-9DN, K. R. Duke Power Co. 78/12/22. ip. 94190:347.
- DOCKET BO-288 REED COLLEGE REBEARCH REACTOR
- G. Inspection reports. IE Bulletins & correspondence
- 7811060007 Forwards IE Inspec Rept#50-288/78-03 on 780911-13 during which no items of noncompliance were noted.

 8000K-16. Region 5. Sen Francisco: Fuel Facility & Materials Befety Branch. 78/09/29. 2pp. 94422:211.
- --7811060008 IE Inspec Rept#80-208/78-03 on 780911-13 during which no itmes of noncompliance were noted. Major areas inspec incl: radiat control, environ monitoring & emergency planning.
 800K.H.E., BAIRD.J.B. Region 5, San Francisco, Fuel Facility & Materials Bafety Branch. 78/09/29. 6pp. 94422:213.
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1
- F. Becurity, medical, emergency & fire protection plans
- 7810300137 Forwards fire svc water piping drawing for TMI-1. Drawing available in Central Files only. HERBEIN.J. @. Metropolitan Edison Co. 78/10/24. ip. 94190:317.
- 7811070135 Notification of implementation of amoking prohibition in safety-related areas of facility. Howevels to be installed per 780612 ltr & Item 3.1.2 of fire protection safety avaluation in order to suppress relay room cable tray fires. HERREIN J. D. Metropolitan Edison Co. 78/10/31. 1p. 94195:335.
- 7811070101 Forwards summary of fire loading for subj facility to satisfy Item 3.8.9 of fire protection safety evaluation rept. HERBEIN.J. 9. Metropolitan Edison Co. 78/11/01. 14pp. 94195:321.
- 7811080204 Forwards table identifying fire hazard analysis of fire doors which will be electrically locked a slammed by 790215. those mechanically locked closed when not in use. I those not unlocked or slammed but kept closed when not in use. HERREIN, J. O. Metropollish Edispn Co. 78/11/01. 3pp. 94198:339.
- 7811270155 Forwards Revision 4 to physical security plan Mithheld (ref. 10CFR2, 790). HERBERINJ. G. Metropoliten Edison Co. 78/11/17. 1p. 94253.332.
- 7812060168 Responds to 780919 fire protection safety evaluation rapt. Documentation search completed re-fire rating of TMI-1 fire doors. Porwards fire heards analysis drawlings.
 HERREIN, J. O. Metropolitan Edison Co. 78/18/01. 5pp. 94270:252.

- 7812190113 Responds to NRC 780017 ltr re fire protection program. No further fire protection measures needed in cable route area between furel pool & control bldg to ensure safe shutdown. HERBEIN, J. G. Hetropolitan Edison Co. 78/12/13. 6pp 94137:331.
- M General correspondence
- 7810230159 Informs that 780830 Tech Spac Change Request 77 re ring girder surveillance test is subj to Class II amend fee. MILLER-H. D. License Fee Hanegement Branch. 78/10/11. ip. 94197.316.
- 7810300148 Appointment of new licensing mgr for GPU Svc Corp.
 MALLACE.E. G. General Public Utilities GPU Service Corp. 78/10/P3.
 1p. 94035:115.
- --7810000133 Informs of appointment of new licensing manager for Qeneral Public Utilities Bvc Corp.

 WKLACE, H. V. Qeneral Public Utilities QPU Bervice Corp.

 78/10/23. 1p. 94035:116.
- 7812110248 Requests payment of Class II fee for 780830 application rering girder surveillance test. Amend classified by NRC 781011 ltr as Class II. MILLER.M. D. License Fee Management Branch. 78/11/89. ip. 94197:352.
- 7812080212 Ack receipt of 780523 application for amend to DPR-50 & fee payment. Finds action is Class III & raquests payment of add1 fee.
 MILLER.W. D. License Fee Management Branch. 78/11/30. 1p. 94193.360.
- 7812280i61 Emphasizes importance of submitting occurate & complete info to NRC. Info must be substantiated by data. NRC must be notified of inscruracies to avoid enforcement action. DAVIB.J.G. Office of Inspection & Enforcement, Office of the Director. 78/18/06. Epp. 94311:350.
- 7812120092 Advises that Generation Licensing Section (Production Supervision) moved back to Pottsville Pike location on 781213.Forwards new telephone numbers. HERBEIN J. O. Metropolitan Edison Co. 78/12/12. ip. 94274:204.
- P. Operating license stage documents & correspondence
- 78:01:01:0148 Forwards hose stretch test results & recommendations.First hose reals will be added to room w/decay heat eve coolers at all elevations except 306 ft elevation of control room bldg to reactor bldg.

 HEREEIN.J. G. Metropolitan Edison Co. 78/10/05. 3pp. 94137:322.
- 7811020228 Requests add1 info re consequences of crane failures when handling heavy loads in proet to complete review for facility. Also requests submittel within 45 days of amend to Tech Spec Change Request 36.
 REIQ.R.M. Operating Reactors Branch 4 (Pre 790625), 78/10/16. 3pp. 94195:318.
- 7810240119 Forwards NPDES Noncompliance Notification 78-22 re waste filter sus discharge sample with pH in excess of genet limitation. TROFFER.G. J. Hetropolitan Edison Co. 78/10/17. 2pp. 00001:235.
- 7811010246 Notification of 781026 meeting w/util re aircraft crash data for THI-2.
 BILVER,H. Light Water Reactors Branch 4. 78/10/19. 1p. 00001:251.
- 78:1140:03 Advises of discharge of 1,100 gallons of water which bypassed industrial waste treatment sys. Caused by increase in flow to facility tubine bldg sump. TROFFER. 9. J. Metropolitan Edison Co. 78/11/03. 2pp.
- 7811160145 Forwards NPDEB Noncompliance Notification 78-23: on 781026, sample from industrial waste filter mys discharge had pH of 9.4. Caused by rise of pH during test while pH monitors were malfunctioning.

 TROFFER. 9. J. Netropolitan Edison Co. 78/11/06. 2pp. 94271:008.
- 78:1280389 Forwards request for add1 info re 780313 application to asend DPR-50 by increasing fraquency for checking calibrations accuracy of power range nuclear instrumentation.

 REID.R.H. Operating Reactors Branch 4 (Pre 790625). 79/11/06. 3pp. 94137:319.

- 7812130109 Notification of workshops for training & qualification of personnel per 10CFR73.App B Requests advance registration of attendees Registration form & list of locations and 1.

 MILLER.U.R Assistant Director for Site & Bafeguords (Pre 791030).
 78/11/13 5pp.
- 7812190039 Forwards NUREO-0473. Revision 1. 'Draft Radiological Effluent Tach Space for PMRs" & NUREO-0133. "Preparation of Radiological Effluent Tech Space for Nuclear Power Plants." W/o encl. QRIMEB.B.X. Assistant Director for Engineers & Projects (Pre 790429). 70/11/15 6pp. 94137 325.
- 7811290343 Natification of 781132 meeting w/util to discuss proposed mode to eliminate need for prompt action in responding to small break LBCA worst single failure.
 ZMETZIG.O.B. Operating Reactors Branch 4 (Pre 790623) 78/11/17.
 Zpp. 94193:331.
- 78/1300037 Informs that NRC has contracted to undertake a series of post-licensing studies to enelyze socioeconomic impacts of nuclear plant const.
 DEYOUNG R C. Division of Site Safety & Environmental Analysis.
 78/11/80. 2pp. 00002:234.
- 7811240110 Forwards proposed small break LDCA lpng-term mod.NRC 780726 ltm did not respond so 780724 util proposel & util believes proposel meets NRC requirements. HERBEIN.J. Q. Hetropolitan Edison Co 78/11/21. App. 94456.275
- 7811280243 Informs NRC that Met Ed will implement 879 for TMJ-1 midcycle instead of at end of 1977 refuelling outage. Lists reasons, advantages & disadvantages HERBEIN J. Q. Metropolitan Edison Co. 78/11/21. 2pp 94137: 317.
- 7812070194 Notice of seminar on 781208 on new model radiological effluent Tach Spece for nuclear plants Requests advance submitsion of seminar-apecific questions ORIER, B.H. Region 1. Philadelphia. Diffice of the Director 78/11/21. Opp. 94375:069.
- 7B1R180045 Forwards Amend 46 to DPR-50.safety evaluation & notice of (sauance. REID.R.H. Dperating Reactors Branch 4 (Pre 790625) 78/11/22. 2pp 74271:023.
- --7812180047 Amend 46 to DPR-50, revising Tech Spece by increasing frequency at which heat balance checks are performed to verify calibr of power range nuclear instrumentation REID.R.W. Operating Reactors Branch 4 (Pre 790625), 78/11/82, 78p. 94133:036.
- --7812180049 Safaty evaluation supporting Amend 46 to DPR-50. * Office of Nuclear Reactor Regulation, Director. 78/11/22. Epp. 94132:063.
- --7812180051 Notice of issuance of Amend 46 to DPR-80. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/92. 2pp. 94133:065.
- 7812100087 Discusses possible dangers of LOCA in containment purging during normal plant operation. Requests either commitment to limit or justification for continuing purging. Forwards 89P Bection 6. 2. 4. Revision 1, re-containment purging.
 REID. R. H. Operating Reactors Brench 4 (Pre 790620), 78/11/29. 6pp. 94270.272.
- 7812030098 Responds to NRC 781016 itr re consequences of cransfailures when handling heavy loads. Based on answers to NRC questions no amend to Tach Spac Change Request 38 considered necessary. HERBEIN.J. Ø. Metropolitan Edison Co. 78/12/01. 3pp. 94270: 246-
- 7812060161 Responds to NRC 781011 ltr & contends that Tech Brec Change Request 77 clearly simplifies facility Tech Specs No further review by NRC of ring girder insp program required. HERBEIN.J. Q. Metropolitan Edison Co. 78/18/01. 2pp. 94270: 249.
- 7812080090 Forwards Tech Bpec Change Request 85 re DPR-50 re deletion of enubbers from Table 3.16.1.Certificate of Svc & Class II amend fee encl.
 HERBEIN J. Q. Metropolitan Edison Co. 78/12/04. 13pp. 94270:240.
- 7812180281 Responds to 781121 ltr & requests addl info re schedule for implementing mod to eliminate reliance of facility on operator action following small break LOCA.

- 7812280049 Summary of 781122 meeting w/util in Betheada:MD re util revised proposed mod to sliminate relience on operator action following small break LOGA List of attendees & proposed mechanical mode smal. ZWETZIG. G. B. Operating Reactors Branch 4 (Pre 790625). 78/12/12. 10pp 00008:042
- 7812290129 Forwards NPDES Noncompliance Notification 78-25. TRDFFER, Q. J. Metropolitan Edison Co. 78/12/19. 2pp.
- 7812290086 Forwards responses to NRC 781208 ltr re installation of long-term solution to small break LDCA problem Prodent time for installing mod is during 1980 TMI-I refueling outage. HERBEIN, J. G. Metropolitan Edison Co. 78/12/21. 3pp.
- 9. Inspection reports, IE Bulletins & correspondence
- 7810160250 Forwards IE Sullstin 78-12, "Atypical Held Matl in Reactor Pressure Vessel Helds." Licensee action required M/o encl. ORIER, B.H. Region i. Philadelphia, Dfflics of the Director. 78/09/29. 6pp. 94471:302.
- 7810200228 Notification of meeting on 781012-13 w/Met Ed re TMI-1 inservice insp program per 10CFR30.55a(g) & to discuss licensee submittal & responses to questions. ZWETZIO.G. B. Operating Reactors Branch 4 (Pre 790625). 78/10/05.20p
- 7810230194 Notification of meeting w/Met Ed, rescheduled for 781018-19, to discuss TMI-1 inservice insp program per 1005830, 354(g) & to discuss licensee submittal & responses to questions. ZWETZIG.0. B. Operating Reactors Branch 4 (Pre 790625). 78/10/05. ip. 94137:314.
- 7811060186 Forwards IE Circuler 78-17.4/a encl.
 GRIER.8.H. Region 1, Philadelphia, Office of the Director.
 78/10/13. ip. 00001:R65.
- 7812010345 Forwards licensee performance evaluation for Region 1.No operating reactor in Region 1 considered to have either abnormal or unusual safety contarn. GRIER, 8. H. Region 1. Philadelphia. Office of the Director. 78/11/01. 4pp. 00002:259.
- 7811290199 Forwards IE Circular 78-18. "UL Fire Test." ORIER, 8.H. Region 1. Philadelphia. Office of the Director. 78/11/06. 1p. 00002:226.
- 7812010000 Repts on status of review of 770817 & 770930 submittals reinspruce insp & testing. Forwards request for add1 info & minutes of 781018-19 meetings. Requests reply within 14 days. REID. R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/20. 1200. 94271: 011.
- 7812010140 Bummary of 781018 & 17 meeting re 770817 & 0930 licensee submittals on inservice insp & testing of pumps valves, component pressure boundaries, conflicts between code & sefety requirements & concerning pressure isolation valves. ZWETZ19, 0. B. Operating Reactors Branch 4 (Pre 790625). 78/11/20, 7pp. 74195:353.
- 7812270047 Forwards 12 Insp Rept 50-289/78-18 & 50-380/78-31 on 781006, 10-12 & 17-19 & notice of violation.

 SMITH, O.H. Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch. 78/11/21, 3pp. 00007:362.
- --7812270051 Notice of violation from insp on 781006.10-12 & 17-19.

 Region 1. Philadelphia. Office of the Director. 78/11/21. 2pp. 00007:002.
- --7812270057 IE Insp Rept 50-289/78-18 & 50-390/78-31 on 781006, 10-12 & 17-19. Noncompliance noted: failure to barricade high radiation area or maintain records of effluent sampling. PLUMLEE, K. E.; BERABIAN, J. A. Region i. Philadelphia, Office of the Director. 78/11/15. 12pp. 00008:004.
- 7812130144 Forwards IE Bulletin 78-12A, "Atypical Weld Matl in Reactor Pressure Vessel Welds." ORIER, B.H. Region 1, Philadelphia, Office of the Director. 78/11/24, 1p. 94212:202.
- 7812200171 Forwards answers to NRC 781120 questions re inservice insp t testing program, Prepering revision program submitted util 770817 & 0930 HERBEIN.J. Q. Metropolitan Edison Co. 78/12/13. 17pp. 94271:025.

- R. Periodic operating reports & related correspondence
- 7811210184 Forwards monthly operating rept for Oct 1978.

 HERBEIN, J. O. Metropolitan Edison Co. 78/11/15. 1p 94488:077.
- --7811210186 Monthly operating rept for Oct 1978. HITCHELL.D.G. Metropolitan Edison Co. 78/11/09. Spp. 94488-078.
- 7812190166 Forwards monthly operating rept for Nov 1978. HER8EIN.J. G. Metropolitan Edison Co. 78/12/13 1p. 94137:337.
- --7812190170 Monthly operating rept for Nov 1978.
 MITCHELL, D. G. Metropolitan Edison Co. 78/12/13. 4pp. 94137:338
- B. Reportable occurrences, LERs & related correspondence
- 7810100090 Forwards LER 78-029/01T-0. HERBEIN, J. Q. Metropoliten Edison Co. 78/09/28. ip. 94271:007.
- --TB10100099 LER 78-029/017-0: on 780914, temp sensor for A emergency diesel generating room found to be inoperable & fire watch not established within 1-h. Caused by personnel error. Procedural guidance will prevent recurrence.

 MITCHELL, D.O. Metropolitan Edison Co. 78/09/28. 2pp. 94033:170.
- 7810310184 Forwards LER 78-30/03L-0.
 HERBEIN, J. G. Metropolitan Edison Co. 78/10/20. 1pp. 94137:315.
- --7810310192 LER 78-30/03L-0: on 780923, borated water found in heater terminal box due to cladding rupture. Caused by hot spot from evaporator tank crud buildup.
 BTANLEY, W. B. Hetropolitan Edison Co. 78/10/20. 1p. 94137:316.
- 7811070191 Forwards LER 78-027/017-0.W/o encl. HERBEIN, J. Q. Metropolitan Edison Co. 78/10/27. 1p. 94195:336
- 7B12110146 RO 7B-31/4P:river water temp change exceeded Tech Spec limits. Caused by low inlet temp & high ambient temp & relative humidity, resulting in inability of mechanical draft cooling towers to cool discharge water properly. BEELINGER, J. L. Metropolitan Edison Co. 78/12/05. 1p. 94195:351.
- 7812260191 Forwards LER 78-031/04T+0. HERBEIN, J. O. Metropolitan Edison Co. 78/12/15. 1p. 94270:344.
- --7812260194 LER 78-031/04T-0:on 781204, station river water discharge delta temp limit of 12 F was acceeded by 2 F. Caused by heating of station river discharge by mechanical draft cooling towers.

 NIELSEN.E.B. Metropolitan Edison Co. 78/12/15. 2pp. 94199:161.
- V. Operator Examinations
- 781:130145 Forwards applications for senior operator licenses for JB Logen, CE Hartman, RW Zechman, HB Shipman & ED Hemmila.
 MILLER, Q. P. Metropolitan Edison Co. 78/09/14. 2pp.
- DOCKET 50-290 PROOF TEST FACILITY

 F. Security, medical, emergency & fire protection plans
- 7810310076 Forwards rev to copies 6 thru 10 of sub; facil security plan dtd 780926. Revs reflect letest changes in proposed security sys & procedures. Revs are proprietary (ref 100FR2, 790). QLUELAND, J.E. Tannessee Valley Authority. 78/10/25. 79pp. 94094:315.
- Q. Inspection reports. IE Bulletins & correspondence
- 7812030037 IE Inspec Repts#30-289/78-21,#30-260/78-23 & #30-296/78-20 on 780828-0901 during which no items of noncompliance were noted. Major areas inspected incl: paportable occurrences & followup on 16 bullstims & circulars.

 SULLIVAN.R.F. Region 2. Atlanta, Office of the Director. 78/10/26. 10pp.
- DOCKET 50-293 PILGRIM NUCLEAR POWER STATION, UNIT 1 F. Security, medical, emergency & fire protection plans
- 7811130168 Forwards suppl info re mode to security plan dtd 781005, which is withheld pursuant to 2.790.
 ANDOONINI. Q. C. Boston Edison Co. 78/11/06. 1p. 94271: 225.

- 7812290230 Ack receipt of 781005 & 781106 ltrs re changes to security plan Concurs withe finding that these changes do not detrease the effectiveness of the plan IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/12/21. 2pp 94191:204
- I Financial information
- 7810230205 Forwards tabular data on earnings for Aug 1978. 8071ER.R.M. Boston Edison Co 78/10/16 3pp. 94195 188
- 7812050228 Forwards BECO 1977 Annual Rept & BECO Form 10-0 for quarter anding 780930 as filed w/BEC 1979 Cash Flow Forecast & narrative statement of curtailment of capital expenditures also encl. available in CF & PDR only.

 KELMON-R-M Boston Edison CD 78/11/29. 43pp. 94201 201.
- K Utility Final Safety Analysis Report (FSAR) & amends
- 78iii40i32 Forwards suppl info to proposed lic amend of 78i016 re changes pertaining to receipt possession & use of byproduct, source & special nuc meth. Encl is rev to FSAR updating source inventory to comply w/Reg Guide 1.70.3
 ANDOONINI, Q. C. Boston Edison Co. 78/11/02. 3pp. 94428:247.
- 7812260218 Forwards Rev#1 to Emergency Plan & Amend#38 to FBAR. ANDONINI, Q. C. Boston Edison Co. 78/12/18. 2pp. 94162: 099
- --7812260223 Rev 1 to Emergency Plan. Amend 38 to FSAR Mejority of revised pages correct typographical errors. ANDOMINI.9.C. Boston Edison Co. 78/12/18 77pp. 94152:101.
- P. Operating license stage documents & correspondence
- 7810170136 Responds to 780807 NRC request for evaluation of reactor protects system supply. Believes that continued safe open of subjecti is justified Gen Elec will rept on failure modes & effects by mid-Nov. Public health & safesty not affected.

 ANDOONINI.G. C. Boston Edison Co. 78/10/05. 3pp. 94236:008
- 78:0180:13 Informs NRC that info requested re effects of elevated temp on safety relief valve discharge loads will be submitted by 78:105 Instead of 78:1001 due to delay in completing transient enelyses.
 ANDODNINS.O C. Boston Edison Co. 78:107:10. ip.
- 781020107 Requests amend to facil operating LicHDPR-35 pertaining to receipt possession & use of byproduct source & special nucleat! Amend may produce more flavibility in plant oper by generalizing approach to lic.
 FELOMANN.M.J. Boston Edison Co. 78/10/16. App.
- 7811030001 Notice of 781018 meeting w/Boston Edison in Bethesda.MQ to discuss BECD proposal to provide augmented dissal generator for startup w/1 dissal generator inoper.

 HANNON.J.N. Operating Reactors Branch 3 (Pre 790625). 78/10/18.
 2pp. 02720:216.
- 7810270103 Responds to 780913 itr request for proposal of corrective measures as recommended by NRC Staff re Emergency diesel generator control & elerm circuitry. Response is considered acceptable for the stated conditions for each criteria. ANDOSNINI.Q.C. Boston Edison Co. 78/10/20. 3pp. 94059:292.
- 7811130333 Summary of 780914 meeting w/GE representatives & Mart 1 Owners Group re progress of Long Term Prog w/attendence list & agenda(RD-9-A-Herki,Standards.) ORIMES.C. Plant Systems Branch (Pre 791030). 78/10/26 67pp.
- 7811070185 Forwards memb summerizing operating history of the "B" distal generator & 3 unique situations that resulted in abnormal stresses. Concludes that feilure of "B" generator stator were not generic problems, but unique to the "B" unit. ANDONNINI.G.C. Boston Edison Co. 78/10/31. 2pp. 94044:191.
- 7811290288 Responde to 781106 request for info concerning licensee reg performence eval for Region 1 plants by NRC. Provides details. GRIER.B.H. Region 1, Philadelphia, Office of the Director. 78/11/09. 9pp.
- 78:2150:39 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out mati. W/encl Registration Form & List of Locations. MILLER. J.R. Assistant Director for Bite & Bafeguards (Pre 791030). 78/11/15. Spp.

- 78:2180259 Forwards Revel "Draft Radiological Effluent Tech Specs" for BMR's(NUREG-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Per Plants" (NUREG-0133).

 GRIYES B K Assistant Director for Engineers & Projects (Pre 790625) 78/11/15 6pp 94365 316
- 78:1270163 Responds to 77:212 request for info & forwards detailed analysis of suppression pool temp transients & monitoring. Concludes that inadvertent opening of eafety relief valve will have no adverse effect in pool or reactor vessel. ANDOGNINI. G. C. Boston Edison Co. 78/11/20. 36pp. 94386.169.
- 7812060223 Registers intent to utilize peckaging(UBA/9122/A.model#18-450)for shipment of Type A & large quantities of redicactive math. Licensed peckaging user of retord is Chem-Nuc Sys. Inc.
 ANDOONINI. 0 C Baston Edison Co 78/11/21 to 94382 165.
- 78:2070:35 Notice of seminer on 78:208 on new Model Radiological Effluent Tech Specs for nuc pur plants. Requests edvants submission of seminer specific questions W/encl Seminar Info Sheet Proposed Agenda & meps.

 ORIER B H Region i. Philadelphia. Office of the Director. 79/11/21. Spp. 79375.208
- 7812050272 Ack receipt of 780227 ltr re need for deedwater pump trip or reactor high water level. Finds proposed sched for installation acceptable.

 IPFOLITO T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/28.
 20p. 94202.223.
- 7812110058 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wiencl AND: e7812080207 TPPCLTC, T. Operating Reactors Branch 3 (Pre 790625). 78/11/29. 8pp 94337.142.
- 7812110166 Advises that Mark I Containment Prog QE Rept, "NEDE-23898-6 Analytical Model for Computing Water Rise In a Sefety/Relief Valve Discharge Line Following Valve Closure" has been transmitted to NRC Should be included on subj facil dkt. ANDOQNINI-0. C. Boston Edison Co 78/11/30. 1p. 94337:085
- 7812140176 Forwards Oct 1978 Prog Activity Review Listing meetings he & providing task-by-task activity summary for the month SOSON-L.J. General Electric Co. 78/12/04. 11pp.
- 7812210238 Responds to Quelity Assurance requirements published in 770804 Fed Register Subj Facil's prog was approved in 751112 NRC ltr.but Facil will extend the scope of that prog to the lic shipping casks now used.

 ANDOGNINI.G.C. Boston Edison Co. 78/12/06 2pp. 94162:353.
- 7812290138 Emphasizes importance of submitting accurate & complete in to NRC by licensees & applicants. Info submitted must be substantiated by date & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB.J. 0. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94310:348.
- 78:12:0367 Forwards add1 info re multiple consecutive safety/relief valve actuation of Mark I containment program.
 BOBON.L.J. General Electric Co. 78/11/13. 3pp.
- Q. Inspection reports, IE Bulletins & correspondence
- 7811100008 forwards IE Inspec Rept#50-293/78-22.on 780905-08 during which no items of noncompliance were noted. SRUNNER.E. J. Region i. Philadelphia. Office of the Director. 78/09/27. 2pp. 94179:258.
- --7811100012 IE Inspec Rept#50-273/78-22 on 780905-08 during which no items of noncompliance were noted, Major areas inspected included: plant opers. IE Circuler 78-08. IE Sullstin 78-03 & LER review. * Region 1. Philadelphia. Office of the Director. 78/09/26. 9p
- 94179: 260.
 7810160080 Forwards Rept on Mgt Heeting#50-293/78-23 held at subj fac
- on 780728.

 BRUNNER, E. J. Region t. Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/28. 2pp. 94003:229.
- --7810160082 IE Mgt Meeting Rept#80-293/78-23 on 780928 re recent ins findings to provide licensee w/info on inspec program. ARCHITZELR.E., MCCABE.E.C. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/28. 3pp. 94003:231.

- 7810170027 Forwards IE Bulletin@78-12 "Atypical Held Material in Reactor Pressure Vessel Welds" requesting action w/in 60 days.6. Jist of JE Bulletins issued in 1978. (see AMD 7810040253)
 GRIEF, B. H. Region i. Philadelphia. Office of the Director. 78/09/29, 6pp. 94241;360
- 7811060176 Forwards IE Circular#78-17 (See AND 7810230221 Docket #50-133 781013)
- ORIEN B H Region 1, Philadelphia, Office of the Director 76/10/13. Ip. 94489 117
- 7811290210 Forwards IE Circular #78-18. "UL Fire Test "W/encl AND: 7811150002 0RIER, B.H. Region 1. Philadelphia. Office of the Director 78/11/06 ip 94237. 341
- 7812260300 Forwards IE Inspec Rept#50-293/78-24 on 781003-06 during which no items of noncompliance were noted. MARTIN.W C. Region 1. Philadelphia. Safeguards Branch. 78/11/08. 2pp. 94349-356
- --7812280309 IE Inspec Rept#50-293/78-24 on 781003-06 during which no items of noncompliance were noted Major areas inspected incl.physical protec inspec.implementation of accepted Becurity Pien & sections of 10CFR73-35.

 MADDEN,H., LADUN,R., DEVLIN,J. Region 1. Philadelphia, Office of the Director. 78/11/07. ip. 94349-358
- 7B120B0185 Responds to 7B0929 NRC ltr & IE Bulletin#78-12 requesting info re reactor welds. Requests extension to 7B1231 for responses as contractor QE needs time for compilation ANDCONINI, Q Q Toston Edison Co. 7B/11/14 lp. 94109:205.
- 78)12150121 Forwards IE Bulletine78-12A.suppl to IE Bulletine78-12 W/antl AND:7011300055 ORIER B H Region 1, Philadelphia, Office of the Director, 78/11/24, ip 94212, 153.
- R. Periodic operating reports & related correspondence
- 7010100130 Forwards Monthly Open Rept for Bept 1978 MCGUIRE, P. J. Boston Edison Co. 78/10/01 1p 94413:002
- 7011210263 Forwards Monthly Open Rept for Oct 1978 MCGUIRE, P. J. Boston Edison Co. 70/11/01 ip 94405:350
- --78:12:10269 Monthly Open Rept For Oct 1978. * Boston Edison Co 78/11/01. 7pp. 94485 287
- 7812200183 Forwards Monthly Open Rept of Nov 1978. MCGUIRE, P. J. Boston Edison Co. 78/12/01 1p. 94158:351.
- --7812200185 Monthly Open Rept for Nov 1978. GAFFNEY, C. Boston Edison Co. 78/12/11. 6pp. 94158:352.
- B Reportable occurrences, LERs & related correspondence
- 7810310158 Forwards LERW78-045/03L-0. MCOURE,P J Boston Edison Co. 78/10/24, 1p. 94090:214.
- MCQUIRE, P. J. Boston Edison Co. 78/10/24, 1p. 94090:214,
- --7810310163 LER#7B-045/03L-0 on 780926 indicator needle for TI-5047 water temp gage emapped off from dusting since the needle had been exposed by a broken protec covering.

 HATHIB: C. J. Boston Edison Co. 78/10/24. 1p. 94090 215.
- 7811080152 Forwards LER#78-047/03L-0. MCGUIRE, P. J. Boston Edison Co. 78/11/02. 1p. 94394:321.
- --7811080196 LER#78-047/00L-0 on 781002: Position of Chief Radiol Engr was incorp into PNP8 organization which assumed responsibilities of Health Physics Organization. Caused by efforts to improve quality of Health Physics Prog.
 MATHIS.C J. Boston Edison Co. 78/11/02. 1p. 94399: 322.
- 7811090161 Forwards LERW78-046/03L-0. HCGUIRE, P. J. Boston Edison Co. 78/11/02. [p. 94043:03].
- --7811090168 LERM78-046/03L-0 on 781006: oxygen analyser valves CV-5065-12, CV-5065-16 & CV-5065-25 appeared inoperable but local observation showed valves working property. Caused by switch misalignment LERW inconsistent w/LERW in cover ltr. MATHR.C. J. Roston Edison Co. 78/11/02 20a 94043-030

- 7811140207 Forwards LERM78-048/03L-0 MCQUIRE, P. J. Boston Edison Co. 78/11/07 ip 94384-345.
- --78111402;2 LER 78-048/03L-0 on 781009 reactor strammed on a load rejection causing generator lockout relay trip. Cause was excessive pilot seat leakage keeping second stage 6 main valve open. Relief/safety valve replaced MATHIB.C J. Boston Edison Co. 78/11/07. 1p. 94384:346
- 7811140183 Forwards LER#78-049/03L-0 MCGUIRE, P. J. Boston Edison Co. 78/11/10 2pp. 94384: 254
- --7811140108 LER 78-049/03L-0.on 781011.uhile performing surveillance testing on diesel generator 8.generator output breaker tripped due to short from one coil to stator Caused by loose laminations. Coils replaced & test re-run satisfactorily.

 MATHIS.C. J. Boston Edison Co. 78/11/10. 2pp. 94384:257.
- 7811210341 Forwards LER#78-050/04T-0.
 MAGUIRG, P. J. Boston Edison Co 7D/11/14. 1p. 94484: 338.
- --7811210345 LERM78-050/04T-0 on 781106:Yankee environ lab indicated that 63pGi/kg of CO-60 existed in sample mussel meat. This exceeds by 10 times the concentration measured at Marshfield control station Resulted from new analysis technique MATHIS.C J Baston Edison Co 78/11/14 1P 94484:339
- 7811280333 Forwards LERW78-051/01X-0 MCQUIRE,P J Seston Edison Co 79/11/22. 1p 94395:351.
- --7811280335 LERM78-051/01X-0 on 781030 M of operable SRM's was reduced below minimum req when SRM "A" was jumpered to sliminate problems w/downscale rod block Caused by inadvertent jumpering of entire "A" SRM trip logic Procedures being rev 80ston Edison Co. 78/11/22: 18. 94395:352.
- 7812040173 Forwards LER#78-052/03L-0 MCOUIRE,P. J Boston Edison Co 78/11/27. 1p 94456: 232
- --7812040176 LERM78-052/03L-0 on 781028:8UAE offgee radiat monitor readings were low caused by shut block valve to FCV-118. Valve was opened Proper flow rate established Valve will be properly identified in future by personnel. MATHIB.C. J. Boston Edison Co. 78/11/27. 1p. 94456:233
- 7812050185 Forwards LER#78-053/01T-1.
 MCQUIRE, P. J. Boston Edison Co. 78/11/29. 1p. 94035: 173.
- --7812050192 LER#70-053/01T-0 on 701116 during repair of fire hydrent facing condenser retube bldg. shut-off valve blew off line causing local flooding & removal of fire suppression from Bvc. Cause was improper reinstallation at retube bldg constr. MATHIB, C. J. Boston Edison Co. 78/11/29 ip 94335:174.
- 7812120135 Forwards LER 78-031/01T-0 MCGUIRE, P. J. Boston Edison Co 78/12/05 1p. 94276: 180.
- --7812120141 LER 78-051/017-0:on 781121, noted that on 781030 number of operable source range monitors reduced below Tech Spec minimium when monitor A was jumpered to eliminate problems w/downscale rod block Caused by personnel & maint error. MATHIS.C. J. Boston Edison Co. 78/12/05. 3pp. 94276:181.
- 7812180168 Forwarda LER#78-054/03L-0.
 MCGUIRE, P. J. Boston Edison Co. 78/12/08. 1p. 94366:037.
- --7812180172 LERM78-054/03L-0 on 781115:during test of reactor water level, level switches L18-263-57A68 observed to trip at values greater than specified in Tech Speca. Caused by minor setpoint drift.

 MATHIB.C. J. Boston Edison Co. 78/12/08. 1p. 94366:038.
- DOCKET 50-295 ZION NUCLEAR POWER STATION, UNIT 1
- 7811240200 Forwards LER#78-091/03L-0. MANDKE,N.E. Commonwealth Edison Co. 78/10/13. 1p. 94458:344.
- F. Security, medical, emergency & fire protection plans
- 7810120080 Forwards analysis of Electrical Cable Penetration Fire Barrier Test conducted on 780619, Also forwards 3rd party observer rept of test & 5 detailed drawings associated w/test.

 NAUGHTON, H. F. Commonwealth Edison Co. 78/09/29. 44p.

DOCKETED ITEMS

- 7812120193 Informs NRC name of fire protec consulting firm hired by CEIL to fulfill requirements of "Fire Protec Organization of Nuc Plant Fire Protec Functional Responsibilities Admin Controls & OA" will be submitted 790201 NAUGHTON, W. F. Commonwealth Edison Co 78/11/30 2pp.
- 7812270365 Forwards correction of item 3 2 5 of fire protec SER Requests delay in advising licenses of acceptability until there is a response to encl 2 of 780626 ltr LAIMS. 9. Plant Systems Branch (Pre 791030) 78/12/07 ip 04227:016
- Q Adjudicatory correspondence
- 7811130202 "Agreed Motion for Special Prehearing Conference & to Set Sched for Further Proc" on 781120.21 or 22 to heer oral arguments & rule on motions to dismiss & to allow citizens to enter limited appearances.
 STEPTOE.P. Commonwealth Edison Co. SCHELL.S. Illinois, State of 78/10/24. 3pp. 03553:355.
- 7811240022 Amended contentions of St of IL re amends to Oper Lics appR-39 & A8 to increase spent fuel storage capacity at subj facils. Asserts that to approve amend would be contrary to NRC polity position Cert of Svc & affidavit encl.

 8EKULER, 8 N Illinois, State of 78/11/01. 9pp 94458:167
- 7811170012 "Order for Special Preheering Conference." The 781024 joint motion of Petitioner. Applicant & Reg Staff for special preheering conference is granted & set for 781120 LUTON.E. Atomic Bafety and Licensing Board Penel. 78/11/02. 2pp. 94115.123
- 7811200423 Notice of appearance by Q Cunningham in proceedings re-subjectly on behalf of NRC. Cert of Byc encl.
 CUNNINGHAM, Q.H. Office of the Executive Legal Director. 78/11/02.
 2pp 94419:185.
- 7812040311 Commonwealth Edison Co Motion to strike contentions & supporting memo submitted by IL Atty General on 781101 Requests that Amended Contentions#2,#6D & #16 be stricken ROWEJ W., STEPTOE.P.P. Isham, Lincoln & Beale. 78/11/09 17pp. 94129:188.
- 7812050047 Motion to amend Contention 6A of Intervenor's amended Contentions filed 781101 by stating that there has been insufficient dev of all credible accident scenarios in subject SEMULER, B. N. 1111nois, State of 78/11/09 3pp. 94334:159
- --7812050051 Memorandum in support of amend contentions Believes staff & Applicant should not be allowed to use the special prehearing conference as means to circumvent the summary disposition process. Myencl Cert of Byc.

 SEXULER, S. N. Illinois. State of. 78/11/09. 14pp. 94334:162
- 7812050054 NRC Steff brief in apposition to the admission of Illinois' proposed contentions 2.6A.6D. & 16 re proposed mod of spent flust pool. Steff visus cover non-remargently litemaing of storage facils.contention wording, vagueness & irrelevance. GDDARD.R. J. Office of the General Counsel. 78/11/09. 7pp. 94334.231.
- 7812120211 Submits typographical corrections to "Memo in Support of Certain Amended Contentions" filed on 781109 by State of IL W/Cert of Svc. SEKULER, B. N. Illinois, State of 78/11/13. 2pp. 94276:066
- 7812120223 Notice of appearance by A Bielausti as counsel for util in proceedings re suby facils.Cert of Byc encl.
 BIELAMSKI, A. P. Isham, Lincoln & Beale. 78/11/16. 2pp. 94277:127.
- 7812270335 Opposes Commonwealth Edison request to increase spent fuel storage as sub, facil. Fears it will become a permanent dump. ROBERTS M. Affiliation Unknown. 78/11/20. 1p. 94230 286.
- 78:1227037: Notification that respondent has been added to set lists for legal & tech branch documents re Spent Fuel Pool Mod proc for sub; facils as of 78:127 & previous pepers in Formal File are encl. (w/o sncl).

 900DARD,R.J. Office of the Executive Legal Director. 78/12/05. ip. 92002-no.
- J. Insurance & indemnity information
- 7812190109 Requests refund of \$6 per mut in excess indemity fee paid

- O Advisory Committee on Reactor Bafeguards reports & correspondence
- 7812060394 Notice of ACRS Subcommittee on Plant Arrangements 781026 open Meeting at 8:30 AM in Washington, DC to review NRC Generic Issue, Sys Interaction in Nuc Pur Plants, Task A-17 & Zion Station Sys Interaction Study HOYLE, J. C. Office of the Secretary of the Commission 78/09/25 20p. 94382:351.
- P. Operating license stage documents & correspondence
- 7812080026 FDIA request for all records incl quentity of radioactive matl disposed of from former Manhatten proj in IL known as Chicago Piles#1, 2 & 3 Matl disposed of in IL by Lindsay Cos at Horris facil & Oresden facil
 HANGELL, 0. Illinois, State of 78/11/06 2pp
- 7810100025 Current schedule for submittal to NRC Staff of required re-ECCS analysis & associated Tech Spec changes is 780105 We Scheduled rev analysis for subj facil to begin late 781031 NAUGHTON.W.F. Commonwealth Edison Co. 78/10/03. 10. 94033:043
- 781012009B Request for add1 info on Startup Physics Testing Rept of 781015 BCHLENCER.A Operating Reactors Branch 1 (Pre 790625) 78/10/03. 3pp 94474-019
- 7810120036 LiceDPR-39 & DPR-48 appl for amend to Tech Specs proposed incorporating ECCS flow requirements re a blow belance test & tamper-proof covers for manual throttle valves.
 REED.C. Commonwealth Edison Co. 78/10/05. 7pp. 94332.299
- 7810180060 Forwards drawing: "Location & Details of Reactor Coolant Put Trip Pans"for subj facil as fire protec response NAUGHTON.H.F. Commonwealth Edison Co. 78/10/10. 1p.
- 7810200113 Responds to 780029 NRC request for overpressure protec Tect Spec. States that util will submit requested info by 781201 NAUGHTON,W F Commonwealth Edison Co 78/10/13 Spp. 94367:342
- 7810250102 Renewal of request to amend facil operating liceOPR-39 & DPR-48 Proposed amend is a combined class I & class III Amend & dogs not require extensive environ impact rept. Tech Spec & Environ Impact statement encl REED.C. Commonwealth Edison Co. 78/10/13. 17pp.
- 7810230194 Requests withdrawal of proposed amend to facil lics DPR-39 & DPR-4B originally submitted in ltm of 760720. Completion of mod re lake discharge tanks necessitates proposed amend be cancelled NAUGATON, H. F. Commonwealth Edison Co 78/10/17 ip. 94052-277.
- 7810300097 Forwards info in response to 780831 NRC ltr re pipe cracks in chem val control due to excessive charging pump vibrations.
 NAUGHTON-U.F. Commonwealth Edison Co. 78/10/24 2pp. 94035:072
- 7811010069 Forwards add1 info re proposed expansion of spent fuel storage capacity of subj facil in response to 780926 NRC request Responds to 27 NRC questions

NAUGHTON, H. F. Commonwealth Edison Co. 78/10/24. 690p. 74302.28

- 781107014B Requests change to Open Lic*DPR-39 & DPR-4B Tech Specettending rod how penalty curve & EFPH clad collapse limits to incl higher region average fuel burnups
 REED. C. Commonwealth Edison Co. 78/10/27. 7pp. 94044.150.
- 7811140002 Notifies applicant of 781128 NRC-sponsered seminar re-Mod-Radiological Effluent Tech Specs for Nuc Pur Plants U/encl Beminar Info Sheet(to be completed & returned by 781117) & Proposed Aganda.

 KEPPLER, J. O. Region 3. Chicago, Office of the Director. 78/11/07.6pp.
- 7811210410 Provides #ddl info in response to questions 13 & 15 in 781024 ltr re leakage rate from spent fuel gool liner, surface data rate as spent fuel pool, potential impact of proposed spant fuel pool mod re gaseous effluents.
 NAUCHTON.W.F. Commonwealth Edison Co. 78/11/08. 3pp. 94483.123
- 7811300147 Forwards "Licensing Rept for Sub; Facil Spent Fuel Rack Mod" in response to 780203 request. ODDARD,R. J. Office of the Esecutive Legal Director. 78/11/03. 94072:031.

- 7811270104 Summary of 781025 meeting w/Subcomm on Plant Arrangements of Advisory Comm on Reactor Safeguards re Sandia Labe presentation of Sys Interaction Methodology Appl in Nuc Pur Plants & subj facil sys interaction study.

 ANGELGIJ. Division of Project Management. 78/11/13. 36pp. 9422:294.
- 7812180021 Notice of wortshops re implementation of training & qual requirements contained in Append B of 100FR73. Requests pre-workshop registration of attenders to facilitate sending out mat). W/enc1 Registration form & List of Locations. MILLER. U.R. Assistant Director for Bite & Bafeguards (Pre 791030). 78/11/15 5pp. 94133:281
- 7812190011 Forwards Rev#1 "Dreft Radiological Effluent Tech Specs" for PWR's(NUREG-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pwr Plents" (NUREG-0133). ORINES, B. K. Assistant Director for Engineers & Projects (Pre 790625), 78/11/15. 6pp. 94214:274.
- 7811270091 Forwards suppl to Facil Cycle 3 Startup Rept re Further Demonstration of Adequate Shutdown Hargin & responses to NRC questions re Cycle 3 Startup Rept Subj facil completed Cycle 3 oper on 760914. REED.C. Commonwealth Edison Co. 78/11/16. 23pp. 94047:216.
- 7812050107 Forwards rev page to Topical Rept CE-1-A: "Qual Assurance Prog. Rev. 6." Rev. reflects Reg. Quidel. 28 & 1.33 rev. TURBAK.M.S. Cammonwealth Edison Co. 78/11/17. 2pp.
- 7811260213 Forwards current lic status list for subj facils W/encl. REED.C. Commonwealth Edison Co. 78/11/20. 9pp.
- 7811300042 Informs CEIL that NRC has contracted w/Mountain West Res Inc to undertake a erries of post-licensing studies of nuc pur stations. Studies will analyse socioacon impacts which occurred during constr & post-constr periods of each plant. DEYOUND, R. C. Division of Bite Bafety & Environmental Analysis. 78/11/20. 2pp. 94071:037.
- 7812270127 Forwards Commonwealth Edison "Addl Info on Proposed Expansion of Spent Fuel Storage Capacity" dtd 781108. W/o encl. BIELAMBKI, A. P. Isham, Lincoln & Beals. 78/11/27, 1p. 94161:084.
- 7812180114 Discusses possible dangers of LDCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing H/encl ANO 7812080207.

 BCHMENCER, A. Operating Reactors Branch 1 (Pre 790425). 78/11/28. 6pp. 94130: 317.
- 7812080095 Forwards CEIL's Proj Mileposts sched for subj facile fuel pool mode. Also included are brief statements providing bases for these mileposts. Requests that NRC staff expedite its review sched to meet 790201 & 790315 completion dates.

 REED.C. Commonwealth Edison Co. 78/11/29. 4pp. 94107:292.
- 7812180236 Forwards Amend#40 to Oper Lic#DPR-39 & Amend#37 to Oper Lic #DPR-48. Also forwards Safety Eval Rept & Notice of Issuence. BCH-ENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/30. Rpp. 94365:001.
- ---7812180239 Amend#40 to Oper LiceDPR-39 Changes Tech Specs to allow boron concentration in pressuriser to be 200 ppm less than reactor coolant loop boron concentration. Corrections are made to Tech Specs, Changes to Tech Specs encl.

 SCHHENCER: A. Operating Reactors Branch 1 (Pre 790625). 78/11/30.6pp. 94365:003
- --7812180240 Amend#37 to Oper LicWDPR-48. Changes Tech Specs to Allow bords concentration in pressurizer to be 200 ppm less than reactor coolant loop bords concentration. Corrections are made to Tech Specs. Changes to Tech Specs encl. SCHHENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/11/30. 6pp. 94365:009.
- --7812180242 Safety Eval Rept in Support of Amend#40 to Oper Lic#39 & Amend#37 to Oper Lic#48.
 SCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/30.4pp. 94265:015.
- ---7812180244 Notice of Issuance of Amend#40 to Oper Lic#39 & Amend#37 to Oper Lic#48.
 BC#HENCER.A. Operating Reactors Branch 1 (Pre 790623). 78/11/30.
 2pp. 94365:019.
- 78:2070211 Responds to NRC 780828 itr requesting overpressure protection Tech Specis. Requests extension to 790215 for submitsion due to receipt of new info.
 NAUGHTON, M. F. Commonwealth Edison Co. 78/12/01. 2pp. 03555:115.

- 7812280129 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS. J. 9. Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp.
- 7812030013 Requests views of Regional Directors on Licenses performance eval of subj facile. Forwards questions to be answered by 771209.

 THORNBURG. H. Division of Reactor Construction Inspection. 77/11/23
- 7812190097 Accepts topical rept#CE-1-A Rev#6. "Come Edison Co Quality Assurance Prog for Nuc Generating Stations." Requests submittal of 36 copies.
 HAAGELM P. Quality Assurance Branch. 78/12/13. 1p.
- 7811280278 Discusses preparations for subj facil Estended Butnup Progincl fuel sipping test & fuel assemblies exam prog. Reaffires request to NRC to expedite lic mod review & approve changes to higher region exerage fuel burnup Tech Specs by 781220 REED.C. Commonweelth Edison Co. 78/11/21, 3pp. 94395.219.
- G. Inspection reports. IE Bulletins & correspondence
- 7811080046 Forwards IE Inspec Repts#50-295/78-20 & #50-304/78-22 on 780809-11-16,17-23-25,30,31,0901-07 & 08 & Notice of Violation
- FIDRELLIA. Region 3: Chicago: Reactor Operations Nuclear Support Branch. 78/10/04. Rpp. 94398: 274.
- --7811080070 Notice of Violation from inspec on 780809-11, 15, 17, 23-25, 30, 31, 0901, 07, 08.

 * Region 3, Chicago, Reactor Operations Nuclear Support Branch, 78/10/04. 1p. 94098: 276.
- --7811080074 IE Inspec Repts#50-295/78-20 & #50-304/78-22 on 780809-11, 16-17, 23-25, 30-31, 0901, 07-08 during which 1 item of noncompliance was noted preparation for refueling. BOYD. D. C., RIDEN, M. D., KNOP, R. C. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/10/04. 11pp. 94398:277.
- 7812050011 Forwards IE Inspec Repts#50-010/78-29,50-237,-254,-295,-304/78-25.50-249/78-27 t 50-255/78-26 on 781002 during which no item of noncompliance were noted.

 KEPPLER, J. O. Region 3, Chicago, Diffice of the Director. 78/10/30.
- --7812050027 IE Inspec Rapts for subjfacile on 781002 during which no items of noncompliance were noted. Major areas inspected inclidiscussion of actions being taken by util to improve its reg performance & tour of Zion station.

 KNDP.R.C. Region 3. Chicago, Reactor Operations Nuclear Busport Branch. 78/10/30. 3pp.
- 7812060231 Forwards IE Inspec Repts#50-275/78-24 & #50-304/78-24 on 780913-15,780920-21,780927-29 % 781004-05 % Notice of Violation. FIORELLI, Ø. Region 3, Chicago, Reactor Operations Nuclear Support Branch, 78/10/31, 2pp. 94382:184.
- --7812060234 Notice of Violation from Inspec on 780913-15,780920-21, 780927-28 % 781004-05.

 R Region 3, Chicago, Office of the Director. 78/10/31. 1p. 74382:186.
- --7812060236 IE Inepec Repte#50-295/78-24 & #50-304/78-24 on 780913-15.
 20-21, 27-29 & 781004-05 during which i item of noncompliance
 was noted: failure to adhere to conditions of Nork Request
 Authorization.
 BCVD.D.C., BIDEN,M.D., KNOP.R.C. Region 3. Chicago. Office of the
 Director. 78/10/31. Spp. 94382:187.
- 7811150063 Forwards IE Circular 78-18.
 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 78/11/06.
- 7812130329 Forwards IE Inspec Repts#50-295/78-23 & 50-304/78-23 on 781012-13 during which no items of noncompliants were noted. HEISHMAN.R.F. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 78/11/09.
- --7812130338 IE Inspec Repts#50-295/78-23 & 50-304/78-23 on 781012-13 during which no items of noncompliance were noted Major areas inspected incl:IE Bulletin & Circular followup & qual of siec equip & independent inspec.
 HUGHER, J. Region 3. Chicago, Office of the Director. 78/11/09. 6pp. 94307:049.

- 7812050287 Forwards IE Bullstin#78-12A. suppl to IE Bullstin 78-12 W/anci ANO 7811300035 KEPPLER, J G. Region J. Chicago. Office of the Director. 78/11/24. 1p
- 7812280002 Forwards IE Bulletin 78-14 KEPRLER, J. O. Region J. Chicago, Office of the Director. 78/12/19. ip 94133 002
- A Periodic operating reports & related correspondence
- 7810180049 Monthly Oper Rept for Beptember 1978. SCH€IDER, H.L. Commonwealth Edison Co. 78/10/03 13pp 94063.065.
- 7811010141 Forwards rapt entitled "Oper Environ Monitoring in Lake Michigan near subj facil-July 1977 thru June 1978, Vols 1-1V MANDREN. Commonwealth Edison Co. 78/10/24. 1p 94095:002.
- --7811010131 Annual rept entitled "Oper Environ Monitoring in Lake MI near subj facil-July 1977 thru June 1978" prepared by NALCO Environ Sciences • Commonwealth Edison Co. 78/11/01. 1617pp. 94095 003
- B Reportable occurrences. LERs & related correspondence
- 7810170184 Forwards LER#78-078/01L-0.
 WANDKE,N E Commonwealth Edison Co. 78/09/15. 1p. 94270:052.
- --7810170189 LERW78-078/01L-0 on 780818 possible use of atypical weld metal discovered in 4-loop PMR Reactor Vessels in subj facils. Interim RCS heatup & cooldown curves calculated & used to provide adequate conservatism until issue resolved. SHANNON, R. E. Commonwealth Edison Co. 78/09/15. 3pp. 94270-053
- 7810170181 Forwards LERM78-084/03L-0 HANDKE,N.E. Commonwealth Edison Co. 78/09/21. ip. 94270:081.
- --7810170187 LER#78-084403L-0 an 780822: Instru dept found xmtr 1F1-446 failed at 103% Percentage nonconservative for low RC flow RC tip.Caused by failure of oscillator in transmitter(Fisher-Porter mod#1082496) ROMERS.C.L. Commonwealth Edison Co. 78/09/21. 1p. 94270:082.
- 7810170207 Forwards LER#78-082/03L-0. WANDKE,N E. Commonwealth Edison Co. 78/09/22. 1p. 94835:339.
- --7810170212 LER#78-082/03L-0 on 780802 during normal aperidatily surveillance for DRT-PR17 (radiat monitor for control room intake from turbine bldg) was amitted. Honitor was aper prior to & after missed surveillance. No affety implications. OST.F. Commonwealth Edison Co. 78/09/22. 1p. 94235:340.
- 7810180050 Forwards LERB78-083/031-0. WANDKE:N.E. Commonwealth Edison Co. 78/09/22, ip.
- 7810170219 Forwards LER#78-089/01T-0.
 WANDKE.N.E Commonwealth Edison Co. 78/09/25. 1p. 94236:158.
- --7810170227 LER#78-089/01T-0 on 780911: during normal open 1C Svc Water Pump was removed for breaker inspec Other 2 pumps were not immediately verified as operable & their standby AC & DC pur supplies not checked Caused by personnel error.

 a Commonwealth Edison Co. 78/09/25. 4pp. 94236:159.
- 7810170225 Forwards LERM78-085/03L-0. WANDKE, N. E. Commonwealth Edison Co. 78/09/26. 1p. 94236:167.
- --7810170228 LER#78-085/03L-0 on 780827: discovered missing belt on unit 1 containment area post sampler blower. New belt installed. MANDKE, N. E. Commonwealth Edison Co. 78/09/26. 1p. 94236:168.
- 7810170214 Forwards LERM78-086/03L-0. WANDME.N.E. Commonweelth Edison Co. 78/09/29, 1p. 94236:151.
- --7810170223 LER#78-086/03L-0 on 780830: containment isolation valves IFCV-ND17A: IFCV-PR2OA: and IFCV-PR248 feiled during test. Valves feiled dus to 011 in instru air. MANDKE, N. E. Commonwealth Edison Co. 78/09/29. ip. 94236: 152.
- 7810170241 Forwards LER#78-087/01T-0. MANDKE.N.E. Commonweelth Edison Co. 78/10/02. 1p. 94236:326.

- --7810170246 LERM78-087/01T-O on 780902 while IA diesel generator was out of svc for testing. IB diesel failed to start due to improper staking of starting air distributor drive bushing causing shift in starting air timing Bushing was restaked.

 ALINGER, W. A. Commonwealth Edison Co. 78/10/03 2pp. 94236.327
- 7810170231 Forwards LER#78-088/03L-0 WANDME:N E. Commonwealth Edison Co. 78/10/06 1p 94236.177
- --7810170234 LERR78-098/03L-O on 780908 During normal oper channel IL-S was found reading higher than other 2 level channels on loop D by over 5% Caused by ateam lesk on root valve on the reference line of XMTR RDDERB, C L Commonwealth Edison Co. 78/10/O6 1p. 94236: 178.
- 7811240127 Forwards LER678-092/03L-0 WANDKE,N.E. Commonwealth Edison Co. 28/10/13, 1p. 94456: 392.
- --7Bi1240129 LER#7B-092/03L-0 on 7B0914 an inadvertent BI occurred when 1A deisel generator was started due to bent plunger spring causing failure of engine trip lockout solenoid valve (ASCO B320) Valves replaced & springs checked AINGER.K. A. Commonwealth Edison Co. 7B/10/13 2pp 94456:333.
- 7811240197 Forwards LER#78-094/03L-0 WANDME:N E. Commonwealth Edison Co. 78/10/13 1p. 94458:303.
- --7811240198 LERRYB-094/03L-0 on 780914: on a phase A isolation, iFCV-PRS & IFCV-HD17A Pailed to close placing containment isolation sys in degraded mode Caused by ASCO 8920 solenoid valve failing to close due to oil in instru air UGOLINI, D. J. Commonwealth Edison Co. 78/10/13. Ip 94450: 304
- 7811240201 LER#78-091/03L-0 on 780914 Damper switching sequence from normal to accident mode caused pressure differential in IB RCFC Pressure differential caused accident inlet damper blades to flex & bend Switching sequence to be changed JOHNSON.R. Commonwealth Edison Co. 78/10/13 Ip. 94958.345.
- 7811240212 Forwards LERW78-090/03L-0.
 WANDXE.N.E. Commonwealth Edison Co. 78/10/13. 1p. 94463:358.
- --7811240213 LERB78-090/03L-0 on 780914 channel IL-938 read higher than IL-939. IL-938 was found to be out of tolerance & appropriate bistables were tripped Caused by steam leak on root valve (3/4 inch manual globalon sensing line.

 ROSERS.C.L. Commonwelth Edison Co. 78/10/13. 1p. 94463:359.
- 7811240221 Forwards LERW78-093/03L-0. WANDME:N E. Commonwealth Edison Co. 78/10/13. ip. 94458:217
- --7811240223 LERR78-093/02L-O on 780914: Following imadevertant SI.ICRCF felles to low speed auto start due to dirty contacts in the low speed hand switch Operating surveillance rev to keep dirty contacts cleen.

 JOHNBON, R. Commonwealth Edison Co. 78/10/13. 1p. 94458:218
- 7811240227 Forwards LER#78-095/03L-0.
 WANDKE-N.E. Commonwealth Edison Co. 78/10/27, 1p. 94458.201.
- --7811240229 LERM78-096/03L-0 on 780904: channel iL-537 higher than 2 redundant channels due to steam leak on root valve (3/4", Hanual Olobe)on sensing line XMTR. Channel failed again on 780908. Root valve replaced.
 ROSERS.C. Commonwealth Edison Co. 78/10/27. ip 94438: 202
- 7811240205 Forwards LER#78-097/03L-0.
 WANDKE,N.E. Commonwealth Edison Co. 78/11/03. 1p. 94458:350.
- --7811240206 LERM78-097/03L-0 on 781004: Unit 1 component cooling radia monitor would not respond to check source Caused by water demaged detector in detector Hell & defective rate board. TRZYNA.O. Commonwealth Edison Co. 78/11/03. 2pp. 94450: 351.
- 7811240207 Forwards LER#78-102/03L-0. HANDKE:N E. Commonwealth Edison Co. 78/11/03. 1p. 74438:353.
- --7811240208 LER#78-102/03L-O on 781006: Westinghouse reported O. 5% err in APDMS limit calculations due to roundoff & addl apparent error totaled 1. 5% creating potential for exceeding APDMS limits. Caused by x. xxx format of APDMS calculations. PERDIKIS.O.C. Commonwealth Edison Co. 78/11/03. 1p. 94458: 394.
- 7908080684 Natification of deficiency found 780913 in valve cross

WANDKE, N.E. Commonwealth Edison Co. 78/11/17. ip 94339.318

- --78:21:10:29 LERM78-106/03L-0 on 7B:020:during refueling autage surveillance, noted that feed water flow Kmtr 1LT-931 had shifted in excess of Tech Spec limits. Caused by transmitter drift. Xmtr recalibr & channel returned to normal. ROSERS.C.L. Commonwealth Edison Co. 78/11/17. ip. 94339:319.
- 7812110144 Forwards LER#78-100/03L-0.

 WANDME, N. E. Commonwealth Edison Co. 78/11/17. 1p 94393:267.
- --7812110147 LERW78-100/03L-0 on 781018 Containment air particulate monitor: IRE0011 blower continually tripped due to low flow. Caused by improper valve lineup of monitor MEYER, B. A. Commonwealth Edison Co. 78/11/17 lp 94393: 268.
- 7812110137 Forwards LER#78-107/03L-0.
 WANDME, N.E. Commonwealth Edison Co. 78/11/17. 1p. 94337:075.
- ~-7812110139 LERM78-107/03L-0 on 781020 during refueling surveillance, noted that steam generator 10 level channel 1L-548 had drifted above Tech Spec accuracy limit Caused by instrudrift of transmitter Instrusubsequently recalls.

 HANSEN,P. W. Commonwealth Edison Co. 78/11/17. 1p. 94337:07b.
- 761210161 Forwards LER878-104/03L-0
 WANDKE, N E Commonwealth Edison Co 78/11/17 ip 94337:001.
- --7812110163 LERB78-109/03L-0 on 781020: during refueling surveillance noted that steam generator 1D level channel IL-538 was 5% high-exceeding 2X loop tolerance Gaused by blocked instruline teading to transmitter Line subsequently cleared. HANDEN, P. W. Commonwealth Edison Co. 70/11/17. 1p. 94337:002.
- 7812110151 Forwards LERW78-110/03L-0. WANDKE,N.E. Commonwealth Edison Co. 78/11/20, 1p. 94339:341.
- --7012110194 LERM78-J10/03L-0 on 701021: surveillance level xmtrs 950,951 for accumulator A & 935,957 for accum 0 were found out of talerance low Caused by Instru drift CAMPBELL.J. Commonwealth Edison Co. 70/11/20 ip. 94339.362.
- 7812110175 Forwards LERM78-113/03L-0. HANDKE, N. E. Commonwealth Edison Co. 78/11/20. Ip.
- --7812110180 LER#78-113/03L-0 on 7010R1: trip point for reactor coolant flow comparator on channel 1F-414 loop A drifted low by 2.625x, exceeding overall loop accuracy of 2x. Caused by wetpoint drift in channel comparator(Hegen ModelMil8). HANSEN, P. W. Commonwealth Edison Co. 78/11/20. 1p 94937: 102.
- 7B12110160 Forwards LER878-120/03L-0.
 WANDME-N.E. Commonwealth Edison Ca. 78/11/R2. 1p. 94337:077.
- --7812110164 LERW78-120/03L-O on 781027:5 shubbers which had smpty reserviors were proven inoperable when bench tested Caused by hydraulic fluid leakage. Leakage sources: reservior seels, leaking body joints & adjustment screw thread seals. RICHARDBON, C. K. Commonwealth Edison Co. 78/11/22. 3pp. 94337:078.
- 7812110179 Forwards LERM78-118/99L-0.
 WANDME:N.E. Commonwealth Edison Co. 78/11/82. 1p. 94337:098.
- ---7B:2110162 LER#76-118/97L-0 on 7B0314: subj facil did not possess Cert of Compliance for packages for 12 shipments of radioactive meth.10CFR71. 12 had been misinterpreted to apply to Hittman Nuclear packages. Registered w/NRC to use Hittman packages. REBCEK, F. Commonwealth Edison Co. 78/11/22 3pp 94337:099.
- 7812210203 Forwards LERW78-121/03L-0.
 HAND& N.E. Commonwealth Edicon Co. 78/12/01. 1p. 94279:093.
- --7812210213 LER#78-121/03L-0 on 781101:M8IV 1D from Train A did not close when signal was removed, caused by relay plunger sticking.
 MELNICOFF, M. A. Communwealth Edison Co. 78/12/01. 1p. 94279:094.
- 7812120121 Notification of deficiency found 780913 in velve cross assemblies, inlet & enhaust push assemblies of KSV Pur Engine & corrective action to design roller pin & replace hand flaring oper.

 BENDER.B. B. Cooper Industries, Inc. 78/11/03. Ppp. 94276:329.
- 7812R10214 Forwards LBR#78-129/03L-0.
 WANDME.N.E. Commonwealth Edison Co. 78/12/06. 1p. 94279; 112.

- was incorrectly valved indentification of personnel & cause interface of event could not be determined. Control room is being investigated.

 TRIYNA, Q. Commonwealth Edison Co. 78/12/06. ip. 94279:113.
- 7012210227 Forwards LER#78-122/03L-0.

 HANCHE,N,E Commonwealth Edison Co. 78/12/07 ip. 94279:127.
- --7612210229 LER#78-122/03L-0 on 761107 fuel bldg area radiat monitor #CRE0005 alarmed high due to erroneous readings in control room & local readouts Caused by failed 9M tuberdetector replaced MEVER, B A Commonwealth Edison Co. 78/12/07. 1p. 94279:128
- 7812210204 Forwards LERW78-095/99x-0.

 MANDKE,N,E. Commonwealth Edison Co. 78/12/11. 1p. 94279:181.
- --7812210239 LERW78-095/99x-0 on 780914: shortly after reactor trip an inadvertant safety injection occurred from a false delta P steam pressure signal generated from shock of feedwater hammer. No damage resulted from safety injection.

 REISB. J. F. Commonwealth Edison Co. 78/18/11. 3pp. 94979:182.

T. Hearing transcripts on non-antitrust matters

- 7812040047 Transcript of 781120 hearing re subj facil spent fuel pool expansion: ppi-180 LUTON.E., RBHICK.F. J., LITTLE.L.W. Atomic Bafety and Licensing Board Panel. 78/11/20. 181pp. 01791: 057
- 7812040045 Transcript of 781121 hearing re subj fecil spent fuel pool expansion.pp. 181-287.
 LUTUN,E., REMICK.F.J., LITTLE.L.W. Atomic Safety and Licensing Board Panel. 78711/21. 107pp. 94026:179.

DOCKET 50-296 DROWNS FERRY NUCLEAR POWER BIATION, UNIT 3

- 7810110107 Responds to 780829 itr indicating there have been no incidents of control rods failing to fully insert on demend at subj facile GittelAND, J. E. Tennesses Valley Authority. 78/10/05. 1p. 94066: 353.
- F. Becurity, medical, emergency & fire protection plans
- 7BiiR00200 Forwards revs to Physical Security Plan of subj facils reinstallation of emergency lighting firtures. Requests withholding from pub disclosure per IOCFR2. 790. OILLELAND, J. E. Tennessee Valley Authority. 78/11/15. 1p. 94292:036.

H. General correspondence

- 7812210334 Comments on 780927 constituent ltr to Legomeraino revelidity of the Reactor Barety Study the subject fire. It the operating performance of commercial nucleur plants. ODBSICH.L.V. Diffice of the Executive Director for Operations. 78/12/12. 13pp. 94014:305.
- J. Insurance & indemnity information
- 7812010236 Forwards PolicyMMF-66-Endorsement#37 for sub; facil Blates solvance premium \$94768.89, reserve premium \$71349.36 & return premium #3125.17.
 FIEDLER, J. Nuclear Insurance Consultants. 78/11/28. 2pp.
- 7Bi1090096 Advence premium & stendard premium endorsement for 1978. BARDEB.C.S. Nuclear Energy Liability Insurance Association. 7B/10/11. 1p. 94042:141.
- K. Utility Final Safety Analysis Report (FBAR) & amends
- 7812200244 Forwards Amend#67 which the FGAR to reflect current plant configuration. Amend does not req review & is available in PDR.
 OILLELAND, J. E. Tennessee Valley Authority. 78/11/30. Spp. 94197: 001.
- --78)2200246 Amend#67 to FBAR. Vols i-7. This amend does not req review.
 it merely rev FBAR to reflect current plant configuration.
 = Tennessee Velley Authority. 78/11/30. 2900pp.

7811170113 Reports that NRC will assist Los Alamos Scientific Lab team in performing vital area enalysis of subject during the week of 781126.
OILLELAND, J. E. Tennesse Valley Authority. 78/11/13. ip.

94047: 145

- 7811170215 Responds to NRC questions prompted by Gilleland's 780811 ltr requesting Tech Spsc changes Change ensures reconfiguration of GRM's & IRM's & will be placed in non-coincidence trip acce. MILLS.L.M. Tennesses Valley Authority. 78/11/13. 1p. 94136:122.
- 7811200080 Requests addl info for review of recirculation pump trip for use to mitigate Anticipated Turansient w/o Boram Info due w/in 60 days.
- LEAR. Q. Operating Reactors Branch 3 (Pre 790625). 78/05/15. 5pp.
- 7810200131 Notice of issuance of Amend#40 to Facil Operating Lic# DPR-03:Amend#38 to Facil Operating Lic#DPR-52 & Amend#14 to Facil Operating Lic#DPR-58:rev Tech Specs for oper of subj facils.Amends lower law water level setpoint.

 19PQLTD.T.A. Operating Reactors Branch 3 (Fre 790525). 78/08/02.

 2pp. 94411:287.
- 7810230244 Forwards responses to verbal questions re proposed changes to Tech Specs of subj facil as submitted 780322.

 GILLELAND, J. E. Tennessee Velley Authority. 78/10/10. Spp. 94170: 242.
- 7810270239 Requests add1 info for review of reload for tycle 2 oper of subj facil. Requests partial responses to questions as info is devik full responses w/in 30 days.

 IPPCLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/10. 3pp. 94029:218.
- 7810940153 Forwards add1 info re proposed differential pressure control torus water level Teth Space for sub; facils.

 OILLELAND, J. E. Tennessee Valley Authority. 78/10/18. 3pp.
- 7810240144 In response to 780807 ltr to N.B. Hughes, the recommended surveillence of reactor protec sys will continue. Request response date extension to 781815.

 OILLELAND, J. B. Tennesses Valley Authority. 78/10/19. lp.
- 7810250080 Response to 781010 ltr requesting additinfo to complete review of reload analysis for cycle 2 open of subj facil. Info supplied we ODYN licensing code, analysis of Limiting Pressure 2 Pur Increase transient, turbine trip, startup test. OILLELAND, J. E. Tennessee Valley Authority. 78/10/20. 4pp.
- 7811130335 Summary of 780914 meeting w/OE representatives & Mark 1 Owners Group re progress of Long Term Prog w/attendance list & agenda(RD-9-A-Markl/Standards.) ORIMES.C. Plant Systems Branch (Pre 791030). 78/10/86. 67pp.
- 7811070132 Forwards hydrostetic pressure testing prog for subj facil. OILLELAND, J. E. Tennessee Valley Authority. 78/11/03. 17pp.
- 7811200406 Forwards results of measurements of radioactive matl in NRC phenton on whole body counter Encl I contains actual amount of each radionuclide present, encl 2 gives ratio of measurements to DOE values & encl 3 gives racommendations. SUTHERLAND, J.T. Region 27. Atlants. Fuel Facility & Materials Bafety Branch. 78/11/09. Upp. 94419:305.
- 7811210288 Notifies util of 781205 seminar in Atlanta to discuss new Hodel Rod Effluent Tech Specs & encl seminar info sheet, registration form & proposed agende. O'REILLY, J. P. Region 2. Atlante, Office of the Director. Region 2. Atlante. Office of the Director. 78/11/09. 3pp. 94485: 212.
- 7811300049 Forwards NRC staff paper, Policy Session Item(8ECY-78-554) re-licenses reg performance evaluation. Three methods for evaluation are: statistic), trend analysis & regional survey method.W/o encl. O'REILLY,J.P. Re Spp. 94071:051. Region 2, Atlanta, Office of the Director. 78/11/15.
- 78:2150148 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73, Requests bre-workshop registration of attendees to facilitate sending out meth. W/encl Registration Form & List of Locations. HILLER.J.R. Assistant Director for Rite & Safeguards (Pre 791030). 78/11/15. Spp.

- GRIHEBIB. K. Assistant Director for Engineers & Projects (Pre 790628). 78/11/15. 6pp. 94356:340.
- 7812050003 Forwards Amends#44.40 & 17 to LiceDPR-33.DPR-52 & DPR-68 safety eval & Notice of Issuance. IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 3PP. 94200:021.
- --7812050009 Amend#44 to Oper Lic.Permits everage pur range monitor bys to be inoperable in refuel modelpermits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clerifies Tech Specs relrod block monitor. IPPOLITO.T.A. Operating Reactors Brench 3 (Pre 790625). 78/11/16. 94200: 024.
- --7812050017 Amend#40 to Oper Lic.Permits average pur range monitor systobe inoperable in refuel mode; permits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clarifies Tech Specs rerod block monitor. 1PPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 29pp. 94200:055.
- --7812050022 Amend417 to Oper Lic Permits average pur range manitar sys-to be operable in refuel modelpermits less than 3 intermediate range monitors per trip channel to be oper in shutdown mode & clarifies Tech Specs re:rod block monitor.

 ** Operating Reactors Branch 3 (Pre 790625). 78/11/16. 16pp. 94200: 0B4.
- --7812050023 Concludes amends do not involve significant hazards, health safety of public will not be endangered by open in proposed menner & activities in compliance w/regs. * Office of Nuclear Reactor Regulation: Director. 78/11/16. 9pp. 94200:102.
- --7812050026 Notice of Issuance of Amend#44 to Lic#DPR-33 amend#40 to Lic#DPR-52 & amend#47 to Lic#DPR-68 which revise Tech Specs.

 IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. Зрр. 94200:111.
- 7813050012 Forwards Amend#45,41 & 18 to Facil Oper Lic#DPR-33,DPR-52 & DPR-68 rev Tech Bpscs as requested in 780803 ltr w/8sfety Evaluation & Notice of Issuance. IPPCLITO,T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/18. Rpp. 94200:188.
- --7812050016 Amend#45,41 & 18 to Facil Oper Lic#DPR-33.DPR-52 & DPR-68 passionus amandmen, as is to Facil Oper LiceDPR-33. DPR-68 to DPR-68 rev Tech Specs to incorp minor changes for leak teeting containment isolation is check valves. Amendels changes limit of 2000 MMD/t fue) exposure.

 IPPDLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/18.
 60pp. 94200:190.
- ---7812050019 Bafety Evaluation Rept supporting Amend#45,41 & 18 to Faci Oper LiceDPR-33,DPR-32 & DPR-68 concluding that proposed changes are acceptable & safety of pub will not be
- endangered by open in proposed manner.

 # Office of Nuclear Reactor Regulation, Director. 78/11/18.
 18pp. 94200: 250.
- --7812050020 Notice of Issuance of Amend#45.41 & 18 to Facil Oper Lic
- 7811280255 Forwards ray to pump & valve testing prog which suppl 780925 ltr.Rev are based on further raylaw of ABME Baction XI requirements.
 - GILLELAND, J. E. Tennesses Valley Authority. 78/11/22, 13pp. 02725: 322.
- 7812110029 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wienci ANO: #7812080207.

 1PPCLITG. T. Operating Reactors Branch 2 (Pre 790625). 78/11/29.

 8pp. 94408:101.
- 7812030171 Responds to 781118 NRC its issuing AmendWiB to Facil Oper LiceOPR-68.Concludes NRC-approved MCPR oper limits are Tech Spec change approval by 790228.

 GILLEAND, J. E. Tennesses Valley Authority. 78/11/30. Spp.
- 7812080189 Informs that due to delays complete response re suppression pool temp transients will be submitted by 780318.

 GILLELAND, J. E. Tennessee Valley Authority. 78/12/01. 1p. 94336: 123.

```
7812140176 Forwards Oct 1978 Prog Activity Raview listing meetings held
  & providing task-by-task activity summary for the month. BOBON.L.J. General Electric Co. 78/12/04 11pp
```

- 7812200141 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result DAVIB.J O. Office of Inspection & Enforcement, Office of the Birector. 78/12/06. 2pp. 94310:354.
- 7812200194 Provides details of mod motor-generator set characteristics w/postulated M-O set oper modes for low-pressure conlant injection valve pur supply installation will be delayed until and of 2nd refueling outage of Unit 3 OlLLELAND J E. Tennesse Valley Authority 78/12/13 App.
- 7812200256 Responds to NRC ltr of 780807 re reactor protect sys pur supply at subj facil. TVA does not believe that concerns expressed by NRC are a problem Further surveillance of the reactor protect sys supplies is unwarranted.

 OILLELAND, J. E. Tennesses Valley Authority 78/12/13 ip 38000 (Ms.)
- 7812270175 Due to incomplete resolution of inevc prog for Unit 1. submittel of rev Tech Bpecs has been postponed until after details of Unit 3 inevc inspecs prog are resolved. OILLELAND. J.E. Tennessee Valley Authority. 78/12/19 1p.

94017:341

- 7812290217 Responds to 781189 NRC itr re containment purging during normal plant oper & request for info re design of all safety actuation aignel circuits which incorp a manual feature Responses will be submitted by 790301.

 OILLELAND, J. E. Tennesses Valley Authority 78/12/21. 2pp. 94191: 188.
- 7811210367 Forwards addl info re multiple consecutive tefety/relief valve actuation of Mark I containment program. BOBON, L. J. General Electric Co. 78/11/13. 3pp.
- 7011090198 Ack receipt of 781016 ltr informing NRC of steps taken to

O Inspection reports. IE Bulletins & correspondence

- correct violations noted during inspec#50-259/78-18, #50-260/78-19 & #50-296/78-17. KENNA, W.B. Region 2, Atlanta, Office of the Director. 78/10/26 Ip. 9403B; 240.
- ~-7611090204 Responds to 780825 NRC ltr re violations noted in Inspec Reptem50-239/78-18, #50-250/78-19 % #50-296/78-17. Corrective actions are exempt from disclosure IAW IOCFR2 790. GILLELAND. J. E. Tennessee Valley Authority 78/10/16. ip. 74038: 261. 7811130006 Ack receipt of 781010 itr informing NRC of steps taken to
- correct violations noted during inspet#50-259/78-17, 50-260/78-18 % 50-296/78-16. SUTEERLANG.J. T. Region 2. Atlanta. Fuel Facility & Materiala Gafety Branch. 78/10/31. 1p. 94075:275.
- 94077: 012.
- --7811130022 Notice of Violation from inspec on 780725-28. * Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/09/10. 1p. 94075:280.
- ~-7811130049 TE Inspec Repts#50-259/78-17, #50-260/78-18 & #50-296/78-16 on 780725-28 during which i item of noncompliance was noted: release of radioactive effluents above limits.
 TROUP, O. L., GIBSON.A.F. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 78/09/15. 8pp 94075: 282.
- 781212005) Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Becurity Safeguards Newsletter. KENNA, M. B. Region 2, Atlanta, Safeguards Stanch. 78/11/17. 4PP.

- 7810310060 Ack receipt of 780127 ltr informing NRC of st torrect violations noted during Inspec #30-239/77-26. #30-260/77-26 & #30-276/77-26 LOND.F.J Region 2. Atlanta, Reactor Operations Nuclea Branch 78/03/01 lp 94094:129
- --7810010064 Responds to 780103 NRC ltr re violations not Repts #50-259/77-26, #50-260/77-26 & 50-296/77-26 Corrective actions are stempt from disclosure due to security into contained in response OILLELAND, J.E. Tennessee Valley Authority. 78/01/2 94094 130
- --7810310069 Forwards IE Inspec Repts #50-259/77-26, #50-296/77-26 on 771213-16 & w/o Notice of Violation.
 - w/held pursuant to 2.770. LONG.F J. Region 2. Atlanta, Reactor Operations Nuc Branch. 78/01/03. 200 94094;131.
- --7810310074 IE Inspec Repts #50-239/77-26. #50-260/77-2; on 771213-16 during which I item of noncompliance was vital green area gate was open & unattended.
 BRADFORD.WH Region 2. Atlanta. Defice of the Direct ALDERSON.C E. Region 2. Atlanta. Reactor Operations Support Branch 78/01/03. 5pp. 94094:133
- 7810110265 Forwards IE Inspec Repts#50-259/78-15,#50-260. 296/78-14 on 780626 during which no items of moncompliwere noted. SUTIERLAND, J. T. Region 2, Atlanta, Fuel Facility & Ma Branch. 78/08/31. 2pp 94079, 142

- --781i130013 Responds to 780915 NRC ltr re violations noted in Inspec Repts#50-259/78-17.#50-260/78-18 %#80-296/78-16. Corrective actions: 18 & 3A RHR heat exchanges inspected & task test initiated. GRLLELAND, J. E. Tennessee Valley Authority. 78/10/10 2pp.
- --7811130018 Forwards IE Inspec Repts#50-259/78-17,#50-260/78-18 & #50-276/78-16 on 780725-28 & Notice of Violation. BUTHERLAND.J.T. Region 2. Atlanta, Fuel Facility & Materials Sefety Branch. 78/09/15. 2pp. 94075:276.

--7810120004 IE Inspec Repts#50-259/78-i5.#50-240/78-i4. on 780626.during which no items of noncompliance wer Hajdr area inspected:whole body counting practices & procedures & test count of NRC phantom HILLEAP.N J Region 2. Atlanta, Fuel Facility & Mat Branch. 78/08/30 4pp. 7810110283 Forwards IE Inspec Repts#50-259/78-19.#50-260 /78-18 on 760720-21 during which no items of noncompli

BUTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Ma Branch. 78/09/01. 2pp. 03555:076

- --7810110286 IE Inspec Repts#50-259/78-198#80-260/78-20. on 780720-21 during which no itams of noncompliance noted Major areas inspected included emergency plann
- almulated amergency conditions. PERROTTI.D. J. Region 2. Atlanta, Fuel Facility & Ma Branch. 78/08/31. 4pp. 94079:144.
- 7811010249 Forwards IE Inspec Repts#50-259/78-20.#50-240 #50-296/78-19 on 780807-10.during which no items of noncompliance were noted.
 LONG.F.J. Region 2. Atlanta. Reactor Operations Nucle
 Branch. 78/09/10. 2pp 94392:160
- - --7811010280 IE Inap Repts 50-259/78-20,50-260/78-21 & 3 on 780807-10, during which no items of nancompliance noted Major ereas inspected; plant operations, reports occurrences & electrical mods.

 BULIVAN.R.F. Region 2, Atlanta, Office of the Dira 78/09/12. Spp.
 - 7810110056 Forwards IE Inspec Rept 50-259/78-24, 50-250/7
 - 50-296/78-23. O'REILLY, J. P. 200. 94063:246
 - --7810110059 IE Inspec Rept 50-259/78-24,60-260/78-27 to 780915. Mosting held he IVA security program & manage changes being implemented.
 OILLEBPIE.F.P. Region R. Atlenta, Sefeguards Branct Son GAOCH-DAG
 - 3pp 94063: 248.

 - 1p. 94165.093.
- 7810230226 Ack receipt of 780922 ltr re corrective steps items of noncompliance found in inspec as notified by ith of 780829.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Direct

Region 2, Atlanta, Office of the Direct

- --7810230227 Responds to 780825 NRC ltr re violations in Repts#50-259/78-18, #50-260/78-19, #50-296/78-17 OILLELAND, J. E. Tennessee Valley Authority. 78/09/ 94145: 094.
- --7810230230 Forwards IE Inspec Repta%50-259/78-18.490-78-17 on 780726-28. 0'REILLY.J.P. Region 2. Atlanta. Office of the Dir 78/08/25. 3p. 94165:095.

- 7810230300 Forwards IE Circular#78-17. (See AND 781023022).borket 50-313.7810131 G'REILLY, J.P. Region 2. Atlanta. Office of the Director. 78/10/13 18 94164:183
- 7812050169 Forwards IE Inspec Rept#50-296/78-27 on 781017 during which no items of noncompliance were noted MURPHY.C. E. Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch. 78/10/25 ip. 94408 299
- --7812050172 IE Inspec Rept#50-296/78-27 on 781017 during which no items of noncompliance were noted. Major areas inspected incl: ultrasonic examination of recirculation notices. ECONOMOS, N. CONLON.T.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 78/10/20 App 94408.300
- 7812050053 Forwards IE Inspec Repts#50-259/78-21,#50-260/78-23 & #50-296/78-20 on 780828-0901 during which no items of noncompliance were noted.

 LONG.F.J. Region 2: Atlanta: Reactor Operations Nuclear Support Branch. 78/10/27. 2pp. 94034:218.
- --7812050057 IE Inspec Repts#50-259/78-21.#50-260/78-23 & #50-296/78-20 on 780828-0901 during which no items of noncompliance were noted Major areas inspected incl: reportable occurrences & followup on IE bulletins & circulars.

 BULLIVAN.R.F. 00278-J.E. Region 2. Atlanta. Office of the Director 78/10/26 10pp. 94334 220.
- 7811150073 Forwards IE Circular 78-18.

 O'REILLY, J. P. Region 2, Atlants, Office of the Director. 78/11/06.

 1p. 94112:288.
- 7812210355 Forwards 1E Inspec Repts#50-259/78-26.#50-260/78-29 & #50-296/78-25 during which no items of noncompliance were noted.

 KENNA, M. B. Region 2, Atlanta, Sefequards Branch. 79/11/08. 2pp. 94014:353
- --7812210363 IE Inspec Repts#50-259/78-26,#50-260/78-29 & #50-296/78-25 during which no items of noncompliance were noted Major areas inspected incl:physical security requirements previous items:elerm,access.communications.

 BEBECKER, K. H., GILLESPIE, F. P. Region 2, Atlante, Befeguards Branch, 78/11/08, 4pp. 94014:335.
- 7812180320 Forwards IE Inspec Repts#50-259/78-25, #50-240/78-28 & #50-276/78-29 on 780725-27 during which no items of noncompliance were noted.

 LDNO.F.J. Region 2, Atlanta. Reactor Operations Nuclear Support Branch. 78/11/09. 2pp. 94336:285.
- --7812180325 IE Inspec Repte#50-259/78-25.#50-260/78-28 & #50-296/78-24 on 78972-27 during which no items of noncompliance were noted Major areas inspected incl:refueling plant oper & LER & IE Circulare/Bullstine review.
 BLLIVAN.R.F. DANCE.H.C. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch. 78/11/09. 6pp. 94356:287.
- 7812130372 Forwards emended response to IE Bulletine78-09.describing steps taken to effect a good seal between drywell head & containment flangs.

 OILLELAND, J. E. Tennessee Valley Authority. 78/11/13. 2pp. 94292:125.
- 7812040369 Forwards IE Bulletin878-12A, suppl to IE Bulletin 78-12. W/ancl ANC: 7811300085. G'REILLY, J. P. Region 2, Atlanta, Defice of the Director. 78/11/24. 1p. 94127:177.
- 7812060015 Ack receipt of 781122 itr informing NRC of steps taken to correct violations noted during inspec#50-259/78-22, #50-260/78-25 & #50-296/78-21.
 SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/11/28. ip. 94418:338.
- ~~7812060021 Responds to 781027 NRC ltr re violations noted in Inspec Rept#850-259/78-22, #80-2260/78-25 & #800-296/78-22, Corrective actions: surveyilance instruc sched change to reflect 18 month testing req. QLLELAND.J.E. Tennessee Valley Authority. 78/11/22. 3pp. 74418:339.
- --7812060026 Forwards IE Inspec Rept#50-259/78-22, #50-260/78-23 & #50-296/78-21 on 780911-14 & Notice of Violation.

 BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/10/27. 2pp. 94415:312.

- --7812060033 IE Inspec Rept#50-259/78-22.850-260/78-25 & #50-296/78-21 on 780911-14 during which 1 item of noncompliance was noted surveillance testing of air cleaning sys TROUP, 9 L. JACKBON. L. 01880N. A F Region 2, Atlanta, Office of the Director. 78/10/27. 9pp 94415.315
- 7812150248 Forwards requests for relief from ABME Section XI exam requirements that would be conducted per subj fecil insverinspec prog Rev insve inspec prog replecting util position will be submitted pending completion of prog dev OILLELAND. J. E. Tennessee Valley Authority. 78/12/11. 21pp. 94213. 293
- 7812280014 Forwards IE Bulletin 78-14.

 O'REILLY,J.P. Region 2. Atlanta, Office of the Director 78/12/19
 2PP. 94131.032
- R. Periodic operating reports & related correspondence
- 7810160106 Forwards Monthly Open Rept for Bept 1978
 DEWEASE, J. 0 Tennesses Valley Authority. 78/10/10. 1p. 94004: 201
- --7810160109 Monthly Oper Rept for Bept 1978.
 DEMEASS.J.Q. Tennesses Velley Authority. 78/09/30. 34pp.
- 7810170161 Monthly Oper Rept for Bept 1978.
 DEWEASE, J 9 Tennessee Valley Authority. 78/10/31. 3lpp. 94226.097.
- 7810300103 Files fish impingement rept for subj facil for 3rd quarter 1978 01LLELAND J. E. Tennessee Valley Authority. 78/10/19. 14pp. 94035:048
- 7811140137 Forwards Monthly Oper Rept for Oct 1978, DEWEASE, J. Q Tennessee Valley Authority. 78/11/09. 1p. 94425:275.
- --7811140140 Monthly Oper Rept for Oct 1978.

 OREEN,D. Tennesses Valley Authority. 78/11/02. 33pp. 94428:276.
- 7812190161 Forwards Monthly Oper Rept for Nov 1978.
 DEWEASE, J. G. Tennesses Valley Authority. 78/12/02. ip. 94340:160
- --7812190162 Monthly Oper Rept for Nov 1978.

 DEMEASE, J. G. Tennessee Valley Authority, 78/12/02. 29pp.
 94340:181.
- B. Reportable occurrences, LERs & related correspondence
- 7810100002 Fowards LER#78-024/03L-0. FDX:H.S. Tennesse Valley Authority. 78/09/29. ip. 94007:302
- --7810100006 LERM78-024/03L-0 on 780911: during refueling while performs: surveillance instru 81-428-31 2 broken wire was found on signal lead for RCIC turbins high steam flow switch PDIS-71-18 which provides RCIC isolation. Loose connection repaired. PITMAN.J.R. Tennesse Valley Authority. 78/09/29. 2pp.
- 7810100042 Forwards LERW78-025/01T-0. FDX:H.S. Tennessee Valley Authority, 78/09/29, ip. 94033:072.
- --TBJ0100047 LERM78-025/017-0 on 780917: during refueling 4 MBTV's exceeded leakage limits. Defective valves will be repaired & retested.

 * Tennessee Valley Authority. 78/09/29. 2pp. 94033:073.
- 7810240146 Forwards LER#78-026/03L-0. FOX:H.S. Tennesse Valley Authority. 78/10/20. 1p.
- --7810240151 LER#78-026/03L-0 on 780924: during refueling outage.ambke detector X8-39-93K8 alarmed w/o proper cause & could not be cleared due to normal aging.

 * Tennessee Valley Authority. 78/10/17. 2pp.
- 7811140165 Supplementary Reportable Documence Rept SFRO-50-296/7822: on 780822; during startup at 3 percent thereal pur. MSRV 1-4 opened & did not completely close resulting in excessive cooldown rate. Caused by excessive pilot leakage. FOX:M.S. Tennesses Valley Authority, 78/11/08, 3pp. 94383:317.
- 7811140168 Supplementary Reportable Occurrence Rept#8FRO-50-296/78Q1

- --7811140195 LERH7B-027/03L-0 on 781012 during refueling outage.panel 3-25-327 was inoperable placing 2 smoke detector somes out of eve Caused by a contact on power transfer relay which failed to close after short power interruption * Tennessee Valley Authority 78/11/08 2pp 94084 273
- 7811140201 Forwards LER#78-028/03L-0 FOX.H 8 Tennessee Valley Authority 78/11/08 1p 94384:333
- ~~7811140205 LER#78-028/03L-0 on 781014 during refuel outage: 1 smoke detector XB-39-1082E in mech equip room on elevation 617 caused false alarm that would not clear Caused by normal natural aging of detector * Tennessee Valley Authority. 78/11/06 2pp. 94384.334.
- 7811160099 Forwards RON50-296/7822. FOX.H 8 Tennessee Valley Authority. 78/11/09. 1p 94135:094.
- --781[[60]04 R0#50-296/7822 on 780822 during startup at 3% thermal pur-MERV 1-4 opened & did not reclase completely, resulting in excessive vessel cooldown rate due apparently to excessive pilot & second-stage leakage in the valves. Tennessee Valley Authority. 78/11/08. 1p 94135 095.
- 7811280294 Forwards LER#78-029/03L-0 FOX.H.B. Tennessee Valley Authority 78/11/21, 1p. 94395:254.
- --7811280298 LER#78-029/03L-0 on 781029: during refueling, while reloading fuel in vessel w/ell rods inserted.2 IRM thannels were inoperable in same trip sys IRM F signal cable was sheared by CRC repair platform IRM H signal cable disconnected. Tennesses Vallay Authority 70:11/15, 2pp 94395:235
- 7812050199 Furwards LER#78-030/03L-0 FDX,H B. Tennessee Valley Authority 78/11/27 Ip
- --7812050201 LER#78-030/03L-0 on 781031 evidence of grease in 6 enubbers located in core spray, main steam & residual heat removal eys Boubbers replaced Recurrence control action incl replacement of grease fittings withous incompatible wiguns. * Tennessee Valley Authority 70/11/27. 3pp. 94331 007.
- 7812110168 RO-50-296/782: Bendix connectors used inside primary containment which failed post-aging environ test were modified by potting plug & receptacle portion of connectors & passed 10 year qualifying tests.

 FDX:H 9 Tennessee Valley Authority. 78/18/06. 2pp. 94037:006
- 7812190110 Forwards LERM78-031/01T-0 FOX.H 8. Tennessee Valley Authority. 78/12/11. 1p. 94381:198.
- --7812190111 LERW78-031/01T-0 on 781128 during CRD acram timing & associated LPRM connect on verification noted that all LPRMs had been connected in reverse order. Caused by lack of explanation in documents describing connection procedure
 Tennessee Valley Authority, 78/12/11, 2pp. 74381:1 74381: 199.
- 7812190119 Forwards LERM78-033/03L-0. FOX.H. B. Tennessee Valley Authority. 78/12/13 1p. 94076:278.
- --7812190122 LER#78-033/03L-0 on 781114: leakage from 35 isolation valves which terminate below suppression pool water lavel exceeded inventory restriction of 20781 cubic feet per 30 days. Caused by wearing of seats on valves. Tennessee Velley Authority. 78/12/13. 1p. 94376:279.
- DDCKET 50-297 NORTH CARDLINA BTATE UNIV. PULBTAR REACTOR G. Inspection reports, IE Bulletine & correspondence
- 7812010182 IE Inspec RepteM50-160/78-04.W50-276/78-02.W50-297/78-04 & #70-0386/78-04 on 780926-27 during which no items of noncompliance were noted Major areas inspec inclinur methornerol & accounting procedures review TODD.0.4., WILLIAMS.0.H. Region 2, Atlanta, Safeguards Branch. 78/10/20, 3pp. 94409:223.
- 7810140037 Forwards Inspec Rept 50-297/78-3 on 780817 during which no item of noncompliance was noted. KENNA.H B. Region 2. Atlanta. Bafeguerds Branch. 78/10/02. 2pp. 74413:034

- Decurity Plan HENNESSEY, R. J. OILLESPIE, F. P. Region 2. Atlanta, Safeguards Branch 78/10/02 5pp 94413-035
- DUCKET 50-298 COOPER NUCLEAR STATION E. NRC Barety Evaluation Report (SER), supple & correspondence
- 7811270041 Review of augmented main steam isolation valve rept has determined that midcycle MSLIV leak testing is no longer required IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790425). 78/11/01
- 94253 337 2рр
- -- 7811270043 "Bafaty Eval Rept of Main Stream leolation Valve Test nitrooms "Barety Ever Rept of Teaching CNB in present fuel cycle for addl mid-cycle MBLTV leak test is approved.

 " Operating Reactors Branch 3 (Pre 790625). 78/11/01. 2pp * Operating Reactors Branch 3 (Pre 790625).
- F. Becurity, medical, emergency & fire protection plans
- 7811220248 Presents results of 781013 meeting re-fire protec. Wencl attendes list, staff review positions agreed to by licenses & review positions licenses agreed to consider further. IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790525). 78/11/01.
- 7812130166 Submits data requested in 781120 NRC ltr re fire inspec review. Subj incl: self contained breathing apparatus, fire emergency radio communication, manual foem suppression & conduit risers in battery room.
 PILMY, J. M. Nebraska Public Power District. 78/12/11. 23pp. 94303: 144.
- P. Operating license stage documents & correspondence
- 7810130233 Notice of Issuance of Amend#52 to Facil Open LicwDPA-46 on 780929 tPPDLtTG.T.A. Operating Reactors Branch 3 (Pre 790625). 78/09/29.
 2pp 94081 342
- 7810130266 Forwards Amend #52 to Facil Oper Lic #DPR-46. as requested in 770722 itr. Bafaty Evaluation & Notice of Issuance.
 1PPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/09/29.
- --7810140015 Amend 852 to Facil Oper Lic MDPR-46 revising tech space for increase in storage capacity of spent fuel pool from 740 to 9366 fuel essemblies. GRIMEB.B.K. Assistan K. Assistant Director for Engineers & Projects (Pre. 78/09/29. 4pp. 94003:17). 7906251.
- --7810140018 Safety Evaluation Rept supporting Amend #52 to Facil Oper Lic MDPR-46 concludes that installation & use of new fusl racks can be accomplished safety & health & safety of pub ⊎ill not be endangered. # Office of Nuclear Reactor Regulation, Director. 78/09/29. 11pp. 94003:175.
- --7810140021 Environ Impact Appraisal for Amend#52 to Facil Oper Lic# BPR-46 concludes that increase in storage capacity for spent fuel pool will not affect quality of human environ. * Office of Nuclear Reactor Regulation, Director. 32pp. 94003: 189.
- --7810140024 Notice of Issuance of Amend M52 to Facil Oper Lic MDPR-46 & Negative Declaration. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/09/29. 22pp. 94322; 306.
- 7810170152 Responds to 780907 NRC ltr re subj Pacil reactor protec sys pur supply Possibility is remote for undetacted or setamic related failures Probability & possible effects are still under analysis No facil mods are proposed at this time. 78/10/06. 2pp. PILANT, J. N. Nebraska Public Power District. 94236-069
- 7810120037 Requests revision of radiological Tech Specs change primary containment & reactor vessel isolation tables emergency plandrills & organization chart Changes are Class 2 amend. PILANT, J. M. Nebraska Public Power District. 78/10/09. Bpp. 94332: 306.

- 78]1130335 Summary of 780914 meeting w/GE representatives & Mark 1 Owners Group re progress of Long Term Prog w/attendance list & agenda(RO-9-A-Mark).Standards.1 GRIMER.C. Plant Systems Branch (Pre 791030). 78/10/26 67pp
- 7811020253 Forwards addl info re exemptions from requirements previously unacceptable covering personnel airlock.belious lesiages & water testing for feedwater check valves W/ oversize drawings PILMT.J M. Nebraska Public Power District. 78/10/30 11pp
- 7811140130 Responds to 780918 ltr requesting add1 info re Quality Assurance Prog. Add1 info will be submitted by 790115 re exceptions which licensee will take relative to requirements contained in the "Orange Book."
 PILWILJM. Nebraska Public Power District 78/11/09 8pp. 94425-239
- 7811200115 Forwards new proposed Tech Specs, amplified because of new 10CRR30 44 Asks NRC to disrepard earlier proposed. Changes gertain to Atmospheric Containment Atmosphere Dilution (ACAD)sys for subj facil. PILNYT.J.M. Nebraska Public Power District. 78/11/14. 13pp 94280:233
- 7812010122 Forwards enalysis in support of functional form used in the centerline temp rise relationships for the thermal plumes. Also attached are centerline temp rise plots showing actual field data points from past monitoring years. PAILY-P.P. Hazelton Environmental Sciences Corp. 78/11/15. 10pp. 94418-027.
- 7812130139 Notice of workshops rs implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendes to facilitate sending out matl. Wiencl Registration Form & List of Locations MILLER.J.R. Assistant Director for Bits & Bafeguards (Pre 791030). 78/11/15 3pp.
- 7812180271 Forwards RevWi "Draft Radiological Effluent Tech Bpecs" for BHR's(NUREO-0473) & "Preparation of Radiological Effluent Tech Bpecs for Nuc Pur Plants" (NUREO-0133). GRIMES K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15 6pp. 94366:079.
- 7812040196 Requests that the rept NEDE-23898-P. "Analytical Model for Computing Water Rise in a Safety/Relief valve Discharge Line Following Valve Closure." be utilized in containment eval program.
 PILANT, J. M. Nebraska Public Power District. 78/11/27. 1p. 94457-128.
- 7812050148 Requests Radiological Tech Specs be rev to incl proposed changes re primary containment surveillance instrureactivity control testable penetrations w/dqubble O-ring seals & safety related Hydraulic Shock Suppressors. PILMT.J.M. Nebraske Public Power District. 78/11/29. 11pp. 94382-056
- 7812110018 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to purging or justification for continuing Wiencl ANG: 87812080207.

 1PPQLITG. T. Operating Reactors Branch 2 (Pre 790625) 78/11/29. 6pp. 94339:265.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held & providing task-by-task activity summary for the month. 8080N/L,J. General Electric Co. 78/12/04, 11pp.
- 7812110197 Forwards request for add1 info re 781109 submittal of quality assurance prog for subj facil. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/12/05. 3pp. 94408:055.
- 7812280105 Emphasizes importante of submitting accurate & complete info to NRC by licenses & applicants. Info submitted must be substantiated by data & celculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J.Q. Office of Inspection & Enforcement, Dffice of the Director. 78/12/06. 2pp. 03555:321.
- 7812260031 Forwards request for add1 info re suppression pool temp transients in order to complete review of topical rept NEDE 21078P "Test Results Employed by QE for 8HR Containment & Vertical Vent Loads."

 DAVIS, D. K. Operating Reactors Branch 2 (Pre 790625). 78/12/13. App. 94020:357.

- 7812270328 Responds to 781205 ltr requesting add1 info re Quality Assurance prog for subj facil PILANT.J.M Nebraska Public Power District 78/12/21 App. 94232 021
- 7811210367 Forwards add1 info re multiple consecutive safety/relief valve actuation of Hark I containment program.
 BDBON-L J General Electric Co 78/11/13 3pp.
- Q Inspection reports. IE Bulletins & correspondence
- 7810140132 Forwards IE Inspec Rept#50-298/78-14 on 780818 during which no items of noncompliance were noted.

 MADEN.O L. Region 2: Atlanta, Reactor Operations Nuclear Support Branch. 78/08/22 2pp. 94422-084.
- --7810140133 IE Inspec Rept#50-298/78-14 on 780818 during which no items of noncompliance were noted. Major areas inspec included rev of IE inspec prog.licensee's enforcement history, assessment of licensee's performance & implementation of security plan.

 SEYFRIT, K.V. MADSEN, O.L. JOHNSON, E.H. Region 4, Dallas, Office of the Director. 78/08/22 2pp 94422 086.
- 7810120012 Forwards IE Inspec Rept#50-298/78-13 on 780815-18 & Notice of Violation MADECN.O L. Region 4. Dellas. Reactor Operations Nuclear Support Branch. 78/08/29. 2pp. 94421:195
- --7810120014 Notice of Violation from inspec on 780815-18 * Region 4, Dallas, Vendor Inspection Branch. 78/08/29. 2pp. 94421:197
- --7810120016 IE Inspec Rept#50-298/78-13 on 780815-18 during which 4 items of noncompliance were noted activities in Tech Spec 6 2 B.4 not rev by Bafety Rev & Audit Board & lic procedures not adhered to for rev of design changes.

 JCHNSON, E.H., KELLEY, D.L., MADEEN, O.L. Region 4, Dallas, Vendor Inspection Branch. 78/08/29 12pp 94421-198
- 781106003: Forwards IE Inspec Rept#90-298/78-19 on 780928-30 & notice of deviation MADEEN.O.L. Region 4. Dallas. Reactor Operations Nuclear Support Branch. 78/09/12 2pp. 94423.306.
- --7811060053 Natice of Deviation from Inspec on 780828-30 * Region 4, Dallas, Reactor Operations Nuclear Support Branch. 78/09/12 1p. 94423:308
- --7811060055 IE Inspec Rept#50-298/78-15 on 780828-30 during which I its of noncompliance was noted: Pailure to maintain 2 fire doors in an aperable status as req by Natl Fire Code. JOHNSON, E.H., VERDUZCO.O. H. MADBEN, O.L. Region 4. Delles, Reactor Operations Nuclear Support Branch. 78/09/12. 6pp. 94423:309.
- 7810110011 Forwards IE Bulletin #78-12 requiring action by util. SEYFRIT.K. V. Region 4. Dallas. Diffice of the Director. 78/09/29.
- 7810230209 Ack receipt of 780919 ltr informing NRC of steps taken to correct deviations noted in Inspec Rept#30-298/78-13.

 MADEEN.Q.L. Region 4. Dallas, Reactor Operations Nuclear Support Dranch. 78/10/04. 2pp. 94488:336.
- --7810230213 Responds to 780827 NRC ltr re violations noted in Inspec Rept#50-298/78-13 Corrective actions document control, test of valves AR-183AV & AR-184AV. PILANT,J.M. Nebreske Public Power District. 78/09/19. 6pp. 94888-398.
- 7810230276 Forwards IE Circuler#78-17. (See AND. 7810230221 Docket 50-133.781013)
 8EYFRIT,K.V. Region 4. Dailes, Office of the Director. 78/10/13. 1p. 74174:355
- 7811200325 Forwards IE Inspec Rept#50-298/78-16 on 780927-29 & Notice of Violetion which is withheld from public disclosure.
 MADERNO, L. Region 4. Delias, Reactor Operations Nuclear Support Brench. 78/10/18. 2pp. 94251-023
- --7811200330 IE Inspec Rept#50-278/78-16 on 780927-29 during which a noncompliance was noted in the area of Physical Barriers.

 Details are withheld from public disclosure.

 WARD. J. J., CALDMELL. R. A., EVANG. E. A., Region 4, Dallas, Reactor Operations Nuclear Support Branch. 78/10/18. ip. 94251:025.
- 7811080106 Ack receipt of 781003 ltr informing NRC of steps taken to correct deviations noted in Inspec Rept#30-298/78-15.

 MADSEN.O.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 78/10/25. ip. 94399:138.

- #50-298/78-15. Corrective ections: hose removed from doprimay. PILANT J M. Nebraska Public Power District. 78/10/03: 2pp.
- 7812180348 Forwards IE Inspec Repts#50-298/78-17 on 781002-05 during which no items of noncompliance were noted. MADEN.Q.L. Region 4. Dellas. Reactor Operations Nuclear Support Branch. 78/10/30. 2pp. 94334.043
- --7812180350 Notice of Violation from Inspec on 781002-05 * Region 4, Dellas, Reactor Operations Nuclear Support Branch 78/11/27. ip. 94356:045.
- --- 7812180356 IE Inspec Repts#50-298/78-17 on 781002-05 during which 2 items of noncompliance were noted feilure to follow procedure for control of valves in liquid control sys & to sched requal lectures for lic operators.

 JOHNSON, E. H. Region 4, Dalles, Reactor Operations Nuclear Support Scento. 78/10/27. 8pp. 94356:046.
- 78:11:30079 Ack receipt of 78:031 itr informing NRC of steps taken to correct violations noted during inspect50-278/78-16.
 MADBEN. g. L. Region 4. Dallas. Reactor Operations Nuclear Support Branch. 78/11/03. ip. 94076:324.
- 7811220124 Forwards IE Circulere78-19. "UL Fire Test." W/encl ANG:7811150002 BEYFRIT,K. V. Region 4, Dallas, Office of the Director. 78/11/06. 1p. 06911:001.
- --7811270129 Responds to 780829 NRC ltr re violation noted in Inspec Rept #50-298/78-13. Corrective actions: OC protedures will be written. QC prog objectives, responsibilities & requirements clarified PILANT, J. M. Nebresia Public Power District. 78/10/25. 2pp. 94271: 284.
- 7812210180 Forwards IE Inspec Rept#50-298/78-18 on 781030-1102 during which no items of noncompliance were noted. MADEEN.G.L. Region 4, Dellas. Reactor Operations Nuclear Support Branch. 78/11/17. 2pp. 94278:323.
- ---7812210184 IE Inspec Repts50-298/78 on 781030-1102 during which no litems of noncompliance were noted hajor areas inspected inclinations, Philow-up on IE Sullatine, Circulars, open items, unresolved items & prior deviations.

 JCHNBON.E.M., CUPP.E.A., MADERN.D.L. Region 4, Delias, Reactor Operations Nuclear Support Branch. 78/11/17. 7pp. 94278:328.
- 7812060261 Forwards (E Bulletins78-12e, suppl to IE Bulletins78-12, w/encl AND:781100055. SEYFRIT.K. V. Region 4, Delles, Office of the Director, 78/11/24, tp. 94371:342.
- 7812060049 Ack receipt of 781120 itr informing NRC of steps taken to currett violations noted during inspect30-298/78-17.

 MADBENIO L. Region 4. Deliasi Reactor Operations Nuclear Support Branch. 78/11/29. ip. 94234:061.
- --7812060052 Responds to 781030 NRC ltr re violations noted in Inspec Repta50-299/78-17. Corrective action: sealed open valve SLC-10 was closed per surveillance procedure & the seal removed & not replaced. PILANT, J. M. Nebrasia Public Power District, 78/11/20. 2pp. 94236-062
- R. Pariodic operating reports & related correspondence
- 7810170268 Forwards Monthly Oper Rept for Sept 1978. LESSOR.L.C. Nebrasia Public Power District. 78/10/05. ip. 94242:194.
- --- 7810170299 Monthly Oper Rept for Bept 1978.
 BURER. P. J. Nebraska Public Power District, 78/10/05. 4pp.
 94242: 195
- 7811160113 Forwards Monthly Open Rept for Oct 1978. LESEOR.L.C. Nebreaks Public Power District. 78/11/03. 1p. 94103:160.

7812130158 Forwards Monthly Open Rept for Nov 1978
LEBEOR.L.C Nebraska Public Power District. 78/12/06. 1p. 94305 115

Medbacks and is bomen nietzicz. ANII/O3

HUNER P J

94135: 161.

- --7812130160 Monthly Oper Rept for Nov 1978. BCRER, P. J. Nebraska Public Power District. 78/12/06. 4pp. 94305.116.
- B. Reportable occurrences, LERs & related correspondence
- 7812120121 Notification of deficiency found 780913 in valve cross assemblies, inlet & exhaust push assemblies of KSV Pur Engine & corrective action to design roller pin & replace hand Flaring oper.
 BENDER, B. B. Cooper Industries, Inc. 78/11/03. 2pp. 94275:329.
- 7810300173 Forwards LER#78-030/03L-0. LEBEOR:L.C. Nebreska Public Power District. 78/09/12. 2pp. 74034:236
- 7810300201 Forwards LERe78-029/03L-0. LESBOR.L.C. Nebraska Public Power District. 78/09/12. 2pp. 94033:319.
- --7810300229 LER#78-029/03L-O on 780814: Core Spray Time Delay Relay did not operate w/in req time limits. Caused by type of relay used relay does not operate properly after periods of inactivity. Design change being prepared to replace relay. PHILLIPB, D. L. Nebraska Public Power District. 78/09/12. 19. 94033: 321.
- 7812030166 Forwards LER#78-031/03L-0. LEBSOR.L.C. Nabraska Public Power District. 78/09/28 2pp. 94335:115
- --7812050170 LER#78-031/03L-0 on 780912: Cooper-Bessemer dissel angine type MSV-16-7 main bearing averheated. Main bearing@10 was damaged due to minimel oil flow during engine coastdown.

 Caused by Poreign particles in oil.

 BEDNAR.L.F. Nebraska Public Power District. 78/09/28. 1p. 94335:117.
- 7810300177 LERB78-030/03L-0 on 780815:13 primary containment genetrations were identified which were not leak tested. Penetrations were not identified in preoper testing. Penetrations added to Yech Spet Table 3.7.2 will be tested. PHILLIPS.D.L. Nebraska Public Power District. 78/09/12. 1p. 94034:238.
- 7812050135 Forwards LERW78-032/03L-0. LESBOR.L.C. Nebreske Public Power District. 78/10/13. 299-94036-057
- --7812050138 LER#78-032/03L-0 on 780918: during normal oper-after cooling down the torus.RNR Heat Exchanger 18 SupassMRNR-MO-668 failed to oper-due to loose set screw on yoke of Limiterque SMS-3 operator.

 BMRMS-C. Nebraska Public Power District. 78/10/13. 1p. 94335-039.
- 7812050144 Forwards LERM78-033/03L-0. LE860R.L.C. Nebraska Public Power District. 78/11/13. 2pp. 94334:352.
- --7812050145 LER#78-033/03L-0 on 781016:cable HP38.Div 1, was found route thru Div 11 riser under panel 9-3.Caused by personnel error during constr. Redundant sys were operable.
 BEDNAR, L. F. Nebraska Public Power District. 78/11/13. 1p. 94334-334.
- 7812200299 Initial Notification of Reportable Occurrence 50-298-78-25 on 781124. Recirculation M9 Bet 8 was tripped, then a fuse was pulled for exam, allowing M0 Bet 8 to ramp up in speed, causing fast pur increase. Due to personnel error. LEBBOR. L. C. Nebraska Public Power District. 78/11/29. 2pp. 94204: 002.
- 7812290197 Forwards LER#78-034/03L-0. LESBOR:L.C. Nebraska Public Power District. 78/12/07. 2pp. 94190:185.

Control Red Uperability, control red 50-51 was volume uncoupled from its control red drive. Cause cannot be determined until control red drive is removed & examined. BALLINGER.P. Nebreske Public Power District. 78/12/07. 1p. 94190 187.

- 7812200271 Forwards LER#78-033/01T-0 LESSOR.L C. Nobraska Public Power District. 78/12/08 2pp
- --7812200274 LER#78-035/017-0 on 781124-while checking RR MO Set 1D speed control. I amp fuse(FZ) in drive amplifier circuit was pulled out & checked Caused rapid increase in pur level tripping RR MO Set 1B BEDNER.L F Nebraska Public Power District. 78/12/08. Ip 2007 149

DOCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

F. Security, medical, emergency & fire protection plans

- 7811150167 Forwards copies of Rev#8 to Emergency Plan Manual. BURSTEIN.8 Hisconsin Electric Power Co 78/11/06. 2pp. 94223-001.
- --78ili30i73 Rev#8 to Emergency Plan Manual covering reporting of radiat incidents & emergencies to Reg agencies med assistance, minor radiat incidents-major radiat emergencies & gen health physics procedures
 * Historisin Electric Power Co 78/09/13 222pp. 94223-003.
- 7812260169 Forwards Rev#9 to Emergency Plan Manual for subj facil to to replace outdated pages of Manual.
 BURSTEIN.9. Hisconsin Electric Power Co. 78/12/14 2pp. 94159: 294
- --7812260172 Rev#9 to Emergency Plan Manual for subj facil replacing outdated pages of Manual. + Historian Electric Power Co 78/12/14 9pp. 94159: 296
- Q. Adjudicatory correspondence
- 7812040183 Dismisses Contention#4 of Intervenors; sustains objections raised by applicant MIEP to intervenors' Contention#10 & intervenors' intervenors' intervenors et their Contention#9 Contentions concern security plans & health cere plans.
 MILLER.M E Atomic Safety and Licensing Board Panel 78/11/17 4pp. 94457.081.
- 7812080175 Dives notice that effective 781122.8 Berson withdraws as NRC representative in proceeding re-subj facil Certificate of 8vc encl.
 8ER90N.B.A. Office of the Executive Legal Director. 78/11/17. 3pp. 94107:255
- 7810110017 Interrogetories propounded to Applicant re environ & safety aspects of proposed facil.

 Affiliation Univown. 78/09/27. 12pp
- 7810110018 NRC Staff first set of interrogatories to. & Request for the
- 781011001B NRC Staff first set of interrogatories to. & Request for the production of documents from St of WI Case involves amend to LickDPR-24 & 27 re increased spent fuel storage capacity BERBON.8.A. Office of the Executive Legal Director 78/09/29 13as
- 7810110023 NRC interrogatories to & request for production of documents from intervenor Lakeshore Citizens for Safe Energy Admitted contentions also submitted BERSON B. A. Office of the Executive Legal Director. 78/09/29 39pp. 94063:091.
- 7810110072 NRC Staff Interrogatories to & request for the production of documents from applicant per IOCFR2.7406 re amend to lic MDPR-24 & DPR-27. Admitted contentions also submitted DERBON.S.A. Office of the Executive Legal Director. 78/09/29. 14pp. 94061:116.
- 7810130223 Bubmission of interrogatories by applicant WIEP to intervenor Lakeshore Citizens for Bafe Energy. Interrogatories addressed to contentions contained in intervenor's amended contentions.

 TROUBRIDGE, G. F. Shaw, Pittman, Potts & Trowbridge. 78/10/02. 6pp. 74081:345.

94005-319.
--7810190088 Interroos asked of applicant WMPC by St of WI pertaining

store's costeion to tech merit de pach intorvenor

LAFOLLETTE.8 C . WALSH.P

Lakashore Citizens for Bafe Energy's admitted contentions

--7810190088 interrogs asked of applicant WMPC by St of Wi pertaining maint of spent fuel pool in particular danger from radiat emission & exposure.
WALSH.P Wisconsin. State of 78/10/02. 10pp.

Wisconsin, State of. 78/10/02

Зрр

- 7810230326 Applicant. HI Elec Pur. objections to interrogs submitted by Intervenor, Lakeshore citizens for safe energy, are stated.

 Objections based on Interrog's reliance on contentions that were rejected by ASLB or are still being argued.

 TROUBITIONE, 0. F. Shaw. Pittman. Potts & Troubridge 78/10/12 6pp. 24194-179.
- 7810260222 NRC advises NASL® that issuance of SER & environ assessment will be delayed until Dec 1978 due to reording of NRC tech staff's priorities w/respect to review efforts on pending appls. Delay has been discussed w/applicant's representative BERBON.B A. Office of the Executive Legal Director 78/10/17 ip 94036:183.
- 7811200275 "Lakeshore Citizens for Safe Energy Responses to the NRC Staff's First Sat of Interrogs." Urges evaluation of airborne emissions which add to existing background radiat Cert of Svc encl SCHAEFER.H. Lakeshore Citizens for Safe Energy. 78/10/25. 22pp. 94250: 280
- 7811200268 "Lakeshore Citizens for Safe Energy Responses to the WI Elector Co's First Sat of Interrogs " Defines "increased worker activity" re spent fuel pool activities ESTES. J. Lakeshore Citizens for Safe Energy 78/10/26 App. 94250:271
- 7811150262 "Applicant's Answers to Interrogs Propounded by Intervenor on 780927" Cert of Svc encl NEWTON:R A Wisconsin Electric Power Co. 78/10/27. 6ipp 94273:167
- 7811150089 Answer by NRC Staff to interrogs of St of WI re contentions of Lakeshore Citizens for Safe Energy who oppose amends to lits for subj facil concerning increase in spent fuel storage capacity. Affidavits & Cert of Svc encl.

 BERSON, B A Office of the Executive Legal Director 78/11/01 55pp. 94113.200.
- 78:1240:19 Applicant WIEP's answers to interogs propounded by Bt of HI on 70:1002 re amend to lies for sub; facile to increase spent fuel storage capacity. Supporting documentation & Cert of Svc ancl NEWTON,R A. Hisconsin Electric Power Co. 78/11/01 39pp. 94449, 201.
- 7812040344 Forwards Affidavits of CM Trammell & FM Altmeter of NRC Staff. BERBON-B.A. Office of the Executive Legal Director 78/11/08 4pp 94131 Aug
- 7812050049 Applicant's answers to 780929 NRC interrogs relamend to LICMDPR-24 & MDPR-27. Increasing Bpent Fuel Storage Capacity. W/list of names background & professional quals of witnesses & answers relpotential incremental airborne releases. NEWTON.R.A. Wisconsin Electric Power Co. 78/11/08. 23pp. 94334:188
- 7812140359 Swears that listed persons have been authorized by intervenors LACSE to respond to interruge submitted by NRC Staff & applicant WIEP re LACSE contentions BAST.8.A Lekeshore Citizens for Safe Energy. 78/11/13. ip 03557:203.
- 7812270050 St of WI's Answers to NRC Staff's first set of interrogs & request for production of documents. St has not yet located qualified uitnesses re admitted contentions. Cert of Svc encl.
 WALDW.P. Wisconsin, State of 78/11/14 3pp 94160:261.
- 7812270452 Intervenors request NASLB for leave to w/draw.Intervenor, WEPCD.NRC staff & St of WI move NASLB to enter order to approve w/drawel of Intervenor as party & enter Order dismissing proc. Agreement & Cert of Svc encl.
 BAST.S.A. Lakeshore Citizens for Befe Energy. BARTH.C.A. Office of the Executive Legal Director. CHURCHILL.B.W. Wisconsin Electric Power Co. 78/12/13. 9pp. 94016:008.

- H. General correspondence
- 7812140368 Requests copies of NURE9-0410 & NURE9-0471. BUST.S.A Lateshore Citizens for Safe Energy. 78/11/13. 1p. 03857:244.
- P. Operating license stage documents & correspondence
- 7811140133 "Analysis of Capsule R from HI Elec Pur Co Fecility Reactor Vessel Radiation Surveillance Program." YANICHKO, 8.E., ANDERSON. B.L. Westinghouse Electric Corp. MCAP-9357. 78/08/31. 62pp. 94383:176.
- 7811170297 Forwards rough dreft workingpapers on subj facil amended Security Flam, intended solely for use of UR Barggren. Comments withheld from public disclosure pursuant to 2.790. ROSE. D. 9. Los Alamos Scientific Laboratory. 78/11/01. 3pp. 02766:230.
- 78:2010225 Requests amend to Fecil Oper Lic to incorp changes to Tech Bpecs Changes consist of rev to reactor coolant sys heatup & cooldown limitation curves for oper of subj facil. M/check for 84, 400, 60.

 BURBTEIN-8. Wisconsin Electric Power Co. 78/11/16. 6pp. 94409:326.
- 7810250016 Request for additinfoire expansion of spent fuel pool storage capacity, which will region-site neutron attenuation testing of boron plates that are to be in pool, removel of which will requested rept to NRC SCHMENCER.A. Operating Reactors Brench i (Pre 790625), 78/10/03.38 p.
- 7810170153 Responds to 780913 ltr requesting sched for submittel of rev ECCB cooling performance analysis Submittel of completed ECCB analysis to NRC will be on or before 790112 Analysis will use new Hestinghouse ECCB swal model.

 BURSTEIN, B. Wisconsin Electric Power Co. 78/10/10. 1p. 94236:08B.
- 7810230272 Forwards responses to requests for add1 info re spent fuel storage expansion plans for subj facil Discusses fuel loading limit radiat dose in Boraflex plate, thickness of stainless steel inner can fuel region dimension.

 BURSTEIN 8. Historian Electric Power Co. 78/10/10. 44pp. 94167-105.
- 7810190130 Forwards copy of 780510 ltr from subj facil to Univ of WI. COLLING.P.F. Operator Licensing Branch. 78/10/11. 1p. 94414:027.
- --7810190133 Requests copy of 780510 ltr be sent to Univ of MI. Ack 780609 ltr to WI Elec has been placed in Univ of MI. JACOBSON. N. Affiliation Unknown. 78/09/25. 1p. 94414:028.
- --7810190136 Responds to 780413 NRC itr re admin of licensed Oper Requal Prog. Nine examinations were regraded IAM conversations of 780420 & 21.Results of the regreding are attached. Regraded scores will be used at record scores. REED. 9. A. Wisconsin Electric Power Co. 78/05/10. App. 74414:029.
- 7810190101 Dutlines agreement reached re proposed use of rod banks awap measurement technique to confirm adequate reactor shutdown capability. Technique to be used for subj facil only further use must obtain NRC generic approval.

 8CHMENCER.A. Deprating Reactors Branch 1 (Pre 790625), 78/10/12.

 4pp. 94413: 272
- 7810310016 Summarizes meeting on 780929 re Westinghouse rod bank swap measurement prog.
 ROSENTHAL J. E. Reactor Safety Sranch (Pre 791030). 78/10/13. App. 24004. 202
- 7811130203 Forwards Tech Spec change Request 56 to DPR-24 & DPR-27. Tech Spec 15.3.15 "Overpressure Mitigating Sys Oper." entl outlining functional requirements & limiting conditions for oper re pressurizer pur operated relief valve.
 BURSTEIN-8. Hisconsin Electric Power Co. 78/11/02. 16pp. 03594.001.
- 781i140i24 Forwards reactor matis surveillance capsule test repts for subj facils. Conservatiam in the curves used to predict the change in transition temp as a function of fluence is clearly demonstrated by the results.

 8URBTEIN, 8. Wisconsin Electric Power Co. 78/11/08. 3pp. 94381;113.

- 7812150203 Notice of workshops to implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out math. H/encl Registration Form & List of Locations. MILLER. J. R. Assistant Director for Bite & Bafeguards (Pre 791030). 78/11/13. 5pp.
- 7812190060 Forwards Rev#1 "Draft Radiological Effluent Tach Space" for PHR 's (NAREG-0473) & "Preparation of Radiological Effluent Tech Bapec for Nuc Pur Plants" (NUREG-0133).

 ORIMES 8, K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 60p. 94215:095.
- 7812090188 Request to amend Facil Oper Lic to incorp changes to Tech Bpeck re testing of containment isolation valves valve & pump testing code requirements main steam stop valve periodic testing & auxiliary feedwater pumps testing.

 8URSTEIN.8. Hisconsin Electric Power Co. 78/11/27. 11pp. 021% 110
- 7812150008 Discusses presible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing. H/enc] AND #7612080207.
 8CHMENGER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/28. 6pp. 94209:230.
- 7812210320 Forwards request For add1 info re subj Facil expension of 8pent Fuel Storage capacity.

 8CHENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/12/06.
 5pp. 03556:104.
- 7812270389 Responds to 781113 request t encl "Generic Task Problem Descriptions" NUREG-0471)& "NRC Prog for Resolution of Generic Issues Related to Nuc Pur Plants" (NUREG-0410), M/a encl.

 8ARTH.C.A. Office of the Executive Legal Director. 78/12/06. Ip.
- 7812280060 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiable by data & talculations. Licensee must notify NRC of any inecuracies or enforcement action will result. DAVIS.J. Q. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94085:360.
- 7812290110 Ack receipt of 781116 appl for amend to Lics#DPR-24 & 27. Requests addl #3600 lic fee.
 DIQUER, M. License Fee Hanagement Branch. 78/12/20. lp. 94191.338
- G. Inspection reports, IE Bullatins & correspondence

94229: 286.

- 7810270371 Forwards 1E Inspec Rept #50-301/78-19 on 780907-06 during which no items of noncompliance were noted. FIGRELLIA. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/09/20. 2pp. 94030:178.
- --7810270376 IE Inspec Rept 50-301/78-19 on 780907-08 during which no items of noncompliance were noted. Major areas inspected included reactor physics test performed prior to full per oper for Cycle 5.
 KGMLER, V. E., 8TREETER, J. F. Region 3. Chicago, Reactor Departions Nuclear Support Brench. 78/09/19, 4pp. 94030:180.
- 7810130054 Ack receipt of 780911 ltr informing NRC of steps taten to correct violations noted in ltr of 780822 re noncompliance & rev of adequacy of the weld repair.

 KEPPLER, J. Q. Region 3. Chicago, Diffice of the Director. 78/10/05.

 19. 74421:026.
- 7810190079 Forwards IE Inspec Repts #50-266/78-14 & #50-301/78-18 on 780822-25. Notice of Violetion w/held pursuant to 100FR2. 790. HIND.J.A. Region 3. Chicago. Safeguards Branch. 78/10/10. 2pp. 94007:023.
- 7810230332 Forwards IE Circular#78-17. (8se AND: 7810230221, Docket 50-313-781013)
 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 78/10/13. 1p. 94181; 355.
- 7811210415 Forwards IE Inspec Repts#50-266/78-15,#50-301/78-20 on 78091-15 during which no items of noncompliance were noted. FIORELLI, Q. Region 3. Chicago, Reactor Operations Nuclear Support Brench. 78/10/16. 2pp. 94483:132.

-- 7811140131 Handwis of Consult T down by Clas Bur On Castling Boscher

- --7811210436 IE Inspec Repts#30-266/78-15.#80-301/78-20 on 780911-15 during which no litems of noncompliance were noted.Major areas inspected included:plant oper.procurement nonroutine event to safety injection reset procedures.

 CHOWLES N.C., HUMES J., HARNICK R.F. Region 3, Chicago. Office of the Director. 78/10/16. Iipp. 94493:134.
- 7811070374 Responds to IE Bulletin#78-12 dtd 780929 re atypical weld asti in Reactor Pressure Vessel welds. Vessels in subj facil antedate the atypical mati, so the matter does not apply.

 BURBTEIN, B. Wistonsin Electric Pawer Co. 78/10/26. 6pp. 94043:245.
- 78:1060072 Notice of Violation-failure to rept a significant fish kill-appended to 780612 ltr is retracted. Thirty six fish killed is not significant to warrant a rept.
 KEPPLER, J. G. Region 3. Chicago, Office of the Director. 78/10/31.
 1p. 94423:334.
- 7811150071 Forwards IE Circular 78-18. KEPPLER.J.Q. Region 3. Chicago. Office of the Director. 78/11/06. 1p. 94112:272.
- 7812290068 Forwards IE Inspec Repts #50-266/78-22 & #50-301/78-23 on 781017-20 during which no items of nancompliance were noted. FIORELLI.G. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/11/22. 2pp. 94190:047.
- 7812290074 IE Inspac Repts #50-266/78-22 & #50-301/78-23 on 781017-20 during which no items of nancompliance were noted. Major areas inspected incl. calibr t surveillance of safety related components and equip.

 STRETER, J. F., BMITH, J. D. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/11/20. Spp. 94190:049.
- 781205027) Forwards IE Bulletin#78-12A.suppl to IE Bulletin 78-12. W/encl AND: 7811300055. KEPPLER.J.G. Region J. Chicago, Dffice of the Director. 78/11/24. 1p. 94202: 218.
- 7812290022 Forwards IE Inspec Rept#50-266/78-21 & #50-301/78-22 on 781023-26 during which no items of noncompliance were noted. FIORELLI, 0. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/11/24. 2pp. 94207:352.
- -7812290032 IE Inspec Repts#50-264/78-21 & #50-301/78-22 on 781023-26 during which no items of noncompliance were noted. Hajor areas inspected incliquality assurance prog.records. nonroutine event followup & noncompliance followup. CHOWLEB, N. C.; WARNICK, R. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/11/21. 6pp. 94207:334.
- 7812280036 Forwards IE Sulletin 78-14.
 KEPPLER, J. O. Region 3. Chicago, Défice of the Director. 78/12/19.
 19. 94103:216.
- R. Periodic operating reports & related correspondence
- 7812120085 Forwards Monthly Open Rept for Nov 1978. 8URSTEIN:8. Wisconsin Electric Power Co. 78/12/08. 1p. 94274:181.
- --7812120087 Monthly Oper Rept for Nov 1978.

 * Wisconsin Electric Power Co. 78/12/05. 9pp. 94274:182.
- 7810180099 Forwards summary Tech Rept: "Reactor Containment Bldg Integrated Leskage Rate Test for March 1978." BURSTEIN.B. Wisconsin Electric Power Co. 78/10/05. 1p.
- --7810180102 Bummary rept: "Reactor Containment Bldg Integrated Leakage Rata Test for March, 1978". Finds that overall leakage rata is 0.0757 plus 0.07574% per day. Test type: Second periodic type "A". BRUCKNER, Q. E. Hisconsin Electric Power Co. 78/10/05. 216pp.
- 7810170171 Forwards Monthly Open Rept for Sept 1978.
 BURSTEIN.S. Wisconsin Electric Power Co. 78/10/09. 1p. 94270:036.
- ---7810170173 Monthly Open Rept for Bept 1978.

 * Wistonsin Electric Power Co. 78/10/05. 9pp. 94270:037.
- 8. Reportable occurrences. LERs & related correspondence
- 7810180043 Forwards LER#78-012/01X-0.

 **BURSTEIN, 8. Misconsin Electric Power Co. 78/09/12, 1p. 94422:056.

- --7810180046 LER#78-012/01X-O on 780627: during visual inspec of fire barrier penetration seals, horizontal seals found to be constructed differently than specified Error due to change in constructed differently than specified Error due to change in constructed differently than specified Error due to change in construction. No reportable item exists. BURSTEIN: Hisconein Electric Power Co. 78/09/07. 1p. 94422:057.
- 7811210349 LER#78-010/11-0 on 780928: reactor coolant sys pressure, dropped Rate in decrease reached 25 psig per minute. Pressure decrease caused by failed electo-air signal converter.

 GREENWOOD, J. Wisconsin Electric Power Co. 78/09/29. 2pp. 94484: 335.
- 7811240130 Forwards LER#78-010/01T-0. BURBTEIN.8. Wisconsin Electric Power Co. 78/10/12. 1p. 94456:355.
- --7811240136 LER#78-010/01T-0 on 780928: reactor coolant sys pressure began dropping at 25 psi per minute; pressurizer apray value 4318 found partially open despite shut signal due to 0 set point drift causad by heat degradation in transducer. SURBIEIN.8. Wisconsin Electric Power Co. 78/10/12. 2pp. 74456:356.
- 7811240131 Forwards LER#78-009/03L-0.
 BURSTEIN, B. Wisconsin Electric Power Co. 78/10/13. ip. 94456:358.
- --7811240134 LERB78-009/03L-0 on 780913: on 2 occasions, 2 of 3 charging pumps were isolated, 2 3/4" crosby relief valves leaked through causing temporary loss of charging flow. Charging pump relief valve replaced & A pump returned to 8vc. BURBTEIN, 8. Hisconsin Electric Power Co. 78/10/13. 2pp. 94456:359.
- DOCKET 50-302 CRYSTAL RIVER NUCLEAR PLANT, UNIT 3
- F. Becurity, medical, emergency & fire protection plans
- 7810200160 Confirms 781006 rept re patential problem in use of Duct Beal compound used in facil cable spreading room. Util is evaluating the matl & will rept in 14 days.

 BEATTY, D.P. Florida Power Corp. 78/10/10. ip. 94412:012.
- 7811170103 Forwards Rev 8 to Security Plan for subj facil Rev attempts to respond to difficiencies identified by NRC Security Review Team Bince plan contains proprietary info, FPC requests that it be withheld from public disclosure pursuant to 2.790.

 BTEWART, W. P. Florida Power Corp. 78/11/10. 1p. 02765, 266.
- 7811280382 Request for add1 info me fire protecting as described in 770622 submittel. W/encl questionneire. NRC Staff Positions & request for drawings covering fire hazard analysis. Instru air sys & valve concern.
 REID, R. M. Operating Reactors Branch 4 (Pre 790625). 78/11/14.
 20pp. 94397:265.
- 7812210453 Forwards request for add1 info re fire protec prog. Buppl 781114 NRC request resulting from review of 780530 facil submittal on administrative controls. REID, R.M. Operating Reactors Branch 4 (Pre 790625). 78/11/21. 3pp 94168:020.
- 7812140127 Requests titls changes to Security Plan Revs#6.7, & 8 to "Mod Amended Security Plan" (780202). "Rev#1" to the MASP (780517), & "Rev#2" to the MASP (781010) respectively, Mysncl new cover sheets. Amend w/held pursuant 2. 790.

 BTEMART.W. P. Floride Power Corp. 78/12/11. 4pp. 94123:328.
- H. General correspondence
- 7812270168 Requests placement on distribution list for correspondence & repts dealing w/oper status for subj facils.
 SHREVE.J. Florids, State of. 78/12/18. ip. 94018:090.
- J. Insurance & indomnity information
- 7811160123 Forwards copy of Amend #5 to Indemnity Group Agreement #8-54 which adds new Article VIII re premium payments & financial statements.
 PAPALOS,F. A. Florida Power Corp. 78/11/09. 4pp. 94135:185.
- P. Operating license stage documents & correspondence
- 7B10250211 Notice of Issuance of Amend#15 to Facil Oper Lic#DPR-72 & Negative Declaration.
 REID.R.W. Operating Reactors Branch 4 (Pre 790625). 7B/07/24. 3pp 94368:349.

- worst case struck rod SABH did not notify FPC of problem acisting in other units.
 STEHARIM, P. Florids Power Carp. 78/10/05 2pp. 94069:360.
- 7810130130 Re 780926 NRC ltr FPL intends to pursue nod proposed in ltr of 780721 Flow balance enalyses currently being performed are due to be completed on or about 781027. Since no new mod is proposed no submittal sched needed.

 STEMART.W P. Florida Power Corp. 78/10/09 3pp. 94003.091
- 7810270165 Util Production Engr & CR#3 Plant Staff have initiated review of safety related sys that contain snubbers to determine if there are any snubbers that should be added to Tables 3.7-3 of Tech Specs.
 STEWART.W P. Fiprida Power Corp. 78/10/23 2pp. 94036.259.
- 7811080165 Forwards Tech Spec Change Requests 27 & 34 requesting amend to App A of License DPR-72 Changes concern reactor coolant pump power monitors & revisions to heatup cooldown & inservice leak & hydrostatic pressure-temp curves BTEWARI.W.P Florida Power Corp. 78/10/31. 25pp. 94405.078.
- 78i1200394 Forwards request for add1 info re permanent solution to ECCS small break analysis problem per 780727 submittel.
 REIO R.M. Operating Reactors Branch 4 (Pre 790625). 78/11/02. 3pp. 9449:237.
- 7811130181 Refers to 780926 NRC ltr & requests prompt notification of review of proposed mod to Engineered Bafeguerd Sys to mitigate Condition 3 event(small LOCA) Analysis of High Pressure Injection Bys will be completed & sent by 781130. STEMART.W P. Florida Power Corp. 78/11/07. 3pp. 03353:314
- 7811200422 Forwards results of measurements of radioactive math in NRC phantom an whole body counter Encl 1 contains actual amount of each radionulide present encl 2 gives ratio of measurements to DDE values & encl 3 gives recommendations.

 BUTHERLAND. J T Region 2. Atlants. Fuel Facility & Materials Safety Branch. 78/11/09. 5pp 94419.180.
- 7811210270 Notification of 781205 seminar in Atlanta QA to discuss new model rod effluent Tech Specs Forwards seminar info sheet, registration form & proposed agenda. O'fELLLY J.P. Region 2. Atlanta. Office of the Director. 78/11/09. 5pp. 94485:276
- 7811140109 Forwards list of snubbers to be added to Table 3.7-3 of Tech Specs.FPC is corrently preparing a Tech Spec change request which will include these snubbers. Request will be submitted w/next litense amend.

 BTEWART.W. P. Florida Power Corp 78/11/10, 5pp. 94425:136.
- 7811300033 Forwards SECY-78-554, "Policy Session Item." dtd 781025 w/ "Licensee Regulatory Performance Evaluation." W/o encl. O'REILLY, J. P. Region R. Atlanta, Office of the Director. 78/11/15. 2pp. 94070:348.
- 7812130120 Natice of workshops re implementation of training & qual requirements contained in Append 8 of 100FR72. Requests pre-warkshop registration of attendees to facilitate sending out math. W/encl Registration Form & List of Locations. HILLER, J.R. Assistant Director for Site & Safeguards (Pre 791030), 78/ii/15. Spp.
- 7812190033 Forwards Rev#1 "Dreft Radiological Effluent Tech Specs" for PMR's (NAREQ-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREQ-0133), H/o and ANG: 781127013 & 781127018.

 GRIFESIB. N. Assistant Director for Engineers & Projects (Pra 790425) 78/11/15. App. 94215.001.
- 7811240216 Responds to 781102 request & forwards add1 info re proposed solution to ECCB small break analysis problem.

 91544RT.H P. Florida Power Corp. 78/11/17, App. 94466:344.
- 7811300398 Informs FPC that NRC has contracted w/Mountain West Res Inc to undertake a series of post-licensing studies of nuc pur stations. Exudises will enally a sociocon inpacts which occurred during constr & post-constr periods of each plant. DEYQUNQ.R.C. Division of Site Befety & Environmental Analysis. 78/11/20. 2pp. 94116:240.
- 7812040199 Forwards resubmittal of Tech Spec Change Request 27 for amend to App A of License DPR-72 Replaces 781031 request entirely. New submittal deletes time delay relay & clarifies response time in safety analysis, Certificate of Svc encl. BTEMART, W. P. Florida Power Corp. 78/11/29. 16pp. 94457:135.

- during normal plant aper. Requests either commitment to limit purging or justification for continuing Forwards model Tech Speca-SRP Section 6.2.4 w/encl Branch technical position. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/29. Spp. 74211:274.
- 7812280172 Emphasizes importance of submitting accurate & complete info to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS, J O Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94375:013.
- 7812270489 Notification of Porthcoming meeting on 781219 w/util to discuss content & schedule of submittels re pur increase to be proposed.
 NELBON.C Operating Reactors Brench 4 (Pre 790625). 78/12/12 2pp 74015:293
- G. Inspection reports: IE Bulletins & correspondence
- 7810230116 Forwards IE Inspec Rept#50-302/78-19 on 780726-29 during which no items of noncompliance were noted. LONG-F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/09/14. 2pp.
- --7810250154 IE Inspec Rept#50-302/78-19 on 780726-29 during which no items of noncompliance were noted. Major areas inspected included: fuel hendling activities, review of annual rept & a plent tour.

 DANCE, H. C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/09/14. 11pp.
- 7811010299 Forwards suppl info to Item of Noncompliance 478-17-02 re designation & control of temporary auth vehicles & to Unresolved Item 478-17-08 re control of all vehicles.Full compliance will be achieved by 790223.

 BTEMART.W.P. Florida Power Corp. 78/10/05. ip. 94389:132.
- 7811130409 Forwards IE Inspec Rept#50-302/78-20 on 780810-11 during which no items of noncompliance were noted. LONG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/05. 2pp. 94008:332.
- --7811130412 IE Inspec Rept#30-302/78-20 on 780810-11 during which no items of noncompliance were noted. Major areas inspected included; surveillance activities, testing & safety related pining support & restraint sys.

 HARTIN.R.D. Region 2, Atlanta, Office of the Director. 78/10/03.

 7pp. 94008:334.
- 7810230290 Forwards IE Circular#78-17. (See ANO: 7810230221, Docket 50-133, 781013)
 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/10/13. 1p. 94165: 008.
- 7811010298 Ack receipt of 781005 ltm informing NRC of steps taken to correct violations noted during inspec#50-302/78-17.
 KENNA, W.B. Region 2, Atlanta, Bafeguards Branch. 78/10/17. 1p. 94389: 131
- 7811100017 Ack receipt of 781024 ltr informing NRC of steps taken to correct violations noted during inspect50-302/78-21. LONe,F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/01. ip. 94176:295.
- ~~7811100021 Responds to 780929 NRC ltr re violation noted in Inspec Rept#50-302/78-21 Corrective actions: admin procedures rev to make the master mechanic responsible for assuring cleanliness of fuel transfer canel. BTEWART.M.P. Florida Power Corp. 78/10/24. 1p. 94176: 296.
- ---7811100023 Forwards IE Inspec Rept#50-302/78-21 on 780814-18 & Notice of Viglation. LCNO.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 78/09/29, 2pp. 94176:297.
- --7811100026 Notice of Violation from inspec on 780814-19.

 # Region 2, Atlanta: Reactor Operations Nuclear Support Branch.
 78/09/29. ip. 94176;299.
- --7811100030 IE Inspec Rept#50-302/78-21 on 780814-18 during which 1 item of noncompliance was noted: failure to follow procedures re facil cleanliness.
 DANCE, H. C., QUICK, D. R. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/09/29. 15pp. 94176:300.

- 7811150098 Forwards IE Circular 78~18. O'REILLY, J. P. Region 2: Atlants: Office of the Director. 78/11/06. 1p. 94113:285
- 7812180312 Forwards IE Inspec Rept#50-302/78-24 on 781002-06 during which no items of noncompilence were noted. LONG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/08 2pp. 94356:261
- --7812180317 IE Inspec Rept#50-302/78-24 on 781002-06 during which no items of noncompliance were noted Major areas inspected incliplant oper, followup on previous noncompliance items & unresolved items.

 GUICK, D. R., TAYLOR, P. A. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/08. 12pp. 94336-263
- 7812180308 Forwards IE Inspec Rept#50-302/78-28 on 781011-13 during which no items of noncompliance were noted. LONG.F.J. Region 2, Atlanta. Reactor Operations Nuclear Support Branch. 78/11/09. 2pp. 94356:184.
- --7812180311 IE Inapec Rept#30-302/78-28 on 781011-13 during which no items of noncompliance were noted Hajor areas inspected inclizero-pur-physics tests & pur escalation tests. BURNETT, P. T. Repion 2. Atlanta, Reactor Operations Nuclear Support Branch, 78/11/09. App. 74336:186.
- 7811240071 Ack receipt of 781030 ltr informing NRC of steps taken to correct violations noted during inepec#50-302/78-22.

 8UTHERLAND.J.T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 78/11/14. 1p. 94456.311.
- --7811240074 Responds to 781114 NRC ltr re-violation noted in Inspec Rept #50-302/78-22. Corrective actions: rev survey sched divided over 4 day periodiposting of radiat areas once a weekinew log book. BTEMANT. W.P. Floride Power Corp. 78/10/30. 2pp.
- --7811240077 Forwards IE Inspec Rept#50-302/78-R2 on 780905-08 & Notice of Violation.
 SUTHERLAND.J.T. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 78/10/16. 2pp. 94456:314.
- --7811240079 Notice of Violation from inspec on 780905-08.

 Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/10/16. 1p. 94456. 316.
- --7811240081 IE Inspec Rept#30-302/78-22 on 780905-08 during which 3 items of noncompliance were noted: failure to post high radiat area & failure to post two radiat areas. EMALD.8. C., ZAVADOSKI,R.W. Region 2: Atlanta, Fuel Facility & Materials Safety Branch. 78/10/13 11pp. 94456:317.
- 7812120197 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuclear Becurity Bafeguards Nawsletter, in support of IE Circular 78-17. KENNA H.B. Region 2, Atlanta, Bafeguards Branch. 78/11/17. 4pp. 9427:101.
- 7812040306 Forwards IE BulletinW78-12A, suppl to IE Bulletin 78-12. H/encl ANO: 7811300055. D'ABILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/24. ip. 94127: 094.
- 7812050063 Ack receipt of 781115 itr informing NRC of steps taken to correct violations noted during inspect#50-302/78-23. LONG-F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Brench. 78/11/24. 1p. 94334:324.
- --7812050067 Responds to 781023 NRC ltr re violations noted in Inspec Rette50-302/78-23 Corrective actions:personnel instructed, plant heatup oper reviewed. BTEWART, M. P. Floride Power Corp. 78/11/15. 2pp. 94334:325.
- --7812050070 Forwards 1E Inspec Rept#00-302/78-23 on 780830-0901 & Notice of Violation.
 LCM(87.J. Region 2, Atlanta, Reactor Operations Nuclear Bupport Brench. 78/10/23. 2pp. 94334:327.
- --7812050072 Notice of Violation from insper on 780830-0901.

 Region 2: Atlanta: Reactor Operations Nuclear Support Branch. 78/10/23. 1p. 94334:329.
- ~~7812050076 JE Inspec Rept#50-302/78-23 on 780830-0901 during which 1 item of noncompliance was noted:completion & verification of procedures during review of sys realignments.
 OUCK.D.R., DOMAT.T.J., DANCE.H.C. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/20. Spp. 94334:330.

- 7812210303 Ack receipt of 781130 ltr informing NRC of steps taken to correct violations inpted during inspec#80-302/78-25 LDNG-F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/12/08 1p. 94014:289.
- --7812210337 Responds to 781109 NRC ltr re violations noted in Inspec Rept#50-302/78-25 Corrective actions formal qual training guide was rev.upgreded & distrib for implementation STEWART.F.P. Florid# Power Corp. 78/11/30. 2pp. 94014: 290.
- --7812210344 Forwards IE Inspec Rept#50-302/78-25 on 781016-19 & Notic of Violation. LCN2:F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/09 2pp. 94014:292.
- --7812210346 Notice of Violation from Inspec on 781016-19. * Rayion 2. Atlanta. Reactor Operations Nuclear Support Branch. 7871/109. 1p. 94014-294.
- --7812210350 IE Inspec Reptw30-302/78-25 on 781016-19 during which is of noncompliance was noted failure to implement training & retraining for nuc auxiliary operators & assistant nucleusiliary operators.

 BRADFORD, M. H., TAYLOR, P. A., KELLOGO, P. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 78/11/09. Spp. 94014-295
- 7812290096 Ack receipt of its informing NRC of steps taken to correct violations noted during inspec#50-302/78-27 Response is incomplete. Requests add1 info w/in 10 days.

 MENNA-W.B. Region 2, Atlanta, Safeguards Branch. 78/12/18. ip. 94190:117
- --7812290101 Forwards IE Inspec Rept#50-302/78-27 on 781018-19 & Noti of Violation. KENNA, H. B. Region 2: 'Atlanta, Bafeguards Branch. 78/11/15. 2pp 94190-11B.
- --7812290107 Notice of Violation from inspet on 781018-19. * Region 2, Atlanta, Safeguards Branch. 78/11/15. 1p. 94190-120.
- --7812290112 IE Inspec Rept#50-302/78-27 on 78;018-19 during which 2 items of noncompliance were noted: response procedures & vehicle control Details withheld from pub disclosure.Per 2.790.

 OILLEBPIS.F.P., FUCHKO.J.M. Region 2. Atlanta. Bafeguards Branch 78/11/15. jp. 94190:121.
- 7812280025 Forwards 16 Bulletin 78-14. O'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/12/19 1P. 94131:058.

R. Periodic operating reports & related correspondence

- 7810160094 Monthly operating rapt for Sept 1978
 BARRETT, J. E. Florida Power Corp. 78/10/05. 5pp. 94003: 224.
- 76101600B1 Forwards Monthly Oper Rept for Bept 1978.
 BTEWART, N. P. Florida Power Corp. 78/10/09. 1p. 94003:223.
- 7811200184 Forwards Monthly Oper Rept for Oct 1978. STEMART.W.P. Florids Power Corp. 78/11/15. ip. 94252:304.
- --7811200187 Monthly operating rept for Oct 1978.
 SARRETT, J. E. Floride Power Corp. 78/11/15. Spp. 94252:305.
- 7811280268 Forwards revision to monthly operating rept for Oct 1978. BTEWART, M. P. Florida Power Corp. 78/11/20. 1p. 94395:208.
- --7811280271 Revision to monthly operating rept for Oct 1978.
 BARRETT, J. E. Florida Power Corp. 78/11/01. 1p. 94395:209.
- 7812200176 Forwards Monthly Oper Rept for Nov 1978.
 BTEWART, M. P. Florida Power Corp. 78/12/11. 1P. 94158:337.
- --7812200179 Monthly Oper Rept for Nov 1978. BARRETT, J. E. Floride Power Corp. 78/12/01. 3pp. 94158:338.
- 8. Reportable occurrences, LERs & related correspondence
- 7810200132 Forwards LER 78-021/047-0. BTEWART.N.P. Florida Power Corp. 78/08/09. 1p. 94401:186.

SOOKETED LIFIAIS

- --7810200158 LER 78-021/04T-0. on 780729, spent fuel casks were received w/ removable radioactive contamination in excess of 22,000 DPM Isolation & decontamination started Cause unknown CCOPER. J. Florida Power Corp. 78/07/31. 2pp. 94401.187
- 7810110151 Forwards LER#78-045/031-0 STEWART, W. P. Florida Power Corp 78/10/02 1p. 94065:346.
- ---7810110152 LER#78-045/031-0 on 780907 closed indication not received for Control Complex air supply damper D-1 after closed command was issued Causad by mech binding of air supply damper Preventive maint will provide corrective action COOPER. J Florida Power Corp. 78/09/27. 2pp 94065-347.
- 7810110116 Forwards LER 78-044/03L-0 BTEWART W P. Florida Power Corp 78/10/03 1p 94069:147.
- --7810110120 LER 78-044/03L-0.on 780907, during performance of 8P-417, closed position indication not received after CFV-18, core flood B vent to gae decay eys.uss given command to close. Caused by faulty torque switch Torque switch renewed COOPER. J Florida Power Corp. 78/09/29. 2pp. 94067:334
- 7810110170 Forwards LER 78-023/04X-1. STEWART-W. P. Florida Power Corp. 78/10/03. 1p 94069:093
- --7810110173 LER 78-023/04x-1 (supplementary infa): (discovered 780914) during Jul-Aug 1978, environ samples not analysed w/methods providing LLD's equal to or less than Tech Spec requirements
 - requirements * Florida Power Corp. 78/09/29. 2pp. 94069:096.
- 7810170249 Forwards LER 78-023/04T-0. STEWART,W P Florida Power Corp. 78/10/i1 1p. 94236:331.
- --7810170232 LER 78-025/04T-0: on 781001; unplanned radinactive gas release occurred when attempting to place Miscellaneous Maste Evaporator in svc. Caused by procedure inadequacies which have been revised.

 CCOPER.J. Florida Power Corp. 78/10/09. 2pp. 94236-332.
- 7810180105 Forwards LERW78-048/03L-0. STEMART.W.P. Florida Power Corp. 78/10/12 1p. 94421:278.
- --7810180107 LERW78-04B/03L-0 on 780918: Quadrant pur tilt exceeded transient limit but not maximum limit recorded. Caused by uncoupling of grp 5.Rod 1.Control Rod Drop Test Procedure has been ray CCOPER.J. FlorIda Power Corp. 78/10/10. 2pp. 94421:299
- 7810180147 Forwards LER 78-047/03L-0. 67EHART H P. Florida Power Corp. 78/10/12. 1p. 94016:342.
- --7810180152 LER 70-047/03L-0: on 780918 in Mode 1, while performing RCS total gas Surveillance Procedure BP-710, gas chromatograph found inoperablé Caused by failure of separation column.

 # Florida Power Corp. 78/10/10. 2pp. 94316:349
- 7810160133 Forwards LER 78-049/03L-0. GTEWART.W.P. Florida Power Corp. 78/10/12. 1p. 94317:001.
- --7810180185 LER 78-049/03L-0:on 780913, relative position indication for Group 7, Rod 8 found inoperable. Caused by improper termination of reactimeter to relative position indicator module for Group 7, Rod 1. Procedure will be revised.

 COOPER, J. Floride Power Corp. 78/10/09. 2pp. 94317:002.
- 7810180110 Forwards LER 78-046/03L-0. BTEWART.W P. Florids Power Corp. 78/10/13. ip. 94195:201.
- --7810180111 LER 78-046/03L-0: on 780914, auxiliary bldg ventilation exhaust radiat monitor interlock on RMA-2 failed to respond during performance of BP-335. Caused by shorted surge suppressor which inhibited interlock function. CCOPER.W P. Florida Power Corp. 78/10/06. 10. 94193:202.
- 781024011B Forwards LER 78-050/017-0. 8TEWART.W.P. Florida Power Corp. 78/10/17. Ip.
- ---7810240124 LER 78-050/01T-0: on 781006, duct seal compound which supports combustion was used around penetrations in CR-3 cabls spreading room. Duct seal compound used in qualifying cable spreading room for halon sus but not as fire barrier. COOPER. J. Florida Power Corp. 78/10/12. 2pp.

- --7810240162 LER 78-051/OOL-0: on 780920, reactor bidg air sampling moniter inoperable & in low flow alerm. Caused by meladjustment of a flow controller which was subsequently readjusted.
 CDOPER, J. Florida Power Corp. 78/10/17. 2pp.
- 7810310136 Forwards LER #78-027/1T-1. 8TEWART.H. P. Florida Power Corp. 78/10/23. 1p. 94090:156.
- --7810310141 LER 78-027/01T-1:on 780511.1tr received from B&W on 780508 re uncertainties associated w/incore instrumentation found to apply to CR-3. Caused by insufficient data from prototype incore instrument studies. Quadrant power tilt revised. COOPER. J. Florida Power Corp. 78/10/17. 2pp. 94090:137.
- 7810310164 Forwards LER 78-052/03L-0. BTEMART.W. P. Florids Power Corp. 78/10/23. 1p. 94090: 222
- --7810310169 LER 78-052/03L-0.on 780928.operating range level transmitter for once-through steam generator B found out of calibr. Normal maint restored operability through calibr. COOPER.J. Florida Power Corp. 78/10/20. 2pp. 94090:223
- 7811070136 Forwards emended LER 78-023/04X-2 Bupplementary info sheet only encl.
 BTEWART.W.P. Floride Power Corp. 78/11/01. ip. 94040:131.
- --7811070139 LER 78-023/04x-2: (discovered 780914), during Jul & Aug 1978, environ samples not analysed using procedures which would provide LLD's per ETS. Apparently caused by inadequate sample count time. (Supplementary info sheet).

 * Florida Power Corp. 78/10/26. 2pp. 94040:132
- 7811070204 Forwards LER 78-054/03L-0. BTEWART, W. P. Florida Power Corp. 78/11/01. 1p. 94039: 080.
- --7811070208 LER 78-054/03L-0: on 781004, in cable spreading room, several penetrations to control room were found to lack fire barrier matl. Caused by inadequate installation & insp. 8TEWART, W. P. Florida Power Corp. 78/11/01. 2pp. 94039:081.
- 7811070925 Forwards LER 78-083/031-0. STEMART.W.P. Florida Power Corp. 78/11/01. 1p. 74039:153.
- --7811070235 LER 78-053/03L-0:on 781004 during ECCB pump operation procedure 8P-340A valve DHV-110 found incapable of controlling required flow Caused by flow controller DH-43-F18 not being valved in. COOPER, J. Florida Power Corp. 78/10/25. 2pp. 94039:154.
- 7811160136 Forwards LER 78-055/03L-0. STEWART, M. P. Florida Power Corp. 78/11/06. 1p. 94135: 241.
- --7811160140 LER 78-085/ODL-0: on 781014. during routine operation lube oil backup pump MVP-3C lost indication & would not start. Caused by two blown fuses in indication & control power circuit in DPDP 58 switch 4. Circuits checked & fuses renewed. COOPER. J. Floride Power Corp. 78/11/06. 2pp. 94135:242.
- 7811280303 Forwards LER 78-055/03L-0. BTEWART, W. P. Floride Power Corp. 78/11/20. 1p. 94395; 299.
- --7811280307 LER 78-036/03L-0:on 781027.during meteorological monitoring instrumentation calibr, differential temp & wind indications found out of tolerance. Former caused by defective temp probes: latter by worn sensor bearing. Units recalibr. CCOPER. J. Florida Power Corp. 78/11/17. 2pp. 94395:300.
- 7812010246 Forwards LER 78-057/03L-0. 8TEWART, N. P. Florida Power Corp. 78/11/24, 1p. 94390: 156.
- --7812010247 LER 78-037/03L-0: on 781030, during routine plant insp,both concentrated boric acid storage tank discharge valves CAV-38 & 43 were closed Caused by improper valve alignment during restoration of sys from recirculation to normal modes. CODPER, J. Florida Power Corp. 78/11/24. 2pp. 94390: 157.
- 7612180150 Forwards LER 78-060/03L-0. 8TEHART.H.P. Florida Power Corp. 78/12/11. 1p. 94365:251.
- --7812180155 LER 78-060/03L-0:on 781115, conteinment radiation sonitor RMA-1 found in purge made while reactor bldg purge was in progress, preventing air sampling. Caused by personnal error. COUPER.J. Florida Power Corp. 78/12/07. 2pp. 94365:252.

7812200178 Forwards LEG 28-058/031-0

DOCKETED ITEMS

- --7812200181 LER 78-058/03L-0: on 781112, feeder breaker was open & disrupting ac power supply. Caused by personnel opening unmarked ac power feeder breaker. Breaker will be identified b labeled.

 COPER. J. Florida Power Corp. 78/12/05 2pp. 94158.342
- 7812200270 Forwards LER 78-089/03L-0 STEMART.W P. Florida Power Corp. 78/12/11. 1p 94207-140.
- --7812200273 LER 78-059/03L-0: on 781113, control complex atmospheric radiation monitor RMA-5 went to high flow alarm, preventing actuation of interlocks which route control room eir through emergency ventilation sys. Caused by vacuum pump selzing. COOPER, J. Ploride Power Corp. 78/12/06. 2pp. 94207.141.
- 7812200284 Forwards LER 78-061/03L-0. STEMART.W.P. Florids Power Corp. 78/12/13 ip. 94207:212.
- 7812220081 Forwards LER 78-063/03L-0. STEHART N P. Florida Power Corp. 78/12/18. 1p. 94343:326.
- --7812220084 LER 78-063/03L-0:on 781123.start-up transformer disabled, causing loss of power in cable tunnel sump pumps. Operability restored shortly. Engineering evaluation of power sys initiated.

 COPER. J. Florida Power Corp. 78/12/13. 2pp. 94343:327.
- 7812220102 Forwards LER 78-062/03L-0. STEWART, U.P. Florids Power Corp. 78/12/15. 1p. 94343:355.
- --7812220105 LER 78-062/03L-0: on 781121, during control rod exercise procedure BP-333, absolute position indication for Rod 4 Oroup 3 not observed at rod was moved. Caused by sticking red witch COPER, J. Florida Power Corp. 76/12/13. 2pp 94343:356.
- 7812270239 Forwards LER 78-064/03L-0. BTEWART.W.P. Florida Power Corp. 78/12/19. 1p. 94017:146.
- --7812270243 LER 78-064/03L-0; on 781125, during routine operation of air handling fans AHF-14A&C. Tow flow condition was indicated.

 Cause was suction shroud breaking loose & carrying into fan blade assembly. Broken blades AHF-14C replaced & rebalanced.

 COPER, J. Florida Power Corp. 78/12/14. 2pp. 94017: 147.
- 7812270291 Forwards LERR78-065/01T-0. BTEWRT.W.P. Florida Power Corp. 78/12/21. 1p. 94229:344.
- --7812270293 LER#78-065/01T-0 on 781218: during routine oper, discovered that AHF-14C was overldeded & was secured to attempt to balance air flow.AHF-14C was tripped during restart & cause was attributed to not allowing sufficient time for restart. COOPER.J. Florida Power Corp. 78/12/19. 2pp. 94229:345.

U. Congressional/Executive Correspondence

- 781R080210 Responds to 781030 ltr requesting info for CF Danielson. Forwards Bub; Facil Sami-Bosla Annual Radioactive Effluent Repts re gaseous: liquid & solid radioactive matl released during 1977 & first half of 1979.

 DIROMS-W.J. Office of the Executive Director for Operations, 78/11/28. 2pp. 94137:048.
- --7812080211 Forwards Danielson 781020 request for info re facility nuclear waste disposal program & controls on Br-90 emissions. Requests NRC comments & views.

 CHILEB.L. Senats. 78/10/30. 2pp. 94137:050.
- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2
- F. Security, medical, emergency & fire protection plans
- 7810120080 Forwards analysis of Electrical Cable Penetration Fire Barrier Test conducted on 780619, Also forwards 3rd party observer rept of test & 5 detailed drawings associated w/test.

 NAUGHTON, W. F. Commonwealth Edison Co. 78/09/29, 44p.
- 7812120195 Informs NRC name of fire protec consulting firm hired by CEIL to fulfill requirements of "Fire Protec Organization of Nuc Plent Fire Protec Functional Responsibilities Admin Controls & GA" will be submitted 790201.

 NAUGHTON, W. F. Commonwealth Edison Co. 78/11/30. 2pp.

- 7812270365 Forwards correction of item 3.2.5 of fire protec BER. Requests delay in advising licenses of acceptability until there is a response to encl 2 of 780626 ltr LAINASO. Plant Bystems Branch (Pre 791030) 78/12/07. ip. 94229:016.
- 9 Adjudicatory correspondence
- 78iii30202 "Agreed Motion for Special Prehearing Conference & th Sat Bithed for Further Proc" on 78ii20.21 or 22 to hear oral arguments & rule on motions to dismiss & to allow citizens to enter limited appearances
 BTEPTOS.P. Commonwealth Edison Co. SCHELL.8 Illinois, State of 78/10/24. 3pp. 03533:355.
- 7911170012 "Order for Special Prehearing Conference." The 781024 joi motion of Petitioner-Applicant & Reg. Staff for special prehearing conference is granted & set for 781120. LUTON.E. Atomic Safety and Licensing Board Panel 78/11/02. 2pp 94116.123.
- 7812120211 Bubmits typographical corrections to "Memo in Support of Certain Amended Contentions" filed on 781109 by State of IL W/Cert of Svc. BEKULER-S.N. Illinois. State of 78/11/13 2pp. 94276 066
- 7811240022 Amended contentions of St of IL re amends to Oper Lics MDPR-39 & 48 to increase spent fuel storage capacity at subjfacils. Asserts that to approve amend would be contrary to NRC policy position. Cert of Svc & afficiant encl SEKULER. S. N. Illinois. State of. 78/11/01 9pp. 94458-167.
- 7811200423 Notice of appearance by 0 Conningham in proceedings re surfacils on behalf of NRC. Cert of Svc encl.
 CUNNINGHAM, 0, H Office of the Executive Legal Director 78/11/02
 2pp. 94419:185
- 7812040311 Commanwealth Edison Co Motion to strike contentions & supporting memo submitted by IL Atty General on 781101.
 Requests that Amended Contentions#2.#6D & #16 be stricken.
 ROMEJ. H. STEPTOE.P. P. Isham, Lincoln & Beels. 78/11/09. 17pp.
 94129:188
- 7812030047 Motion to emend Contention 6A of Intervenor's amended Contentions filed 781101 by stating that there has been insufficient dev of all credible accident scenarios in subj proc.

 86KULER.8.N. Illinois, State of. 78/11/09 3pp. 94334:159.
- --7812050051 Memorandum in support of amond contentions Believes sto Applicant should not be allowed to use the special prehearing conference as means to circumvent the summary disposition process. W/encl Cert of Byc. SEXULER, B.N. Illinois, State of. 78/11/09. 14pp. 94304:162.
- 7812050054 NRC Staff brisf in apposition to the admission of Illino proposed contentions 2.6A.6D. & 16 re proposed mod of spent fuel pool. Staff views cover non-emergency licensing of storage facils, contention wording, vagueness & irrelevance. QDDDARD.R. J. Defice of the General Counsel. 78/11/09. 7pp. 74334; 231.
- 7812120223 Notice of appearance by A Bielawski as counsel for util proceedings re subj Pacits Cert of Byc encl.
 BIELAMBKI, A.P. Isham, Lincoln & Beals. 70/11/16. 2pp. 94277-1
- 7812270335 Opposes Commonwealth Edison request to increase spent fu storage at subj facil Fears it will become a permanent dump. ROBERTS.M. Affiliation Unknown. 78/11/20. 1p. 94230: 286.
- 7812270371 Notification that respondent has been added to svc lists lagal & tech branch documents re Spent Fuel Pool Mod proc for sub; facils as of 781127 & previous papers in Formal File are encl. (w/o encl).

 ODDDARD.R. J. Diffice of the Executive Legal Director. 78/12/05. 94229:023.
- J. Insurance & indemnity information
- 7812190109 Requests refund of \$6 per mut in excess indumity for psi for LiceDPR-2, #DPR-19, #DPR-25, #DPR-29, #DPR-30, #DPR-39, #DPR-48. POOLE, R. D. Commonwealth Edison Co. 78/12/13. 1p.

D. Advisory Committee on Reactor Safeguards reports & correspondence

- 7812060394 Notice of ACRS Bubcormittee on Plant Arrangements 781026 open meeting at 9:30 AM in Washington DC to review NRC Zion Bistion Sys Interaction in Nuc Pur Plants Task A-17 k
 Zion Bistion Sys Interaction Biddy.
 HOYLE, J. C. Office of the Secretary of the Commission. 78/09/25 2pp. 94382:351.
- P. Operating license stage documents & correspondence
- 7812080026 FOIA request for all records incl:quantity of radioactive matl disposed of from former Hanhatten proj in IL thoun as Chicago Piles#1.2 & 3. Math disposed of in IL by Lindsay Cos at Morris facil & Dresden facil. HANGELL, D. Illinois, State of. 78/11/06. 2pp.
- 7812080095 Forwards CEIL's Proj Mileposts sched for subj facils fuel pool mods. Also included are brief statements providing bases for these mileposts Requests that NRC staff expedite its review sched to meet 790201 & 790315 competion dates 94107: 292. REED, C. Commonwealth Edison Co. 78/11/29. App.
- 7812180239 Amend#40 to Oper Lic#DPR-39. Changes Tech Space to allow borom concentration in pressurizer to be 200 ppm less than reactor coolant loop borom concentration Corrections are made to Tech Specs. Changes to Tech Specs encl. BCHHENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/30. 6pp. 94365:003.
- --7812180242 Bafety Eval Rept in Support of Amend#40 to Oper Lic#39 & Amend#37 to Oper Lic#4B.

 SCHWENCER.A. Operating Reactors Branch i (Pre 790625). 78/11/30. 94365: 015.
- 78:01:00025 Current schedule for submittal to NRC Staff of required rev ECCS analysis & essciated Tech Spec changes is 780:05. We Bicheduled rev analysis for subj facil to begin late 78:031. NAUGHTON.H.F. Commonwealth Edison Co. 78/10/03. 1p. 94033:043.
- 7810120036 LiceDPR-39 & DPR-48 appl for amend to Tech Spece proposed incorporating ECCS flow requirements re a blow belance test & temper-groof covers for menual throttle velves. REED.C. Commonwealth Edison Co. 78/10/03. 7pp. 94332:299.
- 7810180060 Forwards drawing: "Location & Details of Reactor Coolent Pump Trip Pans" for subj facil as fire protec response. NAUGHTDN.W.F. Commonwealth Edison Co. 78/10/10. 1p.
- 7B10200113 Responds to 780829 NRC request for overpressure protec Tech Spec. States that util will submit requested info by 781201. NAUGHTON:W.F. Commonweelth Edison Co. 78/10/13. 2pp. 94367: 342.
- 7810230102 Renewal of request to amend facil operating liceDPR-39 & DPR-48 Proposed amend is a combined class I & class III Amend & does not require extensive environ impact rept. Tech Bpec & Environ Impact statement encl. REED C. Commonwealth Edison Co. 78/10/13. 17pp.
- 7810230194 Requests withdrawal of proposed amend to facil lits BRR-G9 & BPR-48 originally submitted in 1tr of 760780. Completion of mod re lake discharge tanks necessitates proposed amend be cancelled. NAUGHTON, W. F. Communweelth Edison Co. 78/10/17, 1p. 94052:277.
- 7810300097 Forwards info in response to 780931 NRC ltr re pipe crecks in them vol control due to excessive charging pump vibrations. NAUGHTON, W. F. Commonwealth Edison Co. 78/10/24, 2pp. 94035:072.
- 7811010069 Forwards add1 info re proposed expansion of spent fuel storage capacity of subj facil in response to 780926 NRC request. Responds to 27 NRC questions.
 NAUGHTON. M. F. Commonwealth Edison Co. 78/10/24. 69pp. 94302:283.
- 7811070168 Requests change to Oper LiceDPR-39 & DPR-48 Tech Spec. extending rod bow penalty curve & EPPH clad collapse limits to incl higher region everage fuel burnups. REED.C. Commonwealth Edison Co. 78/10/27. 7pp. 94044:150.
- 7811140002 Notifies applicant of 781128 NRC-sponsered saminar re Model Radiological Effluent Tech Speca for Nuc Per Plants e/encl Seminar Info Bheetito be completed & returned by 781117) & Proposed Agenda. KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/11/07,

- 781:210410 Provides add1 info in response to questions 13 & 15 in 781024 ltr re leakage rate from spent fuel pool liner, surface does rate as spent fuel pool potential impact of proposed spent fuel pool mod re gaseous effluents NAUGHTON, W. F. Commonwealth Edison Co. 78/11/08. 3pp. 94483:123
- 7811300147 Forwards "Licensing Rept for Subj Facil Spent Fuel Ract Mod" in response to 780203 request.
 GDDDARD.R.J. Office of the Executive Legal Director. 78/11/03. 39. 94072:031.
- 7811270104 Summary of 781025 meeting w/Subcomm on Plant Arrangements of Advisory Comm on Reactor Bafeguards re Bandia Labs presentation of Bys Interaction Methodology Appl in Nuc Per Plants & subj facil sys interaction study.

 ANORLOJ. Division of Project Management. 78/11/13. 36pp. 94223:294.
- 7812180021 Notice of workshops re implementation of training & qual DIMINUTE NOTICE OF WORKSHOPS TO IMPLEMENTATION OF TRAINING & qualitation of training & qualitation contained in Append B of 10CFA73. Requests pre-workshop registration of attendees to facilitate sending out math. W/encl Registration Form & List of Locations. MILLER, JR. Assistant Director for Site & Safeguerds (Pre 791030), 78/11/10. Spp. 94133:281.
- 7812190011 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PWR's (NUREQ-0473) & "Preparation of Radiological Effluent Tech Specs for Nur Punts" (NUREQ-0133).

 GRIMEBLE K. Assistant Director for Engineers & Projects (Pre 790@5). 78/11/15. 6pp. 94214:274.
- 7812050107 Forwards rev page to Topical Rept CE-1-A: "Qual Assurance Prog. Rev 6. " Rev reflects Rep Quidel 28 & 1.33 rev. TURBAK, M.B. Commonwealth Edison Co. 78/11/17. 2pp.
- 7811280213 Forwards current lic status list for subj facils. W/snc). REED.C. Commonwealth Edison Co. 78/11/20. 9pp.
- 7811300042 Informs CEIL that NRC has contracted w/Mountain West Res LINDOUNK INTOTAL LEIL THAT NMC has contracted W/Mountain Mast Re Int to undertake a series of post-licensing studies of nuc pur exations. Btudies will enably a socioecon impacts which occurred during constr & post-constr periods of each plant. DEYQUNO, R. C. Division of Site Bafety & Environmental Analysis, 78/11/20. 2pp. 94071:037.
- 7812270127 Forwards Commonwealth Edison "Addl Info on Proposed Expansion of Spent Fuel Storage Capacity" dtd 781108 W/o BIELAWSKI, A. P. Isham, Lincoln & Beals. 78/11/27. 1p. 94161:084.
- 7812180116 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing Wencl AND 7812080207.

 SCHENCER A. Operating Reactors Branch 1 (Pra 790)

Operating Reactors Branch 1 (Pre 790625). 78/11/28. 6pp. 94130; 317.

- 7812190236 Forwards Amend#40 to Oper Lic#DPR-39 & Amend#37 to Oper Lic #DPR-48 Also forwards Safety Eval Rept & Notice of Issuence. BCHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/30. BCHWENCER, A. Op 200. 94365: 001.
- --7812180244 Notice of Issuence of Amend#40 to Open Lic#39 & Amend#37 to Oper Lic#48. Operating Reactors Branch 1 (Pre 790625). 78/11/30. BCHWENCER, A. 2pp. 94365:019.
- 7812070211 Responds to NRC 780828 ltr requesting overpressure protection Tech Specs. Requests extension to 790215 for submission due to receipt of new info.

 NAUGHTON.H.P. Commonwealth Edison Co. 78/12/01. 2pp. 03555:115.
- 7812280129 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB. J. 0. Défice of Inspection & Enforcement, Défice of the Director. 78/12/06. Spp.
- 7812050013 Requests views of Regional Directors on Licenses performance eval of subj facils. Forwards questions to be answered by 771209. THORNBURG, H. Division of Reactor Construction Inspection. 77/11/23. Zoo.
- 7812190097 Accepts topical rept#CE-1-A Rev#6."Comm Edison Co Quality Assurance Prog for Nuc Generating Stations. "Requests submittel of 36 copies.
 HARBS, W. P. Guality Assurance Branch. 78/12/13. 1p.

incl fuel sipping test & fuel assemblies exam prog. Reaffirms request to NRC to expedite lic mod review & approve changes to higher region average fuel burnup Tech Specs by 781220. REED.C. Commonwealth Edison Co. 78/11/21. 3pp. 94398:219.

Q. Inspection reports. IE Bulletins & correspondence

- 7811080066 Forwards 1E Inspec Repts#50-295/78-20 & #50-304/78-22 on 780809-11, 16, 17, 23-25, 30, 31, 0901, 07 & 08 & Notice of Vialation. F108ELLI.0. Region 3, Chicago, Reactor Operations Nuclear Support
- FIORELLIA. Region D. Chicago, Reactor Operations Nuclear Support Branch. 78/10/04 2pp. 94398-274.
- --7811080070 Nobice of Viplation from inspec on 780809-11-16-17-23-25-30-31-0901-07-08-Region 3- Chicago: Reactor Operations Nuclear Support Branch. 78/10/04- 1p. 94398: 276-
- --7811080074 IE Inspec Repts#50-295/78-20 & #50-304/78-22 on 780809-ii.
 16-17.23-25.30-31.0901.07-08 during which 1 item of noncompliance was noted:properation for refueling BOYD.D.C., Riben.M.D., KNDP.R.C. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/10/04. 11pp. 94398:277.
- 7812050011 Forwards IE Inspec Repts#50-010/78-29, 50-237, -254, -295, -304/78-25, 50-249/78-27 & 50-265/78-26 on 781002 during which no items of noncompliance were noted.

 **XEPPLER.U. Q. Region 3: Chicago: Office of the Director. 78/10/30 2pp.
- --7812050027 IE Inspec Repts for subj facile on 781002 during which no items of noncompliance were noted Hajor areas inspected inclidiscussion of actions being taken by util to improve its reg performance & tour of Zion station MNDP,R C. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/30. 3pp.
- 78]206023] Forwards IE Insp#c Repts#50-295/78-24 & #50-304/78-24 on 780913-15.780920-21.780927-29 & 781004-05 & Notice of Violation.
 FIDRELLI.G. Region 3. Chicago. Reactor Operations Nuclear Support Branch 78/10/31. 2pp. 94382:184.
- --7812060234 Notice of Violation from inspec on 780913-15,780920-21, 780927-28 & 781004-05.

 * Region 3, Chicago, Office of the Director. 78/10/31. ip. 94982-186.
- --7812040234 IE Inspec ReptaW30-293/78-24 & w30-304/78-24 on 780913-15, 20-21,27-29 & 781004-05 during which I item of noncompliance was noted; failure to adhere to conditions of Work Request Authorization.
 BOYO, D. C., BIDEN, M. D., KNOP, R. C. Region 3, Chicago, Office of the Director. 78/10/31. 5pp. 94382:187
- 781119063 Forwards IE Circuler 78-18.

 KEPPLER J. 9. Region 3. Chicago. Office of the Director 78/11/06
 is.
- 7812130329 Forwards IE Inspec Repts#50-295/78-23 & 50-304/78-23 on 781012-13 during which no items of noncompliance were noted. HEISEMAN, R. F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/11/09. 2pp. 94307: 047.
- --7812130338 IE Inspec Repts#50-295/78-23 & 50-304/78-23 on 781012-13 during which no items of noncompliance were noted Major areas inspected incl.1E Bullstin & Circular followup & qual of elec equip & independent inspec.

 HUDHEB, J. Region 3, Chicago, Office of the Director. 78/11/09. 6pp. 94307:049.
- 7812050287 Forwards IE Bulletin#78-12A, suppl to 1E Bulletin 78-12. W/encl ANO: 7811300055, KEPPLEA, J. Q. Region 3, Chicago, Office of the Director. 78/11/24. tp.
- 7812280002 Forwards IE Bulletin 78-14.
 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 78/12/19.
 19. 94133:002.
- A. Periodic operating reports & related correspondence
- 7810180049 Monthly Oper Rept for September 1978. SCHNEIDER, H. L. Commonweelth Edison Co. 78/10/03. 13pp. 94063:065.

- Michigen near sub; facil-July 1977 thru June 1978 Vols 1-1V " WANDKEN Commonwealth Edison Co. 78/10/24. Ip 94095:002.
- --7811010131 Annual rept entitled "Oper Environ Monitoring in Lake MI near subj facil-July 1977 thru June 1978" prepared by NALCO Environ Sciences a Commonwealth Edison Co. 78/11/01. 1617pp. 94095:003.
- B Reportable occurrences, LERs & related correspondence
- 7812120121 Notification of deficiency found 780913 in valve cross assemblies inlet & enhanct push assemblies of KGV Pur Engine & corrective action to design roller pin & replace hand flating open.

 BENDER, B. B. Cooper Industries, Inc. 78/11/03. App. 94275: 329.
- 7810170208 Forwards LERB78-057/031-0.

 HANDKE N E. Commonwealth Edison Co. 78/09/08, 1p. 94236; 131.
- --7810170211 LERM78-037/03L-Q on 780B11 Unit 2 Containment Particulate Ventilation Red Monitor PRECOllies hibited spurious elerms. & detector would not respond to source check due to loose signal wire on "oper"selector switch in control room TRZYNA, Q. Commonwealth Edison Co. 78/09/08. 1p. 94236:132.
- 7810170184 Forwards LER#78-078/01L-0 WANDKE:N E. Commonwealth Edison Co. 78/09/15 Ip. 94270:052.
- --7B10170189 LERW7B-078/01L-0 on 7B0B1B.possible use of atypical weld metal discovered in 4-loop PWR Reactor Vessels in subj facils Interim RCB heatup & cooldown curves calculated & used to provide adequate conservation until issue resolved.

 BHANNON, R. E. Commonwealth Edison Co 78/09/15. 3pp. 94270.053
- 7810170251 Forwards LERW78-060/03L-0

 WANDME/N.E. Commonwealth Edison Co. 78/09/25 Ip. 94236: 338.
- --7810170253 LER#78-060/03L-O on 780826: Unit 2 Air-Ejector rod monitor RRTPR26 failed and would not reset. Event resulted from failure of Roots-connersville blower. Pump was replaced and returned to service.

 WANDKE.N. E. Commonwealth Edison Co 78/09/25. 1p. 94236.339
- 7810170218 Forwards LERW78-061/03L-0. WANDKE, N.E. Commonwealth Edison Co. 78/10/05. 1p. 94236:156.
- --7810170222 LER#78-061/03L-0 on 780905 during testing.NCC tripped due to a cracked Limitorque case caused by Jamming Redundant VLV was operable to insure containment integrity. Motor case, handwheel & bracket replaced & VLV returned to svc. REISB.J. Commonwealth Edison Co. 78/10/05. 1p. 94236:157.
- 7810170239 Forwards LER#78-062/03L-0.
 HANDKE-N.E. Commonweelth Edison Co. 78/10/06. 1p. 94236-324.
- --7810170242 LER#78-062/031-0 on 780906: During testing, RW8T to charging PP suction valve, 2mov-vc112e, failed to open remotely degrading sys per T. S. C. S. L. B. Limitorque model BM800 valve openator torqued out Valve stroked 3 times.

 REI88, J. Commonwealth Edison Co. 78/10/06. 1p. 94236:325.
- 7911240218 Forwards LER#78-054/03L-0. WANDKE, N. E. Commonwealth Edison Co. 78/10/13. 1p. 94466:350.
- --7811240220 LER#78-064/03L-0 on 780913: during normal open-received a channel deviation alarm. Pur range channel N42 was reading 93% instead of 100% Caused by defective 25 volt pur supply in N42 pur range drawer. PIECK-T. A. Commonwealth Edison Co. 78/10/13. 1p. 94466:351.
- 7811240145 Forwards LER#78-065/03L-0.
 WANDKE,N.E. Commonwealth Edison Co. 78/10/19. 1p. 94456:248.
- 7811240147 LERRYR-065/03L-0 on 780919: during normal oper-channel PL-5 had failed high & assoc histables were tripped due to faulty XMTR(level, mode 1302495W). XMTR replaced w/spare & channel receilbr. ROQERB.C.L. Commonwealth Edison Co. 78/10/19. 1p. 94456:249.
- 7811240195 Forwards LER#78-066/03L-0.
 WANDKE,N.E. Commonwealth Edison Co. 78/10/25. 1p. 94458:342.

- ---7811240196 LER#78-066/03L-0 on 780925; pressurizer level 2LT-459 was found to be 6% lower that the other 2 channels No cause was found for failure.

 HNNEEN,P Corronwealth Edison Co. 78/10/25. 1p. 94458:040.
- 7811240139 LERBYRE-067/03L-O on781008:8/0 level channel 2 LI-538 was found to be indicating 6% higher than the other 2 channels. Caused by dirt in XMTR sensing lines & a XMTR oscillator PN803827U01 being out of tone. CAMPBELL, J. Companyaelt bedison Co. 78/11/04. ip. 94456:362.
- 7811240135 Forwards LER#78-067/03L-0.

 WANDKE,N.E. Commonwealth Edison Co. 78/11/06. Ip. 94456:361.
- 7811240176 Forwards LER#78-069/03L-0. WANDME:N E. Commonwealth Edison Co. 78/11/14. 1p. 94458:271.
- ---7811240178 LER#78-049/03L-0 on 781015:20 MSIV failed to close from the control room Caused by failure of both DC solenoid valves & AC solenoid valve. AC solenoid valve replaced.
 MELNICOFF, M.A. Commonwealth Edison Co. 78/11/14. 3pp. 9455:272
- 7812210217 Forwards LER#78-071/03L-0.
 WANDKE N. E. Commonwealth Edison Co. 78/12/08. lp. 94279:117.
- --7812210221 LER#78-071/03L-0 on 781108: during monthly performance test on containment spray pump 2C.a cooling water hose on diesel engine broke. Caused by a defective cooling water hose on diesel angine.
 KRAMCZAK.a.T. Cormonwealth Edison Co. 78/12/08. 1p. 94279: 118.

T. Hearing transcripts on non-antitrust matters

- 7812040045 Transcript of 781121 hearing re subj facil spent fuel pool expansion, pp. 181-287.
 LUTON.E., REMJCK.F. J., LITTLE.L.W. Atomic Bafety and Licensing Board Panel. 78/11/21. 107pp. 94325:179.
- 7812040047 Transcript of 781120 hearing rs subj facil epent fuel pool sypansion, ppi-180. LUTON.E., REMICK.F.J., LITTLE.L.W. Atomic Safety and Licensing Board Panel. 78/11/20. 181pp. 01791:057.
- DOCKET 30-305 KEHAUNEE NUCLEAR POWER PLANT

 F. Security, medical, emergency & fire protection plane
- 78i03001i6 Sumary of 780928 & 29 meeting re fire protec open items. Util agreed to implement some parts of the "Fire Safety Protec Eval" by 800101 & present further rept as to why other recommendations need not be met.

 MLYNCZAK.M.M. Operating Reactors Branch 1 (Pre 790625). 78/09/29.

 4pp. 94035:189.
- 78:0330110 Request for add1 info on fire protec w/add1 steff position re fire rating of barriers separating diesel generator rooms from corridor to screenhouse.

 9CHHENCER.A. Operating Reactors Branch i (Pre 790825). 78/10/06.
- 7810300105 Forwards responses to 781006 NRC request for add1 info re fire protec: "Responses to Request for Add1 Info", "Analysis of Circulating Haber Pump Oil Fire", "Analysis of Relay Room Fire", "AMED: E. W. Wisconsin Public Service Corp. 78/10/25. 14pp. 94035:026
- 7812810194 Forwards rev to Industrial Security Manual of subj facil. Requests w/holding from public disclosure.

 JAMESIE H. Wisconsin Public Service Corp. 78/12/18. ip. 94279:064

9. Adjudicatory correspondence

- 7810160017 Expresses concern re adequete à reliable elec pur supply. Requests limited appearance in support of util in subj lic renewal proceedings.

 MOFPNAN.R.P. Green Bay Packing, Inc. 78/09/29. Ip. 94004:339.
- 7B10170040 Requests limited appearance in support of WI Pub Svc in increesed apent fuel storage matter. PEARSON.T.R. Affiliation Unknown. 7B/10/02. ip. 94235:338.

- 7811210471 Issuance date for principal documents has been deferred to 781127.
 LAHRENCE, J. F. Office of the Executive Legal Director. 78/10/31.
 1p. 03956: 220.
- 7812010079 Requests into re-making appearance at pub hearing re-subj-facil. SCHMIDT.T.H. Wisconsin Paper Council. 78/10/31. 1p. 94416.225.
- 7812040141 Forwards NRC Staff's interrops to Citizens for Safe Energy/ Safe Haven, Ltd. Response must be served on or before 781128. LAWRENCE, J. F. Office of the Executive Legal Director. 78/11/09. 1p. 74456:097
- --7812040144 NRC Staff interrogs to & request for production of documents from intervenors Citizens for Bafe Energy/Bafe Meven Ltd. Interrogs concern testimony to be presented, admitted contentions & ASLB questions.

 LMRENCE, J. F. Office of the Executive Legal Director. 78/11/09, 79p. 94456.088.
- 7812040283 Forwards Staff Interrog to Citizens for Bafe Energy/Bafs Haven Ltd. Response must be served by 781128. LAWRENCE, J. F. Office of the Executive Legal Director. 78/11/09, 1p. 94379-342
- --781204028B NRC Staff Interroge to & Request for the Production of Documents from Intervenors Lakeshors Citizens for Bafe Energy/Bafe Haven Ltd LAHRENCE, J. F. Office of the Executive Legal Director. 78/11/09. 9pp.
- 7812050245 Forwards Staff Interops to State of MI.Response requested by 781128.

 LAWRENCE, J. F. Diffice of the Esecutive Legal Director. 78/11/09.

 1p. 94202:068.
- --7812050252 NRC request for production of documents from & interrogs to Blate of MI re planned testimony & witnesses.

 LAHRENCE, J. F. Diffice of the Executive Legal Director. 78/11/09. 3pp. 94202:069.
- 7812110306 Interrogs submitted by intervenor LACSE to applicant WPSC re LACSE contentions on such topics as radioactive emissions, experiments on deterioration of neutron absorber plates & ramovel of radioactive wastes. Certificate of Svc encl. BABT.B.A. Leveshore Citizens for Bafe Energy. 78/11/11. 4pp. 94204:090.
- 7811270273 Notice of w/drawel by J Lawrence as counsel representing NRC in proc re increase spent fuel storage capacity at subj facil. Future correspondence should be addressed to W Climstead. Cert of Svc encl.
 LAWRENCE, J. F. Office of the Esecutive Legal Director. 78/11/13.
 3pp. 94237:036.
- 7812130220 Licensee HI Pub Bvc first set of interrogs to & request for production of documents from intervenors LACE & Bt of HI. Interrogs concern, inter elia, identification of intervenors contentions & presentation of evidence.

 BAKER, D. A., KEANE, B. E. Wisconsin Public Service Corp. 78/11/20. 3pp. 94243:049.
- 7812180267 Response by intervenors 8 Bast & H Scheefer to NRC Steff's first set of interrogs. Cert of Svc encl. BAST, 8. A. . SCHAEFER, W. Affiliation Unknown. 78/11/28. 9pp. 94365: 335.
- 7812210006 "Intervenors Responses to Licensess' First Set of Interrogs' A Thermo-Inversion around the plant sites may cause a higher level of radiat to be present. Thermo-Inversion prevents emissions escaping to higher atmosphere. Cert of Svc ancl. CURDARQ.W. M. Affiliation Unknown. 78/11/28. 7pp. 94249:291.
- 7812220027 Interrogs propounded by St of WI to applicants WIPS, HI Par & Light & Madison gas & Elec re appl to mod spent fuel pool.
 Interrogs concern Contentions#2 & #13.
 WALSH, P. Wisconsin, State of, 78/11/30. 4pp. 94248: 322.
- --7812220029 Interrage propounded by St of WI to NRC Steff. Interrage concern Steff's position re tech merit of each of intervenor's admitted contentione.

 MMLSH, P. Misconsin, State of, 78/11/30. 4pp. 94248: 326.
- --7812220031 Bt of MI's answers to NRC Staff's first set of interrogs to request for production of documents. St does not anticipate utilizing in its crose-exam any documents not already listed by Staff to applicant MIPS.Cart of Svc encl.

 WALBH.P. Misconsin, State of, 78/12/01, 3pp. 94248:330.

7812270037 Notifies intervenor that they failed to address section "c" of "Interrogatories Relating to Bd Questions" of 781107, which must be answered in timely writing. gvANB.D.J. OPfice of the Executive Legal Director. 78/12/05. 3pp. 94160:207.

- p. Operating license stage documents & correspondence
- 7812130386 "Fire Protec in Oper Nuc Pur Stations-Kewaunee Safety Eval Rept Review" lists suceptions to fire protec progressenting a differing engr point of view which should be eval by NRC incl turbine bldg.control valvestair compressor. HALLR.E. Brookhaven National Laboratory. 7812130386. 78/09/06.6pp. 94292:222.
- 78:01:01:00 Qualification of Reactor Physics Methods for appl to subject. Addresses reactor model description, qualification & quantification of an addresses after evaluations of subject.

 e Wisconsin Public Service Corp. 78/09/29, 188pp. 94065:001.
- 78:012004: Forwards non-proprietary & proprietary copies of "dualification of Reactor Physics Methods for Appl to Rewennese"w/description of neutronic calculation methodology for NRC rev. H/o encl repts.

 JAMES E. H. Wisconsin Public Service Corp. 78/10/05. 2pp. 94322:315.
- --7810120042 States that some math in the rept"Qualification of Reactor Physics Methods for Appl to Kewaunee"is proprietary & should be withheld from public.
 P18MER.J.R. Nurlear Associates International Corp. (subs. of Control Data Corp.). 78/09/28. 6pp. 94332:317.
- 7810110092 Responds to 780913 NRC request for schedule for submittal of rev ECCB analysts w/corrected tircontum-mater heat generation calculations. Earliest submittal date is Jan, 1974 JANES, E. H. Wisconsin Public Service Corp. 78/10/06. jp. 94065-352.
- 7810310016 Summarizes meeting on 780929 re Westinghouse rad bank swap measurement prog. RDSENTHAL.J.E. Reactor Safety Brench (Pre 791030). 78/10/13. 4pp. 94094:326.
- 7811080339 Notice of 781101 meeting w/util re reactor physics methods qualification. MLYNCIAK.M.M. Operating Reactors Branch 1 (Pre 790628). 78/10/23. 201. 74406:305.
- 7810270139 Forwards copies of proposed Amend#35 to subj facil Tach Bpscs. Proposed change responds to NRC request dtd 780828 re Overpressure Proteciton Tech Specs on mode installed in subject!

 JANES. E. W. Wisconsin Public Service Corp. 78/10/24, 8pp. 94060:037.
- 7811200373 Bummerizes meeting of 781101 w/representatives of MPBC.NAI & Exten re NRC review of MPBC topical rept. "Qual of Reactor Physics Methods for Appl to Newaunes" of 781005.NRC will issue formal request for add1 info. Attendence list encl. MLYNCZAK.M.M. Operating Reactors Branch 1 (Pre 790625). 78/11/06.3pp. 94419:224.
- 7811130141 Notifies applicant of 781128 NRC-sponsored seminer re Model Radiological Effluent Tech Specs for Nuc Per Plants Encl w/Sminer Info Sheet(to be completed & returned by 781117) & Proposed Agenda.

 KEPRER.J. 9. Region 3. Chicago. Office of the Director. 78/11/07.6pp. 94087:325.
- 7811140196 Forwards proposed Amend#36 to subj Pacil Tech Spec, changing definition of rated pur, updating safety related shock suppressor listing & correcting error in listing of fire detectors. Also forwards check for fee.

 Misconsin Public Service Corp. 78/11/10. 18pp. 94384:295.
- 7811280079 Forwards request for add1 info after reviewing topical rept, "Qualification of Reactor Physics Methods for Appl to Kewaunes." Response requested by 781130. BCHAENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/15. 3pp. 03554:262.
- 7811280359 Forwards copy of TB 3.10-1 which was issued w/Amend@16 to Facil Oper LiceDPR-43 on 770325. This page was inadvertently satted from some Tach Spec copies.

 8CHAENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/15.
 3pp. 94397:219.

- 7812:50198 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out math. H/encl Registration Form & List of Locations. HILLER.J.R. Assistant Director for Bite & Bafeguerds (Pre 791030). 78/11/15. Spp.
- 7812190062 Forwards Rev#1 "Dreft Radiological Effluent Tech Specs" for PWR's\NNREG-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pwr Plants" (NUREG-0133).

 @RIMES.B.K. Assistant Director for Engineers & Projects (Pre 790623). 78/11/15. 6pp. 94215:101.
- 7812150006 Discusses possible dangers of LOCA in containment purging during normal plant open. Requests either commitment to limit purging or justification for continuing. W/encl AND #7812080207. BCHMENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/11/28. App. 94209:206.
- 7812080198 Forwards Safety Eval & Environ Impact Appraisal dtd 781201 re auth to increase spent fuel storage pool capacity at subj facil.

 8CHMENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/12/01 2pp. 94109:230.
- --7812080190 Befety Eval re Mod of spent fuel storage pool of subj facil Concludes such expansion will not be inimical to pub health or security. * Office of Nuclear Reactor Regulation, Director. 78/12/01. 13pp. 94109:232.
- --7812080193 Environ Impact Appraisal re mod to spent fuel storage pool. Finds proposed lic amend will not significantly affect quality of human environ so environ impact statement need not be prepared.

 M. Office of Nuclear Reactor Regulation, Director. 78/12/01, 20pp. 94109:246.
- 7812080108 Responds to 781115 request for add1 info re "Gual Reactor Physics Methods for Appl to Kewsunes." Add1 info describing methodology & procedures to evel key physics parameters to determine if reenalysis of accidents is req set for 790115.

 JAMES E. W. Hisconsin Public Service Corp. 78/12/05. 22pp. 94107:314.
- 7812280119 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J. 0. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94310:215.
- 7812260011 Forwards Amend®23 to Facil Oper LicHDPR-43--revising tech specs as requested in 781025 ltr w/BaFaty Eval & Notice of Issuance.

 BCHMENCER, A. Operating Reactors Branch i (Pre 790625). 78/12/12.

 Zpp. 94130:193.
- --7812280015 Amend#23 to Facil Oper Lic#DPR-43 rovising Tech Baecs re completion of facil mode for fire protec. SCHMENCER,A. Operating Reactors Branch I (Pre 790625), 78/12/12. 2pp. 94130:195.
- --7812280016 Safety Evel Rept supporting Amend#23 to Oper LicMDPR-43 concluding that proposed mode are acceptable re improvements in fire protec prog & continued safe oper of facil-panding resolution of incomplete items.

 Office of Nuclear Reactor Regulation, Director. 78/12/12, 53pp. 74130:197.
- --7812260018 Notice of Issuance of Amend#23 to Facil Oper Lic#DPR-43 on 781212.

 8CH#ENCER, A. Operating Reactors Branch 1 (Pre 790625), 78/12/12.
 2pp. 94130: 251.
- 7812270171 Responds to 770926 ltr re baron dilution accidents. Re-eval of potential for such accidents concludes no single failure could result in reactor coolent boron dilution by contents of caustic spray additive standpips.

 JAMES. E. M. Wisconsin Public Service Corp. 78/12/20. 2pp. 94018:092.
- G. Inspection reports, IE Bulletins & correspondance
- 7810110182 Forwards IE Inspec Rept#50-305/78-15 on 780807-11 during which no items of noncompliance were noted. FIORELLI, 9. Region 3, Chicago, Office of the Director. 78/09/06. 2pp. 94069:117.

- --/HO10101B5 IE Inspec Reptm30-305/78-15 on 760705 during which no items of noncompliance were noted Major areas inspected included: Plant Oper refueling startup testing, review of plant oper after refueling, non routine event followup. CHOULES, N. C., WARNICK, R. F. Region 3, Chicago, Office of the Director. 78/09/05. lipp. 94069:119.
- 7810190026 Forwards IE Inspec Rept#50-305/78-14 on 780731-0802 during which no items of noncompliance were noted.

 HEISHMAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Bupport Branch. 78/09/12 2pp. 94329:353
- ---7810190029 IE Inspec Rept#50-305/78-14 on 780731-0802 during which no items of noncompliance were noted Major areas inspected included :followup of Unresolved items identified in IE Rept #50-305/78-08 & matls for snubber seals.

 DANIELBON.D. H. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 78/09/12. 5pp 94329:355.
- 7812010065 Forwards IE Inspec Rept#50-305/78-16 on 780911-13 during which no items of moncompliance were nated. DAVIB.A.B. Region 3. Chicago, Fuel Facility & Materials Safety Branch. 78/09/29. 2pp. 74416:190.
- --7812010070 IE Insper Rept#50-305/78-16 on 780911-13 during which no items of noncompliance were noted Major areas inspected incl:quality control of analytical measurements of radiol effluents, internal audits.
 AXELSON, W. L., ESBIO, T. H. Region 3, Chicago, Office of the Director. 78/09/29. 9pp. 94416:192.
- 7810230337 Forwards IE Circular#78-17. (See ANO:7810230221 Docket 50-133.781013)

 XEPPLER, J. Q. Region 3. Chicago. Office of the Director. 78/10/13. Jp. 94166:360
- 7811070227 Responds to 780908 request for add1 info re IE Inspec Rept#50-303/78-10 item of noncompliance:contention that record keeping of ultrasonic test couplant mat1 did not conform to Tech Spece. JAMEB.E.W. Wisconsin Public Service Corp. 78/10/13. 2pp. 74079:196.
- 78:2060124 Forwards IE Inspec Rept#50-305/78-17 on 78:1002-06 during which no items of noncompliance were noted.
 FIORELLI, C. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/27. 2pp. 94332:231.
- --7812060128 1E Inspec Rept#50-305/78-17 on 781002-06 during which no items of noncompliance were noted. Major areas inspected inclidesign changes, procurement, records, nonroutine followup & IE Builetin followup.

 CHOULES, N. C., WARNICK, R. F., Region 3, Chicago, Office of the Director. 78/10/27. App. 94332:233.
- 7811130351 Ack receipt of 781013 ltr informing NRC of steps taken to correct violations noted in 780708 NRC ltr.Blates that recordseeping is licensee's responsibility.

 KEPPLER, J. O. Region 3. Chicago, Diffice of the Director. 78/11/06. lp. 94007:332.
- 78:11:00072 Forwards IE Circular 78-18.
 KEPPLER, J. G. Region 3: Chicago: Office of the Director. 78/11/06.
 1p. 94:12:280.
- 7812120225 Forwards IE Inspec Rept#50-305/78-19 on 781016-17 during which no items of noncompliance were noted. #IORELI.9. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/11/06. 2pp. 94277:135.
- --7812120231 IE Inspec Rept#50-305/78-19 on 781016-17 during which no items of noncompliance were noted. Mejor areas inspected inclitraining & requal prog. fire protec & prevention prog. MASSE.R.E. Region 3. Chicago, Office of the Director. 78/11/02. 3pp. 94277:137.
- 7812050267 Forwards IE BullstinN78-12A. suppl to IE Bullstin 78-12. M/encl AND:7811300055. KIPPLER.J. G. Region 3. Chicago, Office of the Director. 78/11/24. ip. 94202:213.
- 7812290009 Forwards IE Inspec Rept#50-305/78-21 on 781025-26 & Notice of Violation.
 F10RELLI.9. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/11/24. 2pp. 94207:330.
- --7812290011 Notice of Violation from inspec on 781025-26.

 * Region 3, Chicago, Office of the Director. 78/11/24. ip. 94207:332.

- --78:2290014 IE Inspec Rept#50-305/78-21 on 78:025-26 during which i it of noncompliance was noted failure to fully implement an acceptable insvc testing prog for pumps & valves.

 8HITH.J. D., STREETER.J.F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/11/21. 3pp. 74207:333.
- 7812280053 Forwards IE Bulletin 78-14.

 KEPPLER. J. Q. Region 3: Chicago: Office of the Director. 78/12/19
 1P. 03554:358.
- R. Periodic operating reports & related correspondence
- 7810170156 Forwards Monthly Open Rept for Bept 1978.

 JAMES, E. M. Hisconsin Public Service Corp. 78/10/10. 1p. 94236:091.
- --7810170159 Manthly Oper Rept for Bept 1978.
 WALLACE, J. J. Wiecansin Public Bervice Corp. 78/10/04. 4pp. 94236:092.
- 7811140116 Forwards Monthly Open Rept for Oct 1978.

 JAMES, E. W. Hisconsin Public Service Corp. 78/11/08. ip. 74425:177.
- --7811140118 Monthly Oper Rept For Oct 1978. HALLACE, J. J. Wisconsin Public Service Corp. 78/11/03 6pp. 94425-178
- 8. Reportable occurrances, LERs & related correspondence
- 7810100055 Forwards LER#78-030/03L-0.

 JAMES E. H. Hisconsin Public Service Corp. 78/10/02. 1p. 74415:161.
- --7810100062 LER#28-030/03L-0 on 781002:during steady full pur oper one BH pump failed due to excessive undercutting of the encl tube for tool relief at internal end threads during mfg. RUITER.O.H. Hisconsin Public Service Corp. 78/10/02. ip. 94415:162.
- 7810130149 Forwards LER#78-024/03X-3.

 JAMES.E. W. Wisconsin Public Service Corp. 78/10/09. ip. 94002-344
- 7810230247 Forwards LER#78-024/03X-0.

 JAMES E. W. Wisconsin Public Bervice Corp. 78/10/09. ip. 94164: 081.
- --7810230251 LER#78-024/03X-3 on 780905: supply breaker to MCC 1-62F opened 17 times on 9 separate dates. Breaker trip coil does receive 2 spurious electrip signal w/out overload condition present.
 RUITER, 9. M. Wisconsin Public Service Corp. 78/10/09. 1p. 94164-082
- 7810240128 Forwards LERW78-031/03L-0.

 JAMES, E. W. Wisconsin Public Bervice Corp. 78/10/18. 1p.
- --7810240138 LERM78-031/03L-0 on 780918:small leak was discovered on the discharge of coolent charging pump 10 while CCP 18 was out of 8VC & for maint Crack in CCP 10 was caused by oper stress & vibration loading.

 RUITER.O.H. Wisconsin Public Bervice Corp. 78/10/18. 1p.
- 7811220196 Forwards LER#78-032/03L-0.
 JANES E. W. Hisconsin Public Barvice Corp. 78/11/17. 1p. 74074:251.
- --7811920199 LER#78-032/03L-0 on 781019:while performing monthly 4-hour full load E/9 SP load.D/9 lA drifted low & could not be raised until load was decreased to less than 2100 KW. Caused by maladjustment of cam in upper load limit switch. RUITER: 0.M. Misconsin Public Service Corp. 78/11/17. ip. 94074:252.
- 7811280299 Forwards LER#78-033/04L-0 & 78-034/03L-0.
 JAMES.E.M. Wisconsin Public Service Corp. 78/11/22. 1p. 94379: 294.
- --TSi1280305 LERW78-033/04L-0 on 781024; results of PH analysis of grab sample from water softening unit regeneration waste water were not recorded on log sheet. Lab personnel failed to record PH sample results.

 RUITER. G. H. Misconsin Public Bervice Corp. 78/11/22. 1p. 74395; 275.

- --7811280010 LER#78-034/03L-0 on 781025:train B reactor trip breaker would not open immediately when a trip signal was applied. Adjustable reset lever on breaker undervoltage trip attachment would not reset due to normal wear RUITER. 9. H. Wisconsin Public Service Corp. 78/11/22. 1p.
- 7812150232 Forwards LER#78-035/03L-0 JAMES E.M. Hisconsin Public Service Corp. 78/12/11. 1p. 94213.136.
- --7812190234 LER878-035/03L-O on 781111: improper switching sequence caused bus 1-5 to trip. Caused by add1 switching procedure step added in wrong place. Procedure corrected & tested while plant was shutdown.

 BUITER 9. H. Hisconsin Public Service Corp. 78/12/11. 1p. 94313-157.
- DOCKET 30-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2
 F. Security, medical, smergency & fire protection plans
- 7811140143 Forwards responses to 780913 &19 NRC ltra re addl info on fire protest prog quip. MAYER.L.O. Northern States Power Co. 78/11/08. 16pp. 94383:250.
- 7811290076 Summerizes progress of Fire Protec Review W/encl request for additions taff positions: & evals. Requests meeting w/licenses i week after receipt of responses to latest staff positions.

 LAIMS, 0. Plant Systems Branch (Pre 791030). 78/11/16. 27pp. 94192:182.
- 7811290365 Requests addl info re fire protec prog & forwards NRC staff proposal & recommendations. Areas needing info include: equip req for achieving hot shutdown & fire brigade training. 8CHENCER, A. Operating Reactors Brench 1 (Pre 790625). 78/11/21. 88ps. 94180:001.

I. Financial information

- 7810300186 Forwards 1977 Annual Rept & schedule showing 1977 actual Cash Flow to comply with Reg Quide 9. 4. Net income by dividence declared instead of dividence paid has been reduced to get retained earnings figure.

 CARLBON.L.R. Northern States Power Co. 78/10/23. 2pp. 94034:143.
- P. Operating license stage documents & correspondence
- 7811150115 Requests lic emend no later than 781215 re Delation of Reactor Trip on Turbine Trip Below 50% pur & encl requests for Tsth Spec changes & eafety evaluation supporting changes.

 MAYER-L. D. Northern States Power Co. 78/11/03. 34pp. 94113:340.
- 7811170255 Forwards Amend#32 & 26 to subj facil oper lic re pressurized hastup rate reactor vessel pressure-temperature oper limits. Also forwards BER, Notics of lasuance, Tech Specs & Table of contents related to Amend#32 & 26.

 BCHMENCER, A. Operating Reactors Stanch 1 (Pre 790625). 78/11/01.
 2pp. 94049:035.
- ~-7811170259 Amended2 & 26 to open lic changing Tech Specs related to heatup rate reactor vessel pressure-temperature open limits, and the part length rods.

 SOMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/01.
 1899. 94049: 037.
- --7811170265 BER for Amends#26 & 32 to subj fecil oper lic.Concludes that Tach Spec changes related to heatup rate reactor vessel pressure-temp oper limits. & part length rods does not involve a major hazards consideration.

 8CHMENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/01. 35p. 94049:055.
- --7811170268 Notice of Issuance of Amend#32 & 26 to subj facil oper lic. SCHMENCER.A. Operating Reactors Branch 1 (Pre 790629). 78/11/01. 2pp. 94049:060.
- 7811280403 Notice of Proposed Issuance of Amend to Facil Oper Lic 4DPR-42 & DPR-60, rev Tach Spec re use of Exxon fuel in Cycles 5 thru 8. 8CH-ENGER. A. Operating Reactors Branch 1 (Prø 790625). 78/11/09. 4pp. 94397:317.

- 7812010083 Confirms telephone discussion on 781107 re 781116 meating for local pub officials in vicinity of subj facil Forwards tentative agenda.
 KEPPLER.J. G. Region J. Chicago, Office of the Director 78/11/08 3pp. 94417:137
- 7812190047 Forwards Rev#l "Dreft Radiological Effluent Tech Specs" for PWR's(NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133) GRIMES, B.K. Assistant Director for Engineers & Projects (Pre 790625), 78/11/15, 6pp. 94215:039
- 7810170220 Outlines schedules for correction of Zirconium-Water reaction inconsistency & dev of Upper Plenum Injection model & plant specific calculations Tentative completion date is April 1979.

 MAYER L. O. Northern States Power Co. 78/10/12 2pp. 94236-163
- 7810300100 Notice of 781026 meeting w/ util to discuss bases for reactor coolant Tech spec in 780907 NRC ltr to util. 9ROTENHUIS.M. Operating Reactors Branch 1 (Pre 790625). 28/10/12. 2pp. 94035:066.
- 7810300237 Evaluation of Overall Asymmetric LOCA Loads Notifies of decision to discontinue participation in utility task group's activities. Buby util's plan is practical because of relatively recent design of reactor co
- 7011130338 Confirms upcoming 781116 meeting to discuss NRC's reg prog for protecting pub health & safety. A tentative meeting agenda is enclosed. KEFPLER, J. 9. Region 3. Chicago, Office of the Director. 78/11/02. 3pp. 94007.305.
- 7811140022 Confirms uproming 781116 nesting to discuss NRC's reg program for protecting pub health & eafety.A tentative meeting agenda is enclosed. KEPPLER,J. Q. Region 3. Chicago, Office of the Director. 78/11/02 2pp. 94419:024.
- 7811160191 Confirms telephone plans to meat & discuss pub health & eafety protec prog as it relates to subj facil Tentative agenda for 781116 meeting enci. KEPPLER.J.O. Region 3, Chicago, Office of the Director. 78/11/02. 3pp. 94136:059.
- 7811350147 Lic Amend request proposing change to reactor trip on turbine trip setpoint Rev setpoint is justified on basis of NRC approved transient analysis methods employed by Hestinghouse Corp.

 * License Fee Management Branch. 78/11/03. 1p. 94272:360.
- 7811130137 Notifies applicant of 781128 NRC-sponsored seminar re Model Radiological Effluent Tech Specs for Nuc Pur Plents Encl w/Beminar Info Bheet(to be completed & returned by 781117) & Proposed Agenda. KEPPLEN. 1. G. Region 3, Chicago, Office of the Director. 78/11/07. Ann. 03883
- 7811210452 Confirms plans for 781116 meeting concerning reg prog for protec of pub health & safety re subj facil. Tentative agends and. KEPPLER. J. O. Region 3. Chicago, Office of the Director. 78/11/08. 3pp. 94480: 327.
- 7811290010 Forwards "Notice of Proposed Issuance of Amendments to Faci: Oper Lic," in response to 780908 amend appl re refueling of facil WExxon Nuc Co Fuel for oper Cycles 5 thru 8 at each unit. W/encl ANO: 7811280403.

 BCHWENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/11/09.
 2pp. 74179: 112.
- 7812180050 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73 Requests pre-workshop registration of attendees to facilitate sending out math. W/encl Registration Form & List of Locations.
 MILLER, J. R. Assistant Director for Site & Safeguards (Pre 791030), 78/11/15, 0pp. 94103.070.
- 7811290195 Forwards lic amend fee for lic*DPR-42 & DPR-60. Lic amend request involves a single safety issue.

 * Northern States Power Ca. 78/11/22. 1p. 94013:253.
- 7811280279 Request for amend to open lic#DPR-42 & DPR-60 to change Tecl Space re secondary coolant chamistry monitoring requirements. Incl safety eval & minimum frequencies for sampling tests. H/check for 84, 400.
 MAYER.L.D. Northern States Power Co. 78/11/02. Soc. 94299:222

- 7812150051 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing Wienci AND. 7812080207.

 BCHMENCER: A Operating Reactors Branch 1 (Pre 790629). 78/11/28 dpp. 94210:122
- 7812060141 Forwards Environ Event Rept 78-11 on Cooling Tower Open for Nov 1978. Slightly elevated blowdown flow req for 3 days, during month to accompdate cooling sys preventative maint work MARD. E. C. Northern States Power Co. 78/12/01 ip. 94372-251.
- 7812080135 Forwards 780216 rept "Analysis of Capsule V from NSP prairie Island#2 Reactor Vessel Radiat Burveillance Prog. "MCAP-9212 to replace those forwarded 780216 k lost in trensit MAYER.L.D. Northern States Power Co. 78/12/06 ip. 94104 255.
- --7812080138 Forwards "Analysis of Capsule V from NSP subj facil Unit#2 Reactor Vessel Radiat Burvelllance Prog." WCAP-9212 MAYER.L. Q Northern States Fower Co 78/02/16 1p 94104.256.
- --7812080142 'Analysis of Capsule V from NSP subj facil Unit#2 Reactor Vessel Radiat Burveillance Prog." Repts effects of neutron irradiation on reactor pressure vessel matl under operating conditions
 DAVIDSON.JA. YANICHKO.B.E., ANDERSON.B.L. Heatinghouse Electric Corp. MCAP-9212. 77/11/30. 26pp. 74104 297
- 78:2250017 Emphasizes importance of sumbitting accorate & complete info to NRC by licensess & applicants. Info submitted must be substantiated by data & calculations Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIR.J.O. Opfice of Inspection & Enforcement, Office of the Director 70/12/06. 2pp. 94131-034.
- 78:2130215 Requests util help w/vital erea analysis re subj facil. Informs of site visit on 790109-11 by Los Alemos Scien Labrepresentatives.

 8CHMENCER, A. Derating Reactors Branch (Pre 790625). 78/12/08 2pp. 94306:085.
- 7812190154 Summary of 781026 meeting to discuss tech specs for secondary water chem.reactor coolant activity & secondary coolant activity.

 OROTENBUIS.M Operating Reactors Brench 1 (Pre 790625). 78/12/12 Bps. 94340 150.
- 7812290236 Forwards request for add1 info re Topical Rept XN-NF-78-30 in order to complete review of reload conditions Req info should be submitted w/in 45 days.

 IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/12/19
 App. 94191 232

Q. Inspection reports. IE Bulletine & correspondence

- 7810110199 Act receipt of 780918 itr informing NRC of steps taken to correct violations noted in 780829 NRC ltr. FIORELLI.G. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/10/04 ip. 94068:356.
- 7810230338 Forwards IE Circular#78-17.(8ee AND.78102302R):Docket 50-312.781013)
 KEPPLER, J. Q. Region 3. Chicago: Office of the Director. 78/10/13. ip. 94167:041.
- 7811150054 Forwards IE Circular 78-18. KEPPLER.J. Q. Region 3. Chicago. Office of the Director. 78/11/06. 1p. 94112:183.
- 7812200091 Forwards IE Inspec Repts#50-282/78-12 & #50-306/78-13 on 780905-08, 11-14.20-22 & 25-29 & Notice of Violation. FIORELLI, 0. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/11/09. 2pp. 94156:935.
- --7812200095 Notice of Violation from inspec on 780905-08.11-14.20-22 & 25-29.

 # Region 3, Chicago, Office of the Director 78/11/09. ip. 94184-1327
- --78:2200099 IE Inspec Repts#50-282/78-12 & #50-306/78-13 on 780905-08, 11-14, 20-22 & 25-29 during which I item of noncompliance was noted: failure to follow an implementing procedure for approved GA prog.
 FEIERABEND.C.D., WARNICH.R.F. Region 3, Chicago, Office of the Director, 78/11/06, 5pp. 94136:338.

- 7812210046 Forwards IE Inspec Repts#50-282/78-14 & #50-306/78-15 on 781016-20 & Notice of Violation. FIDRELLI, O. Region 3. Chicago, Reactor Operations Nuclear Support Dranch, 78/11/14. 2pp. 94268:335.
- --7812210049 Notice of Violation from inspec on 781016-20.
 Region 3. Chicago. Reactor Operations Nuclear Support Branch 70/11/14. ip 94260:337
- --7812210054 IE Inspec Repts#50-282/78-14 & #50-306/78-15 on 781016-20 during which I item of noncompliance was noted an employee was not wearing proper protective squipment.

 RIDEN.M.D. LITTLE.W.S. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/11/14. 4pp. 94268 338.
- 7812050278 Forwards 16 Dulletin#78-12A, suppl to 16 Bulletin 78-12, W/encl ANO.7811300055 KEPPLER.J. G. Region J. Chicago: Géfice of the Director. 78/11/24 19. 94202:165
- 7812210036 Responds to 781109 NRC ltr re violations noted in Inspec Repts#50-282/78-12 & #50-306/78-13 Corrective actions: Design Change Index Form(A)PINOP#340 rev to incl date of completion of installation. #ACHTERLL J. Northarn States Power Co 78/11/30. ip. 94267.362
- 7012270028 Ack receipt of 781130 ltr informing NRC of steps taken to correct violations noted in 781109 NRC ltr. FlOREULI, 0. Region 3. Chicago, Reactor Operations Nuclear Support Dranch. 78/12/14. 1p. 94159:242.
- 7812280062 Forwards IE Bulletin 78-14. REPPLER, 0 Region 3, Chicago, Office of the Director. 78/12/19. 1P. 03364:330.
- A. Periodic operating reports & related correspondence
- 7811140117 Monthly Open Rept for Oct 1978.

 Northern States Power Co. 78/11/01. 8pp 94425:169
- 7812120091 Forwards Monthly Oper Rept for Nov 1978 MAYER, L. O. Northern States Power Co. 78/12/08. 1p. 94274-195
- --7812120094 Monthly Oper Rept for Nov 1978. HUNGTAD. A A. Northern States Power Co. 78/12/01. Bpp. 94274, 196.
- 7810120029 Forwards Monthly Oper Rept for Bept 1978.

 MAYER, L. D. Northern States Power Co. 78/10/09. ip. 94421:174
- --7810120033 Monthly Oper Rept for Bept 1978. HUMBTAD.A.A. Northern States Power Co. 78/09/30. App. 94081:305
- 7811140113 Forwards Monthly Oper Rept for Oct 1978.
 MAYER.L.O. Northern States Power Co. 78/11/09. 1p. 94423 139.
- 8 Reportable occurrences. LERs & related correspondence
- 7810190034 Forwards LERW78-017/03L-0.
 MAYER, L. O. Northern States Power Co 78/09/12. ip. 94193:199.
- --7810180036 LER#78-017/03L-0 on 780815: During surveillance tast.1 chennel of low pressurizer pressure tripped below 1815 paig limit & 1 chennel of 10/10 steam line pressure tripped below 300 paig limit. Caused by instru drift. HN81AD, A.A. Northern States Power Co. 78/09/12 1p. 94195:200.
- 7810170224 Environ Event Rept 78-09 re open of plant circulating water sys in pertial recycle mode for Bept Except for 780921, excess blowdown flow was needed. For the month, everage delly blowdown flow rate was about 480cfs.

 WARD.E.C. Northern States Power Co. 78/10/02. 1p. 94236:166.
- 7810180021 Forwards LERW78-019/03L-0. MAYER.L.Q. Northern States Power Co. 78/10/12. 1p. 94195:191.
- --7810180025 LER#78-019/03L-0 on 780915: during course of investigative maint on NIB pur range channel 2N41, channel failed.

 Channel taken out of svc w/in 3 minutes. Caused by failure of -25V pur supply. Pur supply replaced.

 HNBTAD, A.A. Northern States Power Co. 78/10/12. 1p. 94195:192

- 70213 Environ Event Rept 78-10 covering oper of Plant circulating or sys in partial recycle mode u/daily average blowdown u in excess of 150 cfs D.E.C. Northern States Power Co 78/11/01. 1p 94039-122
- 00177 Reportable Occurrence 4P-RO-78-21 on 781128 during local a rate test at Unit 2 refueling penetration 258. tainment Purge Supply exhibited leakage in excess of Tech limits SVEY.FP
- Northern States Power Co 78/11/30 to 94335 136.
- 10159 Forwards LER#78-021/01T-0
- R.L.O. Northern States Power Co 78/12/12 1p 94133:531
- 2:40:6: LER#78-02:/017-0 on 78:1128 during refueling local leek rate ising revealed leakage in excess of Tech Specs limits thru sives in penetrations#236 & 238 Cause & Corrective action
- lli be given in Update Rept. NSTAD.A.A. Northern States Power Co. 78/12/12. 1p
- 90222 Forwards LER#78-022/03L-0.
- Northern States Power Co 78/12/20 1p 94159.305 Br. L. D.
- 2260237 LERN78-022/03L-0 on 781128: during survaillance test, valve iking leakage from CV-31239.#22 RHR Heet Exchanger Outlet blve was about 7 gal/hr.due to deteriorated valve packing. NSTAD.A.A. Northern Btates Power Co. 78/12/20 ip. 94139:306
- 30-309 MAINE YANKEE ATOMIC POWER PLANT
- eamphrogratics fater
- 0099 Ack receipt of itr describing training prog underway for irs Lehouillier & Rescorl Prog appears adequate & NRC | accept util centification when the applicants complete
- program successfully. .INS.P. F. Operator Licensing Dranch. 78/10/04. ip 94422.069
- 0101 Comments on 780919 Oper training program submitted by util.
- m interim basis MOLT.D J. Assistant Director for Quality Assurance & Operations.
- 10/04 2pp. 94422:067.
- orance & indemnity information

- 20066 Responds to 780922 NRC ltr by encl liability insurance insempts #21-30,33-38 to Policy #NF-194 & Endorsements #4.26-35 to Policy #NF-60 Endorsements #36,37 & 38 to #26-35 to Policy #NF-60 Endorsements #36,37 & 38 to #26 Nave not yet been received ## #1825.8. A. Maine Yankee Atomic Power Co. 78/10/04. 62pp.
- 9. 151.
- 0137 In response to 700922 request, forwards Endoraements 21 thru 10 NF-194 & Endorsements I thru 24.26 thru 33 to MF-60; 7 % 38 to MF-60 have not been received by util yet. 17RES.R.A. Maine Yankee Atomic Power Co. 78/10/04 1p.
- 7. 184
- rating license stage documents & correspondence
- 0171 Forwards check for \$2800 for licensing rev fee for proposed 199 MaS. deleting lit conditions for water quality limits

 TVeillence requirements falling under EPA. Fee submitted

 For protest pending determination of legality of fee.

 E.R.H. Haine Yankee Atomic Power Co. 78/10/02. 2pp.

 9:098.
- 0036 Forwards supplementary rept.CEN-93(M)-P. Amend 1-P: "ME Yankee 3 Quide Tube Inspec & Analysis", prepared by Combustion inc. Contains proprietary info & is wheld from public.
 ifies continued reactor oper. W/out encl
- E.R.H. Maine Yankee Atomic Power Co. 78/10/06. 2pp.
- 0153 Forwards check for \$8300 for lic_review fee for Class IV SCCS Evaluation Model for EUDOV for LIC review rea for clar SCCS Evaluation Model for Lic#DPR-36. Beliaves NRC fee dule is illegal & makes payment under protest & reserves t to recover all or part thereof. RDS.D. H. Haine Yankee Atomic Power Co. 78/10/11. 2pp.
- 0137 Confirms accomplishment of Item 3.1.2m of Table 3.1 in 1tr 80428 from NRC to R. Groce Notries on hase stations tent to control room replaced w/noizles suitable for use
- tent to control young papeas.

 let equip areas

 Y-D.E. Mains Vantes Atomic Power Co. 78/10/12. ip. 94400:355.

- 7811080043 Confirms sched of Corp mgt meeting for 781027 to discuss NRC inspec findings re util radiat protec prog ORIER.8 H. Region I. Philadelphia. Office of the Director. 78/10/19 ip 94398 134.
- 7810270077 Describes lube oil sys & proposed mod to reduce potential lube oil leakage from reactor coolant pump Lube oil sys oversized drawing encl.
 MDRDV.DE Maine Yankem Atomic Power Co 78/10/23. 3pp. 94059 192
- 7811290317 Forwards Amend#42 to Pacil Oper Lic#DPR-36 rev Tech Specs as requested in 771107 & 771201 ltrs W/appraisal of changes in monitoring prop & Notice of Issuance.
 REID.R.W Dperating Reactors Branch 4 (Pre 790625). 78/11/08 3pp. 94193:264
- --7811270318 Amend#42 to Facil Oper Lis#DPR-36 rev Tech Specs re r4dialogical & thermal effluent monitoring Changes involve shviron surveillance prog.air particulate charcoal gamma monitoring & estuary water temp monitoring REID.R W Operating Reactors Branch 4 (Pre 770625) 78/11/08 10pp 94193 267.
- --7811290319 Notice of Issuance of AmendW42 to Facil Oper LicWDPR-3b on 781108 Amend rev Tech Specs to require single continuously composited radiological sample at plant intake REID.R W Operating Reactors Branch 4 (Pre 790625) 78/11/08 2pp 94193-277
- 7811190091 Forwards "HYAP Reactor Open w/mod CEA Quide Tubes" & Amend 1-P "MYAP Cycle III Quide Tube Inspec & Analysis " ORDCE.R H. Haine Yankee Atomic Power Co. 78/11/09 1p 94114 012
- --7811150099 "MYAP Reactor or Open w/Modified CEA Guide Tubes."Defines guide tube wear observed in C-E reactors & describes modifications which will prevent further wear during Cycle
 - * C-E Power Systems. CEN-093(M)-NP. 78/11/09. 86pp 94114 013
- 7811270086 Forwards Startup Test Rept prior to Open of Cycle 4. W/enci Cycle 4 calculational model changes & CEA drop test results GROCE, R H Maine Yankee Atomic Power Co. 78/11/15 26pp.
- 7812130113 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out mail Wienci Registration form & List of Locations. MiLLER. J. R. Assistant Director for Bite & Safeguards (Pre 791030). MILLER, J.R. A. 78/11/15. 5pp
- 781R190042 Forwards Rev#1 "Dreft Radiological Effluent Teth Specs" for PMR 's (NUREQ-0473) & "Preperation of Rediological Effluent Tech Specs for Nuc Pwr Plants" (NUREQ-0133) GRIMES-B.K. Assistant Director for Engineers & Projects (Pre 790625), 78/11/15. 6pp. 94215:023.
- 7812070212 Notice of seminar on 781208 on new Model Rediclogical SECURE NOTICE OF Seminar on Follow on new model Rediciogics Effluent Tech Specs for nuc pur plants. Requests advance submission of seminar specific questions W/encl Seminar Info Sheet-Proposed Agenda & maps. GRIER B.H. Region is Philadelphia, Office of the Director. 78/11/21. Spp. 03555:107.
- 7811290243 Informs NRC of newly dev spent fuel storage concept to increase spent fuel storage capability of existing storage racks at environ & economic cost below any known alternative involves compaction & storage W/encl eval VANDENBURGH, D. Maine Yankee Atomic Power Co. 78/11/22. 25pp. 94237: 272.
- 7812140040 Finds Yanker Pur Spike Model (YAEC-1140)acceptable. Forwards eval & suppl REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/27. 2pp.
- --7812140042 Sefety Evel Rept for Yankee Pur Bpike Model Finds model acceptable Wencl SER Supplei dtd Aug 1978.

 * Operating Reactors Branch 4 (Pre 790625). 78/11/27. 15pp
- 7812180373 Notification of 781212 meeting re proposed deletion of NELBON.C.C. Operating Reactors Branch 4 (Pre 790625). 78/11/28, 2pp. 94350:198.

うししんとし とり し にいりつ

- 7812150098 Discusses possible dangers of LOCA in containment purging during normal plant open. Requests either commitment to limit purging or justification for continuing Wiencl ANO: 7812080207.
 - REID.R.W. Operating Reactors Branch 4 (Pre 790525). 78/11/29. 6pp. 94212:010
- 7812140383 Requests w/in 60 days specs which provide adequate assurance that containment purge valves & all hatches leading from containment are closed before radioactivity is released to environ
 REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/11/30 2pp. 03580.112.
- 7812180012 Notice of postponed 781213 meeting in Bethesde to discuss ME Yankee Atomic Pur's proposal to store fuel in mod "compact" fuel bundle in spent fuel storage pool. Meeting date to be determined NELSONIC. Operating Reacture Brench 4 (Pre 790625). 78/12/04. 3pp. 94131:248.
- 7812200220 Forwards non-proprietary version of rept entitled "Cladding Damage Analysis of Subj Facil Core II Burnable Poison Rods." GROCE, R. H. Maine Yankee Atomic Power Co. 78/12/14. 1p. 94145:247.
- --7812200223 "Cladding Damage Analysis of Core II Burnable Poison Rods." & Co-bustion Engineering, Inc. CEN-077(M)-NP. 78/10/30. 3ipp. 94145; 24B.
- G. Inspection reports, IE Bulletins & correspondence
- 7B1016024B Forwards IE BulletinW7B-12: "Atypical Weld Material in Reactor Pressure Vassel Welds" requesting action w/in 60 days-& list of IE Bulletins issued in 1978 ORIER.B. H. Region 1. Philadelphia. Office of the Director. 7B/09/29. 6pp. 94471:308.
- 78(1060192 Forwards IE Circular#78-17. (See AND: 7810230221, Docket #50-133, 78 1013)

 ORIER, B. H. Region 1, Philadelphia, Office of the Director. 78/10/13. jp. 94489; 168.
- 7811120092 Ack receipt of 781003 ltr informing NRC of steps taken to correct violations noted during Inspect30-309/78-16.
 BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/03. 1p. 94114:099.
- --7B11150095 Responds to 780912 NRC ltr re violations noted in Inspec Rept#80-309/78-16.Corrective actions opens have been reminded of importance to maintain accurate complete chronological history of plant open events. MCODY, D. E. Haine Yankee Atomic Power Co. 78/10/03. Rpp. 94114-100
- --7811150100 Forwards IE Inspec Rept#50-309/78-16 on 780821-93 & Notice of Violation.

 BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/12, 28p. 94:14:102.
- --7811150102 Notice of Violation from inspec on 780821-23. * Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/12. Ip. 9414:104.
- --781150105 IE Inapec Rept#50-309/78-16 on 780821-23 during which i item of noncompliance was noted failure to log details of a fuel headling problem.

 LAZARUS. N. J. Region I. Philadelphia. Office of the Director. STAVELY. J. N. KEINIG.R.R. Region I. Philadelphia. Reactor Operations Nuclear Bupport Branch. 78/09/07. 7pp. 94114:105.
- 7811290205 Forwards IE Circular #78-18, "UL Fire Test, "W/encl ANO; 7811150002.

 ORIER, J. M. Region i. Philadelphia, Office of the Director, 78/11/06. 1p. 94237; 254.
- 7812010090 Ack receipt of 781020 ltr informing NRC of steps taken to correct violations noted during inspec#30-309/78-17.

 BRUNNER.E. J. Region 1. Philadelphia, Reactor Gereations Nuclear Support Branch. 78/11/17. 1p. 94416:230.
- --7812010093 Responds to 780929 NRC ltr re violations noted in Inspet ReptMb0-309/78-17 Corrective actions: during future requal proge quiries will be admin & "Tugon H2o Manometer" calibr. Buggests Item C be withdrawn. MCDDY, D. E. Maine Vankee Atomic Power Co. 78/10/20. 4pp. 94416: 231.

- --7812010097 Forwards IE Inspec Rept#50-309/78-17 on 780905-08 k Notice of Violetion.
 BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/29. 2pp. 94416, 235.
- --7812010099 Notice of Violation from inspec on 780905-08.

 Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 78709729, 2pp. 94416:237.
- --7812010103 IE Inspec Rept#50-309/78-17 on 780905-08 during which 3 itams of noncompliance were noted: feilure to correct condition advance to quality, to conduct requal prog quittes & use of manomater w/o documented calibr.

 MARKOMSKI, R.S., RUHLMAN, M., KIBTER, M., Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/09/29, 21pp 94416-239
- 7812150140 Forwards IE Bulletin#78-12A-suppl to IE Bulletin#78-12. W/encl ANO:7811300055. ORIEN-B.H. Region I. Philadelphia, Office of the Director. 78/11/24. pp. 94212:191.
- 7812010214 Forwards MYAP Inspec Rept for 780129-780828 covering 1978 refueling outage, Includes abstract of examinations parformed w/conditions observed & corrective measures taken. OROCS.R.H. Maine Yankes Atomic Power Co. 78/11/27. 1p. 94409:284
- --7812010216 Inservice inservet from 780129-780828; covering 1978 refusiing outage inse w/abstract of examinations performed by Nuclear Engineering Sucs & NOT Engineering Personnel.

 a Maine Yankee Atomic Power Co. 78/11/27. 20pp. 94409:287.
- A. Periodic operating reports & related correspondence
- 7810170150 Forwards Monthly Oper Rept for Sept 1978.

 MODDY, D. E. Haine Yankse Atomic Power Co. 78/10/10, ip. 94236:082.
- --7810170151 Monthly Oper Rept For Bept 1978. BJOREN, R. M. Heine Yankse Atomic Power Co. 78/10/10. 4pp. 94236:083.
- 78:1140112 Forwards Monthly Open Rept for Oct 1978. MODDY, D. E. Maine Yankes Atomic Power Co. 78/11/10. 1p. 94425:149.
- ---7811140166 Monthly Oper Rept for Oct 1978. 8JOOREN.R.M. Maine Yankee Atomic Pawer Ca. 78/11/10. Sep. 74425:150.
- 7812150355 Porwards Monthly Open Rept for Nov 1978.
 MODDY, D. E. Maine Yankes Atomic Power Co. 78/12/11. 1p. 94418:159.
- --7812150357 Monthly Oper Rept for Nov 1978. BUDGREN.R.M. Maine Vanker Atomic Power Co. 78/12/11. App. 74418:183.
- 9. Reportable occurrences, LERs & related correspondence
- 7811030137 Forwards LER#78-023/03L-0. W000, E.C. Heine Yankee Atomic Power Co. 78/09/29. 1p. 02723:308
- --7811030140 LER#78-023/031-0 on 780925: Emergency Diesel Generator D0-18 was found inoper due to introduction of air into fuel lines. ANDERSON, P. L. Maine Yankse Atomic Power Co. 78/09/28. 2pp. 02723: 309.
- 7811030131 Forwards LER078-024/03L-0.
 WDOD: E. C. Maine Yankee Atomic Power Co. 78/10/25. 1p. 02722:2%
- --78:1030:35 LER#78-024/03L-0 on 78:017:after temporary 25% output reduction,RC8 chem samples for isotopic analysis of iodine were not taken between 2 & 6 hours: due to personnel error. ANDERSON,P.L. Maine Yankee Atomic Power Co. 78/10/25. 2pp. 02723:297.
- 7811220213 Forwards LER#78-022/03L-1.
 HOOD E.C. Maine Yenkee Atomic Power Co. 78/11/01. 1p. 03668:355.
- --7811220217 LER#78-022/03L-0 on 780907: rev of original LER. Further investigation revealed low RMST boron concentration was dust to dilution effects of draining a loop at a lower boron concentration to the RMST plus add sus latdown to the RMST. ANDERSON, P. L. Maine Vankee Atomic Power Co. 78/11/01. 289-03668: 396.

- SINESURUE LENGTH-023/03L-0 on 781031: channel D Bafety Injection Actuation Signal Bigma meter drifted to lower setpoint than permitted. Caused by instru drift. ANDERSON P. L. Maine Yankee Atomic Power Co. 78/11/08. 2pp. 03495.276 11220202 LER#78-023/03L-0 on 781031: channel D Bafety Injection
- 200213 Forwards LER#78-027/03L-0 DD. E. C. Maine Yankee Atomic Power Co 78/12/13. 1p. 94162: 289.
- 12200217 LER#78-027/03L-0 on 781007: noted that a steam generator gross activity sample result had not been recorded. Caused by personnel failure to record all data.
- ANDERSON, P. L. Maine Vankee Atomic Power Co. 78/12/13. 1p. 94162.290
- 2200252 Forwards LER#78-028/03L-0. 000.E C Maine Yankee Atomic Power Co 78/12/13. 1p. 94206:259.
- S12200254 LER#78-028/03L-O on 781206: noted that a Procedure Change Rept had not been reviewed by the PDRC w/in 14 days of being generated Caused by personnel oversight.
 ANDERSON.P.L. Haine Yankee Atomic Power Co. 78/12/13. IP.
- 94206.260
- ET 50-311 BALEM NUCLEAR GENERATING STATION, UNIT 2
- application/construction stage documents & correspondence
- 2080039 Forwards proprietary & non-proprietary rept"Dyna nalysis of the Reactor Coolant Bys for Loss of Coolant cidents: Balom Nuc Generating Stations 1 & 11. " affidavit rr Withholding & Appl for Withholding VDERBON.T.M. Hestinghouse Electric Corp. 78/12/01. 2pp. rept"Dunamic
- 912080043 "Dynámic Analysis of the Reactor Codlant Bys for LOCAs." Westinghouse Electric Corp. 78/12/01. 16/0pp.
- 1130203 PBEQ has filed appl for special nuc matl re sub; facil on shalf of PBEQ.Pepco.Delmarve Power & Light & Atlantic City lec Co.PBEQ is authorized to act on behalf of other utils.
 PMEIDER.F.W. Public Bervice Electric & Qas Co. of New Jersey.
 3/09/22 ip. 03534:140.
- pi30134 Responds to 780418 & 780508 NRC ltrs requesting addl info re AR Info will be become part of FBAR in future amend to lic ppi Includes reactor veesel matl properites & maxium inner sil end of liferwelds. ITT.-R.L. Public Service Electric & Gas Co. of New Jersey. 8/10/05. 23pp. 94079:274.
- 0170132 Forwards Amend#44 to Lic Appl for subj facil, consisting of 661 financial info as requested by 780419 NRC ltr. 17TL.R.L. Public Service Electric & Gas Co. of New Jersey. 8/10/11. | p.
- 819170133 Forwards Amend#44 to Lic Appl for subj facil.pertaining to
- general & financial info. MARTIN.T.J. Public Service Electric & Gas Co. of New Jersey. 78710/11. 2pp.
- B10170134 Requests add1 financial info for review of subj facil lic appl by 780707.
 PARRIO D. Light Water Reactore Branch D. 78/04/19. App.
- 810170135 Amend#44 to Lic Appl for subj facil.Contains addl financial
- info. Public Bervice Electric & Ges Co. of New Jersey. 78/10/11. 1764pp.
- 0250002 Notice of meeting on 781018 to discuss residual heat emoval as it relates to cold shutdown at subj facil. RDFERICK: A. Light Water Reactors Branch 3. 78/10/12. 2pp.
- 0240149 Responds to requests for add1 info which will incorporated ocedisy Mespands to requests for each into which which will have the FBAR es amend to appl. Disusses mgt respansible for GA org review.measures taken IAW Reg Guides.LOCA analysis, & hviron qual for equip.

 ITIL.R.L. Public Service Electric & Gas Co. of New Jersey 8/10/20. 82pp.
- Public Bervice Electric & Gas Co. of New Jersey.
- 0290069 Submits responses to remaining NRC requests for said info

- 7811080034 Summary of 781018 meeting re residual heat removal sys & its relation to cold shutdown of subj facil. Applicant will demonstrate by oper test that almospheric stoam dump valves will she will submit procedure documentation by 781106 DROMERICA. A Light Water Reactors Branch 3 78/10/23. 4pp. 94399: 099
- 7811270006 Discusses delly staff notes for 781023 re CEIL's intention to replace recirculation inlet nozzle safe ends failure of Reactor Coolant Pump at PSEG facil & 15,000 gal of water leaking into containment & inventory at Nuc Fuel Svrs.

 Office of the Executive Director for Operations. 78/10/24 ip. 94272: 241
- 78:1080:102 Rasponds to 78:1024-25 request for add1 info on elec pur sys re-reliability criteria, stability analysis espected steady-state voltage conditions intentional disconnection of transmission during sys disturbances & reserve definitions. MITTL-R.L. Public Bervice Electric & Gas Co. of New Jersey. 78/11/06. 49pp. 94397:088.
- 7811080227 Forwards response to NRC requests for add1 info re Guality Assumance Prog. which will be incorporated into facil FSAR. MITTL.R.L. Public Bervice Electric & Gas Co. of New Jersey. 78/11/06. 41pp. 94405:20B.
- 78:1090084 Forwards util response to NRC request for addl info re ECCS Analysis Gustion 3.65 & RHR Sys Gusetion 9.61 Encl info will be incorp into Salem FSAR in amend to appl. MITTLR L. Public Service Electric & Gas Co. of New Jersey 78/11/08. 80pp. 94041:293.
- 7811220261 Notification of 781115 meeting in Bethesda w/PSEO to discuss GA prog for subj facil. DROMERICK.A. Light Water Reactors Branch 3. 78/11/09. 3pp. 94378: 133
- 7811290288 Responds to 781106 request for info concerning licensee reg performance eval for Region I plants by NRC Provides
 - ORIER, B. H. Region 1. Philadelphia, Office of the Director. 78/11/09. 9pp.
- 7811200132 Forwards response to request for add1 info re Quality Assurance Prog. Covers overall approach & scope-PBEO corporate QA Prog. Westinghouse Pur Bys Div QA Prog. United Engr & Constructors QA Prog & Operational QA Prog. HITTLERL. Public Service Electric & Gas Co. of New Jersey. 78/11/16. 90pp. 94420:133.
- 7811290125 Forwards Rev#1"Draft Radiological Effluent Tech 8psc for PMR's" (NUREG-0472) & "Preparation of Radiological Effluent Tech 8psc for Nuc Fur Plants" (NUREG-0133), W/encl ANO: 7811270173 & 7811270180.

 VABSALLO, D. B. Assistant Director for Light Water Reactors, 78/11/16. 5pp. 94013:025.
- 7811290354 Summary of meeting on 781115 on quality assurance prog for sub; fec11. Applicant will change QA prog IAW NRC recommendations. DROMERICK, A. W. Light Water Reactors Branch 3. 78/11/17. 3pp. 94194: 28B
- 7811240141 Forwards responses to NRC questions. Will be incorp in Final Safety Analysis Rept as an emend. MITTL.R.L. Public Bervice Electric & Gas Co. of New Jersey. 78/11/20. 1p. 94457:007.
- --7811240142 Answers NRC questions 5.62:5.63:5.83:5.83:5.84 & 5.85 re analyses of main steam lines break within containment of unisolated steam in main steam line & turbine plant.

 * Public Service Electric & Gas Co. of New Jersey. 78/11/20.

 **Adaps. 94457:008
- 7811240225 Forwards Tables 3a, 3b & 3c in support of response to 780418 NRC questions 5.62 & 5.82 assoc w/subj facil. Requests that substitted into be withheld form pub disclosure pursuant to 10CFR2.790.

 MITTL.R.L. Public Service Electric & Qas Co. of New Jersey. 78/11/20. 2pp. 94458:176.
- 7812070156 Notice of seminar on 781208 on new Model Radiological Effluent Tach Space for nuc pur plants Requests advance submission of seminar specific questions. W/encl Seminar Info Sheet Proposed Agenda & maps.

 ORIER, E. H. Region I. Philadelphia, Office of the Director.

- 7012130099 Forwards request for add1 info for review of facil FBAR. FARR.O D. Light Water Reactors Branch J. 78/11/30. 13pp. 94278:079.
- 7812130367 Requests add1 info re facil initial test prog to complete review of FBAR. PARR-0.D. Light Water Reactors Branch 3. 78/12/05. 4pp. 94307:107
- 7812130370 Requests comments by 781210 on Tech Spece. Areas incl:pwr distrib limit & curves reactor trip & ESF setpoints. Post Accident Instru. Overpressure Protec Sys. ECCS pressures & flows: Elec Equip test & Protec Device tables.
 PARR. O. D. Light Water Reactors Branch 3. 78/12/06. ip. 94292:123.
- 781R180260 Forwards request for add1 info on instru & control for review of FBAR.
 PARR.O. Light Water Reactors Branch 3. 78/12/06. Spp. 94365:322.
- 7812190175 Notice of 781215 meeting to discuss open items me subj facil.
 DROMERICK, A. H. Light Hater Reactors Branch 3. 78/12/07. 2pp. 94340:053.
- 78:12200072 Forwards responses to NRC requests for add1 info 01.48.5.96.
 5.110 & 14.20 for FBAR review.Responses cover seismic categories.safety related plant design & sngr safety features.
 MITTL.R.L. Public Service Electric & Qas Co. of Naw Jersey.
 78/12/18. 10pp. 94413:246.
- 7812220143 Forwards response to request for add1 info which will be incorp into FDAR in an amend to appl Buby incl:floor response spectra. Class i slec equip & instrumentation, & seismic qual for sefety-related equip.

 MITTL.R.L. Public Bervice Electric & Gas Co. of New Jersey.
 78/18/21. 23pp. 03506.001.
- F. Security, medical, emergency & fire protection plans
- 7810280083 Forwards Emergency Plan & amends to Pinel Bafety Analysis Rept in response NRC request for addl info. The info will be incorporated in subj facil FBAR in an amend to appl. MITTL. R.L. Public Barvice Electric & Ges Co. of New Jersey. 78/10/24. 106pp. 94370:160.
- 7811300022 Forwards findings of staff review of subj facil 780803 security plan. Encl#1 lists areas NRC considers unresolved, wheld from pub disclosure IAH 10CFR2. 790. Encl#2 is Review Quideling re-plant protec from sabotage by insiders. 8CHMENCER.A. Operating Reactors Branch 1 (Pra 790625). 78/11/16. 4pp. 94070:337.
- 7812040224 Requests add1 info re subj facil Security Plan Forwards list of Unresolved issues (withheld from disclosure) to Review Quideline "Protet of Nuc Pur Plants Against Industrial Sabotege by the Insider."

 BCHMENCER.A Operating Reactors Branch 1 (Pre 790625). 78/11/16.
- --7812040225 Review Quideline#23: "Protec of Nuc Per Plants Against Industrial Sabotage by the Insider." Refers to security measures that place controls on access to vital areas. CLARK.R.A. Reactor Bafaguards Licensing Branch (Pre 791030). 78/11/06. 3pp.
- 7812210206 Remponds to 781116 request for info on security plan. Comments incl detailed attdy to determine Type I & II vital areas is unnecessary & requests response to issues raised in RMC itr re "insider" control procedures.
 LIBRIZZI,F. P. Public Barvice Electric & Gas Co. of New Jersey, 78/12/14. 2pp. 94279:096.
- --7812210210 Appraises Reactor safaguards Licensing Branch Review Guideline#23. "Protec of Nuc Per Planta Against Industrial Sebotage by the Insider" re compartmentalization, two-men rules, personnel reliability.

 MCEMEN, J. R. KMC, Inc. 78/11/28. 5pp. 94279:098.
- 7812290027 Forwards request for add1 info refacil Fire Protec Prog for FBAR review w/encl questionneire. PARR.O.D. Light Water Reactors Branch 3. 78/12/15. 20pp. 74208: 020.

J. Insurance & indemnity information

- 7811070159 Forwards 8 certified copies of captioned endorsement for rev of 1978 premium. Advanced premiums & standard premium endorsement encl.
 - HARTLEY T. F. Nuclear Insurance Consultants. 78/11/02, 288. 94044: 130.
- 7812040223 Porwards insurance Endorsement #24 to MAELU Policy #MF90 for rev of 1978 premium.
 HARTLEY.T.F. Nuclear Insurance Consultants. 78/11/28. 2pp.
- K. Utility Final Safety Analysis Report (FBAR) & amends
- 7810140040 Forwards request for add1 info for ray of subj facil FSAR. PARR.O.D. Light Water Reactors Branch 3. 78/10/06. App. 94389: 203.
- 7811030119 Forwards responses to NRC request for add1 info re:component coolent water supply to resctor coolent pumps, rev response re containment negative pressure, & rev FBAR pages re Radiet Moniboring Bys & mod to containment struc integrity test. MITTL:R.L. Public Bervice Electric & Gas Co. of New Jersey, 78/11/01. 1p. 08783:140.
- --7811030120 Questions & Answers for FBAR Amend 43 re:containment negative pressure & component cooling sys. * Public Bervice Electric & Qas Co. of New Jersey. 78/11/01. R2pp. 02723:141.
- ~-7811030124 Rev pages for Amend#43 to FBAR for subjfecil re:Radiat Monitoring Bys & Containment struc integrity test. # Public Bervice Electric & Gas Co. of New Jersey. 78/11/01. 26pp.
- P. Operating license stage documents & correspondence
- 7810230098 Summary of 781004 meeting re the environ qual of safety related instrumentation & elec equip.

 BROMERICK, A.W. Light Water Reactors Branch 3. 78/10/12. 3pp.
- 7812280045 Emphasizes importance of submitting accurate & complete info to NRC by licensee & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB. J. Q. Office of Inspection & Enforcement, Office of the Director. 78/18/06. 2pp. 94132:220.
- G. Inspection reports, IE Bulletine & correspondence
- 7810280048 Forwards IE Inspec Rept#80-311/78-29 on 780822-24 during which no items of noncompliance were noted. BRUNNER, E. J. Region I, Philadelphia, Reactor Operations Nuclear Bupgort Branch. 78/79/11. 2pp.
- --TBICGS0052 IE Inspec Rept#50-311/78-29 on 780B22-24 during which me items of noncompliance were noted Major areas inspected included: Containment leak rate testing, pips support a restraint sus & presvc testing.

 CAPHTON, D. L., HIGOINS, J. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 78/09/11, 7pp.
- 7810270284 Forwards IE Inspec Rept#50-311/78-28 on 780821-24 during which no items of noncompilance were noted. CARLSON R. T. Region 1, Philadelphia: Reactor Construction & Engineering Support Branch. 78/09/12. 2pp. 94025:331.
- --7810270288 IE Inspec Rept#00-311/78-28, on 780821-24 during which no items of noncompliance were noted Major areas inspected included: elec cable installation, termination & documentation diesel generator installation & records.

 FINKEL.A.E., EBNETER.B.D. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 78/09/07. App. 94026: 333.
- 7811080R90 Forwards IE Inspec Rept#80-311/78-30 on 780828-31 during which no items of noncompilance were noted.

 SRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/19. 2pp. 94406: 203.

- --7811080292 IE Inspec Rept#50-311/78-30 on 780828-31 during which no items of noncompliance were noted. Major areas inspec incl: overall preoper test prog. & preparations for Integrated Hot Functional Test Procedure.

 NCHOLAS.H. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/15. App. 94406:205.
- 7811100099 Forwards IE Inspec Rept#80-311/78-32 on 780913-18 during which no items of noncompliance were noted. BRUNNER,E.J. Region 1, Philadelphia, Resctor Operations Nuclear Bupport Branch. 78/09/26. 2pp. 94179:291.
- --7811100102 IE Imspec Rept#50-311/78-32 on 780913-15 during which no items of noncompliance were noted. Major areas inspected included: preper test prop, interpated hot functional test prog it followup of previous open items.

 NICHOLABIM. Region 1. Philadelphie, Resctor Operations Nuclear Support Branch. 78/09/25. 7pp. 94179:293.
- 7811100157 Forwards 1E Inspec Rept#50-311/78-34 on 780920-22 during which ho items of noncompliance were noted. BRUNNER, J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/02. 2pp. 94047:192.
- ---7811100164 IE Inspec Rept#50-311/78-34 on 780920-22 during which no items of noncompliance were noted. Major areas inspec incl; integrated hat functional test prog status, preoper test prog status, preoper test procedures for review plant tour. NICMCAB.H. Region I. Philadelphia. Office of the Director. 78/09/29. 1p. 94047:194.
- 7811140037 Forwards IE Inspec Rept#50-311/78-36 on 780927-28 during which no items of noncompliance were noted. #RURNER.E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 94420:305.
- 78:11:00:142 Forwards IE Inspec Rept#50-31:1/78-33 on 780920-92 during which no items of noncompliance were noted. BRUNERE, J. Region 1. Philadelphia, Reactor Operations Nuclear Support Brench, 78/10/05. Spp. 94047:148.
- --78ii100148 IE Inspec Rept#50-3ii/78-33 on 780920-22 during which no items of noncompliance were noted. Major areas inspected included matl storage, test & measurement equip control, conduct of GA audits & surveillances.

 BECKMAN.D., NAPUDA.Q., MARKONBKI.R. Region 1, Philadelphia, Office of the Director, 78/10/05. 10pp. 94047:150.
- 7811170295 Forwards IE Inspec Rept#80-311/78-31 on 780911-15 during which no items of noncompliance were noted. CARLEGORE. T. Region 1. Philadelphia. Reactor Construction & Engineering Bupport Branch. 78/10/06. Epp. 08766: R15.
- --7811170299 IE Inspec Rept#50-311/78-31 on 780911-15 during which no items of noncompliance were noted. Major ereas inspected included: structural integrity, piping, & cable installation & quality verification records.

 TOTH:A.D., DURR, J.P., PAOLINA, R.J. Region 1. Philadelphia, Reactor Comstruction & Engineering Support Branch. 78/10/06. 14pp.
- 7811300295 Forwards IE Inspec Repts#50-272/78-23,50-311/78-27 on 760612-0916 during which no items of noncompliance were noted.

 BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 76/10/10. 2pp. 94075;149.
- --7811300298 IE Inspec Repts450-272/78-23,480-311/78-27 on 780812-0916 during which no items of noncompliance were noted Major areas inspected incl:routine inspec of oper & construc. NGRHOLM.L.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/10. 13pp. 94075:151.
- 7812040383 Forwards IE Inspec Rept#80-311/78-38 on 781010-12 during which no items of noncompliance were noted. BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/25. Spp. 94382:279.
- --781206035 IE Inspec Rept#50-311/78-38 on 781010-12 during which no items of noncompliance were noted Major areas inspected inclipreoper test prog implementation & integrated hot functional test prog status.
 NICHOLAS, H. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/85. 7pp. 74982:281.

- 7811130115 Ack receipt of 780928 ltr in response to 780906 & 780612 NRC ltr informing NRC of steps taken to correct deviations noted in Inspec Rept#850-272/78-18 & 30-311/78-13. GRIER, B.H. Region 1, Philadelphia, Office of the Director, 78/10/30. ip. 94076:090
- --7811130119 Responds to 780906 NRC ltr re deviation noted in Inspec Re #50-272/78-18. Util claims alleged violation was not & did not represent noncompliance w/10CFR50. 59 since subteired procedures are controlled by GA Prog to comply u/FBAR BCHNEIDER, W.F. Public Service Electric & Gas Co. of New Jarsey. 78/09/29. 2pp. 94076:091.
- 78:2010345 Forwards licensee performance evaluation for Region 1. No operating reactor in Region 1 considered to have either abnormal or unusual safety concern.
 GRIER, 8. H. Region 1, Philadelphia, Office of the Director 78/11/01. 4pp. 00002:259.
- 7811140271 Ack receipt of 781018 itr informing NRC of steps taken to correct violations noted during inspecu80-311/78-26 CARLBON R. T. Region 1. Philadelphia. Reactor Construction & Engineering Support Dranch. 78/11/02.
- --7B11140274 Responds to 7B0912 NRC ltr re violation noted in linepec Rept#80-311778-26.Corrective actions: pressure testing of welds review of mechanical arrangement drawings & rev of procedures. MARTIN.T. J. Public Service Electric & Gas Co. of New Jersey. 7B/10/19. 3pp. 94400:192.
- --7811140277 Forwards IE Inspec Rept#80-311/78-26 on 780814-16 & Notic of Violation.
 CARLBON, R. T. Region 1. Philadelphia. Reactor Construction & Engineering Support Branch. 78/09/12. 2pp. 94400:195.
- --7811140278 Notice of Violation from inspec on 780814-18 CARLBON, R. T. Region is Philadelphias Office of the Director. 78/09/12. 1p. 94400:197.
- --7011140280 IE Inspec Rept#50-311/78-26 on 780814-18 during which i i of noncompliance was noted: failure to provide Q: 1 length ratio on socket weld.

 TOTH.A.D. Region i, Philadelphia, Office of the Director.

 FASANCIA.N., MCSREARTY.R.A. Region i, Philadelphia, Reactor Construction & Engineering Bupport Branch. 70/09/12. 13pp. 74400: 198.
- 78:1290222 Forwards IE Circular 878-18, "UL Fire Test."H/encl AND: 781:130002.
 ORIER, 8. H. Region I, Philadelphia, Dffice of the Director. 78/11/06. in. 94237:304.
- 7819270417 Forwards IE Inspec Repts#80-311/78-35 & 50-979/78-35 on 780917-1014 during which no items of noncompliance were noted.

 BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 78/11/13, App. 94319:308.
- --7812270423 IE Inspec Repts#50-278/78-25 & 50-311/78-35 on 780917-101 during which no items of noncompliance were noted Major areas inspected incl:test prog controls, ing & record review. Emergency Drill, preoper plent personnel training. NORRHOLM, L. J., KEIMIO, R. R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/06. 15pp. 94312:310.
- 7819280007 Forwards IE Inspec Rept#80-278/78-25 t #50-311/78-35 on 780917-1014 during which no items of noncompliance were noted.

 8RUNNER. E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/13. 2pp. 94130:149.
- --7812280012 IE Inspec Repts#80-279/78-25 & #50-311/78-35 on 780917-10 during which no items of noncompliance were noted. Major areas inspected incl: tours of facil, log & record reviews, observation of emergency drill & review of recent LERS.
 NCRRHOLM, L.J., KEIMIG.R.R. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/06. 15pp. 94130:151.
- 7819490049 Forwards IE Inspec Rept#50-311/78-37 on 781025-37 during which no Items of noncompliance were noted.

 BRUNNER, 5. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Brench. 78/11/13. 2pp. 94189:349.
- --7812270044 IE Inspec Rept#50-311/78-37 on 781025-27 during which no items of noncompliance were noted Major areas inspected incl:overall preoper test prog.followup on unresolved items & plant tour.
 NICHOLAS.H., CAPHTON.D.L. Region 1, Philadelphia. Reactor Operations Nuclear Support Branch. 78/11/13. Opp. 94189; 351.

- 7812150042 Forwards 1E Builetin#78-12A.suppl to IE Builetin 78-12 W/amcl ANO 7811300055. GRIER.8 H Region i. Philadelphia. Office of the Director 78/11/24. 1p 94210: 225.
- 7812200210 Ack receipt of 781109 ltr informing NRC of steps taken to correct violations noted during Inspect*00-311/78-26 CARLBON.R.T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 78/12/08. 1p. 94373:190.
- --7812280215 Provides add1 info re violetions noted in Inspec Rept#50-311/79-26 Corrective actions:75 welds properly reworked & accepted & 3 welds will be properly reworked prior to Core Load. MARTIN,T J. Public Service Electric & Gas Co. of New Jersey. 78/11/09 2pp. 94373:191
- R. Periodic operating reports & related correspondence
- 7810180120 Forwards Hastewater Treatment Rept for Sept 1978 for sewage treatment plant at subj facil.
 MIDURA.H.J. Public Service Electric & Qas Co. of New Jersey.
 78/10/10, 2pp. 94195: 296.
- 7810180144 Forwards Discharging Monitoring Repts for Subj facil for Bapt 1978. MIDURAHLJ. Public Bervice Electric & Gas Co. of New Jersey. 78/10/10. 19pp. 94316:328
- 7811210323 Forwards Hastewater Treatment Rept for Oct 1978. MIDURAH, J. Public Bervice Electric & Ges Co. of New Jersey. 70/11/10. 2pp. 94485:267.
- 78:12:10343 Forwards Discharge Monitoring Repts for Oct 1978. MIDURA.H. J. Public Bervice Electric & Oas Co. of New Jersey. 78/11/17. 10pp. 94484:342.
- DOCKET 90-312 RANCHO BECO NUCLEAR GENERATING STATION

 F. Becurity, medical, emergency & fire protection plans
- 7810230097 Bubmits design details for two items identified by NRC as requiring approval & one item where util proposes mod differing from one described in fire protection safety evaluation in response to request for addl info.

 MATTIMOC. J. J. Bacramento Municipal Utility District. 78/10/17.

 Top. 94052:212
- 7812010344 Forwards Amend 24 to License DPR-54, safety evaluation, & notice of issuance & availability.
 REID, R.H. Operating Reactors Branch 4 (Pre 790625). 78/11/14. 2pp. 94418:227
- --7012010347 Amend 24 to License DPR-54, revising administrative controls portion of Tech Space in response to 780221 application. Reflects rovised facility organization structure & clarified review requirements for security & emergency plans. REID.R. M. Operating Reactors Branch 4 (Pre 790623). 78/11/14. 19pp. 94418:229.
- --7812010350 Befety evaluation supporting Amend 24 to License DPR-54 concluding that proposed changes in plant arg are admin in nature 8 preserve intent of Tech Specs. Mode to Security & Emergency Plans are also acceptable.

 ** Office of Nuclear Reactor Regulation, Director. 78/11/14. 4pp. 94418: 240.
- --7812010362 Notice of issuance & availability of Amend 24 to License DRR-54, REID:R.W. Operating Reactors Branch 4 (Pre 790625), 78/11/14, Rpp. 94416:252.
- 7812050146 Application for Amend 61 to License DPR-54-reflecting changes to Table 3.1 of fire protection safety evaluation. MATTIMOS. J. J. Sacramento Municipal Utility District. 78/19/01. Dpp. 94298:359.
- 7012180159 Proposes elternate mod of Paragraphs 3.1.34(2) & 5.17.6(2) of fire protection BER attached to Amend 19 of License DPR-84. Mould relocate transformer 250 ft seet of current location.

 MATTIMOE, J. J. Sacramento Municipal Utility District. 78/12/12. 1p. 94366.020.

- 7812270116 Approves supplemental info re Section 3 of fire protection GER.including installation of thermal insulation on Channel A.C.& D conduits, mod of lube oil pump control circuits associated w/HPIS & procedures for dissel generators. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/12/14 Spp. 94161:066.
- 7811210261 Forwards Amend#4 to Mod Amend security plan for subj facil.
 Requests withholding from pub disclosure (ref 10CFR2 790).
 M/out encl.
 MATTIMOS.J.J. Secremento Municipal Utility District. 78/11/17. 1p.
 94888-194

G. Adjudicatory correspondence

7812140142 Forwards fee for approval of elimination of add1 insplot ITT Grinnel units per 781130 ltr. Fee peid under protest per lawsuit filed in U.B. Court of Appeal for 5th Circuit. MATTINDE, J. J. Bacramento Municipal Utility District. 78/12/06. 4pp. 94478: 346.

P. Operating license stage documents & correspondence

- 7811020084 Forwards Amend#23 to Facil Oper Lic#DPR-54.changing Tech 8pec for plant surveillance times. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/02 2pp 94331:027.
- --7811020087 Amend#23 to Facil Open Lic#DPR~54 changing Tech Spec for plant surveillance times. REID.R.W. Openating Reactors Branch 4 (Pre 790625). 78/10/03. 7pp. 94051:029
- --7811020093 Bafety Evaluation Bupporting Amend#23 to Facil of Lic #DPR-34. Concludes that no increase or hezard will ensue. # Operating Reactors Branch & Pre 790625). 78/10/03. 3pp. 94351:036
- --7811020098 Notice of issuance & availability of Amend 23 to License DPR-04.
 REID:R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/03.
 2pp. 940351:039.
- 78J0120027 Presents into re-proposed mod to assure high pressure injection flow to reactor core following a small break as requested by NRC 780976 ltr.
 MATTHMOS. J. J. Becramento Hunicipal Utility District. 78/10/09. 2pp. 94470:346
- 7810230160 Forwards check for 612,300 in payment for application for Amend 60 to License DPR-54. MATTIMOE, J. J. Sacramento Municipal Utility District. 78/10/13. 2pp. 94164:288.
- 7811070201 Notifies that util cannot obtain NRC approval perfore calculations & purchase new equipment for installation of second level of voltage protection by 1976 refueling outage. Proposes mod completion by end of 1979-80 refueling outage. HATIMOR. J. J. Bacramento Municipal Utility District. 78/10/31. ip. 94039:083.
- 7811200404 Notifies that mods proposed in 780927 ltr.enhancing capability to detect reactor conlant leakage in reactor bidg through radiation monitor use.acceptable in concept Mode to be functionally acceptable.upon approval of equipment. REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/11/04. 2pp. 94419:316.
- 7811R00346 Responds to 780913 request to emend Tech Specs to permit operation w/fuel loading planned for Cycle 3. Forwards request for additife. Reply required by 781117.
 REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/07. 999. 94420:108.
- 7811170117 Responds to NRC 780921 rejection of design criteria for installation of ionization detectors in areas containing both combustibles & equipment/cables required for safe shutdown Requests approval of schedule to make related mods. MATTIMDE. J. Bacramento Municipal Utility District. 78/11/14. Spp. 94047:146.
- 78:12:103:19 Forwards add1 info supporting Amend 60 to License DPR-54 in response to 78:107 request Proposed amend changes Tech Specs to permit operation w/fuel loading planned in Cycle 3. MATTHMS, J. J. Sacramento Municipal Utility District. 78/11/15. 10pp. 94468:038.

209 Insiste subj facil ECCS is acceptable & in conformance w/ 10.46. but in response to staff request util applies for ion to 10CFR30.46 & for lie to open at 2772 MHz for on of Cycle 3.Hill provide details of mod.

10E. J. J Secremento Municipal Utility District. 78/11/22. 94013: 278

- 02 Discusses possible dangers of LOCA in containment purging pormal plant oper. Requests either commitment to limit mg or justification for continuing.

 1. Operating Reactors Branch 4 (Pre 790625). 78/11/29. App. 2:062.
- 116 Discusses failures of Bergen-Paterson snubbers during 1978 -in test program. H/54 tested, 10 failed in same mode: pad spring damaging seat surfaces. Engineer lesizes that failures due to abusive handling. 105.J.J. Bacramento Municipal Utility District. 78/11/30.
- 94333: 284.
- 94 Forwards add1 info re mods eliminating requirement for or action subsequent to small break per 781122 request seption from 10CFR30.46, supplementing 781122 info tel.
- 10E, J. J. Sacramento Municipal Utility District. 78/12/04. 94109:001.
- 107 Notifies that fee for review of util 781130 ltr to NRC 1781206 to ensure that NRC concurrence not to inspirit-Orientel-menufactured snubbers will be issued by 1. Request for concurrence determined to by Category II. 105:1. J. Bacramento Municipal Utility District. 78/18/06. 1p. 1922. 1:337
- 33 Emphasizes importance of submitting accurate & complete info 133 Emphasizes importance or summitting ecturate a compa-ity licenses & applicants Info submitted must be initiated by data & calculations Licenses must notify I any inaccuracies or enforcement action will result. J.O. Office of Inspection & Enforcement, Office of the for. 78/12/06. Ppp. 94311:310.
- 391 Responde to 781130 ltr re hydraulic enubber surveillance M. Cause of Bergen-Paterson snubber failure due to dling during installation. L.W. Dograting Reactors Br
- Operating Reactors Branch 4 (Pre 790525). 78/12/08. App. : 09B.
- .39 Proposes to store seal plate in current position for one well cycle, allowing evaluation of design permitting less of seal plate rigidly above present location.
 1889 probability of rupture of primary cooling loop.
 1881 J. Bacramento Municipal Utility District. 78/12/14. 1p.
 1924 : 335
- ction reports, 1E Bulletins & correspondence
- Pi Forwards IE Circular#78-17. (See ANO: 7810230221, Docket 781013)
- EN.A.H. Region 5. San Francisco, Office of the Director. 43. lp. 94170:160.

- radioactive math properly labeled & radiat level of rooms posted. MATTIMOE, J. J. Bacramento Municipal Utility District. 78/11/07. 2pp. 94260.358
- --7811270097 Ack receipt of 781107 itr informing NRC of steps taken to correct deviations noted in Inspec Rept#50-312/78-15, BOOK-H.E. Region 5, San Francisco, Fuel Facility & Materials Safety Branch. 78/11/17, ip. 94260:360.
- 7811270056 Forwards Inspet Rept #50-312/78-17 on 781011. Requests notification if any matl is proprietary.

 BPENCER.Q B Ragion 5. Ban Francisco. Reactor Construction & Engineering Support Branch. 78/10/24. 2pp. 94246.273.
- --78:1270058 IE Inspec Rept #50-912/78-17 on 78:011: insvc inspec meeting at which licensee discussed governing codes & specs. perticipating organizations nature & extent of prog for ineve inspec during fall 1978 fuel outage. VCRDERBRUGOEN, NARBUT,P.P., HAYNES,R.C. Region 5, San Francisco, Office of the Director. 78/10/24. 3pp. 94246:275.
- 7811210244 Forwards Summary of IE Inspec Rept#50-312/78-#5 on 781016-19 Inspec Rept & Notice of Violation withheld per 10CFR2, 790. NORDERHAUG, L. R. Region D. Ban Francisco, Bafeguard's Branch. 78/11/03. 2pp. 94408:010.
- 78:1150012 Forwards IE Circular 78-18.

 ENGELKEN,R.H. Region 5, San Francisco, Office of the Director.
 78/11/06. 1p. 9411:178.
- 7812140037 Forwards IE Inspec Rept#50-312/78-18 on 761023-25 during match no time of noncompliance were noted.

 CREMBLY. L. Region 3. Ben Francisco Reactor Operations Nuclear Support Branch. 78/11/14. 2pp. 94127:215.
- --7812140039 1E Inapsc Rept 80-312/78-18 on 781023-25 during which no items of noncompliance were noted. Major areas inspected incl:oper surveillance cleanliness, refueling preparation & IE Bullatin/Circular followup. JOHNSON, A.D. Region 5, San Francisco, Office of the Director.

 WOEBSHER, J.D., FAULKENBERRY, B. Region 5, San Francisco, Reactor
 Operations Nuclear Support Branch. 78/11/14. 5pp. 94126:308.
- 7811300092 Forwards IE Bulletin #78-12A, suppl to IE Bulletin 78-12. W/encl AND: 7811300055. RNGELMENR.H. Region 5, San Francisco, Défice of the Director. 78/11/24. lp. 94073:054.
- 7812040202 Ack receipt of 781124 ltr informing NRC of steps taken to correct violations noted during inspec.
 NORDERHAUG,L.R. Region 5. Ban Francisco: Safequards Branch.
 78/12/01. 1p. 94382:147.
- 7812290094 Forwards IE Bullstin 78-14. ENGELKEN, R. H. Region 8, Ben Francisco, Office of the Director. 78/12/19. 1p. 03669;361.
- R. Periodic operating reports & related correspondence
- 7810110126 Monthly Oper Rept for Bept 1978. COLDMBO, R. W. Sacramento Municipal Utility District. 78/10/03. &pp. 94067: 352

1

- RODRIGUEZ, R. J. Bacramento Municipal Utility District. 78/11/07. 1p. 94133:165
- --7811160078 Monthly Oper Rept for Oct 1978. CQ.OHBO.R.W. Secremento Municipal Utility District. 78/10/31. 7pp 94133.166
- 7812200194 Forwards Honthly Open Rept for Nov 1978 RODR(GUE): R J Sacramento Hunicipal Utility District. 78/12/12. 1p. 94162-242
- --7812200197 conthly Oper Rept for Nov 1978.
 COLOMBO, R. W. Sacramento Municipal Utility District. 78/11/30.
 Gpp 94162:243.
- 8. Reportable occurrences, LERs & related correspondence
- 7810100050 Forwards LER 78-006/03L-0.

 MATTIMEE, J. J. Batramento Hunicipal Utility District. 78/07/05.

 2pp. 94032:173
- --7810100056 LER 70-006/03L-0 on 780611 during normal operation, increased leakage noticed, between 1.1-1.7 gallone/min Caused by leaking pressure safety valves & block valve on electromatic relief valve Valves replaced or reworked.

 GLOMBO.R W. Sacremento Municipal Utility District. 78/07/05.

 1p. 94032:175
- 7810100073 Forwards LERH78-003/03L~1.
 MATTIMDE, J. J. Bacramento Municipal Utility District. 78/07/17.
 2pp. 94033:075.
- --7810100077 LERM78-003/03L-1 on 780710: Maintenance on safety sys hydraulic enubber previously found to have low fluid accumulator level revealed 2 deteriorated o-rings made w polyurathene seels instead of ethylene-propulene seels. CCLOMBO. R W Bacramento Municipal Utility District. 78/07/10. 1p. 94033:077.
- 7810100016 Forwards LER 78-004/017.
 MATTIMOE.J. J. Bacramento Municipal Utility District. 78/07/20.
 1p. 94033:016.
- ~-7810100021 LER 78-004/01T-1: on 780414, small break analysis determined to be at RC pump discharge. Analysis identified & evaluated solutions. Facility has incorporated procedural changes & initiated design changes.

 COLOMBO: R. W. Bacramento Municipal Utility District. 78/07/20. ip. 9403: 017.
- 7810100061 Forwards LER#78-008/02T-0.
 MATTINDE, J. J. Bacramento Municipal Utility District. 78/08/15.
 2pp. 94033:081
- --7810100069 LER 78-00B/O2T-O: on 780B04, analysis showed atypicel wild filler wine w/high silicon & low nickel contents in archive weldments. Wire mixed by supplier w/shipment of Mn-Mo-Ni filler wire. Caused by inedequate GA. CQLONBO. R.W. Bacramento Municipal Utility District. 78/08/15. 1p. 74033:090.
- 7810250184 Reportable Occurence#78-10: Tech Spec 3, 14, 5, 2 on 780914 req inoperable fire hose stations to have add1 operable hose win I hour not satisfied win time req.
 AUBRG_R.P. Bacramenta Municipal Utility District. 78/09/22. Ip. 94392: 249
- --7811030162 LERW78-010/017-0 on 780914: During normal oper it was found that Fire Hydrantt3 hose cabinet had not been relocated W/hydrant. Upon discovery of discrepancy hose cabinet was relocated.

 CCLDMBD. R.W. Bacramento Municipal Utility District. 78/09/26. ip. 02723:352.
- 7811030153 Forwards LER878-011/017-0.

 MATTIME: J. J. Bacramento Municipal Utility District. 78/09/27. ip.
 05037:295.

- 7810130131 Forwards LER 78-013/03L-0.
 MATTIMOB.J. J. Bacramento Municipal Utility District. 78/10/09
 2pp. 94003:032
- --7810130135 LER 78-013/00L-0: on 780925, HPI Loop A flow transmitter FT-23807 found inoperable during surveillance procedure 200.14 Caused by broken bellows in flow transmitter, Failed bellows replaced.

 COLOMBO, R.W. Bacramento Municipal Utility District. 78/10/05, 19. 94003: 004.
- 78:0130178 Forwards LER 78-009/03L-0.

 MATTIMOE.J. J. Bacramento Municipal Utility District. 78/10/05.

 ZPP. 94415:102
- 7810170199 Forwards LERW7B-012/03L-0.
 MATTIMOE. J. J. Bacramento Municipal Utility District. 78/10/05.
 2pp. 94053:024
- --781017020; LER 78-012/03L-0: on 780927, header failed to discharge during routine testing of CO2 sys. Caused by defective micro switch on a solenoid which operates a pliot valve integral w/controller of main isolation valve, FV 97809.
 CCLOMBO, R. W. Bacramento Municipal Utility District. 78/10/05, 1p. 94236:336.
- 7810200104 Forwards LERM78-003/04T-0.
 MATTIMOE.J.J. Bacramento Municipal Utility District. 78/10/16.
 2pp. 74195: 224
- --7810200106 LER 78-003/04T-0: on 780913 during steady state operation dispolved oxygen concentration downstream of confluence of Hadselville & Clay Creek was less than minimum of Emg/liter typical of stagnant water.i.ocation is beyond util property. CCLOHBO. R. W. Bacramento Municipal Utility District. 78/10/16. ip 94195:226.
- 7810330277 Forwards LER 78-014/01T-0. HATTIMOE, J.J. Bacramento Municipal Utility District. 78/10/17, 2pp. 94166:358.
- ---7810230283 LER 78-014/017-0 on 781004: during oper w/8 diesel generator out of syciuse of A generator temporarily lost. Reactor Bhutdown commenced until diesel generator oper Bhutdown stopped apray of fuel oil Packing gland tightened. CCLOMBD, R. W. Sacramento Municipal Utility District. 78/10/17. 1p 94166.176.
- 7810310087 RQ-18-16. on 781024.while B generator was out of svc for maint.voltage regulator circuit for A generator malfunction occurred b shut down A generator. Cold shutdown of reactor commenced. A generator returned to svc.Full rept to follow. OURE.R.P. Secramento Hunicipal Utility District. 78/10/25. ip. 74091:165.
- 7911140230 Forwards LER 78-014/017-0.
 MATTIME: J. J. Bacramento Municipal Utility District. 78/11/06
 ZPP. 94400:087
- --7811140236 LER 78-016/01T-0: on 781024, operability of A dissal generator lost due to failure of primary fuses on the voltage regulator's control power circuit. Fuses replaced, A generator tested then returned to svc. GCLOMBO, R.W. Bacremento Municipal Utility District. 78/11/06. 1p. 94400:009.
- 7812120147 RO: on 781023, welder entered filter room to remove three inlet & outlet lines w/osyacstylems cutting torch. During process welder overseppased when head, arms & upper torso extended beyond protective shield to obtain better position. MATTIMOR, J. J. Sacramento Hunicipal Utility District. 78/11/13. Bpp. 74276: 221.
- 7812110170 Forurds LER 78-015/01T-0. HATTINGE,J. J. Bacramento Municipal Utility District. 78/12/04. 2pp. 94337:091
- --7812110173 LER 78-015/017-0:on 781120, failure of 9 Bergen-Patterson enubbers. Seven of 9 Failures caused by abusive handling during reinstallation following 1977 teating. Other two failures isolated cases. Failed units repaired. CLOMBO. R.W. Sacramento Municipal Utility District. 78/12/04. 2pp. 94337:093.

- DOCKET 50-313 ARKANBAB NUCLEAR DNE. UNIT 1 F. Security, medical, emergency & fire protection plans
- 7810700099 Discusses facility emergency plan Amends 54,55 % 56 subsitted on 780426 & 0630. Annual emergency drills, communications links & fire brigade drills amended Changes acceptable & mest NRC 771205 position REID.R.H. Operating Reactors Branch 4 (Pre 790625) 78/10/02 2pp. 94367:351.
- 7811170065 Forwards copies#1, 2, 3, 4 & 8 of 7B1030 amend to proposed Industrial Security Plan dtd 7B0510, which responds to 7B042B NRC ltr. Requests withholding of document from public disclosure pursuant to 2, 790 will 94046 322.
- 7811090170 Forwards Amend#37 to facil Emergency Pien(rev pages for intertion into FBAR). WILLIAMS.D.H. Arkaness Power & Light Co. 78/11/06. 19pp 94039.154
- J insurance & indemnity information
- 7810230200 Forwards Endorsemente #30.31.32.33.34 to Liability Policy Policy NF-74.as requested in 780922 NRC ltr Hilliams.D.H. Arkenses Power & Light Co. 78/10/11. 13pp. 94164-087
- K. Utility Final Bafety Analysis Report (FBAR) & amends
- 7812280125 Forwards annotated ray pages for ANO-1 FGAR to possession & use of Krypton 83 source exceeding current limits of OL-suppressing previous 780816 ray pages. WILLIAMS.D.H. Arkanses Power & Light Co. 78/12/06. 7pp. 94310: 255.
- P. Operating license stage documents & correspondence
- 7810100081 Forwards proposed changes to Tech Spece & Environ Tech Spece listing new job titles & organizational duties.
 CAVANAUGH N Arkanses Power & Light Co. 78/09/22. 5pp. 94032:192.
- 7810230271 Forwards Amend 36 to License DPR-51, safety evaluation & notice of issuance & availability. REIDR.W. Operating Reactors Dranch a (Pre 790525). 78/10/05. Spp. 94167:123.
- --7816030273 Amend 36 to License DPR-51, changing Tech Specs to permit handling of 25 ton shielded shipping cask on one-time basis to remove & ship irradiated B4C test rods stored in facility fuel storage pool. REID-R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/05. 4pp. 94167: 126.
- -7810230279 Bafety evaluation supporting Amend 36 to License DPR-51. . Office of Nuclear Reactor Regulation, Director. 78/10/05. 4pp. 94167, 130.
- --7810230281 Notice of issuence of Amend 35 to License DPR-31. REID.R.W. Dperating Reactors Branch 4 (Pre 790625). 78/10/05 20p. 94167:134.
- 7810240001 Review of appl for Oper Lic. Documents efforts by city of faragould Ar. to participate w/2% interest in AP & L planned facils whencl supporting correspondence.
 HAMILTON.D.B. Cathey, Goodwin & Hamilton. 78/10/12. 13pp.
- JB10240098 Supplements info in 780922 request for proposed changes to Tech Specs & Environ Tech Specs to implement proposed reorganization of plant staff. Describes functions of major positions setablished by reorganization.

 HILLIAMS, D. H. Artansas Power & Light Co. 78/10/17. App.
- '810250098 In response to 780428 NRC ltr.analysis of ECCS small break was discussed in ltrs from J. H. Taylor (B&H) to S. A. Varga dtd 780718 & 780811. WILLIAMS, D. H. Arkenses Power & Light Co. 78/10/17. 1p.
- 811010363 Responds to util 770617,0705 & 1206 proposed Tech Specs 3.3 4.1 for reactor bldg spray sys. Changes acceptable provided sodium hydroxide concentration is 18% weight & computer simulator data varified within 21 days. REID.R.W. Dperating Reactors Branch 4 (Pre 790625). 78/10/17. 3pp. 94386:299.

- 7610260076 Advises that 780719 application to amend OL considered C1 4 action & remaining fee balance should be submmitted MILLER.W D. License Fee Management Branch. 78/10/19 1p 94392.313
- 7811060075 Documents verbal commitment between author & O Vissing ma 781024 re Sequencing Elec Loads on Start Up Transformer "Millstone Mods", still under review are sched for implementation 790301 & oversize drawings availabl in CF. WILLIAMS, D.H. Arkanses Power & Light Co. 78/10/25. Bpp 74423 360
- 7811020091 Reviews Sub, Facil SER on voltage degradation at Class IE 480-volt buses Such degradation could jappardize some fuses in ECCS control circuits.Licensee mod is acceptable. LAINAS.Q Plant Systems Branch (Pre 791030) 94351.066 78/10/27. 1p.
- --78:1020096 SER re potentially serious degradation of off-site pur Bys Mod would change loads from being block started to being sequentially started Concludes that mod is acceptable LAINAB, C. Plant Systems Branch (Pre 791030) 78/10/27 2pp 94351:067
- 7811030106 Supplements 781025 ltr re Sequencing Elec Loads on Startu Transformer Hill req 5 calendar days to implement mod after NRC approval Test of completed sys will req only simple WILLIAMS, D. H. Arkanees Power & Light Co. 78/10/27. 19 02723:3
- 7811030159 Forwards proposed mod to high pressure injection sys Mod meets staff position expressed in NRC 780916 ltr because no oper action util req & it is consistent w/all assumptions of 781017 ECCs Small Breeks Analysis
 HILLIAMS, D.H. Arkansas Power & Light Co. 78/10/27 3pp. 02724: 004
- 7811080136 Responds to NRC concerns re sequencing elec loads on star Proposed mode will be implemented by 781031.
 WILLIAMS D. H. Arkeness Power & Light Co. 78/10/27. 2pp
- 7811130284 Requests registration as user of Chem-Nuc Bys#CNSI 14-195 ehipping cast.
 WILLIAMS.O.H. Arkansas Power & Light Co. 78/10/27. ip 94011.2
- 78:1150032 Notice of mod to Licence DPR-51 to alleviate undervoltage condition which would be created in startup transformers which would in turn provide degraded voltage.

 BTELLO.V Division of Operating Reactors. 78/10/27. App. 94112-171.
- 7Biil30190 Request review of anti-destription of Phase 3 installation for cooling battery/charger rooms Submittal completes followup action re RD 30-313/77-19. Forwards oversite drawings. W/o drawings. Wild frawings.
 HILLIAMS. D.H. Arkansas Power & Light Co. 78/10/31. 3pp. D399-399 03550: 333
- 78i1i60062 Forwards proposed change supporting Topical Rept Tech Spe re parameter changes necessary for tycle 4 oper Determines change to be Class 4 amend & encloses fee Requests approval by Mar 1979 CAVANAUGH, W. Arkansas Power & Light Co. 78/11/09. 24pp. 94132:268
- --7811160064 "Cycle 4 Reload Report." Arkansas Power & Light Co. BAW-1504. 78/10/31. 54pp. 74132:312
- 78:11:60129 Responds to 78:1019 NRC ltr requesting \$8,300 to allow use NAC-1 Cask This figure represents the difference in fee determination between util 78:08:11 to 8 NRC 78:08:11 ltr. Util contest NRC determination & will not remit difference. HILLIAMS, D. H. Arkansas Pawer & Light Co. 78:/11/09 2pp. 94135: 229.
- 7812010370 Forwards Amend 37 to License DPR-51. Amend 5 to License NPF-6.sefety evaluation & notice of issuance & evailability. REID.R.W. Operating Reactors Branch 4 (Pre 790625). BYOLZ.J.F. Light Water Reactors Branch 1. 78/11/13 Rpp. 94409:061.
- --7812010374 Amend 37 to License DPR-51, changing Tech Specs dealing administrative controls, plant organization & revising ETS to make them current w/Unit 2.
 REID,R. W. Operating Reactors Branch 4 (Pre 790625). 78/11/13.
 28pp. 94409:063.

- -- 7812010377 Amend 5 to License NPF-6. changing Tech Specs dealing w/ administrative controls & plant organization BTOLZ.J.F. Light Water Reactors Branch 1. 78/11/13. 19pp 94409 091
- --78120103BO Safety evaluation supporting Amend 37 to License DPR-51 & Amend 5 to License NPF-6. Office of Nuclear Reactor Regulation, Director 78/11/13. 2pp. 94409:110
- --7812010381 Notice of issuance of Amend 37 to License DPR-51 & Amend 3 to License NPF-6. REID,R.H. Operating Reactors Branch 4 (Pre 790625) 78/11/13.
- 7812130118 Notice of wortshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-wortshop registration of attendes to facilitate sending out meth. M/enci Registration Form & List of Locations. MILLER, J. R. Assistant Director for Site & Safeguards (Pre 791030). 78/11/19. Spp
- 7812190002 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PWR's(NUREO-0472)& "Preparation of Radiological Effluent Tech Specs for Nuc Pwr Plants" (NUREO-0133). ORIMES. B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/13. 6pp. 94214:248.
- 7811200350 Forwards order for Mod of lic which amends Facil Open Lic #DPR-51. Implementation of ceratin mode to elec pur sys must begin by 781031 Allows oper of ANO-1 until mode are complete. Operating Reactors Branch 4 (Pre 790625). 78/11/17. 2pp. REID R. W. 94451:001
- --7811200356 "Notice of Order for Mod of Lic#DPR-51." Mod involves connection of load sequence circuitry used for loading diesel generators such that they will also sequence safety STELLO, V. Division of Operating Reactors. 78/11/17. 6pp. 94451:003.
- 7811300045 Discusses Mountain West Research. Inc forthcoming contracted study on regional socioeconomic impacts during Pacility const and post-const periods J Chalmers will brise util re study objectives & design & type of info required.
 DEYOUNG.R.C. Division of Site Bafety & Environmental Analysis. 78/11/20. Rpp. 94071:047.
- 7812040236 Forwards results of impingement monitoring at subj facilintake during Oct 78 pursuant to Environ Tech Spec 4.1 2 a (2). WILLIAMS, D. H. Arkenses Power & Light Co. 78/11/28. 2pp. 94329: 023.
- 78:2:50084 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/encl AND: 7812080207. IEID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/29. 6pp. 94211:318. REID R. W.
- 7812140124 Requests review & approval of elternate method of obtaining reference stress intensity factors which allow continued etud tensioning at minimum temp of 70 degrees F during upcoming refueling outage.

 WILLIAMS.D. H. Arkenses Power & Light Co. 78/12/06. 3pp. 94133: 325.
- 7812280146 Emphasizes importance of submitting accurate & complete info substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or anforcement action will result. DAVIS. J. 9. Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94311:298.
- 7812180120 Provides requested verification by computer simulation of sys re Tech Specs change to delete sodium thiosulfate from Reactor 31dg Boray Bys. Requests expeditious review of attach drawdoum test data M/att comparison of tests. HILLIAMS.D.M. Arkansas Power & Light Co. 78/12/13. App. 94364: 335.
- 0. Inspection reports, IE Bulletins & correspondence
- 7810130045 Forwards IE Inspec Repts 50-313/78-12 & 50-368/78-20 on 780710-14 & 780725-28 & notice of violation. MADEEN, C.L. Region 4, Delias, Reactor Operations Nuclear Support Branch. 78/08/11, Spp. 94001:179.

- --7810130049 Notice of Violation from inspec on 780710-14. Region 4, Dallas, Reactor Operations Nuclear Support Brench. 78/08/11 2pp. 94001:181
- --7810130053 IE Inspec Rept#50-313/78-12 & #50-368/78-20 on 780710-14 & 25-28 during which 3 items of noncompliance were noted: no audits conducted since 770728 under SRC no demonstration of nonsupervised circuits unplugged rad warmer.
 HADSEN, O. L., WESTERMAN, T. F., KELLY, D. L. Region 4, Dalles, Reactor
 Operations Nuclear Support Branch. 78/08/10. 12pp. 94001:183.
- 7810140089 Forwards IE Inspec Repts#50-313/78-13 & #50-368/78-21 on 780801-04 & 780808-10 during which no items of noncompliance MADEEN.G.L. Region 4. Dellas. Reactor Operations Nuclear Support Dranch. 78/08/22. 2pp. 94421:001.
- --7810140092 IE Inspec Repts#50-313/78-13 & #50-368/78-21 on 780801-04 & 780808-10 during which no items of noncompliance were noted. Hajor areas inspec included Tech Spec calibr & surveill & items re Oper Lic issuance & Constr Defiency Repts. HESTERMAN.T.F., BOYTER.N.C., MADBEN.G.L. Region 4, Dallar of the Director 78/08/22. 8pp. 94421:003 Region 4. Dallas, Office
- 7811210114 Forwards IE Inspec Rept#50-313/78-14 on 780814-18 & Notice Of Violation.

 MADREN, O. L. Region 4, Delies, Reactor Operations Nuclear Bupport
 Branch. 78/09/14. 2pp. 94482:176.
- --7811210115 Notice of Violation from Inspec on 780814-18.

 * Region 4. Dallas. Reactor Operations Nuclear Support Branch.
 78/09/14. 2pp. 94482:178.
- --7811210121 IE Inspec Rept#30-313/78-14 on 780814-18 during which 4 items of noncompliance were noted failure to control high radiat areas improper radigactive shipment & failure to MURRAY. B., BROWN, G. D. Region 4. Dallas, Reactor Operations Nuclear Support Branch. 78/09/13. 11pp. 94482:180.
- --7811210125 Responds to 780914 NRC ltr re violations noted in Inspec Rept#80-313/78-14. Corrective actions: door to high radiat area posted w/high radiat area signs. Expended filters double checked for dewatering. Williams. D.H. Arkansas Power & Light Co. 78/10/09. 2pp. 94482; 191.
- ---781121012B Ack receipt of 781009 ltr informing NRC of steps taken to correct violations noted during inspec#50-313/78-14.

 MADSEN.G.L. Region 4, Dallas, Reactor Operations Nuclear Support Branch. 78/10/31. 1p. 94482:193.
- 7810110296 Ack receipt of 780918 ltr informing NRC of steps taken to correct violations noted during IE Insp 50-313/78-10. MADEEN,O.L. Region 4, Dellas, Reactor Operations Nuclear Support Branch. 78/09/25. ip. 94068:343.
- ---7810110301 Responds to 780911 NRC ltr re violation noted in Insp Rept 50-313/78-10 Corrective actions:agrees w/definition of "annual" per NRC interpretation for annual operator requalification asams. WILLIAMS, D. H. Artensas Power & Light Co. 78/09/18. 1p. 740AB: 344
- 7810140131 Forwards IS Bulletin#78-12 requiring action re reactor facil w/oper lic or constr permit.(See ANC:7810004253) BEYFRIT.K.V. Office of Inspection & Enforcement. Office of the Director. 78/09/29. 1p. 94413:048.
- 7811210480 Forwards IE Inspec Repts#50-313/78-15.#50-368/78-23 & Notice of Violation.
 MADEEN.G.L. Region 4. Delles. Reactor Operations Nuclear Support
 Branch. 78/10/04, 2pp. 03658: 228.
- --7811210487 Notice of Violation from inspec on 780822-25,780828-31, 780705-08. * Region 4, Dallas, Reactor Operations Nuclear Support Branch. 78/10/04, 2pp. 03558: 230.
- --7811210501 IE Inspec Repts#50-313/78-15 & #50-368/78-23 on 790822-0913 during which 2 items of noncompliance were noted: verification of operability of main steam isolation valves & non-functional panetration fire barrier. WESTERMAN.T.F., JOHNSON.H.D., DICKERSON.M.W. Region 4, Della Office of the Director, 78/10/03, 23pp. 03558:232. Region 4, Dallas,
- 78:1220117 Forwards IE Circular#78~18. "UL Fire Test." W/encl ANO: 7811150002. SEYFRIT, K. V. Region 4, Dallas, Office of the Director. 78/11/06. 1p. 94071:286.

T.K.V. Region 4: Dallas: Office of the Director: 78/10/13. 74169:173.

53 Forwards IE Inspec ReptsW50-313/78-16 & W50-368/78-24 on -1022 & notice of violation.

79.L. Region 4, Dellas, Reactor Operations Nuclear Support - 78/10/31. 2pp. 94215:066

0088 Notice of Violation from inspec on 780925-1022. egion 4. Dallas. Reactor Operations Nuclear Support Branch. 0/31. ip. 94215:068

006: IE Inspec Repts#50-313/78-16 & #50-368/78-24 on 780925-1022 ng which I item of noncompliance was noted: bypasses were properly verified upon removal.

ERMAN.T.F., SPANGLER.R.G., MADBEN.G.L. Region 4, Dellas, tor Operations Nuclear Support Branch. 78/10/31. 6pp. 5-06.9

13 Act receipt of 781024 itr informing NRC of steps taken to twiolations during inspec#50-313/78-15 & 3/78-23.

9.L. Region 4, Dellas, Reactor Operations Nuclear Support 78/11/03. 2pp. 94087:053

327 Responds to 781004 NRC ltr re violations noted in Inspec 190-368/78-23. Corrective actions: use of sign-off steps teurn HPSI pump hand switches to normal.install "fire" i on fire doors. AMB.D.H. Artaneas Power & Light Co. 78/10/24. 2pp. 1054.

77 Forwards IE Inspec Rept#50-313/78-18 on 781003-06 during in items of noncompliance were noted. 30H.M. Region 3: Chicago: Bafeguards Branch. 78/11/09. 2pp. 20.

7 Forwards Inspec Rept 50-313/78-20 & 50-368/78-27 on 781026 ing w/ pub officials of London & Russellville, AR ing subj Facil.
9. L. Region 4, Dallas, Reactor Operations Nuclear Support 78/11/09. 2pp. 94159:245.

ORO Inspec Rept#50-313/78-20 & #50-368/78-27 on 781026 during NRC officials discussed w/local officials lines of nication w/NRC, the status of sub_facil, & community the

RMAN, T.F., MADBEN, O.L., WIGNER, C.E. Region 4, Dallas, Reactor tions Nuclear Support Branch. 78/11/08. 3pp. 94159: 247.

9 Forwards IE Bulletin #78-12A.suppl to IE Bulletin#78-12. ANO: 7811300035. K. V. Region 4. Dallas. Office of the Director. 78/11/24, 371:357.

7 Ack receipt of 781121 itr informing NRC of steps taken to violations noted in Inspec Rept#50-313/78-17.
3.L. Region 4. Dellas. Reactor Operations Nuclear Support 78/12/07. ip. 94307:007.

321 Responds to 781026 NRC ltr re violations noted in Inspec 30-313/78-17. Corrective actions: procedures used For I bldg purges & detailed instructions For hand lating values have been corrected, WHS.D.H. Arkenses Power & Light Co. 78/11/21. 2pp. 008.

127 Forwards IE Inspec Rept#50-313/78-17 on 781002-06 & Notice lation.

1. G. L. Region 4. Dellas, Reactor Operations Nuclear Support 78/10/2A. 2on. 94307:010.

32 Notice of Violation from inspec on 781002-06. ion 4. Dallas, Office of the Director. 78/10/26. ip.

36 IE Inspec Rept850-313/78-17 on 781002-06 during which 1 f noncompliance was noted; gaseous effluent release streaded.

18., BROWN, O. D. Region 4. Dellas, Fuel Facility & Materials Brench. 78/10/25. 7pp. 94307:013.

Ack receipt of 781122 ltr informing NRC of steps taken to violations noted during inspect50-213/78-16.
L. Region 4, Dellas. Reactor Operations Nuclear Support 78/12/11. 1p. 94279:115.

to maintain compliance. Hill IAMB.D.H. Arkanses Power & Light Co. 78/11/22. ip. 94279-116.

7812210135 Forwards resigness to Items of Inside Programming which were not resolved during 781115-16 meetings. 12 related oversized piping & instrumentation diagrams retained by Ching Cheng WILLIAMS, D. H. Arkenses Power & Light Co. 78/12/15. 3lpp. 94268: 263.

R. Periodic operating reports & related correspondence

7810200067 Forwards Monthly Open Rept for Sept 1978.

HILLIAMS, D. H. Arkenses Power & Light Co. 78/10/10. 1p. 94412: 176.

--7810200070 Monthly Oper Rept for Sept 1978. BHIVELY, C.N. Arkenset Power & Light Co 78/10/11. Spp. 94412:177.

7810310119 Forwards fish impingement monitoring results for Sept 1978. HILLIAMS.D.H. Arkansas Power & Light Co. 78/10/24. 2pp. 94090:017.

7811030151 Forwards third quarter Netl Pollutent Discharge Elimination Bys Rept for NPDES Permit#ARG001372. WILLIAMS, D. H. Arkensas Power & Light Co. 78/10/01. 2pp. 02723-353

7812120138 Forwards Monthly Oper Rept for Nov 1978.
WILLIAMS, D. H. Arkaness Power & Light Co. 78/12/07. 1p. 94276: 250.

---7812120142 Monthly Oper Rept for Nov 1978. 8HIVELY: C.N. Arkansas Power & Light Co. 78/11/30. Spp. 94276: 231.

7812280127 Forwards intake impingement monitoring data for subj facil for Nov 1978.
WILLIAMS,D.H. Arkansas Power & Light Co. 78/12/21. 20pp. 94310: 224.

S. Reportable occurrences. LERs & related correspondence

7810170143 Forwards LERR78-023/017-0 & 78-024/03L-0. WILLIAMS.O.H. Arkansas Power & Light Co. 78/10/06. 1p. 94236:066.

~-7810170146 LER#78-023/01T-0: on 780925, during surveillance test, Control Rod Driveline Breaker A failed to trip on first attempt. Caused by trip mechanism mechanical arm being out of adjustment, Arm adjustment corrected Breaker meets specs. SHIVELY: C.N. Arkeness Power & Light Co. 78/10/06. App. 94236: 067.

---7810170149 LER#78-024/03L-0; on 780916, Control Rod Driveline Breaker A failed to trip upon reactor trip. Cause not given. Breaker tripped manually. Minor adjustments made to breaker. Breaker subsequently tested successfully.

BHIVELY, C. N. Arkansas Power & Light Co. 79/10/06. 1p. 94236: 071.

7811040175 Forwards LER#78-025/03L-0.LER#78-026/03L-0 & LER#78-027/03L-0.

NILLIAMB.D.H. Arkenses Power & Light Co. 78/10/13. ip. 94489:113.

--7811060180 LER#78-025/03L-0: on 780917, control rod index reached restricted ione w/worst case condition at 171 % withdrawn at 90 % power. Caused by miscalculated boron addition to RCB. Acceptable rod positions obtained within 2-h. BHIVELY, C.N. Arkensas Power & Light Co. 78/10/13. 1p. 94489:114.

--7811060183 LER#78-026/03L-0: on 780926, normal borated water storage tank chemical sample showed boron concentration below Tech Spece limit. Cause not given. Concentration raised to Tech Spece requirements.

SHIVELY. C.N. 'Arkenses Power & Light Co. 78/10/13. ip. 94489: 115.

--7811060189 LER#78-027/03L-0: on 780926, condensets storage tank level dropped below min Tech Specs level, Caused by abnormally high condensate demand due to a smultaneous rinsing of polisher & makeup plant plus makeup to hotwell.

BHIVELY, C. N. Arkanses Power & Light Co. 78/10/13. 1p. 9489: 116.

1060154 Forwards LER#78-028/03L-0. ILLIAMS, D. H. Arkansas Power & Light Co. 78/10/27. 1p. 94489: 072.

811060158 LER#78-028/03L-0: on 780929, leak developed in casing drain line from discharge of Makeup Pump P36C upstream of Valve ABD-9C. Caused by crack in pipe nipple threaded into pump Casing due to apparent overstressing in installation. BHIVELY, C. N. Arkensas Power & Light Co. 78/10/27 94489: 073.

1200176 Forwards LER#78-029/03L-0. ILLIAMS, D. H. Arkenses Power & Light Co. 78/11/06 1p. 94252:293.

811200180 LERW78-029/00L-0:on 781017 during surveillance test. Control Rod Driveline A breaker failed to immediately trip on trip signal. Cause not identified. Breaker replaced. SHIVELY, C.N. Arkaneas Power & Light Co. 78/11/06. 1p. 94252: 294.

1170053 Bummarizes 780916 event & recommends (t be kept as Abnormal courrence; during pur oper Unit 1 tripped due to failure of ne main steam isolation valve & shut down Resulting elso ransient started Unit 2 diesel generature.causing flooding.
AIMAS-Q. Flanb Bystems Branch (Pre 791030), 78/11/07. 2pp. 4046; 253.

2120131 Forwards Addenda A to "Reactor Bldg Containment Integrated eak Test Rept. " It.LIAMS, D. H. Arkansas Power & Light Co. 78/11/30. 1p. 94276:160.

812120137 "Reactor Containment Bldg Integrated Leakage Rate Test Rept, Addenda A.Local Leak Rate Testing."

* Arkanses Power & Light Co. 78/10/08. 15pp. 94274:184.

2270247 Forwards LERW78-030/03L-0. ILLIAMS.D.H. Artansas Power & Light Co. 78/12/19. lp. 94017:161.

812270249 LER#78-030/03L-0:an 781191.borated water storage tank boron concentration Fell below Tech Specs limit Causad by open Condensate Valve CB-3B Valve closed increasing boron concentration.

SHIVELY, C. N. Arkensas Power & Light Co. 78/12/19. ip.

KET 80-315 DOMALD C. COOK NUCLEAR POWER PLANT, UNIT I

Becurity, modical, emergency & fire protection plans 1170204 Reports on investigation of isolation of deluge valves to rumming room & new fuel recaiving area: clasing valves was secssary to prevent apurious oper of sprintler sys during apairs to broken fire header outside bldg from 781027-31. HALLER D. V. Indiana & Michigan Power Co. 78/11/09. 2pp.

2210354 Responds to 781122 request for change in commitment re-inding replacement portable air sample for amergency use, scepte rev plan. EPPLER. J. G. Region 3. Chicago, Fuel Facility & Materials Safei

ncepte few plan. EEPPLER.J. G. Region 3, Chicago, Fuel Facility & Materials Safety Franch. 78/12/13. 2pp. 94014:351.

General correspondence

94017: 162

4048: 295

.1100154 Notice of meeting on 781101 w/AEP to discuss AEP plans for suc plant & related metters. W/att agenda. ILLVER.H. Light Water Reactors Branch 4. 78/10/30, 2pp. 44047:185.

Utility Final Bafety Analysis Report (FSAR) & amende

.1290247 Forwerds Amend#82 to FSAR. ILLINGHABT.J. Indiana & Michigan Power Co. 78/11/27. 4pp. 14237:203.

811290251 Amend#82 to FBAR: rev of response to FBAR Question D, Append Q.Amend#77. & rev to FBAR acctions 1.7. Rev will allow plant to combine load rejection & turbine trip startup tests & perform only load rejection test.

Indiana & Michigan Power Co. 78/11/27. 4pp. 94237:207.

2260198 Remite eddl few for processing Amend#81 to F8AR for subj acils.purusent to discussions w/NRC. ILLINOHAST.J. Indiana & Michigan Pawer Co. 78/12/12. 2pp, 4141:330.

P. Operating license stags documents & correspondence

78:01:00:00 Describes abnormal environ occurrence of 780923 when chlorine residuals showed greater than 0.10 PPM, due to increase in chlorine feed rate resulting from clutch elipping in chlorinator. Tension on clutch adjusted.

BHALLER, D. V. Indiana & Michigan Power Co. 78/10/02. 2pp. 94063: 348.

7811010204 Notice of 781031 meeting u/American Elec Pur Bvc Corp to discuss proposed mod of spent fuel pool. MLYNCZAM.M. M. Deerating Reactors Branch 1 (Pre 790625). 78/10/12 2pp. 94391: 345.

7811030103 Forwards 2 copies of Startup Test Rept For Cycle 3 of subject). Encl evailable in CF only.
TILLINGHABT, J. Indiana & Michigan Power Co. 78/10/24. 2pp. 02721: 184.

7810310090 Response to itr që 780913 from A Schwencer, presents sches for submittel of rev EECS analysis for subj facil.
Hestinghouse has alredy performed reshalysis for Unit 2. Unit i will be removed from area of concern addressed in itr.
TILLINGHAST. J. Indiana & Michigan Power Co. 78/10/25. 2pp. 94091: 167.

7810310204 Requests extension in responding to 780828 1tr from Behwencer re overpressure protec Tech Space. Needed into will not be received & in-house reviews will not be completed in time Extension sought is to 781128.
TILLINOHABT. J. Indiana & Michigan Power Co. 78/10/25. 2pp. 94090: 314.

7811130164 Notifies applicant of 781128 NRC-sponsored seminar re Model Radiological Effluent Tech Specs for Nuc Pur Plants Encl y/Seminar Info Shaetito be completed & returned by 781117) & Proposed Agenda. KEPPLER.J.Q. Region 3, Chicago. Office of the Director. 78/11/07. 6pp. 03553: 275.

78i1280344 Forwards request for add1 info re containment sump tests.
Inter alia, seeks info re NP8H margin & containment sump vent design 9CHWENCER, A. Dp 3pp. 94397: 184. Operating Reactors Branch 1 (Pre 790625). 78/11/07.

7811270018 Forwards Amend#26 & S to facil Open Lic#DPR-58 & DPR-74. Adend consists of changes to Append B Environ Tech Spec in response to 780301 appl.

BCHMENCER.A. Operating Reactors Branch 1 (Pre 790625), 78/11/08. 3pp. 94081:058.

--7811270019 Amend#26 to Lic#DPR-58 re deicing measurements.water chemistry in plant sys, chemical discharges, thermal discharge surveillance, groundwater monitoring & termination of biota monitoring. BCHWENCER, A. Operating Reactors Branch 1 (Prs 790625). 78/11/08. 2pp. 94081:061.

--78:1270020 Amend#8 to LiceDPR-74 re deicing measurements, water chemistry in plant sys.chemical discharges, thermal discharge surveillance, groundwater monitioring & termination of biote monitoring. SCHHENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/08. 60mp 940H1:063.

--7811270021 Environ Impact Appraisal & safety aval supporting Assade26 b 88 to facil oper lic #DPR-74.
SCHMENCER, A. Deprating Reactors Branch 1 (Pre 790625), 78/11/08. 12pp. 94081:124.

--7811270023 Notice of issuance of smend to facil open lic & negative declaration relating to descing measurements, water chamistry implent sys.chemical discharges, thermal discharge surveillance, groindwater monitoring. BCHMENCER, A. Operating Reactors Branch I (Pre 790625). 78/11/08. BCHNENCER, A. Op. 3pp. 94081: 142.

7811210260 Forwards "Reactor Containment Bldg Integrated Leal Rate Test" rept for subj facil conducted 780527-29. TILLINGHABT, J. Indiana & Michigan Power Co. 78/11/14. 29p. 94486: 052.

--781210265 "Reactor Containment Bldg Integrated Leak Rate Test, 780527-29" Covers acceptance criteria, ILRT test results, test conduct, instr & equip containment model & leak rate calculations, ILRTEST prog printout & analysis.

* Indiana & Michigan Power Co. 78/11/14, 98pp. 94486:054.

781

781

781

EM 781 5

.

781

MI 4 781

7815 He 0 i Bi

7812

NA DA

7812 ٧o 8u

--78

7012 Нa 1n T1

7812

711 74 7612

for

- 49 Notice of workshops re implementation of training & qualseents contained in Append B of 10CFR72. Requests rishop registration of attendees to facilitate sending t1. W/enc1 Registration Form & List of Locations. -J. R. Assistant Director for Bite & Befeguards (Pre 79103D). 15. 5pp.
- 18 Forwards Revél "Draft Radiological Effluent Tech Specs" for UREO-0473) & "Preparation of Radiological Effluent lecs for Nuc Pur Plants" (NUREO-0133).

 B K. Assistant Director for Engineers & Projects (Pre 78/11/13. 6pp. 94215:015.
- O Informs IMPR that NRC has contracted w/Mountain West Resundertake a series of post-licensing studies of nuctions. Studies will analyze socioecon impacts which diduring constrike post-constriperiods of each plant. 98. C. Division of Site Bafety & Environmental Analysis. O. 2pp. 94071:083.
- i Lic #DPR-58 & #DPR-74 Appl for Amend to increase spent fuel capacity from 500 to 2.050 fuel assemblies W/encl ption & Bafety Analysis for the Fuel Storage Capacity on Prog."

 .9. P. Indiana & Michigan Power Co. 78/11/22
- 5 Summary of 781031 meeting re spent fuel pool expansion at cil.Licensee outlined preferred lic sched & will rerack appl on 781115 & 781211.NRR lic review to be ed by 780413.

 4.M. M. Operating Reactors Brench 1 (Pre 790628). 78/11/22.

 44187-311
- 3 Discusses possible dangers of LOCA in containment purging normal plant open Requests either commitment to limit or justification for continuing Wencl AND: 307.

 IR.A. Operating Reactors Branch i (Pre 790625). 78/11/28.
 1130:311.
- o Forwards results of 780328 strontium split samples, 780328 ituld waste analysis, 780307 nonacidified split to 781019 acidified split samples.

 D. V. Indiana & Michigan Power Co. 78/11/29. 7pp.
- Reports loss of documentation from 780216 Ice Basket. All final weights, data enalysis & weight standard lity are evailable, so it is felt that requirements Specs are Satisfied.

 D. V. Indiana & Michigan Power Co. 78/11/29. 2pp.
- Emphasizes importants of submitting accurate & complete infog licensees & applicants. Info submitted must be issted by data & calculations. Licensee must notify not inaccuracies or enforcement action will result.

 9. Office of Inspection & Enforcement, Office of the 78/12/06. Rpp. 94311:302.
- Forwards rapt entitled "Hydraulic Model Investigation of § & Bwirl within a Reactor Containment Recirculation to 780930. AGT.J. Indiana & Michigan Power Co. 78/12/20, 2pp.
- 81 "Hydraulic Model Investigation of Vortexing & Swirl Within A r Containment Recirculation Sump" rept. Tests concluded all sump design should be modified to reduce excessive in suction pipes under certain blockage conditions.

 ABHAN.H. Indiena & Michigan Power Co. 108-78/M178PF.

 30. 67pp.
- Provides preliminary info re plans for next refueling outage "acil. Current operatig cycle should end in late early April 1979; startup of next cycle is espacted 179. No Tech Spec changes foreseen.
 18T. J. Indiana & Michigan Power Co. 78/12/20. 2pp.
- Forwards #12700 check for processing of spent fuel storage expension submittals. Hill submit thermal enelysis i & struc enelysis by 780220.

 187. J. Indiana & Michigen Power Co. 78/12/21, 2pp.
- Requests changes to Append "A" Tech Space of subj facil & proposed changes w/appropriate rev pages. Also has al. 200 fee.
- .P. Indiana & Michigan Power Co. 78/12/22. Pob.

- --7812290185 Proposed revs to Append "A" Tech Space of subj facil.
 Contains 16 changes w/appropriate rev pages re: Fire deter
 instru.flow rates for boron injec sys.spray additive sys
 Tech Space.applicability of Tech Bpace & editorial changes.

 Indiana & Michigan Power Co. 78/12/22. 56pp. 94190:124.
- Q. Inspection reports, IE Bulletins & correspondence
- 7810240032 Forwards IE Inspec Repts#50-315/77-26 & #50-316/77-37 on 771114-16 & 1214-15,20-21 during which no items of noncompliance were noted.
 HIND.J.A. Region 3, Chicago, Bafeguarde Branch. 78/01/19. 2pp.
- --7810240035 IE Inspec Repts#30-315/77-26 & #50-316/77-37 on 771114-16 & 1214-15:20-21 during which no items of noncompliance were noted Major areas inspected included security organization, physical berriers, access controls, detection aids. CARLBON, D. M., MADEDAIT, J., HIND, J. A. Region J. Chicago, Safeguards Branch. 78/01/18. 1p.
- 7810270395 Forwards IE Inspec Repts#50-315778-25 & #50-316/78-23 on 780710.12.14.17.19-21.24. & 26-28.780809-10.14.16-18 & Notice of Violation. FIDMELLI.9. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/09/21. 2pp. 94033:296.
- --7810270388 Notice of Violation from Inspec on 780710, 12.14.17, 19-21, 24, 22-28 & 780807-10, 14, 16-18.

 * Region 3, Chicago, Reactor Operations Nuclear Support Branch, 78/09/21, jp. 94033; 298.
- ---7810270398 IE Inspec Repts#50-315/78-25 & #50-316/78-23 on 780710 during which 1 item of noncompliance was noted procedure for equip control was not implemented as required. allowing unplement release of partial contents of 2 gas decay tanks. BAKER.K. R. Region 3. Chicago, Reactor Departions Nuclear Support Branch. 78/09/20. 9pp. 94033:247.
- 7810300375 Forwards IE Inspec Rept #50-315/78-25 & 50-315/78-25 on 780905-07 during which no items of noncomplainte were noted. DAVIS, A. B. Region 3, Chicago, Bafaguards Branch. 78/09/22. 2pp. 34150-345
- --7810300383 IE Inspec Repts #50-315/78-25, 50-316/78-25 on 780905-07 during which no items of noncompliance were noted. Major areas inspected included: apecial confirmatory measurements inspec & sample analyses.

 @REER.R.J. Region 3: Chicago, Bafeguards Branch. 78/09/21, App. 94199:345.
- 7811020111 IE Inspec Repts#50-315/78-23 & #50-316/78-21 on 780905-06 during which no items of noncompliance were noted. Major areas inspected included:action on previously identified items re operability of safety related anubbers. YIN.I.T., DANIELBON.D.H. Region 3. Chicago, Office of the Director. 78/09/25. 5pp. 94351:083.
- 7811020106 Forwards IE Inspec Repts#50-315/78-23 & #50-316/78-21 on 780905-06 during which no items of noncompliance were noted. HEISHMAN.R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/09/27. 2pp. 94351:081.
- 7811080101 Forwards IE Inspec Repts#50-315/78-30 & #50-316/78-28 on 780914 during which no items of noncompliance were noted. KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/10/02. 2pp. 94399:084.
- --7811080104 IE Inspec Repts#80-315/78-30 & #50-316/78-20 on 780914 during which no items of noncompliance were hoted. Major ares inspected included: subj facil operating performance. FIORELLI.G., KEPPLER.J.G. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/09/14. 2pp. 94399:086.
- 7810110297 Act receipt of 780911 ltr informing NRC of steps taken to correct violations noted in 780817 NRC ltr. FIDRELLI.9. Ragion 3. Chicago. Reactor Operations Nuclear Support Branch. 78/10/03. 1p. 03556:083.
- 7811090182 Forwards IE Inspec Repts#50-315/78-24 & #50-316/78-22 on 780829-0901 & Notice of Violation. FIUMELUL, Q. Region 3, Chicago: Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 94038:208.
- --7811090185 Notice of Violetion from inspec on 780829-01.
 # Region 3, Chicago, Reactor Operations Nuclear Support Branch.
 78/10/04, 2pp. 94038:210.

- --7811090189 IE Inspec Rept#50-315/78-24 & #50-315/78-22 on 780829-0901 during which 4 items of nancompliance were noted failure to process off sits safety review comm minutes & failure to implement acceptable inavc pump test prog. REVES.L.A. MASSER E. JABLONSKI,F.J. Region 3. Chicago, Office of the Director. 78/10/04 Bpg. 94038-212
- 7811140185 Forwards IE Inspec Repts#50-315/78-28 & #30-316/78-28 on 780912-15 during which no items of noncompliance were noted. DAVIS.A B. Region 3. Chicago, Fuel Facility & Meterials Bafety Branch. 78/10/11. 2pp. 94384:263
- --7811140189 IE Inspec Repts#30-315/78-28 & 50-314/78-28 on 780912-15 during which no items of noncompliance were noted Major areas inspected included: radioactive waste systeffluent releases, records & repts of effluents.

 SCHUMACHER.M.C. Region 3, Chicago, Fuel Facility & Materials Safety Branch, 78/10/10, 7pp. 94384:265.
- 7810230356 Forwards JE Circular#78-17. (8ee AND: 7810230221 Docket 50-133.781013)
 KEPPLER, J. G. Region 3. Chicago, Office of the Director. 78/10/13. is. 94147:001.
- 7811020160 Forwards replacement cover page for losp Repts 50-315/78-30 & 50-316/78-28, on which signatures had been inedvertently omitted.

 KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/10/13.

 2pp. 94354:343.
- 7811080138 Responds to 780921 NRC ltr re violation noted in Inspec Reptw850-315/78-25 & 50-316/78-23 Congective action: the mod indicated in 780822 ltr will be completed by 781031 DDLAN-J.E. American Electric Power Co., Inc. 78/10/16. 2pp. 94399: 283.
- 7812060388 Forwards IE Inspec Rept#50-315/78-29 & #50-315/78-27 on 780925-29 & Notice of Violation Notice of Violation w/held per 100FR2 790(d), HIND.J.A. Region 3, Chicago, Safeguards Branch. 78/10/29. 2pp. 94388:344.
- --7812060391 IE Inspec Repts#50-315/78-29 & #50-316/78-27 on 780925-29 during which 4 itams of noncompliance were noted: security organization, communications control detection elds & testing & maintenance.

 CREED, J. R., HADEDA, T. J., HIND, J. A. Region 3, Chicago, Befeguards Branch, 78/10/20. Epp. 94382:346.
- 7811210446 Responds to 781004 NRC ltr re-violations noted in Inspec Repta#30-315/78-24 & #50-316/78-22 Corrective actions: procedures nev to include requirements of Tech Spec 4.0.5 & 4.5.2.f. i.new procedure 12THP 4030.8TP.022 stablished. DOLAN.J.E. American Electric Power Co., Inc. 78/10/27. 4pp. 94480:198.
- 7811130061 Forwards 1E Circular 78-18.

 MEPPLER J. O. Region 3. Chicago, Office of the Director. 78/11/06.

 1p. 94112:222
- 7811200045 Ack receipt of 781016 ltr informing NRC of steps taken to correct violations noted during inspec. FIDRELLI,G. Region S. Chicago, Reactor Operations Nuclear Support Branch. 78/11/09. ip. 94215/327.
- 7812130035 Forwards IE Inspec Repts#50-315/78-27 & #50-316/78-31 on 780628-31, 780901, 11-15, 18, 20-22, 25-29, 1002 & 1004-06 & Notice of Violation.

 KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/11/09. 2pp. 94307: 215.
- --7812130037 Natice of Violation from inspec on 780828-31,0901,0911-15,0918,09210-22,0925-29,1002 & 1004-06.

 ** Region 3, Chicago, Diffice of the Director. 78/11/09. 2pp. 94307:217.
- --7812130045 IE Inapec Repta#50-315/78-27 & #50-316/78-31 on 780828-31 during which 2 items of noncompliance were noted: Unit 2 RHST piping for low temp alarm was blocked w/o approval & condition repts not promptly initiated for RO's. BAKER, R. R. MANGER, R. P. Ragion 3, Chicago, Dffice of the Director. 78/11/09. 13pp. 94307:218.
- 7812130206 Forwards IE Inspec Rept#50-315/78-31 & 450-316/78-29 on 781010 Suring which no items of noncompliance were noted. HEIE-MAN.R.F. Region 3, Chicago, Office of the Director. 78/11/09. 2pp. 94306:066.

- --7812130209 IE Inspec Rept#50-315/78-31 & #30-316/78-29 on 781010 during which no items of noncompliance were noted Major areas inspected inclicionses action on IE Circular#78-08.

 LABLONGHI,F.J. Region 3: Chicago, Office of the Director. 78/11/09. Spp. 94306:068.
- 7812050311 Forwards IE Bulletin#78-12A, suppl to IE Bulletin 78-12 W/encl ANO: 7811300055 KEPPLER. J. O. Region 3, Chicago: Office of the Director. 78/11/24. ip. 94203-073.
- 7812050260 Forwards IE Bulletin#78-12e.suppl to IE Bulletin 78-12. H/encl ANO.7811300055. PAPPAB.H. Region 3. Chicago, Office of the Director. 78/11/27. 2pp. 94202:142.
- 7812280047 Forwards IE Bullstin 78-14. KEPPLER.J. G. Region 3. Chicago. Offics of the Director. 78/12/19 1P. 94084-323.
- R. Pariodic operating reports & related correspondence
- 7811210383 Forwards Monthly Open Rept for Oct 1978.

 BHALLER D. V. Indiana & Michigan Power Co. 78/11/14. 1p. 94464:291.
- --7811210391 Monthly Dper Rept Por Oct 1978.
 OILLETT, W.T. Indiana & Michigan Power Co. 78/11/01. App.
- 7812110137 Forwards monthly repts for July, Aug & Sept 1978 re fish implingement at subj facil.

 8HALLER, D. V. Indiana & Michigan Power Co. 78/12/05. 16pp. 94393: 242.
- 7812200173 Forwards Monthly Open Rept for Nov 1978. BHALLER, D. V. Indians & Michigan Power Co. 78/12/14. 1p. 94188-254
- --7812200174 Monthly Oper Rapt for Nov 1978.

 Oll.ETT. M. T. Indiana & Michigan Power Co. 78/12/04. 6pp.
 94158:326.
- 8. Reportable occurrences, LERs & related correspondence
- 7810180106 Forwards LERW78-051/03L-0 & LERW78-052/03L-0. 8HALLER, D. V. Indians & Michigan Power Co. 78/09/27. 1p. 94421: 301.
- --7810180109 LERR7B-051/03L-0 on 780828: exial flux difference went outside target band during rapid load reduction. Caused by repairs to valves resulting in loss of steam to condenser air ejectors.

 RNDOLPH.J.M. Indiana & Michigan Power Co. 78/09/27. (p.
- --7810180158 LERW78-052/03L-0 on 780828: Steam generator loop level found to have exceeded minimum set point limit. Caused by bad solder joint on resistor, causing input resistance to vary. Solder joint reformed.

 BELLMAN, T. P. Indiana & Michigan Power Co. 78/09/27. 1p. 9442: 303.
- 7810100024 Describes abnormal environ occurrence of 780923 when chloring residuals taken of condenser outlet showed greater than 0.10PPM due to vlip of clutch on feed rate control motor. Clutch tension has been adjusted.

 8NALLER. D. V. Indiana & Michigan Power Co. 78/10/02. 3pp. 94033:044.
- 7810110154 Forwards LER#78-053/03L-0 & LER#78-054/03L-0. SHALLER.D.V. Indiana & Michigan Power Co. 78/10/03. ip. 74415:338.
- --7810110192 LERW78-053/09L-0 on 780907: containment atmosphere gassous separticulate monitoring pump discovered inoperable. Failure attributed to obsplasence. Pump replaced w/improved model w/longer operational expectancy.

 BEILMAN, T. P. Indiana & Michigan Power Co. 78/10/03. lp. 79413:339.
- --7810230117 LERR78-054/03L-0 on 780906: during routine surveillance. [cf condenser inlet door monitoring sys was inoperable, due to short caused by water in instr having same breakers as inlet door monitoring sys.

 BEILMAN, T. P. Indiana & Michigan Power Co. 78/10/03. 3pp. 94058: 019.

rds LERW78-055/03L-0. Indiana & Michigan Power Co. 78/10/18. ip.

#78-055/03L-O on 780924; source range chennel N-31 became
11 he withdrawing shutdown banks of control rads.
Caused erratic indication of channel.
Indiana & Michigan Power Co. 78/10/18 ip.

ିପ s LER#78-056/03L-0. Tridiana & Michigan Power Co. 78/10/20. to.

#79-056/03L on 780923: after shutdown baron concentration which is below limit due to requestion of baron # mampling at 1% accumulator vol increase. Admin # rev to req level & baron verification.

Indiana & Michigan Power Co. 78/10/20. ip.

nds LER #78-056/031-0 Emdiana & Michigan Power Co. 78/10/20 Ip.

(OGO, it become necessary to isolate deluge valves to Room & New Fuel Receiving Area as result of Gys headers. Follow up rept will be issued

Emdiana & Hichigan Power Co. 78/10/30. 1p.

^ds LER#78-057/03L-0,LER#78-058/03L-0 & ~CD. 1 stdiene & Michigan Power Co. 78/11/10. ip.

3-05/03L-0 on 781002: result of study declared pump sed by inconsistency of pump's shility to ted speed which was traced to pump speed now replaced. Endiane & Mitchigan Power Co. 78/11/01. 1p.

#78-058/03L-0 on 781003: rounding off of T(2) resulted in 5ms being non-conservative in top of the core. to perform steirstep comparison to FZ limit in 5F core height.

Indiana & Michigan Power Co. 78/11/01. 2pp.

#78-059/03L-0 on 781023:Pressurizer level channel 3 ater than 4% from other 2 channels, Caused by gas acd in sensing line.
Indiana & Michigan Power Co. 78/11/01. ip.

remote mept me Meteorological Bys inoperability. On & 100 ft wind direction instra were improperly wid by leaving jumpers in during installation disgical Bys Translators.
Indiana & Michigan Power Co. 78/11/03. 2pp.

nds condition repts on 780830 & 780928. Indiane & Michigan Power Co. 78/11/03. 7pp.

dition rept: on 780830 both Meteorological Bys Trensletors diducto switching malfunction, calibr & returned DT28, both wind direction instructware observed e-rly switching. Bys were fully recalibr.
Indiana & Michigan Power Co. 78/10/02. 5pp.

nds LERW78-060/03L-0. Emdiene & Michigen Power Co. 78/11/15. 1p.

₩78-060/00L-0 on 7810R8:RCS leak discovered due to cking on a 314 valve in PZR safety valva loop impe. Valve found to be 1/8 turn open. Valve embage stopped. Indiana & Michigen Power Co. 78/11/15. 1p.

rds LER#78-061/03L-0. Emdiene & Michigen Power Co. 78/12/01. ip. 7812120162 Forwards LER 78-062/03L-0.
BHALLER.D.V. Indiana & Michigan Power Co 78/12/07. 1p. 94274-344

Caused by personnel error. BEILMAN, T.P. Indiana & M.

74104.324

--7812120167 LER 78-062/03L-0. on 781107. Unit I AB dimes declared inoperable following inadvertent removal of circuit board card from diseal voltage regulator circuitry, Removal caused by technician snagging the board on clothing.

BEILMAN. T.P. Indiena & Michigan Power Co. 78/12/07. 1p. 94276-1354

--7812080087 LER#78-061/03L-0 on 780823: discovered that during past

Indiana & Michigan Power Co. 78/12/01. 1p

surveillance testing allowable surveillance extension had been exceeded for target flux difference surveillance test.

7812270220 Forwards LERM78-063/03L-0.
8HALLER, D. V. Indiene & Michigan Power Co. 78/12/20. 1p.

--7812270226 LERW78-Q63/03L-O on 781128: aux feed throttle from MDAFF to 4036/9 position indication was intermittentivalve would not close electrically. Caused by broken lead between terminal 443 & 457 on aux switch of limitorque BMB-O-25 operator. HIZNER.D. 0 Indiana & Michigan Power Co. 78/12/20. ip. 94017-123.

DOCKET 50-316 DONALD C. COOK NUCLEAR POWER PLANT, UNIT R F. Security, medical, emergency & fire protection plans

7811170204 Reports on investigation of isolation of deluge valves to drumming room & new fuel receiving area: closing valves was necessary to prevent spurious oper of sprinklar sys during repairs to broken fire header outside bldg from 781027-01. SHALLER, D. V. Indiana & Michigan Power Co. 78/11/09. 2pp. 94048: 295.

7811270136 Forwards Special Rept 81-01: "Sefety Injection Actuation" dtd 780301 & Special Rept 81-02: "Sefety Injection Actuation" dtd 780804.
8HALLER, D.V. Indiana & Michigan Power Co. 78/11/07. Spp. 94238: 137.

7812210354 Responds to 781122 request for change in commitment refinding replacement portable air sample for emergency use. Accepts rev plan. KEPPLER, J. Q. Region 3, Chicago, Fuel Facility & Materials Safety Branch. 78/12/13. 2pp. 94014:35i.

H. General correspondence

7811100154 Notice of meeting on 781101 w/AEP to discuss AEP plans for nuc plant k related metters. W/att agenda.
BILVER:H. Light Water Reactors Brench 4. 78/10/30. 2pp. 94047:185.

K. Utility Final Bafety Analysis Report (FBAR) & amends

7811890247 Forwards Amend#82 to FBAR.
YILLINGHABTJ, Indiana k Michigan Power Co. 78/11/27. 4pp. 94237:203.

--7811290251 Amend#82 to FBAR: rev of response to FBAR Question 0. Append Q. Amend#77. & rev to FBAR sections 1. 7. Rev will allow plant to combine load rejection & turbine trip startup tests & parform only load rejection test.

* Indiana & Michigan Power Co. 78/11/27. App. 94237:207.

781R260198 Remits add1 fee for processing Amend#81 to FBAR for subj facils,purusant to discussions w/NRC. TILLINGHABT, J. Indiana & Michigan Power Co. 78/12/12. 2pp. 94141:330.

P. Operating license stage documents & correspondence

7811280344 Forwards request for add1 info re containment sump tests. Inter alia.seeks info re NPSH margin & containment sump vent design.

3CHNENCER, A. Deparating Reactors Branch 1 (Pra 790628). 78/11/07.

3pp. 94397:184.

- 7812010365 Bummary of 781031 meeting re spent fuel pool expansion at subj facil Licenses outlined preferred lic sched & uill submit reract appl on 781115 & 781211 NRR lic review to be completed by 780413 MLYNCZAK, M M Operating Reactors Branch I (Pre 790625) 78/11/22 4pp 94418 311
- 7812190038 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PHR's(NNREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133).

 ORITES.B.K. Assistant Director for Engineers & Projects (Pre 790625) 78/11/15 6pp. 94215:015
- 7810120062 Forwards Startup Test Rept for subj facil Lic #DPR-74 on 780919.
 DALANT E. American Electric Power Co., Inc. 78/18/02. 2pp 94403:033.
- --7810120067 Startup Test Rept for subj Pacil describing startup/testing activities initial core loading, initial criticality, low purphysics testing & pur ascension testing completed thru 780801.
 BYARRELLA.E. A. American Electric Power Co., Inc. 78/09/19. 224pp. 94403.035.
- 7011010204 Notice of 701031 meeting w/American Elec Pur Bvc Corp to discust proposed mod of spent fuel pool. MLYNCZAK,H.M. Departing Reactors Granch 1 (Pre 790625) 70/10/13. 2pp 94391:345
- 7810230242 Notification that rept entitled "Qual Test of Darton Pressure & Differential Pressure Transmitters"in both proprietery & nonproprietery versions is being forwarded under separate cover.

 TILLINGHABT.J. Indiane & Michigan Power Co. 78/10/05. Rpp. 94194:323.
- 7810300006 Ack receipt of 780929 itr in response to 780816 NRC ltr. Believes corrective actions re-diesal generator problems are adequate.
 MOSELEY.N.C. Division of Reactor Operations Inspections. 78/10/20. ip. 74034. 221.
- 7810310090 Response to ltr of 780913 from A Bithwencer.presents sched for submittel of rev EECB analysis for subj facil.
 Heatinghouse has alredy performed resnalysis for Unit 2 Unit 1 Will be removed from area of concern addressed in ltr.
 TILLINGHABT. J. Indiana & Michigan Power Co. 78/10/25. 2pp. 94091:167.
- 7810310204 Requests extension in responding to 780828 ltr from Schwencer re overpressure protec Tech Specs. Needed info will not be received & in-house reviews will not be completed in time. Extension sought is to 781128
 TILLINGHAST.J. Indiana & Michigan Power Co. 78/10/25. 2pp. 94090-314
- 7811120164 Notifies applicant of 781128 NRC-sponsored seminar re Model Radiological Effluent Tech Specs for Nuc Pur Plants. Encl W/Seminar Info Sheetito be completed & returned by 781117) & Proposed Apanda.

 KEPPLER, J. Q. Region 3. Chicago, Office of the Director. 78/11/07. 6pp. 03553:875.
- 7811270018 Forwards Amend#26 & 8 to facil Open Lic#DPR-58 & DPR-74.
 Amend consists of changes to Append 8 Environ Tech Spec in
 response to 780301 appl.
 - response to 780301 appl. BCHMEMCER.A Operating Reactors Dranch 1 (Pre 790625). 78/11/08. 3pp. 94081:038.
- --7811270019 Amend#26 to Lic#DPR-38 is deteing measurements water chemistry in plant sys. chemical discharges, thermal discharge surveillance, groundwater monitoring & termination of biota monitoring.

 BCHWERKER, A. Operating Reactors Branch i (Pre 790623). 78/11/08. 2pp. 74081:04:
- --7811270020 Amend#8 to Lic#DPR-74 rs delicing measursments,water chamistry in plant sys, themical discharges; thermal discharge surveillence; groundwater monitioring & termination of blota monitoring.

 BCHMENCER.A. Operating Reactors Branch 1 (Pre 790623). 78/11/08.60pp. 94081:063.
- --7811270021 Environ Impact Appraisal & mafety eval supporting Amend#26 & #8 to facil oper lic #DPR-74.
 BCHWENCER.A. Depending Reactors Branch 1 (Pre 790625). 78/11/08.
 12pp. 94081:124.

- --78/1270023 Notice of issuance of emend to facil oper lic & negative declaration relating to deticing measurements water chemistry inplant sups.chemical discharges, thermal discharge surveillance.groindwater monitoring.

 SCHWENCER.A. Operating Reactors Branch 1 (Pre 790625). 78/11/08 3pp. 94081:142.
- 7811300050 Informs IMPR that NRC has contracted w/Mountain West Res Inc to undertake a series of post-licensing studies of nuc pur stations. Studies will analyze socioscon imports which occurred during constr & post-constr periods of each plant. DEYQUNG.R C Division of Dite Bafety & Environmental Analysis 78/11/20 2pp. 94071:053
- 7811270171 Lic WDPR-50 & WDPR-74 Appl for Amend to increase spent fuel aborage capacity from 500 to 2 050 fuel assemblies. W/encl "Description & Befety Analysis for the Fuel Storage Capacity Expansion Prop" MALCNEY, 0, P. Indiana & Michigan Power Co. 78/11/82. 4ipp. 94197:109.
- 7812180113 Discusses possible dangers of LOCA in containment purging during normal plant oper.Requests either commitment to limit purging or justification for continuing.W/encl ANO. 7812080207.
 BCTHENCER.A. Operating Reactors Branch 1 (Pre 790525). 78/11/28. 6pp. 94130:311
- 7812070216 Forwards results of 780320 strontium split samples, 780328 Cs-134 liquid waste analysis, 780907 nonecidified split samples & 781019 acidified split samples. BHALLER, D. V. Indiana & Michigan Power Co. 78/11/29 7pp. 03535, 094
- 7812280149 Emphasizes importance of submitting accurate & complete info to NRC by licensess & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVID.J.O. Diffice of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94311:302
- 7812280145 Ack 701218 rept to KR Baker re R-11 & R-12.Air Perticulate Detector & Queeous Black Monitor that were out of Svc in conjunction w/Containment Dew Point Recorders. A Pollowup rept will be submitted by 781231.

 BIMALER D. V. indiana & Michigan Power Co 78/12/18. ip. 04/110/138
- 7812270170 Forwards rept entitled "Hydraulic Model Investigation of Vortexing & Bwirl within a Reactor Containment Recirculation Bump," dtd 780930.
 TILLINGHABY. J Indiana & Michigan Power Co 78/12/20. 2pp.
- --7012270101 "Hydraulic Model Investigation of Vortexing & Buirl Within A Reactor Containment Recirculation Sump" rept. Tests concluded original sump design should be modified to reduce excessive swirl in suction pipes under certain blockage conditions. PADMANABIAN.M. Indiana & Michigan Power Co. 108-78/M178PF. 78/09/30. 67pp.
- 7819260242 Forwards \$12700 check for processing of spent fuel storage capacity expansion submittals Hill submit thermal analysis by 790103 & struc analysis by 780220.
 TILLINGHABT. J. Indiana & Hichigan Fower Co. 78/19/21. 2pp. 94199:346.
- Q. Inspection reports, IE Bullstins & correspondence
- 7811090182 Forwards IE Inspec Repts#50-015/78-24 & #50-016/78-22 on 780829-0901 & Notice of Violation. FilmeLLLiq. Region 3. Chicago, Reactor Operations Nuclear Bupport Branch. 78/10/04. 2pp. 94038:208.
- --7811090185 Notice of Violation from inspec on 780829-01. • Ragion 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 94038:210.
- --7811090189 IE Inspec Rept#50-315/78-24 & #50-316/78-22 on 780829-0901 during which 4 items of noncompliance were noted: failure to process off site safety review comm minutes & failure to implement acceptable insec pump test prog. REYES, L. A. HABBE, R. E. , JABLONSKI, F. J. Region 3, Chicago, Office of the Director. 78/10/04. Bpp. 94038:212.
- 7810240032 Forwards IE Inspec Repts#50-315/77-26 & #50-316/77-37 on 771114-16 & 1214-15.20-21 during which no items of noncompliance were noted.
 HIND.J.A. Region 3. Chicago, Bafeguards Branch. 78/01/19. 298.

- --7810240035 IE Inspec Repts#50-315/77-26 & #50-316/77-37 on 771114-16 & 1214-15, 20-21 during which no items of noncompliance were noted. He jar areas inspected included: security organization, physical barriers, access controls, detection aids. CALSON, D H., MADEDA, T. J., HIND, J. A. Region 3, Chicago, Bafeguards Branch. 78/01/18. 1p.
- 7810270385 Forwards IE Inspec Repts#50-315/78-25 & #50-316/78-23 on 780710.12.14.17.19-21.24. & 26-28.780809-10.14.16-18 & Notice of Violation.
 FIDRELLI Q. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/09/21 2pp. 94033-296.
- --7810270398 IE Inspec Repts#50-315/78-25 & #50-316/78-23 on 780710 during which I item of noncompliance was noted procedure for equip control was not implemented as required allowing unglanned release of partial contents of 2 gas decay tanks. BAKER.K. R. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/09/20. 9pp. 94033:299.
- 7810300375 Forwards IE Inspec Rept #50-315/78-26 & 50-316/78-25 on 780906-07 during which no items of noncomplaince were noted. DAVIB.A B. Region 3. Chicago, Safeguards Branch. 78/09/22. 2pp. 94199-343.
- --7810300383 IE Inspec Repts #50-315/78-26, 50-316/78-25 on 780906-07 during which no items of noncompliancs were noted. Major areas inspected included: special confirmatory measurements inspec & sample analyses.

 OREER.R J. Region 3: Chicago: Bafeguards Branch. 78/09/21. 4pp. 74199-345.
- 7811020111 IE Inspec ReptsW50-315/78-23 & W50-316/78-21 on 780903-06 during which no items of nancompliance were noted Major areas inspected included; action on previously identified items re operability of safety related snubbers. VIN.I.T. DANIELBON.D.H. Region 3. Chicago, Office of the Director. 78/09/25. Spp. 94351:083.
- 7810310335 Forwards IE Inspec Rept#50-316/78-24 on 780824-25 during which no items of noncompliance were noted. FIDRELLI.G. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/09/26, 2pp. 94089:109
- --7810310340 1E Inspec Rept#80-316/78-24 on 780824-25 during which no items of noncompliance were noted. Major areas inspected included:preoper test involving initial rise to 70% & 100% pur.

 KOLER.J.E. Region 3. Chicago, Office of the Director. 78/09/26. App. 94089:111.
- 7811020106 Forwards IE Inspec Repts#50-315/78-23 & #50-316/78-21 on 780905-06 during which no items of noncompliance were noted. HEIBHAN.R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/09/27. 2pp. 94351:081.
- 7811080101 fromwards IE Inspec Repts#50-315/78-30 & #50-316/78-28 on 780914 during which no items of noncompliance were noted. KEPPLER.J. Q. Region 3. Chicago. Office of the Director. 78/10/02. 2pp. 94399:084.
- ~7811080104 1E Inspec Repts#30-315/78-30 & #50-316/78-28 on 780914 during which no items of noncompliance were noted. Major ares inspected included: subj facil operating performance. FIGRELLI, Q., KEPPLER, J. Q., Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/09/14. 2pp. 94399:086.
- 7810110297 Ack receipt of 780911 ltr informing NRC of steps taken to correct violations noted in 780817 NRC ltr. FIORELLI.Q. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/03. ip. 03536:083.
- 7811140185 Forwards IE Inspec Repts#50-315/78-28 & #50-316/78-28 on 780912-15 during which no items of noncompliance were noted. DAVIS-A B. Region S. Chicago, Fuel Facility & Materials Bafety Branch. 78/10/11. 2pp. 94384:263.
- --7811140189 IE Inspec Repts#50-315/78-28 & 50-316/78-28 on 780912-15 during which no items of noncompliance were noted Major areas inspected included: radioactive waste systeffluent releases, records & repts of effluents.

 BCHUMACHER, M. C. Region 3, Chicago, Fuel Facility & Materials Bafety Branch. 78/10/10. 7pp. 94384:265.
- 7810230356 Forwards IE Circular#78-17. (See AND: 7810230221 Docket 50-133, 781013)
 KEPPLEN,J. G. Region 3. Chicago, Dffice of the Director. 78/10/13. 1p. 94167:001.

- 7811020160 Forwards replacement cover page for Insp Repts 50-315/78-30 & 50-316/78-28 on which signatures had been inadvertently omitted KEPPLER, J. G. Region 3, Chicago, Office of the Director 78/10/13 2pp. 94354 343
- 7811090138 Responds to 780921 NRC ltr re violation noted in Inspec Repts#50-315/78-25 & 50-316/78-23 Corrective action, the mod indicated in 780822 ltr will be completed by 781031 DDLAN.J.E. American Electric Power Co., Inc. 78/10/16. 2pp. 94399:283
- 7812060388 Forwards IE Inspec Rept#80-315/78-29 & #50-316/78-27 on 780925-29 & Notice of Violation Natice of Violation w/held per 10CFR2 790(d) HIND. A. Region 3, Chicago, Bafeguards Branch 78/10/29, 2pp. 94382:344
- --7812060391 IE Inspec Rapts#50-315/78-29 & #50-316/78-27 on 780925-29 during which 4 items of noncompliance were noted security organization.communications control detection aids & testing & maintenance.

 CREED, J. R., MADEDA, T. J., HIND, J. A. Region 3, Chicago, Befeguards Branch. 78/10/20. 2pp. 94382:346.
- 7811210446 Responds to 781004 NRC itr re violations noted in Inspec Repts#50-315/78-24 & #50-316/78-22 Corrective actions: procedures rev to include requirements of Tech Spec 4.0 5 & 4.5.2 f. inew procedure 12THP 4030 BTP.022 established. DDCAN.J E. American Electric Power Co., Inc. 78/10/27 App. 94480-198
- 781115006) Forwards IE Circular 78-18.
 KEPPLER.J.G. Region 3, Chicago, Gefice of the Director 78/11/06
 1p. 94112:232.
- 7811200045 Ack receipt of 781016 ltr informing NRC of steps taken to correct violations noted during inspec. F10RELLI.G. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/11/09. ip. 94215.327.
- 7812130035 Forwards IE Inspec Repts#50-315/78-27 & #50-316/78-31 on 780828-31, 780901, 11-15, 18, 20-22, 25-29, 1002 & 1004-06 & Notice of Violation.

 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 78/11/09. 200. 94307, 215.
- --7812130037 Notice of Violation from inspec on 780828-31,0901,0911-15 0918,09210-22,0925-29,1002 & 1004-06. * Region 3, Chicago. Office of the Director. 78/11/09. 2pp. 94307-217
- --7812130045 IE Inspec Repts#50-315/78-27 & #50-316/78-31 on 780828-31 during which 2 items of noncompliance were noted:Unit 2 RMST piping for low temp alarm was blocked w/o approval & condition repts not promptly initiated for RO's.

 BAKER.K.R., MASSER.E., WARNICK.R.F. Region 3, Chicago, Office of the Director. 78/11/09. 13pp. 94307/218.
- 7812130206 Forwards IE Inspec Rept#50-315/78-31 & #50-316/78-29 on 781010 during which no items of noncompliance were noted. HEIBHMAN,R.F. Region 3, Chicago, Office of the Director. 78/11/09. 2pp. 94306.066
- --7812130209 IE Inspec ReptW50-315/78-31 & #30-316/78-29 on 781010 dur which no items of noncompliance were noted Major areas inspected incl:licenses action on IE Circular#78-08. LABLONBKIF. J. Region 3. Chicago, Office of the Director. 78/11/09. Spp. 94306:068.
- 7812050311 Forwards IE Bulletin#78-12A, suppl to IE Bulletin 78-12. W/encl ANG: 7811300055. KEPPLER: 0. Region 3. Chicago. Office of the Director. 78/11/24. ip. 94203:073.
- 7812050260 Forwards IE Bulletin#78-12e.suppl to IE Bulletin 78-12. H/encl ANO:7811300055. PAPPAB.H. Region J. Chicago. Office of the Director. 78/11/27. 2pp. 94202:142.
- 7812280047 Forwards IE Bulletin 78-14.

 KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/12/19.

 1P. 94084:323.
- R. Periodic operating reports & related correspondence
- 7812110137 Forwards monthly repts for July, Aug & Sept 1978 re fish

- 7810200053 Forwards Monthly Oper Rept for Sept 1978. SHALLER,D V. Indiana & Michigan Power Co. 78/10/10. 1p. 94412:214.
- --7810200036 Monthly Oper Rept for Sept 1978.
 OILLETT, N. T. Indiana & Michigen Power Co 78/10/03. 10pp.
 94412-215
- 7811210437 Forwards Monthly Oper Rept for Oct 1978. 8HALLER, D. V. Indiene & Michigen Power Co. 78/11/14. ip.
- --7811210438 Monthly Oper Rept for Oct 1978 GILLETT, M.T. Indiane & Michigen Power Co. 78/11/01. Spp. 94482:195.
- 7812200203 Forwards Monthly Oper Rept for Nov 1978. BHALLER,D. V. Indiane & Michigen Power Co. 78/12/14. 1p. 04149-041
- --7812200205 Monthly Oper Rept for Nov 1978.
 OILLETT, N. T. Indiana & Michigan Power Co. 78/12/04. 12pp. 94.62 262
- S. Reportable occurrences, LERs & related correspondence
- 7810180016 Forwards LERW78-064/03L-0.
 SMALLER, D. V. Indiana & Mithigan Power Co. 78/09/27. 19.
 94429-001
- --7810180018 LER#78-064/03L-0 on 780905: rad position indication for Rod C-9 showed deviation of greater that 12 steps from demand position. Caused by drift of signal conditioning module. Hodule recalibrated.
 RIBCH_ING.J. Indiana & Michigan Power Co. 78/09/27. 2pp. 94422: 002.
- 7810100044 Forwards LER#78-065/03L-0 & 78-066/03L-0.
 8HALLER, D. V. Indians & Michigan Power Co. 78/09/29. ip. 94418-142
- --7810100044 LER978-066/03L-0 on 780905:interlock on 650 ft level containment air lock failed to function during test, as interlock cable was too loose to operate locking machanism. Tension adjustment was added to maintenance prog. BROWN.M.B. Indiane & Michigan Power Co. 78/09/29. 1p. 94415:164.
- --7B1010006B LER678-065/03L-0 on 780901:viscosity of dissel lube oil was low during routine check due to fuel oil contamination: for fuel oil injection pumps & 1 fuel injectors were replaced. BROWN.H.S. Indiana & Michigan Power Co. 78/09/29. 1p. 94415:165.
- 7810310199 LER #78-071/03L-0 on 780926: during surveillance test on containment hydrogen skimmer recirculation for(2HV-CEO-1).46 ice condenser lower inlet doors opened, due to jammed actuator.
 RIBORING, J.L. Indiana & Michigan Power Co. 78/10/26. 2pp.
- 78101f0198 Forwards LER#78-067/03L-0 & LER#78-068/03L-0 SHALLER.D. V. Indiana & Michigan Power Co. 78/10/03. 1p. 94069:142.
- 7810180002 Forwards LER#78-067/03L-0 & LER#78-068/03L-0. SHALLER:D. V. Indiana & Michigan Power Co. 78/10/03. 1p.
- c-7810180004 LERW78-067/03L-0 on 780903: While in Mode 1 open condensate storage level reduced below limit of 175,000 gel due to closing of valve during leakage check. Level was returned to minimum requirements win 15 min from Unit 2 storage age LEASE, R. 9. Indiana & Michigan Power Co. 78/10/03. 1p.
- --7810190005 LER#78-068/03L-0 on 780705: It was discovered that APDMB rounds off the T(2) calculation using interper-arithmetic rather than real arithmetic w/resulting F2 calculations being non-conservative in top core. Engr raview underway. RISCHLING, J. Indiana & Michigan Power Co. 78/10/03. 2pp.
- 7810180027 Forwards LER#78-049/03L-0. & LER#78-070/03L-0. 8HALLER, D. V. Indiana & Michigan Power Co. 78/10/11. 1p. 94108:192.

- --7810180030 LERW78-069/03L-0 on 780913 While performing surveillance test on protec set 4 pressurizer pressure high-reactor trip bistable feiled to trip on simulated high pressure signal due to bad triac. Bistable was replaced.

 RIBCHLING, J. L. Indiana & Michigan Power Co. 78/10/11. 1p. 94148 1973
- 7810180032 LERB78-070/03L-0 on 780911: Air start line of 2A8 diesel wes found to be hot during load test due to loose piston bolt latting combustion vapors in air starting line. Check valve was replaced & engine retested satisfactorily.

 BROWN M.S. Indiane & Michigan Power Co. 78/10/11. 1p. 94168:194.
- 7810230177 Forwards LER#78-063/03L-1 & #78-072/03L-0. SMALLER D. V. Indiana & Michigan Power Co. 78/10/18, 1p.
- --7810230183 LER#78-072/03L-0 on 780926: During rapid load reduction fr 100X to 20X per pressurizer press reduced below Tech Spec. Recovery w/in allowed time. Cause was rapid per reduction. Tech Spec allows per increase transient not decrease. LEASC.R.S. Indiana & Michigan Power Co. 78/10/18. ip. 94167:091.
- --7810230185 LERW7B-063/03L-1 on 780820:While test closing turbins vel at 99% puristesm flow was reduced causing reactor coolant temp to increase & pur to decrease, both inviolation of Tech Spec due to testing valve at too high pur level. LEASE.R. S. Indiane & Hichigan Power Co. 78/10/18. 1p. 94167:090
- 7810270309 Forwards LERW78-073/03L-0 & LERW78-074/03L-0. 8HALLER, D. V. Indiana & Mithigan Power Co. 78/10/20. 1P. 94089: 092
- --T810270314 LERM78-073/03L-0 on 780922:Automatic Control adjustment experienced pressure reduction below Tech Spec 3.2:56(2220 P8IA)due to error in interpretation of calibr procedure. Operator closed valve. Pressure returned to normal. LEASE.R. B. Indiena & Michigan Power Co. 78/10/20. 2PP. 94087:093.
- --7810310155 LERM78-074/03L-0 on 780921: bistables returned to normal introprocessition w/o dynamics of lead-leg portion of unit being calibrated Caused by improper communications.
 RISCHLING.J. Indiana & Michigan Power Co. 78/10/20. 2pp. 94089: 095.
- 7810310190 Forwards LER #78-071/03L-0 & #78-075/03L-0. 8HALLER, D. V. Indiana & Michigan Power Co. 78/10/26. 1p. 94090: 277.
- 7811020252 On 781030, it became necessary to isolate deluge valves to facil Drumming Room & Naw Fuel Receiving Area as result of repeir on Fire Sys headers. Follow up rept will be issued 781010.

 BHALLER, D. V. Indiana & Michigan Power Co. 78/10/30. 1p. 94247:125.
- 7811090151 Forwards LER#78-076/03L-0 & LER#78-077/03L-0. BHALLER.D.V. Indiana & Michigan Power Co. 78/11/01. 1p. 94045:011.
- ---7811090153 LER#78-076/03L-0 on 781003; surveillence tests on train-8 solid at protec eye showed that several switch positions were bad, Caused by bad universal logic card. Card replaced & sys returned to syc.

 #### RECHLING.U. Indiana & Michigan Power Co. 78/11/01. ip. 94043-012.
- --7811090158 LER#78-077/03L-0 on 781005:main turbine stop valves "C" i "D" closure limit switches found inoperable. Caused by excessive vibration of stop valves due to poor design. RISCHELING. J. Indiana & Michigan Power Co. 78/11/01. 1p. 94043:013.
- 7811140210 Forwards LERW78-034/03X-2.W78-078/03L-0 & W78-079/03L-0. SHALLER,D. V. Indiana & Michigan Power Co. 78/11/08. 1p. 94441: 355
- --7811140218 LER878-034/03X-2 on 780515: hydrogen skimmer recirculation fams starting times were found to be 10 minutes, 6 seconds for 2HV-CE02 & 10 minutes, 5 seconds for 2-HV-CE02 & 10 minutes, 5 seconds for 2-HV-CE01. One athuts T8 tolerance for Unit 2 & agestate are of 0-60 minute range. RISCHLING. J. Indiana & Michigan Power Co. 78/11/08. 2pp. 94084:352.

N226 LER 7B-034/031-0:on 781010, menual isolation valve in flow circuit of turbine driven aux feed pump found unlocked in. Instructions issued to keep a manual valve in test closed & locked except when testing LR.S. Indiana & Michigan Power Co. 7B/11/08 2pp. 1294.

200 LER 78-079/03L-0: on 781019, engine failed to start while whing to prove operability of 2AB Emergency diesal in to remove 2CB diesel from svc. Cause for apparent lack rel could not be determined.

33. D. G. Indiana & Michigan Power Co. 78/11/08. 1p. 8: 356.

77 Forwards LER#78-080/05L-0.LER#78-081/03L-0.LER#78-082/03L-0./8-083/03L-0.
1. D. V. Indiana & Michigan Power Co. 78/11/22. 1p.

2181 LERW78-080/03L-0 on 781024; during test of salid at protection A.3 logic test positions tested unsatisfactorily, d by failure of a universal logic card & a test card, subsequently replaced.

WN.T.P. Indiana & Michigan Power Co. 78/11/22. ip. 3.100.

DIBS LERM78-081/OSL-O on 781023; boron injection tank boron intration found to exceed fech Spec limit. Caused by it lack of effective mixing from a previous boric acid tion addition or by faulty sampling methods.

LPH. J. M. Indiana & Michigan Power Co. 78/11/22. 2pp. 3:101

DIBB LERW7B-082/03L-0 on 7B1025: during leak rate test on the 650 elevation airlock doors, noted that leakage rate eded acceptable limits. Caused by inadequate seal of floor, Switch indicator subsequently readjusted.

AN.T.P. Indiana & Michigan Power Co. 7B/11/22. 2pp.

0193 LER#78-083/03L-0 on 781023: noted that cycling times for a operability test after maintenance not recorded when ses stroked. Caused by defective document control for ing changes to instructions.
4.R.S. Indiane & Michigan Power Co. 78/11/22. 1p. 3: 105

10 Confirms 781128 verbal rept.While investigating cause of coming from upper containment spray header: 2 lower mant spray check valves were found installed rds. Rept will be submitted 781212.
3.D. V. Indiana & Michigan Power Co. 78/11/28. Ip.

49

51 Forwards LERM78-084/03L-0 & M78-085/03L-0. R.D. V. Indiana & Michigan Power Co. 78/12/01. 1p.

0068 LER#78-085/00L-0 on 7Bi106: during routina surveillance test ins driven auxiliary Feedwater pump did not start. Caused ener diode which had shorted at electronic overspeed tor, resulting in constant overspeed trip signal.

MAN.T.P. Indiana & Michigan Power Co. 78/12/01. 1c.

7:349.

0070 LERM78-084/O3L-O on 781101; rod H-8 rod position remained at steps after control bank D position reduced from 220 to steps. Ceused by drift for H-8 signal conditioning le. Was reset to correct position.
-LING.J.L. Indiana & Michigen Power Co. 78/12/01. ip. 7:350.

86 Forwards LER#78-086/03L-0. 4,D.V. Indiana & Michigan Power Co. 78/12/04. ip. 785

0089 LER#78-086/03L-0 on 7807R3; snubber#63 was found to be ried on its horizontal exis during inspec due to loose end locknut Snubber removad; tested & reinstalled. N.M.S. Indiana & Michigan Power Co. 78/12/04. ip. 8: 354.

19 Forwards LER#78-087/03L-0 & #78-088/03L-0.
R,D.V. Indiana & Michigan Power Co. 78/12/06. 1p.
323.

0120 LER#78-087/03L-0 on 781110: Containment integrity was broken issessembling an NESM check valve while reactor plant was ode 3. Early start of repair has been reviewed by onnel to prevent future mistake, 5.8.8. Indiana & Michigan Power Co. 78/12/06. 1p. 6:324.

- --7812080122 LER#78-088/03L-0 on 781125: One RHR sub-sys made inoperable w/reactor in Mode 2.less than 5% pur, due to essumption that plant was still in Mode 1 at greater that 5% pur. New safety sys unit start-up instructions issued.

 LEASE, R 9 Indiane & Michigan Power Co 78/12/06 ip. 94106-325.
- 7812120178 Forwards LER#78-089/03L-0 BHALLER, D. V. Indiene & Michigan Power Co. 78/12/07 ip. 94276.399.
- --7812120186 LER#78-089/03L-0 on 781109 emergency load reduction resulted in axial flux difference outside target band Caused by loss of all generator bus duct cooling.

 RAMDOLPH.J.M. Indiana & Michigan Power Co. 78/12/07. 1p. 94276.360
- 7812180207 Forwards LER#78-090/01T-0. 8MALLER.D. U. Indiana & Michigan Power Co. 78/12/12. 19. 94363:094.
- --7812180212 LERW78-090/01T-0 on 781121: \(\omega/RHR\) in open, leakage was noted from some upper containment spray noriles, caused by check valves CTB-127E & CTB-127H being installed backwards.
 RISCHLING, J. L. Indiena & Michigan Power Co. 78/12/12 3pp. 9436-055
- 7812270252 Forwards LER#78-091/03L-0; #78-092/03L-0/: #78-093/03L-0; #78-094/03L-0; #78-095/03L-0; #78-095/03L-0; #78-097/03L-0; #78-098/03L-0; #78-098/03L-
- --7812270235 LER#78-091/03L-0 on 781125: source range neutron flux channel N-G1 inoperable. Caused by unclean connectors on high voltage cable & signal cable at pream.

 RISCH_ING.J.L. Indiana & Michigan Power Cp. 78/12/20. 1p. 94017:171.
- --7812270260 LERW78-092/03L-0 on 781125: reactor coolant average temp on 2 of 4 loops below Tech Specs of 941P resulting in P-12 permissive being actuated. Caused by turbine test w/minimum steam dump, increase steem flow caused temp drop. RANDOLPH.J. M Indiana & Michigan Power Co. 78/12/20. 1p. 94017:172.
- --7812270264 LERW78-093/03L-0 on 781125:rod position indication(RPI)for control rod H-B exceeded 12 step limit. Caused by H-B drift. RISCRLING.J.L. Indians & Michigan Power Co. 78/12/20. 1p. 94017.172
- --7812270268 LER#78-094/03L-O on 781202: halon eys for cable epreading area was discharged & therefore imperable. Caused by operator error.

 SMITH, J. K. Indiana & Michigan Power Co. 78/12/20. 1p. 94017: 174.
- --7812270272 LERM78-095/03L-0 on 781206: while decreesing turbine load. reactor coolant average temp exceeded 576.2 F. Caused by faulty drain values on 5-A heater creating unstable feedwater control & turbine load.

 MURPHY.C.E. Indiana & Michigan Power Co. 78/12/20. ip. 94017:175.
- --7812270277 LERM78-096/03L-0 on 781209; during rapid load reduction from 100% to 88%, axial flux difference went outside target band. Air lask on "A" condenser vacuum breaker caused increase in back pressure on main condenser.

 8 Indiana & Michigan Power Co. 78/12/20. 1p. 94017:176.
- --7812270282 LER#78-097/03L-O on 781209: during rapid pur raduction from 100% to BBX, pur pressurizer pressure reduced below tech spec limit of 2220psia. Caused by rapid pur reduction because of decreasing vacuum on main turbine/generator.

 KEITH.R.8. Indiena & Michigan Power Co. 78/12/20. lp. 94017:177.
- --7812270286 LER#78-098/03L-0 on 781010: axial flux difference(AFD) monitoring alarm point was discovered to be set at 103X vice BAX. Caused by AFD alarm trip point being reised for testing purposes & not returned to correct point.

 BEILMAN, T.P. Indiane & Michigan Power Co. 78/12/20. 2pp. 94017:178.
- 7812290083 Confirms 781224 verbal rept re brief inoperability of control room pressurization fans due to Fire Protec logic preventing fans from starting Followup rept will be submitted 780106.
 BHALLER.D. V. Indiana & Michigan Power Co. 78/12/27. ip. 94190: 107.

- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 1
 F. Becurity, medical, emergency & Pire protection plans
- 7810310271 Forwards Suppl 1 to Rev of Calvert Cliffs Modified Amended security plan re temporary security arrangement during constr of new eye hidg. Encl withheld from public disclosure (ref 10CFR2 790).

 LUNDVALL, A.E. Baitimore Gas & Electric Co. 78/10/17. 3pp. 94088.238
- 7810230162 Forwards add1 info re firs protec study in response to 780830 ltr. Covers trasient combustibles, dealin basis fire methodology, conduits & covered cable trays & determination of burning rates.

 LUNDVALL, A. E. Baltimore Que & Electric Co. 78/10/20. 39pp. 94164: 208
- 7811130375 Notifies of completion of review of temporary security arrangements to be established during construct of new avoidid. Changes do not decrease security & no action is required.

 OALTANIB, M.J. Reactor Bafety Branch (Pre 791030). 78/10/30. ip. 74008:077.
- 7B11120155 Responds to 7B1031 NRC request re requirements for non-copersonnel access to facility. Encis outline training requirements for antry to controlled area & escurity requirements for admittence.

 LUNDVALL, A E Beltimore Oas & Electric Co. 78/11/01. 7pp. 94270:167
- 7811150189 Forwards copies of Sev 4 of Mod Amend Security Planincluding additions verbally requested by MJ Galtanes & reflecting impending organizational changes. Info withheld pursuant to 2.790. LUNDVALL, A. E. Baltimore One & Electric Co. 78/11/06. 1p. 94242:338.
- 73:1170197 Announces another review of NRC guidelines re facil Fire Protec Prog will be performed because review may have been misleading. Next response will be submitted no later than 78:1229.

 LUNDYALL, A. E. Beitimore Gas & Electric Co. 78/11/14. 1p. 94048:294.
- 761R180265 Notification of 781221 meeting in Bethesda w/802E re fire protec review & instru cable fire retardant properties. CONNER.E.L. Operating Reactors Branch 4 (Pre 790625). 78/12/07. 3pp. 94366:346.
- P. Operating license stage documents & correspondence
- 7811270166 Forwards "Chesapsake Bay LNO OPLAN." Plans establish procedures to ensure safe arrival transit & departure of vessels carrying lquefied natural gas on Chesapsake Bay. BCHUMACHER.K. B., THOMPSON.C.R. Coast Quard, Transportation, Dept. of. 78/03/09. 42pp. 94223:207.
- 7810250143 Notifies NRC per iOCFR71.12b of intent to use package AN-1008(USA/9809/A)supplied by Hittman Nuc Dev Corp for shipment of radioactive matls.

 LUNDVALL, A. E. Baltimore Qas & Electric Co. 78/10/05. 1p.
- 7811030079 Requests add1 info re radiat dose to control room operators following postulated LOCA Analysis of postulated event finds add1 info is req. REID.R.W. Operating Reactors Branch 4 (Fre 790625). 78/10/10. 3pp. 02723:032.
- 7811010233 Notifies util of 781018 meeting re implementation of Intl Atomic Energy Agency Befaguards Requirements pursuant to proposed "Agreement Between the UBA % Intl Atomic Energy Agency for Appl of Bafaguards in the UBA." REID.R.W. Operating Reactors Brench 4 (Pre 790625). 78/10/13. Spp. 94372:074.
- 7810230148 Forwards suppl & corrected data to be included in rept on test conducted re reactor containment bidg integrated leak rate.

 LUNDVALL, A.E. Baltimore Oas & Electric Co. 78/10/16. 4pp. 94164: 278.
- 7810260202 Responds to 780502 NRC 1tr re add1 infd to complete review of emend request dtd 780727. Also forwards rept on containment tendom surveillance lift-off acceptance criteria which is basis for several responses to NRC questions. LUNDVALL, A. E. Baltimore Gas & Electric Co. 78/10/20. Sipp.

- 7811170121 Requests 1 change & 1 addition to Svc 1ist, DLSCN.R.C. Baltimore Ges & Electric Co. 78/11/09, 1p. 94048.277.
- 781120020A Requests amend to oper lic tech specs re:limiting merimua boron concentration in SII's & RWI's to 2200ppm.ellow lesser shutdown copiling flow when reactor coolent loop partially drained & add loss of field trip to 00 surveillance. LUNDVALL, A. E. Daltimore Das & Electric Co. 78/11/13. 30pp. 94292, 049.
- 7B11R40214 Remits Lic amend for for Class 4 & Class 1 amend involving 11 proposed changes to open lic.

 OLSON.R.C. Beltimore Gas & Electric Co. 7B/11/15. 1p. 94463:360.
- 7B12150106 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out matl. Wencl Registration Form & List of Locations.

 MILLER, J. R. Assistant Director for Site & Rafeguards (Pre 791030). 7B/11/15. 5pp.
- 7812190008 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PHR's(NUREO-0472)& "Preparation of Radiological Effluent Tech Specs for Nuc Per Flants" (NUREO-0133).
 0811889. B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. App. 94214:266.
- 7811240193 Forwards response to NRC request for add1 info re analysis of potential radioactive dose to control room operators following loss-of-coolant accident.
 LUNDVALL.A. E. Baltimore Gas & Electric Co. 78/11/20. 22pp. 94498:279
- 7811300046 Informs BOE that NRC has contracted w/Mountain West Res Inc to undertake a earles of post-licensing studies of nuc pur stations. Bitudies will analyze socioacon impacts which occurred during conetr & post-constr periods of each plant. DEYCUNO. R. C. Division of Bite Bafety & Environmental Analysis, 78/11/20. 2pp. 94071:049.
- 7B12070161 Notice of asminar on 7B1208 on new Model Radiological Effluent Tach Spece for nuc per plants. Requests advance submission of seminar specific questions. W/encl Seminar Info Sheet Proposed Agenda & maps. QRIER, B. H. Region i. Philadelphia, Office of the Director. 70/11/21. Spp. 74370:168.
- 7GI2140379 Forwards discussion topics for meeting to be held on 7BI212. Furpose of meeting is to obtain Info for use in "Reactor Safety Bludy Methodology Apris Prog" res proj. REID.R.H. Operating Reactors Branch 4 (Pre 770625). 7B/11/28. App. 03558:128.
- 7812130293 Aske util to reexamine 780725 request for exemption from 10CFR21 in 11ght of 781019 amend to Part 21. DENTON-H.R. Office of Nuclear Reactor Regulation, Director, 78/11/29, 2pp. 94294:360.
- 7812150079 Discusses possible dangers of LOCA in containment surging during normal plant open. Requests either commitment to limit pureling or justification for continuing. W/encl ANC: 7812080207.
 REID.R.N. Operating Reactors Branch 4 (Pre 790625). 78/11/29. 69p. 9421: 295.
- 7812280140 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or snforcement action will result. DAVIB. J. 9. Office of Inspection & Enforcement, Office of the Director. 78/12/06. Spp. 94310:352.
- 7819270384 Forwards into re forthcoming 781920 meeting to discuss fuel demonstration prog related to subj facils' transitions to 18 month cycles. CONNER.E.L. Operating Reactors Branch 4 (Pre 790695). 78/12/12. 2pp. 94228: 292.
- 7811090061 Responds to 780731 ltr on Liquid Natural Que Contingenty Plans spent fuel storage capacity & shallow water draft trials of LNO tankers. Whenci itr from Coast Quard that maneuvers near facil will not be silowed w/gas.

 REID.R.W. Operating Reactors Branch 4 (Pre 790625), 78/10/18. 3PP. 94040:119.
- Q. Inspection reports, IE Bulletins & correspondence

- --7811090096 IE Inspec Repts#50-317/78-23,#50-318/78-17 on 780822-26 during which no items of noncompliance were noted. Major areas inspected included monthly oper status repts facility turns timplementation of 10CFR21 requirements. UH-NSON. D. F., KEINIG.R.R. Region 1, Philadelphis, Reactor Operations Nuclear Support Branch. 78/09/18 3pp. 94399:074.
- 7810170026 Forwards IE Bulletine78-12: "Atypical Weld Material in Reactor Pressure Vessel Welds" requesting action w/in 60 days & list of IE Bulletins issued in 1978. GRIER.B.H. Region I, Philadelphia, Office of the Director. 78/09/29. 6pp. 94241:352.
- 7811060188 Forwards IE Circuler#78-17. (See AND: 7810230821; Docket e50-133, 781013.)
 GRIER: 8, M. Region 1, Philadelphia: Office of the Director. 78/10/13. 1p. 94489: 158.
- 7811090025 Ack receipt of itr informing NRC of steps taken to correct violations noted during inspec#30-317/78-22 & #50-318/78-16.

 MNITH, 0. H. Region I. Philadelphia, Fuel Facility & Materials Bafety Branch. 78/10/26. 1p. 94040:025.
- --7811090030 Responds to 780813 NRC ltr re violations noted in Inspec Repte850-317/78-22 & 30-318/78-16. Corrective actions: Red-Chem technicions properly reinstructed: CCI-6078 rev by 781201:atr supply maint procedures written by 781101. LLNDVALL.A E. Beltimore Oas & Electric Co. 78/11/08. 3pp. 94040: 030.
- --7811090032 Forwards IE Inspec Rept#50-317/78-22 & #50-318/78-16 on 780808-18 & Notice of Violation. CROCKER, H. W. Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch. 78/09/13. 2pp. 94040:031.
- --7811090034 Notice of Violation from inages on 780808-ii. CROCKER. H. H. Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch. 78/09/i3. 2pp. 94040:033.
- --781109003B IE Inspec Rept#50-317/78-22 & #50-318/78-16 on 780808-11 during which 3 items of noncompliance were noted:radiat protec procedures:Procedure CCI-607B not incorp into training:NURE9-0041. Section 9. B procedures ignored.
 HHITE.J. R. SERABIAN.J.A. KNAPP.P.J. Region 1. Philadelphia, Fuel Facility & Materials Sefety Brench. 78/09/12, 11pp. 94040:035.
- 7811140045 Requests that util prepare answers to encl questions on insvc test prog for meeting on 781108-09 at Calvart Cliffs, MO & formally document responses by 781127. REID.R W. Operating Reactors Branch 4 (Prs 790625). 78/10/31. Gpp. 94420:326.
- 7812010345 Forwards licensee performance evaluation for Region 1.No operating reactor in Region 1 considered to have either abnormal or unusual safety contern. ORIER.B.H. Region 1, Philadelphia. Office of the Director. 78/11/01. 4pp. 00002:259.
- 7811150265 Ack receipt of 781017 ltr informing NRC of steps taken to correct violations noted during inspec#30-317/78-26 & #50-318/78-20.

 SRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/11/02. 1p. 94273:229.
- --7811150269 Responds to 781006 NRC ltr re violation noted in Inspec Rept 650-317/78-26 & #50-318/78-20. Corrective actions: informing control room operators of requisite procedures.

 LUNDVALL.A.E. Beltimore Gas & Electric Co. 78/10/17. 2pp. 94273;230.
- --7811150272 Forwards 1E Inspec Rept#50-317/78-26 & #50-318/78-20 on 780912-15 & Notice of Violation.
 BRUNNER, E.U. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/06. 2pp. 94273:232.
- --7811150274 Notice of Violation from inspec on 780912-13. BRUNNER, E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 78/10/06, 1p. 94273;234.
- ~~7811150276 IE Inspec Rept#50-317/78-26 & #50-318/78-20 on 780912-15 during which I item of noncompliance was noted: failure to comply w/limiting conditions for open.
 JONBON, D. F. Region I, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/06. 12pp. 94273:235.
- 7811290220 Forwards IE Circular #78-18, "UL Firs Test. "W/encl ANO: 7811150002.

 9RIER, B. H. Region i, Philadelphia, Office of the Director. 79/11/06. ip, 94237: 298.

- 7B12010291 Ack receipt of 7B1017 itr informing NRC of steps taken to correct violation noted during inspec#50-317/78-25 & #50-318/78-19
 BRUNNER.E. J. Region i, Philadelphia, Office of the Director.
- --7612010295 Responds to 760928 NRC ltr re violations noted in Inepec Reptem50-917/78-25 & #30-318/78-29. Corrective actions: 219 Safety Injection Tank drained to spec level & personnel reprimanded. LUNDVALL, A.E. Baltimore Oes & Electric Co. 78/10/17. 2pp. 94417: 267.
- --7812010296 Forwards IE Inspec Repts#90-317/78-25.#50-318/78-19 on 780905-08 & Notice of Violation. BRUNNER.E. J. Region i. Philadelphia. Office of the Director. 78/09/28. 2pp. 94417:269.
- --7812010298 Notice of Violetion from Inspec on 780905-08. ** Region 1. Philadelphia, Office of the Director. 78/09/28. 1p 94417:271.
- --7812010303 [E Inspec Repts#50~317/78-25 & #50~318/78-19 on 780905-08 during which 2 items of nuncompliance were noted: failure to conduct Typa B tests w/in 2 years, failure to follow approved procedure.
 HIGGINS, J. C. . SMITH, T. H. . WONO, H. J. Region 1, Philadalphia, Defice of the Director. 78/09/28. 12pp. 94417:272.
- 7812290028 Forwards IE Inspec Repts#50-317/78-30 & 50-318/78-27 on 781023-26 during which no items of noncompliance were noted. BRUNNERE J. Region i. Philodelphia, Reactor Operations Nuclear Bupport Branch. 78/11/13. 2pp. 94208:040.
- --7812270034 1E Inspec Repts#50-317/78-30 & #50-318/78-27 on 781023-26 during which no items of noncompliance were noted. Major areas inspected inclished logs & records & licensee followup actions concerning previous inspec findings. JCHMBON, D.F., KEIMIO, R.R. Region i. Philadelphia, Office of the Director. 78/11/09. App. 94208:042.
- 7812110105 Responds to IE Bullstine78-12 re reactor pressure vessel welds. Requests permission to deal w/problems on a generic rather than a plant spacific basis.
 LUNDVALL.A.E. Baltimore Cas & Electric Co. 78/11/17. 2pp. 94329-062
- 7812080125 Responds to 781031 & 761124 NRC ltrs requesting add1 info r pump & valve testing insvc proge. H/encl oversite drawings available in Central Files only. LUNDVALLIA.E. Baltimore Gas & Electric Co. 78/11/20. 9pp. 94106: 326.
- 7B12190125 Forwards IE Bulletin#7B-1RA, suppl to IE Bullstin#7D-1R. W/encl AND: 7B11300055. GRIER, B. H. Region 1. Philadelphia. Diffice of the Director. 7B/11/24. 1p. 94212: 159.
- 7812060242 Forwards IE Inspec Repts#50-317/78-29 & #50-318/78-26 on 780410-3 during which no items of noncompliance were noted. BHITH, 9.H. Region is Philadelphia. Fuol Facility & Materials Bafett Oranch. 78/11/25. 2pp. 94372:340.
- --7812060244 IE Inspec Repts#50-317/78-29 & #50-310/78-26 on 780410-3 during which no items of noncompliance were noted Major areas inspected incl: effluent sample. KGTTMI, J.J. 1870HR, J.P. Region I. Philadelphia, Fuel Facility & Materials Sefaty Branch. 78/10/24, App. 94372:342.
- 7812080096 Discusses ASME Boiler & Pressure Vessel Code Requirements for Insuc inspec of Nuc Components Requirement for piping examination is burdensome because extra teams must be utilized who will be unnecessarily exposed to radiat. LUNDVALL.A. E. Baltimore Gas & Electric Co. 78/12/05. 2pp. 94107:296.
- R. Periodic operating reports & related correspondence
- 7810230178 Forwards Monthly Oper Rept for Bept 1978.
 MERSON, B. D. Baltimore Gas & Electric Co. 78/10/15. ip. 94164:10
- --7810230182 Monthly Oper Rept for Bept 1978.

 ** Baltimore Qas & Electric Co. 78/10/15. 20pp. 94164:105.
- 7811240215 Forwards Monthly Oper Rept for Oct 1978.
 MERBON, B. D. Baltimore Gas & Electric Co. 78/11/15. Ip. 94473:33

- --7811240217 Monthly Oper Rept for Oct 1978. MRRSON, B D. Baltimore Que & Electric Co. 78/11/15. 18pp. 94473 134
- 7812220076 Forwards Monthly Oper Rept for Nov 1978
 MERBON, B.D. Baltimore Gas & Electric Co. 78/12/15. ip 94343.880
- --7812220077 Monthly Oper Rapt for Nov 1978. MERBON, B. D. Baltimore Gas & Electric Co. 78/12/15. 18pp. 94343:281
- 8. Reportable occurrences, LERs & related correspondence
- 7B1010005) Forwards LER#7B-043/04T-0.
 DBUQLASB.R M Baltimore Gas & Electric Co. 7B/09/25. ip. 94032:170.
- --7810100058 LERM78-043/04T-0 on 780912: approximately 6200 Manidia (Atlantic silversides) were collected batwarn 0900 & 1000 hours from U-1 travelling screens. Studies after 1000 hours did not reveal any unusual numbers of implinged fish. # Baltimore Ose & Electric Co. 78/09/26. 3pp. 94032:171.
- 7910110169 Forwards LER#78-023/03L-0 DOUGABB,R M Baltimore Gas & Electric Co. 78/10/06, 1p. 94069-093
- --TB10110174 LERM7B-023/03L-0 on 7B0906: failurs of containment atmosphere particulate monitor due to moisture from condensation & some corrosion; caused by high ambient containment humidity & sub-sequent condensation inside detector pig.

 CARROLL, J. T., MyERNICKI, M. J. Baltimore Gas & Electric Co. 78/10/06 ip 94057:074
- 7810130173 Forwards LER#78-046/04L-0.
 BOUGLASS,R M. Daltimore Gas & Electric Co. 78/10/09. 1p. 94003-032.
- --7810130176 LER#78-046/04L-0 on 780708: radioactive liquid waste release rate exceeded 1.25 Curies per quarter on 780708 Change has been submitted to change Tech Beccion 4.6.2c to requirements in Section 2.3.4.7.
 CRINIOAN.P.T. Rallimore Gas & Electric Co. 78/09/12. ip. 94003-023
- 7810270235 Forwards LERW78-045/03L-O. DOUGLABS, R. M. Daltimore Oas & Electric Co. 78/10/20. ip. 94057: 003.
- --7810270240 LER#78-045/03L-0 on 780926: Voltage deviated greater than 1.0 volts for channel 70 from other channels caused by nonlinear isolation transformer i-E/E-1013A w/ssceesive A/C ripple & output voltage .2V high.

 DAVIB.B. H. MIERNICKI, M. J. Baltimore Oas & Electric Co. 78/10/20. 2pp. 94039:004
- 7810310102 Forwards LERW78-047/03L-0. DDUGLABB, R.M. Baltimore Gas & Electric Co. 78/10/20 ip. 94092:134.
- --7810310:05 LER 78-047/03L-0: on 781010: 13KV Breaker 252-2104 tripped open-de-maergizing #21 12KV evo bus. Caused by signal of unknown source.

 DAVIE: 8. M. . ROMNEY: K. M. Baltimore Gas & Electric Co. 78/10/20. 1p. 94092:135.
- 7810310197 Forwards LER#78-044/03L-0.
 DOUGLABB, R.M. Baltimore Qas & Electric Co. 78/10/20. 1p. 94090: 305.
- --7810310200 LERH78-044/03L-0 on 7809R3: during post-maint test on spent fuel pool 12.exhaust for the flow rate was found to be less then requdue to discharge damper leakage.

 DAVIS.8. M.: MERNICKI.M.J. Beltimore Oas & Electric Co. 78/10/20.

 Rpp. 94090:306.
- 7811010113 Forwards LER878-048/03L-0. DOUGLASS.R.M. Baltimore Qua & Electric Co. 78/10/26. ip. 74/288: 033.
- --7811010116 LER#78-048/03L-0 on 781017; while moving group 5 CEAs to control ASI, CEA#36 dropped into core from full-out position, caused by spike in the 15 volt pur supply. Design mod(FCR78-72) is under review to improve sys reliability.

 DAVIS, S. M. MERNICKI, M. J. Baltimore Gas & Electric Co. 78/10/26.

 1p. 94286: 054.

- 7811030112 Forwards LER#78-050/04L-0.
 DDUCLA88 R M. Baltimore Cas & Electric Co. 78/10/27. 1p. 09723:315
- --7811030117 LERM78-050/04L-0 on 781023 excessive release of redirective liquid seftuents caused by clogged strainer which put Miscellaneous Weste Filters & Ton Exchangers out of svc. CRINIOAN.P.T. Baltimore Que & Electric Co. 78/10/27, 1p. 02723-316.
- 7811210407 Forwards LERM78-049/03L-0. RUBBELLL B. Baltimore Oas & Electric Co. 78/11/16. 1p. 94463 121.
- --7811210409 LERW78-049/03L-0 on 781020 pump for radiat monitors seized, perhaps due to graphite particles from pump being deposited in bearings. A normal end of life failure. Code Pump Model&b. DAVIS.8 M., MIERNICKI.M J. Beltimore Ges & Electric Co. 78/11/16. 19. 94483:122.
- 7811300196 Forwards LERW78-051/03L-0. RUSBELL. B. Daltimore Cas & Ejectric Co. 78/11/17. ip. 94076.360.
- --7811300199 LERM78-051/03L-0 on 781031: solenoid valve 1-8V-4043 for main steam isolation valve hydraulic accumulators was leaking due to failure of 1 of 4 "0" ring seels. Cause of ring failure unknown. All 4 seels replaced & valve raturned to svc. DAVIG.8. M., WATKING, K. 8. Geltimore Qes & Electric Co. 78/11/17. 1p. 94076:361.
- 7811290264 Forwards LERM78-052/03L-0 RUSBELLL D. Baltimore Gas & Electric Co. 78/11/84. ip. 94270:101.
- --7811290267 LER#78-052/OSL-0 on 781103: in routine surveillance test, if auxiliary feed pump was tripped per procedure & open was unable to reset throttle valve due to binding. Assembly was freed upon lubrication of stem & nut.

 DAVIB.8.M., ROMNEY.K.M. Deltimore Cas & Electric Co. 78/11/24.
 ip. 94270: 102.
- 7812130189 Forwards LER#78-053/03L-0. RUBERLU.L.B. Saltimore Oas & Electric Co. 78/12/07. ip. 94308:022.
- ---TB12130194 LER#78-053/03L-0 on 781113: during normal open the containment particulate radioactivity monitor failed low at 1110. Caused by disconnection of signal cable to monitor. Cable connected & monitor returned to 8vc. GRROUL, J. T., MIERNICKI, M. J. Daltimore Gas & Electric Co. 78/12/07. 1p. 94306:023.
- 781220026: LERe79-054/0ix-0 on 7812:3: reactor was made critical w/ii component cooling heat axchanger out of svr & ii saltwater sub-say partially drained. Caused by personnel error. CARROLL J. T. Baltimore Qas & Electric Co. 78/12/14. 1p. 94207:093.
- DOCKET 30-318 CALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2
 F. Security, medical, emergency & fire protection plans
- 7811170197 Announces another review of NRC guidelines re facil fire Protec Prog will be performed because review may have been misleading. Next response will be submitted no later than 781229.

 LUNDVALL, A. E. Baltimore Cas & Electric Co. 78/11/14. 1p. 94046.294.
- 7810310271 Forwards Suppl 1 to Rev of Calvert Cliffs Modified Amended security plan re temporary security arrangement during constr of new eve bldg. Encl withheld from public disclosure (ref 10CFR2, 790).

 LUNDVALL, A. E. Baltimore Cas & Electric Co. 78/10/17. 3pp. 94088-238
- 7810230162 Forwards add1 info re fire protec study in response to 780800 ltr. Covers trasient combustibles design basis fire methodology, conduits & covered cable trays & determination of burning rates.

 LUNDYALL, A. E. Beltimore Que & Ejectric Co. 78/10/20. 39pp. 94144: 208
- 78iii30375 Notifies of completion of review of temporary security arrangements to be established during constr of new evoluted. Changes do not decrease security & no action is required.

 QAITANIB.N.J. Resector Sefety Branch (Pre 791030). 78/10/30. \$5.

- 7811150155 Responds to 781031 NRC request re requirements for non-coparsonnel access to fecility Encls outline training requirements for entry to controlled area & security requirements for admittance. LUNDVALL.A.E. Baltimore Gas & Electric Co. 78/11/01. 7pp. 94270: 167.
- 7811190189 Forwards copies of Rev 4 of Mod Amend Security Plan, including additions verbally requested by MJ Gattanas & reflecting impending organizational changes. Info withheld pursuant to 2.790.
 LUNDYALLIA.E. Baltimors Gas & Electric Co. 78/11/06. 1p. 94242:338.
- 7812180265 Notification of 781221 meeting in Bethesda w/80%E re fire protec review & instru cable fire retardant properties. CONER.E.L. Operating Reactors Branch 4 (Pre 790625). 78/12/07. 3pp. 94365:346.
- P. Operating license stage documents & correspondence
- 7811170121 Requests 1 change & 1 addition to Byr list. OLBON-R. C. Baltimore Ges & Electric Co. 78/11/09. ip. 94048:277.
- 7811270166 Forwards "Chesapeake Bay LNG OPLAN." Plans establish procedures to ensure safe arrival transit & departure of vessels.carrying liquefied natural gas on Chesapeake Bay. 8CHMACHER.K.B., THOMPSON.C.R. Coast Guerd, Transportation, Dept. of. 78/03/09. 42pp. 94223:207.
- 7810290143 Notifies NRC per 10CFR71.12b of intent to use package AN-10081UBA/9809/A)supplied by Hittman Nuc Dev Corp for ahignent of radioactive matis.
 LUNDVALL,A. E. Baltimore Gas & Electric Co. 78/10/05. 1p.
- 7810170162 Forwards non-proprietary responses to questions reised in ltr from NRC of 780908 re reload appl.

 ODREJ.W. Baltimore Qas & Electric Co. 78/10/06. ip. 94236:214.
- 7811030079 Requests add1 info re radiat dose to control room operators following postulated LOCA Analysis of postulated event finds add1 info is req.

 REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/10/10. 3pp. 02723:332.
- 7811010233 Notifies util of 781018 meeting re implementation of Intl Atomic Energy Agency Safeguards Requirements pursuant to proposed "Agreement Between the USA & Intl Atomic Energy Agency for Appl of Bafeguards in the USA."
 REID.R.M. Operating Reactors Branch 4 (Pro 790625). 78/10/13. 2pp. 94392:074.
- 7810180073 Forwards supplementary info re Cycle 2 Reload Appl. Encl contains proprietary info & is w/held. LUNDYALL. A. E. Baltimore Gas & Electric Co. 78/10/16, 48pp.
- 7810230246 Enc1 suppl info & changes to reload eppl requested in 781013 NRC ltr.
 LUNDVALL.A.E. Beltimore Ges & Electric Co. 78/10/17. 3pp.
- 7811030076 Forwards AmendMiB to Facil Oper LicMDPR-69 revising Tach Spect as requested in 780726 ltr w/Befety Evaluation & Notice of Issuance. REID.R.M. Operating Reactors Branch 4 (Pre 790625). 78/10/21. 3pp. 02721:008.
- ~~7811030080 Amend#18 to Facil Oper Lic#DPR-69 revising Tech Specs re: incorp changes resulting from analyses of Cycle 2 reload fuel, & authorizing removal of all part length control element assemblies. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/21. 38pp. 08721:011.
- --7811030085 Safety avaluation supporting Amend 18 to License DPR-69.
 Operating Reactors Branch 4 (Pre 790625). 78/10/21. 30pp.
- ---7811030088 Notice of Issuance of Amend#18 to Facil Oper Lic#DPR-69 on 781021.
 REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/21.
 200.
- 7811200206 Requests amend to oper lic tech specs re: limiting maximum baron concentration in SIT's & RHT's to 2200ppm.silow lesser shutdown cooling flow when reactor coolent loop partially drained.k add loss of field trip to DO surveillance. LUNDVALL.A.E. Seltimore Gas & Electric Co. 78/11/13. 30pp. 94252-045.

- 7811240214 Remits Lic amend fee for Class 4 & Class ! Amend involving 11 proposed changes to oper lic. CLBCN.R C Blitimore Gas & Electric Co. 78/11/15. 1p. 94463:360.
- 781R150106 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CR973. Requests pre-workshop registration of attendees to facilitate sending out math. Hyench Registration Form & List of Locations.

 HILLER.J. R. Assistant Director for Bite & Refeguerds (Pre 791030). 78/11/15. Spp.
- 7812190008 Forwards Rev#1 "Draft Radiological Effluent Tech Specs" for PHR '4(NUREQ-0472)& "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREQ-0133) GRIMES.8.K. Assistant Director for Engineers & Projects (Pr# 790625). 78/11/15. 6pp. 94214:266
- 7811240183 Forwards response to NRC request for add1 info re analysis of potential radioactive dose to control room operators following loss-off-coolent accident.

 LUNDVALL, A. E. Baltimore Oes & Electric Co. 78/11/20, 22pp. 74458. 279.
- 7811300046 Informs BGE that NRC has contracted w/Mountain West Res Inc to undertake a series of post-licensing studies of nuc pur stations. Studies will analyse socioecon impacts which occurred during constr & post-constr periods of each plant. DEYOUNG.R.C. Division of Site Safety & Environmental Analysis. 78/11/20 2pp. 94071:049.
- 781207016: Notice of seminar on 781208 on new Hodel Radiological Effluent Tech Specs for nuc pur plants. Requests advance submission of seminar specific questions. W/encl Beminer Info Sheet. Proposed Agenda & maps GRIER.B.H. Region 1. Philadelphie. Office of the Director. 78/11/21 Spp. 74375:168.
- 7812140379 Forwards discussion topics for meeting to be held on 781212. Purpose of meeting is to obtain info for use in "Reactor Bafety Study Methodology Appls Prog" res proj. REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/11/28. App. 03558:128.
- 78:2130293 Asks util to reexamine 780725 request for exemption from 10CFR21 in light of 78:019 smend to Part 21. DENTON.H.R. Defice of Nuclear Reactor Regulation, Director. 78/11/29, 2pp. 94294:360.
- 7812150079 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing. W/encl AND: 7812080207.
 REID.R.W Deparating Reactors Branch 4 (Pre 790625). 78/11/29. 6pp. 94211:295.
- 7812280140 Emphasizes importance of submitting accurate & complete inf to NRC by licensess & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuracies or snforcement action will result. DAVIS.J. 9. Defice of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94310:332.
- 7812270354 Forwards info re forthcoming 781220 meeting to discuss fuel demonstration prog related to subj facils' transitions to 18 month cyclus.

 CONNER.E.L. Operating Reactors Branch 4 (Pre 790625). 78/12/12.

 2pp. 94228:292.
- 781109006: Responds to 780731 itr on Liquid Natural Gas Contingency Plan spent fuel storage capacity & shallow water draft trials of LNQ tanters W/encl itr from Coast Quard that maneuvers near facil will not be allowed w/gas.
 REID.R.W. Operating Reactors Branch 4 (Pre 790625). 78/10/18. 3PP 94040:119.
- Q. Inspection reports. IE Bulletins & correspondence
- 7812010291 Ack receipt of 781017 ltr informing NRC of steps taken to correct violation noted during inspec#50-317/78-25 & #50-319/78-19.
 BRUNNER.E.J. Region 1, Philadelphia, Office of the Director, 78/11/06. 1p. 94417:266.
- --7812010296 Forwards IE Inspec Repte#50-317/78-25,#50-318/78-19 on 780905-08 & Notice of Violation. BRUNNER, E. J. Region 1, Philadelphia, Office of the Director. 78/09/28. 2pp. 94417: 269.
- --7812010298 Notice of Violation from inspec on 780905-08. * Region i. Philadelphia, Office of the Director. 78/09/28. is. 94417.271.

- /Bix010303 IE Inspec Repts#50-317/78-25 & #50-318/78-19 on 780905-08 during which 2 items of noncompliance were noted failure to conduct Type B tests w/in 2 years failure to follow approved procedure eppinoved processors HIGGINS, J.C., SMITH, T.H., WONG, H.J. Region I, Philadelphia, Office of the Director. 78/09/28 12pp. 94417.272
- 7912080096 Discusses ABME Boiler & Pressure Vessel Code Requirements for Insyc Inspec of Nuc Components Requirement for piping examination is burdensome because extra teams must be utilized who will be unnecessarily exposed to radiat LUNDVALL.A E. Baltimore Gas & Electric Co. 78/12/05 2pp 94107 296
- 7812080125 Responds to 781031 & 761124 NRC ltrs requesting addl info re pump & valve teating insvc progs. W/encl oversize drewings available in Central Files only. LUNDVALL, A. E. Baltimore Gas & Electric Co. 78/11/20 9pp.
- 7812110105 Responds to 15 Bulletin#78-12 re reactor pressure vessel walds. Requests permission to deal w/problems on a generic rather than a plant specific basis.

 LUNDYALL, A. E. Baltimore Gas & Electric Co 78/11/17. 2pp. 74339: 062.
- 7811080091 Forwards IE Inspec Repts#50-317/78-23.#50-318/78-17 on 780822-25 during which no items of noncompliance were noted. BRUNNER, E. J. Region I. Philadelphia. Reactor Operations Nuclear Buggort Branch. 78/09/20 2pp. 94399-072
- --7811080096 1E Inspec Repts#50-317/78-23.#50-318/78-17 on 780822-25 during which no items of noncompliance were noted. Major areas inapected included nonthly oper status repts:fecility tours & implementation of 100FR21 requirements. DEMINGON D.F., KEIMIG.R. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 78/09/18. Spp. 94399:0
- 7810170026 Forwards IE Bulletin#78-12. "Atypical Weld Material in Reactor Pressure Vessel Welds" requesting action win 60 days & list of IE Bulletins issued in 1978. ORIER.8. H. Region 1. Philadelphia, Office of the Director. 78/09/29. 6pp. 94241.332
- 7811050188 Forwards 1E Circular#78-17. (See ANO: 7810230221, Docket #50-133, 781013) QRIEN, B. H. Region I. Philadelphia, Office of the Director 78/10/13. 1p. 94489.158.
- 7811090025 Ack receipt of itr informing NRC of steps taken to correct violations noted during InspecM50-317/78-22 & M50-318/78-16.

 BMITH.O H. Region 1. Philadelphia. Fuel Facility & Materials Safety Branch. 78/10/26 1p. 94040:029.
- --7811090030 Responds to 780813 NRC ltr re violations noted in Inspec Repts#50-317/78-22 & 50-318/78-16. Corrective actions; Rad-Chem technicians properly reinstructed/CCI-6078 rev by 781201/air supply maint procedures written by 781101. LUNDVALL, A.E. Beltimore Gas & Electric Co. 78/11/08. 3pp. 94040: 030.
- ~-7811090032 Forwards IE Inspec Rept#50-317/78-22 & #50-319/78-16 on 780908-10 & Notice of Violation. CROCKER, H. W. Region I. Philadelphia, Fuel Facility & Materials Bafaty Branch. 78/09/13. 2pp. 94040:031.
- --7811090034 Notice of Visiation from inspec on 780808-11.
 CROCKER, H M. Region 1. Philadelphia. Fuel Facility & Materials
 Bafety Branch. 78/09/13. 2pp. 94040:033.
- --781109003B IE Inspec Rept#50-317/78-22 & #50-318/78-14 on 78080B-11 during which 3 thems of noncompliance were noted:redat during which 3 thems of noncompliance were noted:redat protec procedures:Procedure CCI-6078 not incorp into training:NUREO-0041.Section 9.8 procedures ignored. WHITE.J.R. BERMBIAN.J.A., KNAPP.P.J. Region 1. Philadelphie, Fuel Facility & Materials Sefety Branch. 78/09/12. 11pp. 94040:035.
- 7811140045 Requests that util prepare ensuers to encl questions on insvc test prog for meeting on 781108-09 at Calvert Cliffs. MD & formally document responses by 781127. REID.R.H. Operating Reactors Branch 4 (Pre 790625). 78/10/31, 8pp. 94420:326.
- 7812010345 Forwards licensee performance evaluation for Region 1. No. operating reactor in Region 1 considered to have either abnormal or unusual safety concern. ORIER, B.H. Region 1, Philadelphia, Office of the Director. 78/11/01. 4pp. 00002:259.

- 7811150265 Act receipt of 781017 ltr informing NRC of steps taken to correct violations noted during inspec#50-317/78-26 & #50-318/78-20 BRUNNER.E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/02. 1p. 94273:229.

 - --7811150269 Responds to 781006 NRC ltr re violation noted in Inspec Rep #50-317/78-26 & #50-318/78-20 Corrective actions: informing control room operators of requisite procedures.

 LUNDVALL, A.E. Beltimore Gas & Electric Co. 78/10/17. 2pp. 94273: 230
 - --7811130272 Forwards IE Inspec Rept#50-317/78-26 & #50-318/78-20 on 780912-15 & Notice of Violation.
 BRUNNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/06. 2pp. 94273:232.
 - --7811130274 Notice of Violation from inspec on 780912-15. BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/06. 1p. 94273:234.
 - --7811150276 IE Inspec Rept#50-317/78-26 & #50-318/78-20 on 780912-15 during which I item of noncompliance was noted: failure to comply which is the noncompliance as Nobel resistor of comply will miting conditions for open.

 JCHNSON, D. F. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 78/10/06. 12pp. 94273:235.
 - 7811290220 Forwards IE Circular #78-18, "UL Fire Test. "W/encl ANO: 7811150002. GRIER:B.H. Region 1. Philadelphia. Office of the Director. 78/11/06 1p. 94237:298
 - 7812280313 Forwards IE Inspec Rept#50-318/78-22 on 780925-29 & 1017-18 during which no items of noncompilance were noted. CARLSON,R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch, 78/11/09. 2pp. 94082:049.
 - --7812280319 IE Inspec Rept#50-318/78-22 on 780925-29 & 1017-18 during which no items of noncompliance were noted. Major areas inspected incl:Steam Generator Inspec Prog & Inspec Inspec (IBI)Activities.
 MCBREARTY,R A , EBNETER,B.D. Region i Philedelphia Office of the Director. 78/11/07. Spp. 94082:051.
 - 7812290028 Forwards IE Inspec Repts#50-317/78-30 & 50-318/78-27 on 781023-26 during which no items of noncompliance were noted. BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/11/13. 2pp. 94208:040.
 - --7812290034 IE Inspec Repts#50-317/78-30 & #50-318/78-27 on 781023-26 during which no items of noncompliance were noted Major areas inspected incl: shift logs & records & licensee followup actions concerning previous inspec findings JOHNSON, D. F., KEIMIC, R. R. Region 1, Philadelphia, Office of the Director 78/11/09. 6pp. 94208:042.
 - 7812130125 Forwards IE Bulletin#78-12A.suppl to IE Bulletin#78-12. H/encl ANO: 781300055. GRIER, B.H. Region 1. Philadelphia, Office of the Director. 78/11/24. 1p. 94212:159.
 - 78:2060242 Forwards 1E Inspec Repts#50-3:7/78-29 & #50-3:8/78-26 on 780410-3 during which no items of noncompliance were noted. BMITH.G.H. Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch. 78/11/23. 2pp. 94372:340.
 - --7812060244 IE Inspec Repta#50-317/78-29 & #50-318/78-26 on 780410-3 during which no items of noncompliance were noted. Major areas inspected incl:seffluent sample.
 KOTTAN,J.J. BYOHR,J.P. Region 1. Philadelphia, fuel Facility & Materials Gefety Branch. 78/10/24. 4pp. 94372:342.
 - R. Periodic operating reports & related correspondence
 - 7810230178 Forwards Monthly Open Rept for Sept 1978.

 MERBON(B.D. Beltimore Gas & Electric Co. 78/10/15. 1p. 94164:104.
 - --7810230182 Monthly Oper Rept for Bept 1978.

 Beltimore Gas & Electric Co. 78/10/15. 20pp. 94164:105.
 - 7812220076 Forwards Monthly Oper Rept for Nov 1978.
 MERBON.S. D. Beltimore Ges & Electric Co. 78/12/15. 1p. 94343:280.
 - --7812220077 Monthly Open Rept for Nov 1978.
 MERSON.8.D. Beltimore Gas & Electric Co. 78/12/15. 18pp. 94343; 281.

- 8. Reportable occurrences, LERs & related correspondence
- 7810310209 Forwards LER#78-003/03L-0. DOUGLASS.R M. Beltimore Gas & Electric Co. 78/10/20. ip. 94090-318
- --7810310216 LER 78-033/03L-0 on 780924: while filling refueling pool from refueling water tank an RAS actuated & tripped both LPSI pumps, due to poor calibr of Sigme instr level indicator 2-L1-4143.

 CARROLL. J. T. ROMNEY, K. M. Baltimore Qas & Electric Co. 78/10/20.

 1p. 94090, 319.
- 7811130166 LERM78-036/01X-0 on 781023 during inspec of steam generator isolation signal logic.21 main steam isolation valves failed to shut when given 5018A & SCISS signal. Cause undetermined. DAVIS.8.M. Baltimore Gas & Electric Co. 78/10/24. 1p. 94087:359.
- 7811060133 LER#7B-038/01X-0 on 781025:containment air lock inner door remained open for 4 days Caused by misonderstanding between shift supervisor & maintenance personnel.

 CARROLL, J. Baltimore Gas & Electric Co. 78/10/31. 2pp. 94424:203
- 7811060155 Forwards LER#78-035/01T-0.
 00094.885.R.M. Baltimore Qas & Electric Co. 78/10/31. 1p. 94499:074.
- --7811060161 LER#78-035/01T-0 on 781017:air binding of LP8I pumps resulted when air being used to transfer purification system leaked into the BDC Sys. Oper instruct are being rev. CARROLL.J. T. Baltimore Gas & Electric Co. 78/10/31. 1p. 94489.075
- 7811130211 Forwards LER#78-034/03L-0.
 DDUCLA88.R.M. Baltimore Oas & Electric Co. 78/11/02. 1p. 03554:033.
- --7811130214 LER#78-034/03L-0 on 781023: in Mode 3 at 500F, 12 mein steem safety valve relief sat points were outside tolerances of TS 4.7. Liell were adjusted & satpoints returned to spac. DAVIS.B. M., MIERNICKI.M. J. Baltimore Gas & Electric Co. 78/11/02. ip. 03504;034.
- 7811140164 Forwards LER#78-036/01T-0 DOUGLASB, R. M. Beltimore Gas & Electric Co. 78/11/02. ip. 94382:314.
- --781140170 L6R#78-036/01T-0 on 781023:during routine test of steam generator isolation signs logic, 21 mein steam isolation valve failed to shut upon 801BA & 801BB signs or hand switch in Control Room.due to atticking MSIV solenoid valves.

 DAVIS. B. M. J. WATKINB, X. B. Beltimore Gas & Electric Co. 78/11/02. 2pp. 74083:315.
- 7811170165 Forwards LER#78-037/03L-0.
 RUSEELL-L. B. Baltimore Qas & Electric Co. 78/11/10. ip. 94047:353.
- --7811170171 LERA78-037/03L-0 on 781025: during open reactor protec instruwide range logarithmic neutron flux monitor Channel A read 2 decades lower than other Channels due to connector for Channel A not being dried completely when recently cleaned. DAVIS.8.M. ROMNEY.K.M. Baltimore Gas & Electric Co. 78/11/10.
- 7811170179 Forwards LERM78-038/017-0. RUBERLL-L.B. Baltimore Oas & Electric Co. 78/11/13. 1p. 94134:033.
- --7811170187 LEAW78-038/01t-0 on 781025:during LPPT in Mode 2, containment air lock was opened to repair failed open mechanism & was kept a jar-due to misunderstanding between supervisor & maintenance personnel. All personnel have been reinstructed. CAROLL, J., ROMNEY, K. Baltimore Gas & Electric Co. 78/11/13. 2pp. 94048:136.
- 7811300211 Forwards LER#78-041/03L-0 RUGEELL. L. B. Raltimore Oas & Electric Co. 78/11/24. ip. 94075-217.
- ---781300223 LER#78-041/03L-0 on 781115:RWT level discovered to be at 455 inches. Caused by Red-Chem technician's failure to fully close local sample valve after drawing routine sample. Technician has been reinstructed in valve sampling. DWIS.S.M. Baltimore Oas & Electric Co. 78/11/24. ip. 94075-218.

- 7812130170 Forwards LER#78-039/03L-0 RUBBELLL B Baltimors Gas & Electric Co 78/12/07. 1p. 94294:335.
- --7812130174 LERW78-039/03L-0 on 781115 during normal open periodic a inventory balance indicated that unidentified reactor coolant lessage was 1 72 gpm at 0500. Leak identified as crecked weld.

 CARROLL, J.T., WATKINS.K. 8. Baltimore Gas & Electric Co. 78/12/0 ip. 94294:336.
- 7812130183 Forwarde LER#78-043/03L-0 RUSEELL-L B. Baltimore Gas & Electric Co. 78/12/07 1p. 94300-341
- --7812130187 LER 78-043/03L-0 on 781126 during monthly surveillance to CEA 3 dropped to bottom of core at 0049. Pur reduced to 70% per Tech Spec until CEA 3 was restored to its group position at 0158.

 CARROLL, J. T., MIERNICKI, M. J. Baltimore Gas & Electric Co. 78/12/07. 1p. 94306:362.
- 7812260244 Forwards LERM78-040/03L-0 RUSELLL B. Baltimore Gas & Electric Co. 78/12/14. 1p 94197:349
- --7812260248 LER#78-040/03L-0 on 78[117: M5 halon sub-sys discharged a door to 22 inverter was open. Caused by thermal detector being overly sensitive to rate of rise of temp. When door opened, internal strflow disturbed, setting off detector. CARROLL, J. T., MIERNICKI, M.J. Baltimore Gas & Ejectric Cd. 78/12/14. 1P. 94159: 350.
- DOCKET 50-320 THREE MILE IBLAND NUCLEAR STATION, UNIT 2 F. Security, medical, emergency & fire protection plans
- 7811870135 Forwards Revision 4 to physical security plan. Withheld ire 10CFR2.7901. HERBEIN.J.Q. Metropolitan Edison Co. 78/11/17. 1p. 94253:352.
- O. Adjudicatory correspondence
- 7810140104 Recommends that 781117 be set so new filling deadline, as a result of addl inquiries posed in 780915 order. CHANDLER, L. J. Défice of the Executive Legal Director. 78/10/04. ip. 94421:344.
- 7810200034 Requests extension until 781117 to file suppl testimony on aircresh probability analysis, due to difficulty in obtaining data & witness.
 TROMBRIDGE, G. F. Bhaw, Pittman, Potts & Trowbridge. 78/10/04. 2pp 94367:031.
- 7810240046 Extends time for the filing of prepared testimony on the airplane crash probability issue until 781117. DUFLO:M.E. Atomic Safety and Licensing Appeal Panel. 78/10/10. 2pp. 00001:229.
- 7811010342 Forwards order for mod of license which amends DPR-73 & supersedes order for mod of license 6td 780526. VARQA.8.A. Light Hater Reactors Branch 4: 78/10/13. 3pp. 94391:077.
- --7811010368 Order for mod of license amending DPR-73 & superseding 780526 order. Adds provision limiting reactor core power level to 2772 MHt. 8070-R.S. Division of Project Management. 78/10/13. 6pp. 94391:080.
- 7812030090 Forwards recent NRC memos re problems associated w/pipe support base plate design which apply to facility.
 MCGURREN,H.J. OPFice of the Executive Legal Director. 78/11/14
 9pp. 94335:228.
- 7812040244 Motion for extension of time for filin 781130. Certificate of Svc encl. CHANDLER,L.J. Office of the Executive Legal Di App. 94129:352.
- 7812130375 Forwards portion of NRC testimony re d Carrier creshes & cresh info for heavy military CHANDLER,L.J. Office of the Executive Legal Di 849p. 94292:128.

200. Y4436 INY

- 7812130088 Act receipt of ASLAS 781121 order scheduling evidentiary hearing on aircreft cresh probability lesue at 9:00em.Monday 781211
 - DLER.L J Office of the Executive Legal Director 78/11/22 94294: 284 CHANDLER, L. J. 10.
- 7812210456 Act receipt of 781121 order echeduling evidentiary hearing on 781211 on plane crash probability Both respondent & AJ Weishard will represent applicants. TROUBRIDGE, Q.F. Shaw, Pittman, Potts & Troubridge. 78/11/29. Ip. 94165-027
- 781R270030 Forwards NRC testimony re aircraft crashes pertaining to facility Forwards tables re sircraft accidents
 CHANDLER, L. ... Office of the Esecutive Legal Director 78/11/30. 86pp. 00007.147.
- --7812270033 Forwards data requested for preparation of testimony before ABLAB re military aircraft Forwards info to C-SA sixtraft be aircraft mishaps rates per 100,000 hours of flying. NASH-E J Air Force-Dept. of 78/08/02 6pp. 00007: 232
- --7812270040 NRC testimony re US air carrier & military accident & traffic data.
 • Office of the Executive Legal Director. 78/11/17. 45pp. 00007: 280
- --7812270052 Forwards testimony re aircraft crashes covering a real crash density at TM1-2 & off-runway crash probabilities.
 MODRE.R., ABRAMSON.L. Office of Management and Program Analysis.
 78/11/30. 16pp. 00007-324.
- --7812270056 Evaluation of aircraft crash potential for nuclear power plants. FIGENHUT, D.Q. Assistant Director for Systems Engineering (Pre 791030): 78/11/30. 21pp. 00007:341.
- 7812130217 Memo & order to ALAB-509. Any party who disagrees w/ASLAB approach re radon emissions should file brief within 45 DUFLO, M.E. Atomic Safety and Licensing Appeal Panel. 78/12/01-11pp. 94306:087.
- 7812180307 Responds to 781121 ASLAB order & informs that NRC will be represented at forthcoming hearing on aircraft crash issue by SA Treby & RL Black. CHANDLER, L.J. Office of the Executive Legal Director. 78/12/01.
- 7812220141 Notice of appearance of AJ Weisbard on behalf of util, Certificate of Svc encl. WEISBARD, A. J. Shaw, Pittman, Potts & Trombridge, 78/12/05. 3pp. 94249:067.
- 7812270360 Forwards professional qualifications of NRC witnesses & "Table of Effective Aircraft Impact Target Area" inadvertently omitted from NRC testimony on 781130. CHANDLER, L. J Office of the Executive Legal Director. 78/12/05. 2000. 94232:333.
- 7812270366 Forwards revised page to testimony of J Read, et al on 781130. & errate sheet to testimony of R Moore & L Abramson.

 8LACK,R.L. Dffice of the Executive Legal Director. 78/12/06. 4pp. 94229:017.
- 7812270114 Notices of appearance for RL Black-SA Treby & JF Scinto on behalf of NRC. Certificate of Svc encl.
 8LACK-R.L. Office of the Executive Legal Director. TREBY.S.A., SCINTO-J.F. Hearings Division. 78/12/08. 3pp. 0000B:016.
- 7812280314 Forwards Table 4 Revision Exproviding Inforce weather conditions prevailing at time of accident shown on Table 4, type of radar & causative factors. CHANDLER.L.J. Office of the Executive Legal Director. 78/12/08. 20pp. 94082:059.

H. General correspondence

7812190112 Bosing has delivered forty 727-200s to THA: fourteen are of 191,000 lb gross taxi weight, w/takeoff weight of 190,500 lb & landing weight of 154,500 lb.

MHEELER, J. R. Bosing Co. 78/32/05, ip. 94381:201.

- 7812120092 Advises that Generation Licensing Section (Production Bupervision) moved back to Pottsville Pike location on 781213 Forwards new telephane numbers. HERBEIN, J. G. Metropolitan Edison Co. 78/12/12. 1p. 94274: 204.
- J. Insurance & indomnity information
- 7811060092 Forwards copy of Endorsement 1 to NELIA Binder EB-65.

 MDREAU,W.N. General Public Utilities QPU Service Corp. 78/10/30.
 2pp. 94424:142.
- K. Utility Final Bafety Analysis Report (FBAR) & amends
- 7811090048 Forwards Amend 66 to FBAR. Certificate of Byc encl. HERBEIN, J. Q. Metropolitan Edison Co. 78/11/08. 3pp. 00001:276.
- --7811090054 Amend &6 to FSAR. Metropolitan Edison Co. 78/11/08. 175pp. 00001:279.
- P. Operating license stage documents & correspondence
- 7810260147 Forwards C-141 & E-4A info re destroyed aircraft, flying hours, sorties, & landings 1968-Jul 1978 in response to NRC 780920 ltr Air Force: Dept. of. 78/10/02. ip. 94055:330. CREWBE, R. O.
- 7810100046 Unit 2 will install feedwater sys mod prior to startup following plant first refueling outage Requests opportunity to meet u/NRC 781019. HERBEIN, J. G. Metropolitan Edison Co. 78/10/04. 1p. 94032:178.
- 7810190132 Responds to NRC 780804 questions re operability of containment purge valves in the event they are open at the time of a LDCA.
 HERBEIN.J. Q. Matropolitan Edison Co. 78/10/13. 2pp. 94/ Matropolitan Edison Co. 78/10/13. 2pp. 94413:009.
- 7810310305 Notification of 781019 meeting w/util re details of steam BILVER: H. Light Water Reactors Branch 4. 78/10/16. 1p. 94089:090.
- 7810240097 In response to 780918 phone call, util will submit Tech Spec change request requiring implementation of interim corrective action for single auxiliary transformer. HERBEIN.U. G. Metropolitan Edison Co. 78/10/17. 2pp. 00001:233.
- 7810240119 Forwards NPDES Noncompliance Notification 78-22 re wasts filter sys discharge sample with pH in excess of permit limitation. TROFFER, Q. J. Metropolitan Edison Co. 78/10/17. 2pp. 00001:235.
- 7811010246 Notification of 781026 meeting w/util re sircraft crash data BILVER,H. Light Water Reactors Branch 4. 78/10/19. 1p. 00001:851.
- 7810240120 In view of new Burns & Ros analysis, util will defeat automatic transfer feature when loading on 4160 volt buses exceeds 19 MW. Modifies 780929 commitment. HERBEIN, J. G. Metropolitan Edison Co. 7 78/10/20, 2ap. 00001:237.
- 7810300187 Appointment of new licensing mgr for OPU Svc Corp.
 WALLACE,E. Q. general Public Utilities GPU Service Corp.
 1p. 94035:117.
- 7811090114 Forwards responses to NRC 780508 ltr re steam line break & environ qualification of electrical components. FGAR pages & environ qualification test repts encl.

 HGRBEIN.J. G. Metropoliten Edison Co. 78/10/31. 600pp. 94049:291.
- 7811030174 Forwards date requested for preparation of testimony before ABLAS, info on gross weight of sircraft & active ruhway is unavailable. NASH E. J. Air Force, Dept. of. 78/11/03. 2pp. 02724:072.
- 7811140172 Forwards Tech Spec Change Request 16. Certificate of Svc & mffidavit. HERBEIN, J. G. Metropolitan Edison Co. 78/11/06. 5pp. 94384: 229.
- 7811150161 Remits fee for NRC review of Tech Spec Change Request 16 re euziliary transformer operation.
 HERBEIN.J. Q. Metropolitan Edison Co. 78/11/09. ip. 94273:000.

- 7811290343 Notification of 781122 meeting w/vtil to discuss proposed mode to eliminate need for prompt action in responding to small break LOCA worst single failure.
 ZHETZIQ.O.B. Operating Reactors Branch 4 (Pre 790625). 78/11/17 2pp. 94193.351.
- 7811300037 Informs that NRC has contracted to undertake a series of
- post-licensing studies to analyze socioeconomic impacts of nuclear plant const.

 DEYGUNG,R. C. Division of Bite Safety & Environmental Analysis.
 78/11/20. 2pp. 00002:234.
- 7811240110 Forwards proposed small break LOCA long-term mod NRC 780926 ltm did not respond to 780724 util proposel & util believes proposal meets NRC requirements.
- HERBEIN, J. G. Metropolitan Edison Co. 78/11/21. 6pp. 94456:275.
- 7812070194 Notice of seminar on 781208 on new model radiological effluent Tech Specs for nuclear plants. Requests advance submission of seminar-specific questions.

 ORIER B. H. Region 1. Philadelphia. Office of the Director. 78/11/21. Spp. 94375:069.
- 7812080244 Summary of a 781026 meeting re aircraft crash data at TMI-2 BILVER.H. Light Water Reactors Branch 4. 78/11/21. 5pp. 94137:168.
- 7612070203 Forwards summary of 781019 meeting on feedwater isolation
- HERBEIN, J. G. Metropolitan Edison Co. 78/12/04, 1p. 94375.131.
- --7812070205 Summary of 781019 meeting in Bethesda, MD to reach agreement on feedwater isolation sys:conceptual design.design criteria & conformance to Condition C(3)1. • Metropolitan Edison Co 78/12/04. 20pp. 94379.132.
- 7812130109 Summary of 781019 meeting w/util & Rurns & Roe on steam line break fix Discussed conditions of TMI-2 license, feedwater isolation valves & Type C test.

 8ILVER.H. Light Water Reactors Branch 4. 78/12/04. 2ipp. 94295:309.
- 7812180187 Forwards Tech Spec Change Request 18 requesting amend re reactor coolent pumps. HERBEIN, J. O. Metropolitan Edison Co. 78/12/11. App. 94364:002.
- 7812280049 Summary of 781122 meeting w/util in Bethesda MD re util revised proposed mod to eliminate reliance on operator action following small break LOCA List of attendees &
 - proposed mechanical mods encl. ZWETZIG.G.B. Operating Reactors Branch 4 (Pre 790625). 78/12/12. 10pp. 0000B.042.
- 7812190096 Forwards add1 info to TMI-2 Tech Spec Change Request 18. Amend 1. Changes involve restructuring format in RCS/flow reactor power level entries. HERBEIN.J. Q. Metropolitan Edison Co. 78/12/13. 5pp. 94376:318.
- 7812290131 Provides add1 info re steam line break environ qualifications. W/revised pages containing environ test parameters for Anaconda Instrument cable & Test Rept F-C2935
- HERBEIN, J. G. Metropolitan Edison Co. 78/12/14, 42pp. 94190:216.
- G. Inspection reports, IE Bulletins & correspondence
- 7811090284 Forwards IE Insp Rept 50-320/78-28 on 780905-07 No. noncompliance noted.

 #RUNNER.E. J. Region 1, Philadelphia, Dffice of the Director.
 78/09/21. 2pp. 00002:131.
- --7811090290 IE Insp Rept 50-320/78-28 on 780905-07 No noncompliance noted. Major areas inspected; safety injection sys reset feature & LERs.
 HAVERKAMP. D. R. Region i, Philadelphia, Office of the Director,
 78/09/18. Spp. G0G02:133.
- 7810160250 Forwards IE Bulletin 78-12. "Atypical Held Matl in Reactor Pressure Vessel Welds." Licensee action required. H/o encl. ORIER, 8, H. Region 1, Philadelphia, Office of the Director, 78/09/29. 6pp. 94471:302.
- 7810180221 Ack receipt of 780918 1tr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-320/78-24. GRIER.8.H. Region 1. Philadelphia. Office of the Director. 78/10/03. 1p. 94412:241.

- ~-7810190001 Responds to NRC 780824 ltr re violations noted in IE Insp Rept 30-320/78-24. Corrective actions holding/storage oven repaired weld not returned to oven to remove addl hydrogen, HERBEIN, J. Q. Metropolitan Edison Co. 78/09/18. 2pp. 94418: 242
- ~~7810190005 Forwards IE Insp Rept 50-320/78-24 on 780718-21 & 0731-0803 & notice of violation. BRUNNER, E. J. Region 2, A Branch. 76/08/24 2pp. Region 2. Atlanta. Reactor Operations Nuclear Support 8/24 2pp. 94412:244
- ~-7810190006 Notice of violation from insp on 780718-21 & 0731-0803 HAVERNAMP,D.R. Region 1. Philadelphia. Reactor Operations Nuclear Bupport Branch. FABAN,A.N. DURR.J.P. Region 1. Philadelphia. Office of the Director. 78/08/24. ip. 94412:246.
- --7810190007 IE Insp Rept 50-320/78-24 on 780718-21 & 0731-0803 Noncompliance noted: failure to maintain weld rod storage oven at required temp.

 HAVERKAMP.D.R. Region I: Philadelphia, Reactor Operations Nuclear Support Branch. FABANO.A.N., DURR.J.P. Region I: Philadelphia. Office of the Director. 78/09/23. 22pp. 94412:247.
- 7811060186 Forwards IE Circular 78-17. We encl. ORIER.B.H. Region i. Philadelphia. Office of the Director. 78/10/13. 1p. 00001:265.
- 7812010280 Forwards 1E Insp Rept 50-320/78-29 on 780914-15 & 19-22. No noncompliance noted. BRUNNER.E.J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/10/18. 2pp. 94417:232.
- --7812010282 1E lnsp Rept 50-320/78-29 on 780914-15.19-22. No noncompliance noted Major areas inspected; preoperational & startup test results & power ascension test. Haylor B., COLEMAN.H.E., BETTENHAUSEN-L. Region 1, Philadelphia, Office of the Director, 78/10/18, 15pp. 94417:234.
- 7812010336 Forwards IE lines Rept 50-320/78-30 on 781004-06. No noncompliance noted. BRUNNER, E. J. Ragion 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/20 2pp. 94418:184.
- --7812010338 IE Inep Rept 50-320/78-30 on 781004-06 No noncompliance noted Major areas inspected: limiting conditions for operation & control of design changes.
- HAVERRAMP, D. R., KEHDE, D. V. Region 1. Philadelphia, Office of the Director. 78/10/19. Spp. 94418:186.
- 7811290324 Forwards IE Inspec Rept#50-346/78-27 on 780905-05 during which no items of noncompliance were noted.

 FIDMELI, O. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/10/25. 2pp. 94193:300.
- --7811290326 IE Inspec Rept#50-346/78-27 on 780905-08 during which no items of noncompliance were noted. Major areas inspected incl:inspec of selected startup test performed during Cycle TB pur escalation testing.

 CRESMELL,J.S. Region 3. Chicago, Dffice of the Director.
 78/10/24. 5pp. 94193:302.
- 7812010345 Forwards licenses performance evaluation for Region 1. No operating reactor in Region 1 considered to have either abnormal or unusual safety concern.

 GRIER.B.H. Region i, Philadelphia: Office of the Director.
 78/11/01. 4pp. 00002:259.
- 7811290199 Forwards JE Circuler 78-18, "UL Fire Test."
 ORIER.B.H. Ragion i, Philadelphia, Office of the Director.
 78/11/06. ip. 00002:224.
- 7812270047 Forwards IE Insp Rept 50-287/78-18 & 50-320/78-31 on 781006, 10-12 & 17-19 & notice of violation.
 BMITH.9.H. Region 1. Philadelphia, Fuel Facility & Materials Sefety Branch. 78/11/21. 3pp. 00007:362.
- --7812270051 Notice of violation from insp on 781006,10-12 & 17-19.

 * Region 1, Philadelphia, Office of the Director. 78/11/21. 2pp. 00007:002.
- --7812270057 IE Insp Rept 50-289/78-18 & 30-320/78-31 on 781006,10-12 &
- 17-19. Noncompliance noted: failure to barnicade high radiation area or maintain records of effluent sampling.
 PLUMLEE.K.E., BERABIANJ.A. Region i. Philadelphia, Office of the Director. 78/11/15. 12pp. 00008.004.
- 7812150144 Forwards IE Bulletin 78-12A. "Atypical Held Matl in Reactor Pressure Vessel Helds,"

 ORIGE, R. H. Recton 1. Philadelphia. Diffice of the Director.

- 7819290116 Forwards corrected page of Table D-1 to "Inservice Insp Program Pumps," W/justification as Attachment A. HERBEIN. J. O. Metropolitan Edison Co. 78/12/13. 3pp. 94082:318.
- R. Periodic operating reports & related correspondence
- 7810170147 Forwards monthly operating rept for Bept 1978. HERBEIN J. Q. Metropolitan Edison Co. 78/10/10. 1p. 94236:077.
- --7810170148 Monthly operating rept for Sept 1978. LENGELIR. A. Metropolitan Edison Co. 78/10/09. 4pp. 94236:078.
- 78:12:0380 Forwards munthly operating rept for Oct 1978 & corrected "Unit Shutdown & Power Reductions" page for Spet rept. HERBEIN, J. G. Metropolitan Edison Co. 78/11/15. 1p. 94483:156.
- ~-7811210384 Monthly Operating rept for Oct 1978 & corrected "Unit Bhutdown & Power Reductions" page for Sept rept. LENGEL.R. A. Metropolitan Edison Co. 78/11/15. 5pp. 94485:157.
- 7812190132 Forwards monthly operating rept for Nov 1978.

 HERBEIN, J. Q. Hetropolitan Edison Co. 78/12/15. 1p. 94340:348.
- --7812190134 Monthly operating rept for Nov 1978. HARDING, L. W. Metropolitan Edison Co. 78/12/15. Spp. 94340:349.
- B. Reportable occurrences. LERs & related correspondence
- 7810100088 Forwards LER 78-053/03L-0 HERBEIN, J. G. Metropolitan Edison Co. 78/09/26 ip. 94033:172.
- ~~7810100095 LER 78-053/03L on 780831: safety injection channel "C" did not trip when pressure was reduced below 1640 psi. Caused by failure of bi-stable. LENGEL.R.A. Metropolitan Edison Co. 78/09/26. 1p. 94033:173.
- 7810100076 Forwards LER 78-054/03L-0.
 HERBEIN, J. G. Metropolitan Edison Co. 78/09/27. ip. 94032:238.
- --7810100080 LER 78-054/03L-0 on 780907: while in Mode 5, determined containment grade suitches, torque switch & motor. Caused by purchasing error.
 LENGEL.R.A. Metropolitan Edison Co. 78/09/27, 2pp. 94032: 239.
- 7810180165 Forwards LER 78-057/03L-0.
 HERBEIN, J. Q. Metropolitan Edison Co. 78/09/29. ip. 94317:094.
- --7810180168 LER 78-057/03L-0 on 780830: during maint on remote shutdown display patch panel, patch power supply was grounded, causing loss of display instruments.

 4 Metropolitan Edison Co. 78/09/29. ip. 94317:095.
- 7810110082 Forwards LER 78-059/031-0.
 HERBEIN, J. G. Metropolitan Edison Co. 78/10/02. ip. 94063:350.
- --7810110083 LER 78-059/03L-0 on 780908: Driginal bolted connections on containment isolation values MU-V2A/8 not taped properly caused by personnel error during construction.

 LENGEL R. A. Hetropolitan Edison Co. 78/10/02. Ip. 94063: 351.
- 7810110130 Forwards LER 78-058/03L-0. HERBEIN J. G. Metropolitan Edison Co. 78/10/04, 1p. 94378:359.
- --7810110134 LER 78-088/03L-0 on 780908: containment isolation valve MDL V1125 failed to close on manual initiation test signal. Baliseed event caused by dirty control relay contact. LENGEL.R. A. Metropolitan Edison Co. 78/10/04. ip. 94378:360.
- 7810180171 Forwards LER 78-035/03L-0. HERBEIN. J. Q. Metropoliten Edison Co. 78/10/05. ip. 94317:100.
- --7810180174 LER 78-055/03L-O on 780913: damper 4092-C failed to respond to close signal caused by drawing misinterpretation.

 * Metropolitan Edison Co. 78/10/05: 1p. 94317:101.
- 7810240125 Forwards LER 78-060/03L-0. BERBEIN, J. Q. Metropolitan Edison Co. 78/10/13. 1p. 00001:239.
- --7810240129 LER 78-060/03L-0 on 780915: trip setpoint of reactor bldg pressure switch 88-78-3987 was .01 psig greater than allowed. Caused by setpoint drift.
 87A1R.J. R. Hetropolitan Edison Co. 78/10/13. ip. 00001:240.

- 7810240131 Forwards LER 78-056/03L-0. HERBEIN, J. Q. Hetropolitan Edison Co. 78/10/16. 1p. 00001:2
- --7810240134 LER 78-056/03L-0 on 780917: while in Mode 2 & pullinrods to increase power, asymmetric elarm was activated. Caused by improperly operating reed switch. STAIR.J.R. Metropolitan Edison Co. 78/10/16. 1p. 00001: 2
- 7811090247 Confirms RD 78-62/1P on 781019:Action 8 for T.S. 3.4.6 not invoked when surveillance 2301-2301 showed unidentified leakage over 1 gpm. Caused by personnel error. 86ELINGER, J.L. Metropolitan Edison Co. 78/10/19. ip. 00002
- 7811090171 Forwards LER 78-062/017-0.
 HERBEIN J. O. Metropolitan Edison Co. 78/11/01. lp. 94038:1
- ---7811090174 LER 78-062/017-0 on 781019: misinterpretation of Tecled to increased frequency of performance of surveillance procedure: causing leakage limits to appear excessive.

 8TAIR.J. R. Metropolitan Edison Co. 78/11/01. 3pp. 94038:
- 7811090274 Forwards LER 78-061/03L-0. HERBEIN, J. Q. Hetropolitan Edison Co. 78/11/01 1p. 00002:1
- 7811210332 Forwards LER 78-066/03L-0. HERBEIN, J. Q. Metropolitan Edison Co. 78/11/15. ip. 94484:3
- --7811210336 LER 78-066/03L-0 on 781014: control rod drive trip be closed w/only one source range detector operable. Caused by inoperable power supply for one source range channel. LENGEL.R.A. Metropolitan Edison Co. 78/11/15. 2pp. 94484
- 7812050171 Forwards LER 78-053/03L-0. HERBEIN, J. Q. Metropolitan Edison Co. 78/11/29. ip. 94392:0
- --7812060177 LER 78-063/03L-0 on 781029: during shutdown ratchet Group 5 control rode occurred. Caused by incorrect installation of field change in three gate drive modules. LENGEL.R.A. Hetropolitan Edison Co. 78/11/28. ip. 94382:
- 7B1213027B Notifies NRC of a reportable accurrence discovered at meeting between facil & Babcock & Hilcor Station procedure EP-1202.26 directed operator to take action that kept Steam Generator from going up to 120".

 MURRAY.T.D. Toledo Edison Co. 78/11/28. 1p. 94213:249.
- 7812130199 Forwards LER 78-064/03L-0.
 HERBEIN, J. O. Metropolitan Edison Co. 78/12/04. 1P. 94306: 0
- ---7812130197 LER 78-064/03L-0 on 781107; borated water storage ta switches exceeded Tech Spec limit. Caused by switches out of calibr. LENGEL.R.A. Metropolitan Edison Co. 78/12/04. 1p. 94306;
- 7812200275 Forwards LER 78-067/03L-0. HERBEIN, J. G. Metropolitan Edison Co. 78/12/11. 1p. 94207:1
- --7812200278 LER 78-067/03L-0 on 781112: fuses blow in bettery ch 2-2A & 2-28. Caused by defective gating filter module in each battery charger. STAIR, J. R. Metropolitan Edison Co. 78/12/11. 2pp. 94207:
- 7812290092 Confirms RO 78-71/1P on 781208:control logic discrepa existed for make-up (HPI) pumps. KUNDER.G.A. Metropolitan Edison Co. 78/12/11. ip. 94190:11
- 7812260239 Forwards LER 78-068/03L-0. HERBEIN J. Q. Metropolitan Edison Co. 78/12/13. ip. 94159:3
- --7812260261 LER 78-068/03L-0 on 781113:noted that 12 diese1 gen load sequence timers' setpoints were outside Tech Spec limits. Caused by sepoint drift. 8TAIR.J. R. Metropolitan Edison Co. 78/12/13. 1P. 94139:3
- T. Hearing transcripts on non-antitrust matters
- 7812200331 Transcript of 781212 evidentiery hearing before ABLAS Includes questions on takeoff & landing speeds.Pp 224-320. A Atomic Befety and Licensing Appeal Panel. 78/12/12. 450pp 00003:105.

DOUNCE LE ITEMO

- DOCKET 50-321 EDWIN I. HATCH NUCLEAR PLANT, UNIT 1

 F. Security, medical, emergency & fire protection plans
- 7810100039 Forwards Amend 8 to Fire Protection Rept for operating lice DPR-57 & NPF-5. MHITMER, C. F. Georgie Power Co. 78/09/21. 2pp. 94033:050.
- --7810100045 Amend B to Fire Protec Prog Rept for subj fatil. Contains rev to show rooms prior to Amend 4. * Georgia Power Co. 78/09/21. 17pp.
- 7811030043 Ack 781011 phone conversation with 0111espie.10CFR2.790(d) exempts from pub disclosure activities involving safeguards & security measures & encl will not be placed in PDR.H/out encl.
 KENNA.M.B. Region 2. Atlanta. Bafeguards Branch. 78/10/24. 2pp. 02721:336.
- 7811220200 Responds to 780727 ltr forwarding Rev 2 to Emergency Plan: Rev 2 is acceptable inesmuches it merely consists of aditorial changes to previously approved Plan. incl Rev 1. 1PPCLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/26. 200.
- 7811280223 Forwards rev. "Shutdown from Outside Control Room. "procedures which are applicable to commitment contained in aval of fire protec prog. MHITMER.C.F. Georgie Power Co. 78/11/16. 36pp. 94012:093.
- Adjudicatory correspondence
- 7B10140146 Notice of Issuance of Amend#60 to Fecil/Oper Lic #DPR-57 on 7B1004 re fecil mod for fire protec.
 IPPCLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/04.
 2pp. 94421:162.
- J. Insurance & indemnity information
- 7811170205 Requests Transmittel of 5 signed originals of Amend 10 to Indemnity Agreement 8-69 to replace first 5 which were lost in transit.
 WHITMER.C.F. Georgia Power Co. 78/11/10. 1p. 94048:297.
- P. Operating license stage documents & correspondence
- 7811010062 Mods info in 780322 ltr to NRC, which responded to IE Bulletin # 78-03. Requests extension until 781231 for commitment to develop procedures for handling conditions which threaten integrity of off-gas sys.

 87AFFA.R.W. Georgia Pawer Co. 78/10/02. lp. 94302:354.
- 7811130093 Submits add1 info to mod 770613 ltr re response to infraction 1.A. 2.781031 extension will be necessary to install hardware & perform functional tests to aquip airlocke.
 8TAFFA.R. W. Georgia Power Co. 78/10/02. ip. 94113:275.
- 7810140051 Bafety Evaluation supporting Amend WAO to Facil Oper Lic WDPR-57 concluding that the probability of disruptive fires is small & mode to improve fire resistance capability for fire doors.dampers.fire barriers are acceptable. e Commissioners. 78/05/16. 31pp. 94421:101.
- 7B10140046 Forwards Amend #60 to Facil Oper Lic #DPR-57 rev Tech Bpace w/BaPety Evaluation & Notice of Issuance. IPPOLITO.T.A Operating Reactors Branch 3 (Pre 790625). 7B/10/04. 2pp. 94421:097.
- ---7810140049 Amend #60 to Facil Oper Lic #DPR-57 revising Tech Epecs re limiting conditions for oper & surveillance requirements for existing fire protoc sys & admin controls of subj facil IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625), 78/10/04. 2pp. 94421:099.
- --7810140053 Notice of Issuance of Amend #60 to Facil Oper Lic #DPR-57 on 781004.

 IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/04.

 2ps.
- 7B10160104 Responds to dreft Append I model Tech Specs issued by NRC on 7B0711 & forwards mark-up of sections of draft NUREQ-0473, WHITMER, C. F. Georgie Power Co. 78/10/06. 74pp. 94234:131.

- 7810240110 Proposes amend to Tech Spac for Oper Lic##DPR-97, substituting Core Maximum Fraction of Limiting Pur Density for Maximum Total Peaking Factor in determining Average Pur Range Monitor scram & rod block trip settings.

 WHITMER, C. F. Georgia Power Co 78/10/18 12pp.
- 7811120335 Summary of 780914 meeting w/GE representatives & MBTk 1
 Dwners Group re progress of Long Term Prog w/attendence
 list & agenda(RD-9-A-MBTk).Standards. 1
 GRIMER.C. Plant Systems Branch (Pre 791030). 78/10/26 47pp
- 7812260134 Forwards Reactor Containment Bldg Integrated Leak Rate Test for subj facil. MANRY.M. Georgia Power Co. 78/11/07. 1p. 94144:277.
- --7812260156 "Reactor Containment Bidg Integrated Leakage Rate Test."

 Type A & suppl verification tests performed in accordance
 w/tech specs using formulas from ANSI N45.4-1972 & BN-Top-1.

 Rev 1
 - MANRY, M. Georgie Power Co. 78/06/30. 70pp. 94144: 278.
- 7811200409 Forwards results of measurements of radioactive matl in NRC phanton on whole body counter. Encl 1 contains actual amount of each radionuclide present encl 2 gives ratio of measurements to DDE values & encl 3 gives recommendations. BUTHERLAND.J.T. Region 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/11/09. Spp. 94419:311.
- 7811210297 Notifies util of 781205 seminar in Atlanta to discuss new Model Rod Effluent Tech Space & encl seminar info sheet, registration form, & proposed agenda.
 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 79/11/09.
 5pp. 94488:131.
- 7811300066 Forwards NRC staff paper, Policy Bession Item(8ECY-78-554) relicenses reg performance evaluation. Three methods for evaluation are: statistical, trend analysis & regional survey method. W/o snct.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/18.
 200.
- 7812150164 Notice of workshops re implementation of training & qual requirements contained in Append 8 of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out math. Wanci Registration Form & List of Locations.
 MILLER.J.R. Assistant Director for Site & Bafeguards (Pre 791030), 78/11/13. 5pp.
- 7812180277 Forwards Rav#1 "Draft Radiological Effluent Tech Specs" for BHR's (NUREO-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREO-0133). ORIMES.B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/18. 6pp. 94337:012.
- 7812060003 Forwards Amend#61 to Fecil Oper LiceOPR-37 changing Tech specs as raquested in 780613 ltr. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 2pp. 94328:092.
- ---7812060009 Amend#61 to Fecil Oper Lic#DPR#57 rev Tech Bpecs to delete existing Append B Environ Tech Bpecs (ETB) & adopt ETB approved for Unit 2. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 61pp. 94328:094.
- --7812060013 Environ Impact Appraisal supporting Amend#61 to Fact1 Open Lic#OPR-B7 concluding that there will be no environ impact attributable to proposed action & no environ Impact statement need be prepared.
 - statement need be prepared.

 Office of Nuclear Reactor Regulation. Director. 78/11/16. Spp. 44328:155.
- --7812060119 Notice of Issuence of Amend#61 to Facil Oper Lic#DPR-57. IPPOLITO,T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. 2pp. 94328:160.
- 7812110035 Discusses possible dangers of LDCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/encl ANO: 97812080207. IPPCLITO-T. Operating Reactors Branch 2 (Pre 790625). 78/11/29. Bpp. 94408:141.
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings hell typroviding task-by-task activity summary for the month. BOBON.L. J. General Electric Co. 78/12/04. 11pp.

- 7812280170 Emphasizes importance of submitting accurate & complete info to NRC by licensee & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB, J.Q. Diffice of Inspection & Enforcement, Office of the Director 78/12/06 2pp. 94375.009.
- 7812270274 Forwards proposed amends to Tech Boscs & to Environ Tech Boscs of subj facils minus section on solid radioactive waste which is still under dev Requests delay of implementation to 790701 or later pending review completion. WHITMER, C.A. Georgia Power Co. 78/12/21. 400pp 94231:001
- 7811210367 Forwards addl info re multiple consecutive safety/ralisf valve actuation of Mark I containment program.
 SOBDN.L.J. General Electric Co 78/11/13. 3pp.
- G. Inspection reports. IE Bulletins & correspondence
- 7810130092 Ack receipt of 1E Inspec Rept#50-321/78-27 & #50-366/78-35 on 780724-0804 Does not consider any info therein to be proprietary STAFFA.R.H. Georgia Power Co. 78/09/27. lp.
- --7810130095 Forwards 16 Inspec Rept#50-321/788-27 & #50-366/78-35 on 780724-0804 during which no items of noncompliance were noted LOWS.F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 78/09/11 2pp.
- --7810130099 IE Inspec Rept#50-321/78-27 & #50-366/78-35 on 780724-0804 during which no items of noncompliance were noted. Major areas inspected included inspec to review LER plant open I Action in response to IE Circular 78-08.

 CANTRELL, F B . KLINOLER.O.R . VOOT-LOWELL.R. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/09/08. 9pp.
- 7810110089 Forwards proposed amend to Tech 8pecs which will upgrade the insvc inspec requirements per 10CFR55e(q)(4)(11). Proposed changes rely on standard Tech 8pecs.

 WHIPMER, C. F. Georgia Power Cp. 78/10/03. 31pp. 94066:258.
- 7811100168 Responds to 781003 NRC ltr re violations noted in Inspec Repts#50-321/78-30.#50-366/78-38 Corrective action: details withheld IAH 10CFR2 790(d). STAFFA:R.W. Georgia Power Co. 78/10/23, 1p. 94179:346.
- 7811100105 Act receipt of 781023 ltr informing NRC of steps taken to correct violations noted during inspec#50-321/78-30 & #50-366/78-3B KENNA, H.B. Region 2: Atlante: Safeguards Branch. 78/10/31. 1p. 94179:345.
- 7811130256 Ack receipt of 781027 ltr informing NRC of steps taken to correct violations noted during insper#50-321/78-29.#30-366/ 78-37. LONG, F. J LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/06 Ip.
- --7811130261 Responds to 781004 NRC 1tr re violations noted in Inspec Repts#50-321/78-29 & #50-366/78-37. Corrective actions: formal instruc to departmental supervisors on manning of work w/OC hold paints. STAFFA.R H. Georgie Power Co. 78/10/27, 2pp.
- --7811130262 Forwards IE Inspec Repts#50-321/78-29 & #50-366/78-37 on 780821-24 & Notice of Violetion. LONG.F. J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/04. 2pp.
- --78iii30268 Notice of Violation from inspec on 780821-24.
 Region 2. Atlanta, Office of the Director. 78/10/04. ip.
- --7811130286 IE Inspec Repts#50-321/78-29 & #30-366/78-37 on 780821-24 during which 2 items of noncompliance were noted failure to follow 2 different procedures 321/78-18-29-01 & 366/78-37-01
 - SKOLD9, J. L. Region 2. Atlanta, Office of the Director. 76/10/04. 700 94075: 238
- 7811150118 Forwards IE Circular 78-18. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/06.
- 7811220034 Act receipt of 1E Inspec Repts#50-321/78-31 & #50-366/78-39 on 780905-08. Does not consider any into therein to be proprietary. BTAFFA.R. H. Georgia Power Co. 78/11/13. 1p. 94336:007.

- --7811220059 Forwards IE Inspec Repts#50-321/78-31 & 50-366/78-39 on 780803-08 during which no Items of noncompliance were noted LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Brench. 78/10/20. 2pp. 94336-008.
- --7811220064 IE Inspec Repts#30-321/78-31 & #50-366/78-39 on 780903-08 during which no items of noncompliance were noted Major areas inspected included: lic operator requal training progr training prog for monlic personnel & plant tour.
 BRADFORD, H. H., TAYLOR, F. A., KELLOGO, P. J. Region 2. Atlanta.
 Reactor Operations Nuclear Support Branch. 78/10/19. 2pp.
- 7811280006 Ack receipt of IE Inspec Repts#50-321/78-32 & #50-365/78-40 on 780913-15. Does not consider any info therein to be proprietary STAFFA.R.W. Georgie Power Co. 78/11/13. 1p. 02726:314.
- --7811280008 Forwards IE Inspec ReptsW50-321/78-32 & #50-346/78-40 on 780913-15 during which no items of noncompliance were noted. LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/10/18 2pp.
- --- 7811280012 IE Inspec Repts#50-321/78-32 & #50-366/78-40 on 780913-15 during which no items of noncompliance were noted Major area inspected included: review of LER's rept procedure for 10CFR21 repts & fire equip inspec & off-gas sys hardware. CANTRELL, F.S., RILEY-B.W., DANCE, H.C., Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/18. Spp. 02726:317.
- 7812120063 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Safeguards Newsletter.
 KENNA-H.B. Region 2. Atlanta. Bafeguards Branch. 78/11/17. 4pp. 94278: 100.
- 7812070082 Act receipt of IE Inspec Repts#50-321/78-28 % #50-366/78-36 on 780815-19. Does not consider any info therein to be proprietary. STAFFA:R.W. Georgia Power Co. 78/11/20. 1p. 94347:348.
- --7812070097 Forwards IE Inspec Rept 50-321/78-28 & 50-366/78-36 on 780815-18 No items of noncompliance noted. LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/20. 2pp. 94347:349.
- --7812070148 1E Inspec Repts#50-321/78-28 & #50-366/78-36 on 780815-18 during which no items of noncompliance were noted. Major areas inspected incl:surveillance activity on pipe support & restraint sys for Unit 1 incl examination of procedures. HHITEMER. M. L. MARTIN, R. D. Region 2, Atlants, Office of the Director. 78/11/20. 9pp. 94347:331.
- 7812040310 Forwards IE Bulletin#78-12A.suppl to IE Bulletin 78-12. M/encl ANO:7811300055.

 M/encl ANO:7811300055.

 O'REILLY, J.P. Region 2, Atlanta, Dffice of the Director. 78/11/24.

 ip. 94129:176.
- 7812060343 Ack receipt of TE Inspec Repts#50-321/78-35 & #50-366/78-43 on 780828-1006. Does not consider any info therein to be proprietary. STAFFA:R.H. Georgie Power Co. 78/11/27. 1p. 94382:248.
- --7812060345 Forwards IE Inspec Repts#50-321/78-35 & #50-366/78-43 on 780828-1006 during which no items on noncompliance were
 - LONG.F. J. Regic Rep. 94382; 249. Region 2: Atlanta, Office of the Director. 78/11/07.
- --7812060350 IE Inspec Repts#50-321/78-35 & #50-366/78-43 on 780828-100 during which no items of noncompliance were noted hajor after them of noncompliance were noted hajor areas inspected incl:unit I plant operations. Unit 2 startup testing, lic access training & on-site comm meeting minutes. ROBERS.R.F., DANCE.H.C. Region 2. Atlanta, Office of the Director. 78/11/01. 6pp. 94382:251.
- 7812280286 Ack receipt of IE Inspec Repts#50-321/78-39 & 50-366/78-48 on 781130. Does not consider any info therein to be proprietary. STAFFA.R.W. Georgia Power Co. 78/12/14. ip. 94083:117.
- --7812280290 Forwards 1E Inspec Repts#50-321/78-39 & 50-366/78-4B on 781007-1110 during which no items of noncompliance were noted. LONG,F. J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/11/30. 2pp. 94083:118.

- ---7812280294 IE Inspec Repts#50-321/78-39 & 50-366/78-48 on 781007-1110 during which no items of noncompliance were noted. Major areas inspected incl:plant oper-startup testing minutes. Tech Bpec compliance & reportable occurrances.

 DANCE, H. C., RODERS, R. F., Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/11/20. 5pp. 94083:120.
- 7812280022 Forwards IE Bulletin 78-14.

 O'REILLY, J. P. Region 2. Atlanta. Office of the Director. 78/12/19.

 1P. 94131:056.
- 7810270018 Forwards 1E Circular #78-17. (See ANO: 7810230221. Docket 50-133.781013)
 D'REILLY, J. P. Region 2, Atlanta, Office of the Director, 78/10/13.
- R. Periodic operating reports & related correspondence
- 7810170141 Monthly Oper Rept for Sept 1978. WILSON-B.H. Georgia Power Co. 78/10/05. 7pp 94235:001.
- 7811180086 Forwards Monthly Open Rept for Oct 1978. MANRY.M. Georgia Power Co. 78/11/08. ip. 94133:182.
- ~~7811160068 Monthly Open Rept for Oct 1978. WILSON, S. Georgia Power Co. 78/11/05. 10pp. 94133:123.
- 7812130287 Forwards Monthly Open Rept for Nov 1978. MANRY, M. Georgia Power Co. 78/12/07. 1p. 94409:191.
- --7812150294 Monthly Oper Rept for Nov 1978. WILSON, S. Georgia Power Co. 78/12/05. 11pp. 94409:192.
- B. Reportable occurrences, LERs & related correspondence
- 7810170233 Forwards LERM78-077/01T-0.
 MANRY.M. Georgia Power Co. 78/09/25. 1p. 94236:316.
- --7810170237 LER#78-077/01T-0 on 780920: while under open-follow-up review of diesel generator control logic identified potential problem under LOCA & LOSP preventing diesel which failed or was shutdown from being restarted by control room.

 GREENE, T. Tennesses Valley Authority. 78/09/28. 3pp. 94236:317.
- 7810170256 Forwards LERW78-071/03L-0. MANRY, M. Georgie Power Co. 78/09/25. 1p. 94236:343.
- --7810170261 LER078-071/03L-0 on 780911: psak LHQR went from about 98% of limiting value to about 100.01%. Caused by inaccurate base distribs in process computer, resulting in erronsous calculation of LHQR in that region.

 GREENE.T. Georgia Power Co. 78/09/25. 2pp. 94236:344.
- 7810170291 Forwards LERW78-074/03L-0.
 MANRY.M. Georgia Power Co. 78/09/25. 1p. 94415:087.
- --7810170298 LERW78-074/03L-0 on 780913: During inspec of fire rated penetration seal repair in cable spreading room floor, 3 penetrations in calling were discovered which had not been sealed. Caused by ceiling limited accessibility.

 9REENE, T. Georgia Power Co. 78/09/25. Rpp. 94415:088.
- 7810180112 Forwards LERW78-073/03L-0.
 MANRY, M. Georgia Power Co. 78/09/27. ip. 94195:204.
- --7810180114 LERM78-073/03L-0 on 780912: firs seals in RPS vertical cable way were found to be breached at 130 k 147 elevations. Caused by feilure of constr crew to repair fire seals efter installing 2 cables thru RPS room.

 NIX:R.T. Georgia Power Co. 78/09/27. ip, 94195:205.
- 7810170329 Forwards LERN78-076/03L-0. MANRY.M. Georgie Power Co. 78/09/29, 1p. 94234:340.
- --7810180014 LER078-076/03L-0 on 780915:Refueling vent sthaust sensor gave false, high & erratic indication while at 99X reactor pum. Caused by failure of 0-M tube which was replaced NIX:R.Y. Georgia Power Co. 78/09/29. 1p. 94234:341.
- 7810180029 Forwards LERW78-075/031-0.
 MANRY.M. Georgie Power Co., 78/09/29. 1p. 94195:195.
- 7810180010 Forwards LERR78-078/03L-0. MANRY.M. Georgie Power Co. 78/10/06. 1p. 94422:012.

- --7810180011 LER#78-078/03L-0 on 780924: while in hot standby, discovered main steamline radiat monitor surveillance test had not been performed during hot standby due to personnel oversight. MANRY, M. Georgia Power Co. 78/10/06. 1p. 94422:013.
- 7810230175 Forwards LER#78-080/03L-0.
 MANRY-M. Georgia Power Co. 78/10/13. 1p. 94164:100.
- --7910230176 LER#78-DB0/021-0 on 780929: during normal release of bat liquid raduaste the Hi elerm trip of liquid raduaste radiat monitor terminated flow due to lab technician selecting wrong analyser. Cautioned lab personnel to be very careful. RODERS. M. H. Georgia Power Co. 78/10/13. 3pp. 94169:305.
- 7810310146 Forwards LER#78-079/03L-0 MANRY.M. Georgia Power Co. 78/10/13. ip. 94090:176.
- --7810310130 LER#78-079/03L-0 on 780928: main steam flow switch was overranged & made inoper by overpressurized DP cell Switch & other redundant Barton instru with snubbers in mensing line were checked & varified to be clear.

 ORESMETTU. Opengia Power Co. 78/10/13. 2pp. 94090:177.
- 7810310157 Forwards LERM78-082/00L-0.
 MANRY M. Georgia Power Co. 78/10/20. 1p. 94090:211.
- --7810310162 LER#78-082/03L-0 on 781010. After SB0T fan removed from w/reactor in run mode, other SB0T train not run w/in 4 hours to prove operability. Requirement fargotten during work on other SB0T. Personnel responsible admonfehed.

 BAXLEY, B. X. Georgia Power Co. 78/10/20. 2pp. 74090: 212.
- 7810310165 Forwards LER#78-084/03L-0.
 MANRY-M. Georgia Power Co. 78/10/23. 1p. 94090:225.
- --7810310171 LER 78-084/03L-0: on 781014, secondary containment broken Caused by opening of both turbine bldg roof access airlock doors staultaneously Personnel admonished.
 BAXLEY, B. X. Georgia Power Co. 78/10/23. 1p. 94090: 226.
- 7810310117 Forwards LER #78-068/3L-0. MANRY-M. Georgia Power Co. 78/10/24. lp. 94093:330.
- --TBIG310182 LER #78-086/03L-0 on 781016:Peak LHQR rose to 100.2 per after calibration. Caused by spatial senon variations, which induced slightly non-conservative calculation of the LHQR in affected region.

 OREENE, T. Gaorgia Power Co. 78/10/24. 2pp. 94093:331.
- 7810310160 Forwards LERM78-083/03L-0. MANRY,M. Georgia Power Co. 78/10/25, 1p. 94090;218.
- --7B10310166 LER #7B-0B3/03L-0: on 7B1011; water discovered in starter Caused by low pressure inside diesel bldg: low pressure pulled moisture-laden air into diesel bldg pullbox. Moisture condensed t collected in starter box.

 NIX.R.T. Georgia Power Co. 7B/10/25. 1p. 94090:219.
- 7811060131 Forwards LER#78-088/03L-0 MANRY-M. Georgia Fower Co. 78/10/30. 1p. 944Q4:201.
- --TBi106013B LER#78-08B/03L-0 on 7Bi02i:CMPF found to be R. 562 while about B2% during load increase Did not drop aignificantly after 2 hours. Caused by CMPF increased during large zenon transient increase faster than correctable. GREENE, T. V. Georgia Power Co. 7B/10/30. 1p. 94424:202.
- 7811060135 Forwards LERW78-081/03L-0. HANRY: M. Georgia Power Co. 78/10/30. Ip. 94424:207.
- --7811060140 LER#78-081/03L-0 on 781005: during repair work the valve seat for P41-F3138 blew out Caused by removal of piping 8vc Hater Streiner backwash line.Rev to be made. BAXLEY,8.X. Georgia Power Co. 78/10/30. 2pp. 94424: 208.
- 7811140156 Forwards LERW78-089/031-0.
 MANRY.M. Georgia Power Co. 78/11/02. 1p. 94383:306.
- --7811140162 LER#78-089/031-0 on 781022: severs arcing observed at sx collector ring of 831-8001A. "A" M. O. set tripped before it could be removed from svc. Bolts used to fasten brush holders to yoke assembley caused brushes to arc.
 NIX-R.T. Georgia Power Cq. 78/11/02. 2pp. 94383:307.
- 7811210342 Forwards LER478-090/03L~0.
 MANRY-M. Georgia Power Co. 78/11/13. ip. 94484;340.

- --7811210346 LER#78-090/03L-O on 781028 at 95% rated pur.LPRM calibr GD-1 was performed changing CMFLPD from 0.97 to 1.004 Flow was reduced after which peak LHGR was reduced to 99% of its limit Caused by inaccurate base distrib in computer. OREENE, T. Georgia Power Co. 78/11/13 1p. 94484-341
- 7811R20026 Forwards LER#78-091/03L-0 MANRY,M Georgia Power Co. 78/11/14. 1p. 94308:359
- --7811220028 LER#78-091/03L-0 on 781031: surveillance of fire protec equip & circuitry (Procedures HNP-1-3356 & HNP-1-3360) had been neglected due to personnel oversight. Importance of fire detector surveillance reemphasized to personnel. NIX.R.T. Georgia Power Co. 78/11/14. 1p 945 94308: 360
- 7811210361 Forwards LER#78-092/03L-0, MANRY-M, Georgia Power Co 78/11/13, 1p. 94485:052
- --7811210366 LERM78-092/03L-O on 781101; a main steam line radiation monitor (Dil-M603D) failed to initiate a helf scram during a test.Caused by a loose wire which had damaged some components. NIX.R T. Georgia Pawer Co. 78/11/15. Ip. 94485-053
- 7812060392 Voids LER#50-321/78-89. MANRY, M. Georgia Power Co. 78/11/16. 1p. 94382 350.
- 7812070033 Voids LER#50-321/78-87. Georgia Power Co. 78/11/16. tp 94127.235. MANRY, M
- 7811280242 LER#78-093/03L-0 on 781109 during normal oper core drills were made thru diesel generator room walls to allow conduit to be run thru walls. Fire watch established per Tech Specs. NIX.R.T. Georgia Power Co. 78/11/20. 1p. 94012 133.
- 7811280235 Forwards LERM78-093/03L-0. HANRY.M. Georgia Power Co. 78/11/20. 1p. 94012:154.
- 7812180164 Forwards LER#78-094/03L-0. HANRY, M. Georgia Power Co. 78/11/20. 1p. 94366: 032.
- --7812180170 LER#7B-094/03L-0 on 781120; during NRC audit it was found that RHR time delay relay E11-K126 had been left in uncalibrated state from 780412 to 780627. Redundant relays Eii-Ki25 A & B were functioning Procedures will be rev. QREENE.T. Georgia Power Co. 78/11/20. IP. 94366:033.
- 7812180165 Forwards LER#78-089/03L-0.
 MANRY.M Georgia Power Co 78/12/08. 1p. 94366:034.
- --7812180169 LERM78-089/03L-0 on 781027; severe arcing at exciter collector ring of B31-8001A tripping A*M0 set causing ring k brushes to burn. Caused by bolts used to fasten brush holders to qute assembly having insufficient length.
 NIX.R.T. Georgia Power Co. 78/12/09. 2pp. 94366:035.
- 7812270290 Ferwards LER#78-043/03L-1.
 MANRY.M. Georgia Power Co. 78/12/14. ip. 94229;313.
- --7812270285 LERW78-043/03L-1 on 780609: procedure HNP-1-3902, "Safety Relief Valve Functional Test" tried unsuccessfully on 2 solenaids. One failed due to bent plunger; other failure due to glunger not properly secured to actuating springs. GREENE.T. Georgia Power Co. 78/06/30. 2pp. 94227:314.
- 7812270295 Forwards LER#78-054/03L-1. MANRY, M. Georgia Power Co. 78/12/18. 1p. 94229: 347.
- --7812270296 LER#78+054/03L-1 on 780710; shock suppressor RHRH-229 found to be low on fluid, Caused by leaking "D" ring seal.
 NIX:R. T. Georgia Power Co. 78/12/18. ip. 94229:348.
- 7812270315 Forwards LER678-095/03L-0. MANRY-M. Georgia Power Co. 78/12/18. ip. 94230:352.
- --7812270318 LER#78-095/03L-0 on 781130:refueling floor vent exhaust sensor(Dii-NOi2C)gave false high indication Caused by sensor mounted in such a way as to allow rain water to enter. NIX-R. T. Georgia Power Co. 78/12/18. 1g. 74230:353.

- DOCKET 50-322 SHOREHAM NUCLEAR POWER STATION A Application/construction stage documents & correspondence
- 7810|10307 Ack receipt of proposed agreement re "Disclosure of Confidential Info" filed 740817, whithis is satisfactory.
 Requests inspec of proprietary GE reptimeeds permission from HAND.R.C. Reilly & Like. 78/09/25: 4pp. 94061:012
- 78:0:80:75 Notice of meeting on 78:006 to discuss subj facil MarkII Closure Prog. WILSON.J.N. Light Water Reactors Branch 4. 78/10/02. 3pp. 94317:107
- 7010270394 Response to 780919 ltr informing recipient that GE offices in Ban Jose & Topical Rept#21021-P will be made available for inspec Draft "Agreement Re Disclosure of Confidential Commercial Info" encl. WHITTEMORE,F.C. Hunton & Williams. 78/10/04. App. 94033:273.
- 7810100017 Forwards add1 info requested during NRC Reactor Bys Branch meeting of 780928 re coolent water to recirculation pump, scram capability, line break, new computer codes, & RCPB leakage detection. NOVARRO, J.P. Long Island Lighting Co. 78/10/05. 5pp.
- 7B10270001 Surmary of trip to subj facil by Reactor Sys Branch representatives to tour facil & discuss RSB open items.
 Expects submittal of addl info re items discussed. W/encl list attendees.
 - MILLE, W. R. Division of Systems Safety. 78/10/11. 3pp. 94056:053.
- 7810200231 Summary of meeting of 781005 to discuss subj facil's containment closure prog. Issues discussed include applicant LIL's plan to use Tee-Quencher loads rather than Rams Head loads & plan to combine OBE & BRV loads by BR89. WILBON, J. N. Light Water Reactors Branch 4. 78/10/13. 4pp. 94081:272
- .7811130360 Summarizes 781019 masting w/Mark 2 Owners Group to discuss Staff's Mark 2 Containment Acceptance Criteria, Jattendess list meeting handouts summary of owner's position & final disposition of criteria for add1 review by etaff, PELTIER. I.A. Light Water Reactors Branch 1. 78/11/01. 78/11/01, 37pp. 94009: 087.
- 7811130258 Notifies D89 of forthcoming meeting w/representatives from Mark 2 Owner's Group on 781115 at Bethesda MD to discuss LOCA/BRV submerged structure drag loads for lead plants. ANDERSON.C.J. Containment Bystems Branch (Pre 790101). 78/11/02.
- 7811280097 Forwards Rav#1 Draft Radiological Effluent Tech Spac for PRR's(NUREG-0472) & "Preparation of Radiological Effluent Tech Spac for Nuc Pwr Plants"(NUREG-0133). W/enc1 ANO: 7811270173 & 7811270180.
 VASBALLD. D. B. Assistant Director for Light Hater Reactors. 78/11/16. 5pp. 03584:274.
- 7811280044 Responds to 781107 NRC request for new lic appl plans. Has no new lic appl plans between now & 811231. WDFFDRD.A.W. Long Island Lighting Co. 78/11/17. ip. 02726:333.
- 7812070152 Notice of seminar on 781208 on new Model Rediclogical Effluent Tech Boses for nuc pur plants. Requests advance a Effluent Tech Boses for nuc pur plants. Requests advance submission of seminar specific questions. Myencl Seminar Info Bheet: Proposed Agenda & maps.

 ORIER: 8.H. Region 1. Philodelphia. Office of the Director. 78/11/21. 8pp. 94375: 232.
- 78:2080223 Summary of 78:019 meeting Discusses intent on future effort toward completion of staff review of mark II generic acceptance criteria for lead plants Expects delay in overall review of Intermediate Prog Tasks Wiencl tasks & criteria. BOYD.R.S. Division of Project Management. 78/11/24. App. 94:37:10A 94137: 106.
- 7812280162 Emphasizes importance of submitting accurate & complete inf to NRC by licenses & applicants. Info submitted must be substantisted by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J.O. Dffice of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94311:352.
- 7812200134 Notice of 781215 meeting in Betheeda.MD to discuss Shoreham design for containment isolation & leak test.
 H1LBON.J.N. Light Hater Reactors Branch 4. 78/12/08, 3pp. 94159: 002.

- 7812200131 Notice of 781214 meeting in Bethesda MD w/applicant to discuss unresolved issues in facil review. WILSON, J.N. Light Water Reactors Branch 4 79/12/12. 2pp. 94156.297
- 7812260126 Forwards Rev#3 to Plant Design Assessment Rost for BRV & LOCA loads. W/Executive Summary of Mark II Loads Closure Prog. Final rev will be submitted in June 1979.
 NQVARRO, J.P. Long Island Lighting Co. 78/12/18. 7pp. 94026:001.
- --7812260129 RevN3 to Plant Dasign Assessment Rept for SRV & LOCA loads. Provides info on load definition load combination methods. Acceptance criteria & plant capability to accept hydrodynamic loads # Long Island Lighting Co. 78/12/18 400pp. 94026-008.
- 7812260196 Forwards Proprietary Suppl to BNRC-347. "Design Analysis Rept Rev 3. " Document withheld from pub disclosure.pursuant to 2.790 NDVARRO.J.P. Long Island Lighting Co. 78/12/11. Ip
- 7812260221 Forwards NRC request for add1 info contained in BA Varga ltr to AH Hofford dtd 780831; struc assessment of sacrificial shelld wall under effects of annulus pressurization & rev response #23, previously submitted.
 NOVARROUP. Long Island Lighting Co 78/12/20 19pp 94160.026.
- 7812290005 Summary of Meeting on 781213 w/Mark 2 Owners Group to discuss Staff's Mark 2 containment acceptance criteria W/ettendance list & meeting handouts encl.
 ANDERSON, C. J. Containment Systems Branch (Pre 790101). 78/12/20. 95pp. 94207 239.
- F. Security, medical, emergency & fire protection plans
- 7812140166 Forwards add1 info re fire analysis in response to requests from SA Varga to AN Wofford dtd 780627 & 780809 re fire equip & fire hezards NOVARROJ J.P. Long Island Lighting Co. 78/12/11. 150pp. 94088.022.
- 78:2140:105 Forwards comments on 780808 version of Amended Physical Becurity Plan for subj facil. Encl withheld from disclosurg pursuent to 2.790.
 ROSE D. G. Los Alamos Scientific Laboretory. 78/12/12. jp.
- 9. Adjudicatory correspondence
- 7810160201 Hotion in apposition to Intervenor BUCO's Motion of 780919 > seeking an indefinite amount of time to respond to applicant LIL's interrogs of 771208.19 Motion is granted a deadline of not later than 781016 for BUCO's answer is sought.

 WHITTEMORE, F. C. Hunton & Williams. 78/10/02. Spp. 94092: 346.
- 7810270301 Advises of status of MHB rept on County contentions in proceeding. MHB proposal will be further delayed due to submission of resolution to be voted on by full legislature. LIKE I. Reilly & Like. 78/10/03. 2pp. 06403.356.
- 7810230130 Notice that J.P. Novarro has replaced T. J Burke as facil Proj Mgr. wHITTEMORE.F.C. Hunton & Williams. 78/10/11. ip. 94165:070.
- --7810230133 Notice that J.P. Noverro has replaced T. J. Burke as facil Proj Hgr. MCFFORD, A. W. Long Island Lighting Co. 78/10/05. 1p. 94165:071.
- 7810250003 Order Relative to Discovery Schedule, If Suffelk Legis approves funding for HHB on 781024, then Suffelk will file response to interrogs by 781113.
 SDHERBIE, B. Atomic Safety and Licensing Board Penel. 78/10/12.
 2pp.
- 7810300218 Affidevit in Opposition. H Blau is atty for Consolidated Intervenors Oil Heat Inst of Long Island. Inc. & the North Shore Comm Against Thermel & Nuc Pollution. Affidevit responds to 780818 Motion to Impose Banctions w/cert of svc. BLAU.H.L. Affiliation Unknown. 78/10/12. 3pp. 94034:098.
- 7811020325 Forwards recent memorands re-certain problems experienced in connection w/pipe support base plats design Staff is determining if these problems have generic implications for oper fecils & will keep Lic Bd informed of any new info. GRAY, J.R. Diffice of the Executive Legal Director 78/10/19. 1p. 94240: 221.

- --7811020332 Forwards 780628 memo to R Mattson, re info on failures of safety-related pipe supports at Millstone i & design deficiencies on similar equip on Shoreham i. Hemo gives Dd notification of pipe support base plate design STELLO, V Division of Operating Reactors 78/09/28. 2pp. 94240 222
- --7811020343 Addresses pipe support base plate problem Discusses review of support redesigns & capability of the anchor bolts to uithstend cyclic loadings.

 NONANLV S Engineering Branch (Pre 791030) 78/06/02. 2pp 94260,228.
- 7811200002 Dn 781024 Suffort County Legis authorized preparation of rept as requested by staff & applicant. Hill attempt to complete rept by 781113.

 LIKE I. Reilly & Like. 78/10/25 ip. 94215:220
- 7811070023 Order Granting NRC Staff Hotion of 780818 to Impose Sanctions Consolidated Intervenors have frustrated Bieff's Efforts & have not complied w/Bd orders Staff's motion for dismissal of Intervenor's Contention 7(g) is granted. BUMERS.E 8 Atomic Safety and Licensing Board Penel. 78/10/27 2pp. 94037:132
- 7811300373 Request by BUCO that applicant LIL produce any & all documents reparding communication between LIL & GE relatter's Reed Task Force Rept Cert of Buc encl. LIKE.1. Suffolk County, NY. 78/10/30. 3pp. 94116:360.
- 7811200008 Forwards NRC & Appeal Bd decisions to subj facil, dealing w/ treatment of issues relevant to issuence of 100FR70 lic to store unitradiat nuc fuel assemblies at facil under constrption to issuence of oper lic W/encl 1976 NRC Decisions. HDEFLING.R. K. DFFLE of the Executive Legal Director 78/11/03 26pp. 94215, 230
- 7811200022 Lic appl has been placed in the local PDR. Staff expects to complete raview & issue Part 70 lic to store new fuel at site.

 HDEFLING, R. K. Diffice of the Executive Legal Director 78/11/03.

 19. 94215:288
- 7B12110012 Requests extension of time from 7B1113 to 7B1100 to respond to Bd's "Order Relative to a Discovery Schedule" directing Buffolk County to file responses to interrog. Delay due to lack of funding for county consultents. MHB Tech Assoc. LIKE I. Reilly & Like. 7B/11/10. ip 94339:259
- 7012110201 Applicant LIL's Reply to intervenor Buffolk County's Reques 2 for production of documents LIL objects to request on basis that all documents sought are trial preparation matl4 that LIL has not satisfied 10CFR2.740(b)(2).
 WHITTEMORE, F. C. Hunton & Williams. 78/11/17. 2pp. 94203:237.
- 7812210471 Comments on 2 interrogatories by Suffail County answering Applicants' Second Interrogatories of 781026 re why Criterian 3 mandates tests for suitability of math selection design & bases for higher source terms for accidents. LIKE 1. Reijly & Like. 78/11/21. 2PP 74393:358
- 7812140026 Forwards rev Section 5.7 of FES dtd Oct 1977, NUREG-0285 HOEFLING.R. K. Office of the Executive Legal Director. 78/11/28. 9pp. 94127:191.
- 7812140342 Recipients may attend any pub hearing on suby faciles stated in encl 780628 Fed Register Notice. & will be routinely placed on distrib list for relevant maeting notices & summaries.

 HOEFLING, R. K. Diffice of the Executive Legal Director. 78/11/28.
 2pp. 03557:165
- 7812260322 Motion by intervenor Buffolk County to compel applicant LIL & GE to produce documents sought by Buffolk County on 781030. Asserts Lit. & GE must show that documents are "trial preparation matis."Cert of Svc encl.

 LIKE 1. Buffolk County, NY. 78/11/28 5pp. 94160: 111.
- 7812210411 Reviews status of all contentions raised by intervenor Buffolk County in proceedings re subj fecils. Tech bases & supporting documentation for each combention are provided. Cart of Bvc encl. LIKE I. Buffolk County, NY. 78/11/30. 145pp. 94014:012.
- 7812270042 NRC Steff Motion for an Extension of Time from 781211 to 790112 w/in which to file a motion to compel responsive answers to its interrogs Cert of Svc enci. HQEFLING.R.K. Office of the Esecutive Legal Director. 78/12/08. Spp. 94160:219.

- 7812210297 Grants NRC Steff's Motion for extension of time until 790112 to file a notion to compel Suffolk County to provide responsible ensuers to interrogs submitted to Suffolk County on 780313 SOMERS.E 5 Accoic Befety and Licensing Board Panel 78/12/12 2pp 94101 357
- 7812280333 Applicant's Answer to SC's Motion to Compel Subj util urges Suffoli County's motion be denied Showing request based on false premises is one of the reasons for urging denial Cert of Bvc encl WHITTEPORE.F C Hunton & Williams 78/12/13 6pp 03555.146.
- 7811210110 Intervenor SUCO's suppl response to applicant LIL's second set of interrogs re inclusion of credible large accidents, containment sys design verification & transient condition design verification Cert of Svc encl
 LIKE 1 Suffolk County, NY 78/10/26 Spp. 94482-167
- H. Utility Final Bafety Analysis Report (FSAR) & amends
- 781020009) Notice of Svc of Amend #29 to Lic Appl. Consisting of FBAR Rev #13 MCCAFFREY. B R Long Island Lighting Co. 78/10/12 ip. 94367:091.
- 7812260136 Forwards Amende30 to Lic appl for subj facil, consisting of Revel4 to FSAR Rev contains analysis of pipe failure outside containment for both high & moderate energy systems Corrections to FSAR also included MOFFORD. A N Long Island Lighting Co 78/12/18. 2pp. 94141:001.
- --7812260139 Amend#30 to lic appl for subj facil.consisting of Rev#14 to FEAR
 + Long Island Lighting Co 78/12/18. 300pp. 94141:003.
- D Advisory Committee on Reactor Bafeguards reports & correspondence
- 7811240157 Notice of 781128-30 meeting in 8an Francisco w/ACRS Fluid Dynamic Subcommittee re Mart II LOCA & SRV pool dynamic loads & load combinations.
 ANDERSON, C. J. Containment Systems Branch (Pre 790101). 78/11/13. 3pp. 94456-261.
- --7811240161 Agenda for 781128-30 ACRB meating in Ban Francisco of Fluid Hydraulic Dynamic Effects Subcomm re Mark II LDCA & BRV pool dynamic loads & load combinations. ANDERSON, CJ. Containment Systems Brench (Pre 790101), 78/11/13. 3pp. 94436-264
- G Inspection reports, IE Bulletins & correspondence
- 7810160295 Forwards IE Builetin878-12: "Atypical Weld Material in Reactor Pressure Vessel Helds" requesting action w/in 60 days. & list of IE Bulletin issued in 1978. (see ANO 7810040283) ORIER. B. H. Region 1. Philadelphia. Office of the Director. 78/09/29. 6pp. 94007:013.
- 7811300303 Forwards IE Inspec Rept#50-322/78-14 on 780913-13 during which no items of noncompliance were noted.

 8RUNERS. J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/10. 2pp.
- --7811300306 IE Inspec Rept#50-322/78-14 on 780913-15 during which no items of noncompliance were noted Major areas inspected incl:admin controls sched for completion of sus & tests, status of procedure completion & facil inspec.

 SHEDLOBKY.J.T., SRI0961.E. Region I. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/10. 3pp.
- 78:0180074 Forwards reve to Presvo Inspec Prog Plen for subj facil: Rev80 for ultremsonic examination procedures for piping welds & Rev80 for ultrasonic examination procedures for closure head welds.

 NOVARRO, J. P. Long Island Lighting Co. 78/10/11. 7pp. 94421:264.
- 7811060195 Forwards IE Circular878-17. (See ANO:7810230221, Docket 850-133, 78013.) 97. ORIER. 8. H. Region I. Philadelphia, Office of the Director. 78/10/13. 1p. 94489:176.
- 7812120022 Forwards IE Insp Rept 50-322/78-15 on 780925-29 & notice of violation. CARLBONR. T. Region i, Philadelphia, Reactor Construction & Engineering Support Stanch. 78/10/17. 3pp. 94277:323.
- --7812120024 Notice of Violation from insp on 780926-29.

 Region 1. Philadelphia. Office of the Director. 78/10/17. ip.

- --7812120026 IE Insp Rept 50-322/78-13 on 780926-29 Noncomplience noted: failure to use qualified procedure for welding pipe support. IOTH-A-D. Region 1, Philadelphie. Office of the Director. FABANO.A.N., MCGAUGHY.R.W. Region 1. Philadelphie, Reactor Construction & Engineering Support Brench. 78/10/17. 10pp. 94277:327.
- 78iii40229 Ack receipt of 78i0i8 ltr informing NRC of steps taken to correct violations noted during inepec#50-322/78-12.

 CARLBON.R.T. Region i, Philadelphia, Reactor Construction & Engineering Support Branch. 78/11/02. 1p. 94400:070.
- --7811140234 Responds to 780830 NRC ltr re violations noted in Inspec Rept#50-322/78-12 Corrective actions weld technique sheet issued & slip-on Plange welds to be inspected MOFFORD A.M. Long Island Lighting Co. 78/10/18.
- --7811140239 Forwards IS Inspec Rept#30-322/78-12 on 780808-11 k Notice of Violation.
 CARLSQN.R.T Region 1. Philadelphia. Reactor Construction k Engineering Support Branch 78/08/30 2pp. 94400:074.
- --7811140243 Notice of Violation from inspec on 780808-11. CARLBON.R.T. Region i, Philadelphia, Office of the Director. 78/08/30. 2pp. 94400:076.
- --7811140249 IE Inspec Rept#50-322/78-12 on 780808-11 during which 2 items of noncompliance were noted:single-bevel-groove weld joints for pipe restraints were 30 degrees, pipe spool slip- on flange less than quarter-inch.

 TOTH.A.D. Region 1, Philadelphia, Office of the Director.

 DURR.J.P. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 78/08/30. 9pp. 94400:078.
- 78:11290188 Forwards IE Gircular #78-18. "UL Fire Test. "W/enc1 AND: 78:1130002.

 ORIER.8.H. Region 1, Philadelphia, Office of the Director. 78/11/06. 1p. 94239:219.
- 7812150169 Forwards 1E Bulletin#78-12A.suppl to IE Bulletin#78-12. W/encl ANO: 7811300055. ORIER.8.H. Region 1. Philadelphia. Office of the Director. 78/11/24. 1p. 94212:257.
- 78:2290254 Ack receipt of 78:120 ltr informing NRC of steps taken to correct violations noted during inspect80-322/78-12. CARLBON.R. T. Region i- Philadelphia. Reactor Construction & Engineering Support Brench. 78/12/04. ip. 94:91:278.
- --7812290258 Responds to 780830 NRC ltr re violations noted in Inspec Rept#50-322/78-12-01. Corrective actions: eval of sampling inspec of undersized welds on pipe stool slip-on flanges indicate defects on class 150 & 301. Repairs will be made, WOFFCRD. A. W. Long Island Lighting Co. 78/11/20. ip. 94191: 299.
- 7812270469 Ach receipt of 781124 ltr informing NRC of steps taken to correct violations noted during inspec#80-322/78-15. CARLSON, T. Region J. Philadelphia. Reactor Construction & Engineering Support Branch. 78/12/06. 1p. 94016:001.
- --7812270478 Responds to 781017 NRC ltr re violations noted in Inspec Rept850-322/78-15. Corrective actions: tubular pipe supports having Blowed Tea Joints reviewed & those having angle less than 60 degrees identified. MO
- S. Reportable occurrences, LERs & related correspondence
- 7810270190 Repts deficiency w/miscellaneous elec fittings used in the installation of cable tray & conduit supplied by vendor not listed in field use spec. No corrective action required. NOVARRO, J. P. Long Island Lighting Co. 78/10/10. 3pp. 94054:237.
- 7811130172 Ack receipt of 781010 ltr re cable tray & conduit support fittings certifications. Rept will be reviewed & evaluated & util will be contacted if further info is required. CARLBON, R. T., Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 78/11/01, 1p. 74242:346.
- 7812070:10 Ack receipt of 78:103 final rept re pipe break outside containment. GARLBONR. T. Region 1, Philadelphia, Reactor Construction & Engineering Support Brench. 78/11/21. ip. 94271;191.
- --7812070115 Final Deficiency rept on Pipe Break Gutside Containment, S&W Computer prog resulted in nonconservative temp predictions. Corrective action: new computer model & environ analysis of temp conditions. Equip eval is in progress.
 NOVARGU.J.P. Land Island Lighting Co. 78/11/03 488. 98071.108

- 7812260211 Rept of deficiency in Beiley Controls pur supplies installed in 10 Category I apple principally HVAC analog instrumentation control loops. All potentially defective pur supplies will be replaced.

 NOVARRO J P. Long Island Lighting Co. 78/12/11. 2pp. 94160:175.
- 7812260215 Deficiency rept on installation of socket weld fittings on Category I schedule 160 small bore pipe. All fillst welds for socket weld fitting attachments will be inspected for proper fillet leg length NOVARROLUP Long Island Lighting Co. 78/12/11. 4pp. 94162:094.
- DOCKET 50-323 DIABLD CANYON NUCLEAR POWER PLANT. UNIT 2

 A. Application/construction stage documents & correspondence
- 7811210113 Forwards 781107 ltr to Chairman Hendrie re ACR8 review of appl for permits to oper subj facil STOLZ-J.F. Light Water Reactors Branch 1 78/11/14. 3pp. 94482:172.
- 7812010010 Forwards staff eval of probabalistic seismic risk assessment covering: POE studies on probabilities of earthquakes & resulting ground acceleration at site. & probabilities of various consequences
 BTOLZ.J.F. Light Water Reactors Branch 1. 78/11/21, 3pp. 94409: 128
- --7812010014 Discusses PQE studies in 1977-78 on probabilistic eval of earthquake hazard.Various assumptions are questioned. STEPP.J.C. Geosciences Branch. 78/05/08. 4pp. 94409:131.
- --7812010015 Forwards staff eval of Amend 52 to lic appl re Risk to Pub from Beismic Events. BUHL-A.R. Probabilistic Analysis Branch (Pre 791030). 78/09/08. 7pp. 94409:135.
- --7812010019 Clarifies certain points of eval of analysis of risk to pub from seismic events contained in 780908 memo. Covers probability of Core meltdown, & earthquake probabilities. BURL.A.R. Probabilistic Analysis Branch (Pre 791030), 78/11/06. 2pp. 94409: 144.
- 7812120161 Forwards 8 requests for exemption from ABME Code Bection 11 pump & valve testing requirements. Requests 1 thru 4 are continuations of attachments 7 & 9 to 771010 PGE 1tr recompliance w/Bection 50.59a(g).10CFR50. CRANE.P.A. Pacific Gas & Electric Co. 78/12/06. 10pp. 94276:343.
- 7812210200 Beismic test procedure for 125 volt DC switchgear, distribution panel & mold case circuit breakers. PATTERSON, H. OGAD, L. F., SHIPHAY, Q. D. Pacific Gas & Electric Co. 78/11/28. 34pp. 94279:031.
- 78:0140114 Forwards matl in support of open lic appl re environ qualification of equip. Requests ack of receipt of Matl. CRANE, P. A. Pacific Gas & Electric Co. 78/09/21. 16pp. 94421:081.
- 7810130038 Forwards responses to informal questions posed by 780804 NRC memo on seismic qualifications. Submission is nonproprietary version.

 CRANE.P. A. Pacific Gas & Electric Co. 78/09/22. 64pp. 94081:184.
- 7810190071 In response to 780321 NRC request for add1 info on containment purping forwards enswers to questions dreft Tech Specs & rept on "Analysis of Off-Bite Exposures due to LOCA coincident w/Containment Purging."

 CRANE.P.A. Pacific Gas & Electric Co. 78/09/27. 106pp. 94323:001.
- 7810170179 Forwards response to 780728 ltr re reactor vessel metl properties noncompliance w/10CFR50, Appendix G. fracture toughness requirements. & 10CFR50, Appendix H. reactor vessel metl surveillance prog requirements.

 CRANE_P. A. Pacific Gas & Electric Co. 78/10/02, Spp. 94270:073.
- 7810310226 Forwards responses to 780728 NRC ltr re reactor vessel metl properties noncompliance w/10CFR50 toughness & surveillance requirements. Requests ack of receipts.

 CRANE.P.A. Pacific Gas & Electric Co. 78/10/02. 8pp. 94090:339.
- 7810170221 Submits info re "degraded grid voltage" as result of discussions w/Instrumentation & Control Sys Branch reviewer on 780929 as suppl to previous submittals on second level under/over voltage protec, Design is acceptable by ICSB rev. CRAME.P.A. Pacific Qes & Electric Co. 78/10/04. ip. 94236:165.

- 7810230038 Ack receipt of 780906 ltr re subj facil Provides info or saismic assessment of site decomm estimate & waste mgt.
 DIRCKS.H.J. Defice of the Executive Director for Operations.
 78/10/06. 3pp. 94052:333
- ~~7810230042 Requests addl info re issuance of constr permit. BURTON.P. House of Rep. 78/09/06. lp. 94052:338.
- 7811290294 Trip rept:plant visit & mesting w/seplicant on 780905 to discuss remaining open issues re-subj facil. W/summary of remaining unresolved issues
 KUQ.P.T. Structural Engineering Branch. 78/10/06 4pp. 94239:
- 78:0370205 Attached Table & 3-10, which appeared in Amend 67, has been changed as indicated to reflect Staff's concerns releded valves position & function. Change to be documented in future amend. Five copies of submittal sent to D. Allison. CRAME.P. A. Pacific Gas & Electric Co. 78/10/10. 2pp. 94235:33
- 7810160118 Forwards amend fee per 780811 & 23 requests for extension const completion dates of CPPR-69 & CPPR-39.
 CRANE, P. A. Pacific Gas & Electric Co. 78/10/11. 2pp. 94005:14
- 7810170229 Summarizes discussion w/NRC,PQE, & QE on 780830 in Bethe MD, re-electrical penetration qualification. CRAME.P.A. Pacific Qas & Electric Co. 78/10/11. 4pp. 94236:17
- 7810250206 Responds to requests of 780811 & 780823 by issuing Order extending construction dates for subj facil. STGLT.J.F. Light Water Reactors Branch 1. 78/10/13. 3pp. 94392:203.
- --7810250212 Order extending constr completion dates for subj facil 790430 for Unit 1 & 781031 for Unit 2 Eval of Request for Extension of Constr Permit encl. 8070-R.B. Division of Project Hanagement, 78/10/13. Epp. 94372:356.
- 7810260219 Forwards seismic design audits & lists equip qualified is severe environ.
 ALLIBON.D. P. Light Water Reactors Brench 1. 78/10/16. 34pp. 94058:112.
- 78:1080257 Forwards gen repair prog for arc strikes & weld epatter ABME Code Class 1,2 & 3 pressure boundaries in accordance w/ requirements of ABME Code section XI. summer 1978 addendum. W/o encl.

 CRANE P. A. Pacific Gas & Electric Co. 78/10/16. 2pp.
- 7810260099 Summary of 781012 meeting re selemic quel of elec equip. Raylewed test results of elec equip. Did not discuss review of Mech aspects of test involving type & severity of sheking. H/encl list of attenders & results of discussion. ALLISON.D. P. Light Water Reactors Branch 1. 78/10/18 13pp. 94367:309.
- 7811010391 Bummarises 781005 meeting re-subj Pacil review sched. Ob of meeting: to discuss status of numerous specific items under review & to identify items of most concern re-meeting the scheduls. List of attendess encl.
 ALLISON. D. P. Light Water Reactors Brench 1, 78/10/18, 15pp-4438:149.
- 7811020029 Summary of 781020 meeting re salamic qual of subj facil elec equip. 15 items found acceptable & B items nasded mod. All items pertain to Instru/Control Sys. Wenci Branch Review of NBSB scope equip w/in Meetinghouse qual prog. ALLISON.D. P. Light Water Reactors Branch 1. 78/10/25. 9pp. 74374:117.
- 7811040021 References comments in matter of cross-examination of consultants to ACRS at licensing proc be decided as soon as possible. Comm will consider the matter on a generic basis since 3d agrees that it is a top-level policy question.
 30MERS.E.S. Atomic Bafety and Licensing Board Panel. 78/10/27.
 04402-319
- 7811080040 Ack receipt of 781020 NRC ltr.Repeats opposition to cross examination procedures of ACRB consultants in licensing proc. CRANE,P. A. Pacific Gas & Electric Co. 78/10/27. ip. 94398:114
- 7811080005 Forwards 781024 Gen Elec response to 780830 NRC question subj facil elec penetrations qual 80ms info is new.
 ALLI80N, D. Light Water Reactors Branch 1. 78/10/30. 3pp. 94397:343.

- --7811080008 Responds to questions raised at 780830 meeting w/NRC requalification of elec penetration assemblies for subj facil. Addresses justification of qual by similarity verification of repaired assemblies & GE knowledge of repair. CLEVELAND, J. W. General Electric Co. 78/10/16, 14pp. 94397:346.
- 7811070271 Advises that connister-type penetrations meet environ qual requirements consistent w/those found acceptable for Three Mile Island, Also supplies data re main line steem break analysis & use of diesel generator under test.

 CRANE, P. A. Pacific Oas & Electric Co. 78/11/02. 2pp. 94040:284.
- 7811200366 Forwards GE draft itr re testing of penetrations-adequacy of repair. GE tested a loaking-unrepaired penetration to test spowy seal & concluded that a repaired penetration should not act differently LAINAB.0. Plant Systems Branch (Pre 791030). 78/11/09 ip. 94419-211.
- --7811200384 Responds to 780830 NRC 1tr questioning qual of electrometration assemblies supplied to subj facil. Incl attachment on "Comparison of Cannister & 100 Series Penetration Designs".

 CLEVELAND. J. W. Deneval Electric Co. 78/10/26. 13pp. 94419:212.
- --7811200392 Final prototype test rept "Millstone 2 Elec Penetration Post-LOCA Prototype Test". Low voltage pur & control modules were subjected to 145F degree. 5 pelg. 100% RH environ for 52 weeks Leakage rate was less than 1x10 to 8 pur cc He/sec. LURIA.N Q. General Electric Co. 78/11/09. 4pp.
- 7811210234 Forwards seismic qual summary forms for all HE valves identified in Tables 7-7 & 7-7A of "Hosgri Rept." ANDERSON T.M. Westinghouse Electric Corp. 78/11/10. 33pp. 94497:149.
- 78/12/10:18 Presents ACR8 conclusion from 78/102-04 meeting that Dr Luco's concerns re-seismic eval bases for subj facils were considered in findings & recommendations in 7807/14 ACR8 rept LAHROSKI.S. ACR8 - Advisory Committee on Reactor Befeguerds. 78/11/07. jp. 94482:175.
- 78120500B3 ForJands Rev#1 Oraft Radioligical Effluent Tech Spec for Pur's (MURRO-0472) & "Preparation of Radiological Effluent Tech Spec for Nuc Pur Plants" (NUREG-0133), 4/o encl ANO: 7811270173 & 7811270160
 VASSALLO, D. B. Assistant Director for Light Water Reactors, 78/11/16. App. 94336:164.
- 7811220181 Forward: Amend#72 & Amend#73 to Oper Lic appl. CRANE.P. A. Pacific Oas & Electric Co. 78/11/20. 3pp. 94387:001.
- --7811220182 Amend#72 & Amend#73 to Open Lic appl w/addi mati for Hosgri Beismic Eval & FSAR, respectively. BGHACKLEFORD, B. Pacific Oas & Electric Co. 78/11/15. 286pp. 94387-004
- 7811300364 Informs PGE that NRC has contracted w/Mountain West Res Inc to Undertake a series of post-licensing studies of nuc pur stations. Studies will analyze socioscon impacts which occurred during constr to post-constr periods of each plant. DEVOLNO, R.C. Division of Site Safety & Environmental Analysis, 78/11/20. 2pp. 94116:299.
- 7811300079 Porwards log of contacts from 780419-780505 by resident POLE engr in Bethesde Por lieison w/NRC.
 ALLISON D. P. Light Water Reactors Brench 1. 78/11/21. 12pp.
- 78:22:10229 Forwards seismic test procedure for aub. facil 4160V Class IE Buitchgear Bus Undervoltage Relays. CRANE. P. A. Pacific Gas & Electric Co. 78/11/28. 1p. 94279:129.
- --7812210235 Seismic test procedure for 4160V Class 16 Switchgear. Undervoltage Relays demonstrates relays performance while being switched on & off during the shale.
 HERBST. J.E., NIELSEN. D., COLWELL, J.W. Pacific Gas & Electric Co. 78/11/27. 31pp. 94279:130.
- 7612120208 Requests add1 info re means of accomplishing quality inspec at subj facil. 87012/J.F. Light Water Reactors Branch 1. 78/11/30, 3pp. 94276:061.
- 7812210197 Forwards seismer test procedure for subj facil dissel gamerator control cabinet. CRANE.P. A. Pacific Gas & Electric Co. 78/11/30. ip. 94279:068.

- --7812210209 Seismic test procedure for diesel generator control cabinet Tests will demonstrate that relays are capable of changing stats during a seismic event if necessary. HERBST. J. E., NIELSEN. D., COLNELL, J. W. Pacific Oas & Electric Co. 78/11/30. 9pp. 94279:069.
- 7812210223 Forwards seismic test procedure for subj facil local starter LPF36. CRAME.P.A. Pacific Gas & Electric Co. 78/12/01. ip. 94279:121.
- --7812210225 Beismic test procedure for local starter LPF36. Tests will determine if LPF36 motor contacts main pur contacts change state during a seismic event.
 YOUNG.R.A., NIELGEN.D., COLWELL, J. W. Pacific Qas & Electric Co. 78/12/01. 3PP. 94279:122.
- 7812130389 Forwards 781101 ltr from Wiley Labs re test mounting configurations for seismic qual testing of elec aquip. This mean places metl in file & the PDR & informs parties of info availability.

 ALLIBON. D. P. Light Water Reactors Branch 1. 78/12/06. 3pp. 94292:231.
- --7812130390 Clarifies questions raised at 781020 meeting to test prog for elec aguip. 8HPHMY, 0. D. Affiliation Unknown. 78/11/01. 2pp. 94292:234.
- 78:2150033 Forwards informal info "Investigation of A Seiche due to Design Spectra at Raw Water Storage Reservoir: Buby Facil Nuc Proj" by CE Cecilio discussing potential for seiching in raw water reservoirs.

 ALLISON. D. P. Light Water Reactors Branch 1. 78/12/06. 20pp. 942:10:030
- 7812210193 Forwards seismic test procedure for 125 VDC switchgear distribution panel & mold case circuit breakers & test rept entitled "Beismic Testing of Bafsty-Related Elec Equip for POE."

 CRAME, P. A. Pacific Qas & Electric Co. 78/12/06. App. 94279:027.
- 7812280095 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J. Office of Inspection & Enforcement. Office of the Director. 78/12/06. App. 03555:311.
- 7812190143 Forwards rept presenting results of a large-break loss-of-coolant(LDCA)accident. New enalysis incorp a correction to clad-water heat of reaction calculation & recent ECCB evaluated heat of reaction calculation & recent ECCB evaluated heat of presents.

 CRANE, P. A. Pacific Das & Electric Co. 78/12/07. 78pp. 94376: 031.
- 7812180374 Forwards request for add1 info re-bolted connections in linear supports of subj facil support base plates. Requests response sched.

 8TOL7.J.F. Light Water Reactors Branch 1. 78/12/08. 5pp. 94357: 275.
- 7912260217 Requests add1 time to dev draft Appendix I Tach Specs. Proposes submittel by 790216. CRAME.P.A. Pacific Ses 4 Electric Co. 78/12/14. 1p. 94162:098.
- E. NRC Safety Evaluation Report (SER), supple & correspondence
- 7812070056 Forwards Suppl 8 to SER for subj facil. VABSALLD,D.B. Assistant Director for Light Water Reactors. 78/11/13. 1p. 94462:032.
- --7812070063 Forwards Supplied to SER for subj fecil. STOLZ.J.F. Light Water Reactors Branch 1. 78/11/14. 3pp. 94462:033.
- --7812070067 Suppl S to facility SER. # Division of Project Management. 78/11/15. 110pp. 94462:001.
- 7812050155 Forwards add1 info to address Bection7.8.open item 3 of SER Suppl 7, re environ qual of Fan Gooler Pur Cables. Attachment 81 on Spece. Tasks & Installation of Wires & Cables at subj facil is not encl.

 CRANE. P. A. Pacific Gas & Electric Co. 78/11/27. 12pp. 94335:074.
- F. Becurity, medical, emergency & fire protection plans
- 7811370307 Summary of 780214-15 meeting w/util re sub; facil fire protec proj.All mods will be made prior to fuel loading. HEARN.P.C. Ausiliary Bustoms Branch. 78/03/29. 33pp. 94181:306.

- 7811210164 Forwards rev responses to NRC fire Protec Review questions 5.8.9.21.23.24.26-29.45.46 & 49-51 & rev rept "Bupplementary Info for Fire Protec Review." Review question items incl: constr design, fire protec velves & automatic sprinklers. CRANE.P.A. Pacific Que & Electric Co. 78/11/13. 54pp. 94485:294.
- --7811210169 "Suppl Info for Fire Protection Review." # Pacific Gas & Electric Co. 78/11/13. 138pp. 94486:001.
- 7811290400 Forwards suppl detailed info related to subj fecila seismic design audits & the fire protection review.W/31 drawings available in Central Files.
 ALL IBON, D. P. Light Water Reactors Branch 1. 78/11/21. 1029pp. 94182: 001.
- 7812290102 Review of Fire Protec safety eval rept for subj facil has been completed. Concurs in NRC findings & in NRC conclusion that upon implementation of mods listed in rept, fire protecting will be acceptable.

 BEHN.J.D. Gage-Babcock Associates, Inc. 78/11/29. ip. 94190:116.

9. Adjudicatory correspondence

- 7811100014 No objection to Intervenor's request of 781016 to subpose Dr Grahm for the upcoming evidentiary hearing. TOURTELLOTTE.J. Office of the Executive Legal Director. 78/10/27. 1p. 94176:351.
- 7812010048 Expresss view on gen policy question of subposning ACRB consultants to require their attendance at evidentiary hearings before ABLB Exceptional circumstances standard should not be limited to direct knowledge witnesses. FLEIBCHAKER.D. Center for Law in the Public Interest. 78/11/14. 3pp. 94416:132
- 7812010198 Attorney RK Hosfling enters appearance in captioned matter. Cart of Evc encl.
 HDEFLING.R.K. Office of the Executive Legal Director. 78/11/09.
 3pp. 74409:205.
- 7812040179 Applicant DGE has until 781205 & NRC Staff until 781211 to respond to intervenor's Petition for directed certification to review ASLB's rejection of DD Comey as an expert witness on security matters.

 DUFLO.H.E. Atomic Sefety and Licensing Appeal Panel. 78/11/21.
 2nn 98657:073.
- 7812080024 Requests to make appearance statement at 781204 hearing in Ban Luis Obispo County CA. RICE L. Affiliation Unknown. 78/11/27, ip. 94104:002.
- 7812110219 Asks whether seismic hearings will begin 781204. Believes facil should not be allowed to open for love of humanity in general.
 ROBENBERO.H. Affiliation Unknown. 78/11/17. ip. 94337:353.
- 7812180037 Forwards "Interpretive Comm Statement on Amenebility to Subposes of Consultants to ACRS under 10CFRS.780," which now represents the Comm's views & which will be presented for formal vote at next Comm Affirmative Session.

 KELLEY, U. L. Office of the Executive Legal Director. 78/11/29. 1p. 94130:341.
- 7810160135 Requests by intervenors for production of documents by NRC staff & applicants & enlargement of time to file interrogs. Also submits interrogs to appl & requests that attached documents be explained. FLEIBCHAMER.D., PHILLIPS.J. Center for Lew in the Public Interest. 78/09/27, 17pp. 94005:143.
- 7810190207 Forwards various pleadings of Intervenors(Beenic Shoreline Preservation Conference: Sen Luis Obispo Mothers for Pages, Ecology Action Club, B. A. Silver, & J. J. Forster)re oper lic. PLEISCHAMER, D. Pleischaker, D. S. 78/09/28. 3pp. 94052:017.
- --7810190262 Intervenors(Scenic Shoreline Preservation Conference, etc), request for oral argument. FLEISCHAKER, D. Fleischaker, D. S. PHILLIPS, J. P., KRISTOVICH, S. Center for Lew in the Public Interest. 78/09/28. 3pp. 94052:020.
- ~-7810190267 Intervenors(Scenic Bhoreline Preservation Conference, etc)
 request to reply to NRC & applicant response to intervenors
 request for issuence of ASLB subpoence.
 FLEIBCHAMBR.D. Fleischaker, D. B. PHILLIPB.J.P., HIBTOVICH.8.
 Center for Law in the Public Interest. 78/09/28. Epp. 94052:093.

- --7810190267 Intervenors(Scenic Bhoreline Preservation Conference, etc) request to reply to NRC & applicant response to intervenors request for issuence of ABLB subpones.

 FLEISCHARER D. Fleischaker, D. 8 PHILLIPS, J.P., XRISTQVICH, 8 Center for Law in the Public Interest. 78/09/28 32pp. 94052.025.
- 7810140108 Notice of reconstitution of ABLAB re OL proceeding.

 R Salzman. A Rosenthal & W Johnson will serve on board

 DUFLO.M.E. Atomic Bafety and Licensing Appeal Panel. 78/10/03 ip.
- 7811010324 Buppl Memo in support of intervenor SLOM appeal from 780511 & 780795 Drders re qual of security experts BLOM now seeks direct certification & qual only of D Compy as security expert for discovery purposes.
 JUNCB. Y. I. , VALENTINE. P. C. San Luis Obispo Mothers for Peace.
 78/10/06. 22pp. 94389:275.
- 7810190126 Grants request by intervenor for extension to 781006 to respond to PGE motion to dismiss security contention NRC staff is also granted extension to 781006 per their request. BOHERB E.B. Atomic Safety and Licensing Board Panel. 78/10/10. 2pp. 94414:025.
- 7810250182 Denies request by Intervenors that 8d subpoens 13 persons as witnesses in evidentiary hearing. Denied because 8d recains unconvinced that circumstances are exceptional & werrant granting the request.

 BDMER8.E. 8. Atomic Sefety and Licensing Board Panel. 78/10/10. https://dx.com/ps.94392:234.
- 7810300008 Requests Bd stay issuance of any order on Applicants motion to dismiss security contention until Appeals Bd issues its ruling in repsonse to Intervenors motion for direct certification. W/encl cart of svc. VALDNINE.P.C. Ban Luis Obispo Mothers for Peacs 78/10/10. App. 94034:216.
- 7810300330 PQ&E response to intervenor SLOM's Petition for direct certification & SLOM's appeal from ABLB Order of 780903. PQ&E asserts that cartification is not appropriate. Supporting documentation & Cert of Styc encl.

 NORTON-B. MORRIBGEY, J. C., CRANE, P. A. Pacific Gas & Slactric Co. 78/10/13. 35pp. 94253:279.
- 7810270294 Intervanor's Request to Subposes Dr 8 Orsham to testify recontentions that Applicent has failed to conduct thorough investigations of Hosgri fault sys. Cert of Svc encl. FLEISCHAKER. D. Fleischaker, D. S. PHILLIPS. J. P. KRISTOVICH, B Affiliation Unknown. 78/10/16. 11pp. 94025:347.
- 7810300128 Advises Lic Bd of status of 6 independent experts subpossed at request of Intervenors. FLEIGCHAKER.D. Fleischaker, D. S. 78/10/16. 2pp. 94030:143.
- 7811010318 NRC Staff Answer to Appl Motion to Dismiss Security Contention. Staff augusts the Bd defer on a ruling while Intervenor San Luis Obispo Mothers for Peace awaits ruling on their appeal re the security issue.

 STARNBERG M.R. Office of the Executive Legal Director. 78/10/16. Spp. 94387:265.
- 7810300082 Informs Bd that Staff will comply w/Intervenor's request for documents & interrogs to the Staff no later than 781025 due to error in mails. There will be the same answering time originally anticipated by parties.

 TOURTELLOTES, J. Hearings Division. 78/10/17. 2pp. 94035:096.
- 7811010039 Raplies of Subj Util to Intervenors' Intervogs dtd 780997. Resumes of Guel for Safety Hearings & Cent of Suc encl. GRAGE, A., NORTON, S., FURBUSH, M. H. Pecific Gas & Electric Co. 78/10/17. 95pp. 94290:008.
- 7811130314 Forwards subposes for signature of E Bowers. One will be served upon Dr Stephen Graham; the other 2 copies are for file reference. FLEIBCHAMER, D. Fleischeker, D. B. 78/10/23. 1p. 94087: 042.
- 7811060008 Notice of addition of & J Bullivan to list of staff witnesses provided in Rept 1978 Davis ltr re radiological health & safety hearings.
 TOURTELLOTTE, J. Office of the Executive Legal Director. 78/10/25.
 2pp. 94420:328.
- 7811130199 "NRC Staff Response to Intervenor's San Luis Obispo Mothers for Peace Petition for Directed Cert & Appeal from Licensing Bd Order of 780905." Urges Intervenors petition be denied. Cert of Svc encl.
 STARNBERG.M.R. Office of the Executive Lagel Director. 78/10/26.
 1006. 03553:342.

- 78(1080)83 Hemorandum & Order granting the petition for directed certification vacating Bd's 780905 order & remanding the cause for immediate further consideration consistent u/this opinion in the open licensing proc.

 DUFLO, M E. Atomic Sefety and Licensing Appeal Panel 78/10/27.
 129p 74403:113.
- 78:1080029 Forwards "Blaff Comments on Generic Matter of Cross-Examination of ACRB Consultants in NRC Licensing Proceedings" Wiencl Cert of Svc. TREBY S A. Office of the Executive Legal Director. 78/10/30. 18pp. 94398:067
- 7811280488 Notice that PQE will take depositions of E Silver, J Brune & R Hubbard. Also encl is response of PQE to intervenors' request of 780927 for production of documents. Documents sought are now available for inspec
- 7811070358 Urges ACRS permit cross-examination of consultants Cross-examination is essential to accurate interpretation of opinion & determination of factual bases of assumption. VALENTINE, P. C. Valentine, P. C. 78/10/31
- 7811170007 "Reconsideration of Bd's Order of 780905." Petition of San Luis Obispo Mothers for Peace to establish David Comey as an expert witness is denied.
 80HERS.6.S. Atomic Safety and Licensing Board Panel. 78/11/03.
 3789. 94116:104.
- 7811200042 Evidentiary hearing on 781204 will be held in Avila Beach. CA First 2 days of hearing will be set eside for limited appearance statements of no longer than 3 minutes seach. Hritten statements of any length may be submitted. BDMEHS.E.8 Atomic Safety and Licensing Board Penel. 78/11/07. 2pp. 94215:324.
- 7812040321 Testimony of N Newmerk re earthquake resistance design criteria utilized in constr of subj facils. "Rationale for Development of Design Spectra for Diablo Canyon Reactor Facil" & Cert of Svc and.
 NEWHRM,N.M. M. N. Newmark Consulting Engineering Services, 78/11/15. 75pp. 94122-001.
- --7812040324 Testimony of CJ Stepp re subj facil seismic concerns addressed during constr permit & Dper Lic review. STEPP, J. C. Geosciences Branch, 78/11/15, 41pp. 94122:076.
- --7812040027 "Diable Canyon Testimony of J Knor & F Rose re Seismic Qual of Class IE Equip." discussion of seismic qual eval with criteria in Bafety Eval Rept 3.10 & suppls. ROBA,F. Power Systems Branch. 78/11/15. 12pp. 94122:117.
- ---7812040330 "Testimony of RB Hofmann" re conservative value for ground acceleration from a 7.50 senthquake on the Hospri fault.

 HDFMANN, R. B. Office of Standards Development, Director. 78/11/15.

 22pp. 94122:129.
- --7812040334 Testimony of MJ Hall re adequacy of the structurel criteria for Unit 2 for an 89E of 0-4 g Found during both reviews (1967-9 t 1975-8) that facil had sufficient resistance to meet seismic hazard.

 HALL-W. J. Affiliation Unknown. 78/11/08. 7pp. 94122:151.
- --7812040338 Testimony of UP Knight re the seismic design process (definition of risk & design of sufficiently resistant structures) & its relation to the subj facil seismic review. KNIGHT.J.P. Assistant Director for Engineering. 78/11/15, 56pp. 94122:158.
- 7812130006 Request for info re hearings on sub, facil. TURNER, A. J. Affiliation Unknown. 78/11/15. ip. 74307:172.
- 7812180324 Forwards testimony on behalf of Intervenors re Contention I, Geology & sets forth conclusions re through-poing continuity of the San Gregario-Hosgri fault zone Resume, Study results & Cert of Svc encl.

 ORAHAM.S.A. Affiliation Uninown. 78/11/17. 19pp. 94336:299.
- 7812180309 Patition for directed certification for review of "Reconsideration of Bd's Order of 780903" relating to qual of security expert Forwards Cert of Svc.
 VALENTINE.P.C. Ban Luis Obispo Mathers for Peacs. 78/11/20, 40pp. 94356:190.
- 7812050191 Memorandum ack receipt of intervenor's Petition for Directed Certification. Applicant's response is due 781205:8taff's 781211.8d will not favor requests to extend time. DUFLO, H. E. Atomic Safety and Licensing Appeal Panel. 78/11/21. 2pp. 94382:122.

- 7812130146 Forwards list of publications & rev qualifications sheet omitted from 780927 Staff's response to Intervenor's interrog. KETCHEN.E. Q. Office of the Executive Legal Director. 78/11/21. 22pp. 94289-064.
- 7812080004 Order granting permission to make opening statements pri to limited appearances. Each statement limited to 20 minutes. No change ufil be made from stated location.

 BOHERS E. B. Atomic Safety and Licensing Board Panel. 78/11/27.
 2pp. 94103:314.
- 7812140346 Forwards list of publications of JF Devine & resume of F. McKeown. KETCHEN.E. g. Office of the Executive Legal Director. 78/11/27. 10pp 03557-175.
- 7812140085 Suppl reply of POE to intervenors' interrogs of 780927. Forwards names & quals of 4 add1 witnesses POE intends to call in the licensing hearing re subj fecile. Cert of Svc encl.
 CRAMS.P. A., NORTON, B., HORRISSEY, J.C. Pacific Gas & Electric Co. 78/11/28, 10pp 94128: 231.
- 7812140344 Gives notice that E Ketchen enters an appearance on behalp RC in procine subjifacils. Cent of Svc encl.
 KETCHEN.E.G. Office of the Executive Legal Director. 78/11/28.
 03557:168.
- 7812140373 Confirms 781122 conversation re status of 2 USQB witness appearing for NRC Both witnesses wrote USQB rept which is append C to Suppl 4 of SER & will be at hearing to answer questions.

 TOURTELLOTTE, J. Hearings Division. 78/11/29. 1p. 03558:118.
- 7812180027 Forwards memo to subpose to ACRS consultants entitled "Interpretive Comm Statement on Amenability to Subposes of Consultants to ACRS under IOCFR2.720."
 BOMERS-E.B. Atomic Safety and Licensing Board Panel. 78/11/30. 4pp. 94130:340.
- 7812180416 NRC Staff's Response to Petition submitted by intervenor Luis Obispo Hothers for Peace swelting review & reversal of ASLB's upholding of deniel of D Comey's quals. NRC urges that intervenor's petition be denied. Cert of Svc sncl. STAENBERG, M. R. Office of the Executive Legal Director. 78/12/01. 3pp. 94356:3364
- 781221032: "Suppl Reply of Ut Intervenors' to Applicant's Interrogs 780927. " Cert of Svc encl.
 HUBBARO,R.B. MHB Technical Associates. 78/12/01. 4pp. 94407:3
- 7812270025 Urges approval of plant open as soon as possible, since to elec pur is vitally needed.
 RUSSELL-H.K. Affiliation Unknown. 78/12/05. 1p. 94159:239.
- 7812140273 Forwards Amend#1 to Constr Permit#CPPR-39 & Amend#4 to Constr Permit#CPPR-69 w/related correspondence. ODLDBERG.J.R. Office of the Executive Legal Director. 78/12/07. 1p. 03557: 289.
- --7812140275 Forwards Amendel to constr permit#CPPR-39 & Amende4 to constr permit#CPPR-69 & Fed Register Notice. BVD-8.8. Division of Project Hanagement, 78/12/06. 4pp. 03557:290.
- --7812140278 Amend#1 to Constr Permit#CPPR-39, adding entitrust cond to Paragraph 2.D. SOYD.R.B. Division of Project Management. 78/12/06. 10pp. 03557:294.
- --7812140279 Amend#4 to Constr Permit#CPPR-69 adding entitrust cond to Paragraph 2.D. BUYD.R.B. Division of Project Henagement. 78/12/06. 10pp. 03957:304.
- --7812140283 Notice of Issuence of Amend®1 to Constr Permit#CPPR-39 Amend®4 to Permit#CPPR-69.W/encl Eval of Amend by LWR#1. BTDLZ, J.F. Light Water Reactors Branch 1. 78/12/06. 5pp. 03557: 314.

H. General correspondence

78:21:10040 Responds to 78:1030 ltr re seismic design conservation te W/regard to elec load projections & notice of hearing.
3ALLARD, R. L. Environmental Projects Branch 1. 78/11/30. Epp. 94408; 149.

- 7811130130 Expresses concern over role of nuc energy in US energy progsuggests more res be directed towards solar energy. Daphores Liquid Metal Breeder Reactor & the idea of siting e plant on the James River near her home. NELSON.E.S. Affiliation Unknown. 78/10/21. 3pp. 94272:361
- 7811210312 Ack receipt of 780918 ltr & environ impact statement. Request date & location of public hearing on subj facil & submits questions of concern re subj facil.

 MURPHY-E. Affiliation Unknown. 78/10/30. lp. 94488:090.
- 7812180289 Forwards for Dept of Energy Response, a memo re an inquiry by G Burns into who inspects the structural steel of the subj facil.

 LAQUARRBIND.R.J House of Rep. 78/11/22. 2pp. 94365-142.
- 7812270039 Strongly recommends putting subj facil into oper as soon as possible, aince the energy is necessary. 9EORGE.J. APPLICATION TO NAME OF THE PROPERTY OF THE PROPERTY
- 7811210413 Believes nuc pur cannot be made safe & that constr of subj facil should be stopped.

 8TAN-R.F. Affiliation Unknown. 78/11/13. ip. 94483:126.
- K. Utility Final Bafety Analysis Report (FBAR) & amends
- 7811140126 Forwards copy of Amends 70 % 71 to open lic appl for subj facils. Amends incl add1 math for Hosgri eval & FBAR. Cent of Svc encl.

 CRANE,P.A. Pacific Qas & Electric Co. 78/11/09. 2pp.
- --7811140145 Amends 70 & 71 to Open Lic appl for subj facils. Amends incl addl matl for Hosgri Eval & FBAR. BHACKLEFDRD B. Pacilic Das & Electric Co. 78/11/09. 400pp.
- O. Advisory Committee on Reactor Befeguards reports & correspondence
- 7812150050 Comments transmitted in 780922 ltr from ACRS consultant E Luco re seismic eval bases were discussed at 781102-04 ACRS meeting. These coments were considered in the findings & recommendations in ACRS rept of 780714. LAWROSKI, 8. ACRS Advisory Committee on Reactor Safeguards. 78/11/07. 1p. 94210:253.
- 7811010382 Forwards ACRB consultant rept subj facil seismic design for info. ALLISON, D. P. Light Water Reactors Branch 1. 78/10/24. 3pp. 94388:164.
- --7811010384 Forwards comments by Dr Luco re seismic design basis for subj facil. HCKINLEY, J. C. ACRS - Advisory Committee on Reactor Bafeguards. 78/10713 Ip. 94388:167.
- --7811010288 Comments on 780614 & 780707 acrs meetings re use of effective peak acceleration & underestimation of subj facil response to offshore fault resulting from use of large reduction for tau-effect & small torsion excitation. LUCO_U.E. California, Univ. of, Sen Diego. 78/09/92. 5pp. 94388:168.
- G. Inspection reports. IE Bulletins & correspondence
- 7810230316 Forwards IE Circuler#78-17. (See ANG: 7810230221, Docket 50-313, 781013) ENWELKEN.R.H. Region 5, San Francisco, Office of the Director. 78/10/13. 1p. 94166: 347.
- 7811220263 Forwards IE Inspec Repts#50-275/78-14 & #80-323/78-14 on 780901-30 during which no items of noncompliance were noted. CREMB(J.L. Region 3, Ban Francisco. Reactor Operations Nuclear Support Branch. 78/10/17. 2pp. 94273:355.
- --7811220267 IE Inspec Repts#50-275/78-14 & #50-323/78-14 on 780901-30 during which no items of noncompliance ware noted Major areas inspected included preoper testing, fuel storage, followup on licensee event & IE Bulletin-Circular, testing. BIERNBERG, D. M. Region 5, Ban Francisco, Reactor Operations Nuclear Support Branch. YOUNG, T., BTERNBERG, D. H. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/10/16. Dpp. 94273:357.
- 7811070111 Responds to 781006 NRC ltr re violation noted in inspec. Corrective actions:circuitry is being placed in conformance w/FBAR paragraph 3.3, & implementing instruc will be issued by 781118.

 CRANE,P.A. Pacific Gas & Electric Co. 78/11/02. 2pp. 94043:348.

- 78:11:50007 Forwards IE Circular 78-18.

 ENGELKEN, R H Region 3, San Francisco, Office of the Director. 78/11/06. 1p. 94112:301.
- 7812150001 Forwards IE Inspec ReptsW50-275/78-17 t 50-323/78-16 on 781001-31 during which no items of noncompliance were noted. CREWB.J L. Region 5, San Francisco. Reactor Operations Nuclear Support Branch. 78/11/16. 2pp 94209:190.
- --78:2:50004 IE Inspec Repts#50-275/78-17 t 50-383/78-16 on 78:1001-31 during which no items of noncompliance were noted Hajar areas inspected incl: prepper testing-fire protec.plant tour. problem repts: IE bulletin followup t design changes. YONG.T. STERMERO, D. M. Region 5. San Francisco, Reactor Operations Nuclear Support Branch. 78:11/13 4pp 94209:192
- 7811300088 Forwards IE Bulletin#78-12A. suppl to IE Bulletin 78-18. H/encl AND: 7811300055. ENGELKEN, R H Region 5, San Frantisto. Office of the Director. 78/11/24 10.
- 7812290033 Forwards IE Bulletin 78-14. ENGELKEN.R.H. Region 5, Ban Francisco, Office of the Director 78/12/19. 1p. 0.6911:001
- S. Reportable occurrences, LERs & related correspondence
- 7812210386 Forwards addl info re RO defect in Unit 2 NEMA size#2 motor controllers Unit 1 inspec complete.inspec & replacement of kick-out springs for Unit 2 will be completed prior to functional test.

 WORTHINOTON.U.D Pacific Oas & Electric Co. 78/12/07. 1p. 94015-094.
- T. Hearing transcripts on non-antitrust matters
- 7812070227 Transcript of POLE testimony on 781204. Testimony of RV Bettinger, DH Hemilton, RH Jahns & SN Smith encl. * Atomic Safety and Licensing Board Panel. 78/11/20. 239pp. 74188:016.
- --7812070237 festimony of POLE on 781204.

 † Atomic Safety and Licensing Board Panel. 78/11/20. 2009p.
 74188.278.
- --7812070242 Testimony of POLE on 781204.

 4 Atomic Safety and Licensing Board Panel, 78/11/20. 107pp.
 94189: 162.
- 7812150056 Transcripts of 781204 hearings re subj Facils Pp 3758-3997. BDMERS.E. MARTIN.H.E. BRIGHT.G. O. Atomic Safety and Licensing Board Panel. 78/12/04. 239pp. 94211:030.
- 7812130064 Transcript of 781205 hearing re subj fecil.Limited Appearence Statements. In Avila Beach.CA.PP 3398-4249. BOMERS.E.; MARTIN.H.E.; BRIGHT.G.D. Atomic Befety and Licensing Board Panel, 76/12/05. 251pp. 94296:012.
- 7812200344 Transcript of hearing in Avila Beach.CA on 781207.
 Appearances on behalf of applicant: 8 Norton.HH Furbush. 8
 P Cransion behalf of joint intervenors: D8 Flaishaker.S
 Kristovitch & for NRC: E Ketchen.Pp 4486-4579.
 BDNERS,E., MARTIN.H.E., BRIGHT.Q.O. Atomic Safety and Licensing
 Board Panel. 78/12/07. 193pp. 94124:188.
- 7812200338 Transcript of hearing in Avila Beach, CA on 781208. Appearance on behalf of Pacific Ges & Elec:B Norton, PM Furbush, P Crame, on behalf of joint intervenors:DB Fleischaker, B Kristovich & for NRC:M Staenberg, Pp 4679-4862.

 BOMERS.E., MARTIN.W.E., BRIGHT.G.O. Atomic Sefety and Licensing Board Fanel, 78712/08, 1832p. 94124:003.
- 7812270346 Transcript of hearing re subj fecil at Avila Beach. CA on 781213.Pp 5309-5506.
 BOHERS.E. Atomic Safety and Licensing Board Penel. 78/12/13.
 1979p. 94229:024.
- 7812220014 Transcript of 781214 hearing in Avila Beach.CA pp subj facil.Pp 5507-5706.
 SOMERS.E., MARTIN, M.E., BRIGHT.G. O. Atomic Bafety and Licensing Soard Panel. 78/12/14 199pp. 94248:024.
- 7812290002 Transcript of a 781218 hearing in Avila Beach CA re sub; facil.Pp 6102-6389.
 BOWERS,E,, MARTIN,W.E., BRIGHT, G.O. Atomic Sefety and Licensing Board Panel. 78/12/18. 257pp. 94208:050.

- 7812290279 Transcript of a morning 781214 hearing at Avila Beach.CA resubj facil.ep 6360-6471.
 DDHERSE, MARTIN.WE., BRIGHT.Q. D. Atomic Bafety and Licensing Board Panel. 78/12/19. 111pp. 94192:001.
- 7812290280 Transcript of 781229 hearing on 781220 at Avile Beach.Co. Pp6472-6688 BOMERS.E. MARTIN.W.E., BRIGHT.O.D. Atomic Safety and Licensing Board Panel 78/12/20. 216pp. 94193.001.
- 7812290282 Transcript of 781221 hearing in Avila Beach.CA re subj facil.Pp 6689-6862.
 80MER8.E. MARTIN.W.E., BRIGHT.Q.O. Atomic Safety and Licensing Board Panel. 78712/21. 173pp 94194.001.
- 7812290283 Transcript of a morning 781222 hearing in Avila Beach CA resubj facil. Pp6863-6949.
 BDMER8-E HARTIN, M. E BRIGHT, Q. Q. Atomic Sefety and Licensing Soard Pens1, 78/12/22. Bapp. 94195:001.
- U. Congressional/Executive Correspondence
- 7811080032 Responds to encl 780831 & 780925 congressional correspondence w/DDE requesting info to answer constituent's charges to not subject in large geologic fault.

 DIRCKS H J. Office of the Executive Director for Operations. 78/10/30. 10pp 94378:089
- DOCKET 50-324 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2

 A. Application/construction stage documents & correspondence
- 7810130122 Analysis of suppression pool temp transients as requested by NRC 780113 ltr & as mod at 780309 meeting. Hork has begun & rept will be submitted in about 3 months.

 UYLEY.E.E. Carolina Power & Light Co 78/10/10. Ip 94079:297.
- F. Security, medical, emergency & fire protection plans
- 7812080157 Notification of 781217 site visit by A Leep & D Cameron, security plan reviewers affil w/Los Alamos Sci Leb. 1PPCLITO, T A Departing Reactors Branch 3 (Pre 790625). 78/11/30. 2pg 94107.354
- P. Operating license stage documents & correspondence

ı

+ [

- 7810110110 Responds to 780829 ltr indicating that no incident of control rods failing to fully insert occurred at subjectil. UTLEY.E.E. Ceroline Power & Light Co. 78/10/04. ip. 94066:356.
- 7810130143 Has requested assistance from QE re undetected single failures in reactor protects sys pur supplies. Mill not be able to respond to 780807 HRC ltr w/required info until 781215.

 UTLEY, E.E. Carolina Power & Light Co. 78/10/10. ip. 94002:315.
- 7810240127 Requests rev to Tech Opec for subj facil in response to 780912 NRC ltr requesting rev to spec on total annual gaseous releases.

 UTLEY, E. E. Caroline Power & Light Co. 78/10/16. 16pp.
- 7011100335 Burmary of 780914 meeting w/GE representatives & Mark 1 Dunars Group re progress of Long Term Prog w/attendance list & agende(RD-9-A-Marki, Standards.)
 ORINES.C. Plant Bystems Branch (Pre 7910301, 78/10/26, 67pp.
- 78:1090109 Requests rev of Tech Specs for subj facil re operability requirements for suppression pool-reactor bldg vacuum breaters Hanual valves will be closed & valves will be governed by admin controls.

 UTLEY/E E. Carolina Power & Light Co. 78/11/03. 4pp. 94042:282.
- 78:1240:54 Notice of 78:106 meeting in Sethesda w/CPtL to discuss compensatory measures to allow continued plant oper w/single valve isolation in RB-supression chamber vacuum relief lines.
 HANDN, J. N. Operating Reactors Branch 3 (Pre 790625). 78/11/03.
 19. 94456:259.
- 78:11:60:135 Suppl to 78:103 ltm requesting amend to Tech Spec to mod operability requirements of suppression pool-reactor bldg vacuum breakers. Ltm documents info discussed w/staff during 78:105 meeting & 78:107 telcon.

 UTLEY-E.E. Caroline Power & Light Co. 78/11/08. 5pp. 94:35:236.

- 7811220279 Confirms verbal authorization to change Tech B facil in response to 781103 request. Amend allows all suppression pool-Reactor Bldg Vacuum breaters to be open wiopening setpoint of 0.3 psig wiomanual valves closed. ORIMES.B.K. Assistant Director for Engineers & Project 790625). 78/11/0B. 3pp. 94308:211.
- 7811210273 Notifies util of 781205 seminer in Atlanta to Model Rod Effluent Tech Specs & encl seminer info sheet registration form. & proposed agenda. D'RETLLY,J.P. Region 2. Atlanta, Office of the Directo Spp. 94485:162.
- 7811290406 Forwards NRC staff paper, policy session item (relicense reg performance eval. Three methods for eval statistical, trend enalysis & regional survey method. W/o encl.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Directo 2pp. 94180:099.
- 7812190197 Notice of workshops re implementation of train requirements contained in Append B of IOCFR73. Requests pre-workshop registration of attendees to facilitate se out matl. W/encl Registration Form & List of Locations. MILLERJJR. Assistant Director for Site & Safeguards (78/11/13. Spp.
- 7812180274 Forwards Rev#i "Draft Radiological Effluent To BHR's(NUREQ-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc "Pur Plants" (NUREQ-0133). ORIMES B. K. Assistant Director for Engineers & Project 790625). 78/11/15. App. 94336:346.
- 7812080164 Confirms meeting on 781206 to discuss plans refor refueling outage sched for January 1979. IPPCLITO, I. A. Operating Reactors Branch 3 (Pre 790625) 2pp. 74108-008.
- 7812110023 Discusses possible dangers of LOCA in contains during normal plant oper Requests either commitment to purging or justification for continuing A/encl ANO: e7812080207. IPPCLITO.T. Operating Reactors Branch 2 (Pre 790625).
- IPPCLITO.T. Operating Reactors Branch 2 (Pre 790625). Bpp. 94339:302.
- 7812110315 Notification of meeting on 781206 in Bethesda condition of jet pump riser sefe-ends & evaluate relativation proposed for refueling outsge to begin Jan 1979. HANNON.J.N. Operating Reactors Branch 3 (Pre 790625). ip. 94204:157.

 7812140176 Forwards Oct 1978 Prog Activity Revise listing
- 7812140176 Forwards Oct 1978 Prog Activity Review listing & providing task-by-task activity summary for the month BDBON.L.J. General Electric Co. 78/12/04. 11pp.
- 7812280114 Emphasizes importance of submitting accurate to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licensee must not NRC of any inaccuracies or enforcement action will resulting. Office of Inspection & Enforcement, Office Olivetor. 78/12/06. 2pp. 94133:228.
- 7812210100 Forwards amends#42 & 17 to DPR-71 & DPR-62 & Impact Appraisel & Fed Register Notice.
 BALLARD.R.L. Environmental Projects Brench 1, 78/12/94267:182.
- --7812210102 Amend#42 to Oper Lic DPR-62, changing the in of the cooling tower. HORELV.A. Assistant Director for Environmental Pro 78/12/15. 2pp. 94269:184.
- --7812210104 Amend#17 to Oper Lic DPR-71, changing the in of the cooling tower. MODRE V. A. Assistant Director for Environmental Pro 78/12/15. 3pp. 94269:186.
- --7812210107 Notice of Issuance of Amends#42 & 17 to Ope 71 & Negative Declaration. BALLARD.R.L. Environmental Projects Branch 1, 78/1 94269: 188
- --7812210109 Environ Impact Appraisal supporting Amends# Lics DPR-62 & 71 re cooling tower installation date. • Division of Site Sefaty & Environmental Analysis. 18pp. 94269:190.

- 7812270192 Due to delegs in GE's analysis of reactor protect aga pur supplies.CPL will be unable to respond to 780807 ltr as previously committed to in 781010 ltr.Estimates response by 790301.

 UTLEY.E.E. Carolina Power & Light Co. 78/12/18. 2pp. 94018:038.
- 7812270207 Forwards results of reactor recirculation safe ends inspec prog including a description of existing NDE techniques & discussions of alternate techniques Concludes that present techniques used by subj facil are adequate. UTLEY-E.E. Carolina Power & Light Co. 78/12/22, 13pp. 94168:081
- Q. Inspection reports. IE Bulletins & correspondence
- 7810310134 IE Inspec Repts#30-324/78-19 & #50-325/78-19 on 780808-11 during which no items of noncompliance were noted Major areas inspected included:calibr.surveillance.design & procurement changes & mods
 KELLOGO,P. J. Region 2. Atlanta, Office of the Director. GUZTB.J.E. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/09/20. Bp. 94090:133.
- 7810310128 Forwards 1E Inspec Repte#50-324/78-19 & #50-325/78-19 on 780808-11 during which no items of noncompliance were noted. LONG-F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/21. 2pp 94090:131
- 7811010397 Forwards IE Inspec Rept#50-324/78-20 & #50-323/78-20 on 780815-18 during which no items of noncompliance were noted. LONG-F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/21. 2pp. 94388.313
- --7811010402 IE Inspec Rept#50-324/78-20 & #50-325/78-20 on 780815-18 during which no items of noncompliance were hoted Major areas inspected included: licensee event rept. IE bulletins & circulars. Follow-up of open items.
 HINCKLEY.D.Q. Region 2, Atlants, Reactor Operations Nuclear Support Branch. 78/09/20. opp. 94388:315.
- 7810110240 Ack receipt of 780830 ltr informing NRC of steps taken to correct violations noted during inspec#50-324/78-14 & 50-325 /78-14. BUTHERLAND, J. T. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 78/09/27. ip. 03555:242.
- --7810110242 Responds to 780717 NRC ltr re violations noted in Inspac Repte#50-324/78-14 & #50-325/78-14. Corrective actions: Rev checklist added to chlorination log & level limits added to log checklists. BANKS, H. R. Carolina Power & Light Co. 78/08/30. 3pp. 94068:169.
- ---7810110245 Forwards IE Inspec Repts#50-324/78-14 & #50-325/78-14 on 780612-15 & Notice of Violation BUTHERLAND, J. T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch. 78/07/17. 2pp. 94066:172.
- ---7810110249 Notice of Violation from inspec on 780612-15.
 4 Region 2: Atlanta: Fuel Facility & Materials Bafety Branch. 78/07/17. 2pp. 94068:174.
- --7810110233 IE Inspec Rept#50-324/78-14 & #50-325/78-14 on 780612-15 during unich 3 items of noncompliance were noted failure to include specs in annual audit & surveillance techniques for chlorination.

 HUFHAN, J. W. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 78/07/14, 7pp. 94068:176.
- 7810110291 Responds to 780821 NRC ltr re violation noted in Inspec Rept#50-324/78-17 % #50-325/78-17. Corrective actions: personnel made aware of necessity of protec clothing. BANKS.H.R. Commonwealth Edison Co. 78/09/20. 2pp. 94068:317.
- --7810110295 Forwards IE Inspec Rept#50-324/78-17 & #50-323/78-17 on 780718-21 & Notice of Violation. LCNG.F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch, 78/08/21. 2pp. 94068:319.
- --7810110279 Notice of Violation from inspec on 780718-21.

 * Region 2: Atlanta: Reactor Operations Nuclear Support Branch. 78/08/21. ip. 94048:321.
- --7810110302 IE Inspec Rept#50-324/78-17 & #50-325/78-17 on 780718-21 during which 1 item of noncompliance was noted: failure to follow approved health physics procedures. DANCE.H.C., HINCKLEY, D.Q., RILEY, B.W. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/08/21. 4pp. 94068:322.

- 7811200029 Forwards IE Inspec Repts#30-324/78-24 & #30-325/78-24 on 780918.20-22.26-28 during which no items of noncompliance were noted.

 MURPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch 78/10/11 20p 94215:305
- --7811200034 IE Inspec Repts#30-324/78-24 & #50-325/78-24 on 780718.20-22.26-28 during which no items of noncompliance were noted Major areas inspected included: Non-Destructive Examination of Jet-Pump Riser Bafe-Ends.
 BLAXE, J. J., WILLIAMS, C. C., CON.C.N.T. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 70/10/11 5pp
- 7810260249 Reports that no external pipe snubbers were found in Unit*1. None were found in Unit*2 but one accessible snubber w/out a reedable serial number was replaced.

 UTLEY.E.E. Carolina Power & Light Co. 78/10/17. 1p 94058:320.
- 7810270252 Forwards summary of 781016 meeting re-subj facil inspection of REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/10/20 ip 94029:210
- --7810270272 Summary of 701016 meeting re-util eval of BSEP Reactor Recirculation Safe-End Examination Results Util will inform Region II whether Nov inspec can be deferred BLAKE, U.J. Region 2, Atlanta, Defice of the Director. 78/10/20. 2pp. 94029:211.
- 7810270111 Describes planned feedwater & control rod drive return line nozile inspects to be performed during refueling outages.
 UTLEY.E.E. Carolina Power & Light Co. 78/10/24 2pp. 94059 303.
- 7811090009 Act receipt of 781025 itr informing NRC of steps taken to correct violations noted during inspec#50-324/78-21 & #50-325/78-21. KENNA-M.B. Region 2, Atlanta, Bafeguards Branch. 78/11/01. lp 94039:337.
- --7811090013 Responds to 781003 NRC ltr re violations noted in Inspec Repts#50-324/78-21 & #50-325/78-21 Carrective actions: info W/held from public disclosure pursuant to 10CFR2 790. (See AND.7810140041) FURR.B.J. Caroline Power & Light Co 78/10/26 ip 94039:338.
- 7612110246 Forwards IE Insp Repts 50-325/78-27 & 50-324/78-27 bn 781018-19. Noncompliance noted.
 KENNA, N B. Region 2, Atlanta, Befeguards Branch. 78/11/03. 22p. 94307-249.
- --7812110291 IE Insp Repts 50-324/78-27 & 50-325/78-27 on 781018-19. Noncompliance noted. Major areas inspected security plan access controls communications controls & security organization. MCOUTER D. P. Rector D. Atlanta, Defice of the Director.
- organization.
 MCGUIRE, D.R., Region 2, Atlanta, Office of the Director.
 GILLESPIE.F.P., Region 2, Atlanta, Safeguards Branch 78/11/01.
 3pp. 94337:291.
- 78111500B7 Forwards IE Circular 78-18.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director 78/11/06

 1p.
- 7811170232 Ack receipt of 781108 ltr informing NRC of steps taken to correct violations noted during inspec#50-324/78-18 & #30-325/78-18.
 SUTHERLAND, J. T. Region 2: Atlanta: Fuel Facility & Materials Safety Branch. 78/11/08. 1p. 94136:226.
- --7811170238 Responds to 780921 NRC ltr re violations noted in Inspec Repts#50-324/78-18 & #50-325/78-18. Corrective actions: self-locking spring loaded door locks installes, doors limiting access to high radiat areas will be yellow BANKS, H. R. Carolina Power & Light Co. 78/10/17. 2pp. 94136: 227.
- --7811170240 Forwards IE Inspec Repts#50-324/78-18 & #50-325/78-18 on 780808-11 & Notice of Violetion.
 BUTHERLAND.J. T. Region 2. Atlanta. Office of the Director. 78/09/21. 2pp. 94136:229.
- --7811170242 Notice of Violation from inspec on 780808-11.
 * Region 2, Atlanta, Office of the Director. 78/09/21. 1p.
- --7811170245 IE Inspec Repts#50-324/78-18 & #50-325/78-18 on 780808-11 during which i item of noncompliance was noted: Control of high radiat areas.
 TROUP.O.L. DAVIBLY H. Region 2. Atlanta, Fuel Facility &

94358:004.

- 7812210152 Forwards IE Inspec Repts#50-324/78-23 & #50-325/78-23 on 781002-06 during which no items of noncompliance were noted. 8UTH-ERLANOLJ T. Region 2. Atlanta. Fuel Facility & Materials Safety Branch 78/11/09. 2pp. 94278 176.
- --7812210155 IE Inspec Repts#50-324/78-23 & #50-325/78-23 on 781002-06 during which no items of noncompliance were noted Major areas inspected incl: radiat protec & radioactive weste mgt prog.

 TROUP.0 L. Region 2. Atlanta. Fuel Facility & Materials Sefety Branch. 78/11/09 7pp. 94278:178
- 7812180335 Provides info requested in IE Insper Repts#50-324/78-25 & #50-325/78-25. Info concerns verification of use of E-P seal mat1 in safety-related snubbers & determination of bleed rate at reted load.

 TOULISON.A C Caroline Power & Light Co. 78/11/16. 2pp.
- --7812180340 Parwards IE Inspec Repts#50-324/78-25 & #50-325/78-25 on 780924-9 during which no items of noncompliance were noted. LONG.F.J. Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 78/11/09 2pp. 94358-006.
- --7812180345 IE Inspec Repta#50-324/78-25 & #30-325/78-25 on 780926-9 during which no items of noncompliance were noted Major areas inspected incl: records. plant tour, pipe support & restraint sys. follow-up on IE circulars & requests HINCKLEY.O.Q., MHITENER.H.L., DANCE.H.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch, 78/11/09. 12pp. 94358:008.
- 7812120185 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Safeguards Newsletter. KENNA: M. B. Region 2. Atlanta, Safeguards Branch. 78/11/17, 4PP. 94277:083.
- 7812040359 Forwards IE Bulletin#78-12A.suppl to IE Bulletin 78-12. W/encl ANO: 7811300055. O'REILLY, J.P. Region 2. Atlanta. Office of the Director. 78/11/24. 6pp. 94127 143.
- 7812120294 Ack receipt of 781127 ltr informing NRC of steps taken to correct violations noted during investigation#50-325/78-29 & #50-324/78-29. KENNA: H. S. Region 2: Atlanta: Safeguards Branch. 78/12/07. 1p. 94294-329
- --7812130296 Responds to 781107 NRC ltr re viplations noted in Investigation Rept#50-325/76-29 & #50-324/78-29. Corrective actions: improved admin controls over documentation & testing of security force training prog have been implemented.

 BANKB.H.R. Carolina Power & Light Co. 76/11/27. 3pp. 94296:330.
- --7812130300 Forwards IE Investigation Rept#50-325/78-29 & #50-324/78-29 on 781023-25 & Notice of Violation.
 O'REILLY.J.P. Region 2: Atlanta: Office of the Director.
 78/11/07 2pp. 94296:333.
- --7812130304 Notice of Violetian from investigation on 781023-25.

 # Region 2. Atlanta. Office of the Director. 78/11/07. ip. 94294:335.
- --7812130310 IE Investigation Rept#50-325/78-29 & #50-324/78-29 on 781023-25 during which i item of noncompliance was noted: litensee permitted unqualified & improperly informed individual to guard security posts on 781016.

 KENNA, M. B. Region 2: Atlanta: Safeguards Branch. 78/11/06. 15pp. 94295:336.
- 7812130115 Documents reinaged results of four recirculation inlet notice safe ends & acceptability of continued oper of facils until most refueling outage. Concludes that continued oper presents no safety hazard to the public.

 UTLEY.E.E. Carolina Power & Light Co. 78/12/08. 45pp. 94295:331.
- 7812280024 Forwards IE Bulletin 78-14.
 D'REILLY, U.P. Region 2. Atlants, Diffice of the Director. 78/12/19.
 IP. 94131:057.
- R. Periodic operating reports & related correspondence
- 7810130121 Forwards Monthly Oper Rept for Sept 1978. BANKS, H.R. Caroline Power & Light Co. 78/10/10. 1p. 94079:298.

- 7811160091 Forwards monthly open rept for Oct 1978.

 BANKS.H R. Carolina Power & Light Co. 78/11/10. 1p. 94134:351.
- ~-7811160094 Monthly oper rept for Oct 1978 HILLIS.E. Carolina Power & Light Co. 78/11/02. 9pp. 94134:35
- 7812150330 Forwards Honthly Open Repts for Nov 1978.

 BANKS-H R. Caroline Power & Light Co. 78/12/11. 1p. 94022:043.
- --7812150332 Monthly Oper Repts for Nov 1978. WILLIG.E. Carolina Power & Light Co. 78/12/05. 12pp. 94022:0
- 8. Reportable occurrences. LERs & related correspondence
- 78101000R9 Forwards LER#78-065/03L-0.
 BANKS:H.R. Carolina Power & Light Co. 78/10/03. 1p. 94033:037.
- --7810100032 LERW78-066/03L-0 on 780904: rod block manitor "B" inoper trip came on & stayed on for 1/4 of the control rod selection matrix. Caused by Pailed integrated circuit in rod block monitor self-test circuitry.
 TOLLIBON. A C. Carolina Power & Light Co. 78/10/03. 1p. 94033-038
- 7810130177 Forwards LERM78-059/03L-0 BANKBiH R. Carolina Power & Light Co. 78/10/04. ip. 94003:020.
- --7810130181 LER#78-059/03L-0 on 780904:RCIC isolation channel "A" tripped momentarily.causing RCIC sys to be inoper, due to defective RX-2 relay.
 TCL-LISON.A C. Carolina Power & Light Co. 78/10/04. 1p. 94003-021
- 7810230143 Forwards LER#78-068/03L-0.
 BANKS-H.R. Carolina Power & Light Co 78/10/11. 1p. 94489:009.
- --7810230146 LERW78-068/O3L-D on 780912: during LPCI pump discharge pressure interlock channel functional test, pressure switches E11-P8-N0168 & E11-P8-N02DD felled to actuate at 115P810 due to corrosion buildup in switch plungers.

 a Carolina Power & Light Co. 78/10/11. 1p. 94489:010.
- 7810230193 Forwards LERW78-069/03L-0. BANKS:H.R. Caroline Power & Light Co. 78/10/11. 1p. 94052: 257.
- --7810230195 LERM78-069/03L-0 on 780912: Fire alarms received but wou not reset. Fire detection instrumentation not operable. Caused by smoke & dust resulting from welding & operation of jackhammer. Fire detectors cleaned & repaired.

 BANKS, H. R. Carolina Power & Light Co. 78/10/11. 2pp. 94052: 2
- 7810310232 Forwards LER#78-070/03L=0. BANKS-H.R. Caroline Power & Light Co. 78/10/23. 1p. 94090:355.
- --7810310236 LERW78-070/03L-0 on 780923:Reactor Coolent Conductivity exceeded micro-mho's in Tach Specs Caused by resterting RWGU filter pump after it had tripped which injected resin into reactor coolent. RWGU oper procedure will be revised.

 Carolina Power & Light Co. 78/10/23. 2pp. 94090:356.
- 7810310139 Forwards LER#78-071/03L-0.

 BANKB, H. R. Cerolina Power & Light Co. 78/10/24. 1p. 94090:165.
- --7810310142 LERW78-071/03L-O on 780924: RCIC sys component test foun that RCIC turbine trip k throattle valve E51-v8 was in closed position, due to unknown causa. TGLLISON: A. C. Caroline Power & Light Co. 78/10/24, ip. 94090: 166.
- 7810310217 Forwards LER#78-073/03L-0, BANKS, H. R. Carolina Power & Light Co. 78/10/25, 1p. 94090:321.
- ---7810310222 LER#78-073/03L-0 on 780927: condensate deep-bed deminers conductivity recorder found inoper during shift turnover inspec. Transmitter was turned off due to mislabeling of on-off suitch positions.
 TOLLIBON.A.C. Caroline Power & Light Co. 78/10/25, 1p. 94090: 322.
- 7811220187 LERW78-079/03L-0 on 781017: reactor bldg radiat exhaust Manitor DIE-RM-NGIOS failed safe causing reactor bldg vent

- 7812070175 Forwards LER#78-072/03L-0.
 BANKB.H.R. Carolina Power & Light Co 78/11/30 ip 94375-022.
- --7812070181 LERM78-072/03L-0 on 781101.rod block monitor(R8M) channel A was found out of callbr during testing due to setpoint drift Callbr Prequency will be increased from once to twice par year.
 TCLL180N.A.C. Carolina Power & Light Co. 78/11/30 ip. 794375-023.
- 7812200198 Forwards LERM78-082/03L-0. FURR-8.J. Carolina Power & Light Co. 78/12/13 1P 94148:358
- --7812200199 LERB78-082/O3L-O on 781117: while reactor was in hot shutdown torus level increased .2" above tech speck Caused by demineralized make-up water leakage through valves from RHR Keep-fill system causing torus level to rise.
 TOLLIBON.A.C. Caroline Power & Light Co. 78/12/13. 2PP. 94148: 359.
- 7812200200 Forwards LERM78-074/031-0 FURR.B.J. Carolina Power & Light Co 78/12/13. 1p 94148:361.
- --7812200201 LERW78-074/0DL-0 on 781112: reactor steam done high pressure switch 832-PS-N0188 did not reset & would not ellow RHR valve Ell-F008 to open for shutdown cooling at reactor pressure of 102psig Caused by eticking micro-switch TCLLI80N.A.C. Cerolina Power & Light Co. 78/12/13. 1p. 94148.362.
- 7812270298 Forwards LERW78-075/03L-0.
 BANKS-H.R. Ceroline Power & Light Co. 78/12/21. 10. 94229:338.
- ---7812270303 LERW78-075/03L-0 on 781122:HPCI & RCIC component tests were overlooked because rescheduling technique provided no clear indication of test due dates. Responsible technician reinstructed & admin operating instruction A01-5 rev. TCL-LIBON. A.C. Caroline Power & Light Co. 78/12/21. 2pp. 9429-359
- DOCKET 50-325 BRUNBWICK STEAM ELECTRIC PLANT, UNIT 1

 A. Application/construction stage documents & correspondence
- 7810130122 Analysis of suppression goal temp transients as requested by NRC 780113 ltr & as mod at 780309 meeting Work has begun & rept will be submitted in about 3 months.

 UTLEY, E. E. Carolina Power & Light Co. 78/10/10. lp. 94079:297.
- F. Security, medical, emergency & fire protection plans
- 7812080107 Notification of 781217 sits visit by R Leep & D Cameron, security plan reviewers affil w/Los Alemos Sci Lab. IPPCLITO, T.A. Operating Reactors Branch 3 (Prs 7906R5). 78/11/30. Rpp. 74107:334.
- P. Operating license stage documents & correspondence
- 7812080164 Confirms meeting on 781206 to discuss plans re safe-ends for refueling outage sched for January 1979. IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/29. 2pp. 94108:008.
- 7812:10023 Discusses possible dengers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justification for continuing A/encl ANO: #7812080207. IPPOLITO, T. Operating Reactors Branch 2 (Pre 790625). 78/11/29. 8pp. 94339:302.
- 7812110315 Notification of meeting on 781206 in Bethesda, MD to discuss condition of jet pump riser sefe-ends & evaluate related action proposed for refueling outage to begin Jan 1979.

 HANDON, J. N. Operating Reactors Branch 3 (Pre 790628). 78/12/01.

 1p. 94204:137.
- 7811220177 Withdraws request for extension fo subj facil inaccessible shubber inspec internal due to present operable status of facil.

 UTLEY.E.E. Carolina Power & Light Co. 78/09/22. ip.
- --78:1220:80 Requests temporary, one-time-only, Tech Specs change for subj facil to extend inaccessible inspec period thru 78:1004 due to continuing sus capacity shortage caused by forced maintenance outage. UTLEY, E. E. Carolina Power & Light Co. 78/09/20. 3pp.

- 7810110110 Responds to 780829 ltr indicating that no incident of control rods failing to fully insert occurred at subj facil.

 UTLEY.E.E. Caroline Power & Light Co. 78/10/04 ip 94066.356
- 7810130143 Has requested assistance from QE re-undetected single failures in reactor protects us pur supplies. Will not be able to respond to 780807 NRC ltr w/required info until 781215.

 UTLEY.E.E. Carolina Power & Light Co. 78/10/10 ip. 94002.315.
- 7810240127 Requests rev to Tech Spec for subj facil in response to 780912 NRC itr requesting rev to spec on total ennual gaseous releases.
 UTLEV.E.E. Carolina Power & Light Co 78/10/16 15pp.
- 7811130335 Burmary of 780914 meeting w/0E representatives & Mark 1 Duners Group re progress of Long Term Prog w/ettendance list & agenda(RD-9-A-Mark), Standards, 1 QRIMES, C. Plant Systems Branch (Pre 791030). 78/10/26 67pp.
- 7811090109 Requests ray of Teth Space for sub; facil re operability requirements for suppression pool-reactor bldg veruum breakers. Hanual valves will be closed & valves will be governed by admin controls.
 UTLEY, E. E. Caroline Power & Light Co. 78/11/03 4pp 94042:282.
- 7811240154 Notice of 781106 meeting in Bethesda w/CP&L to discuss compensatory measures to allow continued plant oper w/single valve isolation in RB-supression chamber vacuum relief lines.
- HAMMON: J.N. Operating Reactors Branch 3 (Pre 790625). 78/11/03. 1p. 94456: 259.
- 7811160135 Suppl to 781103 itr requesting amend to Tech Spec to mod operability requirements of suppression pool-reactor bidg vacuum breakers. Ltr documents info discussed w/staff during 781106 meeting & 781107 telcon.
 UTLEY.E.E. Cerolina Power & Light Co. 78/11/08. 5pp. 94135:236.
- 7811220279 Confirms verbal authorization to change Tech Epec at subj facil in response to 781103 request Amend allows all suppression pool-Reactor Bldg Vacuum breakers to be open w/opening setpoint of 0.5 paig w/manual valves closed. ORIMES.B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/08. 3pp. 94308:211.
- 7811210273 Notifies util of 781205 seminar in Atlanta to discuss new Model Rod Effluent Tech Specs & encl seminar info sheet, registration form, & proposed aganda. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/09. 5pp. 94480:162
- 7811290406 Forwards NRC staff paper.policy session item (BECY-78-554) relicenses reg performance eval. Three methods for eval are; statistical.trand analysis & regional survey method. W/o and.

 O'REILLY, J. P. Region 2, Atlanta, Office of the Director, 78/11/15.
 2pp. 94180:099.
- 7812150157 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop repistration of attenders to facilitate sending out mati. W/encl Registration Form & List of Locations.
 MILLER.J.R. Assistant Director for Bite & Befeguards (Pre 791030). 78/11/15. 5pp.
- 7612160274 Forwards Rev#i "Draft Radiological Effluent Tech Specs" for BHR's(NJREG-0473) & "Preparation of Radiological Effluent Tach Specs for Nuc Pur Plants" (NUREG-0133).

 GRIMES, B.K. Assistant Director for Engineers & Projects (Pre 790423). 78/11/15. 6pp. 94356:346.
- 7812i40176 Forwards Dct 1978 Prog Activity Review listing meetings hel & providing test-by-task activity summary for the month. BOBON.L. J. General Electric Co. 78/12/04. 11sp.
- 7812280114 Emphasizes importance of submitting accurate & complete inf to NRC by licenses & applicants. Info submitted must be substantiated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J.G. Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 94133:228.
- 7812210100 Forwards amends#42 & 17 to DPR-51 & DPR-62 & related Enviro Impact Appraisal & Fed Register Notice.
 BALLARD,R.L. Environmental Projects Branch 1: 78/12/15. 2pp. 94267:182.

- --7812210102 Amend#42 to Oper Lic DPR-62, changing the installation date of the cooling tower. MODRE, V.A. Assistant Director for Environmental Projects. 78/12/13. 2pp. 94289-184.
- --7812210104 Amend#17 to Oper Lic DPR-71, changing the installation date of the cooling tower MCORE.V A Assistant Director for Environmental Projects. 78/12/15. 3pp. 94269:186.
- --7812210107 Notice of Issuance of Amends#42 & 17 to Open Lics DPR-62 & 71 & Negative Declaration BALLARD: R L Environmental Projects Branch 1: 78/12/15. Rep. 94269 188
- --7812210109 Environ Impact Appraisal supporting Amends#42 & 17 to Oper Lics DPR-62 & 71 re cooling tower installation date. e Division of Site Sefety & Environmental Analysis. 78/12/15. 18bo 94269:190.
- 7812270192 Due to delays in QE's analysis of reactor protec sys pur supplies.CPL will be unable to respond to 780807 ltr as previously committed to in 781010 ltr.Estimates response by 790201. UTLEY.E.E. Carolina Power & Light Co. 78/12/18. 2pp. 94018:098.
- 7812270207 Forwards results of reactor recirculation safe ends inspec prog including a description of existing NDE techniques & discussions of alternate techniques. Concludes that present techniques used by subj facili

Q. Inspection reports: IE Bulletins & correspondence

- 7811170232 Act receipt of 781108 ltr informing NRC of steps taken to correct violations noted during inspec#50-324/78-18 & #50-325/78-18.
 SUTHERLAND.J T. Region 2, Atlanta, Fuel Fecility & Materials Bafety Branch. 78/11/08. 1p. 94136:226.
- --781117023B Responds to 780921 NRC ltr re violations noted in Inspec Repts#50-324/78-18 & #50-325/78-18 Carrective actions: self-locting apring loaded door locks installed doors limiting access to high radiat areas will be yellow. BANKS.H R Carolina Power & Light Co. 78/10/17. 2pp. 94134:827.
- --7811170240 Forwards IE Inspec Repts#50-324/78-18 & #50-325/78-18 on 780808-11 & Notice of Violation.

 BUTHERLAND.J.T. Region 2. Atlanta. Diffice of the Director. 78/09/21. 29p. 94136: 229.
- --7811170242 Notice of Violation from inspec on 780808-11.

 Region 2. Atlanta, Office of the Director. 78/09/21. 1p. 94136:231.
- --7811170245 IE Inspec Repts#30-324/78-18 & #50-323/78-18 on 780808-11 furing which I item of noncompliance was noted: Control of high radiat areas.

 TRDUP.Q.L., DAVIB.J.H. Region 2. Atlants, Fuel Facility & Materials Ba
- 7812110246 Forwards IE Insp Repts 50-325/78-27 & 50-324/78-27 on 781018-19. Noncompliance noted. KENPA-H. B. Region 2. Atlanta, Safeguards Branch. 78/11/03. 2pp. 94327:249.
- --7612110251 IE Insp Repts 50-324/78-27 & 50-325/78-27 on 781018-19. Noncompliance noted Major areas inspected security plan access controls, communications controls & security organization. MOQUIRE, D.R. Region 2. Atlanta, Office of the Director. GILLESPIE, F.P. Region 2. Atlanta, Befeguards Branch. 78/11/01. 3pp. 94337:251.
- 781230294 Act receipt of 781127 itr informing NRC of steps taken to correct violations noted during investigation#50-325/78-29 th #800-324/78-29.

 KENNA-M.B. Region 2, Atlanta, Safeguards Branch. 78/12/07. 1p. 94296:329.
- 7810310134 IE Inspec Repts#50-324/78-19 & #50-325/78-19 on 780808-11 during which no items of noncompliance were noted Major areas inspected included:calibr, surveillance, design & procurement changes & mods.

 KELLD90,P. J. Region 2: Atlanta, Diffice of the Director. QUZTB, J. E. Region 2: Atlanta, Pactor Operations Nuclear Support Branch, 78/09/20. 8pg. 94090:132.

- 7810310128 Forwards 1E Inspec ReptsM50-324/78-19 & M50-325/78-19 on 780808-11 during which no items of noncompliance were noted. LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/09/21. 2pp. 94090:131.
- 7811010397 Forwards IE Inspec Rept#80-324/78-20 & #90-329/78-20 on 780815-18 during which no items of honcompliance were noted. LONG F. J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/09/21. 2pp. 94388:313.
- --7811010402 IE Inspec Rept#50-324/78-20 & #50-325/78-20 on 780813-18 during which no items of noncompliance were noted. Major areas inspected included: licensee event rept. IE bulletins & circulars/follow-up of open items. HNGMLEY.D G. Region 2. Atlanta. Reactor Operations Nuclear Bupport Branch. 78/09/20. App. 74388:315.
- 7810110240 Ack receipt of 780830 ltr informing NRC of steps taken to correct violations noted during inspec#50-324/78-14 & 50-325 /78-14. BUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/09/27. Ip. 03555; 242.
- --7B10110242 Responds to 780717 NRC ltr re violations noted in Inspec Repts#30-324/78-14 & #30-325/78-14. Corrective actions: Rev checklist added to chlorination log & level limits added to log checklists.
 BANKS, H.R. Carolina Power & Light Co. 78/08/30. 3pp. 94068: 169.
- --7810110245 forwards IE Inspec Repts#50-324/78-14 & #50-325/78-14 on 780612-15 & Notice of Violation. BUTHERLAND.J.T. Region 2. Atlants. Fuel Facility & Materials Safety Branch. 78/07/17. 2pp. 94068:172.
- --7810110249 Notice of Violation from inspec on 780612-15. • Region 2. Atlanta: Fuel Fecility & Materials Safety Brench. 78/07/17. 2pp. 94068:174.
- --7810110253 JE Inspec Rept#50-324/78-14 & #50-325/78-14 on 78061R-15 during which 3 items of noncomplience were noted: failure to include specs in annual audit & surveillance techniques For chlorination.
 HUFHAM.J.M. Region 2. Atlanta, Fuel Facility & Materiala Bafety Branth. 78/07/14. 7pp. 94068:176.
- 7810110287 Act receipt of 780920 ltr informing NRC of steps taken to correct violations noted during Inspec#30-324/78-17 & #50-325/78-17.
 LONG,F.J. Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/09/27. ip. 03596:007.
- --7810110291 Responds to 780821 NRC ltr re violation noted in Inspac ReptM30-324/78-17 & M30-325/78-17. Corrective attions: personnel made aware of necessity of protec clothing. BAMMS.H.R. Commonwealth Edison Co. 78/09/20. Epp. 94068:317.
- --7810110295 Forwards IE Inspec Rept#50-324/78-17 & #50-325/78-17 on 780718-21 & Notice of Violation.
 LNW9.F.J. Region 2, Atlants. Reactor Operations Nuclear Support Branch. 78/08/21. 2pp. 94068:319.
- --7810110299 Notice of Violation from inaper on 780718-21. * Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 78/08/21. ip. 94068:321.
- --7810110302 IE Inspec Rept#30-324/78-17 & #80-323/78-17 on 780718-21 during which I item of noncompliance was noted: failure to follow approved health physics procedures.
 DANCE, H. C., HINCKLEY, D. O., RILEY, S. M. Region 2, Atlanta, Reactor Operations Nuclear Support Stanch. 78/08/21. App. 94068:382.
- 7811200029 Forwards IE Inspec Repts#50-324/78-24 & #50-325/78-24 on 780918.20-22.26-28 during which no items of noncompliance were noted.
 - MURPHY, C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/10/11. 2pp. 94215:305.
- --7811200034 iE Inspec Repts#50-324/78-24 & #50-325/78-24 on 780918,20-22,26-28 during which no items of noncompliance were noted. Major areas inspected included: Non-Destructive Eradination of Jet-Pump Riser Bafe-Ends.

 BLAKE.J.J., WILLIAMB.C.C., CONLON.T.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch, 78/10/11. Spp. 94215;307.
- 7810280249 Reports that no external pipe shubbers were found in United.
 None were found in United but one accessible shubber w/out
 a readable serial number was replaced.
 UTLEY, E. E. Carolina Power & Light Co. 78/10/17. ip. 94058:320.

- 7810270252 Forwards summary of 781016 meeting re subj facil inspec. O'REILLY.J P. Region 2. Atlanta. Office of the Director. 78/10/20. Ln. 94029 210
- --7810270272 Summary of 781016 meeting re util eval of BBEP Reactor Recirculation Bafe-End Examination Results Util will inform Region II whether Nov inspec can be deferred. BLAKE J J. Region 2. Atlanta. Office of the Director. 78/10/20. 2pp. 94029:211.
- 7810270111 Describes planned feedwater & control rod drive return line nozzle inspects to be performed during refueling outages.
 UTLEY.E.E. Carolina Power & Light Co. 78/10/24. 2pp. 94039:303.
- 7811090009 Ack receipt of 781026 ltr informing NRC of steps taken to correct violations noted during inspect50-324/78-21 & #50-G25/78-21. KENNA, H.B. Region R. Atlanta, Safeguards Branch. 78/11/01. 1p.
- -7811090013 Responds to 781003 NRC ltr re violations noted in Inspec Repts#80-324/78-21 & #50-325/78-21. Corrective actions:info w/held from public disclosure pursuent to 10CFR2.790. (See ANO:7810140041) FURR. B. J. Carolina Power & Light Co. 78/10/26. ip. 94039; 338.
- 7811150097 Forwards IE Circular 70-19. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/06.
- 7812210152 Forwards TE Inspec Repts#50-324/78-23 & #50-325/78-23 on 781002-06 during which no items of noncompliance were noted. BUTHERLAND, J.T. Region 2. Atlanta, Fuel Facility & Materials Sefety Branch. 78/11/09. 2pp. 94278:175.
- --7812210155 IE Inspec Repts#50-324/78-23 & #50-325/78-23 pm 781002-06 during which no items of noncompliance were noted. Major areas inspected incl:radiat protec & redicective waste mgt prog. TROUP, Q. L. Region 2. Atlanta. Fuel Facility & Materials Bafety Branch. 70/11/09. 7pp 94278:170.
- 7812180335 Provides info requested in IE Inspec Repts#50-324/76-25 & #50-929/70-25 Info concerns verification of use of E-P seal matl in safety-related snubbers & determination of bleed rate at rated load. TOLLIBON: A. C. Carolina Power & Light Co. 78/11/16. 2pp. 74358: 004.
- --7812180340 Forwards IE Inspec Repts#50-324/78-25 & #50-325/78-25 on 780926-9 during which no items of noncompliance were noted. LDNO:F.J. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/09. Rpp. 94358:006.
- --7812180345 IE Inspec Repts#50-324/78-25 & #50-325/78-25 on 780926-9 during which no items of noncompliance were noted Major areas inspected incl:records.plant tour.pips support & restraint sys.follow-up on IE circulars & requests. HINCKLEY.D.Q., WHITENER.H.L., DANCE.H.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch. 78/11/09. 12pp. 94750.002 74358, 008
- 7812120185 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Becurity Bafeguards Newsletter.
 KENNA, N. B. Region 2, Atlanta, Bafeguards Branch, 78/11/17, 4PP. 94277: 093.
- 7812040357 Forwards IE Bullstin#78-12A, suppl to IE Bullstin 78-12. W/encl ANG: 78:1300055. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/24. 6pp. 94127:143.
- 7812130296 Responds to 781107 NRC ltr re violations noted in Investigation Rept#50-325/78-29 & #50-324/78-29. Corrective actions:Improved admin controls over documentation & testing of security force training prog have been implemented. BANNS-H.R. Carolina Power & Light Co. 70/11/27. 3pp. 94296:330.
- ~-7812130300 Forwards IE Investigation Rept#50-325/78-29 & #50-324/78-29 on 781023-26 & Notice of Violation. O'REILLY J.P. Region 2: Atlanta: Office of the Director. 78/11/07. 2pp. 44296:330

--7812130304 Notice of Violation from investigation on 781023-25.

- --7812130310 IE Investigation Rept#50-325/78-29 & #50-324/78-29 on 781023-25 during which I item of noncompliance was noted: licensee permitted unqualified & improperly informed Individual to guard security posts on 781016. KENNA, H. B. Region 2. Atlanta, Bafeguards Branch. 78/11/04 15pp. 94296: 336.
- 7812130115 Documents reinspec results of four recirculation inlet notile safe ends & acceptability of continued open of facils until next refugling outage Concludes that continued open presents no safety hazard to the public UTLEY, E. E. Carolina Power & Light Co. 78/12/08. 43pp. 94295.33i.
- 7812280024 Forwards IE Bulletin 78-14. O'REILLY, J.P. Region 2, Atlanta, Office of the Director. 78/12/19. 1P 94131.057
- R. Periodic operating reports & related correspondence
- 7810130121 Forwards Monthly Open Rept For Sept 1978.

 BANKS, H. R. Caroline Power & Light Co 78/10/10. ip 94079 298
- --7810130124 Monthly Oper Rept for Sept 1978. WILLIS,E. Carolina Power & Light Co. 78/10/05. 13pp. 94079: 299.
- 7811160091 Forwards monthly open rept for Oct 1978.
 BANKS, H. R. Carolina Power & Light Co 78/11/10. Sp. 94134:351.
- --78iii60074 Monthly oper rept for Oct 1978. WILLIB, E. Carolina Power & Light Co 78/11/02. 9pp. 94134: 352
- 7612150330 Forwards Monthly Oper Repts for Nov 1978. BANKB, H.R. Caroline Power & Light Co. 78/12/11 74022:043.
- --7812150332 Monthly Oper Repts for Nov 1978. WILLIS, E. Carolina Power & Light Co. 78/12/05 12pp. 94022-044
- 9. Reportable occurrences. LERs & related correspondence
- 7810100049 Forwards LER#78-071/03L-0. BANKS, H. R. Carolina Power & Light Co 79/10/03. 1p. 94032:174.
- --7810100053 LER#78-071/03L-0 on 780905:during periodic test; radiat monitor DIR-RM-N010B HI-HI trip point drifted to higher than premitted level. Monitor recalibrated. Drift appears to be isolated incidentino further action taken. TOLLIBON, A. C. Carolina Power & Light Co. 78/10/03. 1p. 94032: 177.
- 7810130152 Forwards LER#78-072/03L-0. BANKS, H. R. Carolina Power & Light Co. 78/10/09. 1p. 94002.340.
- --7010130156 LERM78-072/03L-0 on 780911:Snubber 8M-14288164 found inoperable during periodic test. Caused by seal degradation & resulting loss of fluid.

 TGLLIBGN.A.C. Carolina Power & Light Co. 78/10/09. 1p. 94002: 361.
- 7810130189 Forwards LER 78-072/03L-0. BANKS: H. R. Caroline Power & Light Co. 78/10/09. 1p. 94079:151.
- 7810130158 Forwards LER#78-074/03L-0. BANKS, H. R. Carolina Power & Light Co. 78/10/10. 1p. 94003:001.
- --7810130162 LER#79-074/03L-0 pn 780911: during monthly #1 dissel generator load test it was found that #1 cylinder was not firing due to faulty fuel pump. TGLLIBUNYA.C. Carolina Power & Light Co. 78/10/10. 2pp. 94003: 002.
- 7811090194 Forwards LER#78-075/03L-0. BANKS, H. R. Carolina Power & Light Co. 78/11/02. ip. 94038;253.
- --7811090197 LER#78-075/03L-0 on 781004:pressure switch Eli-PB-NO!68 failed during periods PLCI pump discharges ADB permissive test due to corrosion buildup on plunger of switch.

 TOLLISON.A.C. Caroline Power & Light Co. 78/11/02. ip. 94038: 254.
- 7811160137 Forwards LER#78-078/03L-0.

- --7811160141 LERM78-078/03L-0 on 781105 Control open received control rod drift alarm for rod 10-31. When rod position display was selected, a false "3" was superimposed on actual rod position due to aground on the RPLS probe.
 TOLLISON A C Caroline Power & Light Co. 78/11/06. 2pp. 7413-245.
- 7811150138 Forwards LER#78-077/03L-0 FURR B. J. Carolina Power & Light Co. 78/11/07. 1p. 94135:247.
- --7811160144 LER#78-077/03L-O on 781006 condensate storage tank level suitch E41-LB-N003 found out of calibration during periodic condensate storage tank low level channel. Caused by instrudrift.

 TOLLISON.A.C Caroline Power & Light Co. 78/11/07. Ip 94135:248
- 7811160086 Forwards LERM78-076/03L-0.

 8ANKS, H R Catolina Power & Light Co 78/11/09 ip 94134:346.
- --7811160092 LER#78-076/03L-0 on 78101) torus level dropped below Tech Spec minimum while water from torus was being pumped via RQR to radwaste in efforts to raduce torus water level. Caused by operator being distracted. TOLLISON.A.C. Carolina Power & Light Co. 78/11/09. 1p.
- 7811160132 Forwards LERW78-083/03L-0.

 8ANKS.H.R. Carolina Power & Light Co. 78/11/09. ip 94135:233
- --7811160133 LER#78-083/03L-0 on 781014.RC1C Turbine wes tripped on menual overspeed for training purposes & turbine controlstop valve SS1-VB would not reset. Caused by improperly worn edjusted reset lever.

 **TOLLIBON.A C Caroline Power & Light Co. 78/11/09. 1p. 94135:234.
- 7812140158 Forwards LER#78-086/03L-0. \$ANMS,H.R. Ceroline Power & Light Co. 78/11/11. 1p. 94133:297.
- --7812140160 LER878-086/03L-O on 781109;Reactor vessel chemistry exceeded Tech 8gec limits for conductivity & Concentration due to presence of organic compounds in condensate sys. Organic filtration & high concentration of ion resin cleanup begun.

 Carolina Power & Light Co. 78/12/11. 3pp. 94133:298
- 7811170209 Forwards LERN78-082/01T-0. SANKS.H.R. Carolina Power & Light Co. 78/11/14. ip. 94136:101.
- --7811170213 LER#78-082/01T-0 on 781101; util was informed by NRR of nonconformence w/10CFR50 Append A Gen Design Criteria 54 & 56 Two reactor bidg-to-torus vacuum breater lines have never had design review by NRC Tech B
- 7811220193 Forwards LERH78-079/03L-D. BANKS, H. R. Carolina Power & Light Cd. 78/11/15. ip. 94074: 222.
- 7812070214 Forwards LER#78-081/03L-0 BANKS, H. R. Carolina Power & Light Co. 78/11/28. 19. 03555:105.
- --7812070217 LER#78-W081/03L-O on 781028:main steamline drain isolation valve 821-F017 failed to operate due to faulty brush holder in valve motor. Motor replaced & valve declared operable. TQL150N.A.C. Carolina Power & Light Co. 78/11/28. 1p. 03355:106
- 7812070165 Forwards LER#78-080/03L-0.
 BANKS-H.R. Carolina Power & Light Co. 78/11/30. ip. 94085:345.
- --7812070168 LER#78-080/03L-0 on 781101: containment oxygen monitor CAC-AT-1263 found inoperable. Caused by 2 defective lenon diodes & capacitors in oxygen analyzer transmitter. TCLLISON. A. C. Carolina Power & Light Co. 78/11/30, 1p. 74085: 346.
- 7812080127 Forwards LER#78-084/03L-0. BANKS, H. R. Carolina Power & Light Co. 78/12/01, 1p. 94106:346.
- --7812080130 LERW78-084/03L-0 on 781102:unit I reactor scrammed on loss of condenser vacuum & approximately 2 hours later the torus lavel went over Tech Spec limit by 0.2 inches/due to steam bloudoun & use of RCIC after scram & operator negligence. TCLL180N.A.C. Caroline Power & Light Co. 78/12/01. 1p. 94106:347.
- 7812210181 Forwards LER#78-089/03L-0.

 8ANMS-H.R. Carolina Power & Light Co. 78/12/14. ip. 94278:332.

- --7812210185 LERB78-089/03L-0 on 781114 during Periodic To HPCI EQR actuator failed to oper properly due to water hydraulic fluid corroding EQR actuator. Steam leaking p seat of velve HPCI E41-F001 allowed water into fluid. TOLLISON, A.C. Carolina Power & Light Co. 78/12/14. 94278:333
- 7812210187 Forwards LERM78-088/03L-0. 8ANKS.H.R. Carolina Power & Light Co. 78/12/14. 1p.
- --7812210192 LERM78-088/03L-0 on 781114: Fire hoses of Rado elevation fire stablons were found missing due to use personnel for routine radiuste washdown. New firehoses installed & mod re elternate weter supply is in progru TULLIBUN, A C. Carolina Power & Light Co. 78/12/14. 94278.338.
- 7812210218 Forwards LER#78-087/03L-0.
 8ANKS, H. R. Carolina Power & Light Co. 78/12/14. 1p.
- --7812210222 LERW78-087/03L-0 on 781114 torus level of the control sys was alightly above the allowed 27 inches. Forus level restored to normal Torus level indicator more clearly marked.

 TCLLIBON,A C. Carolina Power & Light Co. 78/12/14. 94279:120.
- 7812270288 Forwards LER#78-091/03L-0. FURR: B. J. Carolina Power & Light Co. 78/12/19. 1p. 5
- --7812270292 LERW7B-091/03L-0 on 781120: Senior Control Ophave completed hatch leak rate test before beginning startup due to misunderstanding. Test completed GP-1 rito require leak test varification by control operator TQLLISON. A C. Carolina Power & Light Co. 78/12/19. 9429: 339.
- DOCKET 50-026 UNIV. OF CALIFORNIA AT INVINE REB. REACTOR
 G. Inspection reports, le Bulletins & correspondence
- 7812080237 Forwards Inspec Rept#50-326/78-03 on 781016 & which no items of noncompliance were noted. CREMB.J.L. Region 5. Sen Francisco, Reactor Operations Support Branch. 78/10/21. 2pp. 94137:162.
- --7812080238 IE Inspac Rept#50-326/78-03 on 781016 t 19 d items of noncompliance were noted Major areas inspec refueling related activities. CANTER.H.L. MILLER.L.F., HORN.A.J. Region 5, Ban Fr Reactor Operations Nuclear Support Branch. 78/10/30. 94137:164.
- S. Reportable occurrences, LERs & related correspondence
- 7812060145 Forwards incident rept on 780928 involving fin ring dropped into reactor core. Present status ban on reoper pending decision on whether removel of objects bet the core should be attempted.

 ROMLAND.F.S. California, Univ. of. Irvine. 78/10/23.
 94382:001.
- DOCKET 30-327 BEOUDYAM NUCLEAR PLANT, UNIT 1

 A. Application/construction stage documents & corresponde
- 7811070240 Final rept re incorrect solenoids in chem vol valves. Overly long valve stroke times due to neglect by constr personnel to follow drawings.

 # Tennessee Vallay Authority. 78/09/08. ip. 94039:1
- 7812210323 Summarizes 780922 Licensing Schedules Review C re status of subj Facils & the lic review process.

 BOYD.R.S. Division of Project Management. DEVOUNO.R.C Site Safety & Environmental Analysis. MATTSON.R.J. Di Bystems Befety. 78/09/28. 12p. 03536:12B.
- 7810110138 Forwards info & test results showing Flamemast suitable substitute for Flamemastic 71-A.which is prohibly local govts due to asbestos content.
 GILELAND.J.E. Tennessee Valley Authority, 78/10/03.
 94069-201.
- 7610130262 Forwards request for add1 info re seismic desi review of applicant's rept "Justification of Seismic De Criteria Used for Bubj Facils, Phase I & II", BUYD, R. S. Division of Project Management. 78/10/04. 94079:171.

- 7810180093 Forwards statement providing addl justification of seismic design criteria used for subj facils.per NRC request of 780817. Statement supports conclusions drawn in TVA rept of
 - GILLELAND, J. E. Tennessee Valley Authority 78/10/06. 18pp.
- 7810230156 Hydrology Engr summary for subj facil as requested in 780913 L.G.Hulman ltr.Recommendations for Nev to Safety Eval Rapt is included BCHRIEBER, D.L. Consulting Engineering Geologist. AT-(49-24)-1283. 78/10/07. 38pp. 94164 302.
- 7810250120 Forwards environ monitoring rept. "Environ Radioactivity Levels Sequoyah Nut Plant 1977". GILLELAND J. E. Tennessee Valley Authority 78/10/19 Ip.
- --7810250122 "Environ Radioactivity Levels, Sequoyah Nuc Plant, 1977". Since the plant has not achieved criticality. It is not contributing radioactivity to the environ Increased tevels of radiat are a result of nuc weapons testing in China.

 * Tennessee Valley Authority. RH-78-4-801 78/09/30 45pp
- 7811070277 Forwards "Tritium Mgt Considerations for PWRs," prepared by GILLELAND, J. E. Tennessee Valley Authority. 78/10/19. 1p. 94040: 324.
- --7811070281 "Tritium Mgt Considerations for PWR's" re tritium dose assessments, alternative disposal methods & TVA conclusions. Concludes that release of overwhelming majority of tritium as liquid is the preferred method of disposal.

 * Tennessee Valley Authority. 78/10/19. 226pp.
- 7811010073 Forwards results of review of environ aspects of changes to subj facil. 4 encl: description of changes, referenced tables & drawings, environ assessment of changes, copy of "Tritium Mgt Considerations for PMRs", No suppl to FEB is nacessary, GILLELAND J. E. Tennessee Valley Authority. 78/10/30. 197pp. 94481:040
- 7Bii060094 Confirms that Solid State Protec Bys gen warning alarm circuit has been mod IAW Westinghouse Field Change Notices TVA-105955 Unit 1 & TEN-10572 Unit 2 QILLELAND, J. E. Tennessee Valley Authority. 78/10/30. 1p. 74424:144
- 7811290147 Notice of 781109 mesting in Bethesde w/util to review seismic questions & responses.
 81LVER.H. Light Water Reactore Branch 4. 78/11/02. 1p. 94239:331.
- 7811150137 Responds to 780330 & 780612 NRC request for eddl info on demonstration test & forwards 3 repts on sump & spray pumps. GILLELAND, J. E. Tennessee Valley Authority. 78/11/07. Rpp. 94272:304
- --7811150176 "Study of Effects of Steam Jets & Water Jets on Emergency Sump." Concludes that air entrainment due to break at steam generator nozzle will not adversely affect functional capability of sump. # Tennessee Vallay Authority. 78/09/30. 14pp. 94272:306.
- --7811150196 "Model Study of Bequoyah RHR Sump." Concludes initial design of sump was satisfactory for all design conditions incl worst-case SOX screen blockage, excepting air entrapment during initial filling. Tennesses Valley Authority. WM28-1-45-102. 78/10/31. FAIN.T. G. Tennes 29pp. 94272: 320.
- --7811150199 "Rev NPBH Calculations for RHR & Containment Spray Pumps Operating in Recirculation Mode. "Verifies effectiveness of the containment sump & describes constr of 1:4 scale physical model w/test results. * Tennessee Valley Authority. 78/10/27. 9pp. 94272:349.
- 78:11:50:52 Forwards draft response to Guestion#8 transmitted in 7705:0 NRC ltr.Response revs Amend#49 to Facil FBAR & will be incl in Amend#58.
 OILLELAND, J. E. Tennesses Valley Authority. 78/11/09. 18pp.
- 78:12:10:298 Notifies util of 78:12:05 seminar in Atlanta to discuss new Model Rod Effluent Tech Specs & ancl seminar info sheet. registration form & proposed agenda.

 D'REILLY, J. P. Region 2. Atlanta, Office of the Director. 78/11/09. Son.
- 7811160098 Responds to 780628 questions trensmitted by R Boyd re FSAR. Encl responses will be intorp into Amenda58 of FSAR. GILLELAND, J. E. Tennessee Velley Authority. 78/11/14. Opp. 94135:091

- 7811160148 Responds to 770802 NRC request for info re analytical modused to determine maximum containment temp & pressure for spectrum of postulated main steam line breaks for various reactor pur levels. GILLELAND. J E. Tennessee Valley Authority 78/11/14. 29pp. 94135: 265.
- 7811210305 Forwards Amend#37 to Lic Appl.
 MILLB.L.M. Tennessee Valley Authority. 78/11/15. 1p. 94487:193
- --7811210310 Amend#37 to Lic Appl consisting of deletion of chapter mejor rev to Section 15.4 to incl ECCS Append K enalysis & TVA's responses to questions 10-23 in 780628 NRC ltr. w .Tennesses Valley Authority. 78/11/17
- 7812060099 Urges timely & complete responses to NRC question to avoid further delays in proparing an acceptable SER for subject. Informs that earliest date SER can be issued is Feb 1979 due to numerous slippages in TVA responses. BOYD.R.S. Division of Project Management 78/11/15. 3pp. 94382-003.
- 7811280081 Forwards Rev#1"Draft Radioligical Effluent Tech Spec"for PMR's (NUREG-0472) & "Preparation of Radiological Effluent Tech Spec for Nuc Pwr Plants" (NUREG-0133). W/ancl ANO: 7811270173 & 7811270160. VASBALLD.D.B. Assistant Director for Light Water Reactors. 78/11/16 5pp. 02728:181.
- 7812080208 Forwards restated NRC views on seismic issues in Phase 11 of subj facils BOVD.R.S. Division of Project Management. 78/11/30. Spp. 94107:355.
- 7812080091 Forwards may response to 770810 NRC 1tm & add1 responses 780811 & 780628 NRC ltrs requesting info on preoper tests to be performed w/UHI sys & sequence of changeover oper from injection to recirculation. Office LAND, J. E. Tennessee Valley Authority. 78/12/04. 4pp. 9410R:028
- 7812150350 Forwards corrections to 781106 ltr transmitting environ 8 seismic qual info.

 GILLELAND, J.E. Tennessee Valley Authority. 78/12/05. 1p. 94418: 140.
- 7812110142 Responds to 781115 ltr relic sched for subjfacil.Forwar list of TVA responses to NRC questions dtd 1977 & 1978. Response to outstanding fire protectiesues will be submitted by 781215. Requests issuance of BER & ACRB hearing. GILLELAND, J. E. Tennessee Valley Authority. 78/18/06. 9pp. paggs. Cap. 94393:256.
- 7812280141 Emphasizes importance of submitting accurate & complete to NRC by licensess & applicants info submitted must be converge to receive a spinituality variety and the control of any inaccuracies or enforcement action will result. DAVIB.J.O. Office of Inspection & Enforcement, Office of the Director, 78/12/06, 2pp.
- 7812120158 Forwards Abnormal Open Instruc #AOI-1 for reactor trip & requested by V Benarous on 781027. The ADI addresses use of auxiliary feeduater sus. Invites NRC to view 790121 preoper hot functional test of subj sys.

 GILLELAND. J. E. Tennesses Valley Authority. 78/12/07. 10pp. 94276: 333.
- 7812120170 Forwards marked-up drawings of control room as requested NRC during 781027 meeting w/TVA, W/encl 3 oversize drawings available in Central Files.
 GILLELAND, J.E. Tennessee Valley Authority. 78/12/07. 4pp. 94275: 362.
- 7812180130 Forwids addl matt to Balance of Plant Class IE equip que Add1 mat1 not encl. QILLELAND, J. E. Tennessee Valley Authority. 78/12/07. 1p. 94366: 001
- 7812140242 Forwards requests for addl info re containment, elec, inst control sys of subj facil. VARGALS.A. Light Water Reactors Branch 4. 78/12/08. 13pp. 74205: 226.
- 7812270202 Responds to 781004 request for edd1 info on spiemic desibases for subj Pacils. Info discusses sensitivity of site specific 88E response spectra dev from strong motion records to probabilities of exceeding 98E design spectra.

 GILELAND, J.E. Tennesses Velley Authority. 78/12/19. 120pp. 94017: 220.

- 7812290047 Summary of a 781207 meeting w/TVA re Subj Facil Environ Tech Speck MATKINS,R v Environmental Projects Branch i 78/12/21. 2pp 94187.359
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 7B11020024 Rept of 780921 conference call w/TVA representatives re the resoulution of 20 open instrumentation % control items in subj facil draft SER Participant list enci. LASHERLOR Electric, Instrumentation & Control Systems Branch, 78/10/25 lipp 94355/340
- F. Becurity, medica), emergency & fire protection plans
- 7810220135 Submitting second interim rept re high pressure fire protection pump feilures. Redesigned mechanism for locking pump impeller to pump shaft Next rept will be submitted by 781103
 OILLELAND. J.E. Tennesses Valley Authority 78/09/14. 1p
- 7810300236 Notifies of 781026 meeting w/TVA to discuss fire protec at auty facil BILVER:H Light Water Reactors Branch 4: 78/10/19 3pp. 94034 038
- 7810310113 Forwards 780825 Physical Security Plan. revised to reflect latest changes in proposed security sys. Replaces 770310 Physical Security Plan. Encl withheld (ref. 10CFR2. 790) OILLELAND, J. E. Tennessee Valley Authority. 78/10/19 2pp. 94093, 318
- 7811140134 Forwards responses to 780920 NRC ltr re Radiological Emergency Plan & quality assurance prog Responses will be documented in Amend 38 of the FSAR OffLUELAND, JE Tennessee Valley Authority. 78/11/09. 13pp.
- 78[1150123 Forwards responses to fire protection review questions in Auxiliary Sys Branch 780901 ltr.
 OLLECAND, J.E. Tennessee Valley Authority 79/11/09. 85pp 0411a 140
- 7812180374 Summary of 781026 meeting w/epplicant to discuss protet items: Containment Annulus Area, ERCH Pur Cables, Feeduater Line Water Hammer & implementation schedule SILVER.H Light Water Reactors Brench 4 78/12/08. 6pp. 94338 200
- 7812210248 Forwards TVA's response to fire profec review questions#1, 812 & #13 re subj facil. Also encl are revised definition of implementation sched & minor editorial revs to TVA responses of 781109.

 O'LLELAND, J. E. Tennessee Valley Authority, 78/12/19, 104pp. 94188, 054
- K. Utility Final Safety Analysis Report (FSAR) & amends

. .

- 7810170197 Forwards affidavit certifying that on 781010, copies of Amend 55 to sub, Fecil FSAR were served on individuals identified in affidavit by use of U.S Mail.

 MILLS.t M. Tennessee Velley Authority. 78/10/10 2pp. 94411:256.
- 7811300198 Forwards cert of svc for amend \$7 to subj facil FSAR. MILLS.L.M. Tennessee Valley Authority. 78/11/24. 2pp.
- 7812120166 Forwards metl for NRC review of subj facil's change of cleaning procedures of austonitic pipe FBAR draft amend page 5.2-38.ref Hestinghouse specs 84351NL & 597760, & ref Dept of Energy Spers.RDT F-IT are encl.
 01LLELAND.J.E Tennessee Valley Authority 78/12/07. 33pp. 94278: 108
- 7819260131 Forwards Amend#38 to appl for subj facil FSAR, changing Chapters 5,7,8,9 t 12.

 OILLELAND, J.E. Tennessee Valley Authority. 78/12/21. 1p. 94028: 226.
- --7812260134 Amende58 to FBAR, changing Chapters 5,7,8,9 & 12.
 Tennesses Valley Authority, 78/12/21, 150pp. 94028:227.

- P Operating license stage documents & correspondence
- 7812040194 Rept on 780927 visit to facil for familiarization info. Industrial & transp facils & control room area wers observed.FBAR subjects were discussed W/list of participants
 FONTECTULA.H M Systematic Evaluation Programs Branch (Pt 78/11/20. 6pp 94457:122
- Q. Inspection reports, IE Bulletins & correspondence
- 7812120091 Forwards reproductions of articles that appeared Aug 1978 editions of Nuc Security Bafeguards Newsletter. KENNA.N B Region 2. Atlanta. Bafeguards Branch. 78/11/
- 7810270213 Forwards IE Inspec Repts #90-327/78-23 & #50-328. 780802-03 during which no items of noncompilance were not BUTHERLAND.J.T. Region 2. Atlanta. Fuel Facility & Mater Branch. 78/09/12 2pp. 94053:131
- --7810270221 IE Inspec Rept#50-327/78-23 & #50~328/78-17 on during which no items of noncompliance were noted Major areas inspected included: liquid waste sys status of unresolved items & preoper testing. EMALO.8 C , JACKSON.L. L. Region 2, Atlanta, Office of Director 78/09/12, 4pp. 94093.133
- 78110B0187 Forwards IE Inspec Repts#50-327778-22,#50-328/78 780802-03 during which no items of noncompliance were not SUTHERLAND, J. T. Region 2, Atlanta, Fuel Facility & Mater Branch. 78/097/27. 2pp 94403.131
- --7811080191 IE Inspec Repts#50-327/78-22,#50-328/78-16 on during which no items of noncompliance were noted Major areas inspected included; prepper environ monitoring, con effects monitoring, environ controls, metsorology measure CUNINGHAM,A.L. Region 2. Atlanta, Fuel Facility & Mat Bafety Branch. 78/09/27. App. 94405:133.
- 7811080194 Forwards IE Inspec Rept #30-327/78-25 on 780823which no items of noncompliance were noted. LONO,F.J. Region 2. Atlanta. Reactor Operations Nuclear Branch. 78/09/27. 2pp. 94405:142.
- --7811080198 iE inspec Repta#50-327/78-26 on 780823-25 duri items of noncompliance were noted Mejor areas inspected included, review of proper test procedures review of pr test packages unresolved items.facil tour. DYER.J.A., DONAT.T.J. Region 2- Atlanta, Reactor Opera Nuclear Support Branch. 78/09/27. 2pp. 94405 144.
- 7811130095 Forwards IE Inspec Repts#50-327/78-29 & #50-328/ 780829-30 & 780901 during which no items of noncompliance were noted. MURPHY.C.E. Region 2. Atlenta. Reactor Construction & Er Support Branch 78/10/02. 2pp. 94011:192.
- --7811130108 IE Inspec Repts#50-327/78-29 & #50-328/78-20 (during which no items of noncampliance were noted Major areas inspected included:procedures work activities qui related records for safety-related components.

 RAUSCH. J. K.; HARRIS, J. K.; HERDT. A. R. Region 2, Atlant. Construction & Engineering Support Branch. 78/10/02. 94011.194.
- 7811200021 Forwards IE Inspec Rept#50-327/78-28 on 780920-6 which no items of noncompliance were noted. LONG.F.J. Region 2. Atlanta. Reactor Operations Nuclear Branch. 78/10/13. 28p. 94213:280.
- --78:1200024 IE Inspec Rept#50-327/78-28 on 780920-23 duri items of noncompliance were noted Major areas inspecte included; preoper tests procedures. & facil. MATIN.R.D., DDNAT,T.J., Region 2. Atlanta, Diffice of 78/10/13. dep. 942:5:282.
- 7810230099 Forwards rev 5 to "Presvc Baseline Inspec & Ins Prog", incorporating changes to Class B presvc inspecs to include only those welds & components which req insvc examination. OllLELAND. J. E. Tennessee Valley Authority. 78/10/19.
- 7812050158 Forwards IE Inspec Rept#50-327/78-31 on 780919which no items of noncompliance were noted. LONG.F.J. Region 2. Atlanta, Resctor Operations Nuclear Branch. 78/10/23. 2pp. 94335:097.

- items of noncompliance were noted. Major areas inspected incl:preoper test prog administrative controls, new fuel storage test activities in progress WESSPAN.R.H., JERMING.H.D. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 78/10/23. 5pp 94335.099.
- 7812050303 Forwards IE Inspec Rept#50-327/78-30 & W50-328/78-22 on 780919-21 during which no items of noncompliance were noted. MURPHYC E Region 2. Atlanta, Reactor Construction & Engineering Buppart Branch. 78/10/24. 2pp 94203.044
- --7812050307 IE Inspec Rept#80-027/78-30 & #50-328/78-22 on 780917-21 during which no items of noncompliance were noted Major areas inspected inclineactor coolent pressure boundary piping welding records & sefety related structures welding. VANDOGRN.P K Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 78/10/23 App. 94203.046
- 7812060268 Forwards IE Inspec Repts#50-327/78-24.50-328/78-19 on 780926-29 during which no items of noncompliance were noted.
 MURPHY-C E Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch. 78/10/31. 2pp. 94372-241.
- --7812060274 IE Inspec Rets#50-327/78-24,50-328/78-19 on 780926-29 during which no items of nancompliance were noted Major areas inspected incl. licensee action on previous findings, licensee identified item. instru work & GC records.

 OIBBONS, T.D., RUFF, A. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/10/27, 5pp. 94372-243.
- 7012060287 Forwards IE Inspec Repts#50-327/78-32:50-328/78-23 on 780921-22 during which no items of noncompliance were noted.
 MURPHY.C E. Region 2. Atlanta, Reactor Construction & Engineering
 Support Branch. 78/10/31. 2pp. 94372:301.
- --7812040291 IE Inspec Repts#50-327/78-32.50-328/78-23 on 780921-22 during which no items of noncompliance were noted Major areas inspected incliaction on previous inspec findings, epoxy anchored bolts in concrete, ERCW concrete cells & pipe HARRIS.J.R., COMPTON.R.M. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/10/31, 4pp. 94372:303,
- 7812130001 Forwards IE Inspec Repts#50-327/78-27 & #50-328/78-21 on 780926-29 & Notice of Violation MURPHY.C.E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 78/11/01. 2pp 94318:266.
- --7812130004 Notice of Violation from inspec on 780926-29. Region 2, Atlanta, Office of the Director 78/11/01. 1p 74318 268.
- --7812130003 IE Inspec Repta#90-327/78-27 & #30-328/78-21 on 780926-29 during which I item of noncompliance was noted failure to document audits of all applicable glaments of the GA prog. HEROT. A R Region 2. Atlanta, Office of the Director.
 RAUSCH, J. K., MCFARLAND, C.R. Region 2. Atlanta, Reactor
 Construction & Engineering Support Branch 78/11/0]. 78/11/01. 13pp.
- 7811150073 Forwards TE Circular 78-18.

 D'REILLY, J. P. Region 2. Atlanta, Office of the Director, 78/11/06.
- 7812150030 Forwards IE Inspec Repts#50-327/78-34 & #50-328/78-25 on 781013 during which no items of noncompliance were noted.
 MURPHY-C E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 78/11/07. 2pp 94210:022
- --7812150040 IE Image: Repta#50-327/78-34 & #50-328/78-25 on 781013 during which no items of noncompliance were noted Major areas inspected incl:previously identified items concerning understrength concrete in Unit 1 & 2 shield bldge. HARRIS.J.R., COMPTON.R.M., BRYANT.J.C. Region 2, Atlanta, D of the Director. 78/11/02. 3pp. 94210.024. Region 2. Atlanta. Office
- 7812050111 Ack receipt of 781025 itr informing NRC of steps taken to correct violations noted during inspec#50-327/78-25 & #50-328/78-18 MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/11/21. ip. 94333-175.
- --7812050117 Responds to 781002 NRC ltr re violations noted in Inspec Rept#50-327778-25 & #90-328778-18. This is rev in response w/add1 infor as requested. Corrective actions several steps & to be taken are detailed re installation of proper shubers. GRLEDAND.J. E. Tennessee Valley Authority 78/11/14. 4pp. 94333: 176

- ReptsM30-327/78-29 & #30-328/78-18 Corrective actions:paint removed form grease fittings of snubber, proper lubrication documented, debris removed from spring can of support OILLELAND, J. E. Tennessee Valley Authority 78/10/29. 3pp. 74333 180
- --7812050140 Forwards IE Inspec Repts#90-327/78-25 & #50-328/78-18 o 780808-11 & Notice of Violation.

 MURPHY, C. E. Region 2. Atlanta: Reactor Construction & Engineers 94333.183. Support Branch. 78/10/02. 3pp
- --7812050147 Notice of Violetion from inspec on 780808-11
 Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 78/10/02 ip. 94333:186.
- --7812050150 IE Inspec Repts#50-327/78-25 & #50-328/78-18 on 780808during which I item of noncompliance was noted failure to follow procedures during hanger installation. ANG.W P., BRYANT.J.C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 78/07/29 5pp. 94333.187.
- 7812040369 Forwards IE Bullstine78-12A, suppl to IE Bulletin 78-12. H/encl ANO 7811300055. O'REILLY, J. P. Region 2. Atlanta. Defice of the Director. 78/11/20
- 7812060065 Ack receipt of 781130 ltm informing NRC of steps taken to correct violations noted during insp 50-327/78-14 & 50-328/78-10.

 MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch 78/11/30. 1p. 94232-264
- --7812050074 Responds to 781002 NRC ltr requesting add1 info re violanted in Inspec Repts#50-327/78-14 & 50-328/78-10 Corrective actions: amployees instructed to protect permanent equip incliinstructubing & stainless steel piping from arc denage. 91LtELAND. J. E. Tennessee Valley Authority. 78/11/09. 4pp. 94727-748 94232:265
- 7812070177 Forwards responses to 781111 IE Insp Repts 50-327/78-27 & 50-328/78-21.re GA unit audits.Contends full compliance has been meintained. Firm audit policy has been established. OILLELAND. J.E. Tennessee Valley Authority. 78/11/30 3pp. 94375: 025.
- 7812270229 Forwards 1E Bulletin 78-14.

 O'REILLY, J. P. Region 2. Atlante. Office of the Director. 78/12/1

 2pp. 94017; 131.
- 7812290114 Ack receipt of 781207 ltm informing NRC of steps taken to correct violations noted during inspec#50-327/78-33 & #30-328/78-24.

 MURPHY.C.E. Region 2. Atlanta: Reactor Construction & Engineering Support Branch 78/12/20. 1p. 94190:188
- --7812290117 Responds to 781115 NRC ltr re violations noted in Inspe Reptse30-027778-33 & #50-028778-24. Corrective actions: closer surveillance over meintenance of oven temp logs. QLLELAND.J.E. Tennessee Valley Authority. 78/12/07. 2pp.
- --7812290122 Forwards IE Inspec Repts#50-327/78-33 & #50-328/78-24 d 781025-27 & Notice of Violation. MURPHY.C.E. Region 2. Atlenta, Reactor Construction & Engineeri Bupport Branch. 78/11/16. 2pp. 94190:191.
- --7812290125 Notice of Violation from inspec on 781025-27.

 * Region 2, Atlanta, Office of the Director. 78/11/16. 1p. 94190.193.
- --7812290128 IE Imagec Repts#50-327/78-33 & #50-328/78j-24 on 781025 during which I item of noncompliance was noted: failure to log welding rod oven temp. VANDOORN,P.K.. CONLON.T.E. Region 2. Atlanta, Reactor Construct b Engineering Support Branch. 78/11/16. Spp. 94190:194.
- B. Reportable occurrences. LERs & related correspondence
- 7811070236 Forwards final deficiency rept re incorrect solenoids on valves.
 OILLELAND, J.E. Tennesses Valley Authority. 78/09/08. 1p. 94039: 187.
- 7810190164 Submits first interim rept re failure to provide seismically qualified path for makeup to spent fuel storage facil. Proposal under study to install qualified line & necessary valves from common discharge of pumps.

 GILLELAND. J. E. Tennessee Valley Authority. 78/09/14. 94414: 103.

- 7811030263 Forwards First Interim Rept re difference between Plant Configuration & Brawing NCR-2p.
 OILLELAND, J.E. Tennessee Valley Authority. 78/10/16 lp.
 02723:236
- --78:1000265 First Interim Rept of Deficiency NCR 2p: "Plant Configuration Different than Drawings of Record", due to error to TVA drawing certification process.

 OILLELAND.J.E. Tennessee Valley Authority 78/10/16 Ip. 02725-297.
- 7811070276 Third Interim Rept re Diesel Generator Hydraulic Actuator Motors. Btates that supplier has instructed governor aff to test governor speed control motor. Next rept will be submitted 781220.

 QILLELAND, J. E. Tannessee Valley Authority. 78/10/03 ip 94040: 299.
- 7812040192 Forwards final rept re incomplete documentation of seismic qual of elec penetrations.

 OILUELAND, J.E. Tennessee Valley Authority. 78/10/20 1P. 94457: 118.
- ~~7812040197 Final rept re incomplete documentation of seismic qual of elec penetrations. Documentation unitten per old TVA requirements. Current construc util ofthstand all design loadings & ho changes in hardware are req. Tennessee Velley Authority. 78/10/20. 1p. 94457:119.
- 7812010266 Forwards final deficiency rept re failure of sump valves to open during automatic switchover testing.

 91LELAND, J. E. Tennesses Valley Authority. 78/10/26. 1p. 94417: 154.
- --7812010268 Final rept on failure of sump valves to open during automatic switchover testing. Circuitry design was inadequate a schematics have been corrected. Correction will be tested before unit oper.

 ** Tennesses Valley Authority. 78/10/26. ip 94417:155.
- 78:1040063 Forwards final rept re reportable deficiency re OEDC GA auditeM77-7.
 OTLUELAND, J. E. Tennessee Valley Authority. 78/10/30. ip.
- 7812050265 Forwards final deficiency rept re-seismically qual path for makeup to spent fuel storage facil.
 OILLELAND, J.E. Tennessee Vailey Authority. 78/11/03. 1p. 94202:143.
- --7818050270 Final deficiency rept: seismically qual path for makeup to spent fuel storage facil not provided due to improper design. Line & valves will be installed & seismically qual. Francessee Valley Authority. 78/11/03. ip. 94202:164.
- 7812050121 Forwards final deficiency rept on Control Room Back Draft Damper Failure. 01LELAND, J.E. Tennesses Valley Authority, 78/11/08. ip. 94332:227.
- --7812060129 Final Rept: failure of Back Draft Damper in Main Control Room Air Handling Unit discovered during routine mod of eys.

 Damper lost all blades due to excessive blade bearing weer.
 Failed dampers replaced w/high-pressure units.

 * Tennessee Vallay Authority. 78/11/08. 1p.
- 7812140286 Forwards revised Pinal rept "Deficient Foundation Preparation for Concrete Culls for the ERCW Pumping Station Access Roadway." QILLELAND, J. E. Tennessee Valley Authority. 78/11/29. 1p. 03557:339.
- --7812140288 Revised rapt "Deficient Foundation Preparation for Concrete Cells for the ERCH Pumping Station Access Roadway."

 PILLELAND. J. E. Tennesses Valley Authority. 78/11/29. 3pp.

 0357: 360.
- DOCKET 50-328 SEGUDYAH NUCLEAR PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7812060099 Urges timely & complete responses to NRC question to avoid further delays in preparing an acceptable SER for subject. Informs that earliest date SER can be issued is Feb 1979 due to numerous slippages in TVA responses.

 80YD.R.S. Division of Project Management. 78/11/15. 3pp. 94382:003

- 7812080091 Forwards rev response to 770510 NRC itr & add1 m 780811 & 780628 NRC itrs requesting info on preoper tests be performed w/UHI say & sequence of changeover open from injection to recirculation. OILLELAND, J.E. Tennessee Valley Authority. 78/12/04. 4 94108-028
- 7812080208 Forwards restated NRC views on seismic issues in of subj facils.

 BOYD.R.B. Division of Project Management. 78/11/30. 59 94109:355
- 7812110142 Responds to 781113 ltr re lic sched for subj fat list of TVA responses to NRC questions dtd 1977 & 1978. Response to outstanding fire protec issues will be submitted by 781215. Requests issuence of SER & ACRS heari QILLELAND, J. E. Tennesses Valley Authority. 78/12/06. 5 74197-258
- 7812120158 forwards Abnormal Oper Instruc #AOI-1 for reactor requested by V Bensroys on 781027. The AOI addresses use of auxiliery feedwater sys. Invites NRC to view 790121 preoperate functional test of subject.

 GILLELAND. J.E. Tennesses Valley Authority. 78/12/07. 194276.333.
- 7811070240 Final rept re incorrect solenoids in chem vol & valves. Overly long velve stroke times due to neglect by constr personnel to follow drawings.

 Tennessee Valley Authority. 78/09/08. 1p. 94039:188
- 7812210323 Summarizes 780922 Licensing Schedules Review Comme status of subj Facils & the lic review process.
 BDYD.R.S. Division of Project Management. 78/09/28. 12
- 78:01:01:08 Forwards info & test results showing Flamemastic suitable substitute for Flamemastic 71-A, which is prohibibly local goots due to asbestos content.

 GILLELAND. J. E. Tennesse Valley Authority. 78/10/03. 374089-201.
- 7810130262 Forwards request for addi info re seismic designeries of applicant's rept "Justification of Seismic Designiteria Used for Subj Facils/Phase I & II".

 BOYD.R.B. Division of Project Hanagement. 78/10/04. 5(94079:171.
- 7810180093 Forwards statement providing add1 justification design criteria used for subj facils.per NRC request of 780817. Statement supports conclusions drawn in TVA rept 780301.

 GILLELAND. J.E. Tennessee Valley Authority. 78/10/06.
- 7810230156 Hydrology Engr summary for subj facil as reques L. Q. Hulman itr. Recommendations for Rev to Safety Eval Re is included. SCHRIEBER, D. L. Consulting Engineering Geologist. AT-(4' 78/10/07. 38pp. 94164:302.
- 7810250120 Forwards environ monitoring rept, "Environ Radi Levels Bequoyah Nuc Plant, 1977". GILLELAND, J. E. Tennessee Valley Authority, 78/10/19.
- --7810250122 "Environ Radioactivity Levels, Beguoyah Nuc Pl Bince the plant has not achieved criticality, it is not contributing radioactivity to the environ. Increased le of radiat are a result of nuc weapons testing in China e Tennesse Valley Authority. RH-78-4-801. 79/09/30
- 7811070277 Forwards "Tritium Mgt Considerations for PWRs." TVA. 91LELAND, J. E. Tennessee Valley Authority. 78/10/19, 94040:324.
- --7811070281 "Tritium Mgt Considerations for PHR's" re tri assessments: alternative disposal methods & TVA conclus Concludes that release of overwhalming majority of tri as liquid is the preferred method of disposal. "Tennasses Valley Authority, 78/10/19. 226pp.
- 78i1010073 Forwards results of review of environ espects of subj facil. 4 encl:description of changes, referenced table that drawings, environ essessment of changes, copy of "Tritiu Mpt Considerations for PHRS". No suppl to FES is nacesser GILLELAND, J.E. Tennessee Valley Authority. 78/10/30. 74481:060.

- 7811060094 Confirms that Solid State Protec Sys gen warning alarm circuit has been mod IAH Hestinghouse Field Change Notices TVA-105955 Unit 1 & TEN-10572 Unit 2.
 @ILLELAND.J.E. Tennessee Valley Authority. 78/10/30. 1p.
- 7811290147 Notice of 781109 meeting in Bethesda w/util to review seismic questions & responses.
 81LVER.H. Light Water Reactors Branch 4. 78/11/02. ip. 94239:331.
- 7811180137 Responds to 780330 & 780612 NRC request for add1 info on demonstration test & forwards 3 hepts on sump & spray pumps. OILLELAND, J. E. Tennessee Valley Authority. 78/11/07 2pp. 94272: 304.
- --7811150176 "Study of Effects of Steem Jets & Mater Jets on Emergency Sump." Concludes that air entrainment due to break at steam generator norsile will not adversely affect functional capability of sump.

 * Tennessee Valley Authority. 78/09/30. 14pp. 94272:306.
- --7811150196 "Model Study of Sequoyah RHR Sump." Concludes initial design of sump was satisfactory for all design conditions incl worst-case 50% screen blockage, excepting air entrapment during initial filling.

 FAIN.T.Q. Tennessee Velley Authority. HM28-1-45-102. 78/10/31. 27pp. 94272.320.
- --7811150199 "Rev NPBH Calculations for RHR & Containment Byray Pumpa Operating in Recirculation Mode. "Verifies effectiveness of the containment sump & describes constr of 1:4 scale physical model w/test results.

 # Tennessee Valley Authority. 78/10/27. 9pp. 94272:349.
- 7811130152 Forwards draft response to Guestion#8 transmitted in 770510 NRC ltr.Response revs Amend#49 to fecil FSAR & will be incl in Amend#58.
 GILLELAND, J. E. Tennessee Valley Authority. 78/11/09. 18pp. 94273:015
- 7811210288 Notifies util of 781205 seminar in Atlanta to discuss new Model Rod Effluent Tech Spece & encl seminar info sheet, registration form & proposed agenda.

 D'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/09.500.
- 7811160098 Responds to 780628 questions transmitted by R Boyd re FBAR. Entl responses will be incorp into Amend#58 of FBAR. OILLELAND.J.E. Tendessee Valley Authority. 78/11/14. Jpp. 94139: 091.
- 791114014B Responds to 770802 NRC request for info re analytical model used to determine maximum containment temp & pressure for spectrum of postulated main steam line breaks for various reactor pur levels.

 OILLELAND, J. E. Tennessee Valley Authority. 78/11/14. 29pp. 74133: 265.
- 7811210305 Forwards Amend#57 to Lic Appl. MILLB.L.M. Tennessee Valley Authority. 78/11/15. 1p. 94487:183.
- --7811210310 Amend#87 to Lic Appl consisting of deletion of chapter 16.
 major rev to Bection 15.4 to incl ECCE Append K analysis &
 TVA's responses to questions 10-23 in 780508 NRC ltr.
 # Tennesses Valley Authority. 78/11/17. 149pp. 94487:184.
- 7811280081 Forwards Rev#i"Draft Radioligical Effluent Tech Bpsc"for PWR's (NURE0-0472) & "Preparation of Radiological Effluent Tech Spsc for Nuc Pwr Plants"(NURE0-0133). W/encl ANO: 7811270173 & 7811270180. VASBALLD,D.B. Assistant Director for Light Water Reactors. 78/11/16. 6pp. 02728:181.
- 7812130330 Forwards corrections to 781106 ltr transmitting environ & seismic qual info.
 OILLELAND, J.E. Tennesses Valley Authority, 78/12/05. 1p. 94488: 140.
- 7812280141 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations, Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS, J. Q. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp.
- 7812120170 Forwards marked-up drawings of control room as requested by NRC during 781027 meeting w/TVA. W/encl 3 oversize drawings available in Central Files.
 GILLELAND, J.E. Tennesses Valley Authority. 78/12/07. 4pp. 94275:3Ap.

- 7812180130 Forwids add1 mat1 in Balance of Plant Class IE equip qua Add1 mat1 not enc1. OILLELAND.J E. Tennessee Valley Authority. 78/12/07. 1p. 94366:001.
- 7812140242 Forwards requests for add1 info re containment, elec, inst control sys of subj facil.
 VARQA, 8.A. Light Water Reactors Branch 4. 78/12/08 13pp. 94205; 226.
- 7812270202 Responds to 781004 request for add1 info on seismic desibases for subj facils. Info discusses sensitivity of site specific SSE response spectra dev from etrong motion records & probabilities of exceeding SSE design spectra OILLELAND. J.E. Tennesse Valley Authority 78/12/19 120pp. 94017: 220.
- 7812290047 Summary of a 781207 meeting w/TVA re Subj Facil Environ Specs.
 HATKINS.R.V Environmental Projects Branch 1. 78/12/21. 2pp. 94189:339.
- E NRC Safety Evaluation Report (SER), supple & correspondence
- 7811020024 Rept of 780921 conference cell w/TVA representatives re the resculption of 20 open instrumentation & control items in subj facil draft BER.Participant list encl. LASHER.D.R. Electric, Instrumentation & Control Bystems Branch. 78/10/25. 11pp. 94355:340
- F. Security, medical, emergency & Pire protection plans
- 7810230135 Submitting second interim rept re high pressure fire protection pump failures. Redesigned mechanism for locking pump impeller to pump shaft. Next rept will be submitted by 781103.

 OILLELAND, J. E. Tennesses Valley Authority. 78/09/14. ip. 94271:173
- 7810300236 Notifies of 781026 meeting w/TVA to discuss fire protects subj facil. 8ILVER.H. Light Weter Reactors Branch 4. 78/10/19. 3pp. 94034:038.
- 7810310113 Forwards 780825 Physical Security Plan, revised to refle latest changes in proposed security sys. Replaces 770510 Physical Security Plan. Encl withheld (ref 100FR2.790). GILLELAND, J.E. Tennessee Valley Authority. 78/10/19. 2pp. 94093:318.
- 78:1140:34 Forwards responses to 780920 NRC ltr re Redicingical Emergency Plan & quality assurance prog. Responses will be documented in Amend 58 of the FBAR. O'LLELAND. J.E. Tennessee Velley Authority. 78/11/09. 15pp. 94423: 250
- 7811150123 Forwards responses to fire protection review questions i Auxiliary Bys Branch 780901 ltr. OlLLELAND. J.E. Tennessee Valley Authority. 78/11/09. 85pp. 94114:149.
- 7812180374 Bummary of 781026 meeting w/applicant to discuss protectitems: Containment Angulus Area. ERCM Pur Cables, Feedwater Line Mater Hammer & implementation schedule.

 SILVER, H. Light Mater Reactors Brench 4. 78/12/08. App. 94358: 200.
- 7812210248 Forwards TVA's response to fire protec review questions? 812 & 813 re subj facil. Also encl are revised definition of implementation sched & minor editorial revs to TVA responses of 781109.

 QILLELAND, J. E. Tennesse Valley Authority. 78/12/19. 104pp. 74/46: 034.
- K. Utility Final Safety Analysis Report (FBAR) & amends
- 7812120166 Forwards meth for NRC review of subj facil's change of cleaning procedures of austenitic pipe.FBAR draft amend page 0.2-36.ref Westinghouse space 94351NL & 597760, & ref Dapt of Energy Space.RDT F-1T are ancl. 01LLELAND, J. E. Tennessee Velley Authority. 78/12/07. 33pp. 94278:108.
- 7810170197 Forwards affidavit certifying that on 781010, copies of 8 55 to subj facil FBAR were served on individuals identified in affidavit by use of U.S. Mail.

 MILLE, L. M. Tennassee Valley Authority. 78/10/10. 2pp. 94411:5

- 7811300198 Forwards cert of evc for amend 57 to subj facil FBAR. NILLS, L. M. Tennessee Valley Authority. 78/11/24. 2pp.
- 7812260131 Forwards Amend#58 to appl for subj Pacil FSAR changing Chapters 5,7,8,9 & 12.
 OILLELAND, J.E. Tennessee Valley Authority, 78/12/21, ip. 94028:226
- --7812260134 Amend#59 to FSAR, changing Chapters 5.7, 8, 9 % 12.
 P Tennessee Veiley Authority, 78/12/21, 150pp. 94028; 227.
- G Inspection reports, IE Builetins & correspondence
- 7812120051 Forwards reproductions of articles that appeared in June & Aug 1978 editions of Nuc Security Bafeguards Nawsletter.
 KENNA.W.B. Region 2. Atlanta, Safeguards Branch. 78/11/17. 4PP.
- 7810270213 Forwards IE Inspec Repts #30-327/78-23 & #30-328/78-17 on 780802-03 during which no items of moncompliance were noted. BUTHERLAND, J. T. Region 2. Atlanta, Fuel Facility & Materials Bafety Branch. 78/09/12. 2pp. 94053:131.
- --7810270221 IE Inspec Rept#50-327/78-23 & #50-328/78-17 on 780802-03 during which no items of noncompliance were noted Major areas inspected included: liquid waste sys, status of unresolved items & preuper testing.

 ETALD, B. C. JACKBON-L. L. Region 2, Atlanta, DPPice of the Director 78/09/12, 4pp. 94053:133.
- 7811090187 Forwards 1E Inspec Repts#50-327/78-22,#50-328/78-16 on 780802-03 during which no items of noncompliance were noted. BUTHERLAND.J. Region 2. Atlants. Fuel Facility & Materials Safety Branch. 78/09/27 2pp. 94405:131.
- --78:1080191 IE Inspec Repts#50-327/78-22,#50-328/78-16 on 780802-03 during which no items of moncompliance were noted Hajor areas inspected included prepayer systrom monitoring, constreeffects monitoring, environ controls meteorology measurement. CUNNINGHAM, A. L. Region 2, Atlanta, Fuel Facility & Materials Bafety Branch. 78/09/27. App. 94403:133.
- 7811130095 Forwards IE Inspec Repts#50-327/78-29 & #50-328/78-20 on 780829-30 & 780901 during which no items of noncompliance were noted. MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 78/10/02. 2pp. 94011:192.
- --78113010B IE Inapec Repta#50-327/78-29 & #50-328/78-20 on 780829-30 during which no items of noncompliance were hoted Hejor areas inspected includes: procedures work activities, quality related records for sefety-related components.

 RAUSCH. J. K., HARRIS, J. K., HERDT, A. R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/10/02. 7pp. 9401: 194.
- 7810250095 Forwards ray 5 to "Presyc Baseline Inspec & Insyc Inspec Prog", incorporating changes to Class B presyc inspecs to include only those welds & components which req insyc examination.

 OllLELAND. J. E. Tennesses Valley Authority. 78/10/19. App.
- 7812090303 Forwards IE Inspec Rept#50-327/78-30 & #90-328/78-22 on 780919-21 during which no items of noncompliance were noted. MURPHY-C.E. Region 2, Atlants, Reactor Construction & Engineering Bugport Branch. 78/10/24. 2pp. 94203:044.
- --7812050307 IE Inspec Rept#50-327/78-30 & #50-328/78-29 on 780919-21 during which no items of noncompliance were noted Major areas inspected inclineactor coolant pressure boundary piping welding records & safety related structures welding. Vendodnn.P.K. Region & Atlanta, Reactor Construction & Engineering Bupport Branch. 78/10/23. 4pp. 94203-046.
- 7812040248 Forwards IE Inspec Repts#50-327/78-24,50-328/78-19 on 780924-29 during which no items of nontempliance were noted, MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/10/31, 2pp. 94372:241.
- --7812060274 IE Inspec Rets#50-327/78-24.30-328/78-19 on 780926-29 during which no items of honcompilance were noted Major areas inspected incl:licensee action on previous findings, licensee identified Item, instru work & GC records.

 GIBDONS, T. D. RUFF, A. Region 2, Atlanta, Reactor Construction & Engineering Support Brench. 78/10/27. Spp. 94372:243.
- 7812060287 Forwards IE Inspec Repts#50-327/78-32,50-328/78-23 on 780921-22 during which no items of noncompliance were noted. MVRPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Bupport Branch. 78/10/31. 2pp. 94372:301.

- ---7812060291 IE Inspec Repts#50-327/78-32.50-328/78-23 on 780921-22 during which no items of noncompliance were noted Major areas inspected inclinetion on previous inspec findings. epoxy anchored bolts in concrete.ERCH concrete cells & pipe. HARRIS, J.R., COMPTON.R.M. Region 2. Atlants. Reactor Construction & Engineering Support Branch. 78/10/31. 4pp. 94372:303.
- 7812130001 Forwards IE Inspec Repts#50-327/78-27 & #50-328/78-21 on 780926-29 & Notice of Violation MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Brench. 78/11/01. 2pp. 94318:266.
- --7812130004 Notice of Violation from inspec on 780926-29.

 * Region 2. Atlants, Office of the Birector. 78/11/01. is.
- --7812130005 IE Inspec Repts#50-327/78-27 & #50-328/78-21 on 780926-29 during which I item of noncompliance was noted: failure to document audits of all applicable alements of the GA prog. HERDI.A.R. Region 2, Atlanta, Office of the Director. RAUBCH.J.K. MCFARLAND.C.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/11/01. 13pp. 9A318-3A9
- 7811150073 Forwards IE Circular 78-18.

 D'REILLY, J. P. Region 2. Atlanta. Diffice of the Director. 78/11/06.

 19.
- 7812130030 Forwards IE Inspec Repts#30-327/78-34 & #50-328/78-25 on 781013 during which no trems of noncompliance were noted. MURPHY.C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/11/07. 2pp. 94210.022.
- --7812150040 IE Inspec Repts#50-327/78-34 & #50-328/78-25 on 781013 during which no items of noncompilance were noted Major areas inspected incli-reviously identified items concerning underestrangth concrete in Unit 1 & 2 shield bldgs. HARRIB.J.R., COMPTON.R.M., BRYANI.J.C. Region 2, Atlanta, Defice of the Director. 78/11/02. 3pp. 94210:024.
- 7812030111 Ack receipt of 781023 ltr informing NRC of steps taken to correct violations noted during inspec#50-327/78-25 & 450-328/79-18.

 MURPHY.C.E. Region 2, Atlenta, Reactor Construction & Engineering Bupport Branch. 78/11/21. 1p. 94333:175.
- --7812080117 Responds to 781002 NRC itr re violations noted in inspec Rept#50-327/78-25 & #50-328/78-18. This is rev in response w/add1 infor as requested. Corrective actions: several steps & to be taken are detailed re installation of proper snubers. GILLELAND, J. E. Tennessee Valley Authority, 78/11/14. 4pp.
- ~-7812050125 Responds to 781002 NRC ltr re violation noted in Inspec Repts#30-327/78-25 & #30-328/78-18. Corrective actions: paint removed form grease fittings of snubber, proper lubrication documented, debris removed from spring can of support. 91LLELAND.J.E. Tennessee Valley Authority. 78/10/25. 3pp. 7433: 180.

94333: 176.

- ---7812030140 Forwards IE Inspec Repts#50-327/78-25 & #50-328/78-18 on 780808-11 & Notice of Violation. MRPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Brench. 78/10/02. 3pp. 94333:183.
- --7812050147 Notice of Violation from inspec on 780808-11.

 Region 2. Atlanta, Reactor Construction & Engineering Support Branch. 7870/02. 19. 94032:186.
- --7812050150 IE Inspec Repts#50-327/78-25 & #50-329/78-18 on 780808-19 during which I item of noncompliance was noted: failure to fallow procedures during hanger installation. AND, M.P., BRYANT.J. C. Region 2, Atlanta, Reactor Construction & Engineering Support Brench. 78/09/29, 5pp. 94333:187.
- 7812040369 Forwards IE Bullstin#78-12A, suppl to IE Bulletin 78-12. W/ancl ANO: 7811300055. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/11/24.
- 7812060065 Ack receipt of 781130 1th informing NRC of steps taken to correct violations noted during inep 50-327/78-14 & 50-327/78-10.

 MURPHY.C. E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/11/30. 1p. 94232:264.

DOCKETED ITEMS

- +-7812060074 Responds to 781002 NRC 1tr requesting add1 info re violation noted in Inspec Repts#50-327/78-14 & 50-328/78-10. Corrective actions: employees instructed to protect permanent aquip incl instructuoing & stainless steel piping from arc damage. OILLELAND.J.E. Tennessee Vallmy Authority. 78/11/09. App. 94232: 265.
- 78:2070177 Forwards responses to 78:111 IE Insp Repts 30-327/78-27 & 50-328/78-21, re GA unit audits Contends full compliance has been maintained Firm audit policy has been established.

 OILLELAND. J. E. Tennesses Valley Authority. 78/11/30. 3pp.
- 94375: 025.
- 7812270227 Forwards IE Bulletin 78-14. O'REILLY, J. P. Region 2, Atlanta, Office of the Director. 78/12/19, 2pp. 94017:131.
- 7812290114 Ack receipt of 781207 ltr informing NRC of steps taken to correct violations noted during inspec#50-327/78-33 &
- #50-G28/78-24.
 MURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 78/12/20. ip. 94190:188.
- --7812290122 Forwards IE Inspec Repts#50-327/78-33 & #50-328/78-24 on 781025-27 & Notice of Violation.
 MLRPHY,C.E. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 78/11/16. 2pp. 94190:191.
- --7812290125 Notice of Violation from inspec on 781025-27.

 * Region 2, Atlanta, Office of the Director. 78/11/16. ip.
- - during which I item of noncompliance was noted: failure to log welding rud oven temp.
 VANDORN.P.K., CONLON.T.E. Region 2: Atlanta, Reactor Construction
 & Engineering Support Branch. 78/11/16. 3pp. 94190:194.

-~7612290126 [E [napec Repts#50-327/78-33 & #50-328/78]~24 on 781025-27

- 8 Reportable occurrences, LERs & related correspondence
- 7812010266 Forwards final deficiency rept re failure of sump valves to open during automatic switchover testing. GILLELAND.J.E. Tennessee Valley Authority. 78/10/26. ip. 94417: 134.
- --7812010268 Final rept on failure of sump valves to open during automatic switchover testing Circuitry design was inadequate & schematics have been corrected. Correction will be tested
 - before unit oper.
 * Tennessee Valley Authority. 78/10/26. 1p. 94417:155.
- 7812140288 Revised rept "Deficient Foundation Preparation for Contrete Cells for the ERCH Pumping Station Access Roadway."

 OILLELAND. J. S. Tennessee Valley Authority, 78/11/27. 3pp.
- 03557:360. 7811070236 Forwards final deficiency rept re incorrect solenoids on
- valves. QILLELAND, J. E. Tennessee Valley Authority, 78/09/08. ip. 94039: 187.
- 7810190164 Bubmits first interim rept re failure to provide seismically qualified path for makeup to spent fuel storage facil Proposel under study to install qualified line & necessary valves from common discharge of pumps. GILLELAND. J.E. Tennasses Valley Authority. 78/09/14. 2pp.
- 94414: 103. 7811030263 Forwards First Interim Rept re difference between Plant
- Configuration & Drawing NCR-2p.
 GILLELAND J. E. Tennessee Valley Authority. 78/10/14. 1p. 02725: 256.
- ~-7811030265 First Interim Rept of Deficiency NCR 2p: "Plant Configuration Different than Drawings of Record", due to error to TVA drawing certification process. OILLELAND, J.E. Tennessee Valley Authority. 78/10/16. ip. 02725; 257.
- 7811070276 Third Interim Rept re Diesel Generator Hydraulic Actuator Motors. States that supplier has instructed governor mag to test governor apsed control motor. Next rept will be submitted 781220.

 OILLELAND. J. E. Tennessee Valley Authority. 78/10/05. 1p. 94040: 299.

- --7612040197 Final rept re incomplete documentation of seismic quel o elec penetrations. Documentation written per old TVA requirements. Current construc will withstand all design loadings & no thanges in hardware are req. • Tennesses Valley Authority. 78/10/20. ip. 94457:119.
- 7812030265 Forwards final deficiency rept re seismically qual path formakeup to spent fuel storage factl.
 GILLELAND, J. E. Tennessee Valley Authority. 78/11/03 ip.
- 94202: LA3.
 - --7812050270 Final deficiency rept: seismically qual path for makeup t spent fuel storage facil not provided due to improper design. Line & valves will be installed & seismically qual. # Tennesses Valley Authority. 78/11/03. 1p. 94202:164. # Tennesses Valley Authority.
 - 7812060121 Forwards final deficiency rept on Control Room Sack Draft Dampar Failurs.
 GILLELAND, J.E. Tennessee Valley Authority. 78/11/08 ip. 94332: 227.
 - -7812040129 Final Rept: Pailure of Back Draft Damper in Main Control | Air Handling Unit discovered during routine mod of sys.

 Damper lost all blades due to excessive blade bearing wear.

 Failed dampers replaced w/high-pressure units.

 Tentlog land. * Tennessee Valley Authority, 78/11/08.
 - 7812140286 Forwards revised Pinel rept "Deficient Foundation Preparation for Concrete Cells for the ERCW Pumping Station Access Roadway." GILLELAND, J. E. Tennessee Valley Authority, 78/11/29. Ip. 03557: 359.
 - DUCKET 50-329 MIDLAND PLANT, UNIT 1 A. Application/construction stage documents & correspondence
 - 7810270024 Forwards I & E Initial Rept on Response to Bulletin
 - 77-03/05A re Use of Elec Connectors appropriate 84s should be natified where there is a question re use of connectors in agenty eye: 780207 memo elso encl.
 TEDEBCO,R.L. Assistant Director for Plant Bystems. 78/02/08. ip.
 - --7810270246 Forwards "Status of Responses from Licensees of Plants of Construc to Sulletins 77-05 & 05A".
 MOSELEY, N. C. Division of Reactor Construction Inspection. 78/02/07 Эрв.
 - 7810310061 Forwards preliminary chart on results of land use survey completed lest year re building & housing trends in Midland County 1969-1977.

 * Midland County, MI. 78/04/10. 3pp. 94093:179.
 - 7810140004 Notice of time & agenda change for meeting on 781025 to discuss augmented insic inspac & testing of pumps & valves.

 HOOD, D. Light Water Reactors Branch 4. 78/09/23. 5pp. 94329:097 7810120072 Forwards BBW rept "Analysis of Bearing Failure in LM&G 900
 - HP Vertical Pump Motor Resulting From Gil Cooler Failurs" prepared for CPC Rept available in CF only, DOMELL.8. Consumers Power Co. 78/10/05. ip. 94470:345. --7810120077 "Analysis of Bearing Failure in LMAG 9000HP Vertical Pun
 - Motor Resulting from Oil Cooler Failure*prepared by B&W for CPC.& forwarded to NRC. Determines Kingsbury thrust bearing to be critical component in event of oil cooler failure.

 * Babcock & Wilcox Co. 77/10/10. 107pp.
- 7810130231 Forwards archaeological site survey for Midland County, MI to be added to minutes of Baginaw meeting of 780906.

 BRUNETT: F. V. Baginaw Archaeological Commission. 78/10/05. 11pp.
- 7810200128 Requests add1 info as result of sits visit to subj facil order to review environ factors. Response should be submitted by 781025. Response should be suppl to Environ Rept. REGAN, W. H. Environmental Projects Branch 2. 78/10/11, 9pp. 94366: 310.
- 7810230375 Believes that there is a potential problem w/Class IE bettery racks supplied to suby facil.Addl isolation bar for assamic protec will be evailable for retrofit w/in 60 days. MCMANUS.C. K. ESB. Inc. 78/10/11. 1p. 94271:184.

7810190066 Forwards duplicate of original 780629 itr containing affidavit re proprietary response to request for addl info. Ltr not previously received.

7812040192 Forwards final rept re incomplete documentation of seismic

- 781:010308 CPC request to withhold as proprietary section 4.C of their gen Agreement w/Dow of 780621 per 10CFR2790 is granted.
 LYNCH.O.D. Environmental Projects Branch 2 78/10/12. 2pp. 94389 160
- 7810240013 Forwards summary dtd 780327: "Summary of March 21-22,1978 meeting & site visit", for the info of the NRC.
 TOURTELLOTTE, J. Office of the Executive Legal Director. 78/10/13. 10.
- --7810240017 Summary of 780321 & 22 meeting w/util in Midland,MI re facility const completion schedule. CRDCKER, L. P. Division of Project Management. 78/03/27. 13pp.
- 7810240213 Requests eddl info for FBAR review.W/encl questionnaire. VARGA.S. A. Light Water Reactors Branch 4. 78/10/13. BOpp.
- 7810230199 Repts on site visit to subj Pacil during week of 780905. Encloses summerized schedule of week's activities & principal personnel contacted. LYNCH.D.D. Environmental Projects Branch 2 78/10/13. 15pp. 94392 205
- 7810250099 Forwards enci preliminary rept "Prelimiary Pump & Valve Inservice Testing Program for CPC Midland Plants Units 1 & 2." Submitted in response to NRC question or FBAR.Plan.in part to form basis of 781025 meeting w/NRC. HOWELL.S.H. Consumers Power Co. 78/10/18. 2pp.
- --7810250100 "Pump & Valve Insvc Testing Prog" covering definitions of operational modes pump summary listing legend & requests for relief from Section-XI requirements.
 PETERSEN.T.A. RICE.R.M. BUCZHINSKI.T.A. Consumers Power Co. 78/10/18 123pp.
- 7810230131 Requests add1 info to estimated GNP annual growth & QN vehicle produc growth tates used to forecast QM elec sales.

 REOMN.H.H. Environmental Projects Branch 2. 78/10/18. 3pp. 94392: 260
- 7B1109001B Responds to 7B1011 NRC request for add1 info re 2 items of noncompliance noted in 7B0B17 NRC ltr. Encl 7B1020 ltr from Bechtel to CPC discusses document control stamping & removal of void drawings from files. HOWELL, S. H. Consumers Power Co. 78/10/20. 3pp. 94398:035.
- 7810270199 Response to 781004 FDIA request for documents re completion dates for subj facil & detailed plant-specific analysis.
 Forwards requested documents. W/encl list of documents.
 FELTUN.J. M. Division of Rules and Records. 78/10/23. QPP. 74054: 30B.
- 7810270201 FOIA request for documents re estimated constr completion dates for subj facil & "detailed plant-spoific analysis"of DOW-W. Public Interest Research Group. 78/10/04. ip. 94056:310.
- 7810310293 Approves request for withholding, section 4.C of the Gen Agreement between Dow Chem & util re-price of energy sold to util under agreement. Price & cost of producing energy is held to be confridential info by NRC.
 REGAN.W.H. Environmental Projects Brench 2. 78/10/23. 3pp.
- 78:1070332 Bummary of 780913 Meeting at Buthesda, MD on info requested by Auxiliary Sys Branch re main steem & process steam piping-reactor coolant pump cooling & fuel cask drop. HOODO D.H. Light Water Reactors Branch 4. 78/10/23. 4pp. 94039:358.
- 78:11:3002: Bummary of 7809:4 Meeting w/util, Bechtel Corp & B&W in Betheads MD re separation criteria & administrative procedures for installation of Class IE belonce of plant equipment & circuits identified in PBAR Amend 32. HOGD.D. Light Water Reactors Branch 4. 78/10/23. App. 94075:313.
- 7810310364 Concludes that separation criteria for NBBS & Class IE balance-of-plant aquipment to non-Class IE circuits are par IEEE Btd 384-1974 & Reg Ouids 1.75 & acceptable. VARGA. S.A. Light Mater Reactors Branch 4. 78/10/24. 3pp. 94093:106.
- 78:10:0092 Ack receipt of 780929 interim rept re settlement of Diesel Generator Found & Bldg Finel rept will be reviewed upon receips. HEISHMAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/10/24. lp. 94381:315.

- 78:10:0000 Responds to 780926 itr requesting NRC decision r potential release of section 4.C of contract between Dow Chem Co & Consumer Pur Co.NRC finds section 4.C matl confidential & proprietary, Request is denied.
 FELTON, J. M. Division of Rules and Records. 78/10/26. 94290: 240.
- --7811010010 FDIA request for info re correspondence involvement bow Chem & Consumer Pur Co. FREEDKIN. B. Public Interest Research Group 78/09/26.

94290: 241.

- --7811010013 FOIA request for section 4. C specifying rates process steam supplied to Dow Chemical by util. FREEDRIN.S. Public Interest Research Group. 78/07/15.
- 7811130107 Notice of 781106 meeting w/subjutil on staff re for edd1 info re extension of constr completion dates for facils.
- HDOD, D. Light Water Reactors Branch 4. 78/10/30. 2pp. --7811150109 Requests addl info re constr permit extension
- on 770829. VARGA. B. A. Light Water Reactors Branch 4. 78/10/27.
 - 94113:309.
- 7811240185 Responds to 781025 ltr.City has 41 police office cars & no impact on crime rate from constr of subj facil. HARCEKID.8. Midland County. MI. 78/10/30. 1p. 94458: 7811240199 Forwards MI Supreme Court decision dtd 771024 &
- documentation re ennexation of sub; site to City of Midla RAE.J.J. Midland City, MI. 78/10/30. ap. 94458: 305. 7811240188 Responds to 781025 ltm.Park ecreage in City of Papprox 2700 acres & total park space exceeds standards. MOFFATT, D. N. Midland City, MI. 78/10/31. ip.
- 7811140059 Forwards request for addl info re main steam lie accident. Requires that power distribution distortions can by stuck rad be considered during both initial portion & later return-to-subcritical-power portion of analyses. VARAA.B A. Light Water Reactors Branch 4. 78/11/01. 5 94425:001.
 - 7811240166 Confirms 780912 info.41 law enforcement officer cars involved. Crime rate not affected by constr of subj Pacil. MCNUTT.J.R. Midland County, MI. 78/11/01. 1p. 94458:
 - 78:1090143 Responds to 78:011 request for add1 info re equiscology; hydrology, water use & quality, & traffic count da w/Agreement between Wolverine Pur Co & CPC, Discharge Per Appl by CPC, & other encl.
 HOHELL-8. H. Consumers Power Co. 78/11/03. 10:pp. 940---7811090149 "Btudy of a Non-Buoyant Plume: Presence of a B in an Undirectional Ambient Flow." Hydrothermal model were conducted to determine satisfactory design for co pond blowdown discharge.
 ROBERGE, J. C., NYGUJBT, R. O. Bechtel Power Corp. (subs. Corp.). 78/09/30. 98pp.
 - --7811090156 "Cooling Pond Oper Study". Preliminary Rept. Fa pend oper was simulated by use of makeup & blowdown sy control pond TDS contentrations. LIOU.C.P., APADAKIS.C.N. Sachtel Power Corp. (subs. o Corp.). 78/09/30. 55pp. 94043:015.
 - --7811090159 Tabular data on traffic counts for county roa
 - 7811240186 Confirms 780912 telephone conversation. City of treatment facils will be expended to treat total of 48 atllion gallone/day & be adequate until 1990.
 EWIND. W. C. Midland City, MI. 78/11/06. ip.

of proposed site, RAD, J. H. Michigan, State of, 78/10/13, 34pp.

- 7811130143 Notifies applicant of 781128 NRC-sponsored semi
- Radiological Effluent Tech Space for Nuc Pur Plants Entl W/Smminer Info Sheet(to be completed & returned by 78111 Proposed Agenda. KEPPLER, J. G. Region 3, Chicago, Office of the Director. App. 94007:333.
- 78:1240184 Responds to 78:025 ltr.Current school enrollmen Bldgs in school district can accommodate 2500 new studen in 1980. BAMER: R. Midland City: MI. 78/11/07. ip. 94458:301.

```
7811200159 Forwards for review by Beismic Qual Review Team(SQRT) listings of enc] portions of SQRT info & schedule for providing currently unavailable data & completed SQRT forms. HOWELL.S. H. Consumers Power Co. 78/11/15. 84pp. 02760:061.
7811200121 Forwards Crene Packing Co Bulletin 3472: "Beal Performance Test for Nuc Pur Plant Bafety Injection Sys". to support util's assumptions on HPI pump seal leakage as discussed at 780720 meeting w/NRC re ESF filtration issue.
HOWELL S. H. Consumers Power Co. 78/11/14. 83pp. 94820: 257.
7811240190 Responds to 781025 request for confirmation of telephoned
     data re Midland Hosp Assoc(personnel count. Not admissions).
Confirms info on file is provided by hosp. Occupancy rete is
     RATHBUN, K. J. Michigan, State of. 78/11/14. 2pp. 94458:310.
```

- 7811280127 Summary of 781106 meeting w/CPC in Bethesda.MD re-extension of const completion dates. Draft response to 781027 questions HOOD, D. Light Hater Reactors Branch 4. 78/11/14. 15pp.
- 7811280130 Notification of 781203-04 meetings w/CPC in Midland, MI resettlement of diesel generator bldg & other structures. Apenda encl. HOOD, D. Light Water Reactors Branch 4. 78/11/14. App.
- 7811280131 Summary of 780820 meeting on ateam line break methodology. cold shutdown position & sereguards pump room leakage H/encl list of attendess & applicant's responses to NRC questions. HODD.D. Light Hater Reactors Branch 4. 78/11/14. 27pp. 94013:053.
- 78:1270087 Porwards request for add1 info for review of app1 for oper lic for subj facil.Response req by 78:208:3 originals & 147 copies:41 are to be forwarded & 109 to be retained.
 REGAN.M.H. Environmental Projects Branch 2. 78/11/16. 5pp. 94260; 340.
- 7811280091 Forwards RevRi"Draft Rediological Effluent Tech Spec for PWR's"(NUREO-0472) & "Preparation of Radiological Effluent Tech Spec for Nuc Pwr Plants"(NUREO-0133). W/encl 7811270173 & 7811270180.

 VASBALLO,D. 8. Assistant Director for Light Hater Reactors, 78/11/16. 6pp. 02726:392. 7811300007 Porwards order extending completion on dates from 781201 & 791201 to 821001 & S11001 for Units 1 & Prespectively.

 VAROA.S.A. Light Hater Reactors Branch 4. 78/11/17. 3pp.
- 94067: 348 --7811300011 Order extending const completion dates from 781201 to 821001 to 811001 for Units 1 & R. respectively, Evaluation of request for extension of CPPR-81 & CPPR-82 encl. BOYD, R. S. Division of Project Hanagement. 76/11/17. 7pp. 94049: 344.
- --7811300019 States environ impact statement for extension of constr permit not warranted. All necessary info described in Finel Environ Statement-Constr Permit Stage. REGAN, W. H. Environmental Projects Brench 2, 78/11/17. 2pp. 94077: 023.
- ~-7811300023 EIA concluding no EI8 need be prepared for proposed action. * Division of Site Safety & Environmental Analysis. 78/11/17. 2pp. 94077: 025. 7812050074 Sefety evaluation supporting extension of Const Permits CPPR-81 & CPPR-82.
- HOOD, D. , VARQA, S. A. Light Water Reactors Branch 4. 78/11/17. Spp.
- ~-7812050097 Environ Impact Appraisal concluding that extension of subj facil Constr Parmits CPPR-B1 & CPPR-B2 will cause no major add1 environ impact, W/Negative Declaration. Division of Site Bafety & Environmental Analysis. 78/11/17.

7811270147 Forwards Amend 53 to CP & OL application, containing update

to general into portion.

~-7811270151 Amend 53 to CP & CL application re-basis for completion date extension. Unit 1 extension from 771201-781201 to 811001-821001 & Unit 2 extension from 781201-791201 to 801001-811001. Delay partially due to finances.

* Consumers Power Co. 78/11/21. 16pp. 94271:344. 7811270152 Forwards add1 capies of CPC responses to Suppl Requests for Add1 Info.Part2.originally transmitted to NRC by itr of 781109. M/enc1 AND:781140108. HOWELL.S.H. Consumers Fower Co. 78/11/21. 1p. 94232:355.

HOWELL. S. H. Consumers Power Co. 78/11/21. ip. 94271: 343.

mafaty grade equipment. HOOD D. Light Water Reactors Branch 4. 78/11/27. 4pp. 94085.05 7812050142 Forwards Cart of Svc for Appl for Constr Permit & Open Li BACON, J. L. Consumers Power Co. 78/11/29. 2pp. 94334: 350.

7812070280 Notification of 781211 meeting w/CPC. Bechtel & 8&W in Bethesda, MD to appeal NRC position that facilities be capable of obtaining cold shutdown conditions using only

- 7812000213 Forwards Certificate of Bvc for Amend 54 to CP to CL application containing Revision 15 to FBAR BACCN.J.L. Consumers Power Co. 78/11/30. 1p. 94318:345.
- 78:2120002 Forwards supplemental second round question from Reactor Physics Section re-criticality of proposed high density storage sys.tEncl 80081305491
 TEDEBCO.R.L. Division of Systems Safety. 78/12/01. ip. 94274:20
- 7812120068 Responds to 781011 NRC ltr.addl info re Aquatic Ecology & Hydrology Nater Use & Guelity & Archaeology Forwards rev of State Discharge Permit Appl.rev of Appl for Permit to Discharge Nater & Archaeological Rept HOWELLIS, H. Consumers Power Co. 78/12/05 283pp. 94278: 104. 7812280118 Emphasizes importance of submitting accurate & complete in to NRC by licensees & applicants. Info submitted must be
- substantiated by data & calculations.Licenses must notify NRC of any inaccuracies or enforcement action will result. DAVIS-J. 0. Office of Inspection & Enforcement, Office of the Director. 78/12/06. 2pp. 94310:213.
- 7812120104 Forwards Amend 55 to application for CP & DL & Revision 4 to Environ Rept, OL stage.
 HOHELLIS.H. Consumers Power Co. 78/12/07. 1p. 94275:029. --7812120111 Application for CP & OL. W/Revision 4 of Environ Rept. HOMELL. 8. N. Consumers Power Co. 78/12/07. 194pp. 94275: 030.
 - 7812180391 Responds to request for withholding info submitted on 7800 & 0629 (ref (OCFR2, 790), Forwards tables listing criteria used by B&W to determine whether submitted matls are proprietary & proprietary claim of matl submitted.
 VARQA(8, A. Light Water Reactors Branch 4, 78/12/07, 7pp. 94.37-24. 94357: 266.
 - 7812260188 Discusses questions raised during visit re diesel generate settlement problem.
 COOME.T.C. Consumers Power Co. 78/12/07. 2pp. 94159:156.
- 7812210294 Notification of 781220 meeting w/CPC & 8&W in Setheeds.MD to discuss single failure proof crane for spent fuel, details of full-scale modeling tests planned for containment sump & steam line break analysis w/stuck control rod assembly.

 H000.D. Light Water Reactors Branch 4. 78/12/11. App. 94167:32 C. Utility Environmental Report (ER), amends & correspondence
- - 7811070149 Responds to 781011 NRC 1tr re review of subi facil Enviro Rept-Oper Lic Stage. Answers questions re archeological investigation of Tittebawassee River floodplain, mitigation or avoidance of archeological sites, ecological survey. HOWELL-8.H. Consumers Power Co. 78/10/20, 2pp. 94044:096.
 - ~-7811170298 Amend 52 to Environ Rept to correction of errors & required add into as requested by WH Regen's 780522.781011. & 781018 1trs.
 HOHELL, B. H. Consumers Power Co. 78/11/10, 20259. 94045:277.
- 7811280282 Forwards affidavit distributing copies of Amend#52 to CPC Appl for Constr Permit Cert of Svc enci. 8AN.J. Consumers Power Co. 78/11/20. 4pp. 94395:288,
- 7812190093 Forwards affidavit for Amend 55 Rev4 to Environ Rept app1 for reactor constr permit & open lic on 781211.

 8ACON.J.L. Consumers Pawer Co. 78/12/12, 4pp. 94381:036.

 - - D. NRC Draft/Final Environmental Statements, suppls & correspondence 7812050222 Ack cooperation in providing info for EIS for subj facile Requests written confirmation of data provided re staffing.

781:170294 Forwards Amend 52 to Environ Rept re corrections of error requests for add1 info re original Amend. HOMELL.B.H. Consumers Power Co. 78/11/10. 1p. 94045:274.

admissions & occupancy rate of Midland Hospital.
HONO.S.W. Argonne National Laboratory. 78/10/25. ip. 94201:146

- 7812050225 Act cooperation in providing info for EIS for subj facils. Requests written confirmation of data provided re planned expansion of water capacity of City of Hidland HDNO.S W. Argone National Laboratory. 78/10/25
- 7812050227 Act cooperation in providing info for EIS for subj facils Requests written confirmation of data provided ne acreage of partiand in the City of Midland & that the total space devoted to parts & recreation exceeds gen standards MONO, S.W. Argume National Laboratory 78/10/25. 1p. 94201-200
- 7812050232 Act comperation in providing info for EIS for subj facils. Requests written confirmation of data provided re % of law enforcement officials 5 patrol cars in Hidland County. & that constr of facils has not affected local crime rate HONO, S N Argonne National Leboratory. 78/10/25 ip 94202:023.
- 7812030239 Act cooperation in providing info for EIS for subj facils. Reausets written confirmation offsta provided rem of police & patrol cars in City of Midland. & that constr of facils does not impact on local crime rate HONO.5 H Argonne National Laboratory. 78/10/25. Ip. 94202:045.
- 7812050244 Act cooperation in providing info for EIS for subj facils.
 Requests written confirmation of data provided re current
 annoliment & unused capacity of the Bullock Creek School

HDNO.8 W. Argonne National Laboratory 78/10/25, Ip. 94202-067.

- 7812050250 Act cooperation in providing info for EIS for subj facils.
 Requests written confirmation of data provided me current annualment & unused capacity of the Hidland School District.
 HDNQ.S.W. Argonne National Laboratory 78/10/25. 1p. 94202:114.
- 7812050255 Act cooperation in providing info for EIS for subj facils. Requests written confirmation of data provided reconfirmation by State Supreme Court of annexation HDNO.S.W. Argonne National Laboratory. 78/10/25 Ip. 94202:127.
- Q. Adjudicatory correspondence
- 7810110309 Answer of Consumers Pur Co to Petition for Leave to Intervene of M.H Marshall on behalf of the Mapleton Intervenors. Intervention should be denied for untimeliness, & participation would not contribute to record. HILLER.M I. OIBBS.M.E. Ishem, Lincoln & Beale. 78/09/28. ISpp. 94061.016
- 7810250152 Notice of withdrawal from proteeding as of 780929. Certificate of Bvc encl. 9ROSSMAN.H.J. Hearings Division. 78/09/29. 3pp.
- 78:0140-027 NRC steff ensuer to petition submitted 78:09:09 by W Marshell requesting leave to intervene on behalf of Magelton interveners NRC staff does not oppose setition at this time. OLHSTEAD.W.J. Office of the Executive Legal Director. 78/10/03. 7pp. 94421 032.
- 7811020381 Notice of Hithdrewal of Appearance accompanied by Notice of Appearance for David Bonderman, replacing Cohen & Cert of Svc.
 COMEN.R.C. Annold & Porter. 78/10/06. 3pp. 94384:282.
- 7810240157 Notice of hearing on issuance of DL license BER, FEB, DEB, ACRO rept on DL application. Tech Specs & intervention petitions, related papers & Board 780814 memorendum & order may be inspected at NRC PDR. Certificate of Bvc encl.

 SMITH, I W Atomic Bafety and Licensing Board Panel 78/10/12. 4pp.
- 7810250188 Hemorendum & order granting WH Marshell temporary status as intervenor pending Board final determination on adequacy of intervention getition. Mapleton Intervenors may file arended patition demonstrating interest in proceeding.

 BNITH: J. M. Atomic Sefety and Licensing Board Panel. 78/10/12. 6pp. 94379:241.
- 7810300311 Repts predicted util figures for long-term electricity demand for 1978-88 per latest short-term forecast.
 MILLER,M. I. Isham, Lincoln & Seale. 78/10/18 2pp. 94253:317.
- 7811010006 Forwards another copy of the 8d Namo & Order of 780814 & Notice of Hearing on issuance of Facil Oper Lic of 781012 In response to 781018 Mailgram Informs that requests for data should go to staff, not 80. W/o encl.

 8MIM-I.M. Atomic Befety and Licensing Appeal Panel. 78/10/23. 26s. 74290.237.

1

- 7812050132 Order referencing re-annexation of subjects to Ci Midland, MI forwarded as encl to ANO. 7811240199. HARRISON, M. O. Michigan, State of 78/10/30. 43pp. 0179: 7811100146 Forwards contentions that MI law prevents lice the a nuisance. 111sgal radiet spills are occurring spent fuel re-
 - /Billivi46 Forwards contentions that MI law prevents lic that a nuisence illegal radiet spills are occurring spent fuel restorage has created hazards icing & fogging nuisence is occurring & present tech fails to achiev zero emission. MARBHALL.W.H. Mapleton Intervenors. 78/10/31. ip. 9404
 - 78:1130:89 In response to motion of 78:029 from W Marshall Trescheduling of prehearing conference, ordered that 8 Gadles will represent Marshall & Mapleton Intervenors at the
 - special prehearing conference.

 SHITH, I.W. Atomic Safety and Licensing Board Panel. 78/103553:330.
 - --7811130192 Request by intervenor W Marshall for continuent prehearing conference on 781110 due to his unavailabilit that day Request for resched made on his own behalf & on behalf of Maplaton Intervenors.
 MASHALLIN H. Affiliation Unknown. 78/10/29. 1p. 035
 - 781:150080 "Brisf of Consumers Pur Co in Support of its Posl
 HH Mershall's Petition to Intervene is Barred by Ras
 Judicata Urges patition be denied Cort of Svc & supporting
 matl enclosed.
 MILLER, H I., GIBBS, M.E. Consumers Power Co. 78/10/31. 9
 - 78:12:10040 Submits add: contentions in support of 780906 con objecting to subj facil re illegal charges & spills, geological conditions & storage of spent fuel rods.

 Certificate of Svc encl.
 - MARCHALL, W.H. Mapleton Intervenors. 78/10/31. 5pp. 941 811150039 Requests that CPC file brief supporting util post
 - 7811150039 Requests that CPC file brief supporting util post NH Marshall patition to intervene be barred by 781031 res judicets. Certificate of Svc encl.
 NARBHALL, N. N. Mapleton Intervenors. 78/11/02. 1p. 9411
 - 7811210036 Berves 8J Gadler w/"Brief of Consumers Pur Co in its position that Marshell's petition to intervene is barr by res jucidata." Q1888.M E. Isham. Lincoln & Beals. 78/11/02. 1p. 03587 7811210493 Contention of intervenor M Sinclair. Asserts that
 - 7811210493 Contention of intervenor M Binclair. Asserts that is responsible for assuring compliance w/Atomic Energy Act of 1934. Also claims that NRC has not implemented an effective direct inapec prog. Cert of Bvc enti. BINCLAIR, M. P. Affiliation Unknown. 78/11/03. 40pp. 03
 - 78:1150252 Only issue remaining for ABLB to consider re-subcharge re-CPC's conduct. Bd will also address issue of environ effects of redon. Bd will not consider CPC's allego history of QA-OC violations & lack of financial quals. CHEMS J. Office of the Secretary of the Commission. 78 7pp. 94273:086.
 - 7811220215 Supple 781018 notice of hearing that special preconference per 100FR2.751(s) would begin on 781115. Meeting will not be held on 781214 in Midland. MI. SMITH. I. M. Atomic Safety and Licensing Board Panel. 78/ 94071:282.
 - 7811300369 Hemorandum & order postponing special prehearing previously scheduled for 781115, until 781214 at same hr & location.
 - SMITH.I.W. Atomic Bafety and Licensing Board Panel. 78/ 94136:281.
 - 7812060126 Requests change of location for 781214-15 prehea conference from Midland MI to Chicago IL. CHERRY,M.M. Cherry, M. M./Cherry, Flynn & Kanter, 78/11 94382: 025.
 - --7812060172 Requests comments on NRC 781106 memorandum & or consideration of operating & const matters.
 CHERRY, M. M. Cherry, M. M. /Cherry, Flynn & Kanter. 78/94382;027.
 - 7812080005 Forwards 780929 10CFR50. 55(e) rept from CPC & Kep mand to Thornburg re-proposed contentions concerning settlement of diesel generator bldg foundations pending before the ASLB. he ASLB. CLMSTEAD, M.J. Office of the Executive Legal Director. 712pp. 94103:315.

- 78:1300356 Objects to M Cherry 78:113 request to change location of licensing hearings to Chicago Poor health would prevent attendance if hearing was not held in Midland, NI. Certificate of Byc enc1 MARBHALL, W. H. Affiliation Unknown. 78/11/17. 1p. 94116:238.
- 7812050257 Informs that itr transmitting radon record should have been atamped "Served 781117." Docksting & Bervices Branch. 78/11/21. 1p. 94202.132
- 7812010257 Memorandum & order confirming date of special prehearing conference. Location of future sessions will be discussed at conference Board will begin 781214 by dealing w/problems involving lawyers. Limited appearance statements deferred. BHITH. I. M. Atomic Bafety and Licensing Board Panel. 78/11/22. 2pp. 74417:123.
- 7812140087 Brief submitted by CPC in response to ASLB Order of 781113 CPC asserts that 27 of petitioner to intervene M Binclair's suppl contentions are inadmissible & that petition to intervene of H Marshall be denied. MILLER, M. I. , GIBBS, M. E. Isham, Lincoln & Beale. 78/11/28. 49pp. 94128:242
- 7812140362 Answer of CPC to Motion by M Cherry representing all intervenors other than Dow Chem Co.for joint consideration of oper & constr matters CPC asserts that consolidation is neither req nor justified Cert of Syc encl.
 MILLER,M.I., 01888,M.E. Isham, Lincoln & Deale, 78/11/28. 12pp. 03557: 251.
- 7812260065 Forwards "Participation in the Instant Proc." W/Cert of Svc. TAYLDR.G.T. Michigan, State of. 78/11/28, 1p. 94027:133.
- --7812260067 "Participation of the State of MI in the Instant Proc." Responds to Bd Order 781117 requiring MI to advise if it intends to participate. Scope & subj matter of intended participation are outlined. TAYLOR, O. T. Michigan, State of. 78/11/28. 2pp. 94027:134.
- 7819260298 NRC Staff's Response to contentions of petitioners to intervene Hapleton Intervenors. Steff asserts that contentions#1.3.4.6 & 7 are vague or w/out basis in fect. Contentions#2 & 5 may be proper if rephresed. H/Cert of Svc. OLMSTEAD. H. J. Office of the Esecutive Legal Director. 78/i1/28 OLMSTEAD, W. J.

50p. 94160:052.

- --7812260303 NRC Staff's response to Contentions of petitoner to intervene M Sinclair. Staff objects to contentions#1-21,23, 26,35,37-41,45,46,448,458,478-34,No objection is made to contentions#22,24,27-34,42-44,47,48 & 46a. OLMSTEAD, W. J. Office of the Executive Legal Director 78/11/28. 10pp. 94160:055.
- 7812140223 Responds to 781120 request for edvance notification of meetings between NRC & consumers re subjects. Respondent has aiready been sent such notices, & recent Fed Register Notice affirms open meeting policy which holds for subjects. OLMSTEAD, H. J. Office of the Executive Legal Director. 78/11/29. 1p. 94204:340.
- 7812180383 Corrects factual error in 781128 Consumers Pur Co brief.
 Steam rate may or may not be subj to jurisdiction of MI Pub Svc Comm. OIBBS.M.E. Isham, Lincoln & Beals. 78/11/29. Lp. 94357:319.
- 78:2280325 Forwards documents re settlement of Diesel Generator Bidg foundations at subj facil.

 QLMBTEAD, W. J. Office of the Executive Legal Director. 78/18/07. 14pp. 940B2: 141.
- --7812280332 Forwards 781120 ltr from M Cherry w/poseible ellegations against resident NRC inspector at subj facil. DANIS.J.Q. Dffice of Inspection & Enforcement, Office of the Director. 78/12/05. ip. 94082:360.
- --7812280334 Forwards 1tr from M Cherry re tub; constr proj. Response is being prepared. KEPPLER, J. G. Re ip. 03555:152. Region 3, Chicago, Office of the Director. 78/11/24.
- --7812280340 Expresses concern that NRC is attempting to minimize problem of diesel generator bldg settlement at subj facil. Suggests NRC resident inspector may be coopted by util. Requests info & permission to attend next inspec.

 CHERRY, M. M. Cherry, M. M. /Cherry, Flynn & Kenter. 78/11/20. 3pp. 03555: 157.

- --7812280343 Transfers lead responsibility for problem of signific settlement of diesel generator bldg to NRR. W/encl repts on deficiency. VABSALLD, D. B. Assistant Director for Light Water Reactors 78/11/17. 11pp. 94082.204.
- 7812270132 NRC Staff's response to NRC Mero & Order of 781106 re r issue. Asserts that ABLB has no need for add1 written evidence me madem question. Notice of appearance for BM Bordenick & Cent of Syc encl.
 BDROENICK, B.M. Office of the Executive Legal Director. 78/12/0
- 10pp. 94161:086. 7812280350 Memo of CPC re environ effects of radon per NRC Order o
- 781106 Asserts that Parkins decision is supported by record of that proc & that radon emissions do not critically effect cost-benefit belance Wench documentation & Cert of Bvc.
 MILLER.M. I., 91888, M. E. Isham, Lincoln & Beale 78/12/08, 19p 94082: 217

H. Deneral correspondence

- 7811010014 Requests OL documents: 50-329 & 50-33 to be sent to N Hatlie P.O. Bor 103: 3609 Shoreline Dr., Nararve, Mn 55392, also to place Hatlie on circulatory list. MARSHALL, W. H. Hapleton Intervenors. 78/10/18 ip. 94290 209.
- 7812280198 Responds to 781120 ltr. Forwards info re resident inspec
- being co-opted by Midland personnel NRC has initiated an investigation into estatement of dissel bidg at facil. KEPPLER, J. G. Region 3. Chicago. Office of the Director. KEPPLER, J. Q. Regi 125pp. 94373: 090. 78/12/
- K. Utility Final Safety Analysis Report (FSAR) & amende
- 7810230192 Forwards Amend 51 to CP & OL applications, consisting of Revision 14 to FSAR. HDWELL, S. H. Consumers Power Co. 78/10/17. ip.
- --7810230196 Revision 14 to FBAR, Vols 1&2.
 * Consumers Power Co. 78/10/17. 1153pp.
- 7810270168 Forwards Cent of Byc for copies of Amend#51(Rev 14 to F Safety Analysis Rept)to appl for constr permits & oper lics. BACCN.J.L. Consumers Power Co. 78/10/24. Rpp. 94056:R66
- 7812010251 Forwards Amend 54 to CP & GL application.containing Rev 15 to FBAR. HOHELL, S. H. Consumers Power Co. 78/11/27. 18pp. 94390:159.
- --7812010252 Rev 15 to the FBAR vols 1 & 2:responses to requests P informer re orifice rod assemblies & high density funl racks
- 7812120154 Forwards advance copy of util response to NRC Request 4 "GA During Operations Phase," PSAR Subsection 17.2 re personnel training steff changes cleaning of fluid sys & GA audit.Response to be submitted w/Revision 16 of FBAR. HOMELL.B.H. Consumers Power Co. 78/12/08. 11pp. 94276:286
- . . 7812180246 Intervenors & applicant CPC mept that prospect for settlement of issues contested in proceedings re subj facils is excellent. An understanding help been reached in all but 2 areas Cart of Byc encl. ROBB.W.W. WATSON.K.B. Wald, Harkrader & Ross. JABLON.R.A Sp & McDiarmid. 78/12/06. App. 94059:333
- 9. Inspection reports, IE Bulletins & correspondence

M. Antitrust correspondence

- 78:0270024 Forwards I & S Initial Rept on Response to Bulletin 77-05/05A re use of Elec Connectors. Appropriate Bds should be notified where there is a question re use of connectors in safety sys. Memo dtd 780207 also enci.
 TEGEBCO, R. L. Assistant Director for Plant Systems 78/02/08.
- --7B10270246 Forwards "Status of Responses from Licensees of Plant Constructo Bulletine 77-05 & 05A". MOSELEY, N.C. Division of Reactor Construction Inspection. 78/02/07. 3pp.
- 78::130340 Forwards IE Inspec Repts#50~329/78-09 & #50-330/78-09 780827-31 & Notice of Violetion.

- --7811130343 Notice of Violation from inspec on 780829-31 # Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/09/21. 1p. 94007:311.
- --7811130350 IE Inapec Repts#30-329/78-09 & #50-330/78-09 on 780829-31 during which I item of noncompliance was noted: failure to follow procedure in welding root pass.

 LEF,E.W., DANIELSON.D.H. Region 3. Chicago, Office of the Director. 78/09/21. 3pp. 94007:312.
- 7810140197 "Preservice & First 10-Yr Interval Insp Plan for NDE & Bus Pressure Tysking at CPC Midland Units 1 & 2 " Prepared For util. BLAGER.H. H., BIRKLE.A.J., MAYNARD.C.J. Bechtel Corp. 78/09/29. 247pp.
- 7810160196 Forwards "Preservice & First 30-Yr Interval Insp Plan For NDE & Bus Pressure Testing at CPC Midland Units 1 & 2." Data reported in Section 3 of plan is prailininary & subj to Change as const progresses. Plan basis of 781025 meeting HOMELLS, H. Consumers Power Co. 78/10/05. 2pp. 94007:150.
- 7811140048 Forwards IE Inspec Repts#50-329/78-10 & #50-330/78-10 on 780913-15 during which no items of noncompliance ware noted. HEISHMAY,R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/10/10. 2pp. 94420.343.
- --7811140054 IE Inspec Repte#50-329/78-10 & #50-330/78-10 on 780913-15 during which no items of noncompliance were noted. Major areas inspected included:inetallation of safety-related hengars & restraints.

 YIN.I.T. Region 3. Chicago, Office of the Director.
 DANIELBON, D.H. Region 3. Chicago, Reactor Construction & Engineering Support Brench. 78/10/10. App. 94420:345.
- 7810200211 Act receipt of 780918 ltm informing NRC of steps taken to correct item of noncompliance identified in IE Insp Repts 50-329/78-07 t 50-330/78-07. Add1 info is requested. KEPPLER. J. O. Ragion 3. Chicago, Office of the Director. 78/10/11. 2pp. 94367:044.
- 7811070336 Responds to 780921 NRC itr re moncompliance noted in Inspec Repts#50-389/78-09 & 50-330/78-09. Corrective actions:rev of Bechtel Walding Procedure Spec & Bechtel Project Quality Control Instruction#7280/W-1.00. HGMELLIS.H. Consumers Power Co. 78/10/23. 3pp. 94043:080.
- 7812140021 Forwards IE Inspec Repts#50-329/78-11 & 50-330/78-11 on 760926-28 during which no items of noncompliance were nated. HEISHMAN.R.F. Region 3. Chicago, Defice of the Director. 78/10/27. 2pp. 94119:347.
- --7812140028 IE Inspec ReptsH50-329/78-11 & H50-330/78-11 on 780926-28 during which no items of noncompliance were noted Major areas inspected incl: Bebook & Hilcox Constr Co nondestructive examination prog procedures & personnel cert. HARD. H. D., DANIELBON, D. H. Region 3. Chicago, Office of the Director. 78/10/26. 7pp.
- 78i1280124 Responds to 780304 NRC ltr re violations noted in Inspec Repts50-329/78-03 & \$50-330/78-03. Corrective actions:weld spec rev.weld voltage range monitoring procedure prepared: disagrees on 15% voltage range limitation. HOWELL.S. H., Consumers Power Co. 78/10/31. 2pp. 94013:023.
- 7812060064 Forwards IE Inspec Repts#50-329/78-13 & #50-330/78-13 on 780724-28.31.0801-31.0901-08 & Notice of Violation. HEID-MAN.R.F. Region 3, Chicaga Reactor Construction & Engineering Support Branch. 78/11/03. 2pp. 94232:254.
- --7812060067 Natice of Violation from inspec on 780724-0928.

 * Region 3. Chicago, Reactor Construction & Engineering Support Branch, 78/11/02. 29p. 9423:236.
- --7812060070 IE Inspec Repts#80-329/78-13 & #50-330/78-13 on 780724-0908 during which 2 items of noncompliance were noted:welds with unequal outside diameters were accepted & Sefety Related Control Rod Drive Primary Breakers were not well protected. COOK.R.J. HAYNES.D.H. Region 3. Chicago. Diffice of the Director. 78/11/03. App. 94233:238.
- 7811190057 Forwards IE Circular 78-18.

 KEPPLER, J. O. Region 3. Chicago: Défice of the Director. 78/11/06.
 1p. 9418:192.
- 7811200041 Ack receipt of 781020 ltr informing NRC of steps taken to correct violations noted during inspec. HEIGHMAN,R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/11/08. jp. 94215:323.

- 7812140130 Forwards IE Inspec Repts#50-329/78-14 & 50-330/78-14 on 780910-29 during which no items of noncompliance were noted. HEIGHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Brench. 78/11/08. 2pp. 94128:334.
- --7812140139 IE Inspec ReptsW50~329/78-14 & 50-330/78-14 on 780910-29 during which no items of noncompliance were noted. Major areas inspected inclieramination of gen sits condition & steam generator & reactor vessel hold down bolting. CDDK.R.J., HAYEB.D.W. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 78/11/06. App. 94128:336.
- 7811220006 Ack receipt of 781023 ltr informing NRC of steps taken to correct violations noted in 780921 ltr. Corrective actions will be reviewed during a future inspec. HEIGHMAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Bupport Branch. 78/11/15. 1p. 94308:246.
- 7812190168 Forwards IE Inspec Repts#50-329/78-12.50-330/78-12 on 781024-27 during which no items of noncompliance were noted.

 HEIS-MAN.R.F. Region 3: Chicago: Reactor Construction & Engineering Bupport Brench. 78/11/17. 2pp. 94340:162.
- --7812190160 IE Inspec Repts#30-329/78-12 & 50-390/78-12 on 781024-27 during which no items of noncompliance were noted. Major areas inspected incl: 10CFR30.55(s) rept concerning settlement of diesel generator foundation & bldg. GALLAMER, E. J., SPESBARD.R.L. Region 3, Chicago, Office of the Director. 78/11/14. 11pp. 94340:169.
- 7812050102 Ack receipt of 781031 ltr informing NRC of steps taken to correct violations noted in 780504 8 780913 ltrs. Re issue(b) NRC requests that sampling measurement sys provide assurance that all welding machines are covered by amperage & voltage. HEISHMAN.R.F. Region 9. Chicago. Reactor Construction & Engineering Support Branch. 78/11/22. 1p. 94935:287.
- 7812050333 Forwards IE Bulletin978-12A, suppl to IE Bulletin 78-12. H/encl ANO:7811300055. KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/11/24. jp. 74409:001.
- 7812080249 Informs NRC of ongoing preparation of response to IE Bulletin 78-12, "A Typical Weld Matl in Reactor Pressure Vessel Welds" for subj fact] & states that written response will be forwarded by 781215.
 HOWELL-B.H. Consumers Power Co. 78/11/28. 1p. 94137:191.
- 7812140080 Act receipt of IE Bulletine78-12A re atypical wald mat1 in pressure vessels. Response will be consistent w/extended sched of IE Bulletine78-12A.

 HOMELLS.H. Consumers Power Co. 78/12/05. ip. 94128:226.
- 7812390015 Forwards IE Bullstin 78-14.
 KEPPLER, J. O. Region 3. Chicago. Office of the Director. 78/12/19.
 10. 04911:001.
- R. Periodic operating reports & related correspondence
- 7810270142 Forwards Monthly Nonconformance rept for Bept 1978. HOWELL.8.H. Consumers fower Co. 78/10/25. 1g. 94060:030.
- S. Reportable occurrences, LERS & related correspondence
- 7810180095 Interim deficiency rept re reactor bldg spray piping supports. Bechtel Associates Prof Corp rept of statue of corrective action & investigation encl. Further rept to be submitted by 781117.

 HOHELLS.H. Consumers Power Co. 78/10/13. 4pp. 94401:088.
- 7811010401 Ack receipt of 780929 final deficiency mept me containment bldg personnal airlocks Review will be completed during future inspa.

 HEIGHMAN, R. F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/10/24. ip. 94388:323.
- 7811010115 Ack receipt of 780929 interim rept re small break analysis. Final rept will be reviewed upon receipt. HEIBHMAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/10/25. ip. 94378:355.
- 7811070222 Act receipt of 781013 interim mept to reactor bldg spray piping supports.
 HEISHMAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/10/30. ip. 94039:141.

- 7811170212 Interim deficiency rept re settlement of diesel generator foundations & bldg. Provides status of actions to be taken.
 Review meeting tentatively planned for last two wks in Nov.
 Further rept to be submitted by 781229.
 MDWELL-8. M. Consumers Power Co. 78/11/07. 7pp 94136:114.
- 7811170222 Interim deficiency rept re reactor bldg spray piping supports. Provides status of analysis being conducted to resolve question of adequacy of supports per ABME Section III Code allowable stress requirements. Final rept by 781219. HOMBLL.S. H. Consumers Power Co. 78/11/10. 4pp. 74136.213.
- 7811220176 Interim deficiency rept re Class IE station battery. Exide Industrial Battery Div asked to provide additional info describing condition-réaliure mode & analysis of will condition was reportable. Related correspondence HOHELLS. H. Consumers Power Co. 78/11/17. 200. 94623:267.
- --7811220178 Reports that add1 isolation ber must be added to Class IE battery racks sent to subj facils in order to isolate horizontal momentum during setwic events Design is being worked out & will be ready in 60 days for retrofit. MCMANUS.C.K. ESB, Inc. 78/10/11. Ip. 94623:269.
- 7811290293 Ack receipt of 781117 interim rept pursuant to 10CFR30. 35(a) re settlement of diesel generator foundations & bldg. HEIGHMAN,R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/11/22. 1p. 94239:246.
- 7812010155 Ack receipt of 781110 interim rept pursuant to 10CFR50.55(e) re reactor building apray piping supports.
 HEIBMAN.R.F. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 78/11/22, jp. 74418:125.
- 7812040287 Ack receipt of 781110 interim mept me reactor bldg spray piping aupports.
 HEISHMAN,R.F. Region 3. Chicago, Office of the Director. 78/11/22.
- 7812140366 Ack receipt of 781117 interim deficiency rept re class IE station battery racks. HEISHMAN.R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/11/22. ip. 03557: 288.
- 7812040218 Interim deficiency rept to component quelification test documentation re-review Rept is being generated by Sechtel documenting status of re-review & results on individual meti requisition basis for all G-components requiring testing. HONELL, B. H. Consumers Power Co. 78/11/28. 2pp. 94445:359.
- 7812270184 Interim deficiency rept re reactor bldg spare piping supports. Bechtel Associates Prof Corp rept on status of analysis being conducted to resolve question of adequacy of reactor bldg spray piping supports per ABME requirements. HOWELL.8.H. Consumers Power Co. 78/12/15. 3pp. 94017:361.
- 7812270254 Forwards nonconformance rept for Nov 1978. (Encl 80081806851 HOWELL-8. H. Consumers Power Co. 78/12/20. 2pp. 94016:082.
- 7812290146 Interim deficiently rept re settlement of diesel generator foundations & bldg. Use of preload to densify existing fill matl in place selected as corrective action. Bectel rept detailing tasks to be sent by Jan. Related correspondence. HOWELL S. H. Consumers Power Co. 78/12/21. 2pp. 94190:281.
- DOCKET 80-330 MIDLAND PLANT, UNIT 2
- A. Application/construction stage documents & correspondence
- 7811090143 Responds to 781011 request for add1 info re equatic ecology, hydrology, water use & quality, & traffic count data w/Agreement between Wolverine Pur Co & CPC, Discharge Permit Appl by CPC, & other encl.

 HDMELL, B. H. Consumers Power Co. 78/11/03. 101pp. 94042:357.
- --7811090149 "Btudy of a Non-Buoyant Plume: Presence of a Buoyant Plume in an Undirectional Ambient Flow." Hydrothermal model tests were conducted to determine satisfactory design for cooling pond blowdown discharge.
 ROBERGE. J. C., NYGUIST. R. G. Bechtel Power Corp. (subs. of Bechtel Corp.), 78/09/30. 98pp.
- --7811090186 "Cooling Pond Oper Study", Preliminary Rept. Facil cooling pond oper was simulated by use of makeup & blowdown sys to control pond TDS concentrations.
 LIOU,C.P., APADAKIS.C.N. Bechtel Power Corp. (subs. of Bechtel Corp.). 78/09/30. 55pp. 94043:015.

- --78:1090159 Tabular data on traffic counts for county roads in vicin of βτοροsad site.
 - RAAD.J.H. Michigan. State of. 78/10/13. 34pp.
- 7812120068 Responds to 781011 NRC ltr.eddl info re Aquetic Ecology & Mydrology, Mater Use & Guelity & Archaeology, Forwards rev of Btate Discharge Permit Appl.rev of Appl for Permit to Discharge Mater & Archaeological Rept. HOMELLS H. Consumers Power Co. 78/12/05. 283pp. 94278:104.
- 7812120104 Forwards Amend 85 to application for CP & DL & Revision 4 to Environ Rept/OL stage.
 HOWELL/S.H. Consumara Power Co. 78/12/07. ip. 94275:029.
- --7812120111 Application for CP & DL. H/Revision A of Environ Rest. HOMELL.8. H Consumers Power Co. 78/12/07. 194pp. 94275:030
- 7810310061 Forwards preliminary chart on results of land use survey completed last year re building & housing trands in Midland County 1769-1977.

 * Midland County, MI. 78/04/10. 3pp. 94093:179.
- 7810140004 Notice of time & agenda change for meeting on 781025 to discuss Augmented insvc inspec & testing of pumps & valves.

 HOOD-D. Light Water Reactors Branch 4. 78/09/25. 5pp. 94329:097.
- 7810120072 Forwards B&W rept "Analysis of Bearing Failure in LMSQ 9000 HP Vertical Pump Motor Resulting From Dil Cooler Failure" prepared for CPC. Rept available in CF only. DUWELL-8. Consumers Power Co. 78/10/05. 1p. 94470:345.
- --7810120077 "Analysis of Bearing Failure in LMt0 9000HP Vertical Pump Motor Resulting from Oil Cooler Failure"prepared by 86W for CPC. & forwarded to NRC. Determines Kingsbury thrust bearing to be critical component in event of oil cooler failure. # Bebcock & Wilcox Co. 77/10/10. 107pp.
- 7810130231 Forwards archaeological site survey for Midland County.HI to be added to minutes of Baginaw meeting of 780906.

 BRUNETT:F. V. Baginaw Archaeological Commission. 78/10/05. 1ipp.
- 7810200128 Requests add1 info as result of site visit to subj facil in order to review environ factors. Response should be submitted by 781025. Response should be suppl to Environ Rept.

 REGAN. H. H. Environmental Projects Branch 2. 78/10/11. 9pp. 94364: 310
- 7810230375 Believes that there is a potential problem w/Class 1E battery racks supplied to sub, facil.Add1 isolation bar for saismic protec will be available for retrofit w/in 60 days. McNANUB.C.K. ESB. Inc. 78/10/11. 1p. 94271:184.
- 7810190066 Forwards duplicate of original 780629 ltr containing affidavit re proprietary response to request for additinfo. Ltr not previously received. HOWELL-8.H., Consumers Power Go. 78/10/12. 1p.
- 78:1010308 CPC request to withhold as proprietary section 4.C of thei gen Agreement w/Dow of 780621 per 10CFR2790 is granted. LVNCH: 0.D. Environmental Projects Branch 2. 78/10/12. Pep. 94392: 160.
- 7810240013 Forwards summary dtd 780027: "Bummary of March 21-22,1978 meeting & site visit".for the info of the NRC.
 TOURTELLOTTE, J. Office of the Executive Legal Director. 78/10/13.
- --7810240017 Summary of 780321 & 22 meeting w/util in Midland.M1 refacility const completion schedule.

 CROCKER, L. P. Division of Project Management. 78/03/27. 13pp.
- 7810240213 Requests add1 info for FSAR review. W/encl questionneirs. VARQA, S. A. Light Water Reactore Branch 4. 78/10/13. 80pp.
- 7810230199 Repts on site visit to subj facil during week of 780905. Encloses summarized schedule of week's activities & principal personnel contacted. LYNCH, D. D. Environmental Projects Branch 2. 78/10/13. 15pp. 94398:205.
- 7810250099 Forwards encl preliminary rept "Prelimiary Pump & Valve Inservice Testing Program for CPC Midlend Plants Units 1 & 2." Bubmitted in response to NRC question ra FBAR. Plan. in parts to form besis of 781025 meeting w/NRC. HOMELL.8.H. Consumers Power Co. 78/10/18. 2pp.

- 7810250131 Requests edd1 info re estimated ONP ennual growth & QM vehicle produc growth rates used to forecast OM elec sales.
 REGMN.M.M. Environmental Projects Branch 2. 78/10/18. 3pp. 94392.260
- 78110B0015 Responds to 781011 NRC request for add1 info re 2 items of noncompliance noted in 780817 NRC ltr. Encl 781020 ltr from Bethtel to CPC discusses document control stamping & removal of void drawings from files.

 HOMELLER H. Consumers Power Co. 78/10/20 3pp. 94398:035.
- 7810270199 Response to 781004 FQIA request for documents re completion dates for subj facil & detailed plant-specific analysis. Forumfor requested documents. Wiencil list of documents. FELTON.J M. Division of Rules and Records. 78/10/23. 2PP. 94055. 308
- 7810270201 FOIA request for documents re-estimated constrict completion dates for subj facil & "deteiled plant-spcific analysis"of those units.

 DOM:W Public Interest Research Group. 78/10/04. 1p. 74036:310.
- 7810310293 Approves request for withholding section 4.C of the Gen Agreement between Dow Chem & util re-price of energy sold to util under agreement Price & cost of producing energy is hald to be confidential info by NRC.

 REONN.W H. Environmental Projects Branch 2. 78/10/23. Spp.
- 7811070332 Summary of 780913 Meeting at Bethesda.MD on info requested by Ausiliary Sys Branch re main steam & process steam piping-reactor coolant pump cooling & fuel cask drop. MOOD.D H Light Mater Reactors Branch 4 78/10/23. 4pp. 94038:358.
- 7811130021 Burmary of 780914 meeting w/util. Bechtel Corp & B&W in Bethesde. HD re separation criteria & administrative procedures for installation of Class IE belance of plant equipment & circuits identified in PSAR Amend 32.


 HOOD. D Light Water Reactors Branch 4. 78/10/23. 4pp. 94079: 313.
- 7810310364 Concludes that separation criteria for NBSB & Class IE balence-of-glant equipment to non-Class IE circuits are per IEEE Btd 384-1974 & Reg Guide 1.75 & acceptable. VARQA. B.A. Light Water Reactors Branch 4. 78/10/24. 3pp. 94093:106
- 7811010092 Act receipt of 780929 interim rept re settlement of Diesel Generator Found & Bidg. Final rept will be reviewed upon receipt.
 HEIBERNIN.R.F., Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/10/24 Ip. 94361:315.
- 7811010008 Responds to 780926 ltr requesting NRC decision re review & potential release of section 4.6 of contract between Bow Chem Co. & Consumer Par Co. NRC finds section 4.6 met) confidential & proprietary. Request is denied. FELTON. J. M. Division of Rules and Records. 78/10/26. 1p. 94290.240.
- --7811010010 FDIA request for info re correspondence involved in contract between Dow Chea & Consumer Pur Co. FREEDKIN.8 Public Interest Research Group. 78/09/26. 1p. 74270:241.
- -781010013 FOIA request for section 4.C specifying rates & charge for process steem supplied to Dow Chemical by util. FREEDKIN.B. Public Interest Research Group. 78/07/15. 2pp. 94290,242
- 7811130107 Notice of 781106 meeting w/subj util on staff requests for edd: info re extension of constr completion dates for facils.

 HOOD D. Light Water Reactors Branch 4. 78/10/30. 2pg. 94113:307.
- ---7811150109 Requests add1 info re constr parall extension as requested on 770829. VAROA, B. A. Light Hater Reactors Branch 4. 78/10/27. 2pp. 4113:309.
- 7811240183 Responds to 781025 ltr. City has 41 police officers, 16 petrol cars & no impact on crims rate from constr of subj facil.

 HARCEK, D. B. Midlend County, Ml. 78/10/30. ip. 94438:302,

- 7811240188 Responds to 781025 itm Park acreage in City or approx 2700 acres & total park space accessed standards. MOFFATT, D. W. Midland City, MI. 78/10/31. ip.
- 7811140059 Forwards request for add1 info re main steam 1 accident, Requires that power distribution distortions obly stuck rod be considered during both initial portion later return-to-subcritical-power portion of analyses. VARGA-B-A. Light Meter Reactors Branch 4. 78/11/01. 94425:001.
- 7811240166 Confirms 780912 info.41 law enforcement office care involved Crime rate not affected by construct outputs (ACNL. MCNUTT.J.R. Midland County, MI. 78/11/01. 1p. 94458
- 7811240186 Confirms 780912 telephone conversation. City of treatment facils will be expanded to treat total of 48 million gallons/day & be adequate until 1990. EHING. M. C. Hidland City, MI. 78/11/06. ip.
- 7811130143 Notifies applicant of 781128 NRC-sponsored sem. Radiological Effluent Tech Spece for Nuc Pur Plants. Enc. w/Seeinar Info Sheat(to be completed & returned by 7811: Proposed Agenda.

 KEPPLEN, J. O. Region 3. Chicago. Office of the Director. App. 94087:332.
- 7811240164 Responds to 781025 ltr.Current school enrollmet Bidgs in school district can accommodate R500 new studet in 1980.
- BAXER, R. Midland City, MI. 78/11/07, 1p. 94459:301,
- 7811200159 Forwards for review by Baismic Qual Review Team listings of encl portions of BGRT info & schedule for providing currently unavailable data & completed BGRT fr HOMELLIB.H. Consumers Power Co. 78/11/13. 84pp. 027
- 7811200121 Forwards Crane Packing Co Sulletin 3478: "Seal F Test for Nuc Pur Plant Safety Injection Sys", to support util's essumptions on HPI pump seal leakage as discussed 780720 meeting w/MRC re EBF filtration issue. HOHELL, S. H. Consumers Power Co. 78/11/14. 83pp. 9420
- 7811240190 Responds to 781025 request for confirmation of data to Midland Hosp Assoc(personnel count, Not admission Confirms info on file is provided by hosp Occupancy rate 71%.
 RATHBUN, K. J. Michigan, State of. 78/11/14
- 7811280127 Bunmary of 781106 meeting w/CPC in Bathesda, MD of const completion dates. Draft response to 781027 quasi encl.
 HDOD, D. Light Water Reactors Branch 4. 78/11/14. 10pp
- 7811280130 Natification of 781203-04 meetings w/CPC in Mic settlement of diesel generator bldg & other structures. Agenda encl.
- HOOD, D. Light Hater Reactors Branch 4. 78/11/14. 4pp.
- 7811280131 Summary of 780820 meeting on steam lins break a cold shutdown position & safeguards pump room laskage. Mulist of attendess & applicant's responses to NRC questic HOOD. D. Light Water Reactors Branch 4, 78/11/14. 27pp 7811270087 Forwards request for addl info for review of an lic for subj facil. Response req by 781208:3 originals &
- 78112/2007 Forwards request for add1 info for review of an lic for subj facil.Response req by 781208:3 originals & copies:41 are to be forwarded & 109 to be retained. REOM.M.H. Environmental Projects Branch 2. 78/11/16. 94260:340.
- 7811280091 Forwards Rev#i"Draft Radiological Effluent Tech PHR's"(NUREG-0472) & "Preparation of Radiological Efflue Tech Spec for Nuc Pur Plants"(NUREG-0133). H/encl 7811270173 & 7811270180. VABBALLD.D. 3. Assistant Director for Light Water Reacto 78/11/16. 6pp. 02726: 322.
- 78:1300007 Forwards order extending completion on dates fr 79:201 to 82:001 & 8:1001 for Units 1 & R. respectively. VARGA. B. A. Light Water Reactors Branch A. 78/11/17. 3



- --7811300011 Order extending const completion dates from 781201 & 791201 to 821001 & 811001 for Units 1 & 2 respectively. Evaluation of request for extension of CPPR-B1 & CPPR-B2 ent1.
 BUYD.R.B. Division of Project Management. 78/11/17. 7pp. 94057-344.
- --781300019 States environ impact statement for extension of construerment not warranted. All necessary info described in Final Environ Statement-Constr Permit Stage.

 REDAN. H Environmental Projects Branch 2. 78/11/17. 2pp. 94077:023.
- --7811300023 EIA concluding no EIB need be prepared for proposed action.

 4 Division of Site Bafety & Environmental Analysis. 78/11/17.
 200. 94077.025
- 78 12050094 Safety evaluation supporting extension of Const Permits CPPR-81 & CPPR-82 HODD. VARGA. 8.A. Light Water Reactors Branch 4. 78/11/17. Spp.
- --7812050097 Environ Impact Appraisal concluding that extension of subj Pacil Constr Permits CPPR-B1 & CPPR-B2 will cause no major addi environ impact.N/Negative Declaration. * Division of Site Bafety & Environmental Analysis. 78/11/17. 20p.
- 78 11270147 Forwards Amend 33 to CP & DL application, containing update to general info portion.
 MOMELL B. H. Consumers Power Co. 78/11/21. 1p. 94271; 343.
- --7811270151 Amend 53 to CP & OL application re basis for completion date extension. Unit 1 extension from 771201-781201 to 801001-821001 Unit 2 extension from 781201-791201 to 801001-811001. Delay partially due to finences.

 Consumers Power Co. 78/11/21. 15pp. 94271:344.
- 78:1270152 Forwards add1 copies of CPC responses to Suppl Requests for Add1 Info.Part2.originally transmitted to NRC by 1tr of 78:102. W/enc1 ANO:78:11160108.

 HOWELL.B.M. Consumers Power Co. 78/11/21. ip. 94232:355.
- 78 12070280 Notification of 781211 meeting w/CPC.Bechtel & 86H in Bethesda.HD to appeal NRC position that facilities be capable of obtaining cold shutdown conditions using only safety grade equipment.

 HDOD.D. Light Water Reactors Branch 4. 78/11/27. 4pp. 94085:054.
- 78 12050142 Forwards Cert of Byc for Appl for Constr Permit & Oper Lic. Amende53. BACON.J.L. Consumers Power Co. 78/11/29. 2pp. 94334:350.
- 79:12050213 Forwards Certificate of Svc for Amend 54 to CP & DL application.containing Revision 15 to FBAR.
 BACON.J.L. Consumers Power Co. 78/11/30. ip. 94318:345.
- 78:12120002 Forwards supplemental second round question from Reactor Physics Section re criticality of proposed high density storage sys. (Encl B008130549)
 TEDEBCO.R.L. Division of Systems Bafety. 78/12/01. ip. 94274:295.
- 78:12280118 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants. Info submitted must be substantiated by data & calculations. Licenses must notify NRC of any inaccuraties or enforcement action will result. DAVIS. J. 0. Defice of Inspection & Enforcement. Office of the Director. 78/12/06. 200.
- 7812180391 Responds to request for withholding info submitted on 780609 & 0629 (ref 10CFR2.790). Forwards tables listing criteria used by BBM to determine whether submitted matls are proprietary & proprietary claim of matl submitted. VARGA. B. A. Light Water Reactors Branch 4. 78/12/07. 7pp. 94397: 266.
- 7812260188 Discusses questions raised during visit re diesel generator estilement problem. COOME. T. C. Consumers Power Co. 78/12/07. 2pp. 94139:156.
- 7812210294 Notification of 781220 meeting w/CPC & 8&H in Bethesda, MD to discuss single failure proof crane for spant fuel details of full-scale modeling tests planned for containment sump & steam line break analysis w/stuck control rod estably.

 HOOD. D. Light Water Reactors Branch 4, 78/12/11. 4pp. 94167:320.
- C. Utility Environmental Report (ER), amends & correspondence
- 7811170294 Forwards Amend 82 to Environ Rept re corrections of errors & requests for add1 into re original Amend.
 HOWELLE.H. Consumers Power Co. 78/11/10. 1p. 94045:274.

- --7811170298 Amend 52 to Environ Rept re correction of errors & requested by WH Regen's 780322.781011. & 781018 ltrs.
 HOMELL, 8 H. Consumers Power Co. 78/11/10. 202pp 94045.277
- 7811070149 Responds to 781011 NRC 1tr re-review of subj facil Environ Rept-Oper Lic Stage. Answers questions re-archeological investigation of Tittabawasses River floodplain. httpation or avoidance of archeological eites
- 7811280282 Forwards affidevit distributing copies of Amend#52 to CPC's Appl for Constr Permit. Cert of Svc encl. BANJJ. Consumers Power Co. 78/11/20. 4pp. 94375:228
- 7812190095 Forwards affidavit for Amend 95 Rev4 to Environ Rept appl for reactor constr parmit & open lic on 781211. BACCN.J.L. Consumers Power Co. 78/12/12, 4pp 94381:036
- D. NRC Draft/Final Environmental Statements, supple & correspondence
- 7812050222 Ack cooperation in providing into for EIS for subj facils. Requests written confirmation of data provided re staffing admissions & occupancy rate of Midland Hospital.

 HONO B.W. Argonne National Laboratory. 78/10/25 pp. 94201:148
- 7812030225 Ack cooperation in providing info for EIS for subj facils. Requests written confirmation of data provided re-planned expansion of water capacity of City of Midland. HONO, S.W. Argonas National Laboratory: 78/10/25 1p. 94201 199.
- 7812050227 Ack cooperation in providing info for E18 for subj facils Requests written confirmation of data provided reacrage of partial in the City of Midland & that the total space devoted to parks & recreation exceeds gen standards HONG 8. M. Argonne National Laboratory 78/10/25 ip. 94201-200.
- 7812030232 Ack comperation in providing info for EIB for subj facils. Requests written confirmation of data provided re 4 of law enforcement officials & patrol cars in Midland County, & that constr of facils has not affected local crime rate. HONO, B. M. Argonne National Laboratory. 78/10/25. ip. 94202.023.
- 7812050239 Ack cooperation in providing info for EIB for subj facile Requests written confirmation ofdata provided rem of police & patrol cars in City of Midland, & that constr of facile does not impact on local crime rate.

 HDN9.8.W. Argonne National Laboratory. 78/10/25. Ip. 94202:045
- 7812030244 Ack cooperation in providing info for E18 for subj facils Requests written confirmation of data provided re-current enrollment & unused capacity of the Bullock Creek School District.

 HONO.S.W. Argonne National Laboratory. 78/10/25. 1p. 94202:067.
- 7812050250 Ack cooperation in providing info for EIS for sub; facils. Requests written confirmation of data provided recurrent enrollment & unused capacity of the Midland School District. HONG.S.W. Argonne National Laboratory. 78/10/83. 1p. 94202:114.
- 7812030205 Ack cooperation in providing info for EIB for subj facils. Requests written confirmation of data provided reconfirmation by State Supreme Court of annexation. HONG.S.M. Argonna National Laboratory. 78/10/25. [p. 94202:127.

9. Adjudicatory correspondence

- 7811100146 Forwards contantions that MI law prevents lic that creates a nutsance, illegal radiat spills are occurring spent fuel rod storage has created hazards, icing & fogging nuisance is occurring & present tech fails to achiev zero enission.

 MARSHALL, W. H. Mepleton Intervenors, 78/10/31, 1p. 94047: 169.
- 7811300369 Hemorandum & order postponing special prehearing conference previously scheduled for 781115, until 781214 at same hr & location.

 BMITH-I.W. Atomic Safety and Licensing Board Panel. 78/11/13. 3pp 94136:281.
- 7812280350 Memo of CPC re environ effects of radon per NRC Order of 781106. Asserts that Perkins decision is supported by record of thet proc & that radon emissions do not critically effect cost-benefit belance, Wencl documentation & Cert of Byc. MILLER, M. I., 91988, M.E. Isham, Lincoln & Beele. 78/12/OS. 19pp. 94082:217.

- 78:01:0307 Answer of Consumers Pur Co to Petition for Leave to SIGNIDUAL ANSWER OF CONSUMERS FUR CO TO RESISTON FOR LEAVE TO Intervene OF M H Marshall on behalf of the Mapleton Intervenors Intervention should be desired for untimeliness. A participation would not contribute to record. MILLERIM E. GIBBS.M E. Isham. Lincoln & Beale 78/09/28. 13pp. 94061 016
- 7810250152 Natice of withdrawal from proceeding as of 780929. Certificate of Svc enci. QROSSMAN.N J. Hearings Division. 78/09/29 ... 3pp
- 78:0140027 NRC steff ensuer to petition submitted 780909 by W. Mershall requesting leave to intervene on behalf of Hepelton interveners NRC staff does not oppose petition at this time. CLMSTEAD.W.J. Office of the Elecutive Legal Director. 78/10/03. 94421 032 700
- 7B110202B1 Notice of Mithérawal of Appearance accompanied by Notice of Appearance for David Bonderman, replacing Cohen & Cert of COMEN.R C Arnold & Porter 78/10/06 Spp. 94354-282
- 7810240157 Notice of hearing on issuance of OL license SER.FES.DES.
 ACRS rept on OL application.Tech Specs & intervention
 petitions related papers & Board 780814 memorandum & order
 may be inspected at NRC PDR.Certificate of Svc anci.
 BHITH.I.W Atomic Baraty and Licensing Board Panel. 78/10/12. 4pp.
- 78102501BB Memorandum & order granting WH Marshall temporary status as Intervention pentition Mapleton Intervenors may file amended petition demonstrating interest in proceeding.

 BHTHLI M Atomic Safety and Licensing Board Panel. 78/10/12. App. 94392 241
- 7810300311 Repts predicted will figures for long-term electricity deand for 1978-88 per latest short-term forecast MILLER.M I. Ishae, Lincoln & Seale. 78/10/18 2pp. 94253:317.
- 781101000A Forwards another copy of the B6 Mama & Order of 78081A & Notice of Hearing on issuance of Facil Oper Lic of 781012 in response to 78101B Mailgram Informs that requests for data should go to staff.not B0. M/o and SMITM. I. W. Atomic Safety and Licensing Appeal Panel. 78/10/23. SHITH I. H Atom 200 94290 237.
- 7811080048 Requests rescheduling of NRC hearing in Midland. MI from 781015 to another date MARBIALL, H H Affiliation Unknown 78/10/29. 1p. 94398:140.
- 7812060152 Order referencing re annexation of tub; site to City of Midland, HI forwarded as encl to ANO: 7811240199.
 MARRISON.M. Q. Michigan, State of. 78/10/30. 43pp. 01791: 057.
- response to motion of 781029 from W Marshall re-rescheduling of prehearing conferences ordered that S Gadlar will represent Marshall & Mapleton Intervenors at the special prehearing conference. BMITM. I.W. Atomic Safety and Licensing Soard Panel. 78/10/31. 2pp. 03003:330. 7811130189 In response to motion of 781029 from W Marshall re
- -->7811130192 Request by intervenor W Marshell for continuance of special prehearing conference on 781110 due to his unavailability on that day Request for reached made on his own behalf & on behalf of Mapleton Intervenors.

 MARSHALL, H. H. Affiliation Unknown, 78/10/29, 1p. 03553: 332.
- 7811210040 Submits eddl contentions in support of 780906 contentions objecting to subj facil re illegal charges & spills, geological conditions be storage of spent fuel rode.

 Cartificate of Svc encl.

 MARSHALLH H Mapleton Intervenors. 78/10/31. Spp. 94101:351.
- 7811150039 Requests that CPC file brief supporting util position that MH Marshall petition to intervene be barred by 781031 res judicate of 8vc and. MARSHALL, W.H. Mapleton Intervenors. 78/11/02. 1p. 94112:349.
- 7811210036 Berves BJ Gadler w/*Brief of Consumers Pur Co in support of its position that Marshall's patition to intervene is barred by res jucidate.* by res jucidete." @1888.H.E. lehem, Lincoln & Beale. 78/11/02. 1p. 03557;039.
- 7811210493 Contention of Intervenor M Binclair, Asserts that NRC Staff is responsible for assuring compliance w/Atomic Energy Act of 1984 Also claims that NRC has not implemented an effective direct Inspec grog Cert of Sec encl.

 BING_AIR.H.P. Affiliation Uninown. 78/11/03. 40pp. 03858:163.

- 7811130252 Only issue remaining to address issue of charge re CPC's conduct. 8d will also address issue of environ effects of reson. 8d will not consider CPC's alleg serving effects of reson. 8d will not consider CPC's alleg serving efficient as lack of financial quals history of 0A-OC violations & lack of financial quals CHILK, 8.J. Office of the Secretary of the Commission. 7cpp. 94273:086.
- 7811220215 Supple 781018 notice of hearing that epscial pre conference per 10CFR2 751(a) would begin on 781115 Meetir will not be held on 781214 in Midlend MI
 - SMITH, I. H. Atomic Sefety and Licensing Board Panel 94071:282.
- 7812060126 Requests change of location for 781214-15 prohe-conference from Midland.MI to Chicago IL. CHERRY.H M. Cherry, M M /Cherry, Flynn & Kanter. 78/1 94382: 025.
- --7812060172 Requests comments on NRC 781106 menorandum & consideration of operating & const matters CHERRY.H.H. Cherry, M. M. /Cherry, Flynn & Kanter. 78 94382:027
- 7811300356 Objects to M Cherry 781113 request to change lo licensing hearings to Chicago. Poor health would prevent attendance if hearing was not held in Midland. MI. Certifi MARGHALLIN. H. APPiliation Unknown. 78/11/17. 1p. 941
- 7812050257 Informs that itr transmitting radon record shot stamped "Berved 781117." Docketing & Services Branch, 70/11/21, 1p. 94202:1
- 7812010237 Memorandum & order confirming date of special ; conference. Location of future sessions will be discussed conference. Board will begin 701214 by dealing whroblem involving lawyers. Limited appearance statements deferred SMITH-I.W. Atomic Safety and Licensing Board Panel. 75 94417:123.
- 7812140087 Brief submitted by CPC in response to ABLB Ord CPC asserts that 27 of petitioner to intervene H Bincle suppl contentions are inadmissible & that petition to intervene of W Marshall be denied. Cert of Suc encl. MILLER.M. 1. 01888, M.E. Isham, Lincoln & Beate. 78/11 94128:242.
- 7812140362 Answer of CPC to Motion by M Cherry, represents intervenors other than Dow Chem Co.for joint tonational of oper & constr matters.CPC essents that consolidation neither reg nor justified Cert of Byc encl. MILLER.M. I., 01888, M.E. Isham, Lincoln & Beale, 78/11 03557 251.
- 7812260065 Forwards "Participation in the Instant Proc." TAYLOR.Q.T. Michigan, State of. 78/11/28. ip. 94027
- --7812260067 "Participation of the State of MI in the Int Responds to Bd Order 781117 requiring MI to advise it intends to participate Scape & sub; matter of intends participation are outlined. TAYLOR.9.T. Michigan, State of. 78/11/28. Rep. 94
- 781220278 NRC Staff's Response to contentions of petitic intervene Maplaton Intervenors. Staff asserts that contentionsHi.3.4.6 % 7 are vague or w/out basis in faccontentionsH2 % 5 may be proper if rephrased. H/Cart of DLMSTEAD.H.J. Office of the Executive Legal Director. 5pp. 94160:052.
- -- 7812260305 NRC Staff's response to Contentions of pati DIMEQUADO NHE SEAFF'S response to Contentions of peti intervene it Sinclair. Staff objects to contentionsWi-26.33.39-41.49.46.44a.45a.47a-54.No objection is mad contentions#22.24.27-34.42-44.47.48 & 46s. DUMSTEAD.H.J. Office of the Executive Legal Directo 10pp. 94160:035.
- 7812140223 Responds to 781120 request for advance notificating between NRC & consumers re-subj site. Responds already been sent such notices. & recent Fed Register effirms open meeting policy which holds for subj site. QLMSTEAD, H. J. Office of the Executive Legal Director. 1p. 94204:340.
- 7812180383 Corrects factual error in 781128 Consumers Pu Steam rate may or may not be subj to jurisdiction of N BVE COMM. 91988.M.E. Isham: Lincoln & Beale. 78/11/29. ip. 5

- 7812280325 Forwards documents to settlement of Diesel Generator Bldg foundations at subj facil.

 DLMSTEAD, H. J. Office of the Executive Legal Director 78/12/07.
 14pp. 94082:141.
- --7812280332 Forwards 781120 ltr from M Cherry w/possible ellegations against resident NRC inspector at subj facil. DAVIB.J.O. Office of Inspection & Enforcement, Office of the Director. 78/12/05 lp. 94082:360
- --7812280334 Forwards ltr from M Cherry re subj constr proj. Response is being prepared.
 KEPPLER. J. Q. Region 3. Chicago. Office of the Director. 78/11/24.
 1p. 03555:152.
- --7812280340 Expresses concern that NRC is attempting to minimize problem of diesel generator bldg settlement at subj facil. Suggests NRC resident inspector may be coopted by util. Requests info & permission to attend next inspec. CHERRY.M.M. Cherry. M. M. /Cherry. Flynn & Kanter. 78/11/20. 3pp. 00355:157.
- --7812280343 Transfers lead responsibility for problem of significant settlement of diesel generator bldg to NRR. H/encl repts on deficiency.
 VABBALLO, D. B. Assistant Director for Light Water Reactors.
 78/11/17. lipp. 94082:204.
- 7819270132 NRC Btaff's response to NRC Memo & Order of 781106 re radon issue. Asserts that ABLB has no need for add1 written evidence re radon question. Notice of appearance for BM Bordenick & Cert of Bvc encl.
 BDRDENICK.B.M. Office of the Executive Legal Director. 78/19/08. 10pp. 94161:086.

H. General correspondence

- 7811010014 Requests OL documents:50-329 & 50-33 to be sent to N Hattle P.O. Box 103.3609 Shoreline Dr., Nararve, Mn 55392, also to place Hatlie on circulatory list. MARSHALL, N. H. Mapleton Intervenors. 78/10/18. ip. 94290:239.
- 7812280198 Responds to 781120 ltr.Forwards info re resident inspector being co-opted by Midland personnel. NRC has initiated an investigation into settlement of diesel bldg at facil. KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/12/14. 125pp. 94073; 090.
- K. Utility Final Bafety Analysis Report (FBAR) & amends
- 7812010252 Rev 15 to the FBAR vole 1 & 2: responses to requests for add1 info.rev re orifice rod assemblies & high density fuel racks & routing design deviadd1 info scheduled for entry. W/encl amend appl for CP & DL.

 * Consumers Power Co. 78/11/30. 1300pp.
- 7810230192 Forwards Amend 51 to CP & OL applications, consisting of Revision 14 to FBAR, HOWELL, B. H. Consumers Power Co. 78/10/17, 1p.
- --7810230196 Revision 14 to FBAR, Vols 1&2. # Consumers Power Co. 78/10/17, 1153pp.
- 7810270168 Forwards Cert of Svc for copies of Amenda51(Rev 14 to Final Bafety Analysis Reptito appl for constr permits & oper lice. BACCN-U.L. Consumers Power Co. 78/10/24. 2pp. 74056:266.
- 7812010251 Forwards Amend 54 to CP & DL application containing Revision 15 to FBAR.

 HOMELLES.H. Consumers Power Co. 78/11/27. 18pp. 94390: 159.
- 7812120154 Forwards advance copy of util response to NRC Request 421.2. "GA During Operations Phase." PSAR Subsection 17.2 repartsonnel training, steff changes, cleaning of fluid sys & GA audit. Response to be submitted w/Revision 16 of FSAR. HOWELL.S.H. Consumers Power Co. 78/12/08. 11pp. 94276:286.
- M. Antitrust correspondence
- 7812180246 Intervenors & applicant CPC rept that prospect for settlement of issues contested in proceedings re subjectls is excellent. An understanding has been reached in all but 2 areas. Cert of Bvc encl.
 ROSS.W.H., WATBON,K.S. Wald, Harkrader & Ross. JABLON,R.A. Spiegel & McDiaraid. 78/12/06. 4pp. 94359:335.

Q. Inspection reports, IE Bulletins & correspondence

- 7812050333 Forwards IE Bulletin#78-12A, suppl to 1E Bulletin 78-12 W/encl ANO; 7811300055.

 KEPPLER, J. O. Region 3. Chicago. Office of the Director 78/11/24 pp. 94409:001.
- 7812080249 Informs NRC of engoing preparation of response to IE Bulletin 78-12, "A Typical Weld Matl in Reactor Pressure Vessel Welds" for subj facil & states that written response will be forwarded by 781215.
 HOWELL-8.H. Consumers Power Co. 78/11/28 Ip. 94137-191.
- 7812140021 Forwards IE Inspec ReptsM50-329/78-11 & 50-330/78-11 on 780926-28 during which no items of noncompliance were noted. MEISHMAN,R,F. Region 3. Chicago. Dffice of the Director. 78/10/27. 2pp. 94119:347.
- 7810270024 Forwards I & E Initial Rept on Response to Bulletin 77-05/05A he Use of Elec Connectors. Appropriate 8ds should be notified where there is a question he use of connectors in safety sus. Hemo dtd 780207 also encl.
 TEDEBCO.R. L. Assistant Director for Plant Bystoms 78/02/08. 19
- --781027024& Forwards "Status of Responses from Licensees of Plants und Construc to Bulletins 77-05 & 03A". MOBELEY, N.C. Division of Reactor Construction Inspection. 78/02/07, 3pp.
- 7811130340 Forwards IE Inspec Repts#50-329/78-09 & #50-330/78-09 on 780829-31 & Notice of Violation.
 HEIB-MAN, R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch, 78/09/21. 2PP. 94007:309.
- --7811130343 Notice of Violation from inspec on 780839-31. * Region 3, Chicago, Reactor Construction & Engineering Support Branch, 78/09/21. 1p. 94007:311.
- --7811130350 IE Inspec Repts#30-329/78-09 & #50-330/78-09 on 780829-31 during which 1 item of noncompliance was nated:failure to follow procedure in welding root pass.

 LEE, E. M., DANIELBON, D. H. Region 3. Chicaga, Office of the Director, 78/09/21. Spp. 94007:312
- 7810160197 "Preservice & First 10-Yr Interval Insp Plan for NDE & Sys Pressure Testing at CPC Midlend Units 1 & 2." Prepared for util. SLAGER, H. W., BIRKLE, A. J., MAYNARD, C. J. Bechtel Corp 78/09/29. 247pp.
- 7810160196 Forwards "Preservice & First 10-Yr Interval Insp Plan for NDE & 8ys Pressure Testing at CPC Midland Units 1 & 2." Data reported in Bettion 3 of plan is preliminary & subj to change as const progresses. Plan basis of 781025 meeting. HDMELLS.H. Consumers Pawer Co. 78/10/05 2pp. 94007:150.
- 7811140048 Forwards IE Inspec Repts#30-329/78-10 & #50-330/78-10 on 780913-15 during which no items of homospitance were noted. HEIBHMAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch, 78/10/10, 2pp. 94420:343.
- --7811140054 IE Inspec Repts#50-329/78-10 & #50-330/78-10 on 780913-15 during which no items of noncompliance were noted Major areas inspected included installation of sefety-related hangers & restraints.

 YIN.I.T. Region 3. Chicago. Office of the Director DANIELBON, D. H. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 78/10/10. Opp. 94420:345.
- 781020021: Ack receipt of 780918 ltr informing NRC of steps taken to correct item of noncompliance identified in IE Insp Repts 50-329/78-07 & 50-330/78-07. Addl info is requested. KEPPLER, J. Q. Region 3. Chicago. Office of the Director. 78/10/11. Pop. 74367:064.
- 7811070336 Responds to 780921 NRC ltr re noncompliance noted in Inspec Repts#30-329/78-09 & 50-330/78-09. Corrective actions:rev of Bechtel Welding Procedure Spec & Bechtel Project Guelity Control Instruction#7220/W-1.00. HOWELL-8. H. Consumers Power Co. 78/10/23 3pp. 94043:080.
- 7812140028 IE Inspec Repts#50-3R9/78-11 & #50-330/78-11 on 780926-28 during which no items of noncompliance were noted Major areas inspected incl: Babcock & Wilcox Constr Conondestructive exemination prog procedures & parsonnel cert. HARD, K.D., DANIELBON, D. M. Region 3. Chicago, Office of the Director 78/10/26, 7pp.

- Reptablo-329/78-03 & #50-330/78-03 Corrective actions weld spec rev, weld voltage range monitoring procedure prepared disagrees on 15% voltage range limitation HDHELL, S. H. Consumers Power Co. 78/10/31. 2pp. 94013-023
- 7812050064 Forwards 1E Inspec Repts#50-329/78-13 & #50-330/78-13 on 780724-28. 31,0801-31,0901-08 & Notice of Violation. HEIGHMAN R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/11/03 2pp. 94232.254.
- --7812050057 Notice of Violation from inspec on 780724-0928. * Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/11/03 2pp. 94232-255
- --7812060070 JE Inspec Repts#50-329/78-13 & #50-330/78-13 on 780724-0908 during which 2 ttems of noncompliance were noted welds with unequal outside diameters were accepted & Safety Related Control Rod Drive Primary Breakers were not well protected. CCON.R.J., HAYNES, D.W. Region 3. Chicago, Office of the Director. 78/11/03. 6pp 94232:258
- 7811150057 Forwards IE Circular 78-18.

 MEPPLER, J G. Region 3, Chicago, Office of the Director. 78/11/06
 1p. 94112:192.
- 7811200041 Ack receipt of 781020 itr informing NRC of steps taken to correct violations noted during inspec. MEIB-MAN.R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch 78/11/08. 1p 94215-323.
- 7812140130 Forwards IE Inspec Repts#80-329/78-14 & 50-330/78-14 on 780910-29 during which no items of noncompliance were noted. HEIS-MANUR, F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/11/08 2pp. 94128:334
- --7812140139 IE Inspec Repts#50-329/78-14 & 50-330/78-14 on 780910-29 during which no items of noncompliance were noted Major areas inspected incleasements on of genetic condition & steam generator & reactor vessel hold down bolting CCOK.R.J., HAYEB.D.W. Region 3. Chicago. Reactor Construction & Engineering Support Branch. 78/11/06 4pp. 94128.336.
- 7811220006 Ack receipt of 781023 itr informing NRC of steps taken to correct violations moted in 780921 itr Corrective actions will be reviewed during a future inspec.
 HEIBHMAN, R. F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/11/15 lp. 94308:246.
- 7812050102 Act receipt of 781031 ltr informing NRC of steps taken to correct violations noted in 780504 & 780913 ltrs. Re issue(b) NRC requests that sampling measurement sys provide assurance that all welding machines are covered by amperage & voltage. HEIGHMAN.R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/11/22. ip. 94035:287.
- 7812140080 Ack receipt of IE Bulletin#78-12A re atypical weld meth in pressure vessels. Response will be consistent w/extended sched of IE Bulletin#78-12A.

 HOWELL-8.H. Consumers Power Co. 78/12/05. Ip. 94128:226.
- 7812290015 Forwards JE 90]]etin 78-14. KEPPLER, J. 9. Region 3, Chicago, Office of the Director. 78/12/19. 1p. 06911.001.
- R. Periodic operating reports & related correspondence
- 7810270142 Forwards Monthly Nonconformance rept for Sept 1978. HDMELLIS.H. Consumers Power Co. 78/10/25 1p. 94060:050.
- S. Reportable occurrences. LERs & related correspondence
- 7812010155 Ack receipt of 781110 interim rept pursuent to 10CFR50.55(e) re reactor building spray piping supports HEIS-MAN,R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/11/22 ip. 94418:125.
- 7810180075 Interim deficiency rept re reactor bldg spray piping supports. Becktel Associates Prof Corp rept of status of corrective action & investigation encl. Further rept to be submitted by 781117.

 HOWELL'S.H. Consumers Power Co. 78/10/13. 4pp. 94401:028.
- 7811010401 Ack receipt of 780929 final deficiency rept re containment bldg personnel airlocks, Review will be completed during future insps.

 HEIG-MAN, 9. F. Region D. Chicago. Reactor Construction & Engineering Bupport Branch. 78/10/24. ip. 94388: 323.

- Final rept will be reviewed upon receipt HEISHMAN.R F Region 3. Chicago, Reactor Construction & Engineeric Bupport Branch. 78/10/25 ip 94375:355.
- 7811070222 Ack receipt of 781013 interim rept re reactor bldg spray piping supports.
 HEJBHMAN.R.F. Region 3. Chicago. Reactor Construction & Engineerin Support Branch. 78/10/30 1p. 94039-141.
- 78:11:702:12 Interim deficiency rept re settlement of diesel generator foundations & bldg. Provides status of actions to be taken. Review meeting tentatively planned for last two wks in Nov. Further rept to be submitted by 78:229.

 HDWOLL:8 H. Consumers Power Co. 78:711/07, 7pp. 94:36:114
- 78il170222 Interim deficiency rept re reactor bldg spray piping supports Provides status of analysis being conducted to resolve question of adequacy of supports per ABME Section III Code allowable stress requirements. Final rept by 78i219. HOWELL-8.H. Consumers Power Co. 78/i1/10. 4pp. 94i36.213.
- 78/12/20176 Interim deficiency rept re Class IE station battery. Exide Industrial Battery Div asked to provide additional info describing condition-failure mode & analysis of why condition was reportable. Related correspondence. HOWELL-8 H. Consumers Power Co. 78/11/17. 2pp. 94623:267.
- --7811220178 Reports that addition ber must be added to Class battery racks sent to subj facils in order to isolate horizontal momentum during seismic events. Design is being worked out & will be ready in 60 days for retrofit.
 MCMANUS.C.K. ESB. Inc. 78/10/ii. 1p. 94623:269.
- 7811290293 Ack receipt of 781117 interim rept pursuant to 10CFR50.55 re settlement of diesel generator foundations & bldg.
 HEIS-MAN.R.F. Region 3. Chicago, Reactor Construction & Engineeric Bupport Branch. 78/11/22. 1p. 94239:244.
- 7812040207 Ack receipt of 781110 interim rept re reactor bldg spray piping supports.
 HEISMAN.R.F. Region 3. Chicago, Office of the Director. 78/11/2
- 7812140366 Ack receipt of 781117 interim deficiency rept re class is station bettery racks HEIGHMAN.R.F. Region 3. Chicago, Reactor Construction & Engineerin Support Branch. 78/11/22. 1p. 03557: 288.
- 7B1204021B Interim deficiency rept re component qualification test documentation re-review Rept is being generated by Bechtel documenting status of re-review & results on individual meti requisition basis for all G-components requisition testing. HOWELL.8 H. Consumers Power Co. 7B/11/RB. 2pp. 94445:359.
- 7812270184 Interim deficiency rept re reactor bldg apere piping supports. Bechtel Associates Prof Corp rept on status of analysis being conducted to resolve question of adequacy of reactor bldg spray piping supports per ASME requirements. HOWELL. B H Consumers Power Co. 78/12/15. 3pp. 94017:361.
- 7812270254 Forwards nonconformance tept for Nov 1978. (Encl 800818068: HONELL/8.H. Consumers Power Co. 78/12/20. 2pp. 94016:082.
- 7812290146 Interim deficiency rept re-settlement of diesel generator foundations & bldg. Use of preload to densify existing fill matl in place selected as corrective action. Bettel rept detailing tasks to be sent by Jan. Related correspondence. HOWELL.B.H. Consumers Power Co. 78/12/21. 2pp. 94190:281.
- DOCKET 50-331 DUANE ARNOLD ENERGY CENTER
- F. Security, medical, emergency & fire protection plans
- 7810230173 Analysis of subj fecil fire protec sys will be submitted b 781115. LIU.L. Iowa Electric Light & Power Co. 78/10/10. ip. 94164:299.
- 7811070121 Responds to 781031 NRC request for fire protec mod effort. Forwards design info re Control Room Fire hazards & Water Buppression Bys. Requests approval by 781020.
 LIU.L. Iowa Electric Light & Power Co. 78/10/30. 3pp. 94038:298
- 7811170159 Fowerds subj facil security Proj sched, Recent proj incl sltwork & fencework continuing on sched, security hardware contract has commenced, bldg facil contract constr work has commenced. LTU.L. Iowa Electric Light & Power Co. 78/11/01. 3pp. 94048:048

- 7811130052 Confirms meeting to be held between util & NRC Region III on 781113 to discuss security prog at site including items of noncompliance identified during past 3 inspections KEPPLER. J. O. Region 3. Chicago. Office of the Director. 78/11/03 ip. 94010 244.
- 7812110106 Forwards Security Proj Eched & states that site & fencing work has been completed while security hardware & bldg facil contract work is proceeding as sched LIU.L lowa Electric Light & Power Co. 78/12/01. 1p 94339.064
- 7811210354 Analyses to adequacy of elec cable fire barrier penetrations will be submitted by 781231 & fire protec sys fire hazard analysis will be submitted by 790131
 LIU.L. Joue Electric Light & Power Co 78/11/15 ip 94405.016

Q. Adjudicatory correspondence

- 7812290233 Requests that NRC institute a hearing suspending facil lic until augmented insvc imapec prog is incorp into the lic iOCR350 55a(a)(1)req licensee to test & inspec qual standards commensurate w/safety function performed. HALLIN.O. Citizens United for Responsible Energy. 78/12/20. 2pp. 94191:212
- H. General correspondence
- 7812130100 Requests full investigation of pipe cracking of facil since leak was discovered in coolant pipe after elec malfunction shut down reactor. Recommends institution of more efficient integer & monitoring procedures.

 KIEGELJ A Affiliation Unknown 78/11/21 1p. 94294:328
- J. Insurance & indomnity information
- 7810110143 Forwards signed copy of Amend#5 to Indemnity Agreement#B-68. SECRMAN.P.E. Ious Electric Light & Power Co. 78/10/04 ip. 94064-277
- --7810110146 Amend #5 to Indomnity Agreement #8-68. adding Article 8 repayment of premiums.

 BALTZMAN, J. Antitrust & Indomnity Group. 78/10/04. 2pp. 94064:278
- P. Operating license stage documents & correspondence
- 7811280030 Forwards request for info on recirculation inlet nozzle enalysis to be delivered in oral & written form at 780707 meeting.

 KEPPLER.J.O. Region 3. Chicago. Office of the Director. 78/07/03 2pp. 02728:337.
- 7811280016 Summary of meeting on 780707 u/IELP to discuss crack in seferend on inlet recirculation notales indications in other seferends on inlet recirculation notales & repair of crack. W/sketch handouts at meeting & attendance list. WOORNUFF, R. W. Division of Reactor Operations Inspections 78/07/10. 20pp. 02788:260.
- 7811280036 Responds to 780703 ltr re subj facil Retirculation Inlet Notile Analysis. Covers dynamic analysis on piping piping isometric drawing of recirculation line, notile load summary, design transients for stress analysis.stress analysis. LIU.L. Iowa Electric Light & Power Co. 78/07/26. 133pp. 02728:012.
- 7811270202 Forwards repair rept entitled. "Duane Arnold Energy Center Recirculation Inlet Safe-End Repair Prog " LIU,L IDwa Electric Light & Power Co. 78/07/31. 9pp. 94272:142.
- 7811280491 Announces expension of scape of the Pipe Crack Study Group to Incl examination of intergranular stress carrosion cracking in the Inconel safe ends at subj facil in June 1978 & recommends actions to be taken to determine cause. DENTON.H.R. Office of Nuclear Reactor Regulation, Director. 78/09/29, ipp. 94414.279.
- ---TB11280493 Outlines recommendations & proposed course of action re results of safe end inspec & metallographics exams relevant to insvc inspec, mod & design qual of 4 types of safe ends for recirculation norrles. JCRDAN.E.L. Office of Inspection & Enforcement, Office of the Director. 78/09/29. 4pp. 94414:280.

- --7811280494 Reports that preliminary test results re pump riser crack problem indicates cracks are intergranular & start in area formed by thermal sleeve & Inconel transition piece & may exist in other plants COLLINS-W Office of International Programs, Director. 78/09/14. 3pp 94414-284
- 7810120047 Responds to 780829 NRC ltr re control rods failing to fully insert on scram No evidence exists that this has occurred according to 1977 records
 HAMMOND,E L. Iowa Electric Light & Power Co. 78/10/05 1p
- 7810240104 Invites NRC staff to conduct tech review meeting re repairs on subj facil at corporate headquarters of IELP This would follow NRC policy of bringing meetings closer to pub actually served by nuc facil.

 TUTHILL.S. J. Idwa Electric Light & Power Co. 78/10/06. 1p
- 7811030205 Forwards Amend#46 to Facil Oper Lic#DPR-49 revising Tech Bpecs as requested in 770414 ltr w/Safety Evaluation & Notice of Issuance. IPPD_ITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/17 2pp 02724 143
- --7811030208 Amend#46 to Facil Oper Lic#DPR-49 revising Tech Specs re limiting conditions for oper & surveillance requirements for drywell to suppression chamber differential pressure control & suppression pool water level. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/17 9p. 02724:145
- --7811030210 Notice of Issuance of Amend#46 to Facil Oper Lic#DPR-49 on 781017. IMPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/10/17. 2pp. 02724:160
- --781030215 Sefety evaluation supporting Amend 46 to Facil Oper Lic DPR-49 concluding that each Mark I containment sys would maintain its integrity in event of LOCA BHR facils can oper safely • Office of Nuclear Reactor Regulation, Director. 78/10/17 5pp 00724:154
- 7811130335 Burmary of 780914 meeting w/GE representatives & Mark | Owners Group re-progress of Long Term Prog w/attendance list & agenda(RO-9-A-Marki, Standards.) GRIMES.C Plant Systems Branch (Pre 791030). 78/10/26. 67pp
- 7810310220 Forwards "Metallurgical Investigation of Crecking in a Reactor Vessel No;zle Bafe-End". Dtd 781020. No significant deviations espected in final rept which FR will incl stress corrosion cracking review of incomal 600.

 LIUL. Joua Electric Light & Power Co. 78/10/27 lp. 94089:113.
- 7811280363 Announces 781114 meeting in Ceder Rapids. IA w/util re repair prog for recirculation sys inlet nozile safe ands at subj facil.

 CLARKIR. Operating Reactors Branch 3 (Pre 790625). 78/11/02 ip. 74397:227.
- 7811120173 Notifies applicant of 781128 NRC-sponsored seminar re-Model Radiological Effluent Tech Specs for Nur Pur Plants.Encl w/Beminar Info Sheet(to be completed & returned by 781117) & Proposed Agenda.

 KEPPLER, J. Q. Region 3, Chicago, Office of the Director. 78/11/07 App. 03533:233.
- 7812130161 Notice of workshops rs implementation of training & qual requirements contained in Append 8 of 10CFR73. Requests pre-workshop registration of attendees to facilitate sending out matl. Wencl Registration Form & List of Locations. MILLER, J. R. Assistant Director for Site & Safeguards (Pre 791030). 78/11/15. 5pp.
- 7812180279 Porwards Rev#1 "Draft Radiological Effluent Tech Specs" for BWR's(MUREG-0473) & "Preparation of Radiological Effluent Tech Bpacs for Nuc Pwr Plants" (NUREG-0133).

 9RIMEB.B.K. Assistant Director for Engineers & Projects (Pre 790623). 78/11/13. 6pp. 94337:023.
- 781127029: Forwards immediate action ltr(IAL) requesting subj facil not to resums welding on individual recirculation inlet nozzle piping weld joints until actions of IAL have been met. KEPPLER, J. Q. Region G. Chicago, Office of the Director. 78/11/17. 2pp. 94224-340.
- 7811290258 Informs NRC that sample location#97 is being dropped from environ monitoring prog, since milk animels are no longer

- 7812110007 Discusses possible dangers of LOCA in containment purging during normal plant oper Requests either commitment to limit purging or justicication for continuing Wiencl AND #7812CB0207 IPPCLITO, T Operating Reactors Branch 2 (Pre 790625). 78/11/29.6p0 94339 225
- 7812130234 Forwards summary of 781113 meeting w/util re-physical security inspecs at subj facil from Aug 1977-Aug 1978 Meeting summary w/held per 100FR2 790 KEPPLER, J.O. Region 3, Chicago, Office of the Director. 78/11/30, 2pp. 94309 337
- 7812120205 Notice of 781206 meeting to discuss IA Elec Light & Pur Coresponses to outstanding issues from 781114 meeting on repair prog for recirculation sys inlet noticle safe and at subj facil.

 CLARAIR J. Operating Reactors Branch 3 (Pre 790625). 78/12/04 2pp. 74276-035
- 7812140176 Forwards Oct 1978 Prog Activity Review listing meetings held & providing task-by-task activity summary for the month SOBON.L.J. General Electric Co. 787(2704 11pp
- 7812280167 Emphasizes importance of submitting accurate & complete info to NRC by licensee & applicants, Info submitted must be substantiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS. J O Deflice of Inspection & Enforcement. Office of the Director 78/12/04. 2pp. 94375.003
- 7812130136 Forwards rept"Duene Arnold Energy Ctr Recirculation Inlet Safe End Repair Prog. 781208" suppl rept submitted 780731.
 Replacement design stress rept seri.
 LIU.L. loue Electric Light & Power Co. 78/12/08. ip. 94295.001.
- --7812130140 "Duane Arnold Energy Ctr Recirculation Inlet Bafe End Repair Prog. 781208. " Suppl IE Repair Rept submitted on 780731. Repts purpose is to document info presented at 781114 meeting in Ceder Repids. IA. • Iowa Electric Light & Power Co. 78/12/08. 101pp. 94295:002.
- --7812130145 "Stress Rept Recirculation Inlet Norrie Bafe End Replacement at Duane Annold Nuc Plant." Incl:primary stress analysis, thermal analysis & primary plus secondary stress analysis. PARDUE, L. H. Jowa Electric Light & Power Co. 78/08/10. 200pp. 9495 108
- 7812210118 Confirms meeting on 781218 to discuss alleged welding deficiencies in repair work KEPPLER.J. O. Region 3: Chicago. Office of the Director. 78/12/08. tp. 94269.301.
- 7812270297 Forwards Bafety Analysis Review requested from GE to verify safety of reconstituted core. Informs that during shutdown subj facil experienced higher off-pes rates. Fuel sipping was performed & leaking bondles will be replaced.

 LIUIL. Idwa Electric Light & Power Co. 78/12/13. Ip. 94229:349.
- --781227030: Safety analysis review re Cycle 48 modified core. Mode do not involve unreviewed safety questions per iOCFR30, 59 & no Tech Bpec change needed.
 - * Iowa Electric Light & Power Co. 78/12/15. Bpp. 94229:350.
- 7812290130 Provides Environ Tech Spec Violation Rept #78-01: on 781211 a discharge of water from make-up demineralizer sys neutralizer tank began w/o tank first being sampled & ph was 12 1 due to incomplete maint work.

 HAMDOND.E. L. Iowa Electric Light & Power Co. 78/12/21. 2pp. 94190:214
- 7811210367 Forwards add1 info re multiple consecutive safety/relief walve actuation of Mark 1 containment program. SUBON, L. J. Openral Electric Co. 78/11/13. Spp.
- 7811210329 Submits questions re fluid mechanics at subj facil as a result of 781114 pub meeting in Ceder Rapids, IA. W/encl disprass from Ceder Rapids Dazette.
 PUGH R. Affiliation Unknown. 78/11/15. 2pp. 94484:314.
- G. Inspection reports, IE Bulletins & correspondence
- 7812060337 Forwards IE Insper Rept#30-331/78-17 on 780620-23, 780707 & 780711-3 during which no items of noncompliance were hoted. FIORELIE. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/06/27. 2pp. 94332:060.

- --7812060340 IE Inspec Rept#30-331/78-17 on 780620-23,780707 &780711-3 during which no items of noncompliance were noted Major areas inspected incliplant opers, leak records, pipe crack & core offloading.

 BHAFER.M. D. Region 3, Chicago, Reactor Operations Nuclear Support Branch. MENNING.J.E., WALKER.R. Region 3, Chicago, Office of the Director 78/06/27 Bpp.
- 7B10250216 Forwards IE Inspec Rept#50-331/78-18 on 780724-2& & Notice of Violation.
 FIDRELLIO Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/09/19. 3pp 94368:361.
- ~-7810250220 Notice of Violation from Inspec on 780705-0816. KNDP:R.C. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/09/19. lp. 94368:359.
- --7810230222 IE Inspec Rept#50-331/78-18 on 780705-0816 during which 1 item of noncompliance was noted: failure to maintain positive control over a high radiat area.

 KNDP.R.C. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/09/19. 7pp. 94370:331.
- 7811130004 Forwards IE Inspec Rept#50-331/78-21 on 780829-30 & Nobice of Violation.
 FIORELLI, O. Region 3, Chicago, Reactor Construction & Engineering Support Brench. 78/10/02. 2pp 94077:009.
- ~-7811130009 Notice of Violation from inspec on 780829-30.

 Region 3. Chicago. Office of the Director. 78/09/27. 1p. 94077:007.
- ~~7811130010 IE Inspec Rept#80~331/78-21 on 780829~30 during which I it of noncompliance was noted: failure to maintain adequate training records.

 MRICHTI-Q. C., LITTLE-N. B. Region 3, Chicago, Office of the Director, 78/09/27, 3pp. 94077:010.
- 7810300258 FOIA request for insec inspec rept of 780301 re subj facil. CONNOR.L. Affiliation Unknown. 78/10/04. 2pp. 94185:331.
- 7811210214 Forwards IE Inspec Rept#50-331/78-25 on 780829-31 & 780918-21 & Notice of Violation. FIORELLI-9 Region 3. Chicago, Reactor Operations Nuclear Support Branch. 78/10/12. 2pp. 94487:132
- ~-7811210216 Notice of Viplation from inspec on 780918-21.

 ** Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/10/12. 1p. 94487;134.
- --7811210220 IE Inspec Rept #50-331/78-25 on 780829-31.780718-21 & 26 & 27 during which 1 item of noncompliance was noted: failure to properly control design change packages.

 BHAFER.M.D., MALKER.R., JACKIM, I.W. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/10/10. 7pp. 94487:135.
- 7810230341 Forwards IE Circular#78-17, (See AND: 7810230221; Docket 50-313, 781013)
 KEPPLER, J. G. Region 3, Chicago, Office of the Director. 78/10/13.
 1p. 74167:039.
- 7810240112 Forwards responses to NRC request of 780522 for add1 info re insec inspec & testing prog & IELP request for relief from ABME Code requirements at subj facil.

 LIU.L. fowa Electric Light & Power Co. 78/10/13. 146pp.
- 7811150086 Forwards IE Inspec Rept#50-331/78-22 on 780803-04 & 780818-23 during which no items of noncompliane were noted. HEIBHMAN.R.F. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/10/13. 2pp. 94113:192.
- --7811500BB IE Inspec Rept#50-331/78-22 on 780803-04 & 780818-23 during which no items of nuncompliance were noted. Major areas inspected included: review of procedures dev for cutting & removal of facebuster recirculation noizles.

 KEY.W.J. Region 3. Chicago. Defice of the Director.

 DANIELSON.D.M. Region 3. Chicago. Reactor Construction & Engineering Support Stanch. 78/10/13. 5pp. 94113:194.
- 7811080002 Responds to 781002 NRC itr re deviation noted in Inspec Rept e50-G31/78-21. Corrective actions: training records updated & personnel instructed. Compliance targeted for 781020. MALLACE. J. A. Iowa Electric Light & Power Co. 78/10/19. 2pp. 94398: 001.
- 7811210018 Forwards IE Inspec Rept#50-331/78-23 on 780623.28-30, Q707, 11-12 & 17 during which no items of noncompliance were noted.

 MEIGHMAN, R.F. Region 3, Chicago, Reactor Construction & Engineering Bupport Branch. 78/10/19. 2pp. 94482:023.

- items of noncompliance were noted. Major areas inspected included: test of recirculation sys riser pipe crack(reactor vessel N2 no;rle sefe end)
 WILLIAMS, C. C., KEY, N. J. HARD, K. D. Region 3. Chicago. Office of the Director. 78/10/19. 22pp. 94482.025.
- --7811280032 IE Inspec Rept#50-331/78-23 on 780623 during which no items of noncompliance were noted Major areas inspected incl: nondestructive test activity of Licensee, See ANO-7811210018.
 WILLIAMS.C.C., KEY.W.J., WARD.K.D. Region 3, Chicago. Reactor Construction & Engineering Support Branch. 78/10/18. 22pp. 74480. 283.
- 7810310215 Ack receipt of 780929 ltr informing NRC of steps taken to correct violations noted in 780927 NRC ltr. HIND.J.A. Region 3. Chicago, Bareguards Branch. 78/10/24. ip. 94090: 320.
- 7811010353 Forwards insvc inspec rept & assor documents for subj facil in response to 781004 FOIA request. FELTON.J.M. Division of Rules and Records. 78/10/24. 2pp.
- 7811070231 Ack receipt of 780920 ltr & response to noncompliance item #2 of IE Inspec Rept#80-331/78-19: ancl discussion of corrective action is withheld from public disclosure. HIND.J.A. Region 3, Chicago, Bafeguerde Branch. 78/10/24. 2pp. 94039:148.
- 7811210090 Responds to NRC 1tr re violation noted in Inspec Rept #50-331/78-25 Corrective actions:new control method to better control & track design change packages routed thru site review & approval process.

 WALLACE J. A. Towe Electric Light & Power Co. 78/11/03. 2pp. 94482: 227.
- 7811150068 Forwards IE Circular 78-18.

 KEPPLER.J. 0. Region 3, Chicago, Office of the Director. 78/11/06.

 1p. 74112:264
- 7811200037 Ack receipt of 781019 ltr informing NRC of steps taken to correct violations noted during inspec. FIORELI, 0. Region 3. Chicaga. Reactor Operations Nuclear Support Branch. 78/11/08. ip. 94215:318.
- 7812140063 Forwards IE Inspec Rept#50-331/78-24 on 780919-22.26-29 & 1023-27 during which no items of noncompliance were noted. HEIGHMAN, R. F. Region 3. Chicago, Reactor Construction & Engineering Support Branch. 78/11/08. 2pp. 94127:340.
- ---7812140066 IE Inspec Rept#50-331/78-24 on 780919-22.0926-29 & 1023-27 during which no items of noncompliance were noted Hejor areas inspected incl: review of recirculation safe end repair procedures & observation of installation.

 KEY,M.J. DANIELBON.D.H. Region 3. Chicago, Defice of the Director. 78/11/06. 10pp. 94127:342.
- 7812120216 Forwards IE Inspec Rept#50-331/78-26 on 781004-06 & 18-20 during which no items of noncompliance were noted. FIORELLI Q. Region 3. Chicago. Reactor Operations Nuclear Support Branch. 78/11/09. 2pp. 94276:137.
- --7812120226 IE Inspec Rept#50-331/78-26 on 781004-06 & 18-20 during which no items of noncompitance were noted. Major areas inspected incl: previous noncompilance & outstanding inspec items & review of decontamination methods.

 8HAFER.W.D. Region 3, Chicago, Office of the Director.
 JACKIW, I.N., MILLER, D.E. Region 3, Chicago, Reactor Operations Nuclear Support Branch. 78/11/06. 8pp. 94276:139.
- 7812130129 Forwards IE Inspec Rept#50-331/78-28 on 780726-28,0818,0914, 0921,1002 & 1026, during which no items of noncompliance were noted. HEIBHMAN.R.F. Region 3, Chicago, Reactor Construction & Engineering Support Branch. 78/11/09. 2pp. 94307:196.
- --7812130134 IE Inspec Rept#50-331/78-28 on 780726-28 0819.0914.0921, 1002 & 1026, during which no items of noncompliance were noted Major areas inspected incl: licenses's metallographic studies of recirculation inlet nozzle safe and N2-A. WILLIAMB.C.C., KEY.W.J. Region 3, Chicago, Office of the Director. 78/11/09, 13pp. 94307:198.
- 7812010093 Ack receipt of 781103 ltr informing NRC of step taken to correct violations noted during inspec & discussed in 780929 ltr. Also submits info re review of forms NRC-741 & 742. KEPPLER J. Q. Region 3. Chirago. Office of the Director. 78/11/16. 2pp. 94416:144.

- 7811280480 Ack receipt of 781103 ltr informing NRC of steps taken to correct noncompliance noted in NRC ltr of 781012. FIDRELLI, 9. Region 3. Chicago, Reactor Operations Nuclear Support Brench. 78/11/20. Ip. 94381:346
- 7812050282 Forwards IE Bulletin#78-12A.suppl to IE Bulletin 78-12. W/encl AND: 7811300055. KEPPLER, J. G. Region 3, Chicago, Office of the Director 78/11/24 ip. 94202:288
- 7812200323 Ack receipt of 780803 ltr informing NRC of steps taken to correct violations noted during inspec#50-331/78-19. Encl withheld from disclosure.

 HIND J. A. Region 3. Chicago, Safaguards Branch 78/12/14. jp. 94082-105.
- 781R280052 Forwards IE Bulletin 78-14.
 KEPPLER, J. G. Region 3, Chicago, Dffice of the Director. 78/12/19.
 19. 03554:356.
- R. Periodic operating reports & related correspondence
- 7810200061 Forwards Monthly Oper Rept for Sept 1978
 MAMMOND.5.L. Iowa Electric Light & Power Co. 78/10/11. ip.
 94419: 191.
- ~-7810200063 Monthly Oper Rept for Best 1978
 VAN SICKEL J. Towa Electric Light & Power Co. 78/10/11. 6PP
- 7811210390 Forwards monthly Oper Rept for Oct 1978 HAMMOND.E.L. Towa Electric Light & Power Co. 78/11/13 ip. 94486-041.
- --7811210394 Monthly Open Rept for Oct 1978.

 VAN BICKEL/J. I Towa Electric Light & Power Co. 78/11/13. 79p. 94486:042.
- 7811280237 Corrects semigenousl rept for 3rd & 4th quarter, 1977, Percent of environ tech specs for gaseous efficients during that time should be changed to X of 16X limit: 5.63% third quarter & 6.63% 4th quarter.

 HAMMOND, E. L. IDWE Electric Light & Power Co. 78/11/17. 1p. 94012: 142.
- 7812190137 Forwards Monthly Open Rept for Nov 1978.

 HAMMOND, E. L. Towa Electric Light & Power Co. 78/12/14. 1p. 94340; 291.
- --7812190139 Monthly Oper Rept for Nov 1978. VAN BICKEL, J. Towe Electric Light & Power Co. 78/12/14. 6pp. 94340-252
- B. Reportable occurrences, LERs & related correspondence
- 7811270160 Notifies NRC of Reportable Occurrance on unspacified date: during inspec of drywell to determine source of unidentified leak leak was discovered in recirculation loop inlet notifie & plant was placed in cold shutdown.

 HAMOND.E.L. lows Electric Light & Power Co. 78/06/19. ip. 94222:356.
- 7811270148 Forwards LERW78-030/01T-0. MAMMOND.E.L. Towe Electric Light & Power Co. 78/06/30. ip. 94271:360.
- --7811270180 LER#78-030/017-0 on 780617: water leak found in area of "B" recirculation sys NGA inlet noizle caused by well crack in noizle safe end. Lab analysis will be performed to determine cause of cracking.

 VANSICKEL, J. lows Electric Light & Power Co. 78/06/30. 2pp. 94271: 361.
- 7810230152 Repts abnormal occurrence event per 42FR10950 et subj facili major degradation of primary coolant pressure boundary in boiling water reactor resulted from crack in fitting that joins recirculation pipe to reactor vessel. CHIU. B. J. Office of the Secretary of the Commission. 78/08/02. 6pp. 94194:345.
- 7Bi01i0141 Reports on violation of Environ Tech Spec 3.3.1.8.2 of subj facil. Open LiceDPR-49.00 780925 discharge of radioactive liquid effluent was begun prior to completion of sample analysis. Approx 500 gallons were discharged.

 HANNOND.E.L. Iowa Electric Light & Power Co. 78/10/04. 2pp. 94064:274.

- 7810310227 "Metallurgical Investigation of Cracking in a Reactor Vessel Nosile Bafe-End. SHRI Proj 02-5389-001. Interim Rept 781020 "Tests & examinations performed inclusivasonic inspec of safe-end. chen analyses of safe-end & thernal sleeve.
 BURGHARD. H C Towa Electric Light & Power Co. 78/10/20. 52pp.
 94009-113
- 7811280204 Forwards LER#78-020/017-1 HAMMOND.E. L. Towa Electric Light & Power Co. 78/11/20. 1p. 94013-262
- --7811280205 LER#78-020/017-1 on 780405 bearing out-of-alignment & rotated sufficiently to shear bearing dowel pin.Caused by lack of lubrication. Valve line-up procedure changed. VAN BICKEL J. Iowa Electric Light & Power Co. 78/11/17. App. 94013: 265.
- 78:2050136 Forwards suppl. "Hardness Data", to 78:020 rept by BW Res Inst#32-3389-991, "Metallurgical Investigation of Cracking in a Reactor Vessel nor:le safe-End Interim Rept." LIUL. Toue Electric Light & Power Co. 78/11/27. Bpp. 94335.086.

DOCKET 50-332 BARNWELL REPROCESSING PLANT

- A. Application/construction stage documents & correspondence
- 7812180147 Requests that Constr Permit CPC8F-4 for Separations Facil be estended to 811231.
 BAXTER.R.C. Allied General Nuclear Bervices. 78/11/09. 3pp. 94365:224
- 7812180144 Forwards add1 copies of 781109 request for extension of completion date under Constr Permit CPCSF-4. BAXTER.R.C. Allied General Nuclear Services. 78/11/14. 2pp. 94363-239
- Q Inspection reports. IE Bulletine & correspondence
- 7811130009 Forwards Inspec Rept#50~332/78-4 on 780822-25 during which no items of noncompliance were noted.
 BUTHERLAND, J. T. Region 2. Atlants. Fuel Facility & Materials Safety Branch. 78/09/29. 2pp. 94075:291.
- --781130014 IE Inspec ReptM50-332/78-4 on 780822-25 during which no items of noncompliance were noted Areas inspected include review of demonstration run in progress, review test procedures, audit prog & facil mod records POTIER, J.P., CORYELLO, P. Repton 2, Atlanta, Fuel Facility & Materials Safety Branch. 78/09/28, 5pp. 94075:293.
- 7811090266 Forwards IE Inspec Rept#50-332/78-03 on 780906-07 during which no items of noncompliance were noted. MRPRYC.E. Region 2. Atlants. Reactor Construction & Engineering Support Branch. 78/10/02. 2pp. 02729: 339.
- --7811090259 IE Inspec Rept #50-332/78-05 on 780906-07 during which no items of noncompliance were noted Major areas inspected inclippergency dissel generator, ventilating blowers. & fuse Pailures in starters.

 HUNIND.: BRYANT, J.C. Region 2. Atlanta: Reactor Construction & Engineering Support Branch. 78/09/29. 3pp. 02729:341.

DOCKET 50-333 JAMES A. FITZPATRICK NUCLEAR POWER PLANT

- 78[1701]0 Forwards analysis by Teledyne Engr Svc re Multiple consecutive safety relief valve actuation evalues requested by NRC on 78[0]8. EARLY P. J. Power Authority of the State of New York. 78/11/14. 11pp. 94047; 120.
- F. Becurity, medical, emergency & fire protection plans
- 7810270149 Forwards responses to NRC steff concerns/positions re fire protec. Futher responses will be submitted in Nov 1978. EARLY.P.J. Power Authority of the State of New York. 78/10/23. 78p. 94037:009.
- 7811070126 Forwards responses to Enc184 of 780922 NRC 1tr re-fire protec prog at subj facil. Reply to Enc183 will be submitted by Nov 1978 QRONBERG.N.L. Power Authority of the State of New York. 78/10/27. 3pp. 94038:305.

- 7812290140 Forwards responses to 780922 NRC itr Enci #3 r# Staff positions on fire protec prog. Responses to Enci#2 & #3 of 780922 NRC itr were submitted to NRC on 781023 & 781027. EARLY.P. J. Power Authority of the State of New York. 78/12/21. 4pp. 94190:274.
- 9. Adjudicatory correspondence
- 7810300275 Forwards request for hearing pursuant to Section 2. 105(d)(1) of the rules of practice of NRC & notice of proposed issuence of amond to facil oper lic issued 780901 % noticed in 43FR40580-B1(1978).
 CABBAN.V. J. Power Authority of the State of New York. 78/10/02.
 1p. 94271:068.
- --7810300280 Request for a hearing re appl for Facil Oper Lic Amend fill 780726. Util would urge relief requested in appl be granted. Appl would auth increase in spent fuel storage capacity. Amend would revise design features & oper limits. BENNETT.L.R. Power Authority of the State of New York. 78/10/06 29p. 74271.069.
- P. Operating license stage documents & correspondence
- 7810200204 Notice of Issuance of Amend#38 to Facil Oper Lic#DPR-89. Revises Tech Specs re radioactive protection reduction of squib charge batch size for surveillance testing & miscellaneous changes to correct errors in present specs. IEPOLITO, 1. A. Operating Reactors Branch 3 (Pre 790623). 78/07/20. 2pp. 94367:081
- 7810110105 Responds to 771209 ltr re subj facil suppression pool temperature transients & monitoring sys. Forwards proposed analysis cases & description of present sys. GRONBERG.M.L. Power Authority of the State of New York. 78/09/29. 18pp. 94069:179.
- 7810120055 Buby reactor protects as pur supplies were evaluated as requested by NRC 780807 ltr.& interim surveillance measures were effected but PABN believes that continuation of such measures or nod of pur supplies is unwarranted.

 EARLY, P. J. New York, State of 78/10/06. 3pp. 94471:351.
- 7810170175 Provides add1 info re Analog Transmitter/Trip Unit 8ys as requested by phone 780905. Provides transmittor vendor name & model s. divisional separation criteria: cebinet layout environ & seismic qual & interconnection diagram. EARLY.P. J. Power Authority of the State of New York. 78/10/10. i2pp. 94236:300.
- 7810180075 Requests oper lic emends be made effective 21 days after date of issuance. Buggests special communications when amend requimmediate or other rapid action.

 EARLY, P. J. Power Authority of the State of New York. 78/10/11.

 Rpp. 74422:046.
- 781017010B Forwards proposed changes to Tech Spec for facil Cycle 3 oper re Reloed #2. Startup is scheduled for 781113. EARLY,P. J. Power Authority of the State of New York. 78/10/13. 2pp. 94234:278.
- --7810170111 Appl for Amend to Oper Lic DPR-59 changing Tech Spec re Raised Sefety/Relisf Valve Setpoints for facil reload#2 EARLY, P. J. Power Authority of the State of New York. 78/10/13. Spp. 94234:280.
- --7B10170114 "Raised Esfety/Relief Valve Setpoint Reenelysis for Subj Facil for Reload M2". Provides results of reanalysis of the most limiting thermal & pressurization transients. 7LL.L.H. General Electric Co. NEDO-24127-1 801. 78/09/30. 12mo. 94234:288.
- 7811010111 Responds to 780601 NRC ltr re results of Comm Bafety evel util's proposed reduction of frequency of control rod scram time surveillance requirements. Plans to respond w/further justification by 790301. EARLY,P. J. Power Authority of the State of New York. 78/10/24. 3pp. 94301:359.
- 7811130335 Summary of 780914 meeting w/GE representatives & Mark 1 Owners Group re-progress of Long Term Prog w/attendance list & agenda(RD-9-A-Markl, Standards.) ORIMES.C. Plant Systems Branch (Pre 791030). 78/10/26. 67pp.
- 7811130299 Finds 780901 proposed Tech Spec changes acceptable. LAIMAS.G. Plant Systems Sranch (Pre 791030). 78/11/02. Ppp.

- --7811130301 Bafety Evel of proposed changes to Tech Spec re Battery Surveillance Test for subj facil. Finds changes acceptable.

 Plant Bystems Branch (Pre 791030). 78/11/02. 1p. 94086:113.
- 7811270243 Forwards Amend#40, BER & Notice of Issuence of mod to Tech Brecs to proposed use of motor operated valves for containment isolation in HPCI.RCIC.LPCI & the Core Spray Sys & air operated check valve surveillance requirements. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/09. 2pp. 94199:184.
- --781127024A Amend#40 to Facil Oper Lic re mod of Append A & B Tach Space related to proposed use of motor operated valves & addition of air operated check valve surveillance requirements. IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790693). 78/11/09. 22pp. 94199:186.
- --7811270250 SER in support of AmendW40 to oper lic.Concludes that amend does not involve significant hazards consideration.essures that publ health & safety will not be endangered.complies w/s11 NRC regs. Operating Reactors Branch 3 (Pre 790625). 78/11/09. 4pp. 94199: 208
- --7811270253 Notice of Issuance of Amend#40 to Fecil Oper Lic#DPR-59. Rev Tech Specs as leak rate testing requirements for sys which penetrate containment boundary & are connected to reactor penetrate containment doubles y a literature content of (Pre 790625). 78/11/09. IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). IPPOLITO, T. A. Op Pop. 94199: E11.
- 78i1290298 Responds to 78i106 request for info concerning licensee reg performance evel for Region I plants by NRC Provides details. GRIER 8.N. Region I. Philadelphia, Office of the Director. 78/11/09. 9pp.
- 7811160069 Provides responses to 780913 NRC request for add1 info re Tech Spec changes & deletion of APRM trip in REFUEL mode. EARLY,P.J. Power Authority of the State of New York, 78/11/13. 300. 94133:136.
- 7812180028 Notice of workshops re implementation of training & qual requirements contained in Append B of 10CFR73. Requests pre-workshop registration of attendess to facilitate sending out mat. H/encl Registration Form & List of Locations.

 MILLER.J. R. Assistant Director for Bits & Befaguards (Pre 791030). 78/11/15. 5pp. 94130: 345.
- 7812180270 Forwards Rev#1 "Draft Radiological Effluent Tach Spacs" for BRR's(NUREG-0473) & "Preparation of Radiological Effluent Tech Specs for Nuc Per Plants" (NUREG-0133). GRIMES,B.K. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. App. 94366:073.
- 78:128029: Forwards results of Gen Elec Co analysis of rotated bundle loading error syent Transmits original Tack Bace regarding Cycle 1 off-gas radiat monitor & new Minimum Critical Pur Ratio Oper Limit for BXOR fuel W/atts.

 EARLY, P. J. Power Authority of the State of New York. 78/11/16. 6pp. 94398; 248,
- 7812050336 Forwards Amend#41 to Facil Open Lic#DPR-59 for subj facil. Amend changes Tech Specs as requested in 780901 ltr. Wisafety Evaluation & Notice of Issuance. IPPOLID. T.A. Operating Reactors Branch 3 (Pre 790623). 78/ Operating Reactors Branch 3 (Pre 790625). 78/11/16. 2pp. 94409: 012.
- --7812050343 Amend#41 to Facil Open LicHDPR-59 revising Tach Space of subj facil re surveillance requirements for discharge secting performed on Station Batteries & on LPCL Motor Operated Valve Pur Supplies to reflect type testing. IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. Spp. 94409:014
- --7812050348 Safety Evaluation Supporting Amend#41 to Facil Oper Lic MDPR-59 concluding that proposed changes to Tech Space are acceptable & safety of public will not be endangered.
 4 Office of Nuclear Reactor Regulation, Director. 78/11/16, 9pp. 94409:022.
- --7819050351 Notice of Issuance of Amend#41 to Fecil Oper Lic#OPR-59, IPPOLITO.T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/16. Rpp. 94409/094.
- 7811210300 Responds to 780913 request for add1 info re proposed changes to Tech Spece, Reload 2 Licensing Submittal for Cycle 3 operation, w/47 oversite drawings available in Central Files. EARLY, P. J. Power Authority of the State of New York. 78/11/17. 22pp. 94488: 105.

- 7811300376 Informs PASM that NRC has contracted w/Mountain West Res Inc psiducuse informs PABN that NRC has contracted w/Mountain Meet R to undertake a series of post-licensing atodies of nuc pur stations. Studies will analyze socioecon impacte which occurred during constr & post-constr periods of each plant. DEYQUNG.R.C. Division of Site Safety & Environmental Analysis. 78/11/20. Epp. 94136: 249.
- 7812070197 Notice of seminer on 791208 on new Model Radiological Effluent Tech Baccs for nuc pur plants, Requests advence submission of seminer specific questions. W/encl Beminer Info Sheet, Proposed Agenda & maps. GRIER, B. H. Ragion I. Philadelphia. Office of the Director. 78/11/21. 8pp. 94375:081.
- 781R080168 Forwards Amend#4R to Open Lic#DPR-99, Changing Tech Specs to reflect installation of Analog Transmitter/trip Unit Sys. Bafety Eval & Fed Register Notice. IPPOLITO T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/22.
- --7812080170 Amend#42 to facil Oper Lic#DPR-59.changing Tech Especa to reflect installation of Analog Transmitter/Trip Unit Bys. IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 790625). 78/11/22. 5pp. 94105: 288
- ---7812080173 Safety Eval Supporting Amend#42 to Facil Oper Lic#DPR-59. Finds proposed amend will not be inimical to common defense & security. Operating Reactors Branch 3 (Pre 790625). 78/11/22. 3pp. 94106: 293.
- 7812110319 Forwards recently issued Amend 43 to License DPR-59. safety evaluation & notice of issuance. Hes not approved APRM and BRV mods approved on interim basis sustting final resolution of Mark I Containment long term program.

 IPPDLITOIT, A. Operating Reactors Branch 3 (Pre 790625). 78/11/22. 300. 94204: 159.
- --7812110320 Amend 43 to License DPR-39, revising Tech Speca re-safety relief valve-analog transmitter/trip unit sys to reactor protection sys. & relief mode.

 IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625). 78/11/22. 45pp. 94204; L62.
- --7812110322 Safety Evaluation supporting Amend 43 to License DPR-59.

 ** Operating Resectors Branch 3 (Pre 790625). 78/11/22. 11pp.
- --7812110323 Notice of Issuence of Amend#43 to Operating Lic#UPR-89. IPPOLITO, T. A. Operating Reactors Branch 3 (Pre 79062B). 79/11/22. 2pp. 94204:218.
- 7812180310 Confirms that meeting will be held at Region I office. King of Prussis. PA on 781130, to discuse certain requirements of util's radiat protec prog conducted per LiceDPR-59.

 ORIER. B. H. Region 1. Philadelphia. Office of the Director. 78/11/24. 19. 94356: 260.
- 7812110046 Discusses possible dangers of LOCA in containment purging during normal plant oper. Requests either commissioners purging or justification for continuing. W/encl ANO: #781208007.

 IPPOLITO. T. Operating Reactors Branch 3 (Prs 790625). 78/11/89.
- 7812110183 Forwards summary tabulation of control rods failing to full insert during reactor scram for calendar year 1977, per NRC ltr of 780829. Rept of drives replaced during current refueling outage included in Oct 1978 Monthly Rept. EARLY, F. J. Power Authority of the State of New York, 78/12/04. 2pp. 94393: 279.

74408: 200.

Өрр.

- 7812140175 Forwards Oct 1978 Prog Activity Review listing meetings held to providing task-by-task activity summary for the month. 8080N-L.J. General Electric Co. 78/18/04. http://doi.org/10.1000/10.1000/10.1000/10.1000/10.
- 7812120080 Forwards QE Rept NERDO-24129-2 Suppl 2, "Fuel Bundle Loading Broom Re-enalysis for JA Fitzpatric Nuclear Power Plant for Reload E: " dtd Nov 1978, EARLY, P.J. Power Authority of the State of New York. 78/12/06. 1p. 94274:115.
- --7812120082 "Fuel Bundle Loading Error Reanalysis for the JA Fittpetr. Nuc Pur Plant for Reload 2. Suppl 2. " ZULL.L.M., BRUGOE,R.D. General Electric Co. NEDO-24129-2 809. 78/11/30. lipp. 94274; ii.6.

- 7812140276 Forwards pages for Amend#43 to Facil Oper Lic DPR-59 that were inadvertently omitted IPPOLITO. I A Operating Reactors Branch 3 (Pre 790625). 78/12/06.5pp 03557 319.
- 7812280095 Emphasizes importance of submitting accurate & complete info to NRC by licensees & applicants info submitted must be substantizated by data & calculations. Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIS.J O Dffice of inspection & Enforcement. Office of the Director 78/12/06 2pp. 03555:313.
- 7812190114 Requests immediate temporary waiver of Tech Specs re leak for the "A" main steam isolation valve to allow plent oper at full pur rather than reduced load w/one main steam line out of svc EARLY/P.J. Power Authority of the State of New York. 78/12/12. 5pp. 943B1.202.
- 7812260189 RO 78-151 on 781215: switches aesoc w/detection of HPCI turbine /stess line area high temp set erroneously due to personnel error. Cautionary warning placed on surveillance procedure to indicate proper conversion table LEDWARD, U.D. Power Authority of the State of New York. 78/12/18. 1p. 94139 158
- 7811210367 Forwards add1 into re-multiple consecutive mefety/relief valve actuation of Mark I containment program.
 8090N.L.J. General Electric Co. 78/11/13 3pp.
- 781:210389 Forwards response to NRC's request for add1 info reinstallation of Amalog Transmitter/Trip Unit Sys(ATTUB). Info supports Appl for Amend to 780810 oper Lic suppl by 781010 Info EARLY.P.J. Power Authority of the State of New York. 78/11/16. App. 94483-356.
- G. Inspection reports, IE Bulletins & correspondence
- 7811080172 Forwards IE Inspec Rept#50-333/78-15 on 780828-31 during which no items of noncoepliance were noted. MARTIN.N Q. Region 1. Philadelphia, Sefeguards Branch. 78/09/20. 2pg. 94379:354
- --7811080177 IE Inspec Rept#50-333/78-15 on 780828-31 during which no items of noncompliance were noted. Major ereas Inspected included: security plan & organization, access controls: communications: detection adds: Response Procedures.

 MADDEN.M.J., LADUN, R.H. Rejion 1, Philadelphia, Bafaguards Branch. 78/09/18, 1p. 94399:356.
- 7811060171 Forwards IE Circular#78-17. (See ANO: 7810230221. Docket 850-133. 781013.)
 ORIER, B.H. Region 1, Philadelphia, Office of the Director. 78/10/13 1p. 94489: 092.
- 7812010034 Forwards IE Inspec Rept#50-333/78-20 on 780927-29 during which no items of noncompliance were noted.
 8MITH-0-M. Region 1. Philadelphia. Fuel Facility & Naterials Sefety Branch. 78/10/20. 2pp. 94416:070.
- --7812010036 IE Inspec Rept#50-333/78-20 on 780927-29 during which no items of noncompliance were noted. He or areas inspected incliprog for quality control of analytical measurement, audit results & effluent control procedures.
 RCTTAN.J.J. STOHR.J.P. Region i, Philadelphia, Fuel Facility & Haterials Bafety Branch. 78/10/19. 8pp. 94416:072.
- 7812060365 Forwards 1E Inspec Rept#50-333/78-22 on 781004-6 during which no items of noncompliance were noted.
 BRUNNER.E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/27. 2pp. 94382:323.
- --78120à00à7 IE inspec Rept850-333/78-22 on 781004-à during which no items of noncompliance were noted Major areas inspected incl:leak testing & procedures.previous inspec findings, plant mode.pumpe & valves.action on IE pubs.
 H1001N8, J. C., BMITH.T. H., MDNG.H. D. Region 1. Philadelphia.
 Reactor Operations Nuclear Support Branch. 78/10/27. 10pp.
 94382:325
- 7811290195 Forwards IE Circular #78-t8."UL Fire Test. "W/enci AND: 7811150002.

 QRIER.B.H. Region i. Philadelphia, Office of the Director. 78/11/06. 1p. 94239:290.
- 7812270493 Forwards IE Inspec Rept#50-333/78-18 on 780918-22 & 1003-06 & 1011-13 during which no items of noncompliance were noted. CARLBON.R. T. Region I. Philadelphia, Reactor Construction & Engineering Support Branch. 78/11/13. 2pp. 94015:339.

- --7812270457 IE Inspec Rept#50-333/78-18 on 780918-22 % 1003-06 % 10%1-13 during which no items on noncompliance were noted Major areas inspected incl:inspec activities & activities areas w/removal of freedwater spargers.

 MCBREARTY, R. A. EBNETER, B. D. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 78/11/08. 10pp. 74015:241.
- 7812180034 Forwards IE Bulletin#78-12A-Suppl to 1E Bulletin 78-12. W/encl AND 7811300035. GRIER, B.H. Region I. Philadelphia. Office of the Director. 78/11/24. 1p. 94133:019
- R. Periodic operating reports & related correspondence
- 7810130128 Forwards Honthly Open Rept for Sept 1978. LEDMARD.J. D. Power Authority of the State of New York. 78/10/05. 19. 03555:270.
- --7810130132 Monthly Open Rept for Bept 1978. ZUFELT, E. Power Authority of the State of New York. 78/10/05. 4pp. 03555:271.
- 7813140121 Forwards Monthly Oper Rept for Oct 1978. LECHARD J. D. Power Authority of the State of New York. 78/11/10. 1p. 94425:211.
- --7811140123 Monthly Oper Rept for Oct 1978. ZUFELT, E. Power Authority of the State of New York. 78/11/10. 11pp. 94425:212.
- 7812150267 Forwards Monthly Open Rept for Nov 1978. LEGMARD J. D. Power Authority of the State of New York. 78/12/09. 1p. 94213:062.
- --7812150274 Monthly Open Rept for Nov 1978.

 ZUFELT, E. Power Authority of the State of New York. 78/12/09.
- B. Reportable accurrences. LERs & related correspondence
- 7810100022 Forwards LER#78-079/04L-0. LEDMARD.J. D. Power Authority of the State of New York. 78/10/03. 19. 94033:008
- --7810100026 LER#78-079/04L-0 on 780914: An apparent excessive solute release from Makaup Mater Treatment Maste Neutralizer tanks to Circulating water Dischergs Turnnel was detected while performing Aug 78 24-hour complete sample enalysis.

 CHILDS: M. V. Power Authority of the State of New York. 78/10/03. 3pp. 94033:009.
- 7810120045 Forwards LER#78-080/03L-0.
 LEONARD, J. D. Power Authoryty of the State of New York. 78/10/06.
 1s. 94322:334.
- --7810120046 LER#78-080/03L-0 on 780714: Resilient seels on valva covers (bonnets) & both ends of oper shefts in pressure suppression chamber were not subjected to "Type B" local leak rate tests as required by Tech Spec Append A. 4. 7. A. 2. d. 2. CHILDS. W. V. Power Authority of the State of New York, 78/10/06 Spp. 94332:325.
- 7810120072 Forwards LER#78-081/03L-0. LEONARD.J. Power Authority of the State of New York. 78/10/06. 1p. 94472:326.
- --7810120079 LER#78-081/03L-0 on 780915:circuit breaker for RHR pump 10-P 10-P-3C would not "charge." Caused by bending of control pur fuse holder causing pump circuit breaker not to make contect.

 CHILDS.M.V. Power Authority of the State of New York. 78/10/06. RPP. 94472:327.
- 7810230186 Forwards LERW78-075/03L-1. LEOMARD.J. D. Power Authority of the State of New York. 78/10/18. 1p. 94195:152.
- --7810230189 LER#78-075/03L-1 on 780902: during surveillance test F-BT-30. normally closed inboard core spray injection valve 14-MOV-128 failed to open electrically & made 1 core spray ays inopen due to high differential pressure. CHILDS.W.V. Power Authority of the State of New York, 78/10/LG. 2pp. 94193:153.
- 7810230263 Forwards LERW78-082/03L-0, LEOMARD.J. D. Power Authority of the State of New York. 78/10/19, 19. 74271:151.

- --7610230265 LER#78-082/03L-0 on 780920: in refuel thutdown.pressure suppression pool(tarus)level increased to 0.8 inches above Tach Specs level.due to waterleeking past seat of safety relief valve.

 CHILDS.W.V. Power Authority of the State of New York. 78/10/18. 2pp. 94271: 152.
- 7810230308 Forwards LER#78-056/03L-1.

 * Power Authority of the State of New York. 78/10/16. 1p. 74166: 344.
- ---7810230310 LERW78-056/03L-1 on 780722: Core spray sys outboard isolation valve would not close due to fact that limitorque oper shaft key was sheared. Key was sheared CHILDS, M. V. Power Authority of the State of New York. 78/10/19 2pp. 94166:345.
- 7810240122 Forwards LER878-084/03L-0.
 LEGNARD, J. D. Pawer Authority of the State of New York. 78/10/19.
 in
- --7810240126 LERW78-084/03L on 780924; During refueling shutdown & discharge of "B" floor drain sample tank the Liquid Redweste Effluent Monitor sample pump would not deliver adequate flow to monitor due to clogging.

 * Power Authority of the State of New York. 78/10/19. 2pp.
- 7810240133 Forwards LERW78-083/03L-0. LEONARD, J. D. Power Authority of the State of New York. 78/10/19.
- ---7810240139 LER#78-083/03L-0 on 780923; during refusling & meint shutdown the logic pur for the "B"LPCI subsys was deenergized.due to operator error.

 CHILDS.W. V. Power Authority of the State of New York: 78/10/19.
 200.
- 7811070244 Forwards LER878-083/04L-0. LEDNARDJ D. Power Authority of the State of New York. 78/11/02. 1p. 74039:176.
- ---7811070248 LER878-085/04L-0 on 781006: Rept level per Tech Spec Append B Paragraph 2.3.8.5. was exceeded for third quarter of calendar year. July high release rate caused by iteem leaks & fuel pin cled perforation. Corrective actions: refueling & repair. Power Authority of the State of New York. 78/11/01. 2pp. 94039: 197.
- 7811070318 Forwards LERW78-087704T-0. LEOWARD. JD. Power Authority of the State of New York. 78/11/01, 1p. 94041:165
- --7911070323 LER#78-087/04T-0 on 781018: Environ Radiological Monitoring Bampla of pariphyton samplas pCi/pm(Wathdoes not meet subj facil Tech Bpac Append B.Paragnaph 3.6.2.6. CHLD8: M.V. Power Authority of the State of New York. 78/11/01. 2pp. 94041: 166.
- 7811140238 Forwards LERM78-086/03L-0. LEONARD.J.D. Power Authority of the State of New York. 78/11/10. 1p. 94400:093.
- 7811210414 Forwards LER#78-088/04L~O. LEONARD.J. D. Power Authority of the State of New York. 78/11/17. 19. 94483;128.
- ---7811210422 LERW78-088/04L-0 on 781024: excess solute release from Makeup Hater Treatment Waste Neutralizer Tanks to Circulating Hater Discharge Tunnel detected, Caused by unsound sampling & method of determining concentrations & dissolved solids. CHILDS.W.V. Power Authority of the State of New York. 78/11/17. 3pp. 94483:129.
- 7812040156 Forwards LERW78-089/03L-0. LEDMARD.J. D. Power Authority of the State of New York. 78/11/28. 1p. 9456:123.
- --7812040157 LERM79-089/03L-0 on 781101: during refueling & meint shutdown it was found that surveillance test had not been performed for combustion fonication products smoke detectors installed in diesel fire pump room on 780310, due to oversight. CHILDE,N.V. Power Authority of the State of New York. 78/11/28. 2pp. 94456-124.

- 7812070174 Forwards LER#78-090/03L-0. LEDMARD, J. D. Power Authority of the State of New York. 78/12/05. ip. 94375:020.
- ~-7812070178 LERW78-090/03t-0 on 781106 supply to part of safety relate hose stations in Reactor Bldg was shut off making stations inoparable Caused by intentional isolation to permit installation of add post indicator valve.

 CHILDS.N V Power Authority of the State of New York. 78/12/05.

 1p 94375:021.
- 7812220099 Forwards LERW78-085/04X-1. LEOMARD.J.D. Power Authority of the State of New York. 78/12/18. 1p. 94343.349.
- --7812220100 LERM78-085/04X-1 on 781006: 3rd quarter release of Halogen particulates greater than Tech Specs. Caused by steem leaks the fuel pin clad performance. CHILDS.W. V. Power Authority of the State of New York. 78/12/18. 2pp. 94343: 350.
- 7812290246 R0878-097/01x-0:during surveillance of Temp switches, instrumers found set above Tech Spec limit due to personnel using wrong conversion table.

 LEONARD, J. D. Power Authority of the State of New York. 78/12/18.

 1p. 94191:282.
- 7812270242 Forwards LERM78-094/03L-0. LEONARD, J D. Power Authority of the State of New York. 78/12/20 ip. 94017:152.
- --7812270250 LERE78-094/03L-0 on 781122: during shutdown & surveillance test.a number of bettery calls were found w/specific gravity k/or individual cell voltage variations(high or low) greater than allowed by Test acceptance criteria.

 CHILDS.N. V. Power Authority of the State of New York. 78/12/20.

 220. 94017:153.
- DOCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

 F. Becurity, medical, emergency & fire protection plans
- 7812120227 Forwards results of 781030-781103 eite visit & NRC staff positions concerning auby facil fire protec prog. Requests comments & implementation sched. BCH-ENCER, A. Operating Reactors Branch 1 (Pre 790625). 78/12/01. 30pp. 94277: 142.
- 78:2140:09 Forwards edd1 info requested in 7807:18 NRC itr re fire Frotec prog. Subj covered incl: combined fire & security emergency personnel. failure analysis, suppl fire dept. & in-house audit plan.

 MOCLEVER.E. J. Duqueene Light Co. 78/12/11. 164pp. 94:19:163.
- 7812190144 Forwards Figure 1 inadvertently left out of 781211 Fire Protec Prog. WOOLEVER.E.J. Duqueane Light Co. 78/12/15. 2pp. 94381:034.
- O. Advisory Committee on Reactor Bafeguards reports & correspondence
- 7812060424 Notification of 780907-09 open meeting of ACRB (changed fro 780823) in Washington DC to discuss failure of subj facil main transformer. FFTF. & evaluation of SWAH-1400. HDYLE. J. C. Office of the Becretary of the Commission. 78/08/25. 5pp. 94383:045.
- 7812070094 Responds to 780828 request for clarification re ACR8 recommendations made between 770101 & 0930. Forwards clarifying info.

 CASE E. O. Office of Nuclear Reactor Regulation, Director, 78/11/28 44pp. 94274-022.
- P. Operating license stage documents & correspondence
- 7812030004 Forwards Licenses Performence Evel Questions for subj facilin response to 771183 request. Feels it is possible that dev of statistical methodology for such evel may not justify the effort Qualitative evel may be as good Urges 1-year test. QRIER, B.H. Region 1, Philadelphia. Office of the Director. 77/12/13. 12pp.
- 7810110144 Forwards proposed Tech Specs for Overpressure Protec per NR 780828 request. No fee encl should be considered as part of the original submittal which predates fee schedule requirements of 100FR170.82s.

 DUNN C.N. Duquesne Light Co. 78/10/04. 12pp. 94054:880.

- 7810180072 Encl \$12,300 youther for license fee omitted in 780922 appl for change to Append A Tech Specs.
 DUNK C N Duquesne Light Co. 78/10/11, ip. 94421.263.
- 7810200100 Forwards Proposed Teth Specs 3.1.2 3 & 3.4.1.4 correcting submittal of 781004, which Palled to include required action statements & surveillance requirements burnellance requirements DUNN&C.N Duquesne Light Co. 78/10/16. 4pp. 94367:347.
- 7810200047 Forwards copy of Chlorine Trailing-Dut Study Results. MODRE.0 H Duqueane Light Co. 78/10/17. ip. 94411:330.
- --7810200050 Submits results of chlorine trailing-out study. Concludes that trailing-out beyond 2 hours per day does occur, but that permit limitations are not exceeded. Chlorination level is reg to prevent blo-fouling of condenser.

 MCALLISTER.R.J. Duqueene Light Co. 78/07/20. 17ap. 94411.331.
- 7810270195 Enrwards requested info on tabulation of mass & energy release data by Westinghouse Provides proposed Tech Specs rev 100 gal increase in refueling water storage tanks.

 BUNN C.N. Duquesne Light Co 78/10/24 Sp. 94054: 242.
- 7811030107 Requests amend to Facil Oper Lic#35 to accommodate new Steamline Break Protec Bys which is sched for installation in Spring of 1979. Forwards proposed Tech Spec & check for \$12,300 for class IV Amend.

 DVNN-C.N Duquesne Light Co. 78/10/27. 423pp. 02722:001.
- 7811080259 Forwards request for add1 info re feedwater pipe vibration for transmittel to applicant.

 LAINAS.0 Plant Systems Branch (Pre 791030). 78/10/31. 2pp. 94405. 150.
- 78i1220239 Provides limited approval of P642 seal matl for hydraulic anubbers for up to 2 normal refueling outages or within months under spacified conditions t defines inspec sched for those seals, w/FE&O Rept on seal matl old 780817.

 BCH-ENCER, A. Operating Reactors Branch i (Pre 790625) 78/11/09. 12pp. 94381:318
- 7811280385 Forwards request for add) info re Nuc Sys Corp Rept#1-78-012 transmitted by ltr on 780317 re feeder line vibration monitoring prog results for subj facil Requests response w/in 30 days.

 SCHMENCER. A. Operating Reactore Branch 1 (Pre 790625). 78/11/13.
 3pp. 94397:292.
- 78ii24004i Ack receipt of 7807i7 transmittal of "Potential Consequences of 011 Pipeline Failure. "Requests payment of Class III fee of \$4000.
 MILLER.W. D. License Fee Nanagement Branch. 78/11/15. 2pp. 94457:242.
- 7812190141 Notice of workshops re implementation of training & qual requirements contained in Append 8 of IOCFR73. Requests pre-workshop registration of attendees to facilitate sending out matl. W/encl Registration Form & List of Locations.
 MILLER, J.R. Assistant Director for Site & Bafeguards (Pre 791030), 78/11/15. 5pg.
- 78(2190028 Forwards Revel "Draft Radiological Effluent Tech Specs" for PMR's(NUREG-0473) & "Freperation of Radiological Effluent Tech Specs for Nuc Pur Plants" (NUREG-0133). QRIMES B. W. Assistant Director for Engineers & Projects (Pre 790625). 78/11/15. 6pp. 94214:392.
- 7812070143 Notice of seminar on 781208 on new Model Radiological Effluent Tech Space for nuc pur plants Requests advance submission of seminar specific questions. W/encl Seminar Info Sheet-Proposed Agenda & maps.
 GRIER.B.M. Region 1, Philadelphia, Office of the Director. 78/11/21. Spp. 94375:268.
- 78:2080143 Notification of meeting w/Duquesne Light Co on 78:205 in Betheeda to discuss containment leak test w/containment liner weld channels unvented.
 HIGGINTON. D. Operating Reactors Branch 1 (Pre 790625), 78/11/28.
 2pp. 94:04:325.
- 7812130066 Discusses possible dengers of LOCA in containment purging during normal plant oper. Requests either commitment to limit purging or justification for continuing. W/encl ANO: 7812080207
 BCHENCER. A. Operating Reactors Branch 1 (Pre 790625). 78/11/28. 6pp. 94210:168.
- 7812060162 Responds to NRC 781115 ltr & forwards \$4000 class III fee. MOORS. G. W. Duquesne Light Co. 78/11/30. ip. 94371:257.

- 7812280103 Emphasizes importance of submitting accurate & complete i to NAC by licensees & applicants info submitted must be a substentiated by data & calculations Licensee must notify NRC of any inaccuracies or enforcement action will result. DAVIB. J 9 Office of Inspection & Enforcement. Office of the Director. 78/12/06. 2pp. 03355.319
- 7812050013 Requests views of Regional Directors on Licensee performa eval of subj facils.Forwards questions to be answered by 771209. THORMAUND, H Division of Reactor Construction Inspection. 77/11/

200.

- 7812190101 Forwards review comments on Suppl#2 to "Soil Study-Catego 1 Struc: of subj facil."Applicant fails to provide basic info re sample preparation & test procedures. Requests study of liquefaction potential & stability analysis by util.

 BTEPP-U.C. Geosciences Branch. 78/12/13. 4pp. 94376:301.
- 7812210215 Forwards add1 info re Reactor Vessel Overpressure Protecto follow up 781123 request that sys be categorized as interim sys. Request interim sys be upgraded as valves now qual to seismic design requirements DUNN.C.N. Duqueens Light Co. 78/12/14. [p. 94279:114.
- 781222071 Forwards add1 info re lic amend app1 covering eval of low feedwater flow reactor trip setpoint change.

 DUNN C.N. Duquesne Light Co. 78/12/14. 16pp 94249:073.
- 7812260214 Forwards proposed amend to Oper LiceDPR-66 for subj facil Beets change to Append "B" of Tech Specs Section 3.1.2 re documentation concerning chem releases. DUNN.C.N. Duquesne Light Co. 78/12/14. 2pp. 94160:187.
- ---7812260216 Proposed amend to Oper Lic for sub; facil. Revises Amend by seeking change to Appl "B" of Tech Specs section 3.1.2 re documentation concerning chem releases. • Duquesne Light Co. 78/12/14. 2pp. 94160:189.
- \mathbf{Q}_{c} inspection reports. IE Bulletins & correspondence
- 7810300292 IE Inspec Rept#90-334/78-21 on 780822-25 \$ 0829-31 during which no items of noncompliance were noted Major ereas inspected included:new high density spent fuel racks & eddy current inspec of steam generator tubes.

 PASMO.A. N. Region 1, Philadelphia, Office of the Director. 78/09/13. 9pp. 94033:180.
- 7810300117 Forwards IE Inspec Rept#50-334/78-21 on 780822-25 & 0829-during which no items of noncompliance were noted.

 CARLEGNR T. Region 1. Philadelphia, Reactor Construction & Engineering Support Branch. 78/09/13. 2pp. 94035:178,
- 7810180215 Forwards IE Inspec Rept #50-304/78-19 on 780808 & Notice of Violation.
 MARTIN-M. G. Region 1, Philadelphia, Bafeguards Branch. 78/08/31.
 2pp. 94311: 397.
- --7810180217 1E Inspec Rept #50-334/78-19 on 780808-11 during which items of noncompliance were noted; security organization & testing & maint.

 BAILEY.R. J. Region 1, Philadelphia, Safeguards Branch. 78/08/3 ip. 94311:359.
- 7810160240 Forwards IE Bulletint/8-12: "Atypical Held Material in Reactor Pressure Vassel Helds" requesting action w/in 60 days. L list of IE Bulletins issued in 1978. (See AND 87810040253)

 ORIER, B.H. Region 1, Philadelphia, Dffice of the Director. 78/09/29. App. 94004:001.
- 7811130271 Forwards IE Inspec Rept#50-334/78-23 on 780909 during whit no items of noncompliance were noted.

 BRUNNER, E. J. Region i. Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/04. 2pp. 94011:218.
- --7811130275 IE Inspec Rept#50-334/78-23 on 780906 during which no of noncompliance were noted. Hejor areas inspected included; corrective actions re environ qual for elec components. RAYMOND, M. J. Region i. Philadelphia, Office of the Director. 78/09/06. 8pp. 94011:220.
- 7811130280 Forwards IE Inspec Rept#50-334/78-25 on 780919-21 during which no items of noncompliance were noted. CARLSON.R.T. Region 1. Philadelphia. Reactor Construction & Engineering Support Brench. 78/10/05. 2pp. 94011:240.

DOCKETED ITEMS

- --7811130285 IE Inspec Rept#50-334/78-25 on 780919-21 during which no items of noncompliance were noted Major areas inspected included; insvc inspec activities, including procedure review & withess of insvc examinations.

 WALTON, Q. A. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch. 78/09/29 3pp. 94011:242.
- 7811060198 Forwards IE Circular#78-17. (See ANO: 7810230221, Docket #50-133, 781013.) GRIER, B.H. Region 1, Philadelphia, Office of the Director. 78/10/13. ip. 94489:189.
- 7810270185 Act receipt of 780926 ltr informing NRC of steps teten to correct violations noted during inspec #50-334778-20 BRUNRER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch. 78/10/16. 1p. 94057:093.
- --7810270189 Responds to 780830 NRC ltr re violation noted in Inspec rept #50-334/78-20. Corrective actions: station administrative directive will be rev to ensure control re vendor procedures. Vendor will be notified.

 DUNN.C.N Duquesne Light Co. 78/09/26 3pp. 94057:094.
- --7810270192 Forwards IE Inspec Rept #50-334/78-20 & Notice of Violation BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Bupport Branch. 78/08/30. 2pp. 94057:097.
- --7810270194 Notice of Violation from inspec on 780808-11. * Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/08/29. 1p. 94057:099.
- --7810270196 IE Inspec Rept #50-334/78-20 on 780808-11 during which 2 items of noncompliance were noted: failure to have approved procedures for conduct of surveillance test & failure to reg periodic reviews of maint procedures
 JOHNSON, D., KEIMIG, R.R. Region 1, Philadelphia, Reactor Operations
 Nuclear Support Branch. 78/08/29. 9pp. 94037:100.
- 7812110232 Forwards IE Inspec Rept#50-334/78-28 on 781013 during which no items of noncompliance were noted.

 BMITH, Q.H. Ragion i. Philadelphia. Fuel Facility & Materials Safety Branch. 78/11/01. 2pp. 94338:030.
- --7812110235 IE Inspec Rept#50-334/78-28 on 781013 during which no items of noncompliance were noted. Major areas inspected incl: results of efficient samples split between licensee & NRC Region I. KOTTAN, J. J. KOTTAN.J.J. Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch. 78/11/01. App. 94338:032.
- 7612080080 Forwards IE Inspec Rept#50-334/78-27 on 781016-18 during which no items of noncompliance were noted. BRUNNER.E.J. Region 1, Philadelphia, Reactor Operations Nuclear Bupport Brench. 78/11/02. 2pp. 94108;013.
- --7812080083 IE Inspec Rept#50-334/78-27 on 781016-18 during which no items of noncompliance were noted Major areas inspected incl:containment integrated leak rate test procedure & local leak rate test. CAPHTON, D. L., HIGGINS, J. C. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 78/10/31, 7pp. 94108:015.
- 7811300241 Ack receipt of 781016 ltr informing NRC of steps taken to Correct violations noted during Inspec#50-334/78-22.

 BMITH, Q. H. Region 1, Philadelphia, Fuel Facility & Materials Sefety Branch. 78/11/03. 1p. 94074:355.
- --7811300243 Responds to 780926 NRC ltr re violations noted in Inspec Rept#50-334/78-22. Corrective actions: repositioned barrier & signs at entry to high rediet area. DUNN.C.N. Duqueene Light Co. 78/10/16. 3pp. 94074:356.
- --7811300246 Forwards IE Inspec Rept#50-334/78-22 on 780830-0901 & Notice of Violation. CROCKER.H.H. Region i, Philadelphia, Fuel Facility & Materials Bafety Branch. 78/09/26. 3pp. 94074:359.
- --7811300248 Notice of Violation from inspec on 780830-0901.

 Region I, Philadelphia, Fuel Facility & Materials Safety Branch, 78/09/26. ip. 94074:362.
- --7811300250 IE Inspec Rept#50-334/78-22 on 780830-0901 during which i item of noncompliance was noted:failure to control high radiat areas IAW Tach Spacs. WHITE.J.R. Region i, Philadelphia, Office of the Director. 78/09/26. 10pp. 94075:001.

- 7812080144 Forwards IE Inapec Rept#50-334/78-26 on 781002-06 & 78100
- 12 & Notice of Violation, GRIER, B H Region 1. Philadelphia, Office of the Director. 78/11/03. 3pp 94104: 327.
- --7812080145 Notice of Violation from inspec on 781002-06 & 781010-1 GRIER, B. H. Region 1, Philadelphia, Office of the Director. 78/11/03. 1p. 94104: 330.
- --7812080147 IE Inspec Rept#50-334/78-26 on 781002-05 & 781010-12 of which I item of noncompliance was noted failure to comply w/equip control procedures. KISTER, H. MARKONSKI.R.S. BECKMAN, B. Region 1, Philadelphia. Reactor Operations Nuclear Support Branch 78/11/03 18pp. 94104. 331.
- 7811290212 Forwards IE Circular #78-18. "UL Fire Test. "W/encl ANO: 781:130002. QRIER, B.H. Region is Philadelphias Défice of the Director. 78/11/06. 1p. 94237: 320.
- 7812270149 Forwards IE Inspec Rept#50~334/78-24 on 780912-19 during which no items of noncompliance were noted BRUNNER.E.J. Region i. Philadelphia. Reactor Operations Nuclear Support Branch. 78/11/13 2pp. 94161-152
- --7812270103 IE Inspec Rept#50-334/78-24 on 780912-15 during which n items of noncompliance were noted. Major areas inspected inclipiant oper.conformance w/Tech Spec L886.LCO's & SLreview of LER's & outage meint activities RAYMOND.W.J. KEIMIO.R.R. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch. 78/11/09 17pp. 94161:154
- 7812290211 Forwards IE Inspec Rept#50-334/78-29 on 781013-15 & 27 during which no items of noncompliance were noted.

 CARLBON, R. T. Region 1. Philafelphia. Reactor Construction & Engineering Support Branch. 78/11/15. 2pp. 74170:350.
- --7812270220 IE Inspec ReptM50-334/78-27 on 781023-25 & 27 during whino items of noncompliance were noted Najor areas inspected int3:high density spent fuel racks & insvc inspec data. PABAND.A.N. MALTON.G.A. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 78/11/15. 5pp. 04107-1957
- 7812130136 Forwards IE 8011et(n#78-12A, supp) to 1E 8011etin#78-12 W/encl AND: 7811300055. GRIER, B. H. Region I. Philadelphia. Office of the Director. 78/11/24. ip. 94212:184.
- R. Periodic operating reports & related correspondence
- 7810160114 Forwards Monthly Oper Rept Por Bept 1978
 DUNNLC.N. Duquesne Light Co. 78/10/10. lp. 94007:121.
- --7810160116 Monthly Oper Rept for Bept 1978 WITHOWSKY, F. P. Duquesne Light Co. 78/10/04 Spg. 94007:122.
- 7811030169 Forwards copies of EPA Quarterly Rept for Sept 1978.4s submitted to EPA & PA Dept of Environ Resources. MODRE- O. W. Duquesne Light Co. 78/10/27. 39pp. 02724:028.
- 7811160109 Forwards Monthly Open Rapt for Oct 1978.

 BUNN. C. N. Duquesne Light Co. 78/11/11. ip. 94135:152.
- --7811160111 Monthly Oper Rept for Oct 1978. WITKOMSKY, F. P. Duquesne Light Co. 78/11/03. 5pp. 94135:153.
- 7812110128 Forwards Monthly Oper Rept for Nov 1978.

 DUNN C. N. Duquegne Light Co. 78/12/06. Ip. 94039: 334.
- --7812110132 Monthly Oper Rept for Nov 1978, WITKOMBKY, F. P. Duqueane Light Co. 78/12/01. 4pp. 94339:335.
- 8. Reportable occurrences, LERs & related correspondence
- 7810100030 Forwards LER#78-048/03L-0. WERLING, J. A. Duquesne Light Co. 78/09/25. 2pp. 94033:034.
- ---7810100034 LER#78-048/03L-0 on 780221: during rev test data on 780 noted that final satigaint valve entered on 780221 for RCS Loop 18 Cold Leg Loop Stop Valve relief line flow interlock was 124 GPM caused by improper sationit.

 WERLING J.A. Duquerne Light Co. 78/09/23. ip. 94033:036.

- 7Bi0100084 LER#7B-031/01T-0 on 7B0912:During surveillance testing of #1 Deisel Generator.output breaker failed to close using control switch #1 Generator operable.Test panel installed to detect abnormal oper.

 MERLING.J.A. Duquesne Light Co. 7B/09/26 2pp.
- 7811030164 RO 78-053/OiP: on 781026 during review of stresscalrulations for safety injection piping inside containment errors in piping stress analysis were discovered. Caused by error in hand calculating method.
 WERLING, J. A. Duquesne Light Co. 78/10/27. ip. 02724:019.
- 7811130218 Forwards LER878-054/03L-0. WERLING, J. A. Duquesne Light Co. 78/11/04 2pp. 03554-058
- --7811130220 LERW7B-054/03L-0 on 781005 During surveillance test on containment high pressure bistable, the setpoint was 2.3 lbs instead of 2.0 Caused by faulty ELCO connector on loop signal comparator. Comparator was replaced.

 WERLING.J.A. Duquesne Light Co. 78/11/04. ip. 03554:060.
- 7811170214 Reportable Occurence#78-058/04P on 781103-08:during plant shutdown, reactor plant river water & turbine plant river water header chlorination levels exceeded allowable value, due to abnormal lineup.

 WERLING, J. A. Duqueene Light Co. 78/11/09. 2pp. 94136:120.
- 7811170219 Submits interim rept re previous LER#78-53/017: Purther investigation into apparent errors in stress analysis for sefecty injection piping inside containment reveals original rept was erroneous.Full rept will follow.

 WERLING, J. A. Duquesne Light Co. 78/11/09. 2pp. 94136:126.
- 7811170172 Forwards LER#78-055/03L-0.
 WERLING, J. A. Buquesne Light Co. 78/11/13 2pp. 94048: 125.
- --7811170178 LERM78-055/03L-0 on 781013: channel N41 rate trip set at 11.8% in 2.2 seconds rather than limit of 5.5% in 2 seconds. Caused by inadventent readjustment or improper calibr of the setpoint.

 WERLING, J. A. Duqueses Light Co. 78/11/13. 1p. 94048:127.
- 7811170221 Forwards LER#78-036/03L-0. WERLING, J. A. Duqueene Light Co. 78/11/13. 2pp. 94048: 299.
- ---7811170234 LER#78-056/03L-0 on 781011: vent exhaust monitor RM-VB-101 removed from eve for grab samples. Sample not taken for one day due to personnel error. (For 1tr see ANO#7811170172.)
 HERLING.J.A. Duqueene Light Co. 78/11/13. 1p. 94048:301.

- 7812120143 Forwards LER 78-053/01T-0. HERLING, J. A. Duquesne Light Co. 78/12/06. 2pp. 94276:260.
- ~-7812120148 LER 78~053/017~0 on 781026, error noted in original pistress analysis for on steam infection line Error caused by misapplication of simplified analysis technique employed during original design. Corrective action implemented. MERLING. J. A. Duquesne Light Co. 78/12/06. 3pp. 94276:262.
- 7812180180 Forwards LER#78-057/04L-0. MERLING.J. A Duguesna Light Co. 78/12/08. 2pp. 94359:344.
- --78:2180184 LERM78-057/04L-0 on 78:110. records review showed gas waste monitor#RM-GM-1088 was inoper from 78:0210-13 & nd results of grab samples could be located due to failure by Radcon personnel to obtain the samples.

 MERLING, J. A. Duquesne Light Co. 78:12/08. ip. 94359: 346.
- 7812290222 Forwards LERB78-058/04T~0. WERLING.J. A. Duquesne Light Co. 78/12/19. 2pp. 94191:193.
- --7812290226 LER#78-058/04T-0 on 781108: chlorination was performs river water headers during plant shutdown & free chlorine residual exceeded allowable 0.5ppm.due to personnel error. WERLING, J. A. Duquesne Light Co. 78/12/19. 2pp. 94191:195.
- 7812270216 Forwards LERW78-059/03L-0.LERW78-060/03L-0 & LERW78-061/03L-0. WERLING.J. A. Duquesne Light Co. 78/12/22. 2pp. 94191:181.
- --7812290223 LERW78-059/03L-D on 781108: during performance of Typ-Containment Penetration Leek Test, 12 valves were found to be leaking at a rate greater than maximum measurable on leek rate monitor caused by excessive valve leakage. -MERLING, J. A. Duquesne Light Co. 78/12/22. 3pp. 94191:183.
- --7812290227 LER#78-060/03L-0 on 770718: during review of surveill test records it was determined that monthly test for 18 RPRW Pump was not performed by 770718 as req. Caused by improper sched of surveillance test.

 WERLING, J.A. Duquesne Light Co. 78/12/22. 1p. 94191:186.
- --7812270235 LERM78-061/03L-0 on 781012: during performance of conisolation check valve surveillance test IA RCP seal injection spring-loaded check velve was found to have an opening pressure of 11.5 PBID Caused by sicess force. WERLING, J.A. Duquesne Light Co. 78/12/22. 1p. 94191:187.

PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asterisk following the accession number in this index indicates that the document is an enclosure to anothe document. To obtain the accession number of the principa document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principa Documents."

AUTHOR	ACCESSION NUMBER	SUBJECT		AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCE8810N NUMBER	SUBJEC CATEGO
ABBOTT, H. S.	7812010042*	30-471	0	ANDERSON T. M.	7811210234	50-275	A	ANTIO, H. A.	7811280473	50-29
ABBOTT, H. S.	7811210140	50-471	Α	ANDERSON, D.	7812210204*	50-213	R	APADAKIS, C. N.	7811090156	50-329
ASRAMSON L.	78122700524	50-320	ä	ANDERBON, C. J.	7811240157	50-322	ö	ARCHER, J. F.	7811220237	50-466
ABBTON, C. Q.	7810300269*	50-387	B	ANDERBON, C. J.	7811240161*	50-322	ŏ	ARCHER, J. F.		
ABBTON: C. C.	7811280425	50-400	Ä	ANDERBON D.	7812130009	50-70	ă	ARCHITZEL, R. E.	7812040316 7811300363*	50-466 50-184
							•			
ACHTERBERG. J. ACHTERBERG. J.	7810270231* 7811160115*	50-249 50-237	8 8	ANDERSON T. M. ANDERSON T. M.	7811160127 7611240164	50-572 50-445	B A	ARCHITZEL, R. E. ARNOLD, T. G.	78101600B2+ 7810310135+	50~293 50~348
ACHTERBERG, J.	7811210181*	50-237	8	ANDERSON, T. M.	7811240165	30-445	Ä	ARON, R.		
ACHTERBERG, J.			8	ANDERSON T. M.			p		7811210325*	50-29
ADAMS, W. E.	7812270271* 7810110119	50-237 50-255	R	ANDERBON, P. L.	7812090039 7812200217*	50-272 50-309	9	ARTHUR, J. E. ARTIGAB, R.	7812280191	50-485
AUANDI N. C.	7810110117	20-822	'n	MADERADIO P. C.	/81550051\#	30-307		ARTIOADIR.	7812010249*	50-447
ADAMS, J.	7611020251+	50~187	P	ANDERBON P. L.	7612200254	30-309	5	ABHENDEN, J.	7810110290*	90-338
ADAMS, H. E.	7811140147	50-255	R	ANDERBON, J. M.	7812190140	50-545	Ą	ABPERGER, R. Q.	7010230373	50-341
ADAMBON, R. W.	7812070066	50-394	P	ANDERSON C. J.	7812290005	20-325	A٠	ASPERGER, R. G.	7811080043	50-341
ADAMS, W. E.	7812110122	30-255	R	ANDERSON T. M.	7812290136	50~480	A	ABPERGER, R. G.	7811080282	50-341
ADAMS, D. S.	7812270075*	50-483	o .	ANDERSON T. V.	7812270197*	50-106	Р	ABHELL, D. L.	7811010004	20-385
ADAMS, D. S.	7812270076*	50-485	۵	ANDOONINI, Q. C.	7810170136	50-293	P	ABWELL, D. L.	7810110115	50-362
ADAMS, D. S.	7812270081	30-4B5	ø	ANDOGNINI. G. C.	7810180113	50-293	P	AGWELL, D. L.	7811170086+	50-3B2
AINGER, K. A.	7911240129*	50-275	8	ANDOONINI, O. C.	7810270105	50-293	P	ABWELL, D. L.	7811300233	50-392
ALBERT: W. Q.	7811010037*	146-06	G.	ANDOGNINI, Q. C.	78110701B5	50-293	P	ABHELL D. L.	7812110230+	50-382
ALBERT, H. Q.	7811270199*	50-522	Q.	ANDOONINI.G.C.	7811140132	50-293	К	ABHELL, D. L.	7812050182	50-382
ALBERT, H. Q.	7812210153*	50-460	q	ANDDONINI Q. C.	7811150168	50-293	F	ASHELL, D. L.	7012110155	50-382
ALBERT, W O.	7812280246*	30~361	G .	ANDOONINI, Q. Q.	7812080185	50-293	a	ASHELL, D. L.	7612120115	50-382
ALBIE, K.	7810120084*	30-344	e	ANDDONINI O. C.	7811270163	50-293	.P	ASHELL, D. L.	7812170072	50-3B2
ALDEN, W. M.	7810230167*	50-277	R	ANDDONINI, O. C.	7612060223	50-293	P	ASWELL, D. L.	7812200133	50-382
ALDEN, W. M.	7811150116	50-171	W	ANDOGNINI. Q. C.	7812110166	50-293	Р	ASWELL, D. L.	7812200242	20-382
ALDEN, W. M.	7811140144#	50-277	R	ANDOGNINI, Q. C.	7612210259	50-293	p	ABWELL, D. L.	7812200248	50-382
ALDEN, W. M.	7811140086#	50-277	Ř	ANDOONINI, O. C.	7612240218	50-273	ĸ	ABWELL, D. L.	7812200230*	50~362
ALDEN, W. M.	7812220064*	50-277	R	ANDBONINI Q, C.	7812260223*	50-293	ĸ	ASHELL, D. L.	7B12290175	20-385
ALDERSON C. E.	7810310074*	30-259	Ö	ANDREWS C. W.	7810170194+	50-250	P	AUBRE, R.P.	7810250184	50-312
ALINGER, K. A.	7810170246+	30-25	8	ANDREWS.R.L.	7810110113	50-285	8	AVERBACH, M.	7810300281+	50-312
ALLAN, J. M.	7810240018	50-219	ρ	ANDREWS R. L.	7810110100	50~285	8	AUT 10, H. A.	7810180008	50-29
ALLEN, J.	7812040220+	50-219		ANDREWS R. L.	7810101010	50-285	8	AUTIO, H. A.	7810180008	
ALLEN, D. R.			H			50-285	8	AUTIO, H. A.		50-29
	7811070315	50-592	M	ANDREWS.R. L.	7610110112		g		7810240152	50-27
ALLEN, D. R.	7811160036	50-592	M	ANDREWS R. L.	7810180159	50-285 50-285	8	AUTIO, H. A. AUTIO, H. A.	7810240156	50-29
ALLEN, R.	7811210392*	50-10	8	ANDREHSIR, L.	7811060200	50-200	•	HOTTOTALA.	7811090145	50-29
ALLIBON, D. P.	7810260219	50-275	Ą	ANDREHS R. L.	7811060204#	50-285	9	AUTIO, H. A.	7811170200	50-29
ALLIBON, D. P.	7810260099	50-275	A	ANDREHS R. L.	7811210368	50-295	8	AUTIO: H. A.	7811170211	50-29
ALLISON, D. P.	7811010381	50-275	A	ANDREWS R. L.	7812010236	50~285	8	AUTIO, H. A.	7811300378	50-29
ALLISON, D. P.	7811010382	50-275	0	ANDREWS R. L.	7812050173	50-285	8	AUT IO. H. A.	7811210317	50-29
ALLIBON, D. P.	7811020029	30-273	A	ANDREWS, R.	7812200272*	50-285	8	AUT IO, H. A.	7811280284	50-29
ALLISON.D.	7811080005	50-275	A	ANDREWS.R.L.	7812200264	50-285	В	AUT IO, H. A.	7811280326	50-29
ALLIBON. D. P.	7B11290400	50-275	F	ANDREWS, R. L.	7812200265	50-285	8	AUT IO, H. A.	7B11280314	50-27
ALLISON, D. P.	7811300079	50-275	A	ANDREWS R. L.	7812200227	50~285	B	AUT IO, H. A.	7811290198	50-29
ALLISON, D. P.	7812130389	50-275	A	ANDREHS, R. L.	7812270213	50-285	B	AXELRAD, M.	7810200003	50-344
ALLISON: D. P.	7812150033	50-275	A	ANDREWS R. L.	7812270219	50-285	8	AXELRAD, M.	7B10140019	50-344
ANCARROW M. R.	7812260014	50-247	P	ANDREWS R. L.	7812270258	50-265	8	AXELRAD.M.	7810270386	50-344
ANDERBON 8. L.	7812080142+	50-306	P	ANDREWS, R. L.	7812270332	50-265	8	AXELRAD, M.	7B11020041	50-376
ANDERBON 8. L.	7811140131*	80-266	P	ANDREUS, R. L.	7812290225	50-295	8	AXELRAD, M.	7812040028	50-344
ANDERSON B. L.	7811140133#	50-266	ė	ANG. W. P.	7612050150*	50-327	æ	AXELRAD, H.	7812040031*	50-344
ANDERSON P. L.	7811030140*	50-309	В	ANG, W. P.	7812060035#	80-395	Q.	AXELRAD, M.	7812180436	50-344
ANDERSON, P. L.	7811030135+	50-309	В	ANG, H. P.	7812280080#	50-424	9	AXELRAD, M.	7812270485	50-344
ANDERSON P. L.	7811220217*	50-309	8	ANG, W. P.	7812290048*	50-390	Ģ.	AXELBON, W. L.	7812010070*	50-305
						50-413	ä			
	7811210254	30-464	•	ANG. N. P.	78122100484	20-413	ч	AXELUUN, W. L.	7R11290307=	50-123
ANDERSON L. H. ANDERSON C. J.	7811210254 7811130258	50-466 50-322	Q A	ANG. W. P. ANG. W. P.	7812210048* 7812290070*	50-413	ä	AXELSON, H. L. AXELSON, H. L.	7811290397* 7812280229*	50-123 50-456

BALLAI BALLAI BALLAI BALLAI	BALLAI	BALLAI BALLAI BALLAI BALLAI	BALLAF BALLAF BALLAF BALLAF	BALLAF BALLAF BALLAF	BALLAS BALLAS	BALDH! BALDH!	BAKER, BAKER, BAKER, BAKER,	BAIR) BAIRD, BAIRD, BAJWA, BAKER,	BAILEY BAIR. 6 BAIR. 6 BAIR. 6	BAER, F BAER, F BAER, F BAOCHI BAILEY	BAER. A BAER. A BAER. A BAER. A	BAER. F BAER. F BAER. F BAER. F	BACON. BACON. BACON. BACON. BADGER	AYERB. BACHRA BACKUS BACKUS BACKUS
ARD:R.L. ARD:R.L. ARD:R.L.		ARD, R. L., ARD, R. L., ARD, R. L., ARD, R. L., ARD, R. L.,	ARDIR. L. ARDIR. L. ARDIR. L. ARDIR. L.	ARD, R. L. ARD, R. L. ARD, R. L. ARD, R. L. ARD, R. L.	ARD, R. L. ARD, R. L. ARD, R. L. ARD, R. L. ARD, R. L.	IIN.W. A. IIN.W. A. IIN.W. A. IIN.W. A. IIN.W. A.	li R. li K. R.), J. 18.), J. 18.), S.	0. 0. 0. 0.	R. L. R. L. II. G.	R. L. R. L. R. L.	R. R. L R. L		B.R.A. S.R.A.
7812140102 7812140115 7812140134 7812140172 7812140253	7040(40400	7812130030 7812040379 7812070049 7812070275 7812110040	7811130272* 7811130428 7811140001 7811200017 7812010331	7812260039* 7811070098 7811080186 7811080235 7811130289	7810230057 7810130024 7810180223 7810310243* 7811030182	7810300062 7810190193 7810230084 7812110278 7812210512	7810270398* 7811240184 7812130045* 7812130220 7812130231	7812120153* 7811060008* 7811270107* 7810300019 7810240005*	7810180217+ 7810170145+ 7811070198+ 7811140141+ 7811160101+	7812110214 7812110243 7812150208 7810260037 7810190116*	7811150030 7811150035 7811160194 7812040042 7812070015	7812180428 7810110003 7811010183 7811100169 7811150015	7810270168 7812050142 7812050213 7812190095 7810230104	7812040207+ 7811020077 7810170060 7812260087 7812260092+
50-502 50-502 50-502 50-502 50-502		50-546 50-454 50-448 50-341 50-275	50-373 50-373 50-373 50-373 50-368	50-247 50-510 50-548 50-510 50-373	50-247 50-498 50-498 50-244 50-286	50-70 50-70 50-70 50-70 50-70	50-315 50-329 50-315 50-305 50-498	50-344 50-266 50-344 50-549 50-437	50-334 50-344 50-344 50-344 50-344	50~352 50~369 50~395 50~70 50~57	50-369 50-437 50-549 50-369 50-369	50-70 50-369 50-369 50-369 50-437	50-329 50-329 50-329 50-329 50-437	50-454 50-516 50-443 50-443 50-443
A A A		A A C H	D D D	P D A A D	P A C P P	0 0 0 0	0 A G M	R G G A	Q R R R	H A A P	A A G	P A A A	K A C A	K 0 0 0
BARRETT, P. A. BARRETT, J. E. BARRETT, J. E. BARRUS, C. BARTH, C. A.		BARRETT,P. A. BARRETT,J. E. BARRETT,L. BARRETT,L. BARRETT,J. A. BARRETT,J. E.	BARLOH, Q. BARNETT, E. W. BARRETT, E. W. BARRETT, P. A.	Bardes, C. R. Barker, J. L. Barker, J. L. Barker, J. L. Barker, H. A.	BANKB, H. R. BANKB, H. R. BANKB, H. R. BANTA, F. L. BARDEB, C. F.	BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R.	BANKB, H. R. BANKB, H. R. BANKB, H. R. BANKB, H. R. BANKB, H. R.	BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R.	Bankb.H.R. Bankb.H.R. Bankb.H.R. Bankb.H.R. Bankb.H.R.	BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R.	BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R.	BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R.	BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R. BANKS, H. R.	BANCROFT, M.H. BANCROFT, M.H. BANKS, H.R. BANKS, H.R. BANKS, H.R.
7812070108* 7811200187* 7812200179* 7812050138* 7810240019		7811020168* 7810160074* 7810180187 7812170155* 7811280271*	7812040348 7810270328 7812180258 7811070285 7811010057*	7812180151* 7811010022* 7811010022* 7811300268* 7812290124	7812210218 7812270257 7812270298 7812270068 7811090096	7812080127 7812150330 7812150348 7812210181 7812210187	7812130251* 7812130294* 7812070214 7812070165 7812070175	7812140158 7812140163 7811170209 7811220183 7812010232	7811090194 7811160088 7811160119 7811160132 7811160091	7610310232 7810310139 7610310210 7610310217 7811090186	7810230193 7810230195* 7810270215 7611170238* 7810310143	7810130121 7810130158 7810160147 7810230020+ 7810230143	7810100029 7810100049 7810130177 7810130152 7810130189	7812010357 7812180077 7810110242# 7810110291# 7810100043
50-456 50-302 50-302 50-298 50-488		50-341 50-302 50-220 50-483 50-302	50-70 50-499 50-445 50-341 50-368	50-213 50-10 50-10 50-10 50-546	50-325 50-261 50-324 50-358 50-259	50~325 50~324 50~261 50~325 50~325	50-26! 50-324 50-325 50-325 50-324	50-325 50-261 50-325 50-325 50-261	50-325 50-325 50-261 50-325 50-324	50-324 50-324 50-261 50-324 50-261	50-324 50-324 50-261 50-324 50-261	50-324 50-325 50-261 50-324	50-324 50-325 50-324 50-325 50-325	50-493 50-493 50-324 50-324 50-261
G R R		Q R P Q R	0 0 M 0	J G G	8 8 8	8 R R B	0 0 8 8	8 8 8 R	9 9 R 8 R	8 8 8 8	8 8 9 9	Я В О В	6 8 9 8	0 0 8
Baunack, W. H. Baunack, W. H. Baxley, B. X. Baxley, B. X. Baxley, B. X.		BAUM, E. A. BAUM, E. A. BAUNACK, H. H. BAUNACK, H. H. BAUNACK, H. H.	BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUM, E. A. BAUM, E. A.	BAUCDM, T. L. BAUCDM, T. L. BAUCDM, T. L. BAUCDM, T. L. BAUCDM, T. L.	BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L.	BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L.	BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L.	BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L. BAUCOM, T. L.	Babt, B. A. Batch, B. Bateman, W. H. Bateb, R. W. Bateb, R. W.	Baskin, K. P. Baskin, K. P. Bast, B. A. Bast, B. A. Bast, B. A.	Babkin, K.P. Babkin, K.P. Babkin, K.P. Babkin, K.P. Babkin, K.P.	Babkin.k.p. Babkin.k.p. Babkin.k.p. Babkin.k.p. Babkin.k.p.	Baskin K.P. Baskir E. Baskin K.P. Baskin K.P. Baskin K.P.	BARTH, C. A BARTON, A. R. BARTON, A. R. BARTON, A. R. BARTON, A. R.
7811290339* 7812110310* 7810180039* 7810180122* 7810310142*		7810270112 7811020306 7810260028+ 7811080246+ 7811150194+	7812270281* 7812270294* 7812270324* 7810110162 7810180137	7812140129# 7812140131# 7812140229# 7812140234# 7812200207#	7812040233+ 7812050209+ 7812050211+ 7812050214+ 7812140126+	7811090210* 7811170185* 7811210266* 7811280292* 7811280238*	7811040213* 7811090240* 7811090215* 7811090217* 7811090219*	7810100079# 7810110132# 7810230262# 7810200112# 7810200118#	7812270452 7812050206+ 7811300387+ 7811280300+ 7812120113+	7812120101 7812290113 7812110306 7812140359 7812180267	7811280219 7811300209 7811280259 7812120220 7812040193	7810310132 7811220169# 7811060086 7811200118 7811220168	7810170103 7810200240 7810180083 7810230155 7810230268	7812270272 7811020351 7811130204 7812070022# 7812110307
50-336 50-245 50-366 50-366 50-321		50-404 50-336 50-220 50-219 50-220	50-281 50-280 50-280 50-338 50-338	50-280 50-281 50-281 50-280	50~280 50~280 50~280 50~280 50~280	50-280 50-280 50-281 50-281 50-280	50-280 50-280 50-280 50-280	50-280 50-281 50-281 50-281	50-266 50-346 50-410 50-336 50-336	50-206 50-361 50-305 50-266 50-305	50-206 50-361 50-206 50-466 50-361	50~206 50~361 50~206 50~466 50~361	50-361 50-466 50-361 50-206 50-206	50-400 50-364 50-364 50-364 50-364

#AWRELJ J.P. 7711001269 30-286 0 SERGOL H. 7812012000 00-297 0 BLACK, R. L. 7812012007 30-286 0 SERGOL F. 7812012000 00-297 0 BLACK, R. L. 7812012007 30-286 0 SERGOL F. 7812012000 00-297 0 BLACK, R. L. 7812012000 30-286 0 SERGOL F. A. 7812112000 00-297 0 BLACK, R. L. 781113000 30-286 0 BLACK, R. L. 781113001 30-286 0	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ANNEL J. P. 7811001299 ANNEL J. P. 7811001299 ANNEL J. P. 7811001290 ANNEL	BAYNE, J. P. BAYNE, J. P. BAYNE, J. P. BAYNE, J. P.	7811100138* 7810250135* 7810100098 7810120058	50-284 0 50-286 0 50-286 8 50-286 8	BERRY, Q. T. BERBON, B. A. BERBON, B. A. BERBON, B. A.	7810110085 7810110018 7810110023	50-286 P 50-266 Q 50-266 Q	BLACK, R. L. BLACK, R. L. BLACK, R. L.	7810230233 7811020315 7811150083	50-522 50-522 50-334 50-522 50-341
ANVELUL P. 7311140104 30-206 R. RESON B. A. 7812000175 30-206 R. RESON B. A. 781200175 30-206 R. RESON B. A. 781200175 30-207 R. RESON B. RESON	BAYNE, J. P. BAYNE, J. P. BAYNE, J. P. BAYNE, J. P.	7611100129# 7811080086# 7812010076# 7811060210	50-286 8 50-286 0 50-286 8	Berbon, B. A. Berbon, B. A. Berbon, B. A.	7811150089 7812040344 7812080163	50-266 Q 50-266 Q 50-580 Q	BLACK, R. L. BLACK, R. L. BLACK, R. L.	7812040342 7812040345 7812080162	50-341 50-522 50-522 50-341 50-341
BANKEL J. P. 781020099 50-280 FEETH-MUREN L. 7810107023 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077 781020077	BAYNE, J.P. BAYNE, J.P. BAYNE, J.P. BAYNE, J.P.	7811140104 7811140247 7811220189 7812150237	50-286 R 50-286 B 50-286 R	Berbon, B. A. Berbon, B. A. Bebecker, K. H.	7812080175 7812130224 7811100130#	50-266 0 50-448 0 50-269 0	BLACK, R. L. BLACK, R. L. BLACK, R. L.	7812270370 7812270366 7812270114	50-522 50-522 50-520 50-320 50-413
SECH-HOEFER C. 7811010432 50-397 0 SEVER S. 7810210324 50-346 6 SLAUH H. L. 78110200328 50-397 0 SECH-HOEFER C. 7811000032 50-397 0 SIDEN. H. D. 7812000324 50-397 0 SLOCK S. 781201032 50-397 0 SLOCK S. 781200032 50-397 0 SLOCK	BAYNE, J.P. Bayne, J.P. Beach, A.B. Beatty, Q.P.	7812220095 7812290170 7812210179* 7812210160	50-286 8 50-286 P 50-445 0 50-302 F	BEST, J. BETTENHAUSEN, L. BETTENHAUSEN, L.	7811090052 7812010282* 7812110310*	50-220 g 50-320 g 50-245 g	BLAKE, J. BLAKE, J. J. BLAKE, J. J.	7811240033# 7810270272# 7812210064#	50-324 50-250 50-324 50-413 50-186
SECH-HOEFER C. 7811300355 90-398 0 31ELAHRIL A. 7. 7613270010 30-356 0 ELUH-S. 7711120030 30-328 ELUH-S. 7711300303 30-338 ELUH-S. 7711300303 30-338 ELUH-S. 7711300303 30-3	BECHHOEFER.C. BECHHOEFER.C. BECHHOEFER.C. BECHHOEFER.C.	7811010432 7811070272 7811060261	50-387 0 50-498 0 50-387 0	Beyer, B. Biden, M.D. Bielawski, A. P.	7812310346# 7812060236# 7812120223	50-346 8 50-295 0 50-295 0	BLAU, H. L BLOCK, S. BLOCK, J. D.	7810300218 7812010373 7812270050	50-387 50-322 50-244 50-247 50-275
BECHHOEFER.C. 7519120120 50-341 0 BIRKEL.R.A. 7811200439 50-427 A BLUME.H.B. 7812210422 50-48 BECHHOEFER.C. 781927043 50-36-37 O BIRKEL.R.A. 7811200439 50-437 A BLUME.H.B. 781227051 50-49 BECHHOEFER.C. 7819270281 50-341 T BIRKEL.R.A. 7811200439 50-437 A BLUME.H.B. 781227051 50-49 BECHHOEFER.C. 7819270281 50-341 T BIRKEL.R.A. 7811200439 50-437 A BLUME.H.B. 781227051 50-49 BECHHAN.D. 78110700129 50-280 0 BIRKEL.R.A. 7811200121 50-437 A BUMM.R.J. 7811200129 50-438 BECHHAN.D. 78110700129 50-280 0 BIRKEL.R.A. 7811200121 50-437 A BUMM.R.J. 781108012 50-311 0 BIRKEL.R.A. 7811200127 50-427 A BUMM.R.J. 781108012 50-311 0 BIRKEL.R.A. 7811200137 50-437 A BUMM.R.J. 781108012 50-32 BECHAN.D. 781100148 50-311 0 BIRKEL.R.A. 7811200137 50-437 A BUMM.R.J. 7811090144 50-32 BECHAN.D. 7811090147 50-334 0 BIRKEL.R.A. 7811200137 50-437 A BUMM.R.J. 7811090144 50-32 BEDWAR.L.F. 78112001270 50-298 B BIRKEL.R.A. 7811200239 50-437 A BUMM.R.J. 7811090144 50-32 BEDWAR.L.F. 7811200270 50-298 B BIRKEL.R.A. 7811200239 50-437 A BUMM.R.J. 7811090144 50-32 BEDWAR.L.F. 7811200270 50-298 B BIRKEL.R.A. 7811200279 50-437 A BUMM.R.J. 7811030144 50-32 BEDWAR.L.F. 7811200274 50-298 B BIRKEL.R.A. 7811200279 50-437 A BUMM.R.J. 7811030147 50-34 BEDWAR.L.F. 7811200274 50-298 B BIRKEL.R.A. 7811200289 50-437 A BUMM.R.J. 7811170106 50-32 BEDWAR.L.F. 7811200274 50-368 B BIRKEL.R.A. 7811200249 50-437 A BUMM.R.J. 7811170106 50-32 BEDWAR.L.F. 7811200281 50-588 B BIRKEL.R.A. 7811200249 50-437 A BUMM.R.J. 7811170106 50-32 BEDWAR.L.F. 7811200281 50-588 B BIRKEL.R.A. 7811200249 50-437 A BUMM.R.J. 7811170106 50-33 BEDWAR.R.J. 7811200281 50-588 B BIRKEL.R.A. 7811200249 50-437 A BUMM.R.J. 7811170106 50-33 BEDWAR.L.F. 7811200281 50-588 B BIRKEL.R.A. 7811200249 50-437 A BUMM.R.J. 7811210028 50-368 B BIRKEL.R.A. 7811200249 50-437 A BUMM.R.J. 7811210028 50-368 B BIRKEL.R.A. 7811200249 50-437 A BUMM.R.J. 7811210028 50-368 B BIRKEL.R.A. 7811200249 50-437 A BUMM.R.J. 7811200249 50-438 B BIRKEL.R.A. 7811200249 50-439 A BUMM.R.J. 7811200249 50-439 A BUMM.R.J. 7811200249 50-439 B	BECHHOEFER, C. BECHHOEFER, C. BECHHOEFER, C.	7811300355 7811290085 7812050087	50-358 0 50-498 0 50-498 0	BIELAWSKI, A. F. BIERBAUM, Q. A. BIERBAUM, Q. A.	7612270010 7610160125* 7611150149*	50-556	BLUM, 8. BLUMBERG, N. J. BLUME, M. B.	7811290350 7812270449+ 7810230124	50-369 6 50-369 6 50-220 6 50-445 1 50-498 1
BECHMAND	BECHHDEFER.C. BECHHDEFER.C. BECHHDEFER.C.	7812130125 7812270043 7812270281	50-341 0 50-387 0 50-341 T	BIRKEL, R. A. BIRKEL, R. A. BIRKEL, R. A.	7811200435* 7811200430* 7811200428*	50-437 A 50-437 A 50-437 A	BLUME, M. B. Blume, M. B. Blume, M. B.	7812210372 7812210262 7812270091	50-498 50-498 50-498 50-498
BEDNERI-L.F. 7812800274* 50-298 B STRKEL.R.A. 7811200246* 50-427 A BINN.R.J. 7811170106 50-36 BEDROBISIN-P. 781011028* 50-568 A BINKEL.R.A. 781021019 50-369 F BONNIR.J. 7810203019 50-36 BEDROBISIN-P. 781011028* 50-568 A BINKEL.R.A. 781021019 50-369 F BONNIR.J. 7812030183 50-36 BEDROBISIN-P. 7810100028* 50-346 B BINKEL.R.A. 781020019 50-369 A BONNIR.J. 7812030183 50-36 BEDROBISIN-P. 78112038* 50-346 B BINKEL.R.A. 781020019 50-369 A BONNIR.J. 781210171 50-36 BEDROBISIN-P. 7811020177* 50-324 B BINKEL.R.A. 7811220041 50-369 A BONNIR.J. 781210174 50-36 BEDROBISIN-P. 7811020177* 50-223 Q BINKEL.R.A. 7811220041 50-369 A BONNIR.J. 7810101046* 50-47 BEDROBISIN-P. 7810101019* 50-270 F BINKEL.R.A. 781120041 50-369 Q BOLLNOM.D. I. 7810101012* 50-28 BETLHAN.T.P. 7810180188* 50-315 B BINKEL.R.A. 7812102883 50-369 Q BDLLNOM.D. I. 7811140148* 50-28 BETLHAN.T.P. 781011019* 50-315 B BINKEL.R.A. 7811202883 50-369 Q BDLLNOM.D. I. 7811140148* 50-28 BETLHAN.T.P. 7810120172* 50-315 B BISHOP.T.M. 7810170179* 50-379 Q BONNER.J.F. 7812130088 50-315 B BISHOP.T.M. 7810170179* 50-379 Q BONNER.J.F. 78121300088 50-315 B BISHOP.T.M. 7810170179* 50-379 Q BONNER.J.F. 78121300088 50-315 B BISHOP.T.M. 7810170179* 50-370 Q BONNER.J.F. 78121300088 50-315 B BISHOP.T.M. 7810170179* 50-370 Q BONNER.J.F. 78121300088 50-315 B BISHOP.T.M. 7810170179* 50-370 Q BONN.M.E. 7810300020* 50-30 BETLHAN.T.P. 7811240178* 50-315 B BISHOP.T.M. 7810100099* 50-277 Q BONN.M.E. 7810300020* 50-30 BETLHAN.T.P. 7811240178* 50-315 B BISHOP.T.M. 7810100099* 50-277 Q BONN.M.E. 7810300020* 50-30 BETLHAN.T.P. 78112001018* 50-316 B BISHOP.T.M. 7810100099* 50-277 Q BONN.M.E. 7810300020* 50-30 BETLHAN.T.P. 78112001018* 50-316 B BISHOP.T.M. 7810100099* 50-277 Q BONN.M.E. 7810200020* 50-30 BETLHAN.T.P. 78112001018* 50-316 B BISHOP.T.M. 7810100099* 50-277 Q BONN.M.E. 7810200020* 50-30 BETLHAN.T.P. 78102000208* 50-316 B BISHOP.T.M. 7810100099* 50-277 Q BONN.M.E. 78102000020* 50-30 B BONN.M.E. 78102000020* 50-30 B BONN.M.E. 78102000020* 50-30 B BONN.M.E. 78102000020* 50-30 B BONN.M.E.	BECKMAN, D. BECKMAN, D. BECKMAN, D.	78111090017# 7811100148# 7812080147#	50-247 G 50-311 G 50-334 G	BIRKEL,R.A. Birkel,R.A. Birkel,R.A.	7811200186* 7811200177* 7811200359*	50-437 A 50-437 A 50-437 A	90HN; R. J. 90HN; R. J. 90HN; R. J.	7810160136 7811030144 7810270091	50-367 F 50-367 F 50-367 50-376 F 50-367 F
BEGHAIN.L.E. 7811020177* 50-223 9 11RKEL.R.A. 7811220041 50-427 A 80LAND.E.P. 781201004& 50-428 BELLMAN.T.P. 781018018* 50-215 8 11RKEL.R.A. 7812130283 50-369 0 BULLNOH.D.I. 7811140148* 50-23 BEILMAN.T.P. 7810110192* 50-215 8 11RKEL.R.A. 7812130283 50-369 0 BULLNOH.D.I. 7811140148* 50-23 80LAND.T.P. 7810110192* 50-215 8 11RKEL.R.A. 7812130283 50-369 0 BULLNOH.D.I. 7811140148* 50-23 80LAND.T.P. 7810110192* 50-23 0 BULLNOH.D.I. 781210123* 50-23 0 BUNNER.J.F. 7812130008* 50-37 0 BUNNER.J.F. 7812130008* 50-37 0 BUNNER.J.F. 7812130008* 50-38 BELLMAN.T.P. 7811240174* 50-315 8 BISHOP,T.M. 7811270122* 50-70 0 BUNNER.J.F. 78121300018* 50-20 BELLMAN.T.P. 7811300161* 50-315 8 BISHOP,T.M. 7811010099* 50-277 0 BUNNER.J.F. 7811000012* 50-28 BELLMAN.T.P. 7811300161* 50-316 8 BISHOP,T.M. 7811010099* 50-277 0 BUNNER.J.F. 781100000000000000000000000000000000000	BEDNER: L. F. BEDROBIAN: P. BEOROBIAN: P.	7819200274* 7810310286* 7810310281*	50-298 8 50-568 A 50-568 A	BIRKEL, R. A. BIRKEL, R. A. BIRKEL, R. A.	7811200246+ 7810110019 7810250195	50-437 A 50-369 F 50-369 A	BÓHN, R. J. BOHN, R. J. BOHN, R. J.	7811170106 7811210360 7812050183	50-367 / 50-367 / 50-367 / 50-367 / 50-367 /
BEILMAN.T.P. 7811240173* 50-315 B SISHOP.T.W. 7810190092* 50-397 0 BONNER.J.F. 7812130008* 50-30 BEILMAN.T.P. 7811240173* 50-315 B BISHOP.T.W. 7810120126* 50-70 0 BONNER.J.F. 7810300020* 50-20 BEILMAN.T.P. 7811240174* 50-315 B BISHOP.T.W. 7810180191* 50-20 0 BONNER.J.F. 7810300020* 50-20 BEILMAN.T.P. 7811200181* 50-316 B BISHOP.T.P.H. 7810180191* 50-20 0 BONN.H.E. 7810300020* 50-20 BEILMAN.T.P. 7811300188* 50-316 B BISHOP.T.P.H. 7811010099* 50-277 0 BOOK.H.E. 7811060007 50-28 BEILMAN.T.P. 7812000088* 50-316 B BISHOP.T.P.H. 7811010099* 50-277 0 BOOK.H.E. 7811270102 50-34 BEILMAN.T.P. 7812000088* 50-316 B BISHOP.D.A. 7810170217 50-155 B BOOK.H.E. 7811270102 50-34 BEILMAN.T.P. 781220167* 50-315 B BISHOP.D.A. 7810110104 50-155 B BOOK.H.E. 7811270093* 50-31 BEILMAN.T.P. 781270088* 50-315 B BIXEL.D.A. 7811240170 50-155 B BOOK.H.E. 7811270093* 50-31 BEILMAN.T.P. 781270288* 50-316 B BIXEL.D.A. 7811240231 50-155 B BOOK.H.E. 7811270093* 50-31 BEILMAN.T.P. 781270288* 50-316 B BIXEL.D.A. 781240231 50-155 B BOOK.H.E. 7811270093* 50-31 BEILMAN.T.P. 7812100034* 50-261 Q BIXEL.D.A. 781240231 50-155 B BOOK.H.E. 7811270097* 50-70 BELSELP.A. 7812150063* 50-261 Q BIXEL.D.A. 7810130171 50-155 B BOOK.H.E. 7811270097* 50-70 BELL.H.H. 7811200276* 50-261 Q BIXEL.D.A. 78101200497 50-155 P BOOK.H.E. 7811270097* 50-31 BELL.H.H. 7811200276* 50-261 Q BIXEL.D.A. 78101200497 50-155 P BOOK.H.E. 7811270097* 50-31 BELL.H.H. 7811200276* 50-241 BIXEL.D.A. 7810200045 50-155 P BOOK.H.E. 7811270097* 50-31 BELL.H.H. 7811200276* 50-344 B BIXEL.D.A. 7810200049 50-155 B BOOK.H.E. 7811270097* 50-31 BELL.L.H. 7811200040* 50-344 B BIXEL.D.A. 7810200049 50-155 B BOOK.H.E. 7811270097* 50-31 BELL.H.M. 7810200040 50-31 BIXEL.D.A. 7810200040 50-35 B BOOK.H.E. 7810200040 50-31 BELL.H.D.A. 7810200040 50-31 BOOK.H.E. 7810200040 50-31 BELL.D.A. 7810200040 50-31 BOOK.H.E. 7810200040 50-31 BELL.D.A. 7810200040 50-31 BOOK.H.E. 7810200040 50-31 BOOK.H.E. 7810200040 50-31 BOOK.H.E. 7810200040 50-31 BOOK.H.E. 7810200040 50-31 BOOK.H.E.D.A. 7810200040 50-31 BOOK.H.E.D.A. 7	BEGHAIN, L. E. BEHN, J. D. BEILMAN, T. P.	7811020177* 7812270102* 7810180158*	50-223 G 50-275 F 50-315 8	Birkel, R. A. Birkel, R. A. Birkel, R. A.	7811220041 7812010148 7812130283	50-437 A 50-349 G 50-369 G	BOLAND, E. P. BOLLNOW, D. I. BOLLNOW, D. I.	7812010046+ 7810110122+ 7811140148+	50-367 F 50-471 G 50-255 F 50-255 F 50-255 F
BEILMAN, T. P., 7812080088 50-316 B SIXEL, D. A. 7810170217 50-158 B BOOK, H. E. 7811270102 50-34 BEILMAN, T. P., 7812120167 50-315 B BIXEL, D. A. 7810110104 50-135 B BOOK, H. E. 7811270093 50-31 BEILMAN, T. P., 7812120167 50-315 B BIXEL, D. A. 7811240170 50-155 Q BOOK, H. E. 7811270093 50-31 BEILMAN, T. P., 7812120167 50-316 B BIXEL, D. A. 7811240231 50-155 B BOOK, H. E. 7811270093 50-31 BEILMAN, T. P., 78121200664 50-10 Q BIXEL, D. A. 7811240231 50-155 B BOOK, H. E. 7812140072 50-70 BEL ISLE, Q. A. 7812150063 50-261 Q BIXEL, D. A. 7810160097 50-135 P BOOK, H. E. 7812150180 50-20 BELL, H. H. 7811200276 50-337 A BIXEL, D. A. 7810250065 50-135 P BOOK, H. E. 7811270097 50-31 BELL, M. A. 78102001088 50-344 B BIXEL, D. A. 7810250065 50-135 P BOOK, H. E. 7811270097 50-31 BELL, N. L. 7811200608 50-344 B BIXEL, D. A. 7810250096 50-135 B BOOK, H. E. 7811210097 50-31 BELL, N. L. 781210324 50-344 Q BIXEL, D. A. 781020099 50-135 B BORDENICK, B. M. 7810240009 30-31 BELL, N. L. 781210324 50-349 Q BIXEL, D. A. 7810310130 50-135 B BORDENICK, B. M. 7810240009 30-31 BELL, N. L. 7812100408 50-349 R BIXEL, D. A. 7810310130 50-135 B BORDENICK, B. M. 7810240009 30-31 BELL, N. L. 7812100408 50-349 R BIXEL, D. A. 7810310130 50-135 B BORDENICK, B. M. 7810240009 50-31 BERNARDYA, V. 7812040284 50-368 P BIXEL, D. A. 7811020212 50-135 P BORDENICK, B. M. 7811040004 50-31 BENARDYA, V. 7812040284 50-368 P BIXEL, D. A. 7811020212 50-135 P BORDENICK, B. M. 7811040004 50-31	BEILMAN, T. P. BEILMAN, T. P. BEILMAN, T. P.	7611240172* 7811240173* 7811240174*	50-315 8 50-315 8 50-315 8	BISHOP, T. W. BISHOP, T. W. BISSETT, P. H.	7810190093+ 7811270126+ 7810180191+	50-397 Q 50-70 Q 50-20 Q	BONNER, J. F. BOOK, H. E. BOOK, H. E.	7812130008* 7810300018 7810300020*	50-361 0 50-133 0 50-206 0 50-206 0
BELLIAL PARTICIPATION PRINCIPATION PRINCIPAL PRINCIPAL PARTICIPAL	BEILMANIT.P. BEILMANIT.P. BEILMANIT.P.	7812080048* 7812080087* 7812120167*	50-316 B 50-315 B	BIXEL D.A. BIXEL D.A. BIXEL D.A.	7810170217 7810110104 7811240170	50-155 8 50-155 8 50-155 Q	800K, H, E 800K, H, E 800K, H, E	7811270102 7811270088 7811270093#	50-288 (50-344 (50-312 (50-312 (50-70 (
BELMORE.C. I. 7810270077* 50-219 R SIXEL. D. A. 7811010163 50-133 P BORDENICK. B. M. 7810200247 50-31. BENARDYA-V. 7812040244 50-368 P BIXEL. D. A. 7811020212 50-133 P BORDENICK. B. M. 7811060108 50-31. BENARDYA-V. 7812040247 50-349 F BIXEL. D. A. 7811020212 50-135 B BORDENICK. B. M. 7811060040 50-31.	BELL: H. H. Bell: M. A.	7812150063* 7811200276* 7810200108*	50-261 G 50-437 A 50-344 B	BIXEL, D.A. BIXEL, D.A. BIXEL, D.A.	7810160097 7810250045 7811210369	50-155 P 50-155 P 50-155 B	800K; H, E 800K; H, E 800K; H, E	7812150180 7811270097+ 7812190194	50-70 0 50-206 0 50-312 0 50-133 0 50-516 0
BENDER, B. B. 7812120121* 50-295 B SIXEL, D. A. 7811060084 50-155 P BORDENICK, B. M. 7811060132 50-51	RELMORE, C. I. BENAROYA V. BENAROYA V.	7810270097* 7812040244 7612060327	50-219 R 50-368 P 50-369 F	BIXEL, D. A. BIXEL, D. A. BIXEL, D. A.	7811010145 7811020212 7811030134	50-155 P 50-155 P 50-155 B	BORDENICK: B. M. BORDENICK: B. M. BORDENICK: B. M.	7810200247 7811060108	50-516 6 50-516 6 50-516 6 50-582 6 50-314 6
BENEDICT R. A. 7810120133 50-382 F BIXEL, D. A. 7811140146 50-155 B BORDENICK, B. H. 781114019 50-58 BENEDICT, R. A. 7811220296 50-382 A BIXEL, D. A. 7811150138 50-155 P BORDENICK, B. H. 7811100162 50-58 BENEDICT, R. A. 7812130323 50-382 F BIXEL, D. A. 781200192 50-155 Q BORDENICK, B. H. 7811200060 50-488 BENEDICT, R. A. 7812130323 50-382 F BIXEL, D. A. 7812000192 50-155 Q BORDENICK, B. H. 7811200060 50-488 BENEDICT, R. R. 78103002804 50-333 Q BIXEL, D. A. 7811270094 50-155 P BORDENICK, B. H. 7811200057 50-228	SENEDICT, R. A. BENEDICT, R. A. BENEDICT, R. A.	7810120133 7811220296 7812130323	50~382 F 50~382 A 50~382 F	Bixel, D. A. Bixel, D. A. Bixel, D. A.	7811140146 7811150158 7812080192	50-155 B 50-155 P 50-155 G	BORDENICK, B. M. BORDENICK, B. M. BORDENICK, B. M.	7811140019 7811100102 7811200060	50-443 0 50-582 P 50-582 0 50-488 0 50-220 0
BENTER W. 7811220102 50-70 H BIXEL D.A. 7812040237 50-155 S BORDENICK, B. M. 7812050292 50-514 BENTER W. 7811120045 50-361 9 BIXEL D.A. 7812070215 50-155 P BORDENICK, B. M. 7811290386 50-584 BENTER TTD. J. A. 7811100045 50-361 9 BIXEL D.A. 7812070215 50-155 P BORDENICK, B. M. 7812050033 50-584	BECLETTO, J. A. BECLETTO, J. A. BECLETTO, J. A.	7811220102 7811100045 7811100046	50-70 H 50-361 Q 50-361 Q	BIXEL, D. A. BIXEL, D. A. BIXEL, D. A.	7812040237 7812070215 7812050224	50-155 8 50-155 P 50-155 P	BORDENICK, B. M. BORDENICK, B. M. BORDENICK, B. M.	7812050292 7811290386 7812050033	50-516 0 50-516 0 50-582 0 50-582 0 50-397 0
SERGER, N. 9. 7811200103 50-389 M SIXEL. D. A. 781220074 50-155 S BORDENICK, S. M. 7812130085 50-514 BERGER, N. 9. 7812040240 50-389 M SIXEL. D. A. 781220212 50-155 P SORDENICK, S. M. 7812270132 50-324 BERGER, N. 9. 7812040240 50-389 M SIXEL. D. A. 7812270130 50-155 Q SORER, P. J. 78101702979 50-294	Berger, M. G. Berger, M. G. Berger, M. G.	7811200103 7812040260 7812040032	50-389 M 50-389 M 50-346 M	BIXEL, D. A. BIXEL, D. A. BIXEL, D. A.	7812220074 7812260212 7812270180	50-155 8 50-155 P 50-155 Q	BORDENICK, B. M. BORDENICK, B. M. BORER, P. J.	7812130085 7812270132 7810170299*	50-514 G 50-514 G 50-329 G 50-298 R 50-298 R

AUTHOR	ACCEBSION NUMBER	BUBJECT CATEGORY	Y	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGOR		AUTHOR	ACCESSION NUMBER	BUB CAT
BORER . P. J.	7812130160+	50-298	R	BOYD, R. S.	7810270026	90-454	A	BRENNER. L	7811010323	50-5
BORES, R. J.	7811060247#	50-3	<u> </u>	BOYD, R B.	7811030172	50~545	A	BRENNER, L.	7611010193	50-3
BORES.R.J. BORES.R.J.	7811100181 * 7812180058*	50-286 50-3	0 0	BOYD, R. S. BOYD, R. S.	7811080330 7811140258	50-397 50-410	A A	BRENNER.L. BRENNER.L.	7811140003 7812050082	50~4 50~4
BORGMANN E. A	7810110157	50-358	Ä	BOYD, R B	7811140265*	50-410	Ä	BRENNER, L.	7812130081	30-4
BORGMANN E. A	7811210170	50-358	J	BOYD, D. C.	7812060236#	50-295	Q	BRENNER, L.	7812140123	50-3
BORGMANN, E. A	7811070370	90-358	ă	BOYD, R. S	7811130397	50-445	A	BRENNER, L.	7812160305	50-4
BORGHANN, E. A	7811010169	50-358	K.	BOYD, R. S.	7811200099	50-490	A	BRENNER L	7812140177	50-4
BORGMANN, E. A BORGMANN, E. A	781101017 1 7811070069	50-358 50-358	K K	90YD, R. B. 90YD, R. B.	78112900054 7811290006+	50-572 50-572	A	BRIGGS, L E BRIGGS, L	7811300306# 7812010276#	20-5
nonowatht e a			_	2012 5 5		** 007		401011 O D	7010116011	50-4
BORGMANN, E. A. BORGMANN, E. A	7811220008 7812060016	90-358 90-358	0	BOYD, R. S. BOYD, R. S	7812060099 7811290275	50-327 50-443	A	BRIGHT, G. D. Bright, G. D.	7812110266 7812150056	50-2
BOROMANN E A.	7812070119	50-358	K	BOYD, R. S.	7811290278	50-440	Ą	BRIGHT. G O	7812130064	50-2
BORGMANN, E. A. BORGMANN, E. A.	7612070147 7612200228	50-358 50-358	0 F	80YD+R.S. 80YD+R.S.	7811300276 7811300315	50~45B 50~424	A	BRIGHT, Q. D. Bright, Q. D.	7812200344 7812200338	90-5
			•							
BOROMANN, E. A. BOROMANN, E. A.	7812210163 7812150306	50-358 50-358	к	80YD+R. 9. 86YD+R. 9.	7811300319 7811300323	50-413 50-491	A	BRIGHT, Q. O. BRIGHT, Q. O.	7812220014 7812270002	50-2 50-2
BOROMANN, E. A.	7812190146	50-358	A	BOYD, R. S.	7811300326	50-410	Ą	BRIGHT, G O.	7812270279	50-2
BOROMANN E. A. BOROMANN E. A.	7612190084 7612200214	50-358 50-358	F K	80YD, R. S. 80YD, R. S.	7811300331 7811300360	50-346 30-367	A	BRIGHT, O. O. BRIGHT, O. O.	7812270280 7812270282	50-2 50-2
BORGMANN, E. A. BORGMANN, E. A.	7812270191 7812270305	50-358 50-358	K A	BOYD, R. S. BOYD, R. S.	7811300372 7811290395	50-363 50-367	A	BRIGHT, G. O. BROËHL, D. J.	7812290283 7810110161	50~2 50~3
BORKNIÇHT.JA.	7610270322	50-498	Ö	BOYD, R. S	7811300011+	50-329	A	BROEHL, D. J.	7810120026	50-3
BOROS: J. J. BOSNACK: R. J.	7611100094* 7811200365*	50-213 50-437	Q A	1907D, R. S. 1907D, R. S.	7811270371 7812040013	50-387 50-373	A A	BROEHL D. J. Broehl D. J.	7810200015 7810130147	50-3 50-3
BOUKNIGHT,JA BOUKNIGHT,JA	7810310179* 7810140017	50~498 50~498	M M	80YD, R. B. 80YD, R. B	7812050099 7812050279	50-352 50-389	A	BROEHL, D. J. BROEHL, D. J.	7811020103 7810240091	50-3 50-3
BOUKN1 CHT, J. A.	7811080021	50-498	М	80YD: R. B.	7811270262	50-352	Α	BROEHL D. J.	7811080228	50-3
BOUKNIGHT, J. A.	7611130259 7611130404	50-389 50-398	H M	80YD, R. S. BOYD, R. S.	7812010379 7812050006	50-382 50-404	A	BROEHL: D. J. BROEHL: D. J.	7811100114 7811070112	50-3 50-3
										_
BOUKNIGHT, J. A. BOUKNIGHT, J. A.	7811130431	50-389 50-445	H	ÓDYĎ, R. S. 6ÖYĎ, R. S.	7812050104 7612050114	50-482 50-460	A	BROEHL D J.	7812110006	50-3 50-3
BOUKNIGHT, J. A.	76:2160256 78:2270410	50-440 50-389	M H	BOYD, R. B.	7812030114 7812070061	50-460	A	BROCKS, A.B.	7611260324 7611200092*	50-3
BOURN LA. A.	7810130026	50-373	A	BOYD, A. B.	7812120005	50-412	A	9ROOK9₁ €. H.	7812140277#	50-3
BOURN LA. A.	7810120106	50-344	н	BOYD, R. B.	7812120046	50-423	A	BROOKE B. P.	7812110116*	50-4
DOURNIA, A.	7812140025	50-373	A	BOYO, R. S.	7812120179	50-461	۸	BROWN, D.	7811210374#	30-3
BOURNIA, A. BOURNIA, A.	7812200026 7812220101	50-373 50-373	A	00YD; R. B. 00YD; R. B.	7812120201 7812050369	50-400 50-438	A A	BROWN, D. BROWN, D.	7810120078* 7810310330*	50-3 50-3
BOUTHELL R. L.	7810180009*	80-29	Ë	BDYD, R. S.	7812060017	50-49B	Ä	BROWN, Q. D.	7811210121*	50-3
BOUTHELL R. L.	7811280290+	50~29	В	BOYD, R. S.	7812080223	50-322	A	BROWNLEE V. L.	7811080220*	50-3
BOUTWELL R. L.	7811290203*	50~27	8	90YD. R. S.	7812080246	90-410	A	BROWN, C.	7810310168*	50-1
BOWERS E. B. BOWERS E. B.	7810190126	50-275 50-275	•	BDYD. R. S.	7812120019	50-397	Ą	BROWN, M. S.	7810100064#	50-3
BOWERS, E. S.	7810250182 7810190160	50~275	0	80YD, R. S. 80YD, R. S	781211003 1 7812060306	50-366 50-318	A	BROWN M. S. BROWN M. S.	7810100068* 7810180032*	50-3 50-3
BOWERS, E. S.	7810250003	20-355	o .	BOYD, R. S	7812070103	50-556	L	BROWN, B. A.	7810230264	50-3
BOWERB, E. S.	7810250193	30-488	o	BOYD, R. B	7812080208	50-327	A	BROWN, S.C.	7810170109	50-4
BOWERB, E. S. BOWERB, E. S.	7811010121	50-397 50-275	0	BOYD, R. S	7812070257	50-387 50-368	A P	BROWN, B. C.	7810230307	50-4
BOWERB, E. S.	7811040021 7811070023	20-355	A Q	80Y0+R. S 80Y0+R. S	7812140013 7812140014*	50-368 50-368	P	BROWN, S. C. BROWN, S. C.	7810200054 7810230299	50~3 50~3
DOWERB, E. S.	7811080073	50~488	•	BOYD, R. S.	7812120030*	50-445	A	BROWN, 8. C.	7812010321	50-3
BOWERB, E. S.	7811070356	50~397	0	BOYD, R. B.	7812120002*	50-445	A	BROWN. B. C.	7810240140	50-3
BOWERS, E. S.	7811170007	50-275	0	90Y0, R. S.	7812140248	50-368	P	BROWNLEE, V. L.	78113001 70 *	50-4
BOWERBLE S. BOWERBLE S.	7811200427 7811210016	50-488 50-580	0	BOYD, R. B. BOYD, R. B.	7812130017 7812140275*	50-595 50-275	A O	BROWN, Q. D. BROWN, C. H.	7812130336* 7812040046*	50-0 50-2
BOWERB, E. S.	7811210026	50-448	ö	BOYO, R. S.	7812140278*	50~275	Q	BROWN, B. C.	7811060102	50~0
BOWERS, E. S.	7811200042	50-275	9	BOYD, R. O.	7812140279*	50~275	Q.	BROWNLEE, V. L.	7812270372*	50-3
BOWERS, E. S. BOWERS, E. S.	7812070260 7812080004	50-397 50-275	0	BOYD, R. Q. BOYD, R. Q.	7812150179 7812210254	50-387 50-416	A	BROWN, B.C.	7811070146	50-0
BOWERS, E. S.	7812180027	50-275	Ğ	BOYD, R. S.	7812210254	50-368	A P	BROWN, S. C. BROWN, S. C.	7811070326 7811090243	50-1 50-1
BOWERS, E.	7812150056	50-275	Y	BOYO, F. O.	7812290171	90-273	н	BROHN, S. C.	7611140129	50-2
BOWERS, E.	7812130064	50-275	T	BOYER, V. 9.	7812130098+	50-352	q	BROWN, S.C.	7811160097	50-0
BOWERS, E. BOWERS, E.	7812200344 7812200338	50-275 50-275	Ţ	BOYER, V. S. BOYER, V. S.	7812130083*	50-352 50-352	Q	BROWN, B. C.	7811210399	50-3
BOWERS, E. S.	7812210297	20-322	T 0	BOYER, V. S.	7811280248 7812110213	50~352 50~352	8 9	BROWN, S. C. BROWN, S. C.	7811210309 7811240111	50-1 50-1
SIOWERS, E. S.	7812210317	50-397	Ö	BOYTER, N. C.	7610140092*	50-313	9	BROWN, B. C.	7811280200	50-4
BOWER & E.	7812270346	50-275	1	BOYTER, N. C.	7811030036*	50-285	Q	BROWN, D. H.	7811280202*	50~:
BOWERB, E. B.	7812220014 7812280088	50-275 50-488	Ŧ	BOYTER, N. C.	7011280062*	50-285	Q.	BROWN, B. C.	7812060142*	60-0
BOWERB. E.	7812290002	50-275	D T	BRADFORD, W. H. BRADFORD, P. A.	7910310074* 7910300266*	50-259 50-389	9	BROWN, S. C. BROWN, Q. D.	7812010255 7812270244*	50-1 50-1
BOWERS. E.	7812290279	50-275	T	BRADFORD: W. H.	7810110290*	50~338	à	BROWN, M. S.	7812080089#	50-1
BOHERB. E.	7812290280	50-275	T	BRADFORD, W. H.	7810310144*	50-261	Q	BROWN, S. C.	7812120117	50-
BOWERB, E. BOWERB, E.	7812290282 7812290283	50-275 50-275	Ţ	BRADFORD, W. H. BRADFORD, W. H.	7811130241*	50-280 50-321	9	BROWN, B. C.	7812200225	50-1
BOYD, R. S.	7811200049*	50-437	T A	BRADFORD, W. H.	7811220064* 7812210350*	50-321 50-302	Q	BROWN: 8. C. BROWN: 8. C.	7812260255 7812270170	50-1 50-1
BOYD, R. S.	7812130054		A	BRADLEY, R. D.	7811300170*	80-400	à	BROWN, G. C.	7812270194	50-:
BOYD. R. S.	7812210323	50-327	A	BRADLEY, R. D.	7812210345+	50-400	G	BROWN, S. C.	7812270189	50-:
BOYD, D. C. BOYD, R. S.	7811080074* 7810130242		Q A	BRADLEY, E. J.	7812180160	50-278 50-375	P M	BRUCKNER, Q. E. BRUDER, Q. F.	7810180102*	50~:
BOYD, R. S.	7810130008	50~572	Ã	BRAND, W. E. BRATTON, J. K.	7812210374 7811210086*	50~395 50~70	U	BRUGGE, R. O.	7811070164* 7812120082*	50-
BOYD, R. S.	7610260038	50-437	A	BRATTON, J. K.	7811070351	90-70	Ā	BRUGGER, R. M.	7812270080	50~
BDYD, R. S.	7810230387	50-592	A	BREDEME IER, Q. E.	7810190217	50-344	9	BRUNETT F. V.	7810130231	50~:
BOYD, R. S. Boyd, R. S.	7810250212+ 7811010368+	50~275 50-320	A 0	BRENNER.L. BRENNER.L.	7810140140 7810140011	50~546 50-443	0	BRUNNER, E. J. BRUNNER, E. J.	7810190005# 7810270192#	50-1 50-1
BOYD, A. S.	7811010052	50-414	A	BRENNER , L.	7810140065	50-443	o	BRUNNER, E. J.	7810180177	50-
BOYD, R. S.	7811010064+	50-414	A	BRENNER, L.	7810140080	50~443	٥	BRUNNER, E. J.	7810260023#	50-1

AUTHOR	ACCEBBION NUMBER	BUDJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT Cateodry
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7810250048 7811150100* 7811300361 7811020182* 7811020178*	50-311 0 50-309 0 50-184 0 50-223 0 50-223 0	BRYANT, J. C.	7812070030* 7812070023* 7812120045* 7812150040* 7812280080*	50-364 0 50-518 0 50-395 Q 50-327 Q 50-424 Q	BURNELL.S.S. BURNELL.S.S. BUBCH.R.W. BUBCH.R. BUBHSBAUH.P.A.	7811220082* 7812080236 7811130128 7811200144 7811130254	50~349 1 50~549 4 50~522 0 50~522 0
BRUNNER, E. J.	7811080238* 7810250224 7811080090* 7811080092* 7811080244	50-219 0 50-219 0 50-286 0 50-286 0 50-286 0	BRYANT, B BRYANT, J. C. BRYANT, J. C. BRYANT, J. C. BRYANT, J. C.	7812200057+ 7812290111+ 7812290048+ 7812050352+ 7812040175+	50-554 H 50-553 0 50-390 0 50-387 0 50-395 0	BUST. B. A. BUTLER. R. M.	7812140368+ 7810230205 7811090140 7811140200 7811210326	50~266 F 50~293 I 50~471 I 50~471 # 50~471 I
BRUNNER, E. J.	7811080290 7811080091 7811090284 7811090053 7811090016	50-311	BRYAN, J. K. BRYANT, J. C. BRYAN, S. E. BRYAN, J. K. BUCHBBAUM, P. A.	7812200237 7812210048• 7812130318 7812290277 7812120233	50-483 G 50-413 G 50-244 G 50-483 A 50-354 G	BUZY, J. J. BYRD, H. F. Caba, E. Caba, E. C. Caba, E.	7811130241# 7812280254 7811070188# 7811140136# 7812130298#	50~290 C 50~338 F 50~346 E 50~346 F 50~346 F
BRUNNER, E. J.	7811100099 7811130190* 7811130192* 7811100008 7812010296*	50-311 Q 50-220 Q 50-220 Q 50-293 Q 50-317 G	BUCKLEY.B.C. BUCZW1NSKI,T.A. BUHL,A.R. BUHL,A.R. BUITER.O.H.	7812220006 7810250100* 7812010015* 7812010017* 7812150234*	50-280 P 50-329 A 50-275 A 50-275 A 50-305 8	CABA: E. CAFFEY: L. W. CAHILL: H. J. CAHILL: W. J. CAHILL: M. J.	7812120173* 7812120090 7810100067 7810110099 7810110153	50-346 E 50-537 E 50-247 E 50-247 F 50-247 E
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7810160080 7812010097* 7811100157 7811100075 7811130271	50~293 0 50-309 0 50-311 0 50-213 6 50-334 0	BURCHETTE, W. H. BURDETTE, T. E. BURDETTE, T. E. BURDETTE, T. E. BURDETTE, T. E.	78121402464 7811080220* 7811220284* 7812080052* 7812080052*	50-445 M 50-369 G 50-395 G 50-518 G 50-518 G	CAHILL, R. J. Cahill, H. J. Cahill, R. H. Cahill, W. J. Cahill, W. J.	7810160105 7810160138 7811060044* 7810200064 7810230149	50-247 E 50-247 E 50-562 G 50-3 R 50-247 R
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7811140037 7811100142 7812010132* 7810260019 7811150272*	50-311 0 50-311 0 50-219 0 50-220 0 50-317 0	BURDICK, W. B. Burger, A. Burger, A. Burger, A. Burger, A.	7812200177* 7812180404 7812180357 7812180414 7810180218	50-458 A 50-70 P 50-70 P 50-70 P 50-206 F	CAHILL, H. J. CAHILL, H. J. CAHILL, H. J. CAHILL, H. J. CAHILL, H. J.	7811140255# 7811070120 7811070274 7811070221 7811070157	50-3 G 50-3 P 50-247 F 50-247 B 50-247 P
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7811150274* 7811020060 7811300295 7811300303 7812010277	50-317 0 50-223 0 50-272 0 50-322 0 50-29 0	BURGER, A. BURGER, A. BURGHARD, H. C. BURKE, D. J. BURKE, D. J.	7810300111 7811070300 7810310227# 7811130241# 7812040242#	50-206 F 50-29 F 50-331 B 50-280 G 50-280 G	CAHILL, H. J. CAHILL, H. J. CAHILL, H. J. CAHILL, H. J. CAHILL, H. J.	7811070163* 7811200181 7811210340 7811220076 7811200155	50-247 P 50-3 F 50-3 R 50-3 L 50-247 F
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7811290387 7810270185 7811290335* 7811290338* 7812060194*	50-272 0 50-334 0 50-336 0 50-336 0 50-20 0	BURKE, D. J. BURMAGTER, M. BURNETT, P. T. BURNETT, P. T. BURNETT, P. T.	7812210113+ 7810250041 7810110236+ 7811200214+ 7812210154+	50-280 0 50-407 0 50-261 0 50-280 0 50-335 0	CAHILL, H. J. CAHILL, H. J. CAHILL, H. J. CAHILL, H. J. CAHILL, H. J.	7811220153 7811280260 7812070182+ 7812190121 7812190102	50-3 R 50-247 E 50-3 P 50-247 E 50-247 F
BRUNNER, E. J BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7812010280 7811300337 7811080229 7812010016* 7812010336	50-320	BURNETT.P.T. BURNETT.P.T. BURSEY,B. BURSEY,B. BURSTEIN.B.	7812180311* 7812130317* 7810310118 7812270139 7810180046*	50-302	CAHILL, W. J. Cahill, W. J. Cahill, W. J. Cahill, W. J. Cahill, W. J.	7812200193 7812200206 7812190174 7812190180+ 7812270188	50-247 S 50-247 S 50-3 P 50-3 P 50-3 R
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7812010047 7812010275 7812110314 7812040353 7811080082	50-286 Q 50-219 Q 50-245 Q 50-311 Q 50-286 Q	BURSTEIN S. BURSTEIN S. BURSTEIN S. BURSTEIN S. BURSTEIN S.	7810180043 7810180038 7810180040# 7810180099 7810170171	50-266 8 50-266 8 50-266 8 50-301 R 50-266 R	CAHILL, N. J. CALDWELL B. CALDWELL, R. A CALDWELL, D. M. CALHOUN, M. L.	7812210207 7811010290 7811200330* 7811220092* 7812130235	50-3 R 50-466 G 50-278 G 50-547 T 50-389 P
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7812060298 7812060365 7812110303 7811150265 7812080080	50-244	BURBTEIN B. BURBTEIN B. BURBTEIN B. BURBTEIN B. BURBTEIN B.	7810170193 7810230272 7810250108 7811240130 7811240136#	50-266 P 50-266 P 50-502 A 50-301 B 50-301 B	CALVO, J. A. CAMPBELL, J. CAMPBELL, J. CANTER, H. L. CANTER, H. L.	7812040382 7811240139* 7812110154* 7810230092* 7812080236*	50-311 # 50-304 E 50-295 E 50-70 C 50-326 C
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7812110295 7811150092 7811150184 7812200276* 7812200280*	50-336	BURSTEIN S. BURSTEIN S. BURSTEIN S. BURSTEIN S. BURSTEIN S.	7811240131 7811240134± 7810250086 7811240149 7811240155	50-301 8 50-301 8 50-502 A 50-266 8	CANTER: H. CANTER: H. L. CANTER: H. L. CANTRELL: F. B. CANTRELL: F. B.	7812070276# 7812130314# 7812270456# 7810130099# 7811280012#	50-206 0 50-275 0 50-133 0 50-321 0 50-321 0
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7812010291 7812270051 7812270149 7812270417 7812270446	50-317	BURSTEIN S. BURSTEIN S. BURSTEIN S. BURSTEIN S. BURSTEIN S.	7811240158+ 7811070374 7811140102 7811140108+ 7811140171	50~266 8 50~266 0 50~502 A 50~502 B	CAPHTON, D. L.	7810250052+ 7812010031+ 7811140043+ 7812080083+ 7812290044+	50-311 (50-277 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311 (50-311
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7812280009 7812290028 7812290042 7812010008 7812070284	50-272	BURBTEIN 8. BURBTEIN 9. BURBTEIN 8. BURBTEIN 8. BURBTEIN 8.	7811140173# 7811130203 7811150167 7811140124 7811140174	50-502 B 50-266 P 50-266 F 50-266 P 50-266 R	CAPLAN, R. CAPRA, R. CARBON, M. CARDONNE, A. T. CARLBON, D. M.	7811210467 7811070053 7811100051 7810130219* 7810240033*	50-485 50-502 50-280 50-400 50-315
BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J. BRUNNER, E. J.	7811290328 7812010090 7812010130 7812060180 7812200116	50-336 G 50-309 G 50-219 G 50-20 G 50-219 P	BURSTEIN S. BURSTEIN S. BURSTEIN S. BURSTEIN S. BURSTEIN S.	7811280240 7812010225 7812110189 7811280229 7811300179	30-302 B 30-266 P 30-266 B 30-266 P 30-502 A	CARLSON,R.T. CARLSON,R.T. CARLSON,R.T. CARLSON,R.T. CARLSON,R.T.	7812130102* 7811080192* 7811080194* 7810250194* 7811140243*	50-352 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-363 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365 (50-365
BRUNNER, E. J. BRYANT, J. C. BRYANT, J. C. BRYANT, J. C. BRYANT, J. C.	7812270057 7810110303* 7810110174* 7810250071* 7810310082*	50-336	BURSTEIN 8. BURSTEIN 8. BURSTEIN 8. BURSTEIN 8. BURSTEIN 9.	7812050188 7812270157 7812270158* 7812110110 7812120085	50-301 P 50-502 C 50-502 C 50-302 A 50-266 R	CARLBON, R. T. CARLBON, R. T. CARLBON, R. T. CARLBON, R. T. CARLBON, R. T.	7811140239* 7611140278* 7810250258 7810270284 7810270391	50-322 50-311 50-354 50-311 50-363
BRYANT, J. C.	7811070269* 7812030150* 7811070238* 7812060035* 7812010040*	50-332 Q 50-327 Q 50-375 Q 50-375 Q 50-566 Q	BURGTEIN B. BURGTEIN S. BURTIN. BURTION P. BURHELL: B. B.	7812150305 7812260169 7812010044* 7810230042* 7810120108	50~502 A 50~266 F 50~471 G 50~275 A 50~547 A	CARLBON,R. T. CARLBON,R. T. CARLBON,R. T. CARLBON,J. T. CARLBON,R. T.	7811140277* 7810250133 7810300117 7811100095 7811130135	50-311 50-412 50-334 50-443 50-387

	ACCES910N	SUBJECT	AUTHDR	ACCESBION NUMBER	SUBJECT CATEODRY	AUTIOR	ACCESSION NUMBER
AUTHOR	NUMBER	CATEGORY				CHILK.S J	7812270430
CARLBON.J D	7811130231+	50-344 0	CARTHRIGHT H R CARTHRIGHT H R	7812040211* 7812040213*	50-338 5 50-338 B	CHILK, S J	7811290309
CARLSON.R T CARLSON.R T	7811130280 7810250255	50-334 0 50-354 9	CARTHRIGHT H R	7812040215	50-338 9	CHILK.8 J	7811290359 7812040177
CARLSON R T.	7811170295	50-311 G	CARTHRIGHT. W. R	7812040217* 7812010265*	50-339 & 50-338 R	CHILK. 8 J	7812040035
CARLSONIR T.	7810250186	50-387 0	CARTHRIGHT, H R	\015010502*			7812070261
CARLSON.R T	7811300383	50-410 G	CARTHRIGHT, N. R	7812050226+	50-338 8	CHILKIB J. CHILKIB J.	7B12070261 7B12130117
CARLSON,R T	7811080175	50-363 0	CARTHRIGHT H R CARTHRIGHT H R	7812070190* 7812070195*	50-338 8 50-338 8	CHILK, B J	7812260011
CARLSON.R T CARLSON.R T	7811070373 7811300345	50-412 S 50-412 G	CARTHRIGHT W R	78121101924	50-33B S	CHO. J.	7812270073 7810300187
CARLSON R T.	7812120022	50-322 0	CARTHRIGHT, W R	7812110208	50-338 8	CHON, W. Y	7610300107
0.15/ 0.5% D. T.	70.0.0004	50-363 Q	CARTURIGHT.W R	7812110196*	50-338 5	CHOOFER'N C	7810110185
CARLSON.R T CARLSON.R T	7812120241 7812010108	50-29 0	CARTHRIGHT H R	7812200239#	50-338 8	CHOULESIN C CHOULESIN C.	7811210436* 7812060128*
CARLEON.L R	7810300156	50-263 1	CARTHRIGHT H R. CASE E. O	7812270238* 7811300102*	50-338 B 50-338 A	CHOULES, N. C.	7812290032*
CARLSON,R.T. CARLSON,R.T	7811130069 7812060344	50-387 S 50-271 G	CASE, C. P.	7812140331*	50-437 H	CHOW, E. T.	78121401474
			C+05 5 0	7812070094	50-334 0	CHRISTMAN, J. N.	7811070367
CARLEON.J D CARLEON.J D	7812130350+ 7812070045+	50-187 G 50-105 G	CASE, E. Q. CASEY, Q. E.	7812210077*	50-245 P	CHRISSOTIMOS N.	7811300268*
CARLSON R T	7811150172	50-322 B	CASEY. 9 B	7811060050	50-361 0	CHRISTOFFER.O M CHRISTIE A M	7811090044# 7812200247#
CARLSON R T	7811140229	50-355 G	CASEY, 8 8 CASSAN, V. J.	7812130093 7810300275	50-204 H 50-333 G	CHRISTMAN, J N	7012000171
CARLSON R T	7011140271	50-311 G	Charlin V. U.				70.1000000
CARLSON, R. T.	7812180078	50-20 Q	CAVANAUGH, W	7810100081 7810180117	50-313 P 50-366 P	CHRISTMAN, J N CHURCHILL, B W	7812260259 7811070322
CARLSON R T. CARLSON R T	7811280454 7812280313	50-412 S 50-318 9	CAVANAUGH, H. CAVANAUGH, H	7811160062	50-313 P	CHURCHILL, B. W.	7812130084*
CARLSON R T.	7812270453	50-333 6	CAVANAUCH. W	7811170227	50-313 0	CHURCHILL, B. W. CHURCHILL, B	7812280345 7812290100
CARLSON R T.	7811290307	50-443 5	CAVANAUGH, W	7811160121	50-368 P		
CARLSON.R T	7812290211	50-334 0	CAVANAUGH, W	7811220190	50-368 P	CHURCHILL B W	7812290105#
CARLSON.R T	7812290249	50-489 0	CERNE A C	7812290238+ 7810230202+	50-387 0 50-315 6	CHURCHILL B W	7812270452 7810270305#
CARLEON.R T CARLEON.R T	7812290234 7812080220	50-397 Q 50-423 B	CHADWELL, H. M CHADWELL, H. M	78102302024	50-315 9	CIEBZKIENICZ. B.	7811240211#
CARLSON D M	7811300117+	50-255 G	CHALLER D V	7811090225	50-315 8	CLARE, Q. H	7810170257*
CARLSON, R. T.	7012020110	30-322 S	CHALMERS, W. J.	7811140149	50-187 H	CLARK, J R	7811100125
CARLSON, R. T. CARLSON, J. D.	7812070110 7812270382+	50-322 S 50-397 G	CHAN, J.	7812270302*	50-237 8	CLARK, R. H	7810200120
CARLBON, R. T	7812180153	50-363 0	CHAN, J.	7812270289* 7811080333*	50-249 8 50-389 M	CLARK, D. CLARK, A. D.	7810170180# 7810230245
CARLBONIJ C CARLBONIR. T.	7812270436 + 7812270037	50-243 0 50-352 9	CHANANIA F.D. CHANANIA F.D	7810300083	50-395 M	CLARK. J. R.	7011170233
						OLADIZ B.D	7010080:100*
CARLSONIR. T. CARLSONIR. T	7812290254	50-322 G	CHANANIA F D CHANANIA F D	7810310327 7811090243	50-395 M 50-389 M	CLARK, D. D CLARK, R. H	7812050290# 7811200050
CARLBON.R. T	7812270469 7812280210	50-311 B	CHANANIA F D.	2815080559	30-389 M	CLARK, A. T.	7011200411
CARLTON, R. T	7810230190+	50-387 0	CHANDLER, L. J.	7810140106	50-320 0 50-70 0	CLARK, R CLARK, R. A	7811280363 7812040225*
CARROLLIJ. T.	7810140116	30-484 A	CHANDLER, L. J	7810300223	30-70 G	CEMAN, A. M	78120402234
CARROLL, J. T	7810110174+	50-317 B	CHANDLER, L. J.	7811030219	50-361 G	CLARK, L.	7812060185*
CARROLLIJ.T. CARROLLIJ.T.	7811080100 7810310216•	50-219 B 50-318 B	CHANDLER, L. J CHANDLER, L. J	7812040264 7812130375	50-320 0 50-320 0	CLARK, D. CLARK, R. H	7812110178* 7012180410
CARROLL.J.	7811050133	50-31B B	CHANDLER, L. J.	7812130088	50-320 0	CLARK, R. H.	7012180412
GARROLLIJ, T.	7811060161•	50-318 8	CHANDLER, L. J	7812270030	50-320 G	CLARK, L.	7812080073
CARROLL.J.	7811170187•	50-318 8	CHANDLER, L. J.	7812180307	50-320 Q	CLARK, R. H.	7812280177
CARROLLIJ. T	7812110093	50-219 8	CHANDLER, L. J	7812270360	50-320 0	CLARK, R. J.	7812120205
CARROLLIJ. T. CARROLLIJ. T.	7812280231 7812290089	50-219 B	CHANDLER, L. J. CHARNDFF, Q.	7812280314 7810190230	50-320 Q 50-483 Q	CLAY, E. L. CLAYTON, F. L	7812140059# 7810130068
CARROLL.J. T.	7812130174+	50-318 B	CHARNDEF. Q	7810240227	50-483 0	CLAYTON, F. L	7010100066
CARROLL, J. T	7812130187+	50-318 8	CHARNOFF, O.	7811270050+	50-483 G	CLAYTON.F. L	7810100085
CARROLL J. T.	7812130194	50-317 B	CHARNOFF, O	7612220109	50-502 G	CLAYTON, F. L.	7810110102
CARROLL J. T.	7812200241	50-317 B	CHARNOFF, G. CHASI B. B.	7812130057	50-403 Q 50-247 Q	CLAYTON, F. L.	7810180097
CARROLL.J. T. CARROLL.J. T.	7812260248* 7812200236	50-318 B 50-219 B	CHEATUM.E. L	7812260002 7812110266	30-247 Q 30-466 Q	CLAYTON.F.L.	7810180145 7810250229
CARTERIR B. CARTERIR B.	7812060286* 7811210320	50-184 G 50-184 B	CHENG, T. M. CHERRY, M. M	7812260045 7812060126	90-199 P 90-329 Q	CLAYTON.F L CLAYTON.F L	7810250238 7811070229
CARTHRIGHT. H R	7810130145*	50-338 8	CHERRY, M. M.	7812060172*	50-329 G	CLAYTON, F. L	7810180079
CARTHRIGHT H R.	7810130148+	50-338 8	CHERRY, M. M.	7812280340+	50-329 Q	CLAYTON F. L	7810180191
CARTHRIGHT. W. R	7810230291+	50-338 B	CHIANGIAN. J.	7812070187	50-400 8	CLAYTON, F. L	7810200077
CARTHRIQHT, W.	7810230260+	50-338 8	CHILDS, W. V.	7810100026	50-333 8	CLAYTON.F. L.	7810250141
CARTHRIGHT, W.R. CARTHRIGHT, W.R.	781026012B+ 7810260129+	50-338 9 50-338 9	CHILDBIH V. CHILDBIH V.	7810120046* 7810120079*	50-333 8 50-333 8	CLAYTON, F. L. CLAYTON, F. L	7810250112 7810310070
CARTHRIGHT N R.	7810260130*	50-338 8	CHILDB. W. V.	7810230189*	50-333 9	CLAYTON, F. L.	7810310131
CARTHRIGHT, W. R.	1810590131*	50-338 8	CHILDB. W. V.	7810230265*	50-333 S	CLAYTONIF. L.	7811080159
CARTHRIGHT, W.R.	7810260132+	50-338 8	CHILDS.W V.	7810230310+	50-333 8	CLAYTON, F. L.	7811130226
CARTURIONT, U. R.	7810240133*	50-338 8	CHILDS.W V.	7810240139*	50~333 g	CLAYTON: F. L.	7811080140
CARTURIGHT, U. R. CARTURIGHT, U. R.	7810240135• 7811280324•	50-338 8 50-338 8	CHILDS.W.V.	7811070323* 7811140248*	50-333 B 50-333 B	CLAYTON, F. L. CLAYTON, F. L.	7811170038 7812050010*
CARTHRIGHT, W. R.	7810260164+	50-338 8	CHILDS.W V	78112104224	50-333 B	CLAYTON F. L.	7811090183
CARTHRIGHT, H. R.	7810310242+	50-338 B	CHILDS. W.V.	7812040159+	50-333 8	CLAYTON, F. L.	7011140000
CARTHRIGHT, H. R.	78103102524	50-338 8	CHILDS. W. V.	7812070178*	5 0-333 8	CLAYTON, F. L.	7811140085 7611140152
CARTHRIGHT, W. R. CARTHRIGHT, W. R.	7611060237#	50-338 8	CHILDS, W. V.	7812220100#	50-333 8	CLAYTON, F. L.	7811140225
CARTHRIGHT, H. R.	7811060240+ 7811060242+	50-338 8 50-338 8	CHILDB.W V. CHILES.L.	7812270250* 7812080211*	50-333 S 50-302 U	CLAYTON, F. L. CLAYTON, F. L.	7811140111 7811210355
CARTHRIGHT, U. R.							
CARTHRIGHT, U.R. CARTWRIGHT, H.R.	7811060245± 7811070261±	50-338 B 50-338 B	CHILK.B J. Chilk.S.J.	7810230026 7810230152	50-70 0 50-331 8	CLAYTON.F.L. CLAYTON.F.L.	7811210176 7811270176
CARTHRIGHT, W. R.	7811170184*	50-338 8	CHILK, 8. J.	781030 027 7#	50~389 8	CLAYTON, F. L.	7811270176
CARTHRIGHT.W.R. CARTHRIGHT.W.R.	7811170189* 7811210294*	50-338 8 50-338 8	CHILK, S. J. Chilk, S. J.	7810230315	50-338 Q 50-247 Q	CLAYTON, F. L.	7011280283
				7810260201	JU-E4/ V	CLAYTON.F. L.	7811280336
CARTHRIGHT, W. R. CARTHRIGHT, W. R.	7811210315	50-338 8	CHILK, B. J.	7811010118	50-389 0	CLAYTON, F. L.	7811280258
CARTHRIGHT, W. R.	7611280325* 7811280330*	50-338 S 50-338 S	CHILK.B.J. Chilk.B.J.	7811070040 7811150252	50-437 G 50-329 G	CLAYTON, F. L. CLAYTON, F. L.	7811280267
CARTHRIGHT H. R.	7811280320*	50-338 8	CHILK, B. J.	7811290184	50-247 G	CLAYTON F. L.	7812010253 7812050159
CARTHRIGHT, N. R.	7811280321+	50-338 8	CHILK. B J.	7812010154	50-247 G	CLAYTON, F. L.	7812110134

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGOR
CLAYTON,F. L CLAYTON,F. L CLAYTON,F. L CLAYTON,F. L CLAYTON,F. L	7812130131 7812140117 7812270169 7812210202 7812200163	50-348 P 50-348 G 50-348 F 50-348 R 50-348 B	CONNER, E. L. CONNER, T. B. CONNOLLEY, J. CONNOLLEY, J.	7812270354 7812280197 7810110117* 7810300258 7810180162*	50-317 P 50-477 Q 50-285 B 50-351 Q 50-285 B	COOPER. J COOPER. J COOPER. J COOPER. J COOPER. J	7811290307* 7812010247* 7812200181* 7812200273* 7812180155*	50 - 302 50 - 302 50 - 302 50 - 302
CLAYTON, F. L. CLAYTON, F. L CLAYTON, F. L CLAYTON, F. L CLEBBCH, A.	7812270308 7812270306 7812270127 7812270278 7810230134	50~348 8 50~348 8 50~348 P 50~348 8 50~274 P	CONBON'N H CONNOTIES'N CONNOTIES'N CONNOTIES'N	7811210371* 7812210304 7812270217* 7812270224* 7811200369*	50-285 8 50-335 P 50-285 8 50-285 8 50-437 A	COOPER.J COOPER.J COOPER.J COOPER.J COPELAND,J O.	7812220084* 7812220105* 7812270243* 7812270273* 7810130195	50-302 50-302 50-302 50-302 50-466
CLEBRCH.A CLEBBCH.A. CLEBZKIENICŽ, B. CLEVELAND, J. H	7611090063 7612200238 7611150049* 7612160228* 7611080008*	50-274 P 50-274 H 50-220 G 50-237 S 50-275 A	CONRAN, J H CONRAD, V. L CONRAD, V. L CONRAD, V. L CONRAD, V. L	781 130334 781 130135 781 2050285* 781 2130138 781 2270231	50~584 A 50~556 S 50~556 G 50~556 A 50~556 A	COPEL AND, J G. COPEL AND, J G COPEL AND, J G COPEL AND, R L COPEL AND, J G	7810110294 7810140159 7810130091 7810170154 7811080054	30-466 30-466 30-466 30-337 30-466
CLEVELAND, J. H. CLOUD, J. D. COALWELL, T. N. COCHRAN, B. J. COCHRAN, B. J.	7811200384* 7812010153 7810110078 7811300339* 7811220264*	50-275 A 50-546 A 50-264 J 50-390 G 50-395 G	CONTE.R.J. CONTE.R.J. CONTE.R.J. CONWAY.W.F.	7811270389+ 7812110301+ 7812270449+ 7812180173 7812180176+	50-272 0 50-336 0 50-220 0 50-271 9 50-271 9	COPELAND, J. G. COPELAND, R. L. COPELAND, R. L. COPELAND, J. G. COPELAND, J. G.	7812050037 7812110014 7811170177 7812110256 7812040024	50-466 50-537 50-537 50-466 50-466
COCHRAN.T.B COHEN.R.C. COHN.B.B. COHN.D.B COLBERT.W F	7811130391* 7811020381 7811270009 7812180077 7811090172*	50-220 P 50-329 G 50-483 G 50-483 G 50-341 B	CONHAY, W.F. CONHAY, W.F. CONHAY, W.F. CONHAY, W.F. CONHAY, W.F.	7812180193 7812180199# 7812180213 7812180216# 7812180190	50-271 S 50-271 S 50-271 S 50-271 S 50-271 S	COPELAND, J. Q. COPELAND, J. Q. COPELAND, J. Q. COPELAND, J. Q. COPELAND, R. L.	7812070058 7812120224 7812040331 7812050046 7812050276	50-466 50-466 50-466 50-466 50-537
COLEMAN, W.E. COLEMAN, W.E. COLLING, W. COLLING, P.F. COLLING, P.F.	7812070295* 7812010282* 7811280494* 7810180173 7810140099	30-219 @ 50-320 @ 50-331 P 50-344 V 50-309 H	CONHAY, W F CONHAY, W F CONHAY, W F CONHAY, W F. CONHAY, W F.	7812180194* 7812180237 7812180241* 7810310244 7810310248*	50-271 8 50-271 8 50-271 8 50-271 8 50-271 8	COPELAND, J G COPELAND, J. G COPELAND, J. G COPELAND, R. L CORDARD, W. M	7812130026 7812130219 7812130020 7812200243 7812210006	50-466 50-466 50-466 50~537 50-305
COLLING,PF COLLING,PF, COLLING,PF, COLLING,PF, COLLING,PF,	7810170281 7810190130 7810190035 7810230380 7810230384	50-387 A 50-266 P 50-592 E 50-382 A 50-341 A	CONHAY, W. F.	7811160102 7811160103* 7811160128 7811160130* 7812180219	50-271 8 50-271 8 50-271 8 50-271 8 50-271 8	CORE, M CORE, M. CORKIN, C. CORKIN, C CORKIN, C	7812200267 7812200231 • 7810310286 • 7810310281 • 7810110310	50-285 50-285 50-549 50-548 50-443
COLLINS.P.F. COLLINS.P.F. COLLINS.P.F. COLLINS.D.M COLLINS.P.F.	7810300284 7811130127 7811130132 78122803484 7810170110	50-89 V 50-188 F 50-204 V 50-250 G 50-261 V	CONHAY: W. F. COOK: K. W. COOK: K. W. COOK: K. W. COOK: R. J.	7812180222* 7812110272 7812110274* 7812110277* 7812060070*	50-271 8 50-277 P 50-277 P 50-277 P 50-329 Q	CORKIN.C. CORVELL.G.P COSTLE.D.M COSTLE.D.M. COTA.P.C	7811200146 7811130014* 7810140048* 7812060157* 7811170048	50-443 50-332 50-213 50-437 50-341
COLLING.P.P. COLLING.P.P. COLLING.P.F. COLLING.P.F. COLDING.P.F.	7810180170 7812050317 7812130089 7812210025 78101000564	50-261 V 50-502 R 50-369 F 50-413 A 50-312 B	COOK. R. J. COOKE. H. D. COOKE. T. C. COOKEY. M. J. COOKEY. M. J.	7812140139* 7810120038 7812260188 7810100082 7810100096	50~329 G 50~97 P 50~329 A 50~277 B 50~278 B	COTE, F. M COTE, F. M COTNER, M. L COTTLE, W. T. COTTLE, W. T.	7811150127 7811130336 7812140168 7810230072* 7810310319*	50-592 50-341 50-361 50-335 50-369
COLOMBO, R. H. COLOMBO, R. H. COLOMBO, R. H. COLOMBO, R. H. COLOMBO, R. H.	7810100077* 7810100021* 7810100069* 7811030152* 7811030156*	50-312 B 50-312 B 50-312 B 50-312 B 50-312 B	COONEY M. J. COONEY M. J. COONEY M. J. COONEY M. J. COONEY M. J.	7810100101 7810100038 7810130155 7810130163# 7810200094	50~277 9 50~277 9 50~277 9 50~277 9 50~277 9	COTTLE, H T. COUGHLIN, J. COUGHLIN, J. COUGHLIN, J. COUGHLIN, J.	7611130364* 7610110136 7610300365 7610300164 7611130176	50-369 50-546 50-546 50-546 50-546
COLOMBO: R. N. COLOMBO: R. N. COLOMBO: R. N. COLOMBO: R. N. COLOMBO: R. N.	7810110126* 7810130135* 7810170201* 7810200106* 7810230285*	50-312 R 50-312 B 50-312 B 50-312 B 50-312 B	CODNEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J.	7810230164 7810270261 7810270270* 7810240164 7811070137	50~277 R 50~278 B 50~278 B 50~278 B 50~277 B	COUGHLIN J. COULBON-CURRIN COUNBIL. H. O. COUNBIL. H. O. COUNBIL. W. O.	7812130128 7811080047* 7810110140 7810110176 7810260182	50-546 50-556 50-245 50-245 50-213
COLOMBOR. W. COLOMBOR. W. COLOMBOR. W. COLOMBOR. H COLMELLIJ. W.	7811140078# 7811140236# 7812200197# 7812110173# 7812210235#	50-312 R 50-312 8 50-312 R 50-312 B 50-275 A	COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J.	7811090141 + 7811090146 - 7811090152 + 7811160095 - 7811140142	50-277 9 50-277 9 50-277 8 50-277 8 50-277 R	COUNBIL.H. 0. COUNBIL.H. 0. COUNBIL.H. 0. COUNBIL.H. 0. COUNBIL.H. 0.	781013013B 7810170140 7810170210 7810200060 7810240099	50-245 50-245 50-336 50-336 50-245
COLWELL, J. W. COLWELL, J. W. COMPTON, R. M. COMPTON, R. M. COMPTON, R. N.	7812210209* 7812210225* 7810250091* 7812040291* 7812150040*	50~275 A 50~275 A 50~424 Q 50~327 Q 50~327 G	CDONEY, M. J. CDONEY, M. J. CDONEY, M. J. CDONEY, M. J. CDONEY, M. J.	7811160084 7811280225 7811280227 7811280230# 7812070210	50-277 R 50-277 B 50-278 B 50-278 B 50-278 B	COUNBIL, W. Q.	7810260171 7810270203 7810310073 7811210178 7810310077	50-213 50-245 50-245 50-245 50-496 50-336
CONLON, T. E. CONLON, T. E. CONLON, T. E. CONLON, T. E. CONLON, T. E.	78102402104 78101301014 7811080158* 7811150067* 7811200034*	50-390 0 50-413 0 50-395 0 50-398 0 50-324 0	CODNEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J.	7812070213* 7812070173 7812130162 7812130130 7812220063	50-277 8 50-277 8 50-277 8 50-277 8 50-277 8	COUNBILIM, OL COUNBILIM, OL COUNBILIM, OL COUNBILIM, OL COUNBILIM, OL	7811030097 7811070196 7811160152 7811090132 7811130193	50-213 50-336 50-245 50-423 50-213
CONLON, T. E. CONLON, T. E. CONLON, T. E. CONLON, T. E. CONLON, T. E.	7812040068# 7811240033# 7811020360# 7812050172# 7812070320#	50-370 0 50-250 0 50-364 0 50-276 0 50-269 0	COONEY, M. J. COONEY, M. J. COOPER, J. COOPER, J. COOPER, J.	7812210165 7812290198 7810200158# 7810110152# 7810110120#	50-278	COUNSIL.W. O. COUNSIL.W. Q. COUNSIL.W. Q. COUNSIL.W. Q. COUNSIL.W. Q.	7811140155 7811170217 7811290332* 7811170208 7811210232	50-213 50-213 50-336 50-213 50-336
CONLON, T. E. CONNER, T. B. CONNER, T. B. CONNER, T. B. CONNER, T. B.	7812290128* 7810270313 7810310017 7811030038 7811290066	50-327	COOPER, H. P. COOPER, J. COOPER, J. COOPER, J. COOPER, J.	7810180111# 7810170252# 7810180155# 7810180107# 7810240124#	50-302 B 50-302 B 50-302 B 50-302 B 50-302 B	COUNBIL.W. Q. COUNBIL.W. Q. COUNBIL.W. Q. COUNBIL.W. Q. COUNBIL.W. Q.	7812210036* 7811240187 7811170210 7811270183 7812070184	50-245 50-245 50-336 50-213 50-245
CONNER, T. B. CONNER, E. L. CONNER, T. B. CONNER, T. B. CONNER, E. L.	7811220159 7811290209 7812130025 7812130279 7812180265	50-510 0 50-326 P 50-395 0 50-358 0 50-317 F	COOPER, J. COOPER, J. COOPER, J. COOPER, J. COOPER, J.	7810240162* 7810310141* 7810310169* 7811070235* 7811160140*	50-302 8 50-302 8 50-302 8 50-302 8	COUNSIL.W. O. COUNSIL.W. Q. COUNSIL.W. Q. COUNSIL.W. Q. COUNSIL.W. Q.	7812290061* 7812080121 7812210101 7812260012 7812180143	50-336 50-245 50-213 50-245 50-245

AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
CDUNBIL.W.O. CDUNBIL.W.O. CDUNBIL.W.O. CDUNBIL.W.O. CDUNBIL.W.O. COWAN.F.P.	7812190083 7812260168 7812200187 7812280137 7812280137	50-245 P 50-476 A 50-336 P 50-336 0 30-344 G	CREMB, E. H CREMB, J. L. CREMB, J. L. CREMB, J. L. CREMB, J. L.	7811220184 7812130301 7812270432 7812270430 7812280355	50-395 A 90-275 G 50-243 G 50-133 G 50-344 G	CUTCHINIJ M CUTCHINIJ M CUTCHINIJ M CUTCHINIJ M CUTCHINIJ M	7811150018 7811150040 7811280416 7811290004 7812290108	50-443 50-368 50-443 50-387 50-387
COHAN, B. Z. COHAN, F. P. COHAN, F. P. COHAN, B. Z. COHAN, B. Z.	7810160112 7810160221 7810230109 7810230383 7811150257	50-437 0 50-344 0 50-344 0 50-437 0 50-437 0	CREMB.E.H CREMB.J.L CREMB.E.H CREMB.J.L CREMB.J.L	7812130364 7812270377 7812050231 7812070126 7812130331	50-395 0 50-397 0 50-395 F 50-344 0 50-187 0	CYR.K D DAIL.L C DAIL.L C DAIL.L C DAIL.L C	7812130036 7810260081 7812040277 7810300330# 7810130076	50-556 50-413 50-413 50-488 50-413
COX, E, L. COX, E, L. COX, T, H. COX, T, H. COX, T, H.	7810180146 7810310051 7810110209 78101190067 7812130044*	50-536 8 50-556 B 50-566 A 50-566 A 50-566 G	CREMB. E. M CREMB. E. M CRINIGAN P. T CRINIGAN P. T CROCKER. L. P	7812120200 7812120156 7810130176+ 7811030117+ 7810240017+	50-395 R 50-395 A 50-317 8 50-317 8 50-329 A	DAIL.L C DAIL.L C BAIL.L C DAIL.L C DAIL.L C	7810230214 7810250217 7811290227 78112010143 7812130287	50-413 50-413 50-413 50-488 50-491
CDZENS, Q. Crabtree, R. A Crabtree, R. A Crahilu, W. J. Crandall W. E.	7811020251* 7810120066 7810230137 7812190075 7811020248	50-187 P 50-309 J 50-309 J 50-247 P 50-187 P	CROCKER.H W CROCKER.H.W CROCKER.H.W CAOCKER.H.W CROCKER.H.W	7811100165* 7812060300* 7812010087* 7811020183* 7811020179*	50-284 0 50-184 0 50-286 0 50-271 0 50-271 0	DAIL, L. C DAIL, L. C. DAIL, L. C DAILEY, E. H. DAIVS, C. L.	7812200312 7812210035 7812210059 7811160126 7811300013*	50-488 50-413 50-413 50-568 50-335
CRANDALLIW.E. CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A.	7812130342* 7812060276 7810140114 7810130058 7810190071	50-187 @ 50-133 P 50-275 A 50-275 A	CROCKER.H.W CROCKER.H.W CROCKER.H.H. CROCKER.H.H CROCKER.H.W	781 0250136+ 781 1080260+ 781 1090032+ 781 1090034+ 781 1140259+	50-286 0 50-219 0 50-317 9 50-317 0 50-3 0	DALTON, A. DALTON, A. T.	7810300211 7811290105 7812050052 7812130196 7812130341	50-554 50-556 50-556 50-556 50-556
CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, E. CRANE, P. A.	7810170179 7810310226 7810170221 7810300074 7810170205	50-275 A 50-275 A 50-275 A 50-466 A 50-275 A	CROCKER, H. W. CROCKER, H. W. CROCKER, H. W. CROCKETT, J. D CROCKETT, J.	7811140256+ 7811300246+ 7811150043+ 7811080146+ 7811080161+	50-3 Q 50-334 Q 50-220 Q 50-336 B 50-336 B	DALTROFF, 8. L.	7811010089* 7810110105 7812010012* 7811300217 7812180221	50-277 50-277 50-277 50-277 50-277
CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A.	7810160118 7810170229 7810180028 7810240113* 7810300350	50-275 A 50-275 A 50-133 B 50-133 P 50-275 G	CROCKER, L. P. CROCKETT, J. CROCKETT, J. CROCKER, L. P. CROCKER, L. P.	7812130044+ 7812030161+ 7812120129+ 7812200296 7812210167	50-566	DALTROFF, B.L. DAMBLY, D.C. DANCE, H.C. DANCE, H.C. DANCE, H.C.	7812260192 7812270419 7810110302* 7810250154* 7811100030*	50-277 50-556 50-324 50-302 50-302
CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A.	7611080257 7611010039 7610240111 7611080040 7611280488	50-275 A 50-275 G 50-133 P 50-275 A 50-275 G	CROBSMAN, H. A CROSSMAN, H. A CROSSMAN, H. A CROSSMAN, H. A CROSSMAN, H. A.	7810230015# 7810240236# 7811030040# 7811040105# 7611070308#	50-445	DANCE, H. C DANCE, H. C. DANCE, H. C DANCE, H. C. DANCE, H. C.	7811220256* 7811280012* 7812050076* 7812050350* 7812150063*	50-261 50-321 50-302 50-321 50-261
CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A.	7811070111 7811070271 7811140126 7811210164 7811220181	50-275 G 50-275 A 50-275 K 50-275 F 50-275 A	CROBBMAN, W. A. CROBBMAN, W. A. CROWLEY, B. R CROWLEY, B. R CROWLEY, B. R.	7811280054* 7812210179* 7810240210* 7811150067* 78120400684	50-556 0 50-445 0 50-390 0 50-395 0 50-390 0	DANCE, H. C. DANIELBON, D. H.	7812180325* 7812180345* 7812280294* 7812200161* 7810190029*	50-259 50-324 50-321 50-13 50-305
CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A.	7812030135 781214085 7812210229 7812210227 7812210223	50-275 E 50-275 G 50-275 A 50-275 A 50-275 A	CROWLEY, B. R. CROWLEY, B. CULP, R. H. CULP, R. H. CULP, R. H.	7812180353+ 7812280315+ 7811080054 7812040024 7812040331	50-416 G 50-395 G 50-466 G 50-466 G	DANTELSON, D. H. DANTELSON, D. H. DANTELSON, D. H. DANTELSON, D. H. DANTELSON, D. H.	7811010059* 7811090007* 7811130350* 7811020111* 7811140269*	50-373 50-341 50-329 50-315 50-341
CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A. CRANE, P. A.	7812130002 7812120161 7812210193 7812190143 7812260217	50-133 J 50-275 A 50-275 A 50-275 A 50-275 A	CULP, R, H CULP, R. H CULP, R. H CULP, R. H CUNNINOHAM, A. L.	7812050046 7812130020 7812130026 7812130219 7811080191*	50-466	DANTELSON, D. H. DANTELSON, D. H DANTELSON, D. H. DANTELSON, D. H DANTELSON, D. H.	7811140054* 7811150088* 7812140028* 7812060178* 7812080057*	50-329 50-331 50-329 50-246 50-358
CREED, J.R. CRESWELL, J. B. CREWB, J. L. CREWB, J. L. CREWB, J. L.	7812060391* 7811290326* 7810240092 7810240094* 7810230090	50-315	CURNENGHAM, A. L. CURNENGHAM, A. L. CUNNENGHAM, O. E. CUNNENGHAM, O. H. CUPP, E. A.	7811130393+ 7812050249+ 7811070115 7811200423 7812180331+	30-364 Q 30-250 Q 50-70 P 50-295 Q 30-267 Q	DANIELSON, D. H. DANIELSON, D. H. DANIELSON, D. H. DANIELSON, D. H DANIELSON, D. H.	7812140066* 7812270156* 7812200308* 7812210131* 7812270078*	50-331 50-341 50-374 50-266 50-409
CREWB, J. L. CREWB, J. L. CREWBE, R. G. CREWB, E. H. CREWB, E. H.	78102300924 7811130227 7810260147 7810120137 7810170105	50-70 G 50-344 G 50-320 P 50-395 A 50-395 A	CUPP, E, A CURRAN, J. M. CURRAN, J. M. CURRAN, J. M. CURRAN, J. M	7812210184* 7810130139 7812130280 7811140181* 7811140080	50-298 G 50-206 R 50-206 B 50-206 B 50-206 R	DARBY, C. B DARBY, C. B. DARMITZD., R. W. DARMITZEL, R. W. DARMITZEL, R. W.	7812040072 7812040084* 7812180435 7812180401* 7810110165	50-397 50-397 50-30 50-70 50-70
CREMB, E. H. CREMB, J. L. CREMB, J. L. CREMB, E. M. CREMB, E. H.	7810230161 7811270111 7811220263 7810300217 7810310083	50-395 A 50-344 O 50-275 O 50-395 A 50-395 A	CURRAN, J.M. CURRAN, J.M. CURTIB, J.R. CURTIB, N.W. CURTIB, N.W.	7811280281* 7812190157 7810300020* 7810120069 7810260033	50-206 R	DARMITZEL, R. W DARMITZEL, R. W. DARMITZEL, R. W. DARMITZEL, D. W. DATTILO, T. M.	7811130177 7812080131 7812140121 7812280275 7810230229	50-18 50-70 50-70 50-70 50-346
CREWS, E. H. CREWS, J. L. CREWS, J. L. CREWS, J. L. CREWS, E. H.	7811010173 7812070246* 7812130346* 7812130347* 7811010120	50-395 C 50-361 G 50-187 G 50-187 G 50-395 K	CURTIS, N W. CURTIS, N W. CURTIS, J. R. CURTIS, N W. CURTIS, N W.	7811130073* 7811170123 7812150185* 7811200190* 7811200165	50-387 A 50~206 G	DAUGHERTY, T. M. DAUGHERTY, T. M. DAUGHERTY, T. M. DAVENPORT, B. G. DAVIDBON, J. A	7810160112 7811150257 7812210451 7810110092* 7812080142*	
CREMB, E. H. CREMB, J. L. CREMB, J. L. CREMB, E. H. CREMB, E. H.	7811010125* 7812070041 7812080237 7811070128 7811210286	50-395 K 50-106 G 50-326 G 50-395 A 50-395 K	CURTIS E. CURTIS N W.	7812080028 7811200185 7811270114 7812050178 7812120096	50-367 Q 50-387 K 50-387 A 50-387 A 50-387 A	DAVIDBON D. R. DAVIDBON J. A. DAVIDBON D. R. DAVIDBON D. R. DAVIDBON D. R.	7810110261* 7811140131* 7810100007 7811270022 7812070223	
CREMB, J. L. CREMB, E. H. CREMB, J. L. CREMB, J. L. CREMB, J. L.	7812070283 7811150181 7812140037 7812130316 7812150001	50-206 G 50-395 F 50-312 G 50-344 G 50-275 G	CURTIS N. W. CURTIS N. W. CURTIS N. W. CURTIS N. W. CUTCHIN J. M.	7812130118 7812210168 7812210173 7812210177 7810140002	50-387 C 50-387 A 50-387 A 50-387 A 50-387 O	DAVIB.D.L. DAVIB.D.K. DAVIB.D.K. DAVIB.A.B. DAVIB.A.B.	7811290026 7812140038* 7812140311* 7810110052 7810110263	

****	7810260179 7811170245*	50~155 50~324	0	DAVIS. J. Q. DAVIS. J. Q.	7812280104 7812280107	50-341 50-220	A P	DENTON: H. R. DENTON: H. R.	7811200044 7811030077	50-70 50-458	0 H
	7810300375 7810110248 7811300398	50-315 50-556 50-263	Q Q	DAVIB. J. Q. DAVIB. J. Q. DAVIB. J. Q.	7812280108 7812280110 7812280112	50-409 50-367 50-213	P P	DENTONAH R. DENTONAH R. DENTONAH R.	7811070059 7811080024 7811130341	90-566 50-584 50-580	A H
	7812010065 7810130252 7811080077	50-305 50-556 50-254	G G G	DAVIS, J. Q. DAVIS, J. Q. DAVIS, J. Q.	7812280113 7812280114 7812280117	50-568 50-261 50-29	A P P	DENTON, H. R. DENTON, H. R.	7811140157 7811210250 7811220107	50-440 50-591 50-272	F A B
	7811070037 7810140165	50-2 50-556	0	DAVIS, J. Q. DAVIS, J. Q.	7812280119	50-329 50-305	A P	DENTON: H. R. DENTON: H. R. DENTON: H. R.	7811220107 7811200089 7811220184	50-70 50-220	A P
	7611090298 7611170316	50-6 50-255	0 0	DAVIB.J.O. DAVIB.J.O.	7812280121 7812280123	50-271 50-440	P A	DENTON, H. R. DENTON, H. R.	7811240117 7811280157	50-70 50-459	H I
	7811140185 7810200018 7810200203	50-315 50-346 50-10	G G G	DAVIS.J.Q. DAVIS.J.Q.	7812280124 7812280126 7812280129	20-10 20-3 20-348	ሉ የ የ	DENTON, H. R. DENTON, H. R. DENTON, H. R.	7811300406 7812060260 7812060376	50-382 50-269 50-549	A P A
	7810300068 7810270087	50-204 50-554	P O	DAVIB.J.G. DAVIB.J.G.	7812280131	50-280	P P	DENTON H. R. DENTON H. R.	7812130293	50-317 50-260	ь Б
	7811290358* 7811290356*	50-400 50-400	Č	DAVIS, J. Q. DAVIS, J. Q	7812280138 7812280140 7812280141	50-293 50-317 50-259	P P	DENTON, H. R. DENTON, H. R.	7812110097 7812120014 7812120017#	50-424 50-424	6
	7810270240* 7810310105*	50-317 50-317	8	DAVIE, J. O.	7812280143	50~52B 50~313	A P	DENTON, H. R. DENTON, H. R.	7812120018*	50-424	o P
	7810310200* 7811010041*	50-317 50-244	9 G	DAVIE, J. O. DAVIE, J. G.	7812280148 7812280149	50~34B 50~315	P P	DENTON, H. R. DENTON, H. R.	7812180378 7812210326	50-387 50-546	A H
	7811290393 7811300397	50-123 50-373	0 0	DAVIS, J. Q. DAVIS, J. Q.	7812280150 7812280153	50~483 50~445	A	DENTON, H. R. DENTON, H. R.	7812180329 7812270003	50-70 50-220	P
	7812010284 7811130144	50-409 50-318	0 B	DAVIS.J.O.	7812280154 7812280155	50~346 50~312	P P	DENTON H R. DENTON H R.	7812280274 7812290240	50-267 50-272	H P
	7811010036 7811080222	50-244 50-356	0 6	DAVIB.J.Q. DAVIB.J.Q.	7812280156 7812280160	50-245 50-416	P A	DENTON, H. R. DESYLVA, D. P.	7812270242 7811160001	50~498 50~463	A F
	7811290327	50-346	Œ	DAVIB. J. Q.	7812280161	20~599	н	DEBYLVA, D. P	7811080073	50-48B	Q
	7811010116* 7812080219*	50-317 50-13	9 0	DAVIB.J.Q. DAVIB.J.Q.	7812280162 7812280163	20~385 20~355	A P	DEVINCENTIS, J. DEVLIN, J. W.	7810110078 7811010135*	50~568 50~443	A Q
	7811160158 7811160159*	50-354 50-356	0	DAVIS, J. Q. DAVIS, J. Q.	7812280164 7812280165	50~482 50~219	P P	DEVLIN. J. W.	7812150240 + 7812280309 +	50-245 50-293	0
	7012060293*	30-261	a	DAVIB.J.Q.	7812280166	50~461	A	DEWEASE, J. Q.	7811020362	50-259	8
	7811130214 4 7811140170*	50-318 50-318	B B	DAVIB. J. Q. DAVIB. J. Q.	7812280167 7812280168	50~331 50~466	P A	DEHEABE, J. O. DEHEABE, J. O	7810160109# 7810250035	50-259 50-259	B
	7811220014 7811240018	50-556 50-556	0	DAVIS, J. G. DAVIB, J. G	7812280169 78122801 7 0	50~458 50~021	A P	DEWEASE, J. Q. DEWEASE, J. Q.	7810160106 7810250083*	50-259 50-259	P P
	7811200052	50-2	Q .	DAVIB.J.Q.	7612280171	20~520	P	DEWEASE, J. Q	7810170161*	50-259	R
	7812040186 7812030055	50-556 50-556	0	DAVIS.J.Q. DAVIS.J.Q.	7812280172 7812280173	50~302 50~269	P P	DEHEASE, J. Q. DEHEASE, J. Q.	7811140137 7812070264	50-260 50-259	₽
	7612030058* 7812050061	50-556 50-556	9	DAVIB.A.D DAVIB.D.K.	7812140252 7812260051	50~366 50~298	G P	DEWEABE, J. O. DEWEABE, J. O.	7812190161 7812190162*	50-259 50-259	R R
	7811170171*	50-318	В	DAVIB. A. B.	7612260314	50-255	Ò	DEHEY, L. B.	7811200103	50-369	М
	7811280430 7812080203e	50-10 50-546	P A	DAY, P. L. DAY, P. L.	7810310375 7811200400	50-466 50-466	о Н	DEMEY, L. S. DEMEY, L. S	7812040260 7812140092	50-387 50-387	M
	7812190172* 7811270258	50-344 50-344	Q P	DEALE, V. B. DEBREMAECKER, J.	7812180418 7810230018*	50-338 50-466	0	DEYDUNG: R. C. DEYDUNG: R. C.	7811200243* 7811200032*	50-437 50-437	A
	7812200299	50-255	a	DEBREMAECKER, J	7811220274	50-466	ō	DEYOUNG R. C.	7811200093*	50-437	A
	7811210409* 7811300199*	50-317 50-317	8 8	DEBREMAECKER, J. DECK, J.	7812030115 7810240003	50-466 50-437	Q A	DEYOUNG R. C. DEYOUNG R. C.	7811200043* 7811200419*	50-437 50-437	٨
	7811240047 7812210003	50-440 50-35B	0	DECK. J. DECK. J.	7810240086 7811290261	50-437 50-437	Ä	DEYOUNG R. C. DEYOUNG R. C.	7811200403* 7811200172*	50-437 50-437	A
	7812210005#	50-358	ä	DEFALCO, P.	7912050174	50-592	p	DEYDUNGIR. C.	78112001964	50-437	A
	7812070244 7812280224	50-536 30-456	Q Q	DELAND, L. H. DELAPORTE, C. T.	7811080145 7811070123	50-344 50-568	Q A	DEYDUNG, R. C. DEYDUNG, R.	7811200310± 7811200224+	50~437 50~437	A
	7812290059 7812130036	50-255 50-556	0	DELFING, J. B. DELFING, J. B.	7811070361 7811240096#	50-70 50-70	G U	DEYOUNG R. C. DEYOUNG R. C.	7812210323 7811300036	50-327 50-280	A P
	7811290267*	50-317	8	DELOEORGE, L. O.	7810100035	50-373	Ā	DEYOUNG R. C.	7811300037	50-289	P
	7811300223# 7812130214	50-318 50-354	8 0	DELGEORGE, L. D. DELGEORGE, L. D.	7810240101 7811140175	50-373 50-373	A H	DEYDUNG R. C. DEYDUNG R. C.	7811300039 7811300042	50-335 50-295	P P
	7812060371 7812110264	50-155 50-482	Q A	DELGEORGE, L. D.	7812050100 7812060153	50-373 50-373	K F	DEYOUNG R. C. DEYOUNG R. C.	7811300045 7811300046	50-313 50-317	P P
	7812280332*	50-327	Ö	DELLUMS, R. V.	7810110248	50-70	o	DEYDUNG R. C.	7811300050	50-31 5	Р
	7812280017 7812280035	50-263 50-171	M b	DELLUMS, R. V. DELLUMS, R. V.	7810110271 7810230084	50-70 50-70	9	DEYOUNG R. C. DEYOUNG R. C.	7811300358 7811300364	50-302 50-275	P A
	7812280045 7812280054	50-272 50-397	P A	DELLUMB, R. V. DELLUMB, R. V.	7811130246 7811290297	50-70 50-70	0	DEYDUNG.R.C. DEYDUNG.R.C.	7811300367 7811300376	50-220 50-333	Ь Б
	7812280040	20-549	P	DELLUMB, R.	7812210171	50-70	ě	DEYOUNG R C.	7811300379	50-269	P
	7812280067 7812280071	50-395 50-206	A P	DENESS & J. DENIBE R. P.	7811300215 7812200056	50-433 50-556	J H	DEYOUNG, R. C. DEYOUNG, R. C.	78113003 95 78113003 89	50-277 50-312	P
	7812280073 7812280077	50-244 50-522	P A	DENTON: H. R. DENTON: H. R.	7811200432* 7811200434*	50~437 50~437	Ä	DEYOUNDIR. C. DIAZIN. J	7812070297 7810110196*	50-44B 50-83	A O
	7812280083	50-554	Ä	DENTON: H. R.	7811200434*	50-437	A	DIAZIN. J.	7810180081	50-83	p
	7612280097 7812280090	50-546 50-267	A P	DENTON, H. R. DENTON, H. R.	7811200440# 7811200076#	50-437 50-437	A	DICKERSON, M. W. DICKERSON, M. W.	7810110308¢ 7811210501*	50-267 50-313	Q Q
	7812280092 7812280094	50-387 50-344	A P	DENTON, H. R. DENTON, H. R.	7811200424* 7811200390*	50-437 50-437	A	DICKERSON, M. W. DICKERSON, M. W.	7812060332* 7812180331*	50-148 50-267	Q Q
	7812280075	50-133	P	DENTON. H. R.	7811200340*	50-437	A	DIENHART, A. V	7812070311	30-484	ā
	7812280096 7812280098	50-294 50-295	P P	DENTON, H. R. DENTON, H. R.	7811200302* 7812190231	50-437 50-70	A	DIGOS.R.M. DIGOS.R.M.	7811150159* 7812140340	50-220 50-29	P P
	7812280102 7812280103	50-580 50-334	A	DENTON, H. R. DENTON, H. R.	7810140043* 7811280491	50-213 50-331	U P	D1008, R.M. D1008, R.M.	7812180055 7812270375	50-368 50-10	P P
	7812280103	50-298	P	DENTON, H. R.	7810310240	50-247	P	DIOOS, R.H.	7812290110	50-266	P

	ACCE891DN	SUBJECT	AUTHDR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTIOR	ACCESSION NUMBER	BUBJECT CATEGORY
AUTHOR DIGGS.R R DIGGAN. T G DIGNAN. T G DILLINBECK.L	7812290154 7811010244 7811060193 7812130090	CATEGORY 50-366 P 50-443 9 50-568 9 50-220 0 50-22 9	DROMERICK A W DROMERICK A W. DROMERICK A DUFLO. M. E. DUFLO. M. E.	7812110081 7812190175 7812200070 7810140148 7810140147	50-338 P 50-311 A 50-338 P 50-437 G 50-50B 0	EARLY, P. J.	7811170110 7811210389 7811280291 7811210300 7811290182	50-333 P 50-333 P 50-333 P 50-333 P 50-286 P
DIRCKS.H J DIRCKS.H J DIRCKS.H J DIRCKS.H J	7811030146 7809260256 7810110207* 7810110200 7810140036	50-70 50-70 90-70 90-70 90-213 90-275 50-275	DUFLO, M. E.	7810140108 7810230089 7810240046 7810300041 7810300133	50-275 0 50-516 0 50-320 0 50-483 0 50-338 0	EARLY, P. J.	7812040205 7812050139 7812050216 7812180388 7812110153	50-549 A 50-549 E 50-549 A 50-549 0 50-333 P
DIRCKS.H J DIRCKS.H J DIRCKS.H J DIRCKS.H J	7810240009 7810240115 7811080032 7811150207* 78111210065	50-440 A 50-488 H 50-275 U 50-356 A 50-70 U	DUFLO: M. E DUFLO: M. E DUFLO: M. E DUFLO: M. E DUFLO: M. E	7811010097 7811010101 7811010177 7811070036 7811080185	50-483 0 50-346 M 50-500 0 50-338 0 50-275 0	EARLY, P. J.	7812120080 7812130168 7812170114 7812170180* 7812270140	50-333 P 50-286 Q 50-333 P 50-3 P 50-333 F
DIRCKS. H J DIRCKS. H J DIRCKS. H J DIRCKS. H J DIRCKS. H J	7811240091 7812010039 7812030043 7812080210 7812140297	50-70 U 50-471 U 50-213 U 50-302 U 50-70 H	DUFLO, M. E. DUFLO, M. E. DUFLO, M. E. DUFLO, M. E DUFLO, M. E	7811080001 7811200071 7811130090 7811170094 7811200046	50-488	EBNETER.B.D EBNETER.B.D EBNETER.B.D EBNETER.B.D EBNETER.B.D.	7810270288* 7811130151* 7812010111* 7812120248* 7812180082*	50-311 8 50-387 0 50-29 0 50-363 0 50-20 0
DIRCKS. N J DIRCKS. N J DISE. D P DISE. D P DISE. D P	7812060160 7812110058 7811220193* 7810110089 7810170188	50-367 U 50-522 9 50-220 P 50-220 P 50-220 P	DUFLO: M. E. DUFLO: M. E. DUFLO: M. E. DUFLO: M. E. DUFLO: M. E.	7811220278 7811290312 7812040166 7812040179 7812060191	50-553 0 50-346 M 50-320 0 50-275 0 50-275 0	EBNETER.B.D. EBNETER.B.D. ECKHARDT.J.H. ECKHARDT.J.H. ECKHARDT.J.H	7812280319# 7812270457# 7810110212# 7810230094# 7812110240#	50-318 0 50-333 0 50-361 0 50-361 0
D18E. D P D18E. D P D18E. D P D18E. D P D18E. D P	7811070114 7811290192 7811240103* 7812050148 7812140136	50-220 P 50-220 F 50-220 0 50-220 P 50-220 F	DUFLO: M. E. DUFLO: M. E. DUFLO: M. E. DUFLO: M. E. DUFLO: M. E	7812110086 7812050302 7812060055 7812070268 7812130217	50-516	ECKHARDT, J. H ECONOMOB, N ECONOMOB, N. ECONOMOB, N ECONOMOB, N.	7812270391# 7811080314# 7812030172# 7812070320# 7812270372#	50~508
DISE.D P DISE.D P DISE.D P DISE.D P DITTERT.J L	7812200194 7812270176 7812270240 7812270287 7810140085	50-220 P 50-220 P 50-220 P 50-220 P 50-220 P	DUFLO, M. E.	7812130203 7812140215 7812140337 7812180443 7812270119	50-556	ECONOMOS. N ECONOMOS. N EDDLEMAN. H EDDLEMAN. H EDDLEMAN. H.	7811290325# 7812280315# 7811140034 7811290059 7812140114#	50-389 0 50-395 0 50-400 0 50-400 0 50-400 0
DIVER. 8 G DOBEL. D C DODD. C. J. DODDS. R. T DODGE. W A	7811070097 7810230170 7812050044* 7810260232* 7810180124	50-556 0 50-498 A 50-213 U 50-344 0 50-361 A	DUGGER, L. J. DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, C. N.	78122702624 78102701894 7810110144 7810160114 7810180072		EDDLEMAN W. EDGAR. Q. L.	7812220121 7811040122 7811070340 7811210451 7811300054	50-400 0 50-554 0 50-554 0 50-70 0 50-70 0
DOHERTY J F DOHERTY J F DOHERTY J F DOLAN T E DOLAN J E	7810110250* 7812060038 7812060041 7810120062 7811080138	50-466 0 50-466 0 50-466 0 50-316 P 50-315 0	DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, C. N.	7810200100 7811300243 7810270195 7811030107 7811160109	50-334 P 50-334 G 50-334 P 50-334 P 50-334 R	EDWARDS, D. W EFROB. M. EFROB. M. EFROB. M. EFROS. M.	7810230153 7811150232 7811270193 7811240083 7812130193	50-309 P 50-556 0 50-556 9 50-556 9 50-556 9
DOLAN, J. E DONALDSON, D. E. DONALDBON, D. E. DONAT, T. J. DONAT, T. J.	7811210446 7811020188* 7811080268* 7811080198* 7811200024*	50-315 Q 50-271 0 50-219 0 50-327 Q 50-327 Q	DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, C. N. DUNN, NG, 1.	7812110128 7812210215 7812220071 7812260214 7810250142	50-334 R 50-334 P 50-334 P 50-334 P 50-206 F	Eprob, M. Ehrensperoer, H. Ehrensperoer, H. Ehrensperoer, H. Ehrensperoer, H. Ehrensperoer, H.	7812110215 7811080162 7811200259* 7811210217 7811200173	50-556 9 50-424 A 50-424 A 50-424 A 50-424 A
DONAT - T. J DOUGHERTY - T. H. DOUGHERTY - T. H. DOUGLASS - R. H. DOUGLASS - R. H.	7812050076+ 7810230383 7812290019 7810100051 7810110169	50-302 0 50-437 0 50-437 0 50-317 8 50-317 8	DURDCHER, H. J. DURR, J. P. DURR, J. P. DURR, J. P. DURR, J. P.	7810190184 7810250207 7810190007 7810190006 7811140249	• 50-387 G • 50-320 G • 50-320 G	EHRENBPEROER, W EHRENBPERGER, W EICHENHOLZ, H EICHHORN, W. H EIBENHUT, D. Q	7812270145 7812270139 7811270134+ 7812180111 7812170178	50-424 B 50-424 F 50-271 P 50-347 9 50-70 P
DOUGLASB, R. M. DOUGLASB, R. M. DOUGLASB, R. M. DOUGLASB, R. M. DOUGLASB, R. M.	7810130173 7810270235 7810310102 7810310197 7810310209	50-317 8 50-317 8 50-317 8 50-317 8 50-318 8	DURR, J. P. DURR, J. P. DYER, J. A DYER, J. A DYER, J. A	7811130151 7811170299 7811090279 7811080198 7812070313	+ 50-311 Q + 50-390 Q + 50-327 Q	EIBENHUT, D. Q. EIBENHUT, D. Q. EIBENHUT, D. Q. EIBENHUT, D. Q. EIBENHUT, D. Q.	7811130059 7811130064 7811130082 7811130088 7811130100	50-10 P 80-213 P 50-217 P 50-245 P 50-29 P
DOUGLASS, R. H. DOUGLASS, R. H. DOUGLASS, R. H. DOUGLASS, R. H. DOUGLASS, R. H.	7811010113 7811030112 7811060155 7811130211 7811140164	50-317 8 50-317 8 50-318 8 50-318 8 50-318 8	DYM.H. EARLY:P.J. EARLY:P.J. EARLY:P.J. EARLY:P.J.	7612260051 7812260019 7610110094 7810110160 7810120055	• 50-247 P 50-286 P 50-286 P	EIBENHUT.D.Q. EIBENHUT.D.Q. EIBENHUT.D.Q. EIBENHUT.D.Q. EIBENHUT.D.Q.	7811130080* 7811130083* 7810300331 7811090042 7811170142*	50-250 P 50-250 P 50-260 P 50-346 P 50-344 P
DOM, M. DOMELL, B. DOMES, J. DOYLE, J. E. DRAKE, M. Q.	7810270201 7810120072 7811070064* 7810270296* 7810270373*	50-330 A 50-329 A 50-568 A 50-237 B 50-341 Q	EARLY: P. J.	7810170175 7810240080 7810180075 7810170106 7810170111	0 50-549 A 50-333 P 8 50-333 P	EIBENHUT.D.Q. EIBENHUT.D.Q. EIBENHUT.D.Q. EIBENHUT.D.Q. ELDER.Q.Q.	7812140033 7812270086* 7812120054 7812150321 7812200251*	50-280 P 50-3 P
DRAKE, M DRAKE, J. H DRAKE, J. H DRAKE, M DRAKE, J. H.	7810240212 7810260118* 7810260115 7812270129 7812190120	50-341 0 50-361 K 50-361 K 50-341 0 50-361 K	EARLY: P. J. EARLY: P. J. EARLY: P. J. EARLY: P. J. EARLY: P. J.	7610230191 7610240109 7610270149 7611010111 7612060113	7 50-286 F 7 50-333 F 1 50-333 P	ELIABON, L. R. ELIABON, L. R. ELIABON, L. R. ELIABON, L. R. ELIABON, L. R.	7810240117 7810300145 7811210307 7812010215 7812210190	50-263 8 50-263 P 50-263 P 50-263 P 50-263 P
DRAKE, J. H. DREHER, F. A. DROHERICK, A. H. DROHERICK, A. H. DROHERICK, A. H. DROHERICK, A.	7812190124# 7810130187# 7810140042 7810230098 7810230002	50-361 K 50-356 Q 50-338 P 50-311 P 50-311 A	EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J.	7811030099 7811200023 7811080116 7811080183 7811080184	3 50-549 A 50-266 P 3 50-286 P	ELIABON.L.R. ELIN.J.C. ELLIGT.R.B. ELLIB.Q.B. ELLIB.L.J.	7812240193 7811010037* 7811140138 7810170258* 7812140247	50-445 A
DROMERICK, A. DROMERICK, A. DROMERICK, A. DROMERICK, A. W. DROMERICK, A.	7811090034 7811220261 7811290397 7811290354 7812120240	50-311 A 50-311 A 50-339 A 50-311 A 50-339 A	EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J. EARLY, P. J.	781108012: 781108012: 781108012: 781116006: 7811121027:	7* 50-286 P 7* 50-286 P 7 50-333 P	enoelken R. H. Enoelken R. H. Enoelken R. H. Enoelken R. H. Enoelken R. H.	7810230305 7810230316 7810230320 7810230321 7810230325	50-344

PERSONAL AUTHOR INDEX

FOX, H, 8. FOX, H, 8. FOX, H, 8. FOX, H, 8.

FOX. H. S.

7811140186 7811140201 7811140217 7811140240

7811160099

50-296 50-296 50-259 50-259

50-296

AUTHOR	ACCEBBION NABRUUN	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTFOR	ACCESSION NUMBER	BUBJE
ENOELKEN. R. H	7810300110	50-361 8	FABANO A N	7811140280+	50-311 G	FIDRELLI.O. FIDRELLI.O. FIDRELLI.O. FIDRELLI.O. FIDRELLI.O.	7811300349	50-255
ENGELKEN. R. H.	7810310357	50-528 8	FABANO A N.	7810300292+	50-334 G		7812010124	50-255
ENGELKEN. R. H.	7812070238	50-361 0	FABANO A N	7812120026+	50-322 G		7812060124	50-305
ENGELKEN. R. Q.	7811150005	50-344 0	FABANO A N.	7812290220+	50-334 G		7812050027*	50-10
ENGELKEN. R. H.	7811150007	50-133 0	FATE M E.	7811280250	50-356 B		7812070074	50-263
ENGELKEN, R. H.	7811150009	50-52B Q	FAULKENBERRY, B.	7812140039*	50-312 0	FIORELLIO.	7812040033	50-254
ENGELKEN, R. H.	7811150012	50-312 Q	FAULKENBERRY, B.	7812130314*	50-275 0	FIORELLIO.	7812040231	50-295
ENGELKEN, R. H.	7811150013	50-397 Q	FAH, R. E.	7810110029	50-188 P	FIORELLIO.	7812140010	50-263
ENGELKEN, R. H.	7811150019	50-204 Q	FEE, H. F.	7810260171	50-213 P	FIORELLIO.	7812060072	50-409
ENGELKEN, R. H.	7811220195	50-397 8	FEIERABEND, C. D.	7812200099*	50-282 0	FIORELLIO.	7812120225	50-305
ENGELKEN, R. H.	7811300063	50-133	FEIST, C. K	7811220083	50-445 A	FIORELLIO	7811200037	50-331
ENGELKEN, R. H.	7811300072		FEIST, C. K.	7812270259	50-445 K	FIORELLIO	7811200045	50-315
ENGELKEN, R. H.	7811300076		FELDMANN, M. J.	7810250107	50-293 P	FIORELLIO	7812120216	50-331
ENGELKEN, R. H.	7811300082		FELTON, J. M.	7810270199	50-330 A	FIORELLIO	7812200091	50-282
ENGELKEN, R. H.	7811300088		FELTON, J. M.	7811010353	50-331 Q	FIORELLIO	7812140141	50-266
ENGELKEN R. H.	7811300090	50-361 0	FELTON, J. M.	781101000B	50-329 A	FIDRELLIO.	7812210046	50-282
ENGELKEN R. H.	7811300092	50-312 0		7811020236	50-245 G	FIDRELLIO.	7812200105	50-263
ENGELKEN R. H.	7811300097	50-206 0		781107028B	50-245 P	FIDRELLIO.	7811280480	50-331
ENGELKEN R. H.	7812110198	50-508 0		7811210403	50-382 H	FIDRELLIO.	7812270062	50-346
ENGELDER: T. C.	7812200186	50-13 0		7811220128	50-267 U	FIDRELLIO.	7812210041	50-358
ENGELKEN, R. H.	7812210110	50-528 8	FELTON, J. M. FELTON, J. M. FELTON, J. M. FEROUSDN, J. H. FERNANDO, A.	7812060296	50-466 A	FIORELLI.O.	7812290068	50-266
ENGELKEN, R. H.	7812210261	50-341 8		7812070052	50-373 A	FIORELLI.O	7812290009	50-305
ENGELKEN, R. H	7812290030	50-133 0		7812180321	50-267 P	FIORELLI.O.	7812290017	50-255
ENGELKEN, R. H.	7812290033	50-275 0		7810250110*	50-213 8	FIORELLI.O	7812290022	50-266
ENGELKEN, R. H.	7812290036	50-528 0		7812110069*	50-522 Q	FIORELLI.O	7812260292	50-254
ENGELKEN R. H. ENGELKEN R. H. ENGELKEN R. H. ENGELKEN R. H. ENGELKEN R. H.	7812290085 7812290094 7812290098 7812290099 7812290103	50-344	FERRIBON, J. FICKEIBBEN, K.O. FIDELL, E.R. FIDELL, E.R. FIEDLER, J.	7812130179* 7812280234* 7812240014 7812270138 7810130223	50~267 8 50~219 8 50~247 P 50~247 Q 50~295 J	FIORELLI, Q. FIORELLI, Q. FIORELLI, Q. FIORELLI, Q. FIORELLI, Q. FIORELLI, Q.	7812260293 7812260302 7812260308 7812270028 7810130161+	50-282 50-263 50-253
ENOLE, L. 8.	7810120094	50-368 P	FIEDLER: J. FINFROCK I.R. FINFROCK I.R. FINFROCK I.R. FINFROCK I.R.	7812010256	50-259 J	FIBCHER.B.	7810270110	50-70
ENOLE, L. 8.	7810230309*	50~368 P		7811080189*	50-363 G	FIBH.R.F.	7812140072*	50-70
ENOLE, L.	7811170223	50-368 P		7810110118	50-219 P	FIBH.R.F.	7812190197*	50-133
ENOLE, L. 9.	7811140061	50-368 P		7810160115	50-219 P	FIBHER.W.L.	7810110062*	50-10
ENOLE, L.	7811200129	50~368 P		7810160120*	50-219 P	FIBHER.J.R.	7810120042*	50-305
ENOLE, L.B. ENOLE, L.B. EPLER, E.P. EPBTE IN, E. ERB, C.M.	7811200378 7812140020* 7811010251 7810300351* 7810260184*	50-368 P 50-368 P 50-572 0 50-201 G 50-341 G	FINFROCK, I.R. FINFROCK, I.R. FINFROCK, I.R. FINFROCK, I.R. FINFROCK, I.R.	7810160143 7810170200 7810170240 7810270094 7811070304	50-219 P 50-219 R 50-219 P 50-219 R 50-219 P	FISHER, N. L. FISHER, N. L. FISHER, N. L. FITCH, H. A. FITE, J. P.	7811090040* 7811080080* 7812200302* 7811170173 78111080225	50~2 50~254 50~255 50~368 50~445
EAB.C.M.	7811010059*	50-373	FINFROCK, I.R.	7811030114	50-219 P	FLEIBCHAKER, D.	7810160155	50-275
ERB.C.M.	7811300221*		FINFROCK, I.R.	7811070105	50-219 B	FLEIBCHAKER, D.	7810190257	50-275
ERB.C.M.	7812050241*		FINFROCK, I.R.	7811220129	50-219 P	FLEIBCHAKER, D.	7810190262*	50-275
ERICKBON.P.	7811070050		FINFROCK, I.R.	7812180161*	50-363 Q	FLEIBCHAKER, D.	7810190267*	50-275
ERICKBON.P.B.	7811280073		FINFROCK, I.R.	7811200160	50-219 P	FLEIBCHAKER, D.	7810190269*	50-275
E8819, T. H. E8819, T. H. E8819, T. H. E8819, T. H. E8TES, J.	7810110270* 7812010070* 7812280227* 7812290063 7811200268	50-345 G 50-305 G 50-456 G 50-255 G 50-256 G	Finfrock, I. R.	7811200164* 7811240194 7811280262 7812120127* 7812120133	50-219 P 50-219 F 50-219 P 50-219 B	FLEIBCHAKER.D. FLEIBCHAKER.D. FLEIBCHAKER.D. FLEIBCHAKER.D. FLEMING.B.T.	7810270294 7810300128 7811130314 7812010048 7811210385•	50-275 50-275 50-275 50-275 50-213
ETHER INGTON, H. EVANB, E. A. EVANB, D. J. EVANB, C. A. EVANB, C. A.	7811100051 7811200330+ 7811080144 7812070002+ 7812180424+	50-280 T 50-298 G 50-250 H 50-128 Q 50-59 Q	FINFROCK, I. R. FINFROCK, I. R. FINFROCK, I. R. FINFROCK, I. R. FINFROCK, I. R.	7812120136* 7812120123 7812180204 7812180208* 7812170105	50-219 B 50-219 B 50-219 B 50-219 B	FLEMING.B. T. FLIEGEL.M. H FLYNN, J. D. FOOD, W. C. FOOD, W. O.	7811210311* 7811070293 7812200148 7811210172 7812270146	50-213 50-387 50-358 50-155 50-255
EVANB.D.J. EVERETT.R.J. EVRAETS.J.C. EWALD.S.C. EWALD.S.C.	7812270037 7811170174* 7812080099 7810270221* 7811240081*	50-305	FINFROCK I.R. FINKEL, A.E. FIGRELLI, O. FIORELLI, O. FIORELLI, O.	7812270185 7810270284* 7812060337 7810110182 7810110218	50-219 P 50-311 Q 50-331 Q 50-305 Q 50-358 Q	FOLEY, T. FOLBUM, B. A. FOLBUM, B. A. FONTANA, L. FONTANA, L.	7812010135* 7811010135* 7811100097* 7811080180 7811210408	50-219 50-443 50-443 50-382 50-382
EHALD: 8. C. EHING: T. N. EHING: H. C. EHING: T. N. EHING: T. N.	7812110225* 7810240095 7811240185 7811130222 7811140192	50-280	FIORELLI, O. FIORELLI, O. FIORELLI, O. FIORELLI, O. FIORELLI, O.	7811080104* 7810250216 7811010067 7810270371 7811010018	50-315 G 50-331 G 50-254 G 50-301 G 50-10 G	FONTECILLA, H. M. FONTECILLA, H. M. FONTECILLA, H. M. FORTUNA, R. A. FORTUNA, R. A.	7811130315 7812040194 7812040198 7810300281* 7810310030	50-244 50-10 50-213 50-389 50-400
EHINO, T. N. EHINO, T. N. EHINO, T. N. EHINO, T. N. FAHRNER, W. J.	7811160081 7811140214 7812220115 7812270200 7811090076	50-556 A 50-556 B 50-556 A 50-556 A 50-341 B	FIDRELLI.O. FIDRELLI.O. FIDRELLI.O. FIDRELLI.O. FIDRELLI.O.	7811010016# 7810270385 7810310029 7811010012# 7810310335	50-10 G 50-315 G 50-182 G 50-10 G 50-316 G	FOSTER: J E. FOSTER: J E. FOSTER: M H. FOSTER: E R. FOSTER: J. E.	7810110274* 7811170264* 7810310030 7811090133* 7812290247*	50-35B 80-35B 50-400 50-423 50-461
FAMRNER.W.J.	7811070169	50~341 8	FIORELLI.O. FIORELLI.O. FIORELLI.O. FIORELLI.O. FIORELLI.O.	7811300314	50-255 G	FOX: A.	7811200179	50-70
FAIN.T.G.	7811130176#	50~327 A		7811130004	50-331 G	FOX: H. B.	7810100002	50-296
FAIROBENT,J.E.	7810300050	50~341 A		7810110297	50-315 G	FOX: H. B.	7810100042	50-296
FAIRTILE.N.B.	7810260149	50~269 P		7810110199	50-262 G	FOX: H. B.	7810100036	50-259
FAIRTILE.M.	7811210032	50~269 F		7811080046	50-295 G	FOX: H. B.	7810180138	50-260
FAIRTILE, M.	7812060019	50-249 F	FIORELLI, O. FIORELLI, O. FIORELLI, O. FIORELLI, O. FIORELLI, O.	7811090182	50-315 G	FOX: H. 9.	7810240146	50-296
FARON, R. B.	7812220113	50-244 P		7811140264	50-373 G	FOX: H. B.	7810300168	50-260
FARRAR, D.	7812180177*	50-10 B		7811150053	50-346 G	FOX: H. 9.	7810310183	50-259
FARRIB, J. R.	7810250075	50-556 9		7811210214	50-331 G	FOX: H. 9.	7811140165	50-296
FARRIS, J. R.	7811150232	50-556 9		7811210415	50-266 G	FOX: H. 9.	7811140168	50-296

FARRIS, J. R.

FABANG A.N. FABANG A.N. FABANG A.N. FABANG A.N.

7811270193

7811240083 7810250207* 7810190007*

7810190006*

30~556

50-356 50-387 50-320

50-320

0

FIORELLI. Q.

FIDRELLI.O. FIDRELLI.O. FIDRELLI.O.

PIORELL I. Q.

7811290324

7811290333 7811300261 7811020335 7811300135

50-320

50-266 50-10 50-10

50-155

99999

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEODR	Y	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
FOX.H 9	7811280214	50-259 9	galen, J. H.	7812130179#	50-247	8	GIAMBUSBO, A.	7811200331#	50-437
FOX.H B	7811280187	50-259	J. H.	7812130185*	50-267	8	GIAMBUSED. A	7811200026# 7811200291#	50-437 50-437
FDX. H. 8	7811280294 7811280205	50-276 B 50-259 B	GAHM, J. 14 GAHM, J. 14	7812200210+ 7812270206+	50-267 50-267	8 8	GIAMBUSSO,A GIBBONS,T.D	7810110194#	50-439
FOX.H S FOX.H B	7811280201	50-260 8	GATTANIS M. J.	7811130375	50-317	F	GIBBONS, T. D.	7B1109023B*	50-375
							OTERANO T O	7812060274#	50-327
FOX.H S	7812030199 7812080101	50-296 S 50-260 S	GAITANIS M J. GALLAGHER, E. J.	7811220062¢ 7810110184◆	50-549 50-367	T Q	GIBBONS, T. D. GIBBONS, T. D.	7812120045*	50-395
FOX.H S FOX.H B	7812110148	50-296 9	CALLAGHER, E J.	7811210112*	50-440	ā	Q1988, M. E.	7810110309	50-329
FOX.H S	7812120174	30-260 8	CALLAGHER E J.	7811170264*	50-358	Q	GEBBS. M. E.	7811150080	50-329
FOX.H S	7812190110	50-296 8	gallagher, E. J.	7812050241*	50-456	G	OIBBB. M. E.	7811210034	50-329
FDX.H 8	7812190119	50-296 5	GALLAGHER, P. M.	7811060034	146-06	Q	GIBBB, M. E.	7612140087	50-029
FOX.H 9	7812270265	50-259 8	GALLAGHER, E. J.	7811300260+	50-358	a	G1999, M. E.	7612140362	50-027
FOX.H S	7812290221	50-260 8	GALLAN, K. P	7811080329	50-556	0	OIBBB. M. E.	7812180383	50-329 50-329
FRAHM, R. X.	7810140026* 7811200239*	50-556 Q 50-437 A	GALLAGHERIE J. Gallerik R.	7812190160* 7812190169	50-329 50-70	0 P	01888. M. E. 01880N. O. T.	7812280350 7810260073#	50-250
FRALEY-R. F	78112002379	30.437 K	THE CANAL TO THE	7012170107	55 75	•			
FRAMSON, R S	7810240033	50-466 0	GALLINA.C.	7812150240*	50-245	G	GIBSON, A.F.	7810180192*	50~335 50~389
FRAMSON.M. 8 FRAMSON.R. 8	7811210245 7811210249	30-466 G 50-466 G	ÇALLD≀R.M. ÇALLD≀J.	7810230207* 7810160202	50~387 50~556	G G	GIBBON, A. F. Gibbon, G. T.	7810190177 * 7811010411 *	50-250
FRAMSON, R. S	7812030291	50-466 Q	GALLO, J.	7810190216	50-556	ě	OIBSON, A. F.	7811130049*	50-259
FRANK L.	7610310092	30-569 A	QALLE, J.	7810250021	50-556	G	QIBBON, A. F.	7810230036*	50-369
FRANKLIN, N. J.	7812280289	50-498 M	QALLD: J.	7810240199	50-556	c	OIBSON, A.F.	7810130064*	50-269
FRANKLIN H J	7812270405	50-498 M	QALLE, J.	7811010433	30-356	G	DIESON, A.F.	7810310054#	20-580
FRAZAR, R. A	78120401274	50-498 G	QALLO, J.	7811130066	50-556	0	GIBBON, A. F.	7811010191*	50-338
FRAZAR.R.A	7811030214	50-498 8	OALLO, J.	7811130252	50-556	9	01880N, 0. T.	7611030235#	50-335
FREEDKIN S	7811010013+	50-329 A	GALLO: J.	7811240076	30-556	0	OIBRON, A. F.	7812050031*	50-269
FREEDKIN S	7811010010+	50-329 A	QALLO, J.	7812050281	50-556	G	GIBSON, A.F.	7612040337*	50-269
FREEMON A M.	7812050251*	50-259 P	QALLO: J.	7812040235	50-536	Q	GIBSON A F.	7011240057#	50-238
FRIEDELL E. FRIEDELL E B	7810110037 7810140064+	50-466 @ 50-466 @	GALLO, J.	781207000B	50-556	0	QIBSON, A.F.	7812060033*	50-259
FRIEDELL E. 8.	7810130242	50-452 0	GALLO,R.M. GALLO,J.	7812290238* 7812110107	50-387 50-556	a	gibson, a.f. Gibson, a.f.	7812070312* 7812110225*	50~261 50~280
				, , , , , , , , , , , , , , , , , , , ,	00 000	•	00-00	70.2110.22	00
FRIEDELLE 9 FRIEDELLE 8	7610240030 7610300252	50-466 0 50-466 0	OALLO: J.	7812050347	30-956	9	91880N, A.F.	7812280348*	50-250
FRIEDELL, E S	7811070172	50-466 9	GALLD: J. GALLD: J.	7812040014 7812140078	50-556 50-556	T O	GIBSON, G. T. Gibson, G. T.	7812140122* 781221007&*	50-348 50-250
FRIEDELLES	7811140094	50-466 G	OALLO, J.	7812140285	30~554	Ğ	GILBERT, L. D.	7810250015+	50-445
FRIEDELL E S	7811130038	50~466 0	GAMBARDELLA, A.	7611080035	50-338	ō.	GILBERTIR. A.	7810120097	30-392
FRIEDELL E. S	7811280483	50-219 9	CAMPLE E II	7011000100	80.00		011 PE07 P 1		
FRIEDELLE S.	7812030085	50-219 G	GAMBLE.F.W. Gammill.W.P.	7811220192+ 7812180330	50-286 50-70	8 P	GILBERTIR. A. GILBERTIS.	7810130093 7810230126	50-592 50-466
FRIEDELL E 8	7811220097	50-465 0	GAMMILL, W. P.	7812180425	30-70	P	OILBERT, L. D.	7812040342+	50-445
FRIEDELLE B. FRY.D.N	7811280143	50-466 G	QAMMILL.W.P.	7811270211	50-267	P	OILBERT B.	7811160053	50-466
(N1) V. II	7812270192	50-267 P	gardebr ing. 8.	7812260328*	50-263	P	GILBERT R. A.	7811270054*	50-460
FRYL ING. C	7811280159*	50-438 I	CARDEBRING, 8. B.	7812270023*	50-263	н	GIL INSKY, V.	7811200015#	50-407
FRYLING.R. FUCHKO.J.M	7812280046	50-272 0	GARFIELD. G.	7811010166	50-245	P	OILINSKY, V.	7B11040260	50-437
FUJITA T. T	7812290112+ 7812200053	50-302 0 50-70 P	GARRETT.8.M Garrett.8.M	7812260061	50-344	0	GILINBRY, V.	7811200013#	50-437
FULLER, J. K.	7810100005	30-267 P	GARRETTIS. M.	7811020235 7812260332	50-344 50-344	0	GILLELAND, J. E. Gilleland, J. E.	7810310064# 7811020074	50-259 50-430
FULLER, J. K				,0,110000	00 014	•	010022.40.0.2.	7011020074	20-420
FULLER, J K	7810100012 7810110136	50-267 P 50-267 P	GARY, R. J.	7810240221*	50-445	g	OILLEBPIE, F. P.	7B11130007#	50-250
FULLER, J K.	7810180141	50-267 P	GARY, R. J. GARY, R. J.	7810240161 7810240186	50-44 5 50-445	A	GILLELAND, J. E. GILLELAND, J. E.	7811070236 781019016 4	50-327 50-327
FULLER, J. K.	7810170139	50-267 P	9ARY, R. J.	7811030249*	30-445	ä	GILLELAND, J. E.	7810230135	50-327
FULLER, J. K.	7810170174	30-247 F	GARY+R, J.	7811070260*	50~445	G	GILLEBPIE, F.P.	7811100130#	50-267
FULLER, J. K	7810310094	50~267 P	GARY, R. J.	7811280347	50~445		GILLELAND, J. E.		
FULLER, J K.	7810250047	50-267 P	GARYIR. J.	7811280387	50~445	9 0	GILLELAND, J. E.	7810230227 * 7811070245	50-259 50-818
FULLER: J. K FULLER: J. K	7810260205 7810310085	30-267 P	GARY, R. J.	7811070134	50~445	ē	OILLESPIE, F. P.	7B10110059*	50-259
FULLER, J. K	7811140096	50-267 P 50-267 F	GARY, R. J. Gary, R. J.	7811300109*	30-445	g .	GILLELAND, J. E.	7811030078*	50-400
515.1.55			ONLINE D	7811300020*	50~445	a	OILLEBPIE.F.P.	7810140060*	50-277
FULLER, J. K. FULLER, J. K.	7812070186 7812270177	50-267 P	GARY+R. J.	7811170133	50~445	A	GILLETT, W. T.	7810200056#	50-316
FULMER, B.	7811030158*	50-267 P 50-346 B	GARY, R. J.	7811210401	50~445	8	GILLELAND, J. E.	7810110158	50-327
FULHER B.	7811210359+	50-346 B	GARY.R.J. Gary.R.J.	7812190142+ 7812190232	30~445 30~445	g G	GILLELAND, J. E.	7810110107	50-259
FURBUSH, M H.	7811010039	50-275 0	GARY, R. J.	7611210348	50~445	A	GILLELAND: J. E. Gilleland: J. E.	7810120065 7810190228	50-259 50-390
FURR, B. J	7810110229+	50-261 0	GARY, R. J.		-				
FURR, B. J.	7810310123	50-261 8	GARY, R. J	7811280183 7811280216	50~445 50~445	8	GILLELAND, J. E. GILLELAND, J. E.	7811070276	50-327
FURR: 8. J FURR: 8. J.	7811090013#	50-024 G	GARY, R. J.	7812070111	50~445	A K	GILLELAND, J. E.	7810170206 7810180093	50-390 50-327
FURRI 8. J.	7811160137 7812070063*	50-025 6 50-261 0	QARY, R. J	7812150264	50~445	C	GILLELAND, J. E.	7810230244	30-259
	,0140,00004	20-%91 M	GARY+R. J.	7812200184	50-445	A	GILLELAND, J. E.	7811130013*	50-259
FURR B J	7811140138	50-325 B	GARY, R. J.	7812280109	50-445	В	GILLELAND, J. E.	70	
FURRIB. J. FURRIB. J.	7812200198 7812200200	50-324 B	GASCHLER, J. A.	7812120089	50-267	8	GILLELAND, J. E	7811080254 + 7811030263	50~430 50~327
FURR. B. J	7812270288	50-324 8 50-325 8	GABE, E. D.	7812170020+	50-70	P	GILLELAND, J. E.	7811030260#	50-327
QAD, R. K.	7811010244	30-443 Q	OASBER, R. A. OATES: O.	7811240032* 7810100014*	50-363	H	OILLELAND, J. E.	7811090204*	50~259
GAD, R. K.	2011000100			7810100014#	50-285	8	GILLELAND, J. E.	7811060090	50-370
GAFFNEY, C.	7811080195 7812200183#	50-368 Q 50-293 R	GATES, O.	7810110114+	50-285	8	GILLELAND: J. E.	7810240153	50-259
GAHM, J. H.	7810300194	50-293 R 50-267 S	GAZLEY, C. GEHR, A. C.	7811200019*	30-437	A	GILLELAND, J. E.	7811030257	50-438
GAHMIJ, IK GAHMIJ, IK	7810160103+	50-267 R	GEORGE, J.	7811020082 7812270059	50-592 50-275	M H	GILLELAND, J. E. GILLELAND, J. E.	7810240144	50-259
	7810300190+	50-267 B	GEDROE, K. D.	7812190091	50-54	P	GILLELAND, J. E.	7810250082 7810250088	50-240
GAHAPI Y. H	7810300313+	50~267 S							50-566
QAHBIL J. IL	7810270232*	50-267 8	GERLACH, D. GERBTNER, H. C.	7812280277*	50-267	H	OILLELAND, J. E.	7810250095	50-327
GAHMI, J. IL. GAHMI, J. IL.	7810270283e	50-267 g	GETTY, B. C.	7810110057* 7812150311*	50-461 50-133	G R	GILLELAND, J. E. GILLELAND, J. E.	7010250120	50-327
OAHMI J. K	7810310230+ 7811070238+	50-267 8 50-267 R	GIAMBUBBO, A	7811200096*	50-437	À	GILLELAND, J. E.	7810300103 7810310113	50-259 50-327
		20 EU/ H	GIAMBUSED, A.	7811200002+	50-437	À	OILLELAND, J. E.	7811070277	50-327
J, I, 19460 J, J, 19460	7811280289•	50-267 B	A COSUBNATO	7811200067*	50-437	A	GILLELAND, J. E.		
OAPEL J. IL	7811280318± 7812130167±	30-267 B 30-267 R	A CBBURMAID	7611200057	50-437 50-437	A	GILLELAND, J. E.	7810250080 7812040192	50-296
OAIH, J. H.	7812130141+	30-267 R 30-267 B	QIAMBUSSO, A.	7811200313+	50-437	A	GILLELAND, J. E.	7810310076	50-327 50-259
QAPHI J. IL	7812130192+	30-267 8	QIAMBUBBO, A. QIAMBUBBO, A.	7811200208*	50-437	A	OILLELAND, J. E.	7912050125#	50-327
				7811200339+	50-437	A	GILLELAND, J. E.	7612010266	50-327

æ

a

a

AUTHOR	ACCESSION NUMBER	BUBJECT	AUTHOR	ACCE881ON NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	DECEUB CATEGO
GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E.	7811020231 7812040226 7811010073 7811060063 7811060094	50~43B K 50-390 8 50-327 A 50-390 B 50-327 A	GIRARD, E. H. GIRARD, E. H. GITTON, E. C. GLABER, M. GLENN, J.	7811150067* 7812180343* 7811200019* 7812130003 7810240011*	50-375 G 50-400 G 50-437 A 50-445 N 50-440 A	ORAVES, R. H. ORAVES, R. H. ORAVES, R. H	7812050140 7812050134 7812210201 7812220061 7810140150	50-213 50-213 50-213 50-213 50-344
OILLELAND, J. E. OILLETT, W. T. OILLETT, W. T. OILLELAND, J. E. OILLESPIE, F. P.	7811080164 7811210391* 7811210438* 7811080160 7812110251*	50-51B A 50-315 R 50-316 R 50-390 P 50-324 Q	OLENN, J. OLENN, J. ODAD, L. F. ODDARD, R. J. ODDARD, R. J.	7812190236 7812120041 # 7812210200# 7810300324 7810310223	50-440 Q 50-580 H 50-275 A 50-237 Q 50-237 Q	GRAY, J. R. Gray, J. R. Gray, J. R.	7810260227 7810300070 7811020270 7811030237 7811020325	50-344 50-344 50-344 50-344 50-344
GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E.	7811220091* 7812080213 7811070192 7811080114 7811080132	50-260 G 50-518 B 50-296 P 50-390 A 50-390 K	QUDDARD,R.J. QUDDARD,R.J. QUDDARD,R.J. QUDDARD,R.J. QUDDARD,R.J.	7811130216 7811220233 7811220010 7811300147 7812050054	50-237 0 50-237 0 50-237 0 50-295 P 50-295 0	GRAY, J. R. GRAY, J. R.	7811030176 7811160001 7812040233 7812080048 7812070228	50-344 50-463 50-344 50-344 50-344
GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E.	7812040035* 7812050245 7811160047 7811150128 7811150129*	50-390 0 50-327 B 50-438 B 50-260 P 50-260 P	QUDDARD, R. J. QUDDARD, R. J. QUDDARD, R. J. QULDBERQ, B. C. QULDBERQ, S. C.	7812080158 7812270371 7812270230 7810180176 7810230120	50-237 H 50-295 Q 50-10 Q 50-395 Q 50-338 Q	GRAY, J. R. GRAY, J. R. GRAY, J. R.	7812070231* 7812130074 7812140084 7812170171 7812270285*	50-344 50-344 50-344 50-321
OILLELAND, J. E. OILLELAND, J. E. OILLESPIE, F. P. OILLELAND, J. E.	7811150137 7811220147 7812060121 7812210363* 7811140134	50-327 A 50-390 A 50-327 B 50-259 Q 50-327 F	OOLDBERG, B. C. OOLDBERG, B. C. OOLDBERG, B. C. OOLDBERG, B. C. OOLDBERG, B. C.	7810140009 7810230369 7810310332 7811130091 7811060129	50-353 @ 50-395 @ 50-395 @ 50-338 @ 50-553 @	Greenman e. g. Greenman e. g. Greene, t. Greene, t. Greene, t.	7811020186* 7811070058* 7810170238* 7810170230* 7810170261*	50-223 50-277 50-366 50-366 50-321
GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLESPIE, F. P.	7811150123 7811150152 7812050246 7812040074* 7811210289*	50-327 F 50-327 A 50-390 B 50-327 G 50-338 G	OCLDBERG, B. C. GOLDBERG, B. C. GOLDBERG, B. C. GOLDBERG, B. C. GOLDBERG, B. C.	7811060193 7811070366 7811130116 7811180170 7811200068	50-502 G 50-395 F 50-395 G 50-502 G 50-553 G	Greene, T. Greene, T. Greenhood, J. Greene, T.	7810170296* 7810170237* 7810180118* 7811210349 7810180022*	50-321 50-321 50-366 50-301 50-366
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7811170113 7811170175 7812130372 7811160098 7811160148	50-259 P 50-259 P 50-259 0 50-327 A 50-327 A	QOLOBERO, B. C. QOLOBERO, S. C. QOLOBERO, S. C. QOLOBERO, S. C. QOLOBERO, J. R.	7811200288# 7812130080 7812130084# 7812210264 7812140273	50-395 @ 50-502 @ 50-502 @ 50-502 @	Greenman e. Greene, t. Greenhood, j. Greene, t. v.	7812010031 h 7810180024 h 7810180024 h 7811210393 7810230190 h	50-277 50-366 50-366 50-266 50-366
OILLELAND, J.E. OILLELAND, J.E. OILLELAND, J.E. OILLESPIE, F.P. OILLELAND, J.E.	7812030117* 7811200200 7811210406 7812290112* 7812290112*	50-327 G 50-259 F 50-518 A 50-302 G 50-553 A	ODLDMAN.M. OOLLER.K.R. OOLLER.K.R. OONTALEB.R.O. OODDHOPE.A.C.	7810140045* 7811200078* 7810130107 7811200362 7811220086	50-213 U 50-437 A 50-70 P 50-592 A 50-549 Q	GREENE, T. V. Greenman, E. Greene, T. Greene, T. V. Greene, T. V.	7810310150* 7819040219* 7810310182* 7811140254* 7811040138*	50-321 50-20 50-321 50-366 50-321
GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E.	7812070250 7812080229 7811280251 7811280255 7812040021*	50-390 8 50-390 8 50-436 A 50-296 P 50-259 0	ODDHOPE, A. C. ODDHOPE, A. C. ODDHOPE, A. C. ODDHOPE, A. C. ODDHOPE, A. C.	7812040200 7812140047 7812280265 7812280303 7812110172#	50-549 Q 50-549 Q 50-549 Q 50-549 Q 50-344 J	oreen, d. Oreenberg, m. Oreene, t. Oreene, t. v.	7811140140* 7811220070* 7811210346* 7812180170* 7812180205*	50-259 50-549 50-321 50-321 50-366
GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLELAND, J. E. GILLEBPIE, F. P.	7811290248 7812110017 7812140286 7812140288* 7812140287*	50-370 K 50-370 S 50-327 B 50-327 B 50-406 G	QOODMAN.R.E. QOODMAN.R.E. QOODWIN.C. QOODWIN.C. QOODWIN.C.	7812110177* 7812180218* 7810120009 7810180070 7811010075	50-344 J 50-10 J 50-344 P 50-344 P	GREENE, T. V. OREER, R. J. GREER, R. J. GREENER, J. OREEVER, J. T.	7812180217* 7810300383* 7811090303* 7812290063 7811030259	50-266 50-315 50-255 50-255 50-70
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7612050171 7612050243 7812070177 7812200244 7812050189	50-276 P 50-259 P 50-327 G 50-259 K 50-259 P	ODDHIN, C. QODHIN, C. QODHIN, C. ODRDON, H. J. QORE, A. S.	781 1070162 781 1140159 781 2280128 7810110025 7810120085+	50-344 P 50-344 P 50-344 K 50-269 P 50-387 B	oreeveb.j.t. Greder,l.r. Greder,l.r. Greger,l.r. Oribbon.d.m	7819260096 7819280981 7810110062* 7811090040* 7812880051	50-18 50-361 50-10 50-2 50-389
OILLETT, W. T. OILLETT, W. T. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7812200174* 7812200205* 7812080091 7812070170 7812070183	50-315 R 50-316 R 50-327 A 50-257 P 50-546 A	ODRE, J. & ODSSICK, L. V. ODSSICK, L. V. ODSSICK, L. V. ODSSICK, L. V.	7810170162 7812050283 7812050284* 7812050289* 7812050293*	50-318 P 50-437 A 50-437 A 50-437 A 50-427 A	ORIER, B.H. ORIER, B.H. ORIER, B.H. ORIER, B.H. ORIER, B.H.	7812050004 7811060239+ 7812130092+ 7811010127 7810160232	50-3 50-3 50-352 50-443 50-352
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E.	7612150350 7812110142 7812120075 7812120099 7812120158	50-327 A 50-327 A 50-390 A 50-390 G 50-327 A	90881CK.L.V. 90881CK.L.V. 90881CK.L.V. 90981CK.L.V. 9000E.M.J.	7812050297# 7812050301# 7812200346 7812210336 7811290323#	50-437 A 50-437 A 50-363 A 50-239 H 50-866 Q	GRIER, B.H. ORIER, B.H. GRIER, B.H. GRIER, B.H. GRIER, B.H.	7810160236 7810160238 7810160240 7810160241 7810160243	50-27 50-277 50-334 50-284 50-219
GILLELAND, J. E.	7812120166 7812120170 7812180130 7812270043* 7812270117*	50-327 K 50-327 A 50-327 A 50-320 Q 50-327 Q	QQULD, W. R. QQULD, W. R. QQULD, W. QQWER, Q. C. QRAHAM, R. L.	7810130160# 7811160082# 7812170159# 7812080041 7811160050	50-206 R 50-206 R 50-206 R 50-184 G 50-367 G	GRIER, B. H. Grier, B. H. Grier, B. H. Grier, B. H. Grier, B. H.	7810160246 7810160248 7810160250 7810160255 7810160257	50-3 50-309 50-299 50-322 50-443
OILLELAND, J. E. OILLELAND, J. E. OILLELAND, J. E. OILLEGPIE, F. P.	7612270038* 7812130248 7812200134 7812200236 7812210287=	50~438	ORAHAM, S. A. ORANT, J. S. ORANT, N. B. ORANT, J. S. ORANT, J. S.	7812180324 7811200067 7812010284* 7811130124 7811240139	50-275 9 50-346 R 50-409 G 50-346 P 50-346 P	ORIER, B.H. Orier, B.H. Orier, B.H. Orier, B.H. Orier, B.H.	7810170001 7810170003 7810170023 7810170024 7810170025	50-367 50-465 50-271 50-415 50-365
OILLELAND, J. E.	7812260163 7812210248 7812270175 7812270202 7812260131	50-259 P 50-327 F 50-259 P 50-327 A 50-327 K	GRAVEB, R. H. GRAVEB, R. H. GRAVEB, R. H. GRAVEB, R. H. GRAVEB, R. H.	7811240163 7811210376 7811210306 7811210306 7810130166 7810180134	50-213 8 50-213 8 50-213 8 50-213 8 50-213 R	ORIER, B. H. Orier, B. H. Orier, B. H. Orier, B. H. Orier, B. M.	7810170026 7810170029 7810170030 7810180221 7812070290*	50-317 50-293 50-213 50-320 50-219
GILLELAND, J. E. GILLELAND, J. E. GILLILAND, D. L. GILHAN, D. H. GIRARD, E. H.	7812290217 7812290126 7812280275 7810260118* 7811080158*	50-259 P 50-390 A 50-70 0 50-361 K 50-395 Q	GRAVES, R. H. GRAVES, R. H. GRAVES, R. H. GRAVES, R. H. GRAVES, R. H.	7810240093 7810250106 7811060103 7811210282 7811300212	50-213 R 50-213 B 50-213 R 50-213 P	ORIER, B.H. Orier, B.H. Grier, B.H. Orier, B.H. Orier, B.H.	7811060171 7811060173 7811060174 7811060176 7811060178	50-333 50-272 50-244 50-273 50-273
						•		

AUTHDR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
ORIER. B.H. ORIER. B.H. ORIER. B.H ORIER. B.H ORIER. B.H	7811060181 7811060182 7811060184 7811060186 7811060188	50-29 0 50-213 0 50-264 0 50-269 0 50-317 0	ORIER, B. H GRIER, B. H ORIER, B. H. GRIER, B. H. ORIER, B. H.	7812150049 7812150121 7812150125 7812150131 7812150133	50-387 G 50-293 G 50-317 G 50-213 G 50-3 G	ORDCE, R. H.	7811270086 7811270130 7811280221 7812010214 7812040171	50-309 P 50-271 P 50-29 P 50-309 Q 50-29 P
ORIER.B.H ORIER.B.H ORIER.B.H ORIER.B.H ORIER.B.H.	7811040190 7811040192 7811040195 7811040197 7811040198	50-387	GRIER, B. H. GRIER, B. H ORIER, B. H ORIER, B. H. ORIER, B. H	7812150136 7812150140 7812150142 7812150144 7812150146	50-334	OROCE, R. H. ORDCE, R. H. OROCE, R. H. OROCE, R. H. OROCE, R. H.	7812050128 7812050130 7812140145 7812200230 7812200220	50-29 F 50-271 F 50-29 P 50-29 P 50-309 P
ORIER. BH ORIER. BH ORIER. BH ORIER. BH ORIER. BH	7811060201 7811060203 7811060205 7811060208 7812060275	50-3 0 50-277 8 50-245 0 50-220 0 50-184 0	ORIER, B. H. Grier, B. H. Grier, B. H. Grier, B. H. Grier, B. H	7812150150 7812150155 7812150158 7812150160 7812150169	50-245 0 50-277 0 50-286 0 50-363 0 50-322 0	ORDNBERG, W. L. Ordnberg, W. L. Ordsbaan, M. J. Ordsbaan, M. Ordsbaan, J. B.	7810110156 7811070126 7810250152 7812120020* 7812270123	50-333 P 50-333 F 50-327 9 50-424 9 50-387 H
ORIER. BH ORIER. BH ORIER. BH ORIER. BH ORIER. BH	7812130071 7811080043 7811060224 7811100056 7811100120	50-352	ORIER, B. H ORIER, B. H. ORIER, B. H. ORIER, B. H. GRIER, B. H.	7812150171 7812180022 7812180025 7812180026 7812180030	50-410	ORDSSMAN, J. B. ORDTENHULS, M. ORDTENHULS, M. ORDTENHULS, M. ORDTENHULS, M.	7812280051 7810300100 7810250252 7812170154 7812180378	50-389 M 50-282 P 50-250 P 50-262 P 50-250 P
ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H. ORIER.B.H.	7812010272 7811130115 7812010345 7812080144 7812080145+	50-245 0 50-272 0 50-3 0 50-334 0 50-334 0	ORIER.B.H ORIER.B.H. ORIER.B.H ORIER.B.H ORIFFITHB.R.	7812180032 7812180034 7812180310 7812219053 7811280275	50-244 0 50-333 0 50-333 P 50-245 0 50-272 J	Ordve, P. A. Guabco, O. Gumble, F. W. Gumble, F. W. Gumble, F. W.	7810310207 7810160151* 7810100100* 7810120060* 7811060215*	50-133 P 50-409 P 50-286 B 50-286 B
GRIER, B H. GRIER, B H. GRIER, B H. GRIER, B. H. GRIER, B. H.	7811290139 7811290142 7811290145 7811290149 7811290151	50-410	GRIMES, B. K. GRIMES, B. K. GRIMES, C. GRIMES, B. K. GRIMES, B. K.	78121303B5* 7810140015# 7811130335 7811270103* 7811220279	50-344 P 50-298 P 50-219 P 50-243 P 50-324 P	QUMBLE, F. H. QUTTERMAN, A. H. QUTTMAN, D. QUTTMAN, D. HAASS, H. P.	7812220098* 7810240037 7812180339 7812180342* 7811170088	50-286 8 50-566 9 50-389 M 50-389 M 50-361 A
GRIER, B.H. GRIER, B.H. GRIER, B.H. GRIER, B.H. GRIER, B.H.	7811290134 7811290158 7811290160 7811290164 7811290170	50-244	ORIMES, B.K. ORIMES, B.K. ORIMES, B.K. ORIMES, B.K. ORIMES, B.K.	7812180248 7612180250 7812180251 7812180253 7812180255	50-10 P 50-133 P 50-219 P 50-245 P 50-409 P	HAABB, W. P. HAFHAM, J. W. HAQA, P. B. HAQA, P. B. HAQA, P. B.	7812190097 7811130393* 7811200058* 7810240103 7811090163	50-10 P 50-364 0 50-437 A 50-437 A
QRIER, B.H. QRIER, B.H. GRIER, B.H. QRIER, B.H. QRIER, B.H.	7811290174 7811290177 7811290183 7811290188 7811290190	50-483 0 50-443 0 50-352 0 50-322 0 50-363 0	Orimes, B. K. Grimes, B. K. Orimes, B. K. Orimes, B. K. Orimes, B. K. Crimes, B. K.	7812180259 7812180262 7812180263 7812180264 7812180266	50-293 P 50-271 P 50-247 P 50-155 P 50-254 P	Haga, P. B. Haga, P. B. Haga, P. B. Haineb, F. D. Hairbton, W. G.	7812070176 7812200160 7812220097 7812150293 7810270311	50-437 A 50-437 A 50-437 A 50-466 A 50-348 8
GRIER: B H GRIER: B.H GRIER: B.H GRIER: B. H GRIER: B. H	7811290193 7811290195 7811290199 7811290205 7811290208	50-272 0 50-333 0 50-289 0 50-309 0 50-219 0	ORIMEB.B.K. ORIMEB.B.K. ORIMEB.B.K. ORIMEB.B.K ORIMEB.B.K.	7812180268 7812180270 7812180271 7812180273 7812180274	50-171 H 50-333 P 50-298 P 50-259 P 50-324 P	HAIRBTON W. O.	7810180082* 7810100072* 7810100086* 7811140233* 7810180149*	50-348 R 50-348 B 50-348 B 50-348 B 50-348 B
ORIER, B. H.	7811290212 7811290214 7811290216 7811290218 7811290220	50-334 0 50-3 0 50-213 0 50-293 0 50-317 0	ORIMES, B. K. GRIMES, B. K. ORIMES, B. K. ORIMES, B. K. ORIMES, B. K.	7812180275 7812180277 7812180279 7812180283 7812180284	50-263 P 50-3R1 P 50-331 P 50-272 P 50-344 P	Hairston W. G. Hairston W. G. Hairston W. G. Hairston W. G. Hairston W. G.	7810180154* 7810200081* 7810200085* 7810200087* 7810250145*	50-348 8 50-348 8 50-348 8 50-348 8 50-348 8
QRIER.B.H. GRIER.B.H. GRIER.B.H. GRIER.B.H. GRIER.B.H.	7811290222 7811290288 7811290291 7812070140 7812070141	50-311 0 50-171 H 50-245 R 50-485 A 50-271 P	ORIMES, B. K. GRIMES, B. K.	7812180288 7812190002 7812190004 7812190008 7812190011	50-281 P 50-313 P 50-348 P 50-317 P 50-295 P	Hairston H. G. Hairston H. G. Hairston H. G. Hairston H. G. Hairston H. G.	7810250114* 7811070187* 7811070172* 7811070176* 7811070200*	50-348 8 50-348 8 50-348 8 50-348 8 50-348 8
ORIER, B. H. GRIER, B. H.	7812070143 7812070144 7812070146 7812070149 7812070150	50-334 P 50-412 A 50-244 P 50-352 A 50-367 A	ORIMES, B. K.	7812190016 7812190017 7812190023 7812190025 7812190028	50-3 P 50-255 P 50-261 P 50-213 P 50-334 P	Haireton W. G. Haireton W. G. Haireton W. G. Haireton W. G. Haireton W. G.	7811140237* 7811140242* 7811140246* 7811140251* 7811210358*	50-348 8 50-348 8 50-348 8 50-348 8 50-348 8
ORIER, B. H.	7812070152 7812070153 7812070154 7812070155 7812070156	50-322 A 50-3 P 50-213 P 50-273 P 50-311 A	ORIMES, B. K. GRIMES, B. K. GRIMES, B. K. GRIMES, B. K. GRIMES, B. K.	7812190031 7812190033 7812190036 7812190038 7812190039	50-269 P 50-302 P 50-250 P 50-315 P 50-289 P	HAIRSTON, W. Q. HAIRSTON, W. Q. HAIRSTON, W. Q. HAIRSTON, W. Q. HAIRSTON, W. Q.	7812080224 7811210179= 7811280272= 7812010254+ 7812210212+	50-348 B 50-349 R 50-348 B 50-348 B 50-348 R
ORIER, B. H.	7812070158 7812070159 7812070161 7812070163 7812070166	50-29 P 50-443 A 50-317 P 50-220 P 50-245 P	orimes, B. K. Orimes, B. K. Orimes, B. K. Orimes, B. K. Orimes, B. K.	7812170042 7812170044 7812170047 7812170048 7812170051	50-309 P 50-336 P 50-282 P 50-286 P 50-285 P	Hairbton, H. G. Hairbton, H. G. Hairbton, H. G. Hairbton, H. G. Hairbton, H. G.	7812110138+ 7812200165+ 7812270311+ 7812270309+ 7812270313+	50-348 8 50-348 8 50-349 8 50-349 8 50-348 8
ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	7812070191 7812070194 7812070197 7812070200 7812070205	50-272 P 50-289 P 50-333 P 50-286 P 50-277 P	ORIMES, B. K.	7812190054 7812190057 7812190059 7812190060 7812190062	50-244 P 50-206 P 50-312 P 50-266 P 50-305 P	HAIRSTON, W. Q. HAIST, D. P. HAIST, D. P. HALL, R. E. HALL, R. E.	7812270283* 7811270126* 7812210380* 7810270417* 7810110076*	50-348 8 50-70 0 50-206 0 50-213 P 50-245 P
ORIER, B. H.	7812070207 7812070209 7812070212 7812070282 7812060271	50-363 A 50-219 P 50-309 P 50-410 A 50-307 A	ORIMEB, B. K. ORIMEB, B. K. ORIMEB, B. K. OROCE, R. M. OROCE, R. M.	7812190063 7812280365 7812180105* 7810110171 7810190056	50-29 P 50-346 P 50-277 P 50-309 P 50-309 P	HALL, R. E. HALL, R. E. HALL, R. E. HALL, R. E. HALL, W. J.	7812130386 7812120125+ 7811030040+ 7811200218+ 7812040334+	50-305 P 50-250 F 50-466 G 50-498 G 50-275 G
ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H. ORIER, B. H.	7812040290 7812110212 7812150041 7812150042 7812150045	50-387 A 50-387 A 50-352 G 50-311 G 50-485 G	OROCE, R. H. OROCE, R. H. OROCE, R. H. OROCE, R. H. OROCE, R. H.	7810130127 7811090166 7811150091 7811170201 7812010146	50-29 P 50-271 H 50-309 P 50-29 P 50-29 Q	HALL, R. E. HAMILTON, D. S. HAMMER, B. J. HAMMER, M. E. HAMMOND, E, L.	7812120119 7810240001 7811280223+ 7812270237+ 7811270160	50-250 F 50-313 F 50-363 E 50-263 E 50-331 E

AUTHOR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODRY	AUTHOR	ACCESSION NUBER	9UBJECT CATEGOR
HAMMOND, E. L.	7811270148	50-331 8	HAVERKAMP, D. R.	7812010282*	50-320 0	Heishman R. F.	7811010092	50-329
HAMMOND, E. L.	7810110141	50-331 9	MAVERKAMP, D. R.	7812010338*	50-320 0	Heishman R. F.	7811010491	50-329
HAMMOND, E. L.	7810120047	50-331 P	HAWK, C.	7811300393	50-70 0	Heishman R. F.	7811030093	50-546
HAMMOND, E. L.	7810200061	50-331 R	HAWK, C.	7812010323	50-70 0	Heishman R. F.	7811010105	50-341
HAMMOND, E. L.	7811210390	50-331 R	HAWK, INS. E. F.	7811200375*	50-70 0	Heishman R. F.	7811010115	50-329
HAMMOND, E. L.	7811280237	50-331 R	HAHKINB, F. C.	7812280316*	50-440 Q	HEISHMAN, R. F.	7811300257	50-358
	7811280204	50-331 B	HAYAKAHA, B. I.	7811240094*	50-70 U	HEISHMAN, R. F.	7812040021	50-452
	7811290238	50-331 P	HAYAKAHA, B. I.	7811080039	50-70 P	HEISHMAN, R. F.	7811300251	50-440
	7812190137	50-331 R	HAYEB, D. H.	7811010057*	50-358 Q	HEISHMAN, R. F.	7812040160	50-346
	7812290130	50-331 P	HAYEB, D. W.	7810300113*	50-341 Q	HEISHMAN, R. F.	7812140021	50-329
HANCHETT, J. G.	7812180408	50-70 P	HAYES, D. W.	7811210112*	50-440 G	HEISHMAN R. F.	7812190117	50-483
HAND, R. C.	7810110307	50-322 A	HAYES, D. W.	7811210027*	50-456 G	HEISHMAN R. F.	7811070222	50-329
HANLEY, H. C.	7811010310	50-502 Q	HAYES, D. W.	7811210013*	50-456 G	HEISHMAN R. F.	7812060108	50-483
HANLEY, H. C.	7812130084*	50-502 Q	HAYES, D. W.	7812040163*	50-546 G	HEISHMAN R. F.	7812060174	50-266
HANNON, J. N.	7811030001	50-893 P	HAYES, D. W.	7812040026*	50-452 G	HEISHMAN R. F.	7812060225	50-254
HANNON; J. N.	7811240154	50-324 P	HAYES, D. H.	7812060112*	50-483 0	HEISHMAN R. F.	7811080284	50-358
HANNON; J. N.	7812110315	50-324 P	HAYES, D. H	7812060358*	50-454 0	HEISHMAN R. F.	7811100074	50-341
HANNUM; D.	7812200241+	50-254 R	HAYES, D. H.	7812070108*	50-456 0	HEISHMAN R. F.	7811130104	50-341
HANSEN; P.	7811240176*	50-304 8	HAYES, D. H.	7812140139*	50-329 0	HEISHMAN R. F.	7812060064	50-329
HANSEN; H. A.	7812040026*	50-452 Q	HAYES, D. H.	7812280244*	50-367 0	HEISHMAN R. F.	7812060352	50-454
HANBELL D.	7812080026	50-10 P	HAYNEB, R. C. HAYNEB, R. C. HAYNEB, R. C. HAYNEB, R. C. HAYNEB, J. Q.	7810110212*	50-361 0	HEISHMAN, R. F.	7812070105	50-456
HANBEN, H. A.	7812210075*	50-546 G		7810190093*	50-397 0	HEISHMAN, R. F.	7811200041	50-329
HANBEN, P. H.	7812110159*	50-295 B		7811010037*	50-361 0	HEISHMAN, R. F.	7811200126	50-367
HANBEN, P. H.	7812110163*	50-295 B		7810230094*	50-508 0	HEISHMAN, R. F	7812140063	50-331
HANBEN, P. H.	7812110160*	50-295 B		7810110096	50-206 P	HEISHMAN, R. F	7812140130	50-329
HARCEK, D. B.	7811240185	30-329 A	HAYNES, J. G.	7810230105	50-205 P	HEISHMAN, R. F.	7812080055	50-358
HARDING, V. R.	7811020333*	30-549 9	Haynes, R. C.	7811270046*	50-361 0	HEISHMAN, R. F.	7812130205	50-315
HARDIN, A. K.	7810130077*	50-348 9	Haynes, R. C.	7811270126*	50-70 0	HEISHMAN, R. F.	7812130129	50-331
HARDING, V. R.	7810230367	50-498 9	Haynes, R. C.	7811270058*	50-312 0	HEISHMAN, R. F.	7812130329	50-295
HARDING, V. R.	7810240090	50-498 9	Haynes, R. C.	78112110240*	50-361 0	HEISHMAN, R. F.	7812270034	50-341
HARDING, V. R.	7811020328	50-549 0	Haynes, J. Q.	7810250066	50-206 P	HEISHMAN, R. F.	7811130425	50-341
HARDIN, A. K.	7812050018*	50-348 0	Haynes, J. Q.	7810270214	50-206 0	HEISHMAN, R. F.	7812280237	50-367
HARDING, V. R.	7812180439	50-498 0	Haynes, J. Q.	7811010167	50-361 H	HEISHMAN, R. F.	7811220006	50-329
HARDING, V. R.	7812180441	50-344 0	Haynes, J. Q.	7811070243	50-206 P	HEISHMAN, R. F.	7811280373	50-341
HARDING, V. R.	7812190196	50-502 0	Haynes, J. Q.	7811060104	50-206 F	HEISHMAN, R. F.	7811290109	50-341
HARDING, V. R.	7812220026	50-395 0	Hayneb, D. W.	7812060070* 7811080103 7812210153* 7811210316 7811210377	50-329 Q	HEISHMAN, R. F.	7812010051	50~440
HARDING, V. R.	7812220028	50-502 0	Hayneb, J. G.		50-206 F	HEISHMAN, R. F.	7812010054	50~358
HARDING, L. H.	7812190134#	50-320 R	Hayneb, R. C.		50-460 Q	HEISHMAN, R. F.	7812190158	50~329
HARDWICK, R. J.	7812120045#	50-395 9	Hayneb, J. G.		50-206 P	HEISHMAN, R. F.	7812200306	50~374
HARDY, H.	7812140325	50-437 H	Hayneb, J. G.		50-206 P	HEISHMAN, R. F.	7812210069	50~546
HARLEBB.B.L.	7611240085	50-464 ff	MAYNEB, J. O.	7811220146	50~206 P	HEISHMAN, R. F.	78122(0120	50~266
HARPBIER.T.L.	7612140016*	50-263 g	MAYNEB, D. W.	7812210075*	50~546 G	HEIBHMAN, R. F.	7812270074	50~409
HARPBIER.T.L	7612200295*	50-358 g	MAYNEB, R. C.	7812280246*	50~361 G	HEISHMAN, R. F.	7812040287	50~329
HARRIB.F.R.	7611200437*	50-437 A	MAYNEB, J. O.	7811280212	50~206 P	HEISHMAN, R. F.	7811290293	50~329
HARRIBON.G.A.	7611060093*	50-556 g	MAYNEB, J. O.	7812050186	50~206 F	HEISHMAN, R. F.	7812010153	50~329
HARRIE, J. K. HARRIE, B. W. HARRIE, J. R. HARRIE, J. R. HARRIEON, H. C.	7811130108* 7810170203* 7811280054* 7812010040* 7811170174*	50-327	HAYNEB, R. C. HAYNEB, J. Q.	7812280224* 7812050219 7812200132 7812190130 7812270165	50-361 Q 50-206 F 50-206 P 50-206 H 50-206 P	HEIGHMAN R F. HEIGHMAN R F. HEIGHMAN R F. HEIGHMAN R F. HEIGHMAN R F.	7812050102 7812140366 7812040365 7812120192 7812120193	50-329 50-329 50-358 50-374 50-358
HARRISON M.F.	7810240109	50-546 A	HAYNEB, J. Q.	7812270205	30-361 K	Heishman R. F.	7812120198	30-358
HARRISON M.F.	7811200109	50-546 P	MEAD, J. T.	7810180089	30-206 8	Heishman R. F.	7812140289	50-456
HARRISI J.R.	7812070023*	50-518 Q	HEAD, J. T.	7810180157	50-206 8	Heishman R. F.	7812290241	30-461
HARRISON M.G.	7812060152	50-329 O	HEAD, J. T.	7810250123	50-206 9	Heishman R. F.	7812280217	50-367
HARRINOTON J.	7811060097	50-568 C	HEAD, J. T.	7810200098	50-206 P	Heishman R. F.	7812290251	50-341
Harrib, J. R. Harribon, A. Harrib, J. R. Harrington, J. Harrib, J. R.	7812060291* 7811240169 7812150040* 7811210364 7812290111*	50-327 0 50-466 D 50-327 0 50-568 A 50-553 0	HEAD, J. T. HEAD, J. T. HEAD, J. T. HEARN, P. C. HEIBHMAN, R. F.	7811280245 7811280277 7812220082 7811290307 7810260169	90-206 P 50-206 B 50-206 F 50-275 F 50-341 Q	HELTEMES, C. J.	7810180185 7811070365 7811130387 7811130437 7811280134	50-395 50-584 50-584 50-470 50-495
HARRINGTON, J.	7811280040	50-36B A	HEIGHMAN R. F.	7810190219	50-454	HELTEMES, C. J.	7812040203	50-470
HARRIS, J. L.	7812140280	50-49B M	HEIGHMAN R. F.	7810110178		HELTEMES, C. J.	7812110250	50-495
HARRIS, J.	7812130298*	50-491 Q	HEIGHMAN R. F.	7810190026		HELTEMES, C. J.	7812130290	50-584
HARRINGTON, J.	7812040151	50-36B A	HEIGHMAN R. F.	7811010050		HELTEMES, C. J.	7812180403	50-584
HARRISON, H. C.	7812290244*	50-267 Q	HEIGHMAN R. F.	7811010047		HELTEMES, C. J.	7812140358	50-584
Harris, J. L. Hart, G. Hart, R. D. Hartigan J. Hartigan J. P.	7812180412 7812130326 7812130279 7812050162* 78112002124	50-498 M 50-400 U 50-346 M 50-346 8 50-346 8	Heibhman R. F. Heibhman R. F. Heibhman R. F. Heibhman R. F. Heibhman R. F.	7811070004 7810300113* 7811130340 7811020106 7811020166	50-341	HENDRIE, J. M. HENDRIE, J. M. HENDRIE, J. M. HENDRICKSON, R. HENDRIE, J. M.	7810300354* 7811200170* 7811200242* 7811060074* 7811000291*	50-201 50-437 50-437 50-116 50-437
HARTIGAN J. P.	7812010213*	50-346 B	HEIBHMAN R. F.	7811300228	50-358	HENDRIE, J. M	7811200238*	90-437
HARTLEY, T. P.	7811070159	50-272 J	HEIBHMAN R. F.	7811090001		HENDRIE, J. M.	7810140039*	50-213
HARTLEY, T. F.	7812040223	50-272 J	HEIBHMAN R. F.	7811210103		HENDRIE, J. M.	7811200006	50-437
HARTMAN, C. J.	7811210350	50-155 B	HEIBHMAN R. F.	7811140268		HENDRICKBON, R.	7811060073	50-116
HARTMAN, C. J.	7812120109	50-155 R	HEIBHMAN R. F.	7810190193		HENDRIE, J. M.	7812130016	50-549
Habeltine, J. D.	7611090254	50-443 A	Heibhman R. F.	7811140048	50-327 G	Hennessey, R. J.	7810140060*	50-297
Habkell, F. K.	7611220132	50-267 U	Heibhman R. F.	7810200016	50-367 G	Hennessey, R. J.	78112102894	50-338
Habkinb, R. C.	7612050241*	50-456 G	Heibhman R. F.	7811020076	50-341 B	Herbe In.J. Q.	7810190001*	50-320
Habtingb, H.	7611010149	50-514 Q	Heibhman R. F.	7811130086	50-331 G	Herbe In.J. Q.	7810100088	50-320
Haughney, C. J.	7611170037	50-201 P	Heibhman R. F.	7810250248	50-454 G	Herbe In.J. Q.	7810100074	50-320
HAUGHNEY, C. J.	7811280370	50-201 P	HEIBHMAN, R.F.	7811210022	50-456 G	HERBEIN, J. Q.	7810100070	50-289
HAUGHNEY, C. J.	7812180114	50-201 P	HEIBHMAN, R.F.	7811210005	50-456 G	HERBEIN, J. Q.	7810180165	50-320
HAVERKAIP, D. R.	7810190007*	50-320 Q	HEIBHMAN, R.F.	7811210018	50-331 O	HERBEIN, J. Q.	7810110082	50-320
HAVERKAIP, D. R.	7810190006*	50-320 Q	HEIBHMAN, R.F.	7812050236	50-456 G	HERBEIN, J. Q.	7810100046	50-320
HAVERKAIP, D. R.	7811090290*	50-320 Q	HEIBHMAN, R.F.	7810310326	50-483 B	HERBEIN, J. Q.	7810110130	50-320

Margarita Company Co	AUTHOR	ACCEBSION NUMBER	BUBJECT CATEOGRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHDR	ACCESSION NUMBER	BUBJECT CATEOORY
Head 1.0 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2010 2	HERBEIN, J. O. HERBEIN, J. O. HERBEIN, J. O.	7810110148 7810180171 7810170147 7810180132	50-289 F 50-320 B 50-320 R 50-320 P	HIGGINB.J. C. HIGGINB.J. C. HIGGINB.J. C.	7810250052+ 7812010303+ 7812010136+	50~311 Q 50~317 Q 50~219 Q	HOFFMAN, D. P. HOFFMAN, D. P. HOFMAYER, C. H	7812270174 7812270202 7811200202+	50~255 50~255 50~437 50~275
CASE 1 0 79 10 10 10 10 10 10 10 1	HERBEIN J. O. HERBEIN J. O. HERBEIN J. O.	7810240097 7810240120 7810310184	50-320 P 50-320 P 50-287 8	HILLIH. J. HILLI J. L. HILLI E. E.	7811240162 7811270014 7812180418	50-263 8 50-498 9 50-338 9	HOOOATT, Q. D HOLODY, D. J. HOLODY, D. J	7812280275 7810180181+ 7812050304+	50-70 50-20 50-97 50-329
September 1.0 7911010020 20-200 1100.1 A 78110100349 20-201 20 1000.0 B 79110100323 20-201 20 1100.1 A 78110100323 20-201 20 1100.1 A 7811010032 20-201 20 1100.1 A 7811010032 20-201 20 1100.0 B 791110032 20-202 20 1100.1 A 7811010032 20-201 20 1100.0 B 791110032 20-202 20 1100.1 A 7811010032 20-202 20 1100.1 A 78110100	HERBEIN.J.O. HERBEIN.J.O. HERBEIN.J.O.	7811070135 7811090114 7811070101	50-289 F 50-320 P 50-289 F	HILLYARD, H. H. HIMEBAUCH, N. HIMEBAUCH, N. HINCKLEY, D. O.	7812180245* 7812120112* 7812270198 7810110302*	50-267 R 50-155 R 50-155 R 50-324 G	HONG, B. H. HONG, B. H. HONG, B. H. HONG, B. H.	7812050227 7812050232 7812050239 7812050244	50-329 50-329 50-329 50-329
HERDELIN_J	HERBE IN.J. Q. HERBE IN.J. Q. HERBE IN.J. Q. HERBE IN.J. Q.	7811090274 7811140172 7811090048 7811130161	50-320 B 50-320 P 50-320 K 50-320 P	Hinghley, D. G. Hinghley, D. G. Hind, J. A Hind, J. A	7812180345* 7812200161* 7810230371 7810240035*	50-324	HONG, S. H. HOOD, D. HOOD, D. H. HOOD, D.	7812030255 7810140006 7811070332 7811130021	50-329 50-329 50-329 50-329
MIND 1	HERBEIN J. O.	7811210332	50-320 8	HIND: J. A.	7810110186	50-255 0	ноар, D.	7811280127	50-329
	HERBEIN J. O.	7811210380	50-320 R	HIND: J. A.	7810130245	50-112 0	ноор, D.	7811280130	50-329
	HERBEIN J. O.	7811270155	50-320 F	HIND: J. A.	7810190247+	50-155 0	наор, D.	7811280131	50-329
	HERBEIN J. O.	7811240110	50-289 P	HIND: J. A.	7810190079	50-266 0	ноор, D.	7812050094+	50-329
MERIELIN_J 0	HERBEIN: J. Q. HERBEIN: J. Q. HERBEIN: J. Q. HERBEIN: J. Q	7812060171 7812050098 7812060161 7812060168	50-320 B 50-289 P 50-289 P 50-289 F	HÌND, J. A HìND, J. A HìND, J. A HìND, J. A	7812060391* 7810310215 7811070231 7811070002	50-315	HOOD, D. HOOD, D. HOOKER, K. HOOKER, K.	7812080241 7812210294 7810260002 7811160046*	50-458 50-329 50-466 50-466
HEBSETN.J. 0	HERBEIN J. G. HERBEIN J. G. HERBEIN J. G. HERBEIN J. G	7812080090 7812130193 7812180187 7812200278	50-289 P 50-320 8 50-320 P 50-320 8	HIND, J. A HIND, J. A HIND, J. A HIND, J. A	7811090044* 7811090040 7811280486 7812140086*	50-87 0 50-87 0 50-10 0 50-10 0	HOOKER, K HOOKER, K HOOKER, K HOOKER, K	7811210030 7812040302* 7812110318 7812050294	30-466 30-466 30-466 30-466
MERSELIN.J. Q. 781207027624 30-200 A MIRES.E. 781210018 50-241 0 MORN.A. 781207027624 30-200 MIRES.E. 781210018 50-220 P MIRES.E. 781210018 50-240 MIRES.E. 781210018 50-240 MIRES.E. 78120018 50-240 MIRES.E. 781210018 50-240 MIRES.E. 781210038 50-240 MIRES.E. 781210008 50-240 MIRES.E. 781210008 50-240 MIRES.E. 781210008 50-240 MIRES.E. 781210018 50-400 MIRES.E. 781210008 50-240 MIRES.E. 781210018 50-400 MIRES.E. 781210008 50-240 MIRES.E. 781210018 50-400 MIRES.E. 781210008 50-320 MIRES.E. 781	HERBEIN.J. G.	7812190096	50-320 P	Hind, J. A	7812280323	50-331 0	HOOKER, K.	7612110103	50-466
	HERBEIN.J. Q.	7812190113	50-289 F	Hinderbtein, C.	7810230248	50-466 9	HOOKER, K.	7812120215	50-466
	HERBEIN.J. Q.	7812190166	50-289 R	Hinderbtein, C.	7811130136	50-466 9	HOPPER, D. M.	7812010265*	50-338
	HERBEIN.J. Q.	7812200171	50-289 Q	Hinderbtein, C.	7812040300	50-466 9	HORN, A. J.	7811130231*	50-344
MERBST. J. E. 78122102389 30-275 A MODREE, J. M. 78124003259 50-280 G MOMARD. J. E. 7810170144 50-471 MERBST. J. E. 78122102979 50-357 G MODREL J. M. 7812400379 50-280 HOME, F. M. 7812103119 50-400 MERDIT. A. R. 78101200272 50-337 G MODREL HOM, R. M. 7811210100 50-367 G MOME, F. M. 7812103119 50-400 MERDIT. A. R. 78101200272 50-337 G MOREL HOM, R. M. 7811210100 50-367 G MOME, F. M. 7812103119 50-400 MERDIT. A. R. 78112003273 50-438 G MOREL HOM, R. M. 7811200022 50-322 G MOME, F. M. 7812103119 50-400 MERDIT. A. R. 78110300349 50-432 G MOREL HOM, R. M. 7812103022 50-322 G MOMELL B. M. 7810190046 50-329 MERDIT. A. R. 7811301089 50-327 G MOREL HOM, R. M. 7812140032 50-322 G MOMELL B. M. 781020039 50-329 MERDIT. A. R. 78111301289 50-328 MERDIT. A. R. 78111301289 50-328 MERDIT. A. R. 78111402359 50-328 MERDIT. A. R. 78111402359 50-328 MERDIT. A. R. 7811240034 50-322 G MOMELL B. M. 781020039 50-329 MERDIT. A. R. 7811240348 50-322 G MOMELL B. M. 781020039 50-329 MERDIT. A. R. 7811240348 50-322 G MOMELL B. M. 781020039 50-329 MERDIT. A. R. 7811240348 50-328 G MOMELL B. M. 781020039 50-329 MERDIT. A. R. 7811240348 50-328 G MOMELL B. M. 781020039 50-329 MERDIT. A. R. 7811240348 50-329 G MOFFHAN. D. P. 7810170244 50-238 G MOMELL B. M. 781020349 50-329 MERDIT. A. R. 7811240348 50-329 G MOFFHAN. D. P. 7810170244 50-238 G MOMELL B. M. 781020349 50-329 MERDIT. A. R. 781120348 50-329 G MOFFHAN. D. P. 7810170244 50-238 G MOMELL B. M. 781020349 50-329 MERDIT. A. R. 781120348 50-329 G MOFFHAN. D. P. 7810170244 50-238 G MOMELL B. M. 781020349 50-329 MERDIT. A. R. 781120348 50-329 G MOFFHAN. D. P. 7810170244 50-238 G MOMELL B. M. 781020349 50-329 MERDIT. A. R. 7811203049 50-329 MERDIT. A. R. 7811203052 50-329 MERDIT. A	HERBE IN.J. Q.	7812280116	50-320 q	HINKEL, L.	7811210082	50~341 0	HORRY, A.	7812070294#	50~206
	HERBE IN.J. Q.	7812290131	50-320 p	Hinkel, L.	7812130015	50~70 0	HOBEY, C. M.	7812050031*	50~269
	HERBE IN.J. Q.	7812190132	50-320 R	Hinkle, N. E.	7812080097	50~395 A	HOBEY, C. M.	7812040339*	50~269
	HERBE IN.J. Q.	7812260191	50-269 8	Hitchenb, D.	7811210357*	50~346 8	HOUSE, D. R.	7810200115	50~369
HERDTIAR. 7811030094* 50-424 0 HOFFLIMB.R.K. 78121010998 50-275 0 HOMELL.B.H. 7810109066 50-229 HERDTIAR. 78111301020* 50-438 0 HOFFLIMB.R.K. 7812140026 50-322 0 HOMELL.B.H. 7810120097 50-229 HERDTIAR. 7811102020* 50-438 0 HOFFLIMB.R.K. 7812240042 50-322 0 HOMELL.B.H. 7810220192 50-229 HERDTIAR. 7811102030* 50-518 0 HOFFLIMB.R.K. 7812270042 50-322 0 HOMELL.B.H. 7810220192 50-229 HERDTIAR. 7811210080* 50-339 0 HOFFMAN.D.F. 7810100017 50-205 B HOMELL.B.H. 7810270142 50-229 HERDTIAR. 7811240036* 50-339 0 HOFFMAN.D.F. 7810100015 50-235 B HOMELL.B.H. 7810270142 50-229 HERDTIAR. 7811240036* 50-424 0 HOFFMAN.D.F. 7810100015 50-235 B HOMELL.B.H. 7810270142 50-229 HERDTIAR. 7811240036* 50-424 0 HOFFMAN.D.F. 7810100015 50-235 F HOMELL.B.H. 7810270142 50-229 HERDTIAR. 7811240036* 50-424 0 HOFFMAN.D.F. 781010111 50-235 F HOMELL.B.H. 7810270142 50-229 HERDTIAR. 7811240036* 50-424 0 HOFFMAN.D.F. 7810101035 50-235 F HOMELL.B.H. 7811240234 50-239 HERDTIAR. 7811240036* 50-424 0 HOFFMAN.D.F. 7810101035 50-235 F HOMELL.B.H. 7811240234 50-237 HERDTIAR. 7811240035* 50-418 0 HOFFMAN.D.F. 7810100035 50-235 R HOMELL.B.H. 7811270324 50-239 HERDTIAR. 78112400035 50-418 0 HOFFMAN.D.F. 7810100137 50-235 P HOMELL.B.H. 781170312 50-239 HERDTIAR. 78121800035* 50-416 0 HOFFMAN.D.F. 7810100137 50-235 R HOMELL.B.H. 781170323 50-239 HERDTIAR. 78121800035* 50-416 0 HOFFMAN.D.F. 781027007* 50-515 P HOMELL.B.H. 7811702974 50-229 HERDTIAR. 7812100445* 50-413 0 HOFFMAN.D.F. 781027007* 50-515 P HOMELL.B.H. 7811702974 50-229 HERDTIAR. 781220045* 50-413 0 HOFFMAN.D.F. 7811070210 50-235 B HOMELL.B.H. 7811702974 50-229 HERDTIAR. 781220045* 50-413 0 HOFFMAN.D.F. 7811070210 50-235 B HOMELL.B.H. 7811702974 50-229 HERDTIAR. 7812210045* 50-414 0 HOFFMAN.D.F. 7811070210 50-235 B HOMELL.B.H. 7811270147 50-229 HERDTIAR. 8. 7812210045* 50-414 0 HOFFMAN.D.F. 7811070210 50-235 B HOMELL.B.H. 7811270147 50-229 HERDTIAR. 8. 7812210045* 50-444 0 HOFFMAN.D.F. 78112004028 50-235 B HOMELL.B.H. 7811270147 50-239 HERDTIAR.B.F. 781120045* 50-430 B HOFFMAN.D.F. 78112004028 50-	HERBBT, J. E.	7812210235*	50-275 A	Hodoeb, J. M.	7812040325*	50~260 G	HOMERO, J. E.	7810170164*	50~471
	HERBT, J. E.	7812210209*	50-275 A	Hodoeb, J. M.	7812140059*	50~267 G	HOME, P. M	7811300165	50~400
	HERDT, A. R.	7810120092*	50-337 G	Hoefling, R. K.	7811210100	50~367 G	HOME, P. M	7812180334*	50~400
	HERDT, A. R.	7811030092*	50-438 G	Hoefling, R. K.	7611200008	50~322 G	HOME, P. M	7812210319	50~400
HERDT. A. R. 7811210089	HERDT, A.R.	7811030054*	50-424 Q	Hoefling, R. K.	7812010198	50-275 0	HOHELL, B. H.	7810190066	50-329
	HERDT, A.R.	7811130108*	50-327 Q	Hoefling, R. K.	7812140026	50-322 0	HOHELL, B. H.	7810180095	50-329
	HERDT, A.R.	7811130120*	50-438 Q	Hoefling, R. K.	7812140342	50-322 0	HOHELL, B. H.	7810230192	50-329
	HERDT, A.R.	7811140253*	50-516 Q	Hoefling, R. K.	7812270042	50-322 0	HOHELL, B. H.	7810250099	50-329
HERDT.A.R. 78121300059 50-327 0 HOFFMAN.D.P. 7810130137 50-255 R HOMELL.B.H. 7811170212 50-329 HERDT.A.R. 781280339 50-518 0 HOFFMAN.D.P. 7810120075 50-155 P HOMELL.B.H. 7811170222 50-329 HERDT.A.R. 7812180339 50-416 0 HOFFMAN.D.P. 781027075 50-155 P HOMELL.B.H. 7811170294 50-329 HERDT.A.R. 78121302998 50-491 0 HOFFMAN.D.P. 7811200779 50-255 0 HOMELL.B.H. 7811170298 50-329 HERDT.A.R. 78122103498 50-400 0 HOFFMAN.D.P. 7811070217 50-255 8 HOMELL.B.H. 7811200159 50-329 HERDT.A.R. 78122203498 50-400 0 HOFFMAN.D.P. 7811070217 50-155 8 HOMELL.B.H. 7811220121 50-329 HERDT.A.R. 7812270918 50-400 0 HOFFMAN.D.P. 7811070183 50-255 8 HOMELL.B.H. 7811220176 50-329 HERDT.A.R. 7812270918 50-508 0 HOFFMAN.D.P. 7811140323 50-255 8 HOMELL.B.H. 7811270176 50-329 HERRING.K.B. 78102603288 50-344 0 HOFFMAN.D.P. 781140323 50-255 8 HOMELL.B.H. 7811270176 50-329 HERRING.K.B. 78102603288 50-344 0 HOFFMAN.D.P. 7811200528 50-255 8 HOMELL.B.H. 7811270147 50-329 HERRING.K.B. 78103000778 50-344 0 HOFFMAN.D.P. 7811200502 50-255 8 HOMELL.B.H. 7811270147 50-329 HERRING.K.B. 78103000778 50-344 0 HOFFMAN.D.P. 781120030 50-255 B HOMELL.B.H. 7811270192 50-329 HERRING.K.B. 78103000778 50-344 0 HOFFMAN.D.P. 781120030 50-255 B HOMELL.B.H. 7811270192 50-329 HERRING.K.B. 7810301968 50-332 0 HOFFMAN.D.P. 7812060024 50-255 B HOMELL.B.H. 781270192 50-329 HIGKLE.B.J. 7810301968 50-332 0 HOFFMAN.D.P. 7812060024 50-255 B HOMELL.B.H. 78120080 50-329 HIGKLE.B.J. 78111401618 50-385 R HOFFMAN.D.P. 7812060024 50-255 P HOMELL.B.H. 781210080 50-329 HIGKLE.B.J. 78111401618 50-385 R HOFFMAN.D.P. 7812060167 50-255 P HOMELL.B.H. 7812120080 50-329 HIGKLE.B.J. 7810140164 50-409 0 HOFFMAN.D.P. 7812100104 50-255 B HOMELL.B.H. 7812120111 50-329 HIGKLE.B.J. 7810140104 50-409 0 HOFFMAN.D.P. 7812100104 50-255 B HOMELL.B.H. 7812120111 50-329 HIGKLE.B.H. 7812120104 50-329 H	HERDT, A.R.	7811210088*	50-339 Q	HOFFMAN.D.P.	7810170244	50-255 B	HOWELL, B. H.	7811070334	50-329
	HERDT, A.R.	7811200188*	50-518 Q	HOFFMAN.D.P.	7810100015	50-255 B	HOWELL, B. H.	7810270142	50-329
	HERDT, A.R.	7811240048*	50-424 Q	HOFFMAN.D.P.	7810110111	50-255 P	HOWELL, B. H.	7811070149	50-329
	HERDT, A.R.	7811220284*	50-395 Q	HOFFMAN.D.P.	7810190233	50-256 R	HOWELL, B. H.	7811280124	50-329
HERDT: A. R. 7812210945 50-400 0 HOFFMAN. D. P. 781107027 50-155 8 HOWELL. B. H. 7811200121 50-329 HERDT: A. R. 7812290070 50-438 0 HOFFMAN. D. P. 781114023 50-255 8 HOWELL. B. H. 7811220174 50-329 HERNANDER, Q. 7812270391 50-808 0 HOFFMAN. D. P. 781114023 50-255 8 HOWELL. B. H. 7811270174 50-329 HERRINGIK. B. 7810260228 50-344 0 HOFFMAN. D. P. 7812060028 50-255 0 HOWELL. B. H. 7811270174 50-329 HERRINGIK. B. 7810230104 0 HOFFMAN. D. P. 781120330 50-255 B HOWELL. B. H. 7811270152 50-329 HERRINGIK. B. 7811220198 50-344 0 HOFFMAN. D. P. 781120330 50-255 B HOWELL. B. H. 7812040218 50-329 HETZEL. H. C. 7811220198 50-342 0 HOFFMAN. D. P. 781210330 50-255 B HOWELL. B. H. 7812040218 50-329 HICKLE. B. J. 78101301948 50-285 R HOFFMAN. D. P. 7812060024 50-255 0 HOWELL. B. H. 7812040218 50-329 HICKLE. B. J. 78101301948 50-285 R HOFFMAN. D. P. 7812060024 50-255 D HOWELL. B. H. 7812060249 50-329 HICKLE. B. J. 781140161* 50-285 R HOFFMAN. D. P. 7812060024 50-255 P HOWELL. B. H. 781210068 50-329 HICKLE. B. J. 7811140161* 50-285 R HOFFMAN. D. P. 7812050119 50-255 P HOWELL. B. H. 7812120068 50-329 HICKLE. B. J. 7810130129 50-409 0 HOFFMAN. D. P. 7812030119 50-255 P HOWELL. B. H. 7812120068 50-329 HICKLE. B. J. 7810130129 50-409 0 HOFFMAN. D. P. 7812030119 50-255 P HOWELL. B. H. 781212011* 50-329 HICKLE. B. J. 7810140129 50-409 0 HOFFMAN. D. P. 7812030119 50-255 P HOWELL. B. H. 781212011* 50-329 HICKLE. B. J. 7810140104 50-409 0 HOFFMAN. D. P. 7812130100 50-255 P HOWELL. B. H. 781212011* 50-329 HICKSTAND. D. B. 7810140104 50-409 0 HOFFMAN. D. P. 7812130103 50-255 B HOWELL. B. H. 781212011* 50-329 HICKSTAND. D. B. 7810140104 50-409 0 HOFFMAN. D. P. 7812130103 50-255 B HOWELL. B. H. 781212011* 50-329 HICKSTAND. D. B. 7810140104 50-409 0 HOFFMAN. D. P. 7812130103 50-255 B HOWELL. B. H. 781212011* 50-329 HICKSTAND. D. B. 7810140104 50-409 0 HOFFMAN. D. P. 7812130103 50-255 B HOWELL. B. H. 7812120114 50-329 HICKSTAND. D. B. 7810140104 50-409 0 HOFFMAN. D. P. 7812130103 50-255 B HOWELL. B. H. 7812120114 50-329 HICKSTAND. D. B. 7810700	HERDT, A. R.	7812130005+	50-327 Q	HOFFMAN.D.P.	7810130137	50-255 R	HOWELL, S. H.	7811170212	50-329
	HERDT, A. R.	7812080652+	50-518 Q	HOFFMAN.D.P.	7810190218	50-155 P	HOWELL, S. H.	7811170222	50-329
	HERDT, A. R.	7812180353+	50-416 Q	HOFFMAN.D.P.	7810270075	50-155 P	HOWELL, S. H.	7811170294	50-329
	HERDT, A. R.	7812130298+	50-491 Q	HOFFMAN.D.P.	7811200079	50-255 Q	HOWELL, S. H.	7811170298*	50-329
HERRING.R. B. 7819130106+ 50-344 5 HOFFHAN.D.P. 7811210330 50-255 B HOWELL.B.H. 7812010831 30-329 HEFTZEL.B.C. 7811220198 50-332 9 HOFFHAN.D.P. 7812060024 50-255 0 HOWELL.B.H. 7812060249 50-329 HIGKLE.B.J. 7810130136+ 50-285 R HOFFHAN.D.P. 7812060024 50-255 P HOWELL.B.H. 7812120088 50-329 HIGKLE.B.J. 7811140161+ 50-285 R HOFFHAN.D.P. 7812060164 50-255 P HOWELL.B.H. 7812120088 50-329 HIGKLE.B.J. 7812130181+ 50-285 R HOFFHAN.D.P. 7812001119 50-255 P HOWELL.B.H. 7812120080 50-329 HIGKLE.B.J. 7810130289 50-409 0 HOFFHAN.D.P. 7812080167 50-255 B HOWELL.B.H. 7812120104 50-329 HIESTAND.D.B. 7810140029 50-409 0 HOFFHAN.D.P. 7812120100 50-255 P HOWELL.B.H. 7812120111+ 30-329 HIESTAND.D.B. 7810140029 50-409 0 HOFFHAN.D.P. 7812120100 50-255 P HOWELL.B.H. 7812120114 50-329 HIESTAND.D.B. 78101401029 50-409 0 HOFFHAN.D.P. 7812120205 50-255 B HOWELL.B.H. 7812120114 50-329 HIESTAND.D.B. 7810140104 50-409 0 HOFFHAN.D.P. 7812120095 50-255 B HOWELL.B.H. 7812120154 50-329 HIESTAND.D.B. 7810140104 50-409 0 HOFFHAN.D.P. 7812102065 50-255 B HOWELL.B.H. 7812120164 50-329 HIESTAND.D.B. 78101070316 50-409 0 HOFFHAN.D.P. 7812102033 50-255 B HOWELL.B.H. 7812270184 50-329 HIESTAND.D.B. 78101070316 50-409 0 HOFFHAN.D.P. 78121301061 50-255 B HOWELL.B.H. 7812270184 50-329 HIESTAND.D.B. 78110700316 50-409 0 HOFFHAN.D.P. 78121301061 50-155 F HOWELL.B.H. 7812270184 50-329 HIESTAND.D.B. 78110700316 50-409 0 HOFFHAN.D.P. 78121301061 50-155 F HOWELL.B.H. 7812270184 50-329 HIESTAND.D.B. 78110700316 50-409 0 HOFFHAN.D.P. 78121301061 50-155 F HOWELL.B.H. 7812270184 50-329 HIESTAND.D.B. 7811070034 50-409 0 HOFFHAN.D.P. 78121301061 50-255 B HOWELT.D.H. 78111401130 50-336	HERDT, A.R.	7812210345*	50-400 G	HOFFMAN D. P.	7811070217	50-155 8	HOMELL, S. H.	7811200121	50-329
	HERDT, A.R.	7812290070*	50-438 G	HOFFMAN D. P.	7811070183	50-265 8	HOMELL, S. H.	7811220176	50-329
	HERNANDEZ, Q.	7812270391*	50-50B G	HOFFMAN D. P.	7811140223	50-255 8	HOMELL, J. C.	7812140086*	50-10
	NERRING, K. S.	7810260228*	50-344 G	HOFFMAN D. P.	7812060029	50-255 0	HOMELL, S. H.	7811270147	50-329
HIESTAND. O. B. 7810130229 50-409 0 HOFFNAN. D. P. 7812030167 50-285 8 HOMELL. B. H. 7812120104 50-329 HIESTAND. O. B. 7810140029 50-409 0 HOFFNAN. D. P. 7812120100 50-285 P HOMELL. B. H. 78121201114 50-329 HIESTAND. O. B. 7810140029 50-409 0 HOFFNAN. D. P. 7812110206 50-285 B HOMELL. B. H. 7812120154 50-329 HIESTAND. O. B. 7810140104 50-409 0 HOFFNAN. D. P. 7812120095 50-285 B HOMELL. B. H. 7812270184 50-329 HIESTAND. O. B. 7810270300 50-409 0 HOFFNAN. D. P. 7812130133 50-155 P HOMELL. B. H. 7812270254 50-329 HIESTAND. O. B. 7811070316 50-409 0 HOFFNAN. D. P. 7812130141 50-155 F HOMELL. B. H. 7812270264 50-329 HIESTAND. O. B. 7811070316 50-409 0 HOFFNAN. D. P. 7812130161 50-155 F HOMELL. B. H. 7812270264 50-329 HIESTAND. O. B. 7811070316 50-409 0 HOFFNAN. D. P. 7812130261 50-285 B HOMELT. O. H. 7811070316 50-409 0 HOFFNAN. D. P. 7812220106 50-285 B HOMELT. O. H. 7811401139 50-336 HIESTAND. O. B. 781160167 50-409 0 HOFFNAN. D. P. 7812220106 50-285 B HOMELT. O. H. 7811401139 50-336	HERRING, K. B.	7812130106+	50-344 0	HOFFMAN.D.P.	7811210330	50-255 B	HONELL, B. H.	7812010251	50-329
	HETZEL: N. C.	7811220198	50-352 0	HOFFMAN.D.P.	7812060024	50-255 0	HONELL, B. H.	7812040218	50-329
	HICKLE: B. J.	7810130126+	50-285 R	HOFFMAN.D.P.	7812060361	50-255 0	HONELL, B. H.	7812080249	50-329
	HICKLE: B. J.	7811140161+	50-285 R	HOFFMAN.D.P.	7812040164	50-255 P	HONELL, B. H.	7812120068	50-329
HIGSTAND. D. 8. 7811070316 50-409 0 HOFFMAN, D. P. 7812130316 50-155 F HOMELL. B. 7812290146 50-329 HIGSTAND. D. 8. 7811070034 50-409 0 HOFFMAN, D. P. 7812130261 50-255 8 HOMLETT, O. H. 7810160130# 50-326 HIGSTAND. D. 8. 7811160167 50-409 0 HOFFMAN, D. P. 7812220106 50-255 8 HOMLETT, O. H. 7811140113* 50-326	HIESTAND O.S. HIESTAND O.S. HIESTAND O.S. HIESTAND O.S.	7810130229 7810230136 7810140029 7810140104	50-409 Q 50-409 Q 50-409 Q 50-409 Q	HOFFHAN D. P. HOFFHAN D. P. HOFFHAN D. P. HOFFHAN D. P.	7812050167 7812120100 7812110206 7812120095	00~255 8 30~255 P 50~255 B 50~255 B	HOMELL, B. H. HOMELL, B. H. HOMELL, B. H. HOMELL, B. H.	7812120104 7812120111= 7812120154 7812270184	50-329 50-329 50-329 50-329
	HIESTAND O.S.	7811070316	50-409 0	HOFFMAN, D. P.	7812130141	50-155 F	HOMELL, B. H.	7819290146	50-329
	HIESTAND O.S.	7811070034	50-409 0	HOFFMAN, D. P.	7812130241	50-255 B	HOMLETT, Q. H.	7810140130#	50-336
	HIESTAND O.S.	7811160167	50-409 0	HOFFMAN, D. P.	7812220104	50-255 8	HOMLETT, Q. H.	7811140113#	50-336

HOYLE, J. C. HOYLE, J. C.	7812040424 7812040394	50-334 50-295	0	1PPOLITO T. A IPPOLITO T A	7811010393+ 7811010400+	50-277 50-277	 የ	IPPOLITO T.	781211002 1 7812110023	50-263 50-324
HOYLE, J. C. HUBACEK, W. Q HUBACEK, W. Q	7812060389 7810240236* 7811030040*	50-290 50-498 50-466	0 0	IPPOLITO, T.A. IPPOLITO, T.A. IPPOLITO, T.A.	7810140045 7810140049# 7810140053#	50-321 50-321	P P	IPPOLITO, T. IPPOLITO, T. IPPOLITO, T. A	7812110029 7812110035 7812080157	50-259 50-321 50-324
HUBACEK, H. Q. HUBACEK, H. Q. HUBACEK, H. Q. HUBBARD, R. B. HUBBE, C.	7811200218* 7811280054* 78122060307* 7812210521 7811220277	50-49B 50-556 50-556 50-275 50-344	0 0 0 0	IPPOLITO, T. A.	7810140146 7810230011 7810230016* 7810230019* 7810230028*	90-321 50-277 50-277 50-277 50-277	0 P P P	IPPOLITO, T. A.	7812180104 7812180112* 7812270018 7812080149 7812110197	50-277 50-277 50-263 50-254 50-298
HUETER: L. J. HUETER: L. J. HUFHAM: J. H. HUFHAM: J. H. HUFHAN: J. H.	7811080080* 7812200302* 7810110253* 7810190061* 7810260067*	50-254 50-255 50-324 50-390 50-261	0 0 0 0	IPPOLITO, T. A.	7810230039 7810230043+ 7810230048+ 7810270239 7811020066	50-271 50-271 50-271 50-274 50-271	ե Ե Ե	IPPOLITO, T. A IRWIN, D. P.	7812140276 7812270049 7812270236 7812270230 7810170223	50-333 50-220 50-282 50-293 50-450
HUFHAM, J. H. HUFHAM, J. H. HUFHAM, J. H. HUFHAM, J. H. HUFHAM, J. H.	7810250209* 7811030235* 7811130419* 7812070075* 7812050249*	50-369 50-335 50-338 50-261 50-250	0 0 0 0	IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A IPPOLITO, T. A	7811020071* 7811020086* 7811030013 7811030016* 7811030017*	50-271 50-271 50-366 50-366 50-366	P P P	IRWIN, D, P. IRWIN, D, P. IRWIN, D, P. JABBOUR, K. N. JABLONGKI, F. J.	7810270007 7811130435 78112130212 7811060172 7811070189+	50-463 50-450 50-463 50-244 50-315
HUFHAM, J. W. HUFHAM, J. W. HUFHAM, J. W. HUFHAM, J. W. HUFHAM, J. W.	7812080010* 7812140122* 7812290088* 7812210076* 7812290066*	50-280 50-348 50-280 50-250 50-337	0 0 0 0	IPPOLITO T.A IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A.	7811030022* 78110240008 7811060125* 7811060130*	50-366 50-271 50-277 50-277 50-277	ዮ ዩ የ	JABLON, R. A JABLON, R. A JABLON, R. A. JABLON, R. A. JABLON, R. A.	7810270370 7811080064 7811100180 7811200103 7811100163	50-498 50-389 50-389 50-389 50-498
HUGHEB, J. HUGHEB, J. HUGHEB, J. HUGHEB, J.	7811020168* 7810250039 7811210436* 7811300268* 7812060230*	50-341 50-206 50-266 50-10 50-254	6 0 1 0	JPPOLITO T. A. IPPOLITO T. A.	7811030205 7811030208* 7811030210* 7811030006 7611220230	50-331 50-331 50-331 50-220 50-321	ት 6 6	JABLON, R. A. JACKIU, I. N.	7812040260 7812180246 7812270071 7812270063 7811010076*	50-389 50-329 50-250 50-389 50-264
HUQHEB, J HULMAN, L. Q. HULMAN, L. Q. HULMAN, L. Q. HULMAN, L. Q.	7812130338* 7811200253* 7811200433* 7811200384* 7811200375*	50-295 50-437 50-437 50-437 50-437	Q A A A	IPPOLITO T. A.	7811160022 7811220251 7811220252* 7811220138 7811220140*	50-220 50-220 50-220 50-263 50-263	6 6 6	JACKIW, I. W. JACKIW, I. N. JACKIW, I. N. JACKBON, R. E. JACKBON, L. L.	7811210220* 7812040046* 7812120226* 7812190198 7810270221*	50-331 50-254 50-331 50-70 50-327
HULMAN, L. 9. HUME, 9. W. HUMPHREYB, L. L. HUMPHREYB, L. L. HUMPHREYB, L. L.	7811130372 7810270167 7810110272* 7812260170* 7811070246	50-549 50-443 50-458 50-458 50-510	A G A A	IPPOLITO, T. A.	7811220144* 7811220248 7811270041 7811270100 7811270110*	50-263 50-298 50-298 50-263 50-263	6 E E	JACKBON, L. L. JACKBON, J. B. JACKBON, L. L. JACKBON, R. E. JACKBON, L. L.	7811240013# 7810180143 7812040033# 7811030259 7812110225#	50-335 50-437 50-259 50-70 50-280
HUMPHREYS, L. L. HUNBTAD, A. A. HUNBTAD, A. A. HUNBTAD, A. A. HUNBTAD, A. A.	7812260166 7810180036# 7810180013# 7810120031# 7810120033#	50-458 50-306 50-282 50-282 50-282	A 8 8 R R	IPPOLITO T. A.	7811240058 7811270243 7811270244* 7811270253* 7811300058	50-220 50-333 50-333 50-333 50-237	ቴ ቴ ቴ	JACKBON, T. J. JACKBON, R. E. JACOBBON, N. JACOBBON, O. W. JAMES, E. W.	7812270078* 7812260076 7810170133* 7812050180 7810100055	50-201 50-18 50-266 50-592 50-305
HUNBTAD, A. A. HUNBTAD, A. A. HUNBTAD, A. A. HUNBTAD, A. A. HUNBTAD, A. A.	7810180025# 7811140117# 7812120094# 7812140161# 7812240209#	50-304 50-282 50-282 50-304	8 R R S	IPPOLITO T. A.	7811300064* 7811300067* 7811300070* 7811300073* 7811300085*	50-237 50-237 50-237 50-237 50-237	ե Ե	JAMES, E. H. JAMES, E. H. JAMES, E. H. JAMES, E. H. JAMES, E. H.	7810120041 7810110093 7810130149 7810230247 7810170156	50-305 50-305 50-305 50-305 50-305
HUNSTAD+A.A. HUNT+M.D. HUNT+M.D. HUNT+M.D. HUNT+M.D.	7812260237* 7811080314* 7810230223* 7811070269* 7811240068*	50-306 50-369 50-413 50-332 50-424	6 0 0 9	IPPOLITO, T. A.	7811290367 7812050003 7812050009* 7812050017* 7812050026*	50-263 50-259 50-259 50-259 50-259	Р Р Р	JAMEB, E. H. JAMEB, E. H. JAMEB, E. H. JAMEB, E. H. JAMEB, E. H.	7811070227 7810240128 7810270139 7810300105 7811140116	50-305 50-305 50-305 50-305 50-305
HUNT, M. D. HUNT, M. D. HUNT, M. D. HUNTER, D. R. HUNTER, D. R.	7812070030* 7812270372* 7812110313* 7811300318* 7811300141*	50-364 50-369 50-364 50-255 50-155	G G G	IPPOLITO, T. A.	7812050336 7812050343* 7812050351* 7812060003 7812060009*	50-333 50-333 50-333 50-321	P P P	JAMEB, E. W. JAMEB, E. W. JAMEB, E. W. JAMEB, E. W. JAMEB, E. W.	7811220196 7811280299 7812080108 7812150232 7812210194	50-305 50-305 50-305 50-305 50-305
HUNTER, D. R. HUBAIN, I. HUTCHIBON, F. D. HUTBON, T. W. HUTBON, T. W.	7811300354* 7810160146* 7811080033* 7810110257* 7812270391*	50-255 50-409 50-384 50-344 50-508	@ P A O G	IPPOLITO, T. A.	7812060119* 7811290078 7812050012 7812050016* 7812050020*	50-321 50-277 50-259 50-259 50-259	թ թ թ	JAMEB, E. W. JANAK, B. JANAK, B. JANBEN, T. JANBEN, T.	7812270171 7812110054 7812110057* 7810240141* 7811030191*	50-305 50-498 50-498 50-249 50-249
IANNI,P.W. IBBON,A.F. IDEKER,R.E. IHRIG,R IHRIG,R.	7812010249* 7810300385* 7811210192* 7810190202 7810190220*	50-447 50-369 50-368 50-484 50-484	A G R O	IPPOLITO, T. A.	7812040062 7812080168 7812080170* 7812080176* 7812110319	50-259 50-333 50-333 50-333 50-333	ե ե ե	Jansen, T. Jansen, T. Jansen, T. Januska, A. Q Januska, A. Q	7811280179* 7812180178* 7812270215* 7810110266* 7810110270*	50-249 50-249 50-237 50-346 50-346
IHRIG.R. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A. IPPOLITO.T.A.	7810300369 7810200204 7810200151 7810200131 7810250191	50-484 50-333 50-271 50-259 50-277	С Р Р Р	IPPOLITO, T.A. IPPOLITO, T.A. IPPOLITO, T.A. IPPOLITO, T.A. IPPOLITO, T.A. IPPOLITO, T.A.	7812110320# 7812110323* 7812050045 7812050371 7812060188	50-333 50-333 50-263 50-263 50-220	<u>የ</u> የ	JANUSKA: A. Q. JANUSKA: A. Q. JANUSKA: A. Q. JAPE: F. JAPE: F.	7811300401* 7811270331* 7812270063 7811080166* 7812140048*	50-262 50-346 50-255 50-395 50-265
IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T.A.	7810130200 7810130202* 7810130210* 7810130233 7810130266	50-259 50-259 50-259 50-298 50-298	р Р Р	IPPOLITO T.A. IPPOLITO T.A. IPPOLITO T. IPPOLITO T. IPPOLITO T. IPPOLITO T.	7812050272 7812080164 7812110046 7812110048 7812110052	50-293 50-324 50-333 50-220 50-277	ያ ያ የ የ የ	JENKINS, G. R. JENKINS, G. R. JENKINS, H. D. JENKINS, G. R. JENKINS, G. R.	7813240013* 7812050031* 7812050165* 781240057* 7812070312*	50-335 50-269 50-327 50-336 50-261
IPPOLITO, T. A.	7810140024* 7810140035 7810190043 7810130232* 7811010390	50-298 50-259 50-271 50-277 50-277	P P P	IPPOLITO T. IPPOLITO T. IPPOLITO T. IPPOLITO T. IPPOLITO T. IPPOLITO T.	7812110038 7812110001 7812110002 7812110007 7812110018	50-293 50-254 50-271 50-331 50-298	P P P	JENS, W. H. JENSCH: B. W. JENSCH: B. W. JENSCH: B. W. JENSCH: B. W.	7811070096 7810240053 7811090286 7812040347 7812050277	50~341 50~522 50~522 50~522 50~522

	ACEGORIS.	G(G /5A+		ACCEBBI O N	BUBJECT		ACCESSION	_ല ്ട പട
AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY	AUTHOR	NUMBER	CATEGORY	ACHTUA	NUMBER	CATEO
JEN9CH, 9 W. JERNIGAN, E., P. JOHN, D. F. JOHN, D. F. JOHN, D. F.	7812070273 7811130151* 7810260008 7812040050 7812270416	50-522 0 60-387 0 50-498 M 50-498 M 50-498 M	Kafin, R. J. Kafoury, G. Kafoury, G. Kainer, G. J. Kalivianakis, N.	7812180406 7810270341 7811140027 7811210123 7810170198	50-549 9 50-344 9 50-344 9 50-466 9 50-265 8	KELLY, D. L. KELMON: R. M. KENDALL, D. M. KENNA: W. B. KENNA: W. B.	7810130053* 7812050228 7811290014 7810270103 7811130003	50-313 50-273 50-478 50-13 50-250
OGHNBON'N D NOHNBON'E H NOHNBON'E H NOHNE'C	7810160132 7810140133* 7810270196* 7810120016* 7811030036*	50-455 H 50-298 Q 50-334 Q 50-298 Q 50-295 Q	Kalivianakis, n Kalivianakis, n Kalivianakis, n Kalivianakis, n Kalivianakis, n	7910170172 7811020375+ 7810170232 7811240175 7811240222	50-265 B 50-254 F 50-254 B 50-254 B 50-265 B	Menna, W. B. Menna, H. B. Menna, H. B. Menna, H. B. Menna, H. B.	7810110198* 7811100086* 7811100124* 7810110187 7810140057	50-93 50-25 50-25 50-93 50-97
JOHNBON, E. H. JOHNBON, R. W. JOHNBON, D. F. JOHNBON, D. F. JOHNBON, D. F.	7811060055+ 7810140087 7810140122 7811080096+ 7810240094+	50-298	Kalivianakis, n. Kalivianakis, n. Kalivianakis, n. Kalivianakis, n Kalivianakis, n.	7811240237 7811240192 7811240179 7811070118 7811240203	50-254 P 50-265 B 50-254 8 50-254 8 50-265 8	Kenna, H. B. Kenna, H. B. Kenna, H. B. Kenna, H. B. Kenna, H. B.	7810260015 7811010298 7812010175 7811060036 7812040322	50-280 50-301 50-140 50-336
JOHNSON, A. JOHNSON, L. C. JOHNSON, M. D. JOHNSON, W. D. JOHNSON, W. P.	7811130381* 7811070294* 7810130046 7811210501* 7810110163	50-349 Q 50-243 P 50-395 Q 50-313 Q 50-29 P	Kalivianakie, n. Kalivianakie, n. Kalivianakie, n. Kalivianakie, n. Kalivianakie, n	7811240239 7811240133 7811220031 7812110181 7812110176	50-265 8 50-265 8 50-254 R 50-254 8 50-254 8	Kenna. H. B. Kenna. H. B. Kenna. H. B. Kenna. H. B. Kenna. H. B.	7811030043 7811090198 7811100103 7811140257 7811100082	50-251 50-251 50-241 50-251
JOHNBON: D. F. JOHNBON: R. W. JOHNBON: W. D. JOHNBON: R. JOHNBON: R.	7811150276* 7810130150* 7811280062* 7811240201* 7811240223*	50-317 G 50-344 D 50-285 G 50-295 B 50-295 B	Kalivianakie, n. Kalivianakie, n. Kalman, O. Kalman, O. Kalman, O.	7812200235 7812270225 7812070295* 7812010031* 7812010276*	50-254 R 50-254 P 50-219 G 50-277 G 50-219 G	Kenna, H. B. Kenna, H. B. Kenna, H. B. Kenna, H. B. Kenna, H. B.	7811100104 7811090009 7812040288 7812110246 7812130310*	20 - 20 - 20 - 20 - 20 - 20 - 20 - 20 -
JOHNSON, M. C. JOHNSON, A. H. JOHNSON, W. P. JOHNSON, R. W. JOHNSON, M. C.	7811080151+ 7812120237+ 7810240085 7811070364 7811070232	50-395	Kaltman, M. Kaminskas, V. A. Kanciruk, P. Kane, O. Kane, N. F.	7610270162+ 7612140152* 7810140076 7612200262* 7612130144	50-443 A 50-251 P 50-395 T 50-280 R 80-550 A	Kenna, W. B. Kenna, H. B Kenna, H. B. Kenna, H. B. Kenna, H. B.	7811200335 7812210355 7811210242 7812290101* 7811300003	50-28 50-23 50-33 50-33
JOHNSON, M. C. JOHNSON, W. P. JOHNSON, E. H. JOHNSON, P. H	7811150062* 7811090147 7811290341* 7812180356* 7812130350*	50-395 Q 50-443 B 50-443 B 50-298 Q 50-187 Q	KANE, H. F. Kapple, A. H. Kapple, A. H. Kapple, A. H. Kapple, A. W.	7612270012 7810100033* 7810100041* 7810100087* 7810200125*	50-447 A 50-272 S 50-272 S 50-272 S 50-272 S	KENNA, W. B. KENNA, W. B. KENNA, W. B. KENNA, W. B. KENNA, W. B.	7811300010* 7812120047 7812120051 7812120053 7812120057	20 - 82 20 - 82 20 - 82 20 - 83
JOHNSON, R. Q. JOHNSON, H. D. JOHNSON, R. H. JOHNSON, R. H. JOHNSON, M. C.	7811140180 7812060381 = 7811210044 = 7811300374 7811220280	50-263 J 50-285 G 50-466 G 50-344 P 50-395 G	KAPPLE, A. W. Kapple, A. W. Kapple, A. W. Kapple, A. W. Kapple, A. W.	7810230249* 7810230255* 7810230304* 7810310240* 7811070245*	50-272 8 50-272 8 50-272 8 50-272 8 50-272 8	KENNA, W. B. KENNA, H. B. KENNA, W. B. KENNA, W. B. KENNA, W. B.	7812120063 7812120157 7812120164 7812120175 7812120180	50-32 50-28 50-41 50-43 50-34
JOHNSON, M. C. JOHNSON, D. F. JOHNSON, A. D. JOHNSON, M. C. JOHNSON, M. C.	7812040028# 7812290034# 7812040167 7812140039# 7812040374	50-395	KAPPLE A W. Kapple A W. Kapple A W. Kapple A W. Kapple A W.	7811070181* 7811070268* 7811200203* 7811240137* 7811280313*	50-272 8 50-272 8 50-272 8 50-272 8 50-272 8	KENNA, H. B. KENNA, H. B. KENNA, W. B. KENNA, H. B. KENNA, H. B.	7812120185 7812120189 7812120197 7812140055* 7812140255	50-24 50-41 50-30 50-26 50-40
JOHNSON, E. H. JOHNSON, R. W. JOHNSON, R. W. JOHNSON, M. C.	7812210184* 7812040031* 7812140211 7812140267 7812010329	50-298	KAPPLE, A. H. Kapple, A. W. Karman, M. Karman, M. Katanich, O.	7812140169* 7812220086* 7812050050 7812130149 7810120091	50-272 8 50-272 8 50-263 9 50-263 9 50-344 9	Kenna, H. B. Kenna, H. B. Kenna, H. B. Kenna, H. B. Kenna, H. B.	7812130294 7812180315 7812180346 7812180352 7812210281	50~32 50~33 50~34 50~26 50~27
JOHNBON, M, C. JOHNBON, A, H. JOHNBON, R, H. JOHNBON, R, W. JOHNBON, M, C.	7812140057 7812040333* 7811280327* 7811280317* 7812120029	50-395 8 50-269 0 50-344 0 50-344 P 50-395 0	Kahula. L Kahula. L Kahula. L Keane , B. S. Kearney, P.	7810230150* 7811210344* 7812210211* 7812130220 7810110137*	50-247 R 50-3 R 50-3 R 50-305 0 50-368 8	Kenna, W. B. Kenrick, J. R. Kenrick, J. R. Kenrick, J. R. Keppler, J. Q.	7812290096 7810160112 7810230383 7811150257 7812120212	50-30 50-43 50-43 50-43 50-25
JOHNOBNAR, W. JOHNOBNAR, W. JOHNOBNAR, W. JOHNOBNAR, W. JOHNOBNAR, W.	7812140377 7812030218# 7812270382# 7812270076 7812280179	50-344	KEARNEY, P. KEBLUBEK, B. KEBLUBEK, B. KEEFE, F. T. KEHOE, D. V.	7810170194* 7811130331 7812130377 7810230197 7812010338*	50-368 8 50-369 A 50-369 A 50-496 A 50-320 Q	KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	7812040172 7811280030 7810110269 7810140050 7810110257	50 - 20 50 - 20 50 - 20 50 - 44
JOHNBON, M. C. JOHNBON, A. Q. JONEB, Y. I. JONEB, C. E. JONEB, C. E.	7612280302 7612270197* 7811010324 7611210027* 7611210013*	50-395 0 50-106 P 50-275 0 50-456 G 50-456 Q	Keiler, E. H. Keimig, R. R. Keimig, R. R. Keimig, R. R. Keimig, R.	7811010389* 7810270176* 7811150105* 7811080096* 7812010062*	50-524 A 50-334 G 50-309 G 50-317 G 50-266 G	KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7811080104* 7811010906 7810300106 7810130217 7810110053	50 - 31 50 - 34 50 - 34 50 - 41
JONES C. E. JONES C. E. JONES C. E. JONES V. E. JONES V. I.	7812040163* 7812150240* 7812070108* 7812210075* 7812180309	50-346 G 50-245 G 50-456 G 50-546 G 50-275 G	KEIMIO, R. R. KEIMIO, R. R. KEIMIO, R. R. KEIMIO, R. R. KEITH, R. S.	7812270423+ 7812280012+ 7812270034+ 7812270153+ 7811300193+	50-272	KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	7811080101 7810110293 7811170260 7810110228 7810130034	2000 2000 2011 2011 2011 2011 2011 2011
JONES, D. JORDAN, E. L. JORDAN, E. D. JORDAN, M. H. JORGENSEN, B. L.	7612200272* 7611280493* 7610170186 7611080073 7611300318*	50-285 8 50-331 P 60-77 P 50-488 9 50-255 0	KEITH, R. B. KELLEY, D. L. KELLEY, J. L. KELLEY, J. J. KELLEHER, J. A.	78122702824 78101200164 7810300262 78111402054 781112200924	50-316 8 50-298 0 50-387 8 50-336 8 50-549 T	KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7810130088 7810130185 7811300225 7810200211 7810200207	90000 9000 9000 9000
JOROENSEN, B. L. JOYCE, J. P. JOYNER, J. H. JOYNER, J. H. JUBACH, R.	7811300354+ 7811220082+ 7810270113+ 78110100994 7811070296	30-235 G 30-349 T 50-13 G 50-227 G 50-348 A	KELLEHER, J. A. Kelley, J. L. Kellogg, P. J. Kellogg, P. J. Kellogg, P. J.	7811220076* 7812180037* 7810110262* 7810310144* 7810310134*	50-549 T 50-275 Q 50-250 Q 50-261 Q 50-324 Q	KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7810230328 7810230332 7810230334 7810230336 7810230338	00000 1777 1777
Julian, C. A. Jutrag, R. Kafin, R.J. Kafin, R.J. Kafin, R.J.	7812130317* 7812140154* 7810200136 7810270265 7812180052	50-269 G 50-220 8 50-349 G 50-549 G 50-549 G	KELLDOG.P. J. KELLDOG.P. J. KELLDOG.P. J. KELLDOG.P. J. KELLDOG.P. J.	7810310116* 7811220064* 7811130229* 7812140156* 7812210350*	50~338	KEPPLER, J. 9. KEPPLER, J. 9. KEPPLER, J. 9. KEPPLER, J. 9. KEPPLER, J. 9.	7810230341 7810230343 7810230346 7810230336 7810230357	00000 00000 00000
						÷		

AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	TOBUECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
XEPPLER.J. O	7810300030	50-10 G	KEPPLER.J. O	7812280041	50-483 Q	KNOP, R. C	7811010074+	50-254 0
KEPPLER.J. O.	7811020160	50-315 G	KEPPLER.J. O	7812280044	50-440 Q	KNOP, R. C	7810250220+	50-331 0
KEPPLER.J. O.	7811020349	50-254 F	KEPPLER.J. O	7812280047	50-315 Q	KNOP, R. C	7810250222+	50-331 0
KEPPLER.J. O.	7811030206	50-483 H	KEPPLER.J. O	7812280052	50-331 Q	KNOP, R. C	7811010022+	50-10 0
KEPPLER.J. O.	7812050011	50-10 G	KEPPLER.J. O	7812280053	50-309 Q	KNOP, R. C	7811080074+	50-295 0
KEPPLER.J. O. KEPPLER.J. O. KEPPLER.J. O. KEPPLER.J. O. KEPPLER.J. O. KEPPLER.J. O.	7812050027+	50~10 Q	KEPPLER.J.O	7812280055	50-409 G	KNOP, R. C.	7812040046*	50-254 Q
	7811060072	50~266 Q	KEPPLER.J.O	7812280056	50-155 G	KNOP, R. C	7812050027*	50-10 Q
	7811080190	50~346 P	KEPPLER.J.O	7812280057	50-341 G	KNOP, R. C	7812060236*	50-295 Q
	7811130338	50~282 P	KEPPLER.J.O	7812280059	50-255 G	KNOP, R. C.	7812270070*	50-346 Q
	7811140022	50~282 P	KEPPLER.J.O	7812280062	50-282 G	KNOTTS, J B.	7812180278	50-498 M
KEPPLER, J. O.	7811160191 7811130052 7811130066 7811130351 7811150004	50-282 P 50-331 F 50-407 G 50-305 G 50-461 G	KEPPLER, J. O.	7812280064 7812280065 7812290015 7812290016 7812290018	50-484 @ 50-263 @ 50-329 @ 50-358 @ 50-367 @	. В . «ВТТОИХ В С . «ВТТОИХ В С . «ВТТОИХ В . «ВТТОИХ В . «ВТТОИХ	7810110064 7810200139 7810110279 7810140141 7811070174	50-397 Q 50-498 M 50-445 Q 50-445 M 50-498 M
KEPPLER,J. O.	781:150024	50-346 0	KEPPLER, J. G	7812290021	50-461	KNOTTB, J B	7811150021	50-397 Q
KEPPLER,J. O.	781:150025	50-440 0	KEPPLER, J. G.	7812290023		KNOTTB, J B	7811300008	50-445 M
KEPPLER,J. O.	781:150031	50-341 0	KEPPLER, J. G.	7812290026		KNOTTB, J B	7812200224	50-445 A
KEPPLER,J. O.	781:150036	50-358 0	KEPPLER, J. G.	7812290037		KNOTTB, J B	7812290123	50-445 M
KEPPLER,J. O.	781:150044	50-367 0	KERR, W.	7812290037		KNOTTH, D F	7811200147	50-437 A
KEPPLER, J. G.	7811150048	50-484 @	KETCHEN, E. O.	7810110055	50-369 0	KNUTH: D. F	7811200151* 7811200114* 7812260141 7810300037 7811060050	50-437 A
KEPPLER, J. G.	7811150051	50-155 @	KETCHEN, E. O.	7810140152	50-566 0	KNUTH: D. F.		50-437 A
KEPPLER, J. G.	7811150054	50-263 @	KETCHEN, E. O.	7810200006	50-369 0	KOCH: L. J		50-461 A
KEPPLER, J. G.	7811150057	50-329 @	KETCHEN, E. O	7810200241	50-369 0	KOCHANNY: Ø. L		50-264 F
KEPPLER, J. G.	7811150059	50-483 @	KETCHEN, E. O	7811090262	50-369 0	KOCHER: C. Å.		50-361 G
KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q. KEPPLER, J. Q.	7611150061 7811150063 7811150068 7811150069 7811150071	50-315	KETCHEN, E. O. KETCHEN, E. O. KETCHEN, E. O KETCHEN, E. O. KETCHEN, E. O	7811160016 7811200074 7811210100 7811210119 7812010087	50-367 @ 50-566 @ 50-369 @ 50-366 @ 50-369 @	KOENTO.L.R. KOEBTER.O.L KOEBTER.O.L KOEBTER.O.L KOEBTER.O.L	7811200019* 7812110282* 7812110276* 7811030217 7811160186*	50-437 A 50-482 A 50-482 A 50-482 S
KEPPLER, J. Q.	7811150072	50-305 Q	KETCHEN.E. O.	7811220149	50~566 0	KOESTER.O L. KOESTER.O L. KOESTER.O L KOESTER.O. KOESTER.O. KOESTER.O.	7811160189+	50-482 0
KEPPLER, J. Q.	7811130137	50-440 A	KETCHEN.E. O.	7812050088	50~369 0		7810250031+	50-482 0
KEPPLER, J. Q.	7811130141	50-305 P	KETCHEN.E. O.	7812050065	50~460 0		7810270320	50-482 A
KEPPLER, J. Q.	7811130143	50-327 A	KETCHEN.E. O.	7812050091	50~566 0		7812110271+	50-482 A
KEPPLER, J. Q.	7811130157	50-263 P	KETCHEN.E. O.	7812130038	50~566 0		7811170249+	50-482 0
KEPPLERIJ. Q.	7811130159	50-484 A	KETCHEN.E. Q.	7812070262	50-566 Q	KOESTER.Q.L	7819200348	50-482 S
KEPPLERIJ. Q.	7811130160	50-367 A	KETCHEN.E. Q.	7812110327	50-513 Q	KOESTER.Q.L.	7819200349*	50-482 S
KEPPLERIJ. Q.	7811130163	50-546 A	KETCHEN.E. Q.	7812080225	50-269 Q	KOHLER.J.E.	7810270376*	50-301 G
KEPPLERIJ. Q.	7811130164	50-315 P	KETCHEN.E. Q.	7812130146	50-275 Q	KOHLER.J.E	7810310340*	50-316 G
KEPPLERIJ. Q.	7811130167	50-155 P	KETCHEN.E. Q.	7812140346	50-275 Q	KOHLER.J.E	7812140147*	50-266 G
KEPPLER, J. O.	7811130167	50-407 P	KETCHEN; E. Q	7812140344	50-275 0	KOKOBZKA, C.	7811210284+	50-213 R
KEPPLER, J. O.	7811130172	50-358 A	KEUCH; R. L.	7811270304#	50-70 0	KOKOBZKA, C.	7812050164+	50-213 R
KEPPLER, J. O.	7811130173	50-331 P	KEY; W. J.	7810110274*	50-358 0	KONKL 1N.J. E	7810190252+	50-454 G
KEPPLER, J. O.	7811130174	50-483 A	KEY; W. J.	7811130088*	50-331 0	KONKL 1N.J. E	7811210112+	50-440 G
KEPPLER, J. O.	7811140002	50-10 P	KEY; W. J.	7811280032*	50-331 0	KONKL 1N.J. E.	7811300254+	50-440 G
KEPPLER, J. O	7811140275	50-346 P	MEY, W. J.	7811210024* 7812140066* 7812130134* 7811270014* 7812060336*	50-331 Q	KONKLIN.J.E.	7812060358*	50-454 C
KEPPLER, J. O.	7811140276	50-461 A	Key, W. J.		50-331 Q	KONKLIN.J.E.	7812280316*	50-440 C
KEPPLER, J. O.	7811210452	50-282 P	Key, W. J.		50-331 Q	KODI,M.	7811240177*	50-254 S
KEPPLER, J. G.	7812010083	50-282 P	Kidd, M. B.		50-338 Q	KOPACZ	7811240193*	50-265 S
KEPPLER, J. G.	7812130035	50-315 Q	Kidd, M. B.		50-338 Q	KORCHYNSKY,M.	7811210339*	50-249 S
KEPPLER, J. G.	7811210457	50-255 G	KIEGEL, J. A.	7812130100	50-331 H	KOTTAN; J. J.	7811020188*	50-271 0
KEPPLER, J. G.	7812010053	50-331 Q	KINDER, E. T.	7810180077	50-443 A	KOTTAN; J. J.	7812010150*	50-244 0
KEPPLER, J. G.	7811270291	50-331 P	KINTIGH. A. E.	7812270264	50-596 A	KOTTAN; J. J.	7812010041*	50-220 0
KEPPLER, J. G.	7812200292	50-35B Q	KINTIGH. A. E.	7812270265	50-596 F	KOTTAN; J. J.	7811300342*	50-213 0
KEPPLER, J. G.	7811300114	50-255 Q	KINTIGH. A. E.	7812270266	50-596 B	KOTTAN; J. J.	7812060244*	50-317 0
KEPPLER, J. Q.	7812050263	50-407 0	KINTIGH, A. E.	7812290267*	50-596 A	KOTTAN, J. J.	7812110235#	50-334
KEPPLER, J. Q.	7812050871	50-266 0	KINTNER, L. L.	7812040206	50-341 A	KO: TAN, J. J.	7812270078#	50-201
KEPPLER, J. Q.	7812050274	50-346 0	KINTNER, L. L.	7812130328	50-341 A	K: JACH, B.	7811210352#	50-346
KEPPLER, J. Q.	7812050278	50-263 0	KIPPLER, J. Q.	7812050267	50-305 G	KOVACH, B.	7811210362#	50-346
KEPPLER, J. Q.	7812050282	50-331 9	KIRCH, D. F.	7812210153*	50-460 G	KOVACH, B. A.	7811210375#	50-346
KEPPLER, J. O.	7812050287	50-10 Q	KIRBCH D.F.	7810110259*	90-344	KOVACH, 8 A.	7810180042+	50-346
KEPPLER, J. O.	7812050300	50-358 G	Kirbch D.F.	7810230094*		KOVACH, 8 A.	7810160140+	50-346
KEPPLER, J. O.	7812050305	50-346 Q	Kister H.S.	7811080097*		KOVACH, 8 A.	7810310201+	50-346
KEPPLER, J. O.	7812050308	50-463 Q	Kister H.B.	7811090017*		KOVACH, 8 A.	7811070267+	50-346
KEPPLER, J. G.	7812050311	50-315 Q	Kister H.	7812010103*		KOVACH, 8 A.	7811070275+	50-346
Keppler, J. O.	7812050314	50-155 G	KISTER, H. S.	7812110310+	50-245 Q	KOVACH, 8.	7812050206#	50-346
Keppler, J. O.	7812050325	50-440 G	Kister, H. B.	7812110301+	50-336 Q	KOVACH, 8.	7812070201#	50-346
Keppler, J. O.	7812050333	50-327 G	Kister, H.	7812080147+	50-334 Q	KOVACH, 8.	7812120146#	50-346
Keppler, J. O.	7812050335	50-341 G	Kister, H. B.	7812270449+	50-220 Q	KOVACH, 8. A.	7812120181#	50-346
Keppler, J. O.	7812050337	50-461 G	Kister, H.	7812270053+	50-271 Q	KRAFT, D. C.	7811170293#	50-148
KEPPLER, J. O.	7612050338	50-367 Q	KLINE, R. V.	7810160013*	50-471 A	KRAFT, D. C.	7812060319*	50-148
KEPPLER, J. O.	7612050344	50-484 Q	KLINE, R. V.	7811030155	50-471 A	KRAHCIAK, A. T.	7812210221*	50-304
KEPPLER, J. O.	7612280334*	50-329 Q	KLINGLER, O. R.	7810130099*	50-321 G	KREGER, W. E.	7811210463	50-556
KEPPLER, J. O.	7612050062	50-456 Q	KLUTH, F. C.	7811160160*	50-440 F	KRISTOVICH, S.	7810190262*	50-275
KEPPLER, J. O.	7612130234	50-331 P	KNAPP, P. J.	7812060316*	50-184 G	KRISTOVICH, S.	7810190269*	50-275
KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O. KEPPLER, J. O.	7812140081 7812220037 7812150202 7812210118 7812200365	50-10 0 50-358 A 50-255 Q 50-331 P 50-367 Q	KNAPP:P.J. KNAPP:P.J. KNAPP:P.J. KNAPP:P.J. KNECHT:W.G.	7812010096* 7811090038* 7811150049* 7811300380* 7812210396	50-286 G 50-317 G 50-220 G 50-20 G 50-482 B	KRIBTOVICH, B. KUESTNER, P. KUNDER, Q. A. KUNSITIS, T. J. KUO, P. T.	7810270294 7812120042* 7812270093 7810180121* 7811290294	50-275 50-580 50-320 50-280 50-275
KEPPLER. J. O.	7612210354	50~315 F	KNIGHT, J. E.	7810260243#	50-344 9	KURKJIAN, T. 9.	7812190431	50-70
KEPPLER. J. Q.	7612280196	50~329 H	KNIGHTON G.	7811030177	50-250 P	KURON. F.	7810260086	50-341
KEPPLER. J. Q.	7612280307	50~440 Q	KNIGHT, J. P.	7812040338#	50-275 9	KUSEK, L. T.	7812010240*	50-285
KEPPLER. J. Q.	7612280002	50~295 G	KNOLL, R. M.	7811100076#	50-213 G	KUSEK, L. T.	7812050179*	50-285
KEPPLER. J. Q.	7612280036	50~266 G	KNOP, R. C.	7811010309#	50-346 G	KUSEK, L. T.	7812270333*	50-285

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOGRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
KUZHYCZ-Q KUZHYCZ-Q KUZHYCZ-Q KUZHYCZ-Q KUZHYCZ-Q.	7811010207 7812010157 7812080021 7812110242 7812130273	50-267 P 50-267 P 50-267 P 50-267 P 50-267 P	LEECH-P. LEED: R. M LEED: R. M LEED: R. M LEED: R. M	7812130320 7810130089 7811300400 7812080165 7812150259	50-592 A 50-522 G 50-522 G 50-522 O 50-443 O	LEMIS, S M LEWIS, N O LEWIS, R C LEWIS, R C LEWIS, R C	7810250314 7811080088 7811130381* 7810250234* 7811070320*	30-484 G 30-397 G 50-369 G 50-34B G 50-250 G
LABLONGKI, F. J LADUN, R. H LADUN, R. LAFLEUR, J. D LAFOLLETTE, B. C	78:2130209* 78:1080:77* 78:2280309* 78:1200215* 78:0190085	50-315 0 50-333 0 50-293 0 50-437 A 50-266 0	LEED.R.M. Leed.R.M. Lefevre.H e Lefevre.H.E. Legate.R.E.	7812110199 7812190080 7810120102 7812080139 7811270099*	50-522 0 50-522 0 50-522 A 50-522 A 50-155 P	LEMIB.R.C LEMIB.R.C. LEMIB.B H LEMIB.B.H LEMIB.R.C	7811130364# 7811270014# 7810300243 7811010148 7811220005#	50-369 @ 50-338 0 50-247 P 50-484 0 50-335 0
Lagdmarbing, R. J Lainab, Q Lainab, Q Lainab, Q Lainab, Q	7812180289 7811020012 7811030255 7811030011 7811020091	50-275 H 50-29 F 50-206 F 50-29 P 50-313 P	LELLOUCHE, O. 8. LEMANONICZ, I. LEMANONICZ, I. LEMANOWICZ, I. LEMLY, M. 8.	7812210183* 7811010435* 7812260008* 7812260003 7811200102*	50-500 A 50-387 0 50-387 0 50-387 0 50-437 A	LEMIS.R C LEMIS.R.C LEMIS.R.C LEMIS.R.C LEMIS.R.C	7812040181# 7811280398# 7812060228# 7812060262# 7812010109#	50-395 0 50-269 0 50-33B 0 50-280 0 50-280 0
Lainas, q Lainas, q Lainas, q Lainas, q Lainas, q	7811020096* 7811030277 7811030259 7811130299 7811170055	50-313 P 50-155 P 50-334 P 50-333 P 50-313 B	LEMLY, M. B. LENAHAN, J. J LENAHAN, J. J LENGEL, R. A LENGEL, R. A.	7811200083* 7812070023* 7812290111* 7810100095* 7810100080*	50-437 A 50-518 G 50-553 G 50-320 8 50-320 8	LEMIS.S.H LEMIS.S.H LEMIS.S.H LEMIS.S.H	7811060236 7811070284 7811130002 7811140003 7811140026	50-484 Q 50-263 Q 50-263 Q 50-443 Q 50-482 F
lainas. 0 Lainas. 0 Lainas. 0 Lainas. 0 Lainas. 0	7811210060 7811200047 7811200366 7811280361 7811290076	30-206 F 50-247 P 50-275 A 50-259 P 50-282 F	LENGEL R.A. LENGEL R.A. LENGEL R.A. LENGEL R.A. LENGEL R.A.	7810110083* 7810110134* 7810170148* 7811210336* 7811210384*	50-320 8 50-320 8 50-320 8 50-320 8	LEWIS, J. O. LEWIS, S. H. LEWIS, N. D. LEWIS, N. D.	7811210353 7811210418 7811150231 7811140279 7811140042	50-255 8 50-255 8 50-349 0 50-522 0 50-522 0
Lainas, o Lainas, o Lancaster, j l Lancaster, j l Lang, p. m	7612260001 7812270365 7812190118 7812190123* 7810250062	50-269 P 50-299 F 50-261 J 50-261 J 50-269 P	LENGELAR. A. LENGELAR. A LEONARD.J. D. LEONARD.J. D. LEONARD.J. D.	7812060177+ 7812130197+ 7810100022 7810130128 7810120045	50-320 8 50-320 8 50-333 8 50-333 R 50-333 8	LENIS, S.H. LENIS, S.H LENIS, R.C. LENIS, A.S. LENIS, B.H.	7812150045 7811150040 7812040334* 7811270049 7811220058	50-482 G 50-549 Q 50-33B Q 50-70 Q 50-549 Q
LANGNER.R.R LARMI.O.J. LARSON.L.K LARSON.L.K. LARSON.L.K.	7810300037 7812280329 7810160108 7810230238 7810180148	50-264 F 50-387 0 50-244 P 50-244 0 50-244 P	LEONARD.J.D. LEONARD.J.D. LEONARD.J.D. LEONARD.J.D. LEONARD.J.D.	7810120073 7810230186 7810230263 7810240122 7810240133	50-333 8 50-333 8 50-333 8 50-333 8	LEHIS, 8. H LEHIS, 8. H. LEHIS, R. C. LEHIS, B. H. LEHIS, S. H	7811220134 7811220137 7812210113* 7812040358 7812130061	50-482 0 50-484 0 50-280 0 50-549 0
LARSON, L. K. LARSON, L. K. LARSON, L. K. LARSON, L. K. LARSON, L. X. LASHER, D. R	7810190068 7811010376 7811060241 7812040283 7811020024	50-244 P 50-485 G 50-485 G 50-485 G 50-327 E	LEONARD, J. D LEONARD, J. D LEONARD, J. D. LEONARD, J. D. LEONARD, J. D.	7811070318 7811070244 7811140121 7811140238 7811210414	50-333 8 50-333 8 50-333 8 50-333 8	LEWIS, S. H. LEWIS, R. C LEWIS, R. C. LEWIS, S. H. LEWIS, S. H.	7812130065# 7812140048# 7812050018# 7812150189 7812180405	50-549 Q 50-249 Q 50-348 Q 50-549 Q 50-450 Q
LASTOVKA, J. M LATHAM, M. E LAURGEN, H. I. LAURENCE, J. F. LAURENCE, J. F.	7811270281 7810200032 7810270402 7810110275 7811130234	50-440 G 50-70 H 50-344 T 50-514 G 50-514 G	LEONARD, J. D LEONARD, J. D LEONARD, J. D. LEONARD, J. D. LEONARD, J. D.	7812040156 7812070174 7812150267 7812220099 7812260189	50-333 8 50-333 8 50-333 8 50-333 8 50-333 P	LENIS, 8. H LENIS, 8. H. Librizzi, F. P. Librizzi, F. P. Librizzi, F. P.	7812270468 7812280262 7810110091 7810100028 7810100037	50-549 0 50-247 0 50-272 P 50-272 8 50-272 8
LAHRENCE, J. F LAWRENCE, J. F. LAHRENCE, J. F. LAWRENCE, J. F. LAWRENCE, J. F.	7811219471 7811290044 7812040141 7812040144 7812040285	50-305 P 50-514 P 50-305 Q 50-305 Q 50-305 Q	LEONARD.J.D. LEONARD.J.D. LEOBOR.L.C. LEOBOR.L.C. LEOBOR.L.C.	7812270246 7812270242 7810300173 7810300201 7812050166	50-333 8 50-333 8 50-298 9 50-298 8 50-298 8	LIBRIZZI, F.P. LIBRIZZI, F.P. LIBRIZZI, F.P. LIBRIZZI, F.P. LIBRIZZI, F.P. LIBRIZZI, F.P.	7810100087 7810250118 7810200119 7810240083 7810230243	50-272 P 50-272 P 50-272 P 50-272 P 50-272 B
LAWRENCE, J. F.	7812040288* 7812030243 7812030252* 7811290239 7811290273	50-305 0 50-305 0 50-305 0 50-314 0 50-305 0	LE88DR, L.C. LE88DR, L.C. LE88DR, L.C. LE88DR, L.C. LE88DR, L.C.	7810170268 7812050135 7811160113 7812050144 7812200259	50-298 R 50-298 R 50-298 R 50-298 S 50-298 S	LIBRIZZI, F.P. LIBRIZZI, F.P. LIBRIZZI, F.P. LIBRIZZI, F.P. LIBRIZZI, F.P. LIBRIZZI, F.P.	7810230252 7810230295 7810250103 7810250103 7810310254 7811060089	50-272 8 50-272 8 50-272 R 50-272 9 50-272 P
LAWRENCE J F. LAWROSKI.S. LAWROSKI.S. LAWROSKI.S. LAZARUS.W.J.	7811290355 7812050007 7811210318* 7812150050 7811150105*	50-397 0 50-500 0 50-275 A 50-275 G 50-309 Q	LESSOR, L. C. LESSOR, L. C. LESSOR, L. C. LESSY, R. P. LESSY, R. P.	7812130158 7812290197 7812200271 7810310179* 7810140156	50-278 R 50-278 B 50-278 B 50-478 M 50-478 Q	LIBRIZZI.F.P LIBRIZZI.F.P. LIBRIZZI.F.P. LIBRIZZI.F.P. LIBRIZZI.F.P	7811060091 7811070262 7811070178 7811070266 7811200201	50-272 P 50-272 8 50-272 8 50-272 8
LAZARUS, H. J LAZARUS, H. J. LAZARUS, W. J LAZO, R. M LAZO, R. M	7811100094* 7811100076* 7812010278* 7810230337 7811130044	50-213 0 50-213 0 50-27 0 50-263 0 50-369 0	LEBSY, R. P. LEBSY, R. P. LESSY, R. P. LESSY, R. P. LESSY, R. P.	7810230124 7810310020 7811680067 7811080076+ 7811080118	30-443 M 30-498 M 30-466 M 30-466 M 50-440 A	LIBRIZZI, F. P.	7811240132 7811240219 7812080134 7811280304 7812110150	50-272 8 50-272 P 50-272 R 50-272 8 50-272 0
LAZO, R. M LEAR, Q. LEAR, Q. LEAR, Q. LFASE, R. B	7812110280 7812130198 7811200080* 7810230035 7810180004*	50-592 Q 50-277 P 50-346 P 50-277 P 50-316 B	LESSY: R. P. LESSY: R. P. LESSY: R. P. LESSY: R. P. LESSY: R. P.	7811270055 7812110203 7812210372 7812210262 7812270091	50-445 M 50-346 G 50-445 M 50-498 M 50-498 M	LIBRIZZI.F.P. LIBRIZZI.F.P. LIBRIZZI.F.P. LIBRIZZI.F.P. LICITRA.E.A	7812140167 7812210206 7812220085 7812270181 7810140110	50-272 8 50-272 F 50-272 8 50-272 P 50-482 A
LEASE, R. S. LEASE, R. S. LEASE, R. S. LEASE, R. S. LEASE, R. S	7810230183* 7810230185* 7810270314* 7811140226* 7812080120*	50-316 8 50-316 8 50-316 8 50-316 8 50-316 8	Leving, J. M. Levin, H. A. Leving, A. J. Levin, H. A. Levin, H. A.	7810130169# 7811100131 7812040018# 7812040303 7812220067	50-213 8 50-237 P 50-556 T 50-10 P 50-237 P	LICITRA-E LICITRA-E, A LICITRA-E, A LIKE-I LIKE-I	7811210277 7811280128 7811280161 7810160107 7810190226	50-466 A 50-582 A 50-592 H 50-7:. 0 50-516 0
LEASE, R. S LEAVITIJ. B LEBERBTEIN, J. H. LEE, E. H. LEE, E. H.	7812080122* 7813010071 7810180121* 7810260184* 7811130350*	50-316 \$ 50-225 J 50-280 P 50-341 Q 50-329 Q	LEVIN, H. A. LEVIN, H. A. LEWALD, Q. H. LEWALD, Q. H. LEWALD, Q. H.	7812240024 7812270104 7811070001 7811070004+ 7812010057+	30-29 P 30-213 P 50-471 0 50-471 0 50-471 0	LIME, I. LIME, I. LIME, I LIME, I	7810200156 7810190235 7810270301 7810310374 7810240087	50-516 0 50-516 0 50-322 0 50-316 A 50-516 0
LEE, E. M. K. LEE, E. M. K. LEE, B. M. LEE, N. R. LEECH, P. H.	7811300254* 7812270156* 7812200308* 7812240148 7812130252	50-440 Q 50-341 Q 50-374 Q 50-458 A 50-592 A	LEWIS R.C. LEWIS R.C. LEWIS R.C. LEWIS R.C. LEWIS R.C.	7810240211# 7810240217# 7810230072* 7810130077* 7810230345*	50-250	LIKE, I. LIKE, I. LIKE, I. LIKE, I. LIKE, I.	7811200002 7811210110 7811200020 7811300373 7811390311	50-322 0 50-322 0 50-516 0 50-516 0

				LINOCIANE	ווטוווטא	HAPL	Λ
AUTHOR	ACCEBBION NUMBER	SUBJEC'		AUTHOR	ACCESSION NUMBER	BUBJEC1 CATEODR	
LIKE, I.	7612110012	50-322	٥	LONG, F. J.	7810310312#	50~369	G.
LIKE, I.	7812150019	50~516	e e	LONG, F. J.	7810310307#	50-369	ā
LIKE, I.	7812210471	50-322	0	LONG, F J.	7810230224#	50-338	ä
LIKE, I.	7812240322	50-322	G	LONG, F. J.	7810310138	50-261	ō
LIKE, I.	7812210411	50-322	G	LONG, F. J.	7810310128	30-324	ä

LONG, F. J.

LONG, F. J.

LONG, F. J.

LONG, F. J

LONG, F. J

LONG, F J

LDNO, F. J

LONG, F. J.

LDNG, F. J.

LONG, F. J.

LONG. F. J

LONG. F. J.

LONG, F. J

LONG, F. J

LONG. F. J

LONG, P. J.

LONG, F. J.

LONG, F. J

LONG, F. J

LONG, F J

LONG, F. J.

LONG, F. J.

LONG, F. J

LDNO, F. J.

LONG. F. J

LONG, F. J.

LONG, F. J.

LONG, F. J.

LONG, F. J.

LDNO, F. J

LONG, F. J.

LONG, LONG, F J

LONG, F. J.

LONG, F. J.

LONG, F. J

LONG, F. J.

LONG, F. J

LONG. F. J.

LONG, F. J.

LONG F. J.

LONG F. J.

LONG, F. J.

LONG. F. J

LONG, F. J.

LONG, F. J

I DNO. F. J.

LONG, F. J.

LONG, F. J.

LONG, F. J.

LONG F. J.

LONG, F. J.

LOWENSTEIN, R.

LOWENBERG, H

LOWERRE, R. W.

LUNDVALL.A.E

LUNDVALL, A. E.

LUNDVALL A. E

LUCO, J. E.

7810310128

7811010397

7810310115

7811090275

7810110287

7811080163

7811080174

7811080285

7811200140#

78112002104

7610110226

7810250231

7811070314#

781 | 100023*

7811130357*

7811130239#

78111302624

78111303784

7611130409

7810230049

7810240067

7811220093#

7B1020025B

7810230013

7811200021

7812050014#

7811220254

7611270011

7812120232

7811280008*

7811280390*

78120401B0

781 I 220003#

7811220059*

7811130228*

7812010104*

78120500704

7812050158

7812060224

7812060258

781 1030031

7812050053

7811100017

7812060334

7612070313

7811130256

7812060345 *

7812140151

7811130237

7811200127

7812140265*

7812140270+

7812180312

7812180308

7812180320

7612180340*

7812210344*

7811220110

7812210108

7811220087

7812270383

7812190238*

76120700974

7812040329#

7812130311+

7812140046#

7812050008

7812050063

7812280290#

7612200158*

7812120236

7812210333

7810230324

7811290014

7811010388#

7810250143

7810180073

7810230148

7812110072*

7812210149#

7810110247

90-324

50-324

50-338

50-390

50-325

50~395

50-327

50-261

50-280

50-280

50-241

30-34B

50-250

50-302

50-250

50-369

50-280

30-321

50-349

50-302

50-335

50-250

50-260

50-369

30-241

50-327

50~348

50-261

50-338

50-250

50-321

50-269

50-395

50-321

50-348

50-250

50-302

50-327

50-338

50-280

30~336

50-259

50-302

30-336

50-369

50-321

50-280

50-280

50-280

50-335

50-335

50-302

50-259

50-324 50-302

50-269

50-280

50-335

30-260

50-390

50-250

50-321

50-269

50-269

50-269

30-34B

50-302

50-321

30-13

50-250

50-344

50-437

50-499

50-275

50-317

50-318

50-317

Ğ

a

G G

3

a

a

a

a

Œ

a

œ

a

a

a

Q Q

æ

a

ø

0

a

ä

Ġ

G

G

a

đ

O

a

a

Ğ

G

Q

0

q

0

٥

ā

ā

ā

a

G

a

Q

n

a ā

a

G

a

a

a

а

Q

٥

٥

Ω

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT
.IKE, I. .IKE, I.	7812110012 7812150019	50-322 0 50-516 0	LONG, F. J. LONG, F. J.	7810310312* 7810310307*	50~369 50~369

50-249

50-237

50-249

50-237

50-249

50-344

50-249

50-249

50-409

50-409

50-409

50-409

50-409

50-409

50~409

50-409

50-409

50-409

50-409

50-409

50-409

50-463

50-522

50~346

50-346

90-346

50-34A

50-329

50-267

50-522

50-182

50~331

50-344

50-263

50-262

50-263

50-522

50-358

50~255

50-295 50-549

50-33£

50~331

30-331

50-331

50-331

50-331

50-331

50-333

50-331

80-331

50-331

50-466

50-466

20-571

50-280

50-2BO

50-259

50-259

50-250

50-261

50-250

50-324

50-335

50-335

50-33B

44E-08

30-369

50-861

50-369

30-321

50-335

50-348

50-259

50-302

50~280

Ø

Я

8

8

В

R

8

я

a

p

я

8

ρ

F

8

8

8

٥

a

G

G

o

a

O

ø

ā

a

τ

ρ

F

a

F

F

8

O

٥

Q

Œ

a

a

۸

a

٥

a

q

a

a

G

a

ā

a

78102401024

7810200097×

7811060162#

7811140199*

78111402274

7811280309#

7811280315

7812210245

7812180148*

7810100003

7811130204

7811170220

7811270109

7812040216

7812070307

2812080137

7812110165

7812110156

7812120124

7812140162

7812200216

7812290161

7811160001

7811070360

7B10310309#

7811210382*

78120701994

7812140140#

7811090156

7810230382

7810130097

78103101684

7811130010#

7611150055*

7812070078*

7812210054*

7812200109*

7812130227

7812040047

7812210043#

7812290025*

7812040045

7811920070#

7811280036

7811270202

7810230173

7810240112

7810310220

7811070121

7811170159

7811210354

7812030154

7812050132

7812110104

7812130136

7812270297

7810260088

7811200004

7812150057

78110104236

7811010414

7810310069*

7810310060

78102402084

78101102314

7810110256#

7810110295#

7810230059#

7810230068

7810130047*

7810300017#

7810230023#

7810230047#

7810130095#

7810230339*

7610130072*

7811010265

7810250116

7810250139

7810110284

LINDBERG, C

LINDRERG, C

LINDBERG, C

LINDBERG, C

LINDRERO, C

LINDBERG, C.

LINDBERG, C.

LINDBERG, C

LINDER, F. H

LINDER, F

LINDER, F

LINDER, F

LINDER, F.

LINDER, P

LINDER, F

LINDER, F.

LINDER, F

I INDER. E

LINDER, F.

LINDER, F

LINDER, F

LINENBERGER, Q.

LINENBERGER, O

LINGENFELTER, J

LINGENFELTER, J

LINGENFELTER, J.

LINGENFELTER, J

LIPINSKI, W. C

LITTLE, D. B

LITTLE, W. B

LITTLE, W. B

LITTLE, W. B.

LITTLE, U.S.

LITTLE, W. S

LITTLE, M. S.

LITTLE, D. 9

LITTLE, W. B

LITTLE, M. S

LITTLE, L. H.

LITTON. F

LIU.L.

LIU, L

LIU, L.

LIU, L.

LIU, L.

LIU.L.

LIU, L.

L TU. I

LIU, L.

LIU, L.

LIU, L.

LIU.L.

LIV. L

LOE, L.

LOE, L.

LONG F. J.

LONG, F. J.

LONG, F. J.

LONG, F. J.

LONG, F.J

LONG: F J

LONG, F. J.

LONG, F. J.

LONG, F. J.

LONG. F. J.

LDNG, F. J.

LONG, F. J.

LONG, F. J.

LONG, F. J.

LONG, F. J.

ONG, F. J.

LONG, F. J.

LONG, F. J.

LONG F. J.

LONG, F. J.

LONG, F. J.

LIDU.C P

LINDBLAD, H. J.

œ	LUNDVALL A E	7811150269#
O	LUNDVALL, A E	7812010295#
G	LUNDVALL, A E	7810230162
G	LUNDVALL, A E	7810260202
G .	LUNDVALL, A E	7811150155
Q.	LUNDVALL A E.	7811150189
	A LIMPURALE A C	20110000304

AUTHOR

LUNDVALL, A. E

LUNDVALL, A. E

LUTON, E.

LUTON, E.

LUTON, E

LUTON E.

LUTON, E

LUTON, E.

LUTON E.

LUTON, E.

LYDDN, J.M.

LYNCH. O. D.

LYNCH, D. D.

L YNCH, M. D.

LYNCH, M. D

LYNCH, M. D

I VNCH, M. D.

MACARTHUR, T. C.

MACCARY, R. R

MACCARY R. R

MACCARY.R. R

MACCARY R. R

MACCARY, R. R.

MACCARY, R. R

MACCARY, R. R

MACKENZIE, V

MACVITTIE. D K

MACVITTIE.D.K

MACVITTIE D. K

MACUITTIE. D K

MACVITTIE D

MADDEN, H J.

MADEDA: T. J. MADEDA: T. J.

MADEDA: T. J.

MADEDA, T. J.

MADGETT. J. P

MADGETT, J. P.

MADGETT, J. P.

MADGETT, J. P

MADGETT, J. P.

MADGETT.J.P

MADDETT, J. P

MADBEN, O. L.

HADSEN, O. L.

MADSEN, O I

MADSEN, Q L.

MATISEN, O. L.

HADSEN, C. L.

HADSEN, C. L.

MADBEN, Q. L.

MADBEN, O. L.

MADBEN, O. L.

MADBEN, O. L.

MADSEN. O. L.

MADBEN. O. L.

MADSEN, O. L.

MADBEN, Q. I.

MADBEN, O. L.

MADBEN, Q. L.

MADSEN, O. L.

MADBEN, O. L.

MADBEN, O. L.

MADREN, O. L.

HADBEN, Q. L.

HADBEN, C. L.

MADSEN, C. L.

MADSEN, Q. L.

MADBEN, Q. L.

MADSEN, Q. L.

MADDEN, W



ACCEBBION

NUMBER

7810230246

7810310271

8UDJE0

CATEGO

50-31B

50-317 50-317

50-317

50-317

50-317

50-317

50-317

20-317

90-317

90-317

50-317

90-317

50-317

90-317

50-275

50-70

50-70

50-70

50-70

50-70

50-295

50-295

30-471

90-295



7811090165#

7811210283#

78112102924

7811080177#

7812280309*

7B10240035#

7812050391#

2B11090044#

7811300117#

7810150142

7810120035

7810240123

7810240143

2810310066

7810310080

7811240233

7810130053#

7810130045

7810110304

2B10140132

7B10140072#

7810140133×

7810140089

7810180206

7810120012

7810120016#

7811030036#

7811030034

7811060051

7811060055#

2B11210114

7810110260

7810110296

7810110219

7810110224

7810230209

7811210480

7811170111

78111701144

7811280058

7811280062*

7812060324

78111701198

7811220133 7811220137 7812040047 7812040045
78120100304
19150100204
7811010308 7810250179
2811170361
7B11200010
7811220208
FOLIEEGEOD
7811270347 7812080010#
7811200157#
7B11200156*
7011200153*
7811200136*

7811010308	50-329
7810250199	50-329
7811170361	30~397
7B11200010	50-440
7011220208	50-440
7011270349	50-397
78120B0010b	50-580
7811200157 *	50-437
7811200156*	50-437
7011200153*	30-437
7811200136#	50-437
7811200441*	50-437
7811200442#	50-437
7811200205#	50-437
7811220094	50~592
7811090273#	30-220

30-
50- 50- 50- 50-
50~ 50~ 50~ 50~
30- 50- 30- 30-
50- 50-

50~4: 50~4: 50~4: 50~4: 50~5
20-5 20-5 20-5 20-5 20-5
50-3 50-3 50-3 50-8
50-2 50-4 50-4 50-4 50-4
50-4 50-4 50-3 50-3
50-2 50-3 50-3 50-3

)-43)-43)-43
0~43 0~43 0~43 0~43 0~59
0-55 0-55 0-55 0-55 0-55
0-33 0-29 0-31 0-31 0-87
0-25 0-40 0-40 0-40 0-40
0-40 0-40 0-40 0-31
0-24 0-29 0-3: 0-3:
10-51 10-51 10-51 10-51
10-2 10-3 10-3

0-440 0-440
0-397 0-280 0-437 0-437
0-437 0-437 0-437 0-437 0-592
10-550 10-550 10-550 10-550 10-550
10-333 10-293 10-31 5 10-31 5 10-87
30-255 30-409 30-409 30-409 30-409
50-409 50-409 50-409 50-313 50-313
90-267 50-298 50-313 50-298 50-313
50-265 50-276 50-276 50-276 50-265
50-298 50-298 50-313 50-267 50-313
90-285 90-366 50-276 50-126 50-313

⁵⁰ 90 50 90 ១០

50-125

20-126

50-285

50-295

50-146

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGURY	AUT HDR	ACCESSION NUMBER	SUBJECT	AUTHOR	ACCEBBION NUMBER	TOBLEUR
MADSEN, G. L	7611200325	50-298 G	MANRY, M	7810310165	50-321 5	MARTIN R D.	7811220099*	50-260 0
MADSEN, D L.	7812210159	50-369 0.	MANRY. M.	7810310117	50-321 5	MARTIN. J B	7811200219	50-201 P
MADSEN, Q. L	7612210149 > 7611060104	50-368 G 50-298 G	MANRY, M. MANRY, M	7810310151 7810310160	50-369 8	MARTIN.T J. MARTIN.R D	7810170133* 7811200024*	50-272 P 50-327 0
MADSEN. G. L. MADSEN. G. L.	7812130327*	50-313 G	MANRY, M.	7810310175	50-366 5	MARTIN, R. D.	7812120237*	50-250 0
MADSEN, O.L.	7812180348	50-29B 0	MANAY, M.	7811060150	50-366 E	MARTIN-K	7812130090	90-220 0
MADSEN.O.L. MADSEN.O.L	7811210128* 7812060348	50-313 0 50-285 0	MANRY, M. MANRY, M	7811140245 7811050131	50-366 6 50-321 5	MARTIN,T J. MARTIN,H G.	7811140274* 7812150214	50-311 0 50-245 0
MADSEN, G L	7812190053	30-313 0	MANRY, M	7811060135	50-321 B	MARTIN, R D	7812070315*	50-369 0
MADSEN, O. L.	7812190061>	50-313 9	MANRY, M	7811140156	50-321 8	MARTIN, W G	7812050286	50-97 0
MADSEN, Q. L. MADSEN, Q. L.	7811170289 7811120079	50-148 G 50-298 G	MANRY M. MANRY, M.	7811140209 7811140198	50-366 S 50-366 S	MARTIN.R D MARTIN.J A	7812140277* 7811220060*	50-335 G 50-549 T
MADSEN, O L	7811130313	50-313 G	MANRY. M	7811210246	50-366 9	MARTIN. J A	7811220065*	50-549 T
MADSEN, O.L.	7812180328 7812190187	50-267 0 50-267 0	MANRY, M. MANRY, M.	7812260154 7811160066	50-321 P 50-321 P	MARTIN.R. MARTIN.U.G.	7811130247 7812280300	50~364 A 50~293 Q
			MANRY, M.	7811160106	50-366 R	MARTIN, T. J	7812280215*	50-311 6
MADSEN, G. L KADSEN, G. L	7812270020* 7812270017	50-313 G 50-313 G	MANRY, M	7811210351	50-366 8	MARTIN R D.	7812210154*	50-335 @
MADSEN. G L	781127 0 123 781221 0 180	50-298 G 50-298 G	MANRY, M MANRY, M.	7811210399 7811210342	30-366 9 50-321 8	MARTIN, A. Q. MARTIN, R. D	7812270386* 7812070148*	50-370 0 50-321 0
MADSEN, O. L. MADSEN, O. L	7812210184*	50-298 G	MANRY, M	7811210238	50-364 8	MARTIN, R D	7812130317*	50-269 0
MADSEN, O. L	7812070002+	50~128 G	MANRY. M	7811220026	50-321 <u>8</u>	MARTIN, T. J.	7812070224	50-354 B
MADSEN, O L MADSEN, O L	7812050311 7812070001	50~149 0 50~128 0	MANRY. M MANRY. M	7811210361 781030397	50-321 8 50-321 8	MARTIN, W.E MARTIN, W.E	7812150056 7812130064	50~275 T 50-275 T
MADSEN, O L	7812060044	50-285 0	MANRY . M.	7812070033	50-321 &	MARTIN. W E	7812200344	50-275 1
MADSEN, Q. L.	7812060207	50-368 6	MANRY. M	7812070035	50-366 B	MARTIN, W. E	7812200338	90-275 f
MADSEN, Q. L. MADSEN, Q. L.	7812290239 7812060049	50~267 Q 50~298 G	MANRY M MANRY M.	7812070038 7811280217	50-366 B 50-366 B	MARTIN, W. E Martin, W. E.	7812220014 7812290002	50-275 T 50-275 T
MADSEN, O. L.	7812060278	50-2B5 G	HANRY - H.	7811280222	50-366 \$	MARTINIT. J.	7812280204*	50-477 0
MADSEN. D. L. Madsen. G. L.	7812180421 7812180424+	50-59 0 50-59 G	MANRY, M. MANRY, M.	7811280235 7811280288	50-321 8 50-346 8	MARTIN.W.E. Martin.W.E	7812290279 7812290280	50-275 ĭ 50-275 T
					50-321 8			
MADSEN. D. L. MADSEN. D. L.	7812130309 7812210214	50-313 G 50-313 G	MANRY.M.	7812180164 7812180162	50-366 8	MARTIN. W. E. MARTIN. W. E.	7812290282 7812290283	50-275 T 50-275 T
MADSEN, Q. L	7812210224	50-369 Q 50-293 B	MANRY, M.	7812180231 7812180201	50-366 8 50-366 8	MASSER.E. MASSER.E.	7811090189*	50-315 0 50-305 0
MAGUIRE, P. J. Mahan, R. R.	7811210341 7810300384	50-293 B 50-395 G	MANRY, M. MANRY, M.	7812180135	50-366 8	MASSE R E.	7812120231* 7812130045*	50-305 0 50-315 0
MAHAN, R. R	7810300387*	50-395 G	MANRY, M.	7812180162	50~366 B	MATERS. B R	7810120021	50-16 J
MAHAN, R. R.	7810190229	50-393 G	MANAY M.	7812180179	50~366 8 50~321 R	MATERS B. R	7810130146	50-341 A
Mahanir.r Makepeace.j.m	7810190163 7810110135#	50-395 Q 50-247 B	MANRY, M. MANRY, M.	7812150287 7812150334	50~366 R	MATERS B R. Mathib. C. J.	7811280231 7810310163*	50-341 A 50-293 8
MAKEPEACE, J M	7810160110+	50-247 6	MANRY M.	7812180178	50~346 B	MATHIB.C.J.	7811080156*	50-293 B
MAKEPEACE, J M.	78101601134	50-247 8	MANRY, M.	7812180165	50-321 8	MATHIB. C. J.	7811070168*	50-293 8
MAKEPEACE, J M MAKEPEACE, J M.	7810160141* 7810160165*	50-247 B 50-247 B	MANRY, M MANRY, M.	7812180220 7812180214	50~366 B 50~366 B	MATHIB.C.J. MATHIB.C.J	7811140212# 7811140188#	50-293 B 50-293 B
MAKEPEACE, J M.	7811070230+	50-247 8	MANRY . M.	7812270280	50-321 8	MATHIS.C J.	7811210345*	50~273 8
MAKEPEACE, J.	7811210344*	90-3 R	MANRY, M.	781 <i>927</i> 0295	50-321 8	MATHIB.C J	7812040176*	50-293 8
MAKEPEACE, J. M. MAKEPEACE, J. M.	7811280270 * 7811280263*	50-247 8 50-247 8	MANRY, M. MANRY, M.	7812270315 7812270325	50-321 B	MATHIB-C J. Mathib-C J.	7812050192+ 7812120141+	50~293 8 50~293 8
MAKEPEACE, J. M	7812190131*	50-247 8	MANRY, M	7812270266	50~366 B	MATHIB. C. J.	7812180172×	50~293 8
MAKEPEACE, J. M. MALMROS, M. H.	7812200208* 7811270115*	50-247 8 50-344 0	MANRY, M MANRY, M	7812270314 7812270319	50-366 B	MATTHENS, P. R. MATTIA, J. C.	7811060073# 7812130112#	50~556 Q 50~352 Q
MALMROS.M H	7812130324+	50-344 @	MANRY, M.	7812270326	50-366 8	MATTIMOE, J. J	7810100050	50~312 8
MALONEY O. P.	7811270171	50-315 P	MARCH, L. T.	7810240137#	50-488 H	MATTINGE, J. J.	7810100073	50~312 8
MALONEY Q P. MANRY M.	7812290192 7812260136+	50-319 P 50-321 P	MARKE, D. MARKE, D.	7811060077 7811130415	50-466 Q 50-466 Q	MATTIMOE J. J. MATTIMOE J. J.	7810100016 7810100061	50~312 B
MANRY, M.	7810170236	50-366 8	MARKOWSKI.R B.	7812010103#	50-309 Q	MATTIMOE. J	7811030149	50-312 B
MANRY - M.	7810170226	50-366 8	MARKOWSKI, R.	7811100148#	50-311 G	MATTIMOE J J	7811030133	50~312 B
MANRY, M. MANRY, M.	7810170233 7810170233	50-321 8 50-366 8	MARKOWSKI,R.S MARLEY,J.	7812020147* 7810160127*	50-334 Q 50-346 B	MATTIMOE J. J. MATTIMOE J. J.	7810130131 7810130178	50-312 8 50-312 8
MANRY, M.	7810170236	50-321 8	MARLEY, J	7812120173#	90- 34 6 9	MATTIMDE J. J.	7810170199	30-312 5
MANRY M.	7810170291	50-321 8	MARGUARDT, P. A.	7810200111	50-452 A	MATTIMOE, J. J.	7810120027	50-312 P
MANRY, M. MANRY, M.	7810180031 7810180112	30-366 S 50-321 S	HARRACH, D. HARRACK, D.	7811020244 7811300111	30-466 0 30-466 0	MATTIMOE, J. J. MATTIMOE, J. J.	7810230160 7810200164	50-312 P
MANRY, M.	7810170311	50-366 8	MARSHALL, W. H.	7811010014#	50-329 H	MATTIMOE, J. J	7810230099	50-312 F
MANRY, M MANRY, M	7810170329 7810180029	50-321 B 50-321 B	MARSHALL W. H MARSHALL W. H.	78110B0048 7811130192*	50-329 Q 50-329 G	MATTIMOE, J. J. MATTIMOE, J. J.	7810230277 7811130089	50-312 8 50-312 0
MANRY, M.	7810180116	50-366 8	MARSHALL W. H	7811100146	50-329 0	MATTIA, J. C.	7812190155*	
MANRY M.	7810180019	50-366 8	MARSHALL W. H.	7811210040	50-329 G	MATTIMOE, J. J	7811070201	50-483 Q 50-312 P
MANRY, M. MANRY, M.	7810170318 7810170322	50-366 B 50-364 B	MARSHALL W. H. MARSHALL W. H.	7811150039 7811300335	50-329 G 50-329 G	MATTIMOE, J. J. MATTIMOE, J. J.	7811140230 7811270096*	50-312 B
MANRY, M.	7810180037	50-366 8	MARTIN, R. D	7810110236*	50-261 G	MATTIMOE J. J.	7812120147	20-315 8
MANRY M.	7810180120	50-366 8	MARTIN- H. O.	7810190107*	50-57 G	MATTIMOE J. J.	7811170117	50-312 P
MANRY, M. MANRY, M.	7810170309 7810170312	<i>50-366 8</i> 50-366 8	MARTIN, H. O. Martin, H. O.	7810180215# 7810180178	<i>50-334 </i>	MATTIMOEJJ.J MATTIAJJ.C.	7611210319 7612290253*	50~312 P 50-485 Q
MANRY M. MANRY M.	7810180023	50-366 8	MARTIN, R. D.	7810130051#	50-366 G	MATTIMOE J J.	7811210261	50~312 F
	7810180001	50-366 \$	MARTIN, R. D.	7810230044×	50-369 0	MATTIMOE, J. J.	7811280209	50-312 P
MANRY, M. MANRY, M.	7810180003* 7810180010	50-366 8 50-321 8	MARTIN, W. Q. Martin, W. Q.	7811010093* 7811080172	50~277 G 50~333 G	MATTIMOE J. J. MATTIMOE J. J.	7812050116 7812050146	50-312 P 50-312 F
MANRY, M. MANRY, M.	7810180011*	50-321 B	MARTIN, W.G.	7811080236	50-271 G	MATTIMOE J. J.	7812080094	50-312 P
MANRY M.	7810180020 7810230206	50-366 8 50-366 8	MARTINAR.D. MARTINAT.J.	7811200214* 7810100020	50-280 0 50-354 B	MATTIMOE, J. J. MATTIMOE, J. J.	7812110170 7812130107	50-312 6 50-312 P
MANRY, M.	7810230175	50-321 B	MART IN T. J.	7810250262#	50~354 6	MATTIMOE, J. J.	7812140142	
MANRY, M.	7810230188	30-J44 B	MARTINIH G.	7810190104	30-57 Q	MATTIMOE, J. J.	7812180159	50-312 Q 50-312 F
MANRY M. MANRY M.	7810310146 7810310157	50-321 B 50-321 B	MARTIN, W. G. MARTIN, R. D.	7812050295* 7811130412*	50-97 G 50-302 G	MATTINOE J. J. MATTBON:R. J.	7812200159 7810300307#	50-312 P 50-556 Q
MANRY, M.	7810310205	30-366 B	MARTIN. W. G.	7811010085	50-277 G	MATTEON, R. J.	7812210323	50-556 G 50-327 A
•								

	ACCESSION	BUBJECT			ACCESSION	SUBJECT			ACCESSION	SUBJEC1
AUTHIR	REMUN	CATEGORY		AUTHOR	NUMBER	CATEGORY	٧	ROLTUA	NUMBER	CATEGOR
MATTBON:R J MATTBON:R J MATTBON:R J MAURA:F.A	781220152* 7812130200* 7812210173* 7810110220	50-263	0 P A 0	MCDURFIE, M A MCDUFFIE, M A MCDUFFIE, M A MCDUFFIE, M A	7811210046 7811140216 7810270123	50-416 50-400 50-400	A E A	MEAD, E MEAD, E MEANS, D. 8	7811020388* 7811020385 7811130128	50-549 50-549 50-522
MAXWELL O F	7811090003#	50-367	å	MCDUFFIE M A	7810300140 7811280226	90-400 50-400	A F	MECCA, J. E. MECCA, J. E.	7811080142 7811080153	50-522 50-522
HAXWELL.OF HAXWELL.OF MAY.E.L. HAY.E.L. HAY.E.L	7811300254+ 7812280244+ 7810180017+ 7811280332+ 7811280323+	50~440 50~367 50~29 50~29 50~29	G G S S S	MCDUFFIE M.A MCEHEN.JE MCFARLAND.CR MCFARLAND.CR MCFARLAND.CR	7812130383 7812210210+ 7811210088+ 7812130005+ 7812210064+	50-400 50-272 50-339 50-327 50-413	0 0 0	MEHAFFEY.R. MEIEROTTO.L E. MELNICOFF.M A MELNICOFF.M A MENDE.R.Q.	7812290228* 7810240142 7811240178* 7812210213* 7812140152*	50-285 50-582 50-304 50-295 50-251
MAY, E. L. HAYER, L. D. MAYER, L. D	7812010224 7812060318 7812080138+	50-29 50-263 50-306	8 P P	MCGARRY, J. M MCGARRY, J. M MCGARRY, J. M	7810120020 7810140127 7810140030	50-369 50-369 50-488	0	MENGER, W M. MENNING, J. E MENNING, J. E	7812210029× 7812060340+ 7811150055+	50-498 50-331 50-346
MAYER.L.O. MAYER.L.O MAYER.L.O	7810180034 7810180012 7810110180	50-306 50-262 50-263	5 5	MCGARRY, J. M. MCGARRY, J. M. MCGARRY, J. M.	7810140139 7810230389	50-488 50-369	0	MENNING.J.E. MENNING.J.E	7811290336* 7812210043* 7814310200*	50-266 50-358 50-317
MAYER.L.D MAYER.L.D MAYER.L.D MAYER.L.D	7810120029 7810120030 7810160122 7810170099	50-263 50-263 50-563	R ff F P	MCGARRY, J. M MCGARRY, J. M MCGARRY, J. M MCGARRY, J. M	7810200132 7811130034 7811240063 7811220231 7811220272	50-369 50-369 50-468 50-468 50-369	T 0 0 0 0	MERNICKI M. J MERRILL.D.N. MERRILL.D.N MERSON.B.D. MERSON.B.D.	7810310189+ 7811070140+ 7810230178 7811240215	50-443 50-443 50-317 50-317
MAYER.L.O MAYER.L.O MAYER.L.O MAYER.L.O MAYER.L.O	7810170220 7810180021 7810250076 7810200078 78102000191	50-282 50-366 50-263 50-263 50-263	P B P B	MCGAUGHY, R. W MCGAUGHY, R. W MCGAUGHY, D. P MCGAUGHY, J. P MCGAUGHY, J. P.	7812130112+ 7810250261+ 7812120026+ 7811150097 7811160073	50-352 50-354 50-322 50-416 50-416	0 0 0 0	MERBON, B.D. MERBON, B.D. MERBON, B.D. MEYER, B.A. MEYER, B.A.	7811240217+ 7812220076 7812220077+ 7812110147+ 7812210228+	50-317 50-317 50-317 50-295 50-295
MAYER.L.O. MAYER.L.O MAYER.L.O	7810300237 7811240124 7811070247	50-263 50-263	P 9 B	HCGAUGHY, J. P. HCGAUGHY, R. W HCGAUGHY, R.	7812060400 7812290238= 7812290253=	50-416 50-387 50-485	6 0	MICHULKA C. L. MICHULKA C. L. MICHULKA C. L.	7810310372 7811170006 7812210368	90~466 30~466 30~466
MAYER, L.O. MAYER, L.O.	7811150115 7811140194 7811140143	50-262 50-263 50-262	P F	MCGAUGHY, J. P. MCGAUGHY, J. P.	7812120098 7812120098	50-416 50-416	8	MIDURA: H. J. MIDURA: H. J.	7810160084 7810180092	50-272 50-272
MAYER.L D MAYER.L D MAYER.L.D MAYER.L.D MAYER.L.D	7811140115 7811140116 78111160116 7811210334 7811200234	20-593 20-593 20-593 20-585	R A P 8	MCGAUGHY, J. P MCGAUGHY, J. P MCGAUGHY, J. P MCGAUGHY, J. P MCGUTRE, P. J.	7812290133 7812140133 7612290260 7612290256 7610180130	50-416 50-416 50-416 50-416 50-293	A G G R	MIDURA, H.J. MIDURA, H.J. MIDURA, H.J. MIDURA, H.J. MIDURA, H.J.	7810180128 7810180144 7810310137 7811130266 7810310180	50-272 50-272 50-272 50-272 50-272
MAYER, L.O MAYER, L.O. MAYER, L.O. MAYER, L.O MAYER, L.O.	7811280279 7812070221 7812080135 7812110118 7812110136	50-263 50-263 50-263 50-263 50-263	P P P R	MCOUIRE,P. J. MCOUIRE,P. J. MCOUIRE,P. J. MCOUIRE,P. J. MCOUIRE,P. J.	7810310158 7811210263 7812110251+ 7811080152 7811090161	50-293 50-293 50-324 50-293 50-293	8 R G S S	MIDURA, H.J. MIDURA, H.J. MIDURA, H.J. MIDURA, H.J. MIDURA, H.J.	7811130263 7811170181 7811280460 7811160074 78111610323	50-272 50-272 50-272 50-272 50-272
MAYER.L.O MAYER.L.O. MAYER.L.O. MAYER.L.O MAYER.L.O.	7812120091 7812140143 7812140159 7812200283 7812200211	50-262 50-263 50-263 50-263 50-263	R P 8 8	MCGUIRE,P. J. MCGUIRE,P. J. MCGUIRE,P. J. MCGUIRE,P. J. MCGUIRE,P. J. MCGUIRE,P. J.	7811140207 7811140183 7811280333 7812040173 7812050185	50-293 50-293 50-293 50-293 50-293	\$ \$ \$ \$	MIBURA, H. J. MIBURA, H. J. MIBURA, H. J. MIERNICKI, M. J. MIERNICKI, M. J.	7811210343 7812050229 7812150242 7810270240* 7811010116*	50-272 50-272 50-272 50-317 50-317
MAYER.L.O. MAYER.L O. MAYER.L.O. MAYER.L.O. MAYER.L.O.	7812260256 7812260207 7812260222 7812270232 7812270241	50-243 50-282 50-304 50-243 50-243	8 8 8	MCOUTRE.P. J MCOUTRE.P. J MCOUTRE.P. J. MCOURREN. H. J. MCOURREN. H. J.	7812200183 7812120135 7812180168 7810170012 7810170015*	50-273 50-273 50-273 50-349 50-549	R 6 6 0	MIERNICKI, M. J. MIERNICKI, M. J. MIERNICKI, M. J. MIERNICKI, M. J. MIERNICKI, M. J.	7811130214* 7811210409* 7812130187* 7812130174* 7812260248*	50-310 50-317 50-310 50-317 30-310
MAYER L. O MAYNARD C. J MAYNARD R. MAYNARD R. MAZZOLA C. A	7812270246 7810160197* 7812130191 7812130202* 7812030354*	50-263 50-327 50-341 50-341 50-547	8 G O T	MCGURREN, H. J. MCGURREN, H. J. MCGURREN, H. J. MCGURREN, H. J. MCGURREN, H. J.	7810170018# 7810170021# 7810170024# 7810240222 7811170027	50-549 50-549 50-549 50-549 50-549	0 0 0 F	MILHOLLIN, Q. L. MILHOLLIN, Q. L. MILHOLLIN, Q. L. MILHOLLIN, Q. L. MILHOLLIN, Q. L.	7810230322 7811010063 7811040259 7811160021 7811200003	50-272 50-237 50-237 50-237 50-237
MCALLIBTER, R. J. HCBREARTY, R. A. MCBREARTY, R. A MCBREARTY, R. A HCGABE, E. G.	78102000504 7811140280+ 7812280319* 7812270457* 7811300363*	50-334 50-311 50-318 50-333 50-184	P G G	MCGURREN H. J. MCGURREN H. J. MCGURREN H. J. MCGURREN H. J. MCGURREN H. J.	7811130234 7811150113 7812050059 7812050370 7812050372*	50-341 50-341 50-341 50-341 50-341	0 0 0	MILHOLL IN, Q, L. MILHOLL IN, Q, B. MILLER, R. N MILLEN, C. N MILLER, Q, P.	7812110284 7812270133 7810300338* 7810110264* 7811130145	50-237 50-237 50-201 50-267 50-289
MCCABE, E. C. MCCABE, E. C. MCCABE, E. C. MCCABE, E. C. MCCAFFREY, B. R.	7810250227* 7811070058* 7810140082* 7812110314* 7810200071	50-219 50-277 50-293 50-245 50-322	K G G	MCOURREN, H. J. MCOURREN, H. J. MCHENRY, T. J. MCHENRY, T. J. MCHENRY, T. J. MCHENRY, T. J.	7812050090 7812050259 7811080289* 7811220256* 7812150063*	50-320 50-498 50-261 50-261 50-261	G G G	MILLER, L.E. MILLER, M.I. MILLER, W.O. MILLER, M.E. MILLEN, G.K.	7810230092* 7810110309 7810110030 7810200135 7810120063	50-70 50-32 7 50-234 50-344 50-267
MCCANN, W. J. MCCAUGHAN, D. M. MCCAUGHAN, D. M. MCCLAIN, C. M. MCCLAIN, C. M.	7810110129* 781107035* 7811070354 7810230261* 7811210241*	50-334 50-510 50-498 50-219 50-219	B G R R	McHenry, T. J. McHedrde, D. W McKeown, L. McKibben, J. C. McKibben, J. C.	7812200161* 7810130227 7811080245* 7811060076 7812290080	50-13 50-170 50-271 50-186 50-186	G G B P	MILLEN, C.K. MILLER, L.K. MILLER, W.O. MILLER, W.O. MILLER, W.O.	7810120064* 7810160090* 7810120104 7810140112 7810230157	30-267 50-272 50-335 50-237 50-285
MCCLAIN.C. M MCCOLLUM K. A MCCOLLOM K. A MCCOLLOM K. A MCCOLLOM K. A.	7812200182* 781102037* 7811100054 7811100050 7811130305	50~219 50~344 50~344 50~344 50~344	R T T T	MCMINLEY, J. C. MCLANE, F. E. MCMANUS, C. K. MCMANUB, C. K MCNAMARA, A. E.	7811010384* 7810170259* 7810230375 7811220178* 7810170215*	50-275 50-537 50-206 50-327 50-244	0 A A 9 R	MILLER, D. E. MILLER, M. E. MILLER, W. O. MILLER, W. O. MILLER, M. E.	7811170319* 7811070025 7810230159 7810240020 7810310366	50-6 50-344 50-289 50-219 50-344
MCCOLLOM, K. A. MCCOLLOM, K. A MCCOLLOM, K. A MCCOLLOM, K. A. MCCOLLOM, K. A	7811100058 7811100024 7811100111 7811100019 7811130380	50-344 50-344 50-344 50-344 50-344	† † † †	MCNATT.T. MCNUTT.J.R. MCHORTER.R.J. MCHORTER.R.J. MCHORTER.R.J.	7811140043* 7811240166 7810130157 7810160128 7810230201	50-311 50-327 50-380 50-380 50-380	G A A E E	MILLER, M. I. MILLER, M. E. MILLER, M. E. MILLER, W. O. MILLER, W. O.	7810300311 7810260203 7811010153 7810260076 7810300003	50-329 50-498 50-445 50-313 50-250
HCCOLLOM K. A. MCCOLLOM K. A. MCCORKLE, B. A MCCORKLE, B. A. MCCORKLE, B. A.	7812280003 7812280004 7811130129 7812040300 7812040303	50~344 50~344 50~466 50~466 50~466	T T G G	HCHHORTER, R. J. HCHHORTER, R. J. HCHHORTER, R. J. MCHHORTER, R. J. MCHHORTER, R. J.	7610250115 7611140164 7611150126 7612050196 7612270204	50-580 50-580 50-580 50-580 50-580	A B A	MILLER, W.O. MILLER, M.E. MILLER, W.O. MILLER, W.O. MILLER, M.E.	7810300290 7811020379 7811080078 7810300378 7811100054	50-339 50-344 50-286 50-285 50-344

AUTFOR	ACCESSION NUMBER	SUBJECT Category	AUTHOR	ACCESSION NUMBER	SUBJECT CATEDORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODR
MILLER, M E MILLER, M E MILLER, N O MILLER, L F	7811100050 7811130305 7811130305 7811150154 78112080238+	50-344 T 50-344 T 50-344 T 50-220 P 50-326 G	MILLER, M.E. MILLER, M.I. MILLER, J.E. MILLER, G. K. MILLEN, C. K. MILLEN, C. K.	7812140221 7812280350 7812150258 7812220062 7812220069*	50-445 M 50-329 0 50-39 P 50-267 P 50-267 F	MOON, C. H. MOON, C. H. MOON, C. H. MOON, C. H. MOON, C. H.	7810230163 7810300241 7811170356 7811130236 78111270297	50-443 50-466 50-466 50-443 50-466
MILLER, M. I	7811150080	50-329 G	Miller, L K	7812150244+	50-272 R	MOORE, R. N.	7811290286	50-597
MILLER, M. E	7811100024	50-344 T	Miller, W C	7812150228	50-207 P	MOORE, D. E	7811130007*	50-250
MILLER, M. E	7811100111	50-344 T	Miller, M E	7812280003	50-344 T	MOORE, J.	7810230101	50-361
MILLER, M. E	7811100019	50-344 T	Miller, M E	7812280004	50-344 T	MOORE, H. Q.	7811030104*	50-390
MILLER, M. E	7811130380	50-344 T	Miller, J	7812220079	50-39 F	MOORE, Q. M.	7810200047	50-334
MILLER, W D MILLER, M E MILLER, D E MILLER, M E MILLER, L K	7811150016 7811210458 7812120226* 7811210235 7811160075*	30-333 P 50-344 G 50-331 G 50-445 M 50-272 R	MILLBAP, W. J. MILLBAP, W. J. MILLBAP, W. J. MILLB, L. M. MILLB, W. R.	7810120004* 7811010191* 7810300385* 7810170197 7810270001	50-259 0 50-338 9 50-369 0 50-327 K 50-322 A	MOORE, V. A. MOORE, V. A. MOORE, Q. H. MOORE, J. B. MOORE, V. A.	7810240228* 7811060056 7811030169 7811140177 7811170135	50-368 50-445 50-334 50-206 50-463
MILLER, L K	7812120151	50-272 R	Mìlle, M.	7811030101	50-390 P	MOORE, J. B.	7812210078* 7812040242 7812140257* 7812060162 7812270052*	50-361
MILLER, W G	7811200361	50-346 P	Mìlle, L.M.	7811070109	50-438 K	MOORE, V. A.		50-463
MILLER, W O	7811240087	50-285 P	Mìlle, L.M.	7811150120	50-390 H	MOORE, D. E.		50-406
MILLER, M I	7812040235	50-556 G	Mìlle, L.M.	7811170215	50-259 P	MOORE, Q. W		50-334
MILLER, M E	7811220018	50-568 G	Mìlle, L.M.	7811210303	50-327 A	MOORE, R.		50-320
MILLER, HO	7811240035	50-368 P	MILLB, L.M.	7811300198	50-327 K	MOORE, V. A.	7812120110*	50-518
MILLER, HO	7811240041	50-334 P	MILLB, L.M.	781219098	50-390 K	MOORE, V. A.	7812120118*	50-518
MILLER, H	7812290048+	50-370 G	MINER, S.	7812010093	50-387 A	MOORE, V. A.	7812120124*	50-518
MILLER, LP	7812130314+	50-273 G	MINER, B.	7812060133	50-387 A	MOORE, V. A.	7812120128*	50-518
MILLER, JR.	7812130071	50-10 P	MINER, S.	7812060197	50-387 F	MOORE, J. B.	7812210263*	50-361
NILLER, J.R.	7812150088	50-3 P	MINNICH, L.E.	7811020246	50-29 P	MOORE, J. B.	7812210388*	50-204
MILLER, J.R.	7812150092	50-29 P	MITCHELL D.G.	7810100099*	50-289 B	MOORE, J. B.	7812130177	50-361
MILLER, J.R.	7812150097	50-245 P	MITCHELL D.G.	7811210186*	50-289 R	MOORE, D. E.	7812210287*	50-274
MILLER, J.R.	7812150106	50-317 P	MITCHELL D.G.	7812190170*	50-289 R	MOORE, V. A.	7812210102*	50-324
MILLER, J.R.	7812150109	50-289 P	MITTL: R.L.	7810130134	50-311 A	MOORE, V. A	7812210104*	50-324
MILLER JR.	7812150113	50-309 P	HITTL:R.L	7810170132	50-272 P	Moreau, W. N.	7810120068	50-219
MILLER JR.	7812150116	50-335 P	HITTL:R.L.	7810240149	50-311 A	Moreau, W. N.	7810240132	50-219
MILLER JR.	7812150118	50-313 P	HITTL:R.L.	7810250069	50-311 A	Moreau, W. N.	7811060092	50-320
MILLER JR	7812150120	50-302 P	HITTL:R.L.	7810250063	50-311 F	Morgenstern, L.	7810300257	50-496
MILLER JR	7812150123	50-269 P	HITTL:R.L.	7811030119	50-311 K	Moriarty, J. M.	7811090134*	50-423
MILLER: J.R.	7812150124	50-312 P	MITTL+R.L.	7811080102	50-311 A	MORIARTY J M.	7811090135*	50-423
MILLER: J.R.	7812150130	50-277 P	MITTL+R.L.	7811080227	50-311 A	MORIARTY J M.	7811090136*	50-423
MILLER: J.R.	7812150132	50-220 P	MITTL+R.L.	7811090084	50-311 A	MORRIL P. J.	7811130231*	50-344
MILLER: J.R.	7812150134	50-133 P	MITTL+R.L.	7811200152	50-311 A	MORRISSEY J. C.	7810240113*	50-133
MILLER: J.R.	7812150135	50-263 P	MITTL+R.L.	7811240141	50-311 A	MORRISSEY J. C.	7810300350	50-275
MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R. MILLER, J.R.	7812150139	50-293 P	MITTL+R.L.	7811240225	50-311 A	MORRILL.P. J.	7812070246*	50-361
	7812150141	50-334 P	MITTL+R.L.	7812200072	50-311 A	MORRILL.P. J.	7812070045*	50-106
	7812150145	50-315 P	MITTL+R.L.	7812270248	50-477 A	MORRILL.P. J.	7812270456*	50-133
	7812150147	50-348 P	MITTL+R.L.	7812280200*	50-477 0	MORRILL.P. J.	7812280358*	50-344
	7812150148	50-259 P	MITTL+R.L.	7812220143	50-311 A	MORRIBSEY, J. C.	7812140085	50-275
MILLER, J.R.	7612150157	50-324 P	MITTNESS, L. T.	7812130087*	50~502 0	MORRILL, P. J.	7812270436*	50-243
MILLER, J.R.	7612150159	50-298 P	MITTNESS, L. T.	7811200040	50~484 0	MORBE, A. K.	7810110042	50-409
MILLER, J.R.	7612150161	50-331 P	MJERNICKI, M. J.	7810110174*	50~317 8	MORELEY, N. C.	7810270246*	50-329
MILLER, J.R.	7612150164	50-321 P	MLYNCZAK, M. M.	7810300116	50~305 F	MORELEY, N. C.	7810300006	50-316
MILLER, J.R.	7612150167	50-271 P	MLYNCZAK, M. M.	7811010204	50~315 P	MONRY, W. R.	7810270104	50-163
MILLER, J.R.	78: 2:50:73	50-155 P	MLYNC ZAH, H. M.	761 1080339	90-305 P	MOURY, M. R.	7810270107#	50-143
MILLER, J.R.	78: 2:50:76	50-244 P	MLYNC ZAH, M. M.	761 1200373	50-305 P	MOURY, M. R.	7812190145	50-89
MILLER, J.R.	78: 2:50:81	50-409 P	MLYNC ZAH, H. M.	761 2010365	50-315 P	MULKEY, M.	7810230168	50-443
MILLER, J.R.	78: 2:50:93	50-219 P	MODENOS, L.	781 2060035*	50-395 B	MULKEY, M. E.	7812280262	50-247
MILLER, J.R.	78: 2:50:97	50-206 P	MODENOS, L.	781 2060362*	50-389 G	MULLER, D. R.	7811200162#	50-437
MILLER, J.A.	7812150198	30-303 P	MOELLER, D.	7811100031	30-280 7	MUNITO, B.	7810140123*	50-344
MILLER, J.R.	7812150203	50-266 P	MOFFATT, D. W.	7811240188	50-329 A	MUNITZING, L. M.	7811200436*	50-437
MILLER, J.R.	7812150205	30-280 P	MOHR, T.	7810170216*	50-10 B	MUNITZING, L. M.	781120086*	50-437
MILLER, J.R.	7812150209	50-344 P	MOLLERUB, F. J.	7812270172	30-447 A	MUNITZING, L. M.	7811200279*	50-437
MILLER, J.R.	7812150212	50-272 P	MONT GOMERY, C. R.	7812010127	50-146 J	MURHPY, C. E.	7812130289*	50-491
MILLER, J.R.	7812180021	50-295 P	MONTI, W.A. MONTI, W.A. MONTI, W.A. MONTI, W.A. MONTI, W.A. HONTI, W.A.	7810240108	50-3 P	MURPHY, C. E.	7810110190	50-438
MILLER, J.R.	7812180028	50-333 P		7811170160	50-3 P	MURPHY, C. E.	7810140075	50-390
MILLER, J.R.	7812180033	50-261 P		7812010206	50-3 R	MURPHY, C. E.	7811030084*	50-438
MILLER, J.R.	7812180035	50-255 P		7812040229	50-247 S	MURPHY, C. E.	7811030089*	50-438
MILLER, J.R.	7812180038	50-250 P		7812180152	50-3 R	MURPHY, C. E.	7810120087	50-339
MILLER, J. R. MILLER, J. R. MILLER, J. R. MILLER, M. I. MILLER, C. K.	7812180039 7812180044 7812180050 7812050347 7811240226	50-213 P 50-254 P 50-282 P 50-556 G 50-267 E	MOODY, D. E.	7811020175* 7811150095* 7810170150 7810170192 7810170176	50-271 G 50-309 G 50-309 R 50-271 R 50-29 R	MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E.	7810110298 7810230236 7810240204 7810250074 7811080213*	50-566 50-553 50-370 50-424 50-369
MILLER, M E. MILLER, W Q. MILLER, R B. MILLER, M I. MILLER, M I.	7812040183	50-266 G	MOODY, D. E.	7810180137	50-309 P	MURPHY, C. E.	7811080215*	50-369
	7811270260	50-244 P	MOODY, D. E.	7810200090	50-271 F	MURPHY, C. E.	7811080314*	50-369
	7812060166	50-254 P	MOODY, D. E.	7810200031	30-29 F	MURPHY, C. E.	7810130098*	50-413
	7812140087	50-329 G	MOODY, D. E.	7812010093%	50-309 G	MURPHY, C. E.	7811080154*	50-395
	7812140362	50-329 G	MOODY, D. E.	7810270077	50-309 P	MURPHY, C. E.	7811080294*	50-438
MILLER, N. O.	7812040334 7812070278 7812110248 7812080132 7812080212	50-250 P 50-335 P 50-289 H 50-260 P 50-289 H	MODDY, D. E.	7811140112 7811140125 7811140120 7812050210 7812150355	50-309 R 50-271 R 50-29 R 50-29 F 50-309 R	MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E. MURPHY, C. E.	7811080296* 7810310081 7810280221* 7810230217 7811030047*	80-369 50-339 50-413 50-424
MILLER, N. D. MILLER, N. E. MILLER, N. D. MILLEN, C. K. MILLER, M. E.	7812110245	50-259 P	MOODY, D. E.	7812150290	50-271 R	MURPHY, C. E.	7811090266	50-332
	7812270144	50-344 Q	MOODY, D. E.	7812150286	50-29 R	MURPHY, C. E.	7811130095	50-327
	7812140343	50-255 P	MOODY, D. E.	7812190087	50-29 F	MURPHY, C. E.	78120501404	50-327
	7812130164	50-267 P	MOODY, D. E.	7812270276	50-271 P	MURPHY, C. E.	7811130113	50-438
	7812130003	50-445 N	MOON, B. T.	7810310116+	50-338 Q	MURPHY, P. M.	7810190216	50-556

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	γ 	AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	•	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
MURPHY, C. E.	7611090235*	50-395	0	HURRAY, R.	7811240191•	50-234	9	NEWMAN, J. R	7812120048	50-466 G
MURPHY, C. E. MURPHY, C. E.	7811140090 7811150064	50-51 <i>0</i> 50-395	G G	MURRAY, T. D. MURRAY, T. D.	7811090131		8	NEUMAN, J.R.	7812040274	50-466 G
MURPHY, C. E.	7811020355#	50-364	9	MURRAY, B.	7810310194 7812130336+		8	NEUMAN, J. R.	7812040329 7812040333	50-466 @ 50-466 @
MURPHY, C. E.	7811210083	50-339	o.	MURRAY, T. D.	7811030157		8	NEWHAN, J R.	7812040343	50-466 Q
MURPHY, C.E.	7811200029	50-324	o .	MURRAY, T. D.	7811070184	50-346	9	NEHMAN, J.R.	7812040350	50-466 G
MURPHY, C. E.	7811200182	50-31B	œ.	HURRAY, T. D.	7811070264	50-346	8	NEWHAN, J. R.	7812040367	50-498 O
MURPHY, P. M. MURPHY, C. E.	7810260199 7812040059#	50-556 50-390	0	HURRAY, T. D. MURRAY, T. D.	7811070273 7811090178		8	NEHMANJUR. NEWMARKIN M	7812030037	50-466 G
MURPHY, P. M.	7811010433	50-556	ō	MURRAY, B.	7812190193+		9	NEWMAN, J. R.	7812040321 7812110236	50-275 G 50-466 G
MURPHY, C. E.	7812060029#	50~395	G							
MURPHY, C. E.	7811240027#	50-250	o o	MURRAY, T. D. MURRAY, T. D.	7811140135 7811210347	50-346 50-346	R EL	NEWMAN, J. R. NEWMAN, J. R.	7812040024 7812070058	50-466 G 50-466 G
MURPHY, C.E.	7811300334	50~390	0	MURRAY, T. D.	7811210372	50-346	9	NEWMAN, J. R.	7812120224	50-465 Q
MURPHY, C.E. MURPHY, C.E.	7812010038 7811240065*	50-566 50-424	0	MURRAY, T. D. MURRAY, T. D.	7811200209 7811280198	50-346 50-346	8 8	NEWMAN, J. R. NEWMAN, J. R.	7812040331 7812050046	50-466 G 50-466 G
					7011200176	20-346		NGWI IPHOTO II.	7515030045	J0-400 G
MURPHY, C. E. MURPHY, C. E.	7811290321 7811220282*	50-566 50-399	a a	MURRAY, T. D.	7812010207	50-346	8	NEWMAN, J.R. NEWMAN, J.R.	781 1130020	30-466 G
MURPHY, C. E.	7611030057	50-43B	ā	MURRAY, T. D. MURRAY, T. D.	7812050157 7812050204	50-346 50-346	6 6	NEWHAN, J. R.	7812130024 7812130219	50-466 Q 50-466 Q
MURPHY, C. E. MURPHY, C. E.	7812030303 7812050169	50-32 <i>1</i> 50-296	9	HURRAY, T. D.	7812050217	50-346	8	NEWMAN, J. R.	7812290308	50-582 G
HOMPHY C. C.	7612030107	30-276	a	MURRAY, T. D.	7812150278	50-320	8	NEWTON, R. A.	7811150262	50-266 G
MURPHY, C. E.	7811300167	50-400	0	MURRAY, B.	7812290244*	50-247	œ	NEWTON: R. A.	7811240119	30-266 G
MURPHY, C. E. MURPHY, P. M.	7812070024* 7811130060	50-364 50-556	G G	HURRAY+ T. D HURRAY+ T. D.	7812070194 7812070198	50-346 50-346	9 9	NEWTON, R. A. NICHOLAS, H	7812030049 7811080292*	50-266 G 50-311 G
MURPHY, P. M.	7811140047	50-556	0	MURRAY, T. D.	7812120165	50-346	9	NICHOLAS, H	7811100102*	50-311 0
MURPHY, C. E.	7811080147	50-395	O .	MURRAY, T. D.	7812120140	50-346	8	NICHOLAS, H.	7811100164*	20-311 G
MURPHY, C. E.	7611080205	50-369	Q	MURRAY, T. D.	7812120172	50-346	8	NICHOLB, T. C.	7810190239#	50-395 G
MURPHY, C. E.	7611080250	50-369	O .	MURRAY: T. D.	7812140137	50-346	В	NICHOLAS, H.	7811140043*	50-311 G
MURPHY.C.E. MURPHY.C.E.	7811080251 7812070016	50-43B 50-51B	Q Q	MURRAY, T. D. MURRAY, T. D.	7612150296 7812150115	50-346 50-346	R 8	NICHOLABIH. NICHOLABIH.	7612060355* 7812290044*	50-311 G
MURPHY, E.	7811210312	50-275	H	MURRAY, T. D. MURRAY, T. D.	7812290200	50-346	8	NICHOLAS T. C.	7812270044*	50-311 G 50-375 J
MUDDLAY A M										
MURPHY, P. M. MURPHY, C. E.	7611210107 7612060268	50-556 50-327	9	MYGATT.S.G. MYRABO.A.L.	7810110109 7810120032*	50-263 50-368	A R	NIELBEN.D. NIELBEN.D.	7812210235* 7812210209*	50~275 A 50~275 A
MURPHY, C. E.	7812060287	50~327	a	MYRABO, A L.	7811160117*	50-263	R	NIELBEN, D	7812210225*	50-275 A
MURPHY, C. E. MURPHY, C. E.	7812130001 7812070319*	50-32 <i>7</i> 50-269	G G	MYRABO, A. L. NAIDU, K. R.	7812110140# 7811140269#	50-243 50-341	R O	NIELSEN, E. S NILSON, R.	7812260194 = 781113017 <i>9</i>	50-287 B 50-564 J
pont mira. c.	7018070017			MALDOIN.G.	76111402514	50 541	•			
MURPHY, C. E.	7812080046	50-51 <i>0</i> 50-395	G G	NAIDU.K.R.	7812040163*	50-546	9	NIX,R,T. NIX,R.T.	7810180033* 7810180114*	50-366 B
MURPHY, C. E. MURPHY, C. E.	7812120033* 7812150192	50-375	9	NAPUDA, Q. NAPUDA, Q.	7810260028* 7811090017*	50-220 50-247	G G	NIX. R. T.	7810170315*	50-366 8
MURPHY, P. M.	7812050281	50-556	0	NAPUDA, Q.	7811100148*	50-311	g	NIX.R.T.	7810180014#	50-321 8
MURPHY, C. E.	7811150058	50-395	a	NAPUDA: Q	7612290053*	50-271	Ġ	NIX. R. T.	7610170313*	50-366 8
MURPHY, C. E.	7812150030	60-327	a	NARBUT, P. P.	7811270058*	50-312	g	NIX.R.T.	78101703144	50-366 8
MURPHY, T. D.	7811220084*	50-549	T	NARROW, L	7811080200*	50-363	g	NIX. R. T.	7810310214* 7810310154*	50-366 B 50-366 B
MURPHY, C. E. MURPHY, C. E.	7812180349 7812040170*	50~416 50~395	G G	NARROW, L. NARROW, L.	7810270392* 7811300387*	50-363 50-410	G G	NIX, R. T. NIX, R. T.	7810310154*	50-321 \$
MURPHY, P. M.	7812040235	50~556	ē	NABH, E. J.	7812270033*	50-320	0	NIX. R. T.	7810310181*	50-366 8
MUDDLIN C C	7811290322*	50-389	Q	NASHI E. J.	7811030174	50-320	Р	NIX. R. T.	7811060153#	50-366 8
MURPHY, C. E. MURPHY, C. E.	7812270364*	50-369	œ.	NAUGHTON, W. F.	7810120080	50-237	F	NIX.R.T.	7811140162*	50-321 8
MURPHY, C. E.	7612290109	30-553	Q.	NAUGHTON, H. F.	7810100025	50-295	P P	NIX.R.T. NIX.R.T.	7811140211* 7811140204*	30-366 B
MURPHY, C. E. MURPHY, C. E.	7812180336* 7812110309*	50~400 50~364	Q. Q	NAUGHTON, W. F. NAUGHTON, W. F.	7810180060 7810200113	50-295 50-295	P	NÍX, R. T.	7811210253*	50-366 8
								MIV O T	7811210404*	50~366 S
MURPHY, C. E.	7812290045* 7812290064*	50-390 50-430	0 0	NAUGHTON, W. F. NAUGHTON, W. F.	7810230194 7810300097	50-295 50-295	P P	NIX, R. T. NIX, R. T.	7B11210370#	50-366 9
MURPHY, C. E. MURPHY, G. E.	7812270054	50-327	ů.	NAUGHTON H. F.	7811010069	50-295	P	NIX. R. T.	7611210243*	50-366 B
MURPHY, P. M.	7812050347	50-556	0	NAUOHTON, W. F.	7811210410	50-295 50-237	P F	NIX,R.T. NIX,R.T.	7611220028# 7611210366#	50-321 S 50-321 S
MURPHY, C. E.	7812280070*	50-424	g	NAUGHTON W. F.	7812070172	30-237	•			
MURPHY, C. E.	7812040049	50-390	<u>a</u>	NAUCHTON U.F.	7812120195	50-237	F	NIX.R.T. NIX.R.T.	7811280242* 7812180234*	50-366 S
MURPHY, C. E. MURPHY, C. E.	7612050111 7612060357*	50-327 50-369	0 0	NAUGHTON, W. F. NAUGHTON, H. F.	7812070211 7812150230	50-295 50-454	P K	NIX.R.T.	7812180167*	50-366 9
MURPHY, C. E.	7812280306#	50-395	a	NAVENTI.R	7810130182	50-445	Ä	NIX, R. T.	7812180183* 7812180169*	50-366 S
MURPHY, C. E.	7812070019	50~364	0	NAVENTI.R.	7810260030	50-445	•	NIX.R.T.	\@1518019A#	איישנו א
MURPHY, C. E.	7812060025	50-398	G.	NAVENTI.R.	7810260032*	50-445	A	NIX. R. T.	7812190225*	50-366 B
MURPHY, C. E.	7812060065	50-327	Q.	NAVENTI-R.	7812050339	50-445 50-445	A A	NIX, R. T. NIX, R. T.	7812270296# 7812270318#	50-321 S 50-321 S
MURPHY, C. E. MURPHY, C. E.	7812200315* 7812210061*	50-488 50-413	Q Q	NAVENTI.R. NAVENTI.R.	7812110244 7812080159	50~445	A	NIX.R. T.	7812270329*	50-366 \$
MURPHY, C. E.	7812210324*	50-400	Q .	NAYLOR, R.	7812270208+	50-346	8	NIX, R. T.	7812270273*	50-366 8
		80-400	a	NEELY, D. R.	7810250138*	50-286	G .	NIX, R. T.	7812270317*	90-366 8
MURPHY, G. E. MURPHY, G. E.	7812210345* 7812210039*	50-400 50-413	O O	NEELY, D. R. NEIL, R. M.	7811300219	50-338	ė	NIX, R. T.	7812270321* 7812270331*	50-366 8 50-366 B
MURPHY, P. H.	7812290255	50-556	•	NEIBLER, J. H.	7811210013# 7812280314#	50-456 50-440	g Q	N1X, R. T. NOLAN, L. L.	7811280256#	50-263 8
MURPHY, C. E. MURPHY, C. E.	7812180333 7812270357	50-400 50-369	Q: G	NEIBLER, J. H. NELBON, P. R.	7810300343*	50-201	Α	NOONANI V. S.	7811020343*	50~344 G
			_		70101000011	50-556	o ·	NOONAN, V. S.	7812200307#	50~280 0
MURPHY, C. E.	7612280029	50-424 50-390	0 0	NELBON, C. E. NELBON, C. C.	7810190216 7810240206	50-70	P	NORDERHAUG L. R.	7810120008	50-344 Q
MURPHY, C. E. MURPHY, C. E.	7812270038 7812270055	50-438	9	NELBON, C. E.	7810260199	50~336	9	NORDERHAUG: L. R. NORDERHAUG: L. R.	7810190135 7810200235	50-206 G
MURPHY, C. E.	7812270272*	50-316	8	NELBON, Q. E. NELBON, E. B.	7811010433 7811150150	50-556 50-275	Q H	NORDERHAUG. L. R.	7811210244	50-312 G
MURPHY, C. E.	7812290114	50-327	a	WELDHIM E B					7812140031	50-394 G
MURRAY, B.	7811210121*	50-313	a	NELBON, C. C.	7812180293 7812180373	50-70 50-309	P P	NORDERHAUG, L. R. NORDERHAUG, L. R.	7812060202	50-312 G
MURRAY, T. D.	7810180041	50~346	8 8	NELBON, C. C. NELBON, J.	7811210379*	50-346	S	NORDERHAUG. L. R.	7812060205	50~344 G 50-142 G
MURRAY, T. D. MURRAY, T. D.	7810310303 7810100040	50~346 50~346	8	NELBON, C.	7812180012	50-309	P P	NORDERHAUG, L. R. NORELIUS, C. E.	7812270421 7811300117#	50-142 G 50-255 G
HURRAY, T. D.	7810120074	50-346	8	NELBON, C.	7812270489	20-305				
MURRAY, B.	7811170119×	50-128	Q	NEPOM, D. L.	7812040118	50-397	0	NOREL 1US, C. E. NORRHOLM L. J.	7812140263* 7811300298*	50-366 G 50-272 G
MURRAY: T. D.	7810130142	50~346	R	NEVILLE, D. C.	7810230267 7810130195	50-368 50-466	A O	NORRHOLM, L. J.	7812270423*	50-272 G
MURRAY, T. D.	7810150124	50-346 50-346	8	NEWMAN, J. R. NEWMAN, J. R.	7810130175	50-466	0	NORRHOLM L. J.	7812280012* 7811010056*	50-272 G 50-414 A
MURRAY, T. D. MURRAY, T. D.	7810160137 7810230269	50-34 <i>6</i>		NEWMAN, J. R.	7811080054	50-466	٥	NORRIS: J. A.	10110100384	20.414
								•		

NORRIB. J. A. NORTH. H. B. NORTON. B. NORTON. B. NORTON. B. NORTON. B.	7812070162+ 7811270107+ 78110300350 7811010039 7812140085	50-556 50-344 50-275 50-275 50-275		O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7811210306 7811240021 7811290406 7811300033 7811300035	50-269 50-260 50-261 50-302 50-269		OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F.	7812120116 7812150301 7812260213 7812290169 7812290205
NOVARRO, J. P. NOVARRO, J. P. NOVARRO, J. P. NOVARRO, J. P. NOVARRO, J. P.	7810100017 7810270190 7810180074 7812070115* 7812140166	50-322 50-322 50-322 50-322	A 8 9 8 F	O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P.	7811300041 7811300049 7811300057 7811300066 7811300353	50-250 50-259 50-280 50-321 50-348	р Р Р Р	OPLINGER, Q. Q. · OPLINGER, Q. Q OPLINGER, Q. Q. OPLINGER, Q. Q. OPLINGER, Q. Q.	7811130288 7812040243 7812040249 7812190072 7812190074
NOVARRO, J. P. NOVARRO, J. P. NOVARRO, J. P. NOVARRO, J. P. NOVARRO, J. P.	7812260196 7812260211 7812260215 7812260126 7812260221	20-355 20-355 20-355 20-355 20-355	A S S A A	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7812040306 7812040308 7812040310 7812040312 7812040314	50-302 50-250 50-321 50-416 50-437	G G G G	OPREA, Q. W. OBANN, E. W. OST, F. OBTER, J. OSTRANDER, F. W.	7810120061 7811160050 7810170212 7812180210 7811080062
MONICKI, B J. NOMICKI, B J. NOMICKI, B J. NOMICKI, B J. NOMICKI, B J.	7811140014 78111140072 7812080214 7812080239 7812270459	50-219 50-219 50-219 50-219 50-219	р Р Р Р	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7812040318 7812040320 7812040357 7812040359 7812040363	50-395 50-280 50-348 50-261 50-269	@ 0 0 0	OSTRANDER, F. W. DSTRANDER, F. W. OSTRANDER, F. W. OSHALD, P. I. OTTERBERG, J.	7811100174 7812110321 7811150140 7811060082 7810110103
NOWICKI-B. J NUTANT, J. A. NYGAARD-G. R NYGAARD-G. R NYGAARD-G. R	7812220108 7812060155 7810110042 7810110288 7810200134	50-219 50-437 50-409 50-409 50-409	P	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, P. D. O'REILLY, P. D. O'REILLY, J. P. O'REILLY, J. P.	7812040369 7812050230 7812080218 7812270229 7812280007	50-259 50-413 50-372 50-327 50-413	0 0 A 0	OTTOBON, H. L. OUBRE, R. P. DUZTB, J. E. OUZTB, J. E. OUZTB, J. E.	7812270195 7810310087 7810110262 7810310134 7811130229
NYGAARD-Q.R NYGAARD-Q.R. NYGAARD-Q.R NYGAARD-Q.R NYGAARD-Q.R NYGUIST-R.Q	7811200393 7812040263 7812270337 /812270339+ 7811090149+	50~409 50~409 50~409 50~409 50~329	0 0 0 A	O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P. O'RETLLY, J. P.	7812280014 7812280020 7812280022 7812280024 7812280025	50-259 50-348 50-321 50-324 50-302	0 0 0 0	OU2T8: J. E. OUZT8: J. E. OVERLID: T. W. OVERLID: T. W. OWEN: H. H.	7812030057 7812140156 7812200287 7812270245 7810140063
O'CONNOR. P. W O'CONNOR. P. M. O'DONNELL. E. P. O'DONNELL. E. P. O'DONNELL. E. P.	7810250165 7811150246 7810170165 7810170168# 7811300203	50-237 50-237 50-591 50-591 50-591	Р К К К	O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7812280027 7812280030 7812280034 7812290040 7812290081	50-424 50-416 50-395 50-280 50-261	@ @ @ @	OWEN, W. H. OWBLEY, O. F. OWBLEY, O. F. PADMANABHAN, M. PAGE, B. M.	7810140066 7810270108 7811130249 7812270181 7811010220
O'HARA, J.C. O'KELLY, A.P. O'LEARY, J.F. O'LEARY, J.F. O'LEARY, J.F.	7812210066 7810190199 7810300362* 7811200039* 7811200053*	50-245 50-522 50-201 50-437 50-437	P G A A	O'REILLY, J. P. O'REILLY, J. P. DBERG, C. R. OBERG, C. R. OBERG, C. R.	7812270097 7812270092 7811020369* 7811270181* 7812060112*	50-250 50-269 50-458 50-482 50-483	a a o o	PAILY, P.P. PANZARELLA, J. PAOLINA, R. J. PAOLINO, R. J. PAPALOS, F. A.	7812010122 7811200327: 7811170299: 7812010111: 7811140123
O'LEARY, J. F.	7811200075* 7811200059* 7811200220* 7811200348* 7811200247*	50-437 50-437 50-437 50-437 50-437	A A A A	OBERG. C. OBLIGADO. A. DESTMANN. M. J. DESTMANN. M. J. CHANZAN. M. J.	7812290253+ 7810100004+ 7811300401+ 7811300402+ 7810110194+	50-485 50-409 50-263 50-373 50-83	0 P 0 0	PAPPAB, H PAPHORTH, L. G. PAPHORTH, L. G. PARADISO, P. J. PARADISO, J. W.	7812030240 7811130209 7812120132 7811240044 7812270164
O'LEARY, J. F. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7811200285* 7810230230* 7810110056 7812050029* 7810230226	50-437 50-259 50-259 50-269 50-259	A G G	DHANIAN, M. J. OLDHAM, W. A. OLDHAM, W. A. DLDHAM, W. A. OLDHAM, W. A. OLMSTEAD, W. J.	7812060149 7811270290 7811270257 7812150036 7810130111	50-83 50-201 50-201 50-201 50-316	P R R O	PARCELL PARCELL PARDUE: L. W. PARKER: W. O. PARKER: W. O.	7811030148 7812150272 7612130145 7810260106 7812060272
O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	781 0230284 781 0230267 781 0230290 781 0230294 781 0230297	50-413 50-269 50-302 50-416 30-437	0 0 0 0	OLMSTEAD, W. J. OLMSTEAD, H. J. OLMSTEAD, H. J. OLMSTEAD, W. J. OLMSTEAD, W. J. OLMSTEAD, W. J.	7810130259 7810140027 7812080005 7812260298 7812260305*	50-516 50-329 50-329 50-329 50-329	0	PARKER, N. C.	7810180076 7810130056 7810110090 7811030221 7810230158
O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	781 0230300 781 0230303 781 0230361 781 0230366 781 0260004	50-259 50-395 50-348 50-261 50-250	Q Q Q Q	OLMSTEAD, W. J. OLMSTEAD, W. J. OLSHAN, L. OLSHAN, L. OLSHAN, L. OLSHAN, L.	7812140223 7812280325 7810300061 7811010001 7812190182	50-329 50-329 50-286 50-247 50-286	0 0 P P	PARKER, H. O.	7810190027 7810200162 7810230058 7810110084 7810110145
O'REILLY, J. P.	7810270018 7810300321 7810270252 7811150073 7811150081	50-321 50-250 50-324 50-259 50-413	0 0 0 0	DLBON, R. C. OLBON, R. C. OLBON, J. F. OPEKA, J. F. OPEKA, J. F.	7811170121 7811240214 7812260044 7811270292* 7810110125	50-317 50-317 50-263 50-245 50-336	P P O R B	PARKER, N. O.	7810130136 7810130174 7810160101 7810180126 7811100115
O'RETILLY, J. P.	7811150085 7811150087 7811150094 7811150098 7811150103	50-269 50-261 50-416 50-302 50-250	0 0 0 0	OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F.	7810120069 7810160117 7810160126 7810200087 7810230207	50-245 50-245 50-336 50-245 50-245	8 8 R R	PARKER, N. O. PARKER, N. O. PARKER, N. O. PARKER, N. O. PARKER, N. O.	7810230029 7810250200 7810310302 7810200068 7810200082
O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P.	7811150110 7811150114 7811150118 7811150122 7811150125	50-280 50-348 50-321 50-395 50-437	0 0 0 0	OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F. OPEKA, J. F.	7811080143 7811080155 7811140187 7811140202 7811140167	50-336 50~336 50-245 50-336 50-245	9 8 8 8	PARKER, N. O. PARKER, N. O. PARKER, N. O. PARKER, N. O. PARKER, N. O.	7810240002 7810310289 7810310336 78110802116 78111001106
O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7812130300+ 7811210256 7811210270 7811210273 7811210279 7811210288	50-324 50-250 50-302 50-241 50-416	Q P P A	OPEKA, J. F.	7811160089 7811140110 7811170104 78111210268 7811210280	50-245 50-336 50-245 50-336 50-245	8 R R 8	PARKER, M. O. PARKER, M. O. PARKER, R. PARKER, M. O. PARKER, M. O.	7810270072 7810300377 7812130090 7811080107 7810240147
O'REILLY, J. P. O'REILLY, J. P. O'REILLY, J. P.	7811210295 7811210296 7811210297 7811210298	50-395 50-348 50-321 50-269	A P P	OPEKA, J.F. OPEKA, J.F. OPEKA, J.F. DPEKA, J.F. OPEKA, J.F.	7811290293 7812050153 7812080117 7812080126 7812120108	50-336 50-336 50-245 50-245 50-336	9 8 8 8	PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	7810250069 7810250153 7810310008 7811010160 7811010162

;

ROHTUA	ACCESSION NUMBER	SUBJECT CATEQORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUB
PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O.	7810300182 7811010412 7810270129 7811130354 7812050025*	50-269 P 50-369 F 50-269 P 50-369 Q 50-269 Q	PARR. O. D. PARR. O. D. PARR. O. D. PARR. O. D. PARR. O. D.	7812130370 7812180260 7812180169 7812190050 7812200107	50-311 A 50-311 A 50-311 A 50-373 A 50-471 I 50-338 P	Pfeffervorn, W. Pfeffervorn, L. Pfeffervorn, H. Pfeffervorn, H. Pfeffervorn, H.	7810260065 7811150101 7810300332 7810300336+ 7812040297	50-4 50-4 50-4 50-4 50-4
PARKER, M. O. PARKER, M. O. PARKER, M. O. PARKER, M. O. PARKER, M. O.	7811010104 7811130374 7811020255 7811070214 7811080137	50-267 P 50-367 Q 50-267 P 50-270 P 50-270 g	PARR, O. D. PARR, O. D. FARR, O. D. PARR, O. D. PATE, R. J.	7812260280 7812270027 7812270269 7812270155 7810110212#	50-404 A 50-311 F 50-307 A 50-308 A 50-361 Q	PHELAN, J. F. PHELAN, J. F. PHELAN, J. F. PHILLIPS, H. B. PHILLIPS, D. L.	7810180104+ 7811140169+ 7812130186+ 7810260184+ 7810300177+	50-10 50-10 50-30 50-20
PARKER, W. O. PARKER, H. O. PARKER, H. O. PARKER, H. O. PARKER, H. O.	7811070110 7811140114 7811150179 7812040328# 7811140065	50-367 F 50-267 P 50-270 P 50-267 G 60-267 P	PATE, R. J. PATE, R. J. PATE, R. J. PATE, R. J. PATEN, W. D.	7811270046* 7812110240* 7812210380* 7812280224* 7812290224	50-361 0 50-361 0 50-206 0 50-361 0 50-556 0	Phillips.O.L Phillips.H.S Phillips.J. Phillips.J.P. Phillips.J.P.	7810300229* 7810300113* 7810160133 7810190262* 7810190267*	20-5; 20-5; 20-3; 20-5;
PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	7811160079 7811160134 7811160153 7811280378 7812010162	50-267 P 50-267 P 50-367 A 50-267 G 50-367 A	PATON, H. D. PATON, W. D. PATON, W. D. PATON, H. D. PATON, H. D. PATON, H. D.	7810300302 7811040054 7811080206 7811150034 7811150264	50-556 0 50-518 0 50-518 0 50-397 H 50-397 H	Phillips, J.P. Phillips, J.P. Phillips, H.B. Phillip.G.A Pieck, T.A.	7810190269* 7810270294 7812280244* 7812140263* 7811240220*	50-2; 50-2; 50-3; 50-3;
PARKER, M. O. PARKER, M. O. PARKER, M. O. PARKER, M. O. PARKER, M. O.	7811220183 7811270165 7811270168* 7811270157 7812060320	50-267 8 50-367 K 50-367 K 50-367 A 50-269 G	PATON: W. D.	7812040003 7811290305 7812070235 7812070240 7812080015#	50-389 0 50-397 0 50-518 0 50-389 0 50-556 0	PIERCE, J. H. PIERCE, A. C. PIGOTT, D. R. PIGOTT, D. R. PILANT, J. H.	7610270197 7811280118 7811060050 7812010142 7810230213•	50-94 50-26 50-26 50-26
PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	7811300172 7812130369 7812010244 7812040147 7812040231	50-270 8 50-367 0 50-267 8 50-267 P 50-269 P	PATON, N. D. PATON, W. D. PATON, W. D. PATTERBON, H. PATTON, H. C.	7812180106 7812210239 7812280317 7812210800+ 7811020379	50-397 H 50-397 G 50-397 G 50-225 A 50-344 T	PILANT, J. M. PILANT, J. H. PILANT, J. H. PILANT, J. H. PILANT, J. H.	7811080112* 7810170152 7810120037 7811270129* 7811020253	50-29 50-29 50-29 50-29
PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	7812070317 7812180131 7812130306 7812140041 7812140053	50-269 0 50-269 P 50-269 0 50-269 0 50-269 0	PAULUS, R. C. PAXTON, H. C.	7810300334 7811100054 7811100050 7811130305 7811130038	50-201 G 50-344 T 50-344 T 50-344 F 50-344 T	FILANT, J. M. PILANT, J. M. PILANT, J. M. PILANT, J. M. PILANT, J. M.	7811140130 7811200115 7812040052* 7812040196 7812040148	50-29 50-29 50-29 50-29
PARKER, W. O.	7812180188 7812270359* 7812130169 7812130176 7812190153	50-270 8 50-369 G 50-287 8 50-269 P 50-287 8	PAXTON, H. C.	7811100024 7811100111 7811100019 7811130380 7812280003	50-344 T 50-344 T 50-344 T 50-344 T 50-344 T	PILANT, J. H. PILANT, J. M. PITTMAN, J. R. PLANCK, C. PLASKON, R. E.	7819130166 7819270320 7810100006* 7811080345 7810230274	50-24 50-24 50-16 50-5
PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O. PARKER, W. O.	7812190127 * 7812210157 7812270211 7812280133 7812270244	80-247 8 80-247 R 80-347 A 80-349 K 80-247 P	Paxton, H. C. Pearbon, Y. R. Pearbon, S. L. Pearbon, S. L. Pedersem, D. E.	7812280004 7810170040+ 7810300196+ 7811240126+ 7811280249+	50-344 T 50-305 Q 50-263 B 50-263 B 50-263 B	Plettinger H. A. Plumlee K. E. Plumlee K. Plumlee K. E. Plumlee K. E.	7812200175 7812040316* 7811150049* 7811300380* 7812270057*	50-45 50-16 50-26 50-26 50-26
PARKER, M. O. PARKYN, J. D. PARMENTER, F. H. PARR, O. D. PARR, O. D.	7819290209 78121101584 7812180412 78112001834 781013003328	80-287 B 80-409 B 80-498 M 80-437 A 80-341 A	PEDERBEN, D. E. PEERY, W. W. PEERY, W. W. PELLUSCH, J. PELLTIER, I. A.	7812260258+ 7810260067+ 7811130419+ 7812280331 7810190099	50-261 8 50-261 9 50-338 9 50-466 9 50-358 A	PODHAL, B. E POIRTER, D. A. POLLOCK, B. L. POOLE, R. D. POOLE, R. D.	7812050356* 7810270157 7811240029 7810180086 7810300150	50-54 50-44 50-36 50-33 50-33
PARR, D. D. PARR, D. D. PARR, D. D. PARR, D. D. PARR, D. D.	7810170134# 7810230178 7810130037 7810110065 7810120002	80-311 A 80-387 A 80-373 A 80-373 A 80-828 A	PELTIER, I.A. PELTIER, I.A. PELTIER, I.A. PELTIER, I.A. PELTIER, I.A. PELTIER, I.A.	7811020097 7811130360 7812110265 7812140261 7812140082	30-322 A 50-322 A 50-338 A 50-358 A 50-358 A	POOLE, R. D. POOLE, R. D. POPDY ICH, M. PORTER, E. O. PORTER, E. O.	7818040190 7812190109 7818270193 7811030092* 7810130113*	50-31 50-16 50-16 50-4 50-3
PARRI O. D. PARRI O. D. PARRI O. D. PARRI O. D. PARRI O. D.	7810120079 7810120110 7810140040 7811020030 7810240176	50~373 A 50~404 A 50~311 K 50~592 A 50~387 A	Peranich M. H. Perdikië. O. C. Perking: T. J. Perking: T. J. Perking: T. J.	7812210401# 7811240208# 7810160121# 7811130319 7811030141	50-482 B 50-275 B 50-220 R 50-220 B 50-220 B	PORTER, W. L. PORTER, W. L. PORTER, E. O. PORTER, M. L. PORTER, M. L.	7810230049 7810200007 7811130120# 7810200076 7810250119	50-4 50-3 50-4 50-3 50-4
PARR; D. D. PARR; O. D. PARR; O. D. PARR; D. D. PARR; D. D.	7810250192 7810250201 7810310360 7811010213 7811020292	50-373 E 50-569 A 50-280 M 50-447 A 50-336 M	Perming, T. J. Perming, T. J. Perming, T. J. Perming, T. J. Permiti, D. J. Permiti, D. J.	7811130400 7811210303* 7812120103* 7812290088* 7810110286*	50-220 8 50-220 R 50-220 R 50-280 Q 50-239 Q	PORTER: W. L. POTTER: J. P. POTTER: R. W. POTTHOFF: F. H. POTTHOFF: F. H.	7812120230 7811130014+ 7812010259 7810190215 7811200073	50-4 50-3 50-2 50-4 50-4
PARR: O. D. PARR: O. D. PARR: O. D. FARR: O. D. PARR: O. D.	7811010224 7811020003 7811070362 7811130107 7811130348	50-502 A 50-502 E 50-397 A 50-483 H 60-466 A	PERROTTI, D. J. PERROTTI, D. J. PERROTTI, D. J. PERROTTI, D. J. PERROY, H. W. PERSON, L. B.	7810250209* 7812070075* 7812050005* 7812060010* 7811170045	50~369 Q 50~261 Q 50~13 G 50~280 Q 50~201 P	POTTHOPP, F. H. POTTHOPP, F. H. PRABMEIVICZ, J. PRATT, K. PRATT, C. H.	7612050352 7812040362 7810200130 7811020378 7812050350	50-4: 50-4: 50-4: 50-4: 50-5:
PARR, C. D. PARR, O. D. PARR, O. D. PARR, D. D. PARR, O. D.	7811150029 7811200199 7811200358 7811280492 7811300344	50-387 A 50-528 A 50-502 A 50-373 A 50-372 M	Peterbon G. Peterbon G. Peterbon G. Peterbon T. A. Peterbon G.	7810110117# 7810110103# 7810180162# 7810250100# 7811210371#	50-285 8 50-285 8 50-285 8 50-327 A 50-285 8	PRATT, C.M. PRATT, C.M. PRENTIBE, R.D. PRENTIBE, R.D. PREVENBLIK, T.V.	7811280297 78112803024 7811010436 7812010335* 7812200251*	30-5 30-6 50-6 50-5 30-5
PARRID.D. PARRID.D.D. PARRID.D. FARRID.D. FARRID.D.	7811300352¢ 7812050048 7812060073 7812110042¢ 7812110260	50-392 M 50-387 A 50-387 F 50-566 A 50-400 A	Peterbon R. S. Peterbon O. Peterbon G. Peterbon G. Peterbon G. Peterbon G.	7812080202 7812200267 7812200231* 7812270217* 7812270224*	50-344 A 50-285 B 50-285 B 50-285 B	PRIETO,R. PRIETTO.R. PRIETTO.R. PRIETTO.R. PRIETTO.R.	7811080030* 7811240125 7812140103 7812290138 7812290143*	30-3 50-3 50-5 50-5
PARR, O. D. PARR, O. D. PARR, O. D. PARR, O. D. PARR, O. D.	7812120171 7812120055 7812110195 7812120007 7812130347	50-400 A 50-311 A 50-338 P 50-438 A 50-311 A	PETERSON O. PETITUEAN, H. R. PETITUEAN, H. R. PETRICK, N. A. PFEFFERMORN, W.	7812270228* 7811210353 7811210418 7812270058 7810300389	50-285 9 50-255 9 50-255 9 50-482 F 50-488 9	PROFFITT, W. L. PROFFITT, W. L. PROXHIRG W. PRZYBYBZ, R. PRZYBYBZ, R.	7811220145 7811220148* 7812280248 7810190240* 7810190237*	50-2 50-3 50-3

AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEOORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
PUGH, R.	7811210329	50-331 P	REED. C.	7812080093	50-295 P	REID, R. H.	7811070061	50-317 P
PULLO, R. E	7810270236*	50-237 B	REED. C.	7812040201	50-454 K	REID, R. H.	7810300255	50-334 P
PULLO, R.	7612040173*	50-237 S	REED. C.	7812040208	50-454 C	REID, R. H.	7811030076	50-318 P
PULS, H	7612180323*	50-267 P	REED. C.	7812040212	50-456 C	REID, R. H.	7811030080*	50-318 P
PURDOH, P. W.	7812130036	50-356 T	REED. C.	7812040212	50-454 K	REID, R. H.	7811030088*	50-318 P
PURDON: P. W. PURDON: P. H. PURDON: P. W. PURDON: P. H. PURDON: P. H.	7812130060 7812150364 7812200325 7812200320 7812200324	50-556 T 50-556 T 50-556 T 50-556 T 50-556 T	REED, C. REED, C. REED, C. REEVEB, E. A REGAN, W. H.	7812070185 7812080114 7812110109 7812130277 7810250205	50-454 K 50-10 P 50-373 A 50-348 F 50-556 A	REID.R. W REID.R. W REID.R. W REID.R. W REID.R. W	7811070013 7811070035* 7811070057* 7811070060* 7811070071*	50-249 P 50-249 P 50-249 P 50-249 P
PURDOM. P. W	7812200321	50-556 T	REGAN, W. H.	7610120101	50-387 A	REID, R. W.	7811170324	50-267 P
PYLE, R. B	7812140247	50-518 0		7810130009	50-361 A	REID, R. W.	7811030166	50-13 P
GUEENER, R. F.	7812010263*	50-338 R		7810130255	50-387 A	REID, R. H.	7811080013	50-157 P
GUEENOZ, B. M	7811070179*	50-346 8		7610130012	50-592 A	REID, R. W.	7811080018*	50-157 P
GUICK, D. R.	7811100030*	50-302 0		7811140023	50-387 A	REID, R. W.	7811130330	50-284 P
QUICK, D.R.	7812050076#	50-302 0	REGAN, W. H.	7810160006	50-387 A	REID, R. W.	7812140065	50-97 P
QUICK, D.R.	7812180317#	50-302 0		7810160009	50-387 A	REID, R. W.	7812140069#	50-97 P
QUINTENZ, T.E	7812110097#	50-219 8		7810160011	50-387 A	REID, R. W.	7811140045	50-317 Q
QUINTENZ, T.E	7812290097#	50-219 9		7810160020	50-387 A	REID, R. W.	7811150247	50-106 H
QUIRK, J.F.	7810310187	50-447 A		7810200128	50-329 A	REID, R. W	7811170029	50-269 P
GUIRK, J.F.	7812130132	50-447 A	REGAN, W. H.	7810240225	50-368 P	REID, R. W.	7811200009	50-106 A
GUZTS, J.E.	78103101164	50-338 Q	REGAN, W. H.	7810240230*	50-368 P	REID, R. W.	7811200394	50-302 P
RAAD, J. H.	78110901594	50-329 A	REGAN, W. H.	7810250131	50-327 A	REID, R. W.	7811210212	50-112 P
RAE, J. J.	7811240199	50-329 A	REGAN, W. H.	7810300027	50-353 A	REID, R. W.	7811290310	50-112 P
RAICHE, S. J.	7810240159	50-549 A	REGAN, W. H.	7810310293	50-329 A	REID, R. W.	7811290315*	50-112 P
RALPHIR.	7810240121+	50-249 8	REGAN, W. H.	7811100135	50-582 D	REID.R.W.	7811200404	50-312 P
RALPHIR.	7811090126+	50-249 8	REGAN, W. H.	7811130328	50-582 A	REID.R.W.	7811210002	50-73 P
RALPHIR.	7812120134+	50-249 8	REGAN, W. H.	7811130332*	50-582 A	REID.R.W.	7811280389	50-289 P
RALPHIR.	7812210252+	50-249 8	REGAN, W. H.	7811170016	50-582	REID.R.W.	7811200346	50-312 P
RAMEYIJT.	7811200248+	50-437 A	REGAN, W. H.	7811130145	50-492 A	REID.R.W.	7811270118	50-269 P
RAHBEY, O.F.	7812070202	50-284 P	REGAN, H. H.	7811270087	30-329 A	REID, R. W.	7811290317	50-309 P
RANDOLPH, J. M.	7810180109*	50-315 S	REGAN, W. H.	7811300019*	30-329 A	REID, R. W.	7811290318*	50-309 P
RANDOLPH, J. M.	7810270193*	50-315 S	REGAN, H. H.	7812110060	30-397	REID, R. W.	7811290319*	50-309 P
RANDOLPH, J. M.	7811300183*	50-316 S	REGAN, H. H.	7812060381*	30-361 A	REID, R. W.	7811280450	50-336 P
RANDOLPH, J. M.	7812120184*	50-316 S	REGAN, H. H.	7812060376	30-361 A	REID, R. W.	7811270169	50-70 P
RANDOLPH, J. M.	7812270260+	50-316 8	REGAN, W. H.	7812070034	50-361 D	REID, R. W.	7811280092	50-57 P
RANSONE, M. O	7810310098	50-518 A		7812120093	50-518 A	REID, R. W.	7612010370	50-313 P
RATHBURN, K. J.	7811240190	50-329 A		7812120139*	50-518 A	REID, R. W.	7812010374+	50-313 P
RAUCOM, T. L.	7811060217+	50-281 8		7812140293	50-438 A	REID, R. W.	7812010381+	50-313 P
RAUSCH, J. K.	7811130108+	50-327 0		7812140294	50-438 A	REID, R. W.	7811280210	50-183 P
RAUSCH, J. K.	7811200188+	50-518 Q	REGAN, W. H.	7812140303	50-438 A	REID. R. W.	7811280382	50-302 P
RAUSCH, J. K.	7811240068+	50-424 Q	REGAN, W. H.	7812140296	50-592 A	REID. R. W.	7812010344	50-318 P
RAUSCH, J. K.	7812130005+	50-327 Q	REGAN, W. H.	7812150003	50-397 Q	REID. R. W.	7812010347*	50-318 P
RAUSCH, J. K.	7812080052+	50-518 Q	REGAN, W. H.	7812210023	50-361 A	REID. R. W.	7812010342*	50-318 P
RAUSCH, J. K.	7812180353+	50-416 Q	REID, R. W.	7812130368#	50-344 P	REID. R. W.	7812040071	50-149 P
RAUSCHIJK.	7812130278+	50-491 0	REID: R. W.	7812130376#	50-344 P'	REID, R. W.	7612040074* 7611200350 7812010005 7612010152 7612210453	50-148 P
RAUSCHIJK.	7812200318+	50-488 0	REID: R. W.	7810250211	50-302 P	REID, R. W.		50-313 P
RAYMONDIHJJ	7811130275+	50-334 Q	REID: R. W.	7810230144	50-70 A	REID, R. W.		50-289 Q
RAYMONDIHJJ	7810180123	50-133 R	REID: R. W.	7810230141	50-87 F	REID, R. W.		50-312 P
RAYMONDIHJJ	7812060304+	50-244 0	REID: R. W.	7810200017	50-193 P	REID, R. W.		50-302 P
RAYMOND, W. J.	7812270153*	50-334 Q	REID: R. H.	7810200021#	50-193 P	REID, R. W.	7812180045	50-287 P
RAYMOND, W. A.	7811150146	50-133 R	REID: R. H.	7810200099	50-313 F	REID, R. W.	7812180047*	50-287 P
RAYMOND, W. A.	7812150310	50-133 R	REID: R. H.	7810200102	50-270 P	REID, R. W.	7812180051*	50-287 P
READ, J.	7811130421	50-549 A	REID: R. H.	7811020084	50-312 P	REID, R. W.	7812140040	50-27 P
READ, J. B.	78111220088*	50-549 T	REID: R. H.	7811020087#	50-312 P	REID, R. W.	7812180072	50-285 P
REAVES, T. E. REAVIS, J. E. REBELDWEKI, T. REBELDWEKI, T.	7812050191	30-416 A	REID: R. W.	7811020098*	50-312 P	REID, R. W.	7812180075*	50-285 F
	7810200083*	30-269 R	REID: R. W.	7810230271	50-313 P	REID, R. W.	7812180083*	50-285 F
	7812210160*	30-269 R	REID: R. W.	7810230273*	50-313 P	REID, R. W.	7812140095	50-20 F
	7811080248*	30-286 @	REID: R. W.	7810230281*	50-313 P	REID, R. W.	7812140098*	50-20 F
	7811300340*	30-247 G	REID: R. W.	7811020014	50-267 E	REID, R. W.	7812140379	50-317 F
REBELDHEKI, T. REDEKER, S. J. REED, Q. A. REED, C. REED, C.	7812010052+ 7810180035+ 7810190136+ 7810110277 7810120036	50-286 Q 50-133 S 50-266 P 50-10 Q 30-295 P	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7810230147 7810230163 7810310297 7810240006 7811030079	50-99 F 50-2 F 50-112 P 50-72 P 50-317 P	REID: R. W. REID: R. W. REID: R. W. REID: R. W. REID: R. W.	7812180076 7812180079* 7812180070 7812180076 7812180078	50-182 F 50-182 F 50-335 F 50-285 F
REED. C. REED. C. REED. C. REED. M. REED. C.	7811010009 7810250102 7810230181 7811240224* 7810270180	50-10 Q 50-295 P 50-373 A 50-265 8 30-237 P	REID-R.W. REID-R.W. REID-R.W. REID-R.W. REID-R.W.	7811080036 7811080038* 7811020140 7811020146* 7811020272	50-284 P 50-284 P 50-2 P 50-2 P 50-57 P	REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812150079 7812150083 7812150084 7812150087 7812150091	50-317 F 50-269 F 50-313 F 50-289 7
REED. A.	7810270283+	50-267 8	REID: R. W.	7811020274*	50-59 P	REID, R. W.	7812130098	50-309
REED. C.	7811020322	50-10 P	REID: R. W.	7811020277*	50-59	REID, R. W.	7812130100	50-346
REED. C.	7811020161	50-10 P	REID: R. W.	7811030222	50-59 F	REID, R. W.	7812130102	50-312
REED. C.	7811020258	50-373 K	REID: R. W.	7811030224	50-113 P	REID, R. W.	7812180040	50-13
REED. C.	7811070168	50-295 P	REID: R. W.	7811030228*	50-113 P	REID, R. W.	7812180044+	50-13
REED, C.	7812060059	50-456 G	REID; R. W.	7811070376	50-93 F	REID: R. W.	7812140383	50~309
REED, C.	7811210314	50-454 A	REID; R. W.	7811010233	50-317 P	REID: R. W.	7812180376	50~265
REED, M.	78121101834	50-254 B	REID; R. W.	7811060013	50-2 P	REID: R. W.	7812180380*	50~265
REED, C.	7811270091	50-275 P	REID; R. W.	7811060013*	50-2 P	REID: R. W.	7812180390*	50~265
REED, C.	7811270170	50-254 P	REID; R. W.	7811020228	50-289 P	REID: R. W.	7812280288	50~265
REED, C.	7811280213	50-10 P	REID, R. W.	7811030063	50-62 P	REID, R. W.	7812150082*	50-245
REED, C.	7812060020	50-254 0	REID, R. W.	7810260021	50-97 F	REID, R. W.	7812150107	50-285
REED, C.	7811280278	50-295 P	REID, R. W.	7811010363	50-313 P	REID, R. W.	7812150114*	50-285
REED, C.	7812130126	50-456 Q	REID, R. W.	7811030009	50-224 F	REID, R. W.	7812150119*	50-285
REED, C.	7811280264	50-373 K	REID, R. W.	7811030014	50-27 F	REID, R. W.	7812180303	50-285
								···

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR	ACCEB910N NUMBER	GUBJECT Category	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
REID, R. W REID, R. W REID, R. W REID, R. W REID, R. W	7812180371 7812180281 7812210391 7812260295+ 7812260306+	50-131 P 50-269 P 50-312 P 30-245 P 50-245 P	RHODE, Q. K. RHODE, Q. K. RHODE, Q. K. RHODE, Q. K. RICE, R. M.	7812070192 7812070219 7812280196 7812280202 7810250100+	50-410 B 50-410 A 50-410 G 50-410 A 50-329 A	ROISMAN.A 2 ROISMAN.A, Z ROISMAN.A Z ROISMAN.A Z ROISMAN.A Z	7812270036 7812110070 7812110074* 7812280271 7812280280*	50-437 50-437 50-437 50-437 50-237
REID, R. W. REID, R. W. REID, R. W. REID, R. W. REID, R. W.	7812260062 7812270116 7812270401 7812270409* 7812280238	50-269 P 50-312 F 50-73 P 50-73 P 50-269 P	RICE, L. RICHARDS, W. RICHARDS, B. R. RICHARDSON, C. K. RICHARDS, B.	7812080024 7811020278* 7810270097* 7812110164* 7812140153	50-275	ROKASY, J. S. ROKASY, J. S. ROMNEY, K. H. ROMNEY, K. M. ROMNEY, K. M.	7811080045 7811130344* 7810310105* 7810310216* 7811170171*	50-580 50-580 50-317 50-318 50-318
REID.R.W. REID.R.W. REID.R.W. REID.R.W. REID.R.W.	76122802474 7812280297 7812290007 7812290008* 7812290188	50-269 P 50-70 P 50-62 P 50-62 P 50-346 P	RIDEN, M. D. RIDEN, M. D. RIDGWAY, K. R. RIDGWAY, K. R. RIEDLINGER, B. A.	7811080074+ 7812210054+ 7811300141+ 7812040077+ 7812140072+	50-295	ROMNEY, X. ROMNEY, K. M RONE, A. H ROOD, H ROOD, H.	7811170187* 7811290267* 7812200240* 7811200063* 7811200396*	50-318 50-317 50-219 50-437 50-437
REINERT, 8. REINERT, 8. REINERT, 8. REINMUTH, Q. W. REIR, E. J.	7811010267 7810300055 7811210467 7810130167* 7811270264	50-443	RILEY, B. W. RILEY, B. W. RILEY, J. RINGLE, J. C. RISCHLING, J.	7810110302* 7811280012* 7812270197* 7810180018*	50-324 0 50-321 0 50-369 0 50-106 P 50-316 8	ROOD, H. ROOD, H. ROOD, H. ROOD, H. ROOD, H.	7811200380 * 7811200343 * 7811200359 * 7811200381 7811280001	50-437 50-437 50-437 50-361 50-361
REIB, E. J. REIB, E. J. REIB, E. J. REIB, E. J. REIB, E. J.	7611290346 7612120228 7612040006 7612140365 7612150340	50-400 0 50-409 0 50-485 0 50-566 0 50-400 0	rischling, J. Rischling, J. L. Rischling, J. L. Rischling, J. L. Rischling, J.	7810180005* 7810180030* 7810310195* 7810310199* 7811090153*	50-316 8 50-316 8 50-316 8 50-316 8 50-316 9	ROOD, H. ROOD, H. ROONEY, V. L. ROONEY, V. L. ROSA, F.	7612050367 7812180450 7811280439 7812070314 7812040327+	50-361 50-361 50-133 50-133 50-275
REIB, E. J. REIB, E. J. REIBB, J. REIBB, J.	7812150344* 7812270424 7812280278 7810170222* 7810170242*	50-400 0 50-247 0 50-400 0 50-304 8 50-304 8	Ribchling, J. Ribchling, J. Ribchling, J. L. Ribchling, J. L. Ribchling, J. L.	7811090158+ 7811140218+ 7812080070+ 7812180212+ 7812270255+	50-316 8 50-316 8 50-316 8 50-316 8	ROSE, D. O ROSE, D. O ROSE, D. O ROSENBERO, A B ROSENBERO, A. B	7811170297 7811220012 7812140105 7810230013+ 7811060103+	30-266 30-358 30-322 30-443 30-362
REIBB, J. F. REMICK, F. J. REMICK, F. J. REMICK, F. J. RENAUD, J.	7812210239* 7611080219 7612040047 7612040045 7810250006	50-275 8 50-318 Q 50-275 T 50-275 T 50-466 Q	RISCHLING, J, L RISCEY, J RISTOVICH, S. RITSHER, J, A. RITSHER, J, A.	7812270264# 7810160146# 7810190267# 7811010244 7811080195	50-316 8 50-409 P 50-275 9 50-443 9 50-568 9	ROSENBERO, A. B ROSENTHAL, J. E. ROSENBERO, A. B. ROSENBERO, A. B. ROSENBERO, H.	7611200216+ 7610310016 7812060342+ 7812210179+ 7812110219	50-49B 50-266 50-445 50-445 50-275
RENBERGER, D. L.	7811070147* 7810110206* 7811010119 7811020245 7811020247*	50-397 Q 50-460 G 50-397 A 50-460 I 50-460 I	RITSHER, J. A. RITSHER, J. A. RITTS, F. H. ROBERGE, J. C. ROBERTBON, R. C	7810310185 7811070138 7812140244 7811090149* 7811270054*	50-443 A 50-443 I 50-445 M 50-329 A 50-488 A	ROSENTHAL, A B. RDBCLle.E. ROSS, D. A ROSS, D. A ROSS, D. A	7812130053 7811020037 7810100070 7810100075* 7811080258*	50-554 50-344 50-217 50-217 50-217
RENBEROER, D. L.	7811070269 7811220197* 7811280265 7812070208 7812130110	50-397 C 50-397 B 50-397 A 50-397 B 50-397 C	ROBERTS, M. ROBERTS, C. P. ROBINSON, J. X. ROBINSON, J. X. RODOER, M. A.	7812270335 7812210374 7811300100 7812060216 7812050354#	50-295 0 50-395 M 50-338 A 50-338 H 50-549 T	R098. D. A. R098. D. A. R098. D. A. R098. D. A. R098. D. A.	7810120071 7810120076# 7811080234# 7810180006 7810180007#	50-219 50-219 50-219 50-219 50-219
renberoer, D. L. Renberoer, D. L. Renberoer, D. L. Renberoer, D. L. Renberoer, D. L.	7812130180 7812210161# 7812270148 7812270183 7812280144	50-397 R 50-460 Q 50-508 A 50-397 A 50-397 C	RODI, J. P. RODRIGUEZ, R. J. RODRIGUEZ, R. J. RODRIGUEZ, R. J. ROE, L. E.	7810170156 7810110124 7811160076 7812200176 7810270171	50-393 A 50-312 R 50-312 R 50-312 R 50-346 P	Ross. D. A Ross. D. A Ross. D. A Ross. D. A Ross. D. A	7810230259 7810240105 7810240107* 7812070286* 7812010131*	50-219 50-219 50-219 50-219 50-219
rentfro.H.E. Regcek, f. Regnikoff, m. Reuter, f. Reuter, A.L.	7810110238* 7812110182* 7812270009* 7812010249* 7812130199	50-466 0 50-275 8 50-220 P 50-447 A 50-549 0	ROE, L. E. ROE, L. E. ROE, L. E. ROE, L. E. ROE, L. E.	7810270177 7811010056 7811010129 7811060118 7811170100	50-346 P 50-500 A 50-500 I 50-346 P 50-346 F	Ross, D. A. Ross, D. A. Ross, D. A. Ross, D. A. Ross, D. A.	7811210239 7811200204 7811200207* 7811210321 7811210324*	50-219 50-219 50-219 50-219 50-219
REUTER, D. A. REUTTER, J. M. REUTTER, J. M. REUTTER, J. M. REVELEY, W. T.	7811210187 7811200095* 7811200098* 7811200100* 7810240038	50-368 R 50-346 R 50-346 R 50-346 R 50-516 0	ROE, L. E. ROE, L. E. ROE, L. E. ROE, L. E. ROE, L. E.	7811200178 7811220174 7811220158 7812040228 7812050143	50-346 F 50-346 F 50-500 E 50-346 F 50-346 P	ROBS, D. A ROBS, D. A ROSS, D. A ROBS, D. A ROBS, W. J.	7811280193 7811280196* 7812070220* 7812070218 7812130323	50-219 50-219 50-219 50-219 50-302
REVELEY, W. T. REVELEY, W. T. REYES, L. A. REYES, L. A. REYES, L. A.	7811200307 7811290087 7811010029* 7811090189* 7812010129*	50-516 0 50-516 0 50-10 0 50-315 0 50-255 0	ROE, L. E. ROE, L. E. ROE, L. E. ROE, L. E. ROE, L. E.	7812190081 7812180204 7812180134 7812200166 7812270236	50-346 P 50-346 F 50-346 P 50-500 A 50-346 F	RD99, W. W. RD99, D. A. RD99, D. A. RD99, D. A. RD99, D. A.	7812180246 7812190107* 7812200190 7812270316 7812270323*	50-327 50-217 50-217 50-217 50-217
REYNOLDS, N. S. REYNOLDS, N. S. REYNOLDS, N. S. REYNOLDS, H. S. REYNOLDS, H. S.	7810110064 7810110279 7810200001 7810200177 7810200182#	50-397	RDOERB, R. F. ROOERB, C. L. ROOERB, M. ROOERB, V. C. ROOERB, R.	7811010428* 7810170187* 7811080245* 7810170056 7810110092*	50-275 B 50-271 G 50-201 P	ROSS, D. A ROSS, D. A ROSZTOCZY, Z R. ROSZTOCZY, Z R. ROSZTOCZY, Z R.	7812270213 7812270217+ 7810300174+ 7810300167 7812110022	50-219 50-219 50-277 50-277 50-330
REYNOLDS, W. B. REYNOLDS, W. B. REYNOLDS, W. B. REYNOLDS, W. B. REYNOLDS, W. B.	7810840227 7811010285 7811070137 7811130071 7811130144	50-483	ROGERB. C. L. ROGERB. M. H. ROGERB. C. L. ROGERB. C. L. ROGERB. C.	7810170234+ 7811240213+ 7810230176+ 7811240147+ 7811240229+	50-295 B 50-321 B 50-304 B	ROTH; J. M. ROTH; A. J. ROTTAN; J. J. ROWE; J. M. ROWLAND; F. 8	7810190248 7811030245 7812010036* 7812040311 7812060145	50-87 50-592 50-333 50-295 50-326
REYNOLDS, W. B. REYNOLDS, W. B. REYNOLDS, W. B. REYNOLDS, W. B. REYNOLDS, W. B.	7811130230* 7811130230* 7811130230* 7811270048 7811270050*	50-346 M 50-346 M 50-493 0	ROGERS, R. F. ROGERS, G. L. ROGERS, M. H. ROGERS, R. F. ROHNER, M. M.	7812060350* 7812110129* 7811280224* 7812280294* 7812210074*	, 50-295 8 , 50-366 8 , 50-321 0	RUETER, D. A. RUETER, D. A. RUFF, A. RUFF, E. J. RUHLMAN, W. A.	7811220134 7812180163 7812060274* 7812150226 7811080097*	50-368 50-368 50-327 50-413 50-286
REYNOLDS. W. B. REYNOLDS. N. B. REYNOLDS. N. B. REYNOLDS. W. B. REYNOLDS. W. B. RHODES. J. G.	7812110254 7811300008 7812270141 7812130057 7810300167*	50-483 9 50-445 M 50-397 9 50-483 9	ROIBMAN, A. I. ROIBMAN, A. I. ROIBMAN, A. I. ROIBMAN, A. I. ROIBMAN, A. I.	7810120088 7810300063 7810300268 7811150223 7811150227	50-349 50-237 0 50-437 0 50-237 0 50-437 0	RUHLMAN, W. RUITER, O. H. RUITER, O. H. RUITER, O. H. RUITER, O. H.	78120101034 78101000524 78102302314 78102401384 78112201974	50 - 309 50 - 305 50 - 305 50 - 305 50 - 305

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY
AUITER O H	78112803054	50-305 B	SCHNETDER, R. R	7811150041*	50-220 0	BCHWENCER. A	7B11150249	50-247 F
RUITER.O H	7811280310*	50-305 8	SCHNEIDER R.	7811130188	50-220 G 50-220 P	BCHWENCER. A BCHWENCER. A	7811170141 7811170143*	50-344 P
RUSSELL.T W RUSSELL.L 8	7810230145 7811170165	50-98 P 50-318 8	BCHNE I DER , R. R. BCHNE I DER , R. R	7810300146 7811090155	50-220 B	BCHWENCER. A	7811130171	50-247 P
RUSSELL.L 8	7811170179	50-31B 8	SCHNE 1 DER . R R	78110902064	50-220 9	SCHWENCER. A	7811170082	50-280 P
RUSSELL.L. B	7811210407	50-317 8	SCHNETDER, R R	7811090271	50-220 8	BCHWENCER, A	7811210200	20-509 b
RUSSELL.L B	7811300196	50-317 8	SCHNEIDER R R.	7811210302	50-220 R	BCHWENCER, A	78112102054	50-284 P
RUSSELL.L B	7811290264	50-317 8	SCHNEIDER R.	7811210281 7811210281	50-220 8 50-220 8	BCHWENCER A. BCHWENCER A	781 210213* 781 290152	50-286 P
RUSSELL.L B RUSSELL.H K	7811300211 7812270025	50-310 S 50-275 G	SCHNEIDER RR. SCHNEIDER RR.	7812140149	50-220 B	BCHWENCER. A.	7811290166*	30-280 P
				7711010100	50-568 A	SCHWENCER, A.	7811270168*	50-280 P
RUSSELL,L B RUSSELL,L B	7812130170 7812130183	50-318 S 50-318 S	SCHOCK, D. SCHOCK, D	7811010132 7812010204	50-568 A 50-568 A	BCHWENCER, A	7811270175*	30-280 P
RUSSELLIL	7812130189	50-317 B	SCHOPPMAN, M. A	7810100102+	50-335 8	BCHWENCER. A.	7811280344	30-315 P
RUSSELL,L 8	7812260244	50-318 S 50-70 P	SCHOPPMAN, M A SCHOPPMAN, M A	7810100092* 7810100093*	50-335 9 50-335 9	SCHWENCER, A SCHWENCER, A.	7811270018 7811270019*	50-315 P
RYAN, L. J	7811070355*	30-70 P	ochorrian ii k	78101000754			70.1270011	
RYAN, L J	7810300272	50-556 0	SCHOPPMAN, M A	7810120052	50-251 B 50-335 B	BCHWENCER, A. BCHWENCER, A.	7011270020*	50-315 P
RYAN, J. D. RYAN, T. G.	781107028 5 7812280338	50-341 G 50-445 M	BCHOPPMAN, M. A. BCHOPPMAN, M. A.	7810120051* 7811080150*	50-251 8	BCHWENCER, A.	7811270021* 7811270023*	50-315 P
SACK. E. J	7812270060	50-247 0	SCHOPPMAN, M. A.	7810170245	50-335 8	SCHWENCER. A	7811280170	30-250 F
BAHM. J R	7810300166	50-267 8	SCHOPPMAN, M A	7810200096	50-251 8	SCHWENCER. A	7811280172*	50-250 F
BALTZMAN, J.	7809150539+	50-13 J	SCHOPPMAN, M. A	7B102001174	50-251 5	SCHWENCER, A.	7811280174*	50-250 F
SALTZMAN J.	7810110146+	50-331 J 50-264 J	SCHOPPMAN H A SCHOPPMAN H A.	7810230169* 7810230253*	50-335 B 50-251 B	SCHWENCER, A SCHWENCER, A	7811280176* 7811290068	50-250 F 50-250 P
SALTZMANL J SALTZMANL J.	7810110101+ 7811210173+	50-264 J 50-358 J	BCHOPPMAN M A	7811040148+	50-250 8	BCHWENCER, A.	7811270000	50-348 P
BALTZMAN J.	7810180140+	50-338 J	SCHOPPHAN, M. A	7811060152+	50-250 8	SCHWENCER. A.	7B11220118*	50-348 P
SALTZMAN J	7811300218+	50-433 J	SCHOPPMAN, M. A.	7811060163#	50-251 8	SCHWENCER. A	7811220125*	50-348 P
BALTZMAN. J	7811280276	50-272 J	SCHOPPMAN, M. A.	78110802174	50-335 8	SCHWENCER, A.	7811220239	50-334 P
SALTZMAN J	7812130008*	50-133 J 50-252 J	SCHOPPMAN M A.	7811220203+	50-250 8 50-335 8	SCHWENCER, A. SCHWENCER, A	7811270136	30-261 F
BALTZMAN J. BADMMAR P.	7812140157# 7811270080#	50-252 J 50-315 B	SCHOPPMAN, M. A. SCHOPPMAN, M. A.	7811300170* 7812040222*	50-333 B	SCHWENCER, A	7811280403 7811290010	50-202 P
SANDERS W F	7812130112* 7812060346*	50-352 0 50-271 0	SCHOPPMAN, M. A. SCHOPPMAN, M. A.	7812040189# 7812050133#	50-250 8 50-335 8	BCHWENCER, A BCHWENCER, A	7811270059 7811270061*	50-348 P
BANDERS N F.	7812180092+	50-20 0	BCHOPPMAN, M. A.	7812050181+	50-251 B	SCHWENCER, A.	7811270066*	50-348 P
BANDVIK.R M. BANDVIK.R.H	7810270354+	50-344 G 50-514 G	SCHOPPMAN, M. A. SCHOPPMAN, M. A.	7812030198+ 7812270312+	50-335 8 50-251 8	SCHWENCER, A	7811280385	50-334 P
SMUATVIE U	7810300162	50-514 G	SCHOPPHANIR A	1018510715*	30-531 9	SCHWENCER, A.	7811280079	50-305 F
SANDVIK.R. M	7811080062	50-344 0	SCHRIEBER D.L.	7810230156	50-327 A	BCHWENCER. A.	7811280357	50-305 P
SANDVIK.R.M SANGER.H.S.	7812110321 7810240037	50-344 0 50-566 0	SCHULMAN, J. M. BCHUMACHER, K. S	7812150279 7811270166	50-346 M 50-317 P	SCHWENCER, A. SCHWENCER, A.	7811300022 7812040224	50-272 F
SAUBER. J	7810240077*	50-249 R	BCHUMACHER K B	7812130387*	50-344 P	SCHHENCER. A	7811290365	50-282 F
SCHACKLEFORD, B.	78112201824	30-275 A	BCHUNACHER, M. C.	78:0260:83#	50-155 0	SCHWENCER: A.	7612140062	50-346 F
SCHAEFER, W.	7811200275	50-266 9	SCHUMACHER M C.	7811140189#	50-315 Q	SCHWENCER A.	7812080148	50-250 F
SCHAEFER, W.	7812180267	50-305 0	SCHWARZ, M. D.	7812040367	50-498 Q	SCHWENCER. A.	7812110085	50~344 F
SCHEID.K.	7812200127 7811130202	50-546 8 50-295 0	SCHWAN, C. A. SCHWENCER, A.	7812140086+ 7812150069	50-10 0 50-70 P	SCHWENCER, A. SCHWENCER, A.	7812140332 7812140351	50-272 F 50-286 F
SCHERER, A. E.	7810300244	50-470 K	SCHWENCER, A.	7812180411	50-70 P	BCHWENCER, A.	7812140357	50-250 F
SCHERER, A E	7811300213#	90-361 Q	SCHWENCER, A.	7000070073	50-70 P	ECHIEVES A		
SCHERER A E.	7811160077	50-470 A	BCHWENCER A.	7809270023 7812010382	50-250 P	SCHWENCER, A. SCHWENCER, A.	7812140364 7812150006	50~348 € 50~305 €
SCHERER A. E.	7811290143	50-470 A	SCHWENCER, A	7810250175	50-250 P	SCHWENCER, A	781215000B	50-266 F
SCHERER A. E SCHERER A. E	7812120074 7812270163	50-470 K 50-470 K	SCHWENCER A. SCHWENCER A	7811130175* 7811210191	50-250 P 50-250 P	SCHWENCER, A SCHWENCER, A	781215001B 7812150026	50-344 F
						OCHWEITE MA	7812130026	50-3 F
SCHINK, D. R SCHMIDT, A. D	7812290281 7810100091	50-341 T 50-335 B	BCHWENCER, A. BCHWENCER, A.	7810110041 7810110044+	50-281 P	BCHWENCER, A	7812150059	50-280
SCHMIDT. A. D.	7810100071	50-335 B	SCHWENCER, A.	7810120098	50-295 P	SCHWENCER, A. SCHWENCER, A.	7812150061 7812150064	50-282 (50-261 (
BCHMIDT.A.D. BCHMIDT.A.D	78101000974	50-335 8	SCHWENCER, A	7810250014	50-266 P	SCHWENCER, A.	7812130045	50-334 I
OCHATOTIM. D	7810120050	50-251 8	SCHWENCER, A	7810130110	30-305 F	SCHWENCER, A.	7812180113	50-316 F
SCHMIDT, A. D	7810120049	50-335 8	SCHWENCER, A	7810310233	30-261 P	BCHWENCER, A	7812180116	50-295 (
SCHMIDTA.D BCHMIDTA.D.	7810120054 7810170243	50-335 9 50-335 B	SCHWENCER A. SCHWENCER A.	7810310237* 7810310244*	50-261 P 50-261 P	BCHWENCER, A.	7812180236	30-275
BCHMIDT, A. D	7810200093	50-231 8	SCHWENCER A	7810200194	50-261 P	SCHWENCER, A. SCHWENCER, A.	7812180239# 7812180240#	50-295 (50-295 (
SCHMIDT.A D	7810200114	50-251 B	BCHHENCER, A.	7810200199*	50-261 P	BCHWENCER, A.	7812180242*	50-295
SCHMIDT-A. D.	7810230166	50-335 8	SCHHENCER, A.	7610200201	50-241 P	SCHWENCER. A	7812180244*	40-70°
SCHMIDT-A D.	7810230250	50-251 9	SCHWENCER, A.	7810190101	50-266 P	BCHWENCER, A.	7812180244+	50-295 (50-305 (
BCHMITT.R.P BCHNIDT.A.D.	7810310170+ 7811060142	50-344 8 50-250 8	BCHHENCER A. BCHHENCER A.	7810250215 7810300325	50-280 P 30-250 F	SCHWENCER, A.	7812110010	50~250
BCHMIDT, A. D	7B11060144	50-250 B	SCHWENCER, A.	7811140030	50-250 P	BCHWENCER, A. BCHWENCER, A.	7812120227 7812120059	50-334 (50-280 (
SCHMIDT.A. D	7811060157	50-251 B	SCHWENCER, A					
SCHMIDT. T. H.	7812010079	50-201 B	BCHWENCER. A	7811140033+ 7811140039+	50-250 P 50-250 P	SCHWENCER, A. SCHWENCER, A.	7812130101	30-599
BCHMIDT.A.D	7811080148	50-251 B	SCHUENCER A.	7810310299	50-247 P	SCHHENCER, A	7812130363 7812210320	50~344 50~266
SCHMIDT.A.D.	7811080208 7811220201	50-235 8 50-250 6	BCHNENCER, A BCHNENCER, A	7810310304* 7811150175*	50-247 P 50-247 P	BCHWENCER, A.	7812130215	50-282
				76111301734	30-247 F	BCHWENCER, A.	7812270486	50-286
SCHMIDT.A.D. SCHMIDT.A.D.	7811300184 7812040221	50-335 8	SCHWEIBINZ, E. R.	7811270181*	50-4B2 G	SCHWENCER, A.	7812280011	50-305
SCHMIDT, A. D.	7812040187	50-251 8 50-250 8	BCHWENCER, A. BCHWENCER, A.	7810270380 7811030203	50-280 P 50-250 P	SCHWENCER, A. SCHWENCER, A.	7812280015* 7812280018*	50-305
SCHMIDT, A. D.	7812050131	50-335 8	SCHWENCER, A.	7811090015	50-250 P	BCHHENCER, A	7812280284	50-305 50-280
SCHMIDT.A.D.	7812050176	50-251 8	SCHWENCER. A	7811090016+	50-250 P	SCIBINICO, M. J.	7812240284	50-450
SCHMIDT.A.D.	7812050195	50-335 6	BCHWENCER. A.	7811090021#	50-250 P	BCINTO, J. F.	7810240209	50-542
SCHMIDTAH.C. SCHMIDTAA.D.	7812190070 7812270307	50-445 K	BCHMENCER, A	7811130075	50-250 P	SCINTO, J. F.	7811290007	50-516 50-48B
SCHNEIDER, F. W	78112003524	50-251 8 50-437 A	BCHNE I B INZ. E. R. BCHNENCER. A.	7812190135# 7811060060	50-493 G 50-280 P	SCINTO, J. F.	7812270114	80-320
SCHNETDER, F. W.	7811130233	50-311 A	SCHWENCER. A	7812140180	50-280 E	SCOTT, J. B. SCOTT, J.	7810110241* 7810160134*	50-466 50-466
BCHNEIDER, R. R.	7810260022*	50-220 G	SCHWEIBINZ, E. R.	78120601124	80-402 4			
SCHNEIDER, R. R.	7810100054	50-220 B	BCHWENCER, A.	7811170256	50-483 G 50-282 P	BCOTT, D.M. BCOTT, J.	7810240145 7811160196	50-271
BCHNEIDER, H. F. BCHNEIDER, H. L.	7811130119# 7810180049#	50-272 g 50-295 r	SCHMENCER A.	7811170259*	50~282 P	BCOTT, J.	7811210038	50~4&& 50~4&&
SCHNE I DER, R. R.	7810160119	50-220 R	SCHWENCER, A. SCHWENCER, A.	7811170265* 7811170268*	50-282 P 50-282 P	BCOTT, J. BCOTT, J.	7812040302#	50-466
			•		,	555.11V.	7812040301	50~466

AUTHOR	ACCESSION NUMBER	BUBJECT	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEODR'
BEDTT, J. BECKMAN, P. E BEED, H. B. BEEGERT, G. L. BEELINGER, J. L.	7812180306 7810110143 7812060086 7811206092* 7811070247	50-466 0 50-331 J 50-206 D 50-346 R 50-320 8	SHAFER, H D. SHAFER, H D. SHAFER, H D SHAH, M. R. SHAKELTON, O C	7811140267* 7811210220* 7812120226* 7810200075* 7811070179*	50-373 Q 50-331 Q 50-331 Q 50-250 P 50-397 Q	SHIVELY, CN SHIVELY, CN SHIVELY, CN SHIVELY, CN SHIVELY, CN	78101701474 7810200070* 7811060147* 7811060151* 7811060156*	50-313 50-313 50-368 50-368 50-368
BEELINGER, J. L. BEGER, R. M. BEIDLE, M. C. BEIDLE, M. C. BEIDLE, M. C.	7812110146 7812180142 7810230007 7810240233 7811020048	50-289 6 50-213 J 50-445 0 50-498 0 50-445 0	SHALLER.D V. SHALLER.D V. SHALLER.D V. SHALLER.D V. SHALLER.D V.	7810180016 7810180106 7810100044 7810100024 7810110080	50-316 S 50-315 S 50-316 S 50-315 S 50-315 P	SHIVELY.C N SHIVELY.C N SHIVELY.C N SHIVELY.C N SHIVELY.C N	7811040140* 7811040180* 7811040183* 7811040187* 7811040158*	50-36B 50-313 50-313 50-313 50-313
SEIDLE, M.C. BEIDLE, M.C. BEIDLE, M.C. SEIDLE, M.C. BEIDLE, M.C.	7811020365 7811030035 7810110267 7811060098 7811020442	50-458	SHALLER, D. V.	7810110154 7810110188 7810180002 7810200053 7810180027	50-315 S 50-316 S 50-316 S 50-316 R 50-316 S	SHIVELY.C N SHIVELY.C N SHIVELY.C N SHIVELY.C.N SHIVELY.C.N	7811200149* 7811200180* 7811280211* 7811270142* 7811270144*	50-368 50-313 50-368 50-368 50-368
BEIDLE, H.C. BEIDLE, H.C. BEIDLE, H.C. BEIDLE, H.C. BEIDLE, H.C.	7810110235 7811070305 7810250027 7811200216 7810240216	50-445 G 50-445 G 50-462 G 50-498 G 50-445 G	SHALLER, D. V. SHALLER, D. V. SHALLER, D. V. SHALLER, D. V. SHALLER, D. V.	7810230177 7810230198 7810270191 7810270309 7810310145	30-316 8 30-315 8 50-316 8 50-316 8	SHIVELY.C.N SHIVELY.C.N SHIVELY.C.N SHIVELY.C.N SHIVELY.C.N	7811270146* 7811270149* 7812120142* 7812170152* 7812270164*	50-368 50-368 50-313 50-368 50-368
SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C.	7811270201 7811270039 7811280050 7811170168 7811270177	50-38R 0 50-445 0 50-556 0 50-556 0 50-482 0	SHALLER, D. V. SHALLER, D. V. SHALLER, D. V. SHALLER, D. V. SHALLER, D. V.	7810310190 7811020852 7811090181 7811140154 78111270069	50-316 8 50-315 8 50-316 8 50-315 6 50-315 9	SHIVELY.C.N SHIVELY.C.N SHIVELY.C.N SHIVELY.C.N SHOGAN,RP	7812200229* 7812270249* 7812270304* 7812270310* 7811140131*	50-368 50-313 50-368 50-368 50-266
BEIDLE, W.C. BEIDLE, W.C. BEIDLE, W.C. BEIDLE, W.C. BEIDLE, W.C.	7812060279 7812060338 7811030244 7811070254 7811020384	50-556 G 50-445 G 50-445 G 50-445 G 50-446 G	SHALLER, D. V.	7811290136 7811140210 7811170204 7811210383 7811210437	50-314 F 50-316 B 50-315 F 50-315 R 50-316 R	SHON, P. J SHON, P. J SHON, P. J SHON, P. J SHON, P. J	7810270345* 7810160221 7810230109 7811170003 78111200415	50-344 50-344 50-344 50-356 50-956
BEIDLE, W.C. SEIDLE, W.C. SEIDLE, W.C. BEIDLE, W.C. BEIDLE, W.C.	7812060335 7811170087 7811170085 7811170247 7811300017	50-445 Q 50-466 Q 50-382 Q 50-482 Q 50-445 Q	SHALLER.D V. SHALLER.D V. SHALLER.D V. SHALLER.D V. SHALLER.D V.	7811210271 7811300177 7812010210 7812070216 7812130384	50-315 8 50-316 8 50-316 8 50-315 P 50-315 P	SHON, F. J. SHON, F. J SHON, F. J SHON, F. J SHON, F. J	7812130056 7812130060 7812130364 7812200325 7812200320	50-556 50-556 50-556 50-556 50-556
SEIDLE, H.C. SEIDLE, H.C. SEIDLE, H.C. SEIDLE, H.C. SEIDLE, H.C.	7811300370 7812040122 7811300105 7812110220 7812210027	30-478	SHALLER.D. V SHALLER.D. V SHALLER.D. V SHALLER.D. V SHALLER.D. V	7612080061 7812080075 7812080086 7812110137 7812080119	50~316 8 50~315 9 50~316 8 50~315 R 50~316 8	SHON, F. J SHON, F. J SHON, F. J SHORB, E. M. SHORB, E. M.	7812200324 7812200321 7812290281 7812050184 7812200142	50-596 50-556 50-341 50-367 50-367
BEIDLE, M.C. BEKULER, B. N. BEKULER, B. N. SEKULER, B. N. BEKULER, B. N.	7812190089 .7811240022 7812050047 7812050051* 7812120211	50-445 G 50-295 G 50-295 G 50-295 G 50-295 G	SHALLERID. V. SHALLERID. V SHALLERID. V. SHALLERID. V. SHALLERID. V.	7812120162 7812120178 7812180207 7812200173 7812200203	50-315 8 50-316 8 50-316 9 50-315 R 50-316 R	BHORT, T.E. BHORT, T.E. BHORT, T.E. SHORT, T.E. SHORT, T.E.	7810110223* 7810110189 7810130151 7810130125 7811290390	50-285 50-285 50-285 50-285 50-285
BERABIAN, J. A. BERABIAN, J. A. BERABIAN, J. A. BEYFRITIK, V. BEYFRITIK, V.	7811090038* 7811300380* 7812270057* 7811160182* 7812110268*	30-317 0 50-20 0 50-289 0 30-482 B 50-482 A	BHALLER, D. V. SHALLER, D. V. SHALLER, D. V. SHALLER, D. V. SHANNON, R. E	7612280145 7612270220 7612270252 7612290063 7610170169*	50-316 P 50-315 8 50-316 8 50-316 8 50-295 8	SHORT, T. E. SHORT, T. E. SHORT, T. E. SHORT, T. E. SHORT, T. E.	7810250079 7810250101 7810250063* 7811060079 7811070099	50-265 50-265 50-265 50-265
SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7610140133* 7810140131 7810110011 7810160215 7810200218	50-298 Q 50-313 Q 50-298 Q 50-285 Q 50-482 Q	SHAD, L. C. SHAPAR, H. K. SHAPAR, H. K. SHAPAR, H. K. SHAPAR, H. K.	7811200236* 7811200089* 7810160009 7810230231 7810190139	50-437 A 50-437 A 50-471 A 50-522 O 50-522 O	SHORT, T.E. SHORT, T.E. SHORT, T.E. SHORT, T.E. SHORT, T.E.	7811130184 7812060048+ 7811090180 7811140107 7811140197	50-285 50-285 50-285 50-285 50-285
SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V.	7810200220 7810200225 7810200226 7810250026 7810230276	50-458 G 50-445 G 50-498 G 50-445 B 50-298 G	SHAPARIH K. SHAPARIH K. SHAPARIH K. BHAPARIH K. BHAPIRGIH.A.	7811080044 7811010202 7812120038 7812280072 7812210517	50-556 A 50-549 H 50-580 H 50-445 M 50-97 0	SHORTZ, S. SHORT, T. E. SHORT, T. E. SHORT, T. E. SHORT, T. E.	7811290113 7811150132 7811170193 7812050193 7811280257	50-387 50-285 50-285 50-285 50-285
BEYFRIT.K. V. BEYFRIT.K. V. BEYFRIT.K. V. BEYFRIT.K. V. BEYFRIT.K. V.	7810230278 7810230360 7810230363 7811130001 7811170145	50-285 Q 50-267 Q 50-313 Q 50-267 P 50-482 G	SHAUB, E. T. SHEA, J. J SHEA, J. J. SHEA, J. J. SHEOLOSKY, J. T.	7811010099# 7811060172 7812260010 7812270462 7811300306#	50-277 Q 50-244 P 50-244 P 50-245 P 50-322 Q	SHORT, T. E. SHORT, T. E. SHORT, T. E. SHORT, T. E. SHORT, T. E.	781280280 7812060282* 7812040161 7812130111 7812130178	50-285 50-285 50-285 50-285 50-285
SEYFRITIK. V. SEYFRITIK. V. SEYFRITIK. V. SEYFRITIK. V. SEYFRITIK, V.	7811170148 7811170151 7811170246 7811170250 78111220117	50-498 Q 50-458 G 50-445 Q 50-382 Q 50-313 Q	SHEDLOSKY, J. T. SHELDON, K. P. SHELDON, K. P. SHENEFIELD, J. H. SHERON, B. W.	7812110316* 7612150263* 7812150273* 7812260137 7810140026*	50-245 0 50-443 0 50-443 M 50-556 0	SHORT, T.E. SHORT, T.E. SHREFFLER, J. R. SHREFFLER, J. R. SHREVE, J.	7812260203* 7812290176 7810230349 7811200132 7812270168	50-285 50-285 50-466 50-466 50-250
SEYFRITALV. SEYFRITALV. SEYFRITALV. SEYFRITALV. SEYFRITALV.	7811220117 7811220121 7811220124 7812060261 7812060264	50-285 0 50-267 G 50-298 G 50-298 G 50-285 G	SHERWOOD, O. O. SHERWOOD, O. O. SHERWOOD, O. O. SHERWOOD, O. O. SHERWOOD, O. O.	7810180108 7812010248 7812050220 7812050221* 7812110113	50-447 A 50-447 B 50-447 A 50-447 A	SHROPSHIRE, R. SHROPSHIRE, R. SIEDLE, W.C. SIL BERG, J. E. SIL BERG, J. E.	7812050354* 7812050356* 7812210178 7810300267 7810310078	50-549 50-549 50-445 50-580 50-484
SEYFRIT, K. V. SEYFRIT, K. V. SEYFRIT, K. V. GEYFRIT, K. V. SEYFRIT, K. V.	7812060269 7812130307 7812130308 7812130312 7812130313	50-313 Q 50-382 G 50-445 Q 50-458 Q 50-482 Q	SHERWOOD, Q. Q. SHERWOOD, Q. Q. SHERWOOD, Q. Q. SHIDELER, J. J. SHIMSHAK, R. E.	7812270162 78122801099 7812280100+ 7812110279+ 7812110167+	50-447 A 50-447 B 50-447 B 50-482 A 50-409 B	SIL BERG, J. E. SIL BERG, J. E. SIL BERG, J. E. SIL VER, H SIL VER, H	7810300359 7810310078 7812080233 7810310306 7810300236	50-482 50-484 50-580 50-320 50-327
BEYFRITIK.V. BEYFRITIK.V. BHACKLEFORD.B. BHACKLEFORD.B. BHAFER, & D.	7612130315 7612130333 7610240113# 7811140145# 7812060340#	50-498	Bhimshaw R. E. Bhipway.g. D. Shipway.g. D. Shibbiab. J. A. Shively.c. N.	7812040219* 7812130390* 7812210200* 7812080113 7810170146*	50-409 S 50-275 A 50-275 A 50-272 R 50-313 S	BILVER, H BILVER, H BILVER, H BILVER, K	7811010055* 7811010246 7811140261* 7811100154 7811290147	50-414 50-289 50-410 50-315 50-327

								1		6	8 6	£	8 8	8 8	8 8	8
BMITH, I.W. BMITH, I.W. SMITH, Q.H. BMITH, Q.H. SMITH, T.T.	BMITH, Q. H. SMITH, Q. H. SMITH, Q. H. SMITH, Q. H. SMITH, I. W.	Bhith, T. H. Smith, I. W. Smith, I. W. Smith, B. H. Smith, O. H.	SMITH-I.W. SMITH-Q.H. SMITH-Q.H. SMITH-I.W. SMITH-I.W.	Smith, I.W. Smith, B.H. Smith, B.H. Smith, Q.H. Smith, B.H.	Smith, O. H. Smith, O. H. Smith, O. H. Smith, O. H. Smith, R. H.	SMITH, Q.H. BMITH, T.H BMITH, B.H BMITH, J.D. SMITH, Q.H.	BMITH, I.W. BMITH, I.W. BMITH, I.W. BMITH, I.W. BMITH, Q.H	BMITH, T.H BMITH, O.H. BMITH, B.H. BMITH, O.H. BMITH, O.R.	BLACER, H. W. BMARRELLA, E. A. BMITH, R. BMITH, R. H. BMITH, J. D.	SKOVHOLT, D. J. SKRUTSKI, R. M. SKRUTSKI, R. M SKRUTSKI, R. H. SKRUTSKI, R. M.	SKOLDS: J. L. SKOLDS: J. L. SKOLDS: J. L. SKOLDS: J. L. SKOLDS: J. L.	BJOGREN, R. M. JJOGREN, R. M. BJOGREN, R. M. BKLAR, D. R. BKOLDB, J. L.	BJOGREN, R. M. BJOGREN, R. M. BJOGREN, R. M. BJOGREN, R. M. BJOGREN, R. M.	IINKULE, M. V. IINKULE, M. V. IINKULE, M. V IINKULE, M. V. IJOGREN, R. M.	IIMMONS, D.E. IINCLAIR, M.P IINKIN, L. IINKIN, L. IINKULE, M.V.	ILVER, R. D. ILVER, H. ILVER, H.
7811200294+ 7811210130 7812010033 7812280199 7812260307	7812110232 7811140232 7811300241 7812180037 7811200364	7812060367* 7811070347 7811130189 7811150060 7811150038	7811070335 7811090025 7811130041 7811070349 7811080342	7811010006 7811080337 7811090198 7811300341 7811070209	7812010147 7811080253 7812010034 7812010037 7812010274*	7811020170 7811290339+ 7810270384 7810310273 7611300366	7810230015 7810270227 7810240157 7810250188 7810250134	7812010303* 7811100092 7810200055 7812010081* 7810110183*	7810160197* 7810120067* 7810190116* 7811010135* 7811010029*	7810140101 7810130244 7811270249 7811270002 7812040317	7810250140+ 7811080166+ 7811130286+ 7812040181+ 7812060262+	7812150357* 7812150292* 7812150288* 7812290245* 7810110290*	7810170151# 7810170193# 7811140166# 7811140127# 7811140122#	7810310319* 7811130381* 7811130384* 7811220005* 7810170178*	7812050200 7811210493 7812110057* 7812110054 7810230072*	7812130353* 7812130109 7812180374
50~395 50~395 50~286 50~220 50~247	50~334 50~3 50~334 50~3 50~395	50-333 50-395 50-329 50-549 50-220	50-387 50-317 50-220 50-592 50-592	50-329 50-272 50-3 50-213 50-471	50-244 50-219 50-333 50-220 50-245	50-271 50-336 50-471 50-568 50-20	50-484 50-400 50-329 50-329 50-286	50-317 50-213 50-471 50-296 50-263	50-329 50-316 50-57 50-443 50-10	50-309 50-354 50-450 50-485 50-556	50-280 50-395 50-321 50-395 50-280	50-309 50-271 50-29 50-498 50-338	50-309 50-271 50-309 50-271 50-29	50-369 50-369 50-369 50-335 50-29	50-446 50-329 50-498 50-498 50-335	50-219 50-320 50-327
0 0 0	0 0 0	3 9 9 9	M G P M M	00000	0 0 0	G G A D G	0000	0 0 .T 0	0 P G G	H 0 0 0 0	G G G	R R R A G	R R R R	0 0 0 R	B 0 0	b b
SPENCER, D. S. SPENCER, D. S. SPENCER, D. S. SPENCER, D. S. SPENCER, D. S.	SPARKS, E. BPENCER, O. S. BPENCER, O. S. SPENCER, O. S. BPENCER, O. S.	Souder, J. L. Souder, J. L. Spangler, R. G. Spangler, R. G. Sparks, E.	SDHINKI: 8. M. BOHINKI: 8. M. BOHINKI: 8. M. SOKOLOFSKY: J. H. BOUDER: J. L.	BOHINKI: B. M. BOHINKI: B. M. BOHINKI: B. M. BOHINKI: B. M. BOHINKI: B. M.	SOHINKI,S.M. BOHINKI,S.M. BOHINKI,S.M. SOHINKI,S.M. BOHINKI,S.M.	SDHINKI,S.M. SOHINKI,S.M. SOHINKI,S.M. SOHINKI,S.M. BOHINKI,S.M.	SCHINKI, S. M. SCHINKI, S. M. SCHINKI, S. M. SCHINKI, S. M. SCHINKI, S. M.	SOHINKI, S. M. SOHINKI, S. M. SOHINKI, S. M. SOHINKI, S. M.	SCHINKI, S. M. SCHINKI, S. M. SCHINKI, B. M. SCHINKI, S. M. SCHINKI, S. M.	SOMINKI.S.M. SOMINKI.S.M. SOMINKI.S.M. SOMINKI.S.M. SOMINKI.S.M.	SOBGNIL.J. SOCOLOFSKYIJ.H SOCOLOFSKYIJ.H. SOHINKIB.K. SOHINKIB.K.	SMITH, T. T. SMITH, T. T. SMITH, J. K. SNOW, B. SOBON, L. J.	SMITH, B. H. SMITH, A. F. SMITH, I. W. SMITH, I. W. SMITH, I. W.	SMITH, I.W. SMITH, B.H. SMITH, B.H SMITH, Q.H. SMITH, B.H.	SMITH: J. D. SMITH: I. W. SMITH: J. D. SMITH: O. H. SMITH: J. D.	SHITH, C.H. SHITH, J. SHITH, I.W.
7810310301* 7810110255 7810110208 7810190091 7811010032	7611200376 7611070164* 7611070133 7610310306* 7610310316*	7812040383 7812190108 7812210169* 7812190061* 7811200371	7812280351 7812280354* 7812280356* 7812010361 7811290254	7812130335 7812130365 7812140349 7812180434 7812270142	7811160024 7811280070 7811280143 7812110296 7812130051	7811100170 7811100171 7811140048 7811130084 7811130090	7811070172 7811100134 7811140074 7811130038 7811100131	7810200143 7810200144 7810230012 7810240030 7810300252	7810130242 7810140096 7810140098 7810190271 7810200141	7810110037 7810110234 7810110238* 7810140056* 7810140064*	7812140176 7810140023 7812110217 7810110241* 7810110230*	7612210506 7612210511* 7612270268* 7610170213 7611210367	7812270468 7812180226 7812140108 7812270055 7812270093	7812010257 7812180394 7812130070 7812060242 7812140227	7811220139 7811300267 7812290074 7812270047 7812270014#	7812270078 7812270070* 7812010028
50-528 50-344 50-361 50-397 50-361	50-389 50-397 50-397 50-528 50-528	50-592 50-454 50-368 50-313 50-446	50-466 50-466 50-466 50-344 50-572	50-466 50-466 80-466 50-437 50-485	50-437 50-485 50-466 50-466 50-466	50-592 50-452 50-466 50-437 50-477	50-456 50-466 50-466 50-466 50-465	50-592 50-592 50-592 50-466 50-466	50-452 50-437 50-465 50-592 50-592	50-466 50-466 50-466 50-466 50-466	50-219 50-344 50-344 50-466 50-466	50-247 50-247 50-314 50-244 50-220	50-549 50-395 50-400 50-400 50-395	50-329 50-471 50-471 50-317 50-272	50-484 50-266 50-289 50-305	50-346 50-400 50-560
0 0 0 0	A Q Q Q	A G G A	9 9 9 0	0 0 0 A	000	0 P F F	0 1 0 0 0	A A Q Q	G O O A A	0 0 0	6 6 6	9 9 8 R P	0 F G O	0 0 0	9 9	g e D
BTALLINGB, C, M. BTALLINGB, C, M. BTALLINGB, C, M. BTALLINGB, C, M. BTALLINGB, C, M.	STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M.	Stallings, C, M. Stallings, C. M. Stallings, C. M. Stallings, C. M. Stallings, C. M.	STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALL, D. H. STALLINGS, C. M.	BTALLINGS, C.M. BTALLINGS, C.M. BTALLINGS, C.M. STALLINGS, C.M. STALLINGS, C.M.	STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M.	BYALLINGS, C. M. BYALLINGS, C. M. BYALLINGS, C. M. SYALLINGS, C. M. BYALLINGS, C. M.	STAIR: J.R. STAIR: J.R. STAIR: J.R. STAIR: J.R. STALEY: Q. B.	STAHL: D.M. STAHL: D.M. STAHL: R.F. STAIR: J.R. STAIR: J.R.	STAFFA, R. W. STAFFA, R. W. STAFFA, R. W. STAFFA, R. W. STAFFA, R. W.	Staffa.R.W. Staffa.R.W. Staffa.R.W. Staffa.R.W. Staffa.R.W.	BTAFFA.R.W. BTAFFA.R.W. BTAFFA.R.W. STAFFA.R.W. BTAFFA.R.W.	SPESBARD, R. L. SPESBARD, R. L. STAENSERO, M. R. STAENSERO, M. R. STAENSERO, M. R.	SPENCER, G. B. SPENCER, G. B. SPEBBARD, R. L. SPEBBARD, R. L. SPEBBARD, R. L.	SPENCER. Q. B. SPENCER. Q. B. SPENCER. Q. B. SPENCER. Q. B. SPENCER. Q. B.	SPENCER. Q. B. SPENCER. Q. B. SPENCER. Q. B. SPENCER. Q. B.	SPENCER. 9. 8. SPENCER. 9. 8. SPENCER. 9. 8.
7811030140 7811040211 7811040233 7811040078 7811070228	7810270174 7810300022 7811130238# 7810310089 7810310238	7810200109 7810200110 7811200133* 7810270153 7810240121	7810230184 7810230171 7810230254 7810250121 7810200073	7810140139 7810140198 7810230237 7810230283 7810170163	7810110149 7810110127 7810120034 7810130140 7810130141	7811010415* 7810250232 7811060038* 7810100057 7810100074	7811090174* 7811090278* 7812200278* 7812260261* 7811080199	7811020467 7812150029 7811210413 7810240129# 7810240134#	7811280006 7812070082 7812060343 7812280069* 7812280286	7811100168* 7811030044 7811130261* 7811220054 7811240061	7810130043 7810130092 7811010062 7811150093 7811150163	7812040230* 7812190140* 7811010318 7811130199 7812180414	7612210166* 7612210379* 7610110184* 7611020168* 7611070003*	7612210370 7612260241 7612270387 7612260223 7612210081	7611270056 7612110237 7612110239* 7612210143	7811270044 7810310284 7811270121



ļ

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT
STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M.	7811070130 7811070190 7811070258 7811240050* 7811090177	50-280 P 50-280 P 50-338 B 50-338 Q 50-280 8	STELLO, V. S STELLO, V. STELLO, V. STELLO, V. STELLO, V.	7810140016* 7811020332* 7610110043* 7811070063* 7811150133	50-553 0 50-344 0 50-281 0 50-269 P 50-269 A	STERNBERG, D M.	7811220267+ 7811220267+ 7811270115+ 7812130350+ 7812070045+	50-275 Q 50-275 Q 50-344 Q 50-187 Q 50-106 Q
STALLINGS, C. M STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M.	7811140101 7811140101 7811140128 7811170107 7811170182	50-281 8 50-338 P 50-280 P 50-338 B	STELLO, V. STELLO, V. STELLO, V. STELLO, V. STELLO, V.	7811150052 7811290392 7811200356* 7812110063 7812180386	50-313 P 50-271 E 50-313 P 50-280 P 50-160 E	STERNBERG, D. M. STERNBERG, D. M. STERNBERG, D. M. STETKA, T. STEVENSON, D.	7812130004+ 7812280338+ 7812270382+ 7812060219+ 7810240077+	50-275 Q 50-344 Q 50-397 Q 50-20 Q 50-269 R
STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M.	7811170193 7811200194 7811210259 7811210290 7811210313	30-280 8 30-280 R 30-281 8 30-338 8 50-338 8	BTELLO, V. BTELLO, V. STELLO, V BTENSVAAQ, J. M BTENSVAAQ, J.	7812260261* 7812280285 7812220032 7812260344 7812260323	50-269 P 50-220 Q 50-280 P 50-263 Q 50-263 P	STEVENS, J R STEWART, M. P STEWART, R. C. STEWART, W. P STEWART, W. P.	7812080104 7810200152 7811050105# 7810110151 7810110116	50-368 A 50-302 S 50-302 S 50-302 S
STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M.	7811280286 7811280322 7811280236 7811280247 7811280308	50-281 8 50-338 8 50-280 8 50-280 P 50-338 P	BTEPHENBON, B. B. STEPHENBON, B. B. STEPHENBON, B. B. STEPHENBON, B. B. STEPHENBON, B. B.	7810170185 7810130145 7811210356 7810170204 7810170148	50-237 P 50-237 8 50-237 8 50-10 9 50-10 P	STEWART, W P. STEWART, W P. STEWART, W. P. STEWART, W. P. STEWART, W P.	7810110170 7810110097 7811010299 7810130130 7810160081	50-302 S 50-302 P 50-302 G 50-302 P 50-302 R
STALL I NGB, C. M. STALL I NGB, C. M. STALL I NGB, C. M. STALL I NGB, C. M. STALL I NGB, C. M.	7811280316 7811300222 7812060134 7812180302* 7812130381	50-336 8 50-280 P 50-338 8 50-338 0 50-280 0	STEPHENSON, S. S. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, S. S. STEPHENSON, B. B.	7610170175 7810180101 7810240100 7810240116 7810240148	50-249 & 8 50-10 R 50-249 9 50-249 B 50-10 8	STEWART.N.P STEWART.R.C STEWART.W P STEWART.W.P	7810170249 7811270209+ 7810180103 7810180147 7810180153	50-302 S 50-302 S 50-302 S 50-302 S
STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M.	7812180358* 7812010264 7812040209 7812040230 7812200169	50-280 Q 50-338 R 50-338 B 50-280 B 50-280 P	STEPHENDON B B STEPHENDON B STEPHENDON B B STEPHENDON B B STEPHENDON B B STEPHENDON	7810200092 7810240136 7810270229 7810270234 7810270302	50-237 8 50-249 8 50-249 8 50-237 8 50-237 8	BTEWART, W.P. BTEWART, W.P. BTEWART, W.P. BTEWART, W.P.	7810180110 7810230187+ 7810240118 7810240160 7810270165	50-302 8 50-280 R 50-302 8 50-302 B 50-302 P
STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M STALL INGS, C. M STALL INGS, C. M.	7812050208 7812050223 7812070189 7812070193 7812120083	50-290 8 50-338 8 50-338 9 50-338 8 30-339 A	STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B.	7811240210 7810270287 7811090125 7811030143 7811030184	50-237 8 50-237 8 50-249 8 50-237 8 50-249 8	STEWART.W.P. STEWART.W.P. STEWART.W.P. STEWART.W.P.	7810310136 7810310164 7811100021= 7811240074= 7811080165	50-302 B 50-302 G 50-302 G 50-302 P
STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M.	7612180433 7612110149 7612110204 7612110191 7612110193	50-280 F 50-338 F 50-338 8 50-338 8 50-338 8	STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, S. S.	7811090116 7811090129 7811090138 7811140160 78111060159	50-237 8 50-237 8 50-237 8 50-237 8 50-249 8	BTEWART. D. L. BTEWART. H. P. BTEWART. H. P. BTEWART. W. P. STEWART. W. P.	7811170192* 7811070136 7811070204 7811070208* 7611070226	50-280 R 50-302 8 50-302 8 50-302 8
STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M.	7612130277 7612140125 7612140224 7612130282 7612130289	50-338 P 50-280 B 50-281 B 50-280 P 50-338 P	STEPHENGON, B. B. STEPHENGON, B. B. STEPHENGON, B. B. STEPHENGON, B. B. STEPHENGON, B. B.	7611090113 7611210301 7611140193 7611140222 7611210333	50-10 9 50-237 8 50-237 8 50-249 8 50-249 8	STEWART, M.P. STEWART, H.P. STEWART, H.P. STEWART, H.P.	7811130181 7811130181 7811140109 7811170103 7811200184	50-302 P 50-302 P 50-302 P 50-302 F 50-302 R
STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M. STALLINGS, C. M.	7812200212 7812200253 7812200260 7812150304 7812200204	50-336 8 50-336 R 50-280 R 50-336 P 50-280 8	STEPHENSON: B. B. STEPHENSON: B. B. STEPHENSON: B. B. STEPHENSON: B. B. STEPHENSON: B. B.	7811140203 7811140215 7811160122 7811140119 7811160112	50-237 B 50-237 B 50-237 B 50-237 B 50-237 B	BTEWART, M.P. STEWART, M.P. STEWART, M.P. STEWART, M.P.	7812050067* 7811240216 7811290268 7811280303 7812010246	50-302 P 50-302 R 50-302 B 50-302 B 50-302 P
BYALL INGB, C. M. BYALL INGB, C. M. BYALL INGB, C. M. BYALL INGB, C. M. BYALL INGB, C. M.	7812190079 7819200234 7819190088 7819190090 7819190148	50-280 P 50-338 B 50-280 P 50-280 P 50-280 P	BTEPHENBON: B. B. BTEPHENBON: B. B. BTEPHENBON: B. B. BTEPHENBON: B. B. BTEPHENBON: B. B.	7811210177 7811210388 7811280301 7811280194 7812040191	50-237 8 50-10 8 50-249 8 50-249 8 50-237 8	STEMART, M. P. STEMART, P. P. STEMART, H. D. STEMART, M. P. STEMART, M. P.	7812040199 7812210337* 7812270027 7812140127 7812180150	50-302 P 50-302 G 50-272 G 50-302 F 50-302 B
STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M.	7812220078 7812240252 7812270235 7812270270 7812270270	50-339 A 50-280 P 50-338 8 50-281 8 50-280 8	BTEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B.	7812120130 7812210242 7812210244 7812180175 7812130184	50-249 8 50-249 8 50-249 8 50-249 8 50-10 8	BTEWART, N. P. STEWART, N. P. STEWART, N. P. STEWART, N. P. STEWART, N. P.	7812200176 7812200178 7812200270 7812200284 7812220081	50-302 8 50-302 8 50-302 8
BTALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STALL INGS, C. M. STAMPLEY, N.	7612270320 7612260195 7612260132 7812260136 7811150164	50-280 8 50-338 P 50-280 P 50-338 P 50-416 F	STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B. STEPHENSON, B. B.	7812150270 7812180145 7812180174 7812180223 7812270300	50~237 8 50~249 9 50~10 9 50~237 8 50~237 8	STEWART, W. P. STEWART, W. P. STEWART, W. P. STEWMARD, D. L. STOBER, Q. J.	7812220102 7812270239 7812270291 7811200198* 7812180418	50-302 B 50-302 B 50-302 B 50-280 R 50-338 P
BTAMPLEY, N. L. BTAMPLEY, N. L. BTAMPLEY, N. L. BTAMLEY, W. B. BTAMLEY, R. B.	7811170198 7812010223 7812270209 7810310192* 7810100048*	50-416 A 50-416 K 50-416 A 50-289 8 50-261 8	STEPHENSON: B. B. STEPHENSON: B. B. STEPHENSON: B. B. STEPHENSON: B. B. STEPP: J. C.	7812270284 7812210189 7812270261 7812270210 7812180355	50-249 8 50-237 8 50-237 8 50-237 8 50-70 P	STODDART, P. G. STOHR, J. P. STOHR, J. P. STOHR, J. P.	7811100181 * 7811100181 * 78111060244* 7811020188* 7811100094*	50-286 0 50-3 0 50-271 0 50-213 0
STARKEY, R. B. STARKEY, R. B. STARKEY, R. B. STARKEY, R. B. STARKEY, R. B.	7810190270 7810270226* 7810310127* 7810310153* 7810310219*	50-261 R 50-261 B 50-261 B 50-261 B 50-261 B	STEPP, J. C. STEPP, J. C. STEPP, J. C. STEPP, J. C. STEPP, J. C.	7812190225 7812010014* 7810120111* 7812040324* 7811300279	50-549 A 50-275 G 50-556 A	STOHR, J.P. STOHR, J.P. STOHR, J.P. STOHR, J.P. STOHR, J.P.	7812010150+ 7812010036* 7812010041+ 7812060244+ 7812180058+	50-201 0 50-303 0 50-317 0 50-3 0
STARKEY: R. B. STARK: F. H. STARKEY: R. B. STARKEY: R. B. STAROSTECKI: R.	7811090191* 7812180229 7812140165* 7812270263* 7811200108*	50-261 B 50-70 H 50-261 B 50-261 S 50-437 A	STEPP, J. C. STEPP, J. C. STEPP, J. C. STEPP, J. C. STEPTDE, P.	7811290201 7812190314 7812190183 7812190101 7810120112	50-400 A 50-553 A 50-554 A 50-334 P 50-237 9	STOHR: J.P. STOLZ: J.F. STOLZ: J.F. STOLZ: J.F. STOLZ: J.F.	7812270078* 7811010387 7810110004 7810230294* 7810230293	50-201 0 50-524 A 50-346 P 50-368 P 50-368 P
STAVELY, J. M. STELLO, V. STELLO, V. STELLO, V. STELLO, V.	7811150105± 7811200105± 7811200192± 7812210127 7810230154	50-309 G 50-437 A 50-437 A 50-70 P 50-280 P	STEPTOE.P.P. STEPTOE.P.P. STEPTOE.P.P. STEPTOE.P.P. STEPTOE.P.P.	7810170131 7811130202 7811200070 7812040311 7812280280	50-237 0 50-295 0 50-237 0 50-295 0 50-237 0	STOL 2, J.F. STOL 2, J.F. STOL 2, J.F. STOL 2, J.F. STOL 2, J.F.	7810230301* 7810230309* 7810130029 7810140095 7810250206	50-388 F 50-348 P 50-341 A 50-358 A 50-275 A

											:		!		
BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	SUTHERLAND, J. T.	BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T. BUTHERLAND, J. T.	BUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	SUMMERS, R. J. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	SULLIVAN R.F. SULLIVAN W.F. SULLIVAN R.F. SUMMA, J. BUMMERS, R. J.	STRIGHT, R. L. STRIGHT, R. L. STRIGHT, R. L. SU, S. T. BULLIVAN, R. F.	STRIGHT,R.L. STRIGHT-R.L. STRIGHT-R.C. STRIGHT-R.L. STRIGHT-R.L.	STREETER, J. F. STREETER, J. F. STREETER, J. F. STRIGHT, R. L. STRIGHT, R. L.	STRATHAN R A STREETER, J. F. STREETER, J. F. STREETER, J. F. STREETER, J. F.	STOLZ.J.F. STOLZ.J.F. STOLZ.J.F. STOLZ.J.F. STOCOLEY.D O	810L7.J.F. 810L7.J.F. 810L7.J.F. 810L7.J.F. 810L7.J.F.	810L2, J. F. 810L2, J. F. 810L2, J. F. 810L2, J. F. 810L2, J. F.	STOLZ, J. F. STOLZ, J. F. STOLZ, J. F. STOLZ, J. F. STOLZ, J. F.
7811130306 7811130009 7811130410 7812070069* 7811240077*	781124009* 7811240019* 7811240011* 7811240013* 7811203231*	7810110240 7810250239* 7810250244*	7811170240* 7810310048 7811010186	7810270213 7810260063 7811020440# 7811130018# 7810230033#	7810110265 7810110283 7810190057 7810180189 7810190030+	7812050304* 7810260010* 7810110245* 78111030171* 7811030175*	7812050057* 7812070054* 7812180325* 7812210070* 7812050304*	7811090260 7812050321 7812010101 7812050253 7811010280*	7810110021 7810230323 - 7810270323 7811020426 7811070129	7812140147* 7812290074 7812290014* 7810300138* 7810120126	7811210275* 7810270376* 7811010029* 7811270326* 7812010129*	7812140020* 7812130391 7812140283* 7812180394 7811070004*	7612080222 7812120016 7612070265 7812120208 7812140017*	7812080023* 7812080025* 7812080027* 7812010010 7812080155	7812010370 7812010377* 7811210113 7812070063* 7812080013
50-364 50-332 50-338 50-261 50-302	50-327 50-335 50-335 50-335	50-250 50-369 50-324 50-348 50-348	30-369 50-269 50-324 50-280 50-336	50-327 50-261 50-160 50-259 50-369	50-259 50-259 50-390 50-335 50-369	50-97 50-250 50-324 50-250 50-250	50-259 50-373 50-259 50-245 50-97	50-592 50-592 50-592 50-502 50-259	50-592 50-592 50-592 50-592 50-592	50-266 50-266 50-303 50-447 50-368	50-336 50-301 50-10 50-320 50-255	50-368 50-358 50-275 50-275 50-471	50-368 50-368 50-358 50-275 50-368	50-348 50-348 50-348 50-275 50-341	50-313 50-313 50-275 50-275 50-368
0 0 0 0 0	9 9 9	0 0 0	9 9 9	0 0 0 0	0 0 0	0 0 0 0	G A G P G	A A A G	A A A A	Q Q Q A A	6 9 0 0	P A O A O	B P I A P	P P A A	P P A E P
TEDESCO.R. L. TEDESCO.R. L. TEDESCO.R. L. TEDESCO.R. L. TEDESCO.R. L. TEDESCO.R. L.	TEDESCO.R. L. TEDESCO.R. L. TEDESCO.R. L. TEDESCO.R. TEDESCO.R. TEDESCO.R. L.	TAYLOR, A. TAYLOR, P. A. TAYLOR, P. A. TAYLOR, Q. T. TAYLOR, Q. T.	TAYLOR, R. Q. TAYLOR, R. Q. TAYLOR, R. Q. TAYLOR, P. A. TAYLOR, R. Q.	TAGLIAMONTE, M. TALMANI, P. TANBLING, T. N. TAPIA, J. I. TAPIA, J. I.	BWANBON, D. T. BWANBON, D. T. BWART, F. E. SWEENEY, B. TAQLIAMONTE, M.	SHANBON, E. R. SHANBON, D. T. SHANBON, D. T. SHANBON, D. T. BHANBON, D. T.	SHANSON.D.T. SHANSON.D.T. BHANSON.D.T. BHANSON.D.T. SHANSON.D.T.	BWALES, J. BWAN, W. B. BWAN, W. B. BWANBON, D. T. BWANBON, D. T.	BUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. BUTHERLAND, J. T.	SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T. BUTHERLAND, J. T.	BUTHERLAND, J. T.	SUTHERLAND, J. T. SUTHERLAND, J. T. BUTHERLAND, J. T. GUTHERLAND, J. T. SUTHERLAND, J. T.	SUTHERLAND, J. T.
7811200130+ 7811200437+ 7811200232+ 7810270024 7811060106+	7811200261+ 7811200263+ 7811200142+ 7811200138+ 7811200134+	7812120044* 7812180317* 7812210330* 7812260065 7812260067*	7811020055# 7811020449# 7811070308# 7811220064# 7812060341#	7811140106* 7810240077* 7812270070* 7811270209* 7812060307*	7612270381 7612270072 7612180243 7610120057* 7610130186*	7812290025* 7812150359 7812140111 7812180292 7812220009	7811070185 7811200064 7812040360 7812040251 7812110331	7611240156* 7612180343* 7612280080* 7610250009 7810240089	7812290056 781206015 7812070059 7812130241 7812280328	7812030021 7812010139 7812040326 7812140118* 7812210071*	7812010116 7812010125 7812140119* 7812270082 7812010261	7811200425 7812210152 7811240001 7811240071 7811240046	7811200413 7811200417 7811200418 7811200421 7811200422	7812080006 7812280342* 7811170232 7811200406 7811200409	7812070301 7812080215 7811130006 7812110222 7812050242*
50~437 50~437 50~437 50~329 50~556	50-437 50-437 50-437 50-437 50-437	50-580 50-302 50-302 50-329 50-329	50-445 50-445 50-445 50-321 50-445	50-286 50-269 50-346 50-382 50-556	50-70 50-338 50-267 50-335 50-286	50-255 50-522 50-70 50-338 50-338	50-338 50-70 50-70 50-338 50-338	50-265 50-400 50-424 50-70 50-50B	50-339 50-259 50-261 50-261 50-250	50-269 50-338 50-269 50-348 50-250	50-250 50-250 50-348 50-280 50-280	50-348 50-324 50-335 50-302 50-338	50-335 50-250 50-369 50-269 50-302	50-280 50-250 50-324 50-259 50-321	50-261 50-13 50-259 50-260 50-250
A A G O	A A A	H G G G	0 0 0 0	R R G G	0 0 R B	0	0	9	G G G G	0 0 0 0	9 0 0 0	P G G G	P P P	0 0 P P	0 0 0
TOTH, A. D. TOURTELLOTTE, J	TOLLIBON A. C. TOMONTO, J. R.	TOLLIBON A. C.	TOLLIBON A. C.	TOLLIBON A. C.	TOLLIBON, A. C.	TOBIN, P. A. TOBIN, P. A. TOBIN, P. A. TOBIN, P. A. TODD, G. A. TODD, M. A.	TILLY, D. D. TOALBTON, A. TOALBTON, A. TOALBTON, A. TOALBTON, A.	Tillinghabt, J. Tillinghabt, J. Tillinghabt, J. Tillinghabt, J. Tillinghabt, J. Tillinghabt, J.	TILLINGHABT, J. TILLINGHABT, J. TILLINGHABT, J. TILLINGHABT, J. TILLINGHABT, J.	THRABH, C. Q. TIBBITTS, D. L. TIEDKE, J. H. TIERNEY, F. P. TIETZ, Q.	Thornburg, H. D. Thrailkill, K. Thrabh, C. Q. Thrabh, C. Q. Thrabh, C. Q. Thrabh, C. Q.	THOMBEN, F. T. THOMBEN, F. T. THONUB, L. H. THONUB, L. THONUB, L. THONNBURO, H.	THOMPSON G. A. THOMPSON G. THOMPSON D. O. THOMSEN, F. T. THOMSEN, F. T.	THOMAB, E. 8. THOMAB, E. B. THOMAB, E. B. THOMAB, E. B. THOMPBON, C. R.	THOMAS. E. B. THOMAS. E. B. THOMAS. R. D. THOMAS. C. D. THOMAS. C.
7811140249 7811140280 7811170299 7812120026 7810240013	7812210192 7812210222 7812270292 7812270303 7812140152	7812070181 7812080130 7812200199 7812200201 7812210185	7811140092 7811140133 7812180333 7812070217 7812070148	7810310149 7810310229 7811090197 7811160141 7811160144	7810100032 7810100053 7810130181 7810130154 7810130162	7911280239 7811280244 7812200219 7812010182 7812200251	7812270251 7810200057 7810200146 7810230074 7811070100	781127024) 7812260196 7812270176 7812270177 7812270179	7810230242 7811030103 7810310090 7810310204 7811210260	7812120224 7810270140 781102007; 781205017; 7811240204	781013018; 781108003; 781013019; 781211023; 781207003;	781107035 781213022 781201009 781114026 781205001	781102031 781204000 781228032 781019019 781030010	781121029 781124010 781205034 781226020 781127016	781027038 781027040 781127009 781102041 781113032

:

•

TOURTELLOTTE, J. TOURTELLOTTE, J. TOURTELLOTTE, J. TOURTELLOTTE, J. TOWER, J.	7810300082 7811060058 7811100014 7812140373 7810110205*	50-275 50-275 50-276 50-275 50-70	0 0 0 P	UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E.	7810110231* 7811030168* 7810230052* 7810240071* 7810120075	50-250 50-250 50-335 50-250 50-250	0 0 0 F	UTLEY, E.E. UTLEY, E.E. UTLEY, E.E. UTLEY, E.E. UTLEY, E.E.	7810110108 7810130122 7810130143 7810240127 7810260249	\$0-261 \$0-324 \$0-324 \$0-324 \$0-324
TOWER, J. TRAINA, P. J. TRAINA, P. J. TRAINA, P. J. TRAMMELL, C. M.	7810110203* 7812280026* 7812010243 7812280040* 7810120120	50-70 50-250 50-390 50-250 50-344	Р Р А Р	UHRIO, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E.	7810110121 7810240075# 7810200252 7810230329 7810200188	50-335 50-230 50-335 50-335 50-250	P G G G	UTLEY, E.E. UTLEY, E.E. UTLEY, E.E. UTLEY, E.E.	7810270147 7810270111 7810310122 7811070109 7811160135	50-261 50-324 50-261 50-324 50-324
TRAMMELL C. M TRAMPLEABURE, L. TRAXLER, D. V. TRAXLER, D. V. TREBY, S. A.	7812160009 7810140100 7810240150* 7811090124* 7810120019	50-344 50-70 50-10 50-10 50-70	P G S G	UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E.	7810110077 7810120022 7810110159 7810110123 7810120028	50-335 50-250 50-250 50-251 50-250	6 6 6 6	UTLEY, E. E. UTLEY, E. E. UTLEY, E. E. UTLEY, E. E.	7811170127 7812110133 7812130115 7812270192 7812270207	30-261 30-261 50-324 50-324 50-324
TREBY, 8. A.	7810230218 7811060167 7811080029 7811200137 7812040371	50-338 50-344 50-275 50-338 50-338	0 0 0 F	UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E.	7810180115 7810230140 7810300107 7810170191# 7810200045	50-335 50-250 50-250 50-250 50-250	J J P P	VAHRENWALD.J. VAHRENWALD.J. VALENTINE.P.C. VALENTINE.P.C. VALENTINE.P.C.	7810170235# 7811240240# 7811010324 7810300008 7811070358	50-254 50-254 50-275 50-275 50-275
TREBY, B. A. TROFFER, Q. J.	7812050342 7812130079 7812280195 7812270114 7810240119	50-338 50-522 50-395 50-320 50-287	0 0 0 P	UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. UHRIO, R.E.	7610240066 7810270182 7811070242 7611100083* 7811030226	50-399 50-250 50-335 50-250 50-335	A P 8 0 0	VALENTINE, P. C. VALLADE, B. VALLIBH, E. J. VALLIBH, E. J. VALLIBH, E. J.	7812180309 7810310309* 7812070030* 7812280315* 7812060362*	50-275 50-346 50-364 50-395 50-389
TROFFER. 9. J. TROFFER. 9. J. TROFFER. 9. J. TROSTEN. L. M. TROUP, 9. L.	7811140103 7811160145 7812290129 7812260014 7811130049*	50-289 50-289 50-289 50-247 50-259	P P P	UHRIO, R. E. UHRIO, R. E. UHRIO, R. E. UHRIO, R. E. UHRIO, R. E.	7811070309 7811240007* 7810316002 7810310121 7812010043	50-250 50-335 50-335 50-250 50-250	0 F F 0	VALLISH.E.J. VALORE,C. VAN ART.A.E. VAN BRUNT,E.E. VAN BRUNT,E.E.	7812040175* 7811280089 7810300204 7810310294* 7810290056	50-393 50-437 50-409 50-526 50-392
TROUP.O.L. TROUP.O.L. TROUP.O.L. TROUP.O.L. TROUP.O.L. TROWBRIDDE.O.F.	7810230036* 7811170245* 7812060033* 7812210155* 7810130228	50-369 50-324 50-257 50-324 50-266	G G G	UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E.	7812010119 * 7811040093 7811070144 7811070180 7811210188	50-250 50-335 50-250 50-250 50-250	Q P t P Q	VAN BRUNT, E. E. VAN BRUNT, E. E. VAN BRUNT, E. E. VAN BRUNT, E. E. VAN BRUNT, E. E.	7810310288* 7810310345* 7810180071 7811040087 7810310140	50-528 50-528 50-592 50-592 50-592
TROWBRIDGE, O. F. TROWBRIDGE, O. F. TROWBRIDGE, G. F. TROWBRIDGE, G. F. TROWBRIDGE, O. F. TROWBRIDGE, O. F.	7810200034 7810230326 7812010316 7812210456 7812280079	50-320 50-266 50-400 50-320 50-400	• • •	UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E.	7812010128+ 7811130221 7811140219 7811160107 78111220002	50-250 50-250 50-335 50-335 50-335	а Р Р Q	VAN BRUNT, E. E. VAN BRUNT, E. E. VAN BRUNT, E. E. VAN BRUNT, E. E. VAN BRUNT, E. E.	7811090086 7811290190 7812210132 7812210114* 7812110126	50-592 50-592 50-592 50-528 50-528
Trubatch 8. L. Trubatch 8. L. Trubatch 8. L. Trzyna, 9. Trzyna, 9.	7812110224 7812110226 7812110228 7810170211* 7811240206*	50-247 50-247 50-247 50-304 50-295	С С В В	UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E.	7811240025 7811140139 7811290320 7811300004* 7811310338	50-250 50-250 50-369 50-335 50-250	9 9 9 9 P	VAN BRUNT, E. E. VAN BICKEL J. VAN BICKEL, J. VAN BICKEL, J. VAN BICKEL, J.	7812190071 7810200063* 7811210394* 7811280206* 7812190139*	50-528 50-331 50-331 50-331 50-331
Trzyna, q. Turbak, m. 8. Turbak, m. 8. Turbak, m. 8. Turbak, m. 8.	7812210219* 7810100027 7810100078 7810200084 7810240158	50-295 50-237 50-10 50-10 50-10	명 무 유 P	UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E. UHRIG.R.E.	7812010100 7811210327 7811210328 7811240207 7811270229	50-250 50-335 50-335 50-335 50-335	G P P P	VANDEL, T. E. VANDENBURGH, D. VANGENBURGH, D. VANDENBURGH, D. VANDENBURGH, D. VANDENBURGH, D.	7811010057* 7810110177 7810140135 7810260140 7811020247	50-358 50-29 50-271 50-29 50-29
Turbak, M. B. Turbak, M. B. Turbak, M. B. Turbak, M. B. Turbak, M. B.	7810310093 7810260153 7811060120 7811140105 7811140099	50-10 50-10 50-254 50-237 50-10	G P G P R	UHRIO, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E.	7812050240 7811270161 7811260228 7812060356 7812180316#	50-250 50-250 50-250 50-369 50-335	9 P 9 0	VANDENBURGH, D. VANDENBURGH, D. VANDENBURGH, D. VANDENBURGH, D. VANDENBURGH, D.	7811140224 7811140190 7811240167 7811240238 7811290243	50-271 50-29 50-29 50-29 50-309
TURBAK: M. B. TURBAK: M. B. TURBAK: M. B. TURBAK: M. B. TURBAK: M. B.	7811210257 7812050107 7811270158 7811280244 7812120155	50-237 50-10 50-10 50-237 50-10	Р Р Р Р	UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E. UHRIG, R.E.	7819270275# 7819140195 7819280339# 7819180239# 7819190145	50-335 50-335 50-250 50-250 50-367	P G G A	VANDENBURGH, D. VANDENBURGH, D. VANDENBURGH, D. VANDEL, T. E. VANDQORN, P. K.	7811290255 7812040234 7812090116 7812290247* 7811080158*	50-29 50-29 50-29 50-441 50-395
TURBAK, M. B. TURBAK, M. B. TURBAK, M. B. TURBAK, M. B. TURDERA, J. L.	7812120070 7812220093 7812200219 7812270327 7812110273*	50-237 50-237 50-254 50-10 50-482	P P P A	UMRIO, R.E. UMRIO, R.E. UMRIO, R.E. UMRIO, R.E. UMRIO, R.E.	7812170235 7812210138 7812280017 7812140146 7812140150	50~250 50~335 50~250 50~251 50~250	0 9 P P	VANDOORN, P. K. VANDOORN, P. K. VANDOORN, P. K. VANDOORN, P. K. VANDOORN, P. K.	7811090302* 7812050307* 7812180343* 7812270128* 7811270150*	50-438 50-327 50-400 50-327 50-331
TURI, G. TURI, G. TURNER, E. A. TURNER, E. A. TURNER, E. A.	7811220060* 7811220068* 7810300088 7811020387* 7810120024	50-549 50-549 50-498 50-498 50-498	Т Т А В К	UMRIG, R.E. UMRIG, R.E. UMRIG, R.E. UMRIG, R.E. UMRIG, R.E.	7812160136 7812210046 7812210196 7812270190 7812270267	50-250 50-250 50-251 50-250 50-335	9 P F P	VANTHIEL, M. VARELA, A. A. VARELA, A. A. VARQA, B. A. VARQA, B. A.	7811020033 7812120246* 7811300347* 7810140083 7810110211	50-70 50-363 50-412 50-390 50-556
TURNER; E. A. TURNER; E. A. TURNER; E. A. TURNER; E. A. TURNER; E. A.	7811020393* 7811170090* 7811010144 7811090106 7811300382*	50-498 50-466 50-498 50-498 50-498	0 A 8 0	UHRIGIR.E. UHRIGIR.E. UHRIGIR.E. UHRIGIR.E. UHRIGIR.E.	7012890147 7012270195 7012270187 7012260139 7012270221	50-335 50-250 50-250 50-250 50-250	P P P	VARQA, B. A. VARQA, B. A. VARQA, B. A. VARQA, S. A. VARQA, B. A.	7810140079 7810140086 7810230063 7810240213 7811010342	30-443 30-413 30-336 30-329 50-320
TURNER, E.A. TURNER, E.A. TURNER, E.A. TURNER, E.A. TURNER, E.A. TURNER, E.A.	7612130006 7611160131 7611300216 7611240114 7612190147	50-975 50-498 50-498 50-498 50-498	e B C A	ULLRICH, M. T. ULLRICH, M. T. ULLRICH, M. T. UPTHEGROVE, H. R. UPTHEGROVE, H. R.	7811080094 7811140886 7811280470 7810110167 7811090082	50-277 50-278 50-278 50-112 50-112	8 8 8	VARQA, S.A. VARQA, S.A. VARQA, S.A. VARQA, S.A. VARQA, S.A.	7810300340 7811010055# 7811010068# 7810310364 7811140261#	50-556 50-414 50-414 50-327 50-410
TURNER, E. A. TUTHILL, S. J. UGOLINI, D. J. UHRIG, R. E. UHRIG, R. E.	7812280151 7810240104 7811240198 7810260007 7810260070	50-466 50-331 50-295 50-250 50-389	B P 8 Q Q	URBAN, J. R. URBAN, J. R. UTLEY, E. E. UTLEY, E. E. UTLEY, E. E.	7812040032 7812140209 7811220180* 7811220177 7810110110	50-346 50-346 50-325 50-325 50-324	M P P	Varga, B.A. Varga, B.A. Varga, B.A. Varga, B.A. Varga, B.A.	7611140266# 7611150109# 7611080249 7611130055 7611140059	50-410 50-329 50-466 50-556 50-329

WARD 1	AUTHOR	ACCEBBION REAMUN	SUBJECT CATEODRY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY
WARDER			60-4D1 A	HALLACE E O	7910200149	90-710 0	UADEMBRIERO. D	7010200170	50-247
WARDLE A									
WARLA S. A.									
WARDLE A. 781170020 90-277 A WALACT J. 78117001 90-207 P WARDLE A. 78117002 90-207 P WARDLE A. 8 P W									
WARDER A 2011 100701 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-1			50-572 A	WALLACE, J. J.	7811140110*	50-305 R	warembourg, D	7810270228	50-267
WARDER A 2011 100701 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-101 100-1			4		20.000000				
WASHALD 1									
WASHALD 1									
Aug. Aug. Aug. Aug. Aug. P. P. P. P. P. P. P.									
MASS, B. A. 7811210100 50-30- A MASS, P. 7812200007 50-30- 0 MASSEMBRIDE, D. 7811200000 50-30- A MASS, B. A. 7812100007 50-30- A MASS, B. A. 781220000 50-30- B MASS, B. A. 781220000 50-30- A MASS, B. A. 781220000 50-30- B MASS, B. A. 78122000									
WARDER PART	VACCOUNT D. III	70.2010215							
VAMPALLO B 781120021 50-39	VARQA. B A	7812110100							
WARDELLO D 781101079 50-357 A WATERLO N, 781110799 70-320 C WARDELLO D, 7811210710 50-257	VARCA, S. A								
WARDELLO B 78119091 50-307 A MALTON D A 7811909091 50-305 D MARCHON D 7811300197 50-267									
WASHALD P. TRIBOTORY P. WASHALD P. WA									
MARCHELLO D. 1 1915/20072 20-277 A MARCHELLO D. 1 7915/20072 20-272 P MARCHELLO D. 1 7915/20072 20-272 20-272 P MARCHELLO D. 1 7915/20072 20-272 P MARCHELLO D. 2	VARUA. B A	\B18100341	JU-367 II	WHE TOWN G. H.	10111205024	30-334 G	MAREI POOR O'D	7612130190	30-207
WASHALLD P. TRIPLICOTE SO-207 A MARCHET IV. TRIPLICOTE SO-207 P MARCHET IV. TRIPLICOTE SO-207 TRIPLICO	UARCA. S A	7612140242	50-327 A	WALTON, Q. A.	7812290220#	50-334 G	WAREMBOURG, D.	7812130176	50-267
MARSALL D 1			50-397 A		7810110075*		WAREMBOURG, D.	7812130179*	
WASSALL D B									
VAMERICE D									
MARIALLO D	VASSALLO, D. B	7811060100	30-356	WARDACH, I. V.	/811260084*	20-5å b	MAKEMBUUKG, D.	7612270201	50-267
MARIALLO D 1	UARRALL C. O. O.	7011030104	30-346 P	WAMRACH. T U	78130400306	50-204 8	MARKE.C R	70117104704	50-556
VARRALLO D 701120001 50-300 A MARGEN R E 7810170202 50-300 E MARGEN R E 7810170202 S MARGEN R E 7810									
WASHILLE D									
MARCHAILLE D. B. 781128001 50-270 A. MADDEL R. E. 7810170007 50-200 B. MARCHAIR, F. 7810140004 50-200 WASHALLE D. B. 7811280007 50-201 B. MARCHAIR, F. 7810170007 50-200 B. MARCHAIR, F. 7810170007 B. MARCHAIR, F. 7810170007 50-200 B. MARCHAIR, F									
WASHALLO D. B. 7911280016 80-495 A	VABSALLO D. B	7812070036	50-275 E	WANDKE, N. E.	7810170181	50-295 8	WARNICK, R. F.	7812060128#	50-305
WASHALLO D. B. 7911280016 80-495 A		#A	EA 222 -	HANDUE	90	**			
WASHALD D 7011200109					7810170207				
MARRICLO D. 1									
WASSALLO D. B. 79112000179 70-720 A WASSALLO D. B. 79112001709 70-720 A WASSALLO D. B. 791120010 79-720 A									
VARRALLO D. 1. 781120007									
WASSALLO D. B. 7811200102 20-373 A MANDRÉ N. E. 78101702784 50-293 8 MATRORD.N. L. 7811120250 50-261 A WASSALLO D. B. 7811201020 50-394 A WASSALLO D. B. 7811201012 50-394 A WASSALLO D. B. 7811201012 50-394 A WASSALLO D. B. 7811201012 50-394 A WASSALLO D. B. 781120113 50-395 A WASSALLO D. B. 781120						JU JUT 0	WWW. CONTINUE.		20-300
WASHALLD D. B. 7811900101 95-97 A MANDELN R. E. 78101702924 50-929 B MATFORD H. L. 7811010205 50-261 WASHALD D. B. 78110010205 50-261 A MANDELN R. E. 7810170214 50-929 B MATFORD H. L. 7811010205 50-261 A MANDELN R. E. 7810170214 50-929 B MATFORD H. L. 7811010205 50-261 A MANDELN R. E. 7810170214 50-929 B MATFORD H. L. 7811010205 50-261 A MANDELN R. E. 7810170214 50-929 B MATFORD H. L. 7811010205 50-261 A MANDELN R. E. 7810170213 50-929 B MATFORD H. L. 7811010215 50-920 A MANDELN R. E. 7810170213 50-929 B MATFORD H. L. 7811010219 50-920 A MANDELN R. E. 7810170213 50-929 B MATFORD H. E. 7811010219 50-920 A MANDELN R. E. 7810170213 50-929 B MATFORD H. E. 781102019 50-920 A MANDELN R. E. 7811010211 50-920 B MATFORD H. E. 781102019 50-920 B MATFORD H. E. 7					7810170225	50-295 8	WARNICK R. F.	7812290032=	50-266
VASSALLO D 8	VASSALLO, D. B.	7811280101		WANDKE, N. E.	7810170228*	50~295 8	HATFORD, M. L.		
WASSALLE D. 8	VASSALLO D. B.				7810170214	50-295 8	WATFORD, M. L.	7B11160120*	50-261
WASHALD D 7911260116 20 - 209 A									
WARRIALD D B	VASBALLO D. B.	7811280113	50-361 A	WANDKE, N. E.	7810170241	30-295 8	WATKINS,R. V.	7810250046	50-502
WARRALLO B. 781128012 50-397 A WANDEL R. 781127023 50-290 B WATKIRSLE R. 781127023 50-301 WATKIRSLE R. 781127023	UARRAIF OLD B	7811280114	40-295 A	HANNER, N. S.	7010170710	50-204 6	HATHING W C	1011140170	60 340
VASBALLO D. 79112010142 30-391 A MANDRÉ, R. 7911201077 30-30-30 B MATKINS, R. V. 79112000007 30-30-30 B VASBALLO D. 79112010142 30-391 A MANDRÉ, R. 7911201077 30-30-31 B MATKINS, R. V. 7911201079 30-31 B VASBALLO D. 79112010142 30-391 A MANDRÉ, R. 7911201079 30-30-30 B MATKINS, R. V. 7911201079 30-31 B VASBALLO D. 79112010149 30-398 A MANDRÉ, R. F. 7911201000 50-392 B MATTH, J. 7911201079 30-31 B VASBALLO D. 79112010149 30-398 A MANDRÉ, R. F. 7911201010 50-390 B MATTH, J. 7911201079 30-31 B VASBALLO D. 7911200004 30-399 P MANDRÉ, R. F. 7911201011 30-390 B MATTH, R. J. 7911200079 30-394 B MATTH, J. 7911200079 30-394 B MATTH, R. J. 7911200079 30-394 B MA				WANDKE N F					
VARSALLO B. 7812010342 50-38 A MANDRÉ, R. 7811240127 50-290 B MATRING, R. 78112101742 50-316 VARSALLO B. 78121010142 50-316 A MANDRÉ, R. 7811240127 50-290 B MATRING, R. 78112101743 50-316 VARSALLO B. 7812010149 50-328 A MANDRÉ, R. 7811240121 50-290 B MATRING, R. 7811240121 50-290 B MAT						50-304 B			
VASSALLO D. 8 79110100145 50-141 A MADNE, N. 7911240177 50-292 S MATRINS, R.V. 7911280077 50-292 VASSALLO P. 8 79110100145 50-140 A MADNE, N. 7911240112 50-292 S MATRIN, J. 7911200709 70-292 VASSALLO D. 8 79110900000 50-244 A MADNE, N. 7911240112 50-290 S MATTI, J. 79112200709 70-294 VASSALLO D. 79110900001 50-297 A MADNE, N. E. 7911240112 50-290 S MATTI, J. 79112200709 70-294 VASSALLO D. 79110900001 50-297 A MADNE, N. E. 79112401145 30-290 S MATTI, J. 7911240011 30-290 A MATTI, J. 7911240011 30-290 A MATTI, J. 7911240011 30-290 B MATTI, N. R. 7911240011 30-290 A MATTI, M. 7911240011 30-290 B MATTI, N. R. 7911240011 30-290 B MATTI, M. 791124011 30-290 B MATTI, M. 79112401			50-498 A						
VASBALLO D. B. 781200349 50-359 A. MANDER, R. 7811240212 50-099 B. MATT. J. J. 7811220070 50-354 A. MANDER, R. F. 7811240218 50-099 B. MATT. J. J. 7811220070 50-354 A. MANDER, R. F. 7811240218 50-090 B. MATT. J. J. 7811220070 50-357 VASBALLO D. 781120004 50-090 P. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120011 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 7811220070 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-	VASSALLO D. R.	7B12010342	50-341 A						
VASBALLO D. B. 781200349 50-359 A. MANDER, R. 7811240212 50-099 B. MATT. J. J. 7811220070 50-354 A. MANDER, R. F. 7811240218 50-099 B. MATT. J. J. 7811220070 50-354 A. MANDER, R. F. 7811240218 50-090 B. MATT. J. J. 7811220070 50-357 VASBALLO D. 781120004 50-090 P. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120011 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 7811220070 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-090 A. MANDER, R. F. 7811240221 50-090 B. MATT. J. J. 781120041 50-									
VASSALLO D 5, 7812030060 50-268 P MANNER, N. E. 7811240018 50-204 S MATTS, A.R. 7811200411 50-295 VASSALLO D 5, 7812050084 50-268 P MANNER, N. E. 7811240018 50-295 S MATTS, A.R. 7811200411 50-295 VASSALLO D 5, 7812050084 50-280 P MANNER, N. E. 7811240195 50-204 S MATTS, A.R. 7811200411 50-295 VASSALLO D 781210011 50-232 P MANNER, N. E. 7811240195 50-204 S MATTS, A.R. 7811200013 50-295 P MANNER, N. E. 7811240195 50-204 S MATTS, A.R. 7811200013 50-295 P MANNER, N. E. 7811240195 50-204 S MEBB-L, D. 7811200003 50-295 P MANNER, N. E. 7811240195 50-204 S MEBB-L, D. 7811200003 50-295 S MEDITER, E. H. 781100012 50-205 P MANNER, N. E. 7811240207 50-295 S MEDITER, E. H. 781100203 50-295 S MEDITER, S. H. 7811010142 50-207 S MEDITER, S. H. 7811010143 50-207 S MEDITER, S. H. 78110100143 50-207 S MEDITER, S. H. 781101001									
VASBALLD D B									
VASHALLO D. 9781205094 90-368 P MANDKE, N. E. 7811240145 50-304 8 MATTS, N. J. 7812150034 50-120 VASHALLO D. 978120011 50-203 0 MANDKE, N. E. 7811240197 50-304 8 MESS, J. D. 781120034 50-433 VASHALLO D. 781120039 50-267 8 MANDKE, N. E. 7811240207 50-304 8 MESS, J. D. 781120034 50-433 VASHALLO D. 781120039 50-267 8 MANDKE, N. E. 7811240207 50-279 8 MEDIS, H. 78112210173 50-237 VELLO, D. J. 781102039 50-267 8 MANDKE, N. E. 7811240207 50-279 8 MEDIS, H. 78112210173 50-237 VELLO, D. J. 781120039 50-267 8 MANDKE, N. E. 7811240207 50-279 8 MEDIS, H. 78112101142 50-487 WELLO, D. J. 781120039 50-287 8 MEDIS, H. 78112101142 50-487 WELLO, D. J. 7811240207 50-279 8 MEDIS, H. 78112101142 50-487 WELLO, D. J. 7811240207 50-279 8 MEDIS, H. 78112101142 50-487 WELLO, D. J. 7811240207 50-279 8 MEDIS, H. 78112101142 50-487 WELLO, D. J. 7811240207 50-287 8 MEDIS, H. 78112101142 50-487 WELLO, D. J. 7811240207 50-287 8 MEDIS, H. 7811210144 50-487 WELLO, D. J. 7811240207 50-287 8 MEDIS, H. 7811240207 50-287 8 WELLO, D. J. 7811240207 50-287 8 WELLO, D. J. 7811240207 50-289 8 WELLO, J. 78									
V-SBALLO D. 8. 7812800349 50-2329 P MANDKE N. 7811010141 50-295 R MESB J. D. 78110701432 50-240									
WASALLO D		, 4,200004		manufic L.	1011M40140	30-304 8	MATTELET. U.	1818190034	20-133
WARDAR D. P. WARDAR D. P. WARDAR D. P. WARDAR D. P. P. P. P. P. P. P.	VASSALLO, D. B.	7812280343*	50-329 9	WANDKE, N	7811010141	50~295 R	WESS, J. D.	7811070143*	50-443
VEILO, J. 7811090319 50-269 8 MADNE, N. E. 7811240203 50-299 8 METINER, R. 7912210193 50-207 CANDELEDBY. J. 78101000219 50-518 0 MADNE, N. E. 7811240203 50-299 8 METINER, R. 79101000219 50-207 CANDELEDBY. H. 781101000219 50-200 0 MADNE, N. E. 7811240172 50-304 8 METISSA, R. 7810000029 50-308 WERDLY. C. V. 7811240172 50-304 8 METISSA, R. 7810000029 50-308 WERDLY. C. V. 7811240172 50-304 8 METISSA, R. 7810000039 50-308 WERDLY. C. V. 7811240172 50-304 8 METISSA, R. 7810000039 50-308 WERDLY. C. V. 7811240172 50-304 8 METISSA, R. 7810000039 50-308 WERDLY. C. V. 7811240172 50-304 8 METISSA, R. 7810000039 50-308 WERDLY. C. V. 7812140184 50-407 MADNE, N. E. 7812110187 30-209 8 METISSA, R. 7810200039 50-308 WERDLY. C. V. 7812140184 50-407 MADNE, N. E. 7812110187 30-209 8 METISSA, R. 7810200039 50-308 WERSLAND, R. 7812140184 50-408 MADNE, N. E. 7812110187 30-209 8 METISSA, R. 7812280158 50-304 MADNE, N. E. 7812110187 30-209 8 METISSA, R. 7812280158 50-304 MADNE, N. E. 7812110173 30-209 8 METISSA, R. 7812280158 50-304 MADNE, N. E. 7812110175 30-209 8 METISSA, R. 7812290144 50-304 MADNE, N. E. 7812110179 30-209 8 METISSA, R. 7812290145 50-304 MADNE, N. E. 7812110179 30-209 8 METISSA, R. 7812290154 50-304 MADNE, N. E. 7812110179 30-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 7812110179 30-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 7812210179 30-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 7812210179 30-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 7812210179 30-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 7812210179 30-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 7812210179 30-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 7812210179 30-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 7812210179 30-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 7812210179 30-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 7812210179 30-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 781221020149 50-209 8 METISSA, R. 78112701076 50-304 MADNE, N. E. 78122102024 50-209 8 METISSA, R. 78112701076 50-304		7812130011							
VENDERY.E. H. 78110703209 50-318 0 MANDRE.N.E. 7811240133 50-395 8 MEIBBARD.A.J. 7811030031 50-320 0 MANDRE.N.E. 7811240137 50-304 8 MEIBBARD.A.J. 7810300037 50-332 0 MANDRE.N.E. 78121010147 50-395 8 MEIBBARD.A.J. 7810300037 50-332 0 MANDRE.N.E. 7812110147 50-395 8 MEIBBARD.A.J. 7810300037 50-332 0 MANDRE.N.E. 7812110147 50-395 8 MEIBB.E.R. 7810300037 50-332 0 MANDRE.N.E. 7812110147 50-395 8 MEIBB.E.R. 7810300037 50-332 0 MANDRE.N.E. 7812110147 50-395 8 MEIBB.E.R. 7810300037 50-332 0 MANDRE.N.E. 7812110147 50-295 8 MEIBB.E.R. 7810300037 50-332 0 MANDRE.N.E. 7812110147 50-295 8 MEIBB.E.R. 7810300037 50-332 0 MANDRE.N.E. 7812110141 50-295 8 MEIBB.E.R. 7810300037 50-332 0 MANDRE.N.E. 7812110151 50-295 8 MEIBB.E.R. 781030034 50-338 0 MANDRE.N.E. 7812110151 50-295 8 MEIBB.E.R. 781030034 50-338 0 MANDRE.N.E. 7812110151 50-295 8 MEIBB.E.R. 781030034 50-334 MANDRE.N.E. 7812110151 50-295 8 MEIBB.E.R. 7811200044 50-514 MANDRE.N.E. 7812210151 50-295 8 MEIBB.E.R. 7811000304 50-334 MANDRE.N.E. 7812210212 50-295 8 MEIBB.E.R. 781100034 50-334 MANDRE.N.E. 7812210212 50-295 8 MEIBB.E.R. 781100034 50-334 MANDRE.N.E. 781221021 50-295 8 MEIBB.E.R. 781100034 50-334 MANDRE.N.E. 781221021 50-295 8 MEIBB.E.R. 781100034 50-334 MANDRE.N.E. 781120021 50-334 MANDRE.N.E. 781221021 50-295 8 MEIBB.E.R. 781100034 50-295 8 MEIBB.E.R.					7811240227		WEBSTER.E. H		
VERDERY, E. H. 7811070320* 50-250 0 MANDKE, N. E. 7811240135 50-304 8 MEISBARD, A. J. 7812220141 50-230 VERDERY, E. H. 7812101019* 50-250 0 MANDKE, N. E. 781210176 50-304 8 MEISBARD, A. J. 7812200037* 50-338 VERDERY, E. H. 7812102035 50-280 0 MANDKE, N. E. 7812101014 50-295 8 MEISB, E. R. 7810300037* 50-338 VERDERY, E. 7812101015 50-295 8 MEISB, E. R. 7810300037* 50-338 VERDERY, E. 7812101014 50-295 8 MEISB, E. R. 7810300038* 50-238 MEISB, E. R. 781030038* 50-238 MEISB, E. R. 781030038* 50-234 MEISB, E. R. 781030038* 50-244 MANDKE, N. E. 7812110179 50-295 8 MEISB, E. R. 781020048* 50-244 MANDKE, N. E. 7812110179 50-295 8 MEISB, E. R. 7810200039 50-244 MANDKE, N. E. 7812110179 50-295 8 MEISB, E. R. 7810200039 50-244 MANDKE, N. E. 7812110179 50-295 8 MEISB, E. R. 781020034* 50-244 MANDKE, N. E. 7812110179 50-295 8 MEISB, E. R. 781020034* 50-234 MOIST, N. H. 7811100034* 50-245 9 MANDKE, N. E. 7812210179 50-295 8 MEISB, M. R. 7811100034* 50-245 MANDKE, N. E. 781221027 50-295 8 MEISB, E. R. 7811100034* 50-234 MANDKE, N. E. 781221027 50-295 8 MEISB, E. R. 7811100034* 50-234 MANDKE, N. E. 781221027 50-295 8 MEISB, E. R. 7811100034* 50-234 MANDKE, N. E. 781221027 50-295 8 MEISB, M. R. 7811100034* 50-234 MANDKE, N. E. 781221027 50-295 8 MEISB, M. R. 7811100034* 50-234 MANDKE, N. E. 781221027 50-295 8 MEISB, M. R. 7811100034* 50-234 MANDKE, N. E. 781221027 50-295 8 MEISB, M. R. 7811100034* 50-234 MANDKE, N. E. 781221027 50-295 8 MEISB, M. R. 7811100034* 50-234 MANDKE, N. E. 7812210227 50-295 8 MEISB, M. R. 7811100034* 50-234 MANDKE, N. E. 7812210234 50-									
VERDERY-E. M. 78120101079 50-295	AFUN CEEDRA'S	7811080219	50-518	WANDKE, N. E.	7811240207	50~295 8	WEIMER, R. H.	7810110142	50-498
VERDERY-E. M. 78120101079 50-295	UFRDERV.E H	7811070320a	50-250 0	HANDER N. C.	7011740178	50.004 0			
VERDUZCO 9. N. 7811200249s 50-280 Q MANDKE, N. E. 7812110124 50-299 B METBB. E. R. 78121000037s 50-238 VEIEV, E. E. 7810100054 50-247 A MANDKE, N. E. 78121101157 30-295 B METBB. E. R. 78102101010 30-2338 VEIEV, E. E. 78121101145 50-447 A MANDKE, N. E. 78121101157 30-295 B METBB. E. R. 7812200138 50-2338 VEIEV, E. E. 78121101157 30-295 B METBB. E. R. 7812200138 50-2338 VEIEV, E. E. 7812110157 30-295 B METBB. E. R. 7812200138 50-2338 VEIEV, E. E. 7812110157 30-295 B METBB. E. R. 7812200138 50-234 VOOT-LDHELL. R. 78101300099 50-221 Q MANDKE, N. E. 7812110157 30-295 B MENER, R. A. 78112701079 50-244 VOOT-LDHELL. R. 78112200999 50-221 Q MANDKE, N. E. 7812110150 30-295 B MENER, M. A. 78112701079 50-244 VOOT-LDHELL. R. 78112200999 50-221 Q MANDKE, N. E. 7812110150 30-295 B MENER, M. A. 78112701079 50-244 VOOT-LDHELL. R. 78112000999 50-221 Q MANDKE, N. E. 7812110150 30-295 B MENER, M. A. 78110100034 50-344 VOOT-LDHELL. R. 78112000999 50-221 Q MANDKE, N. E. 7812110179 50-295 B MENER, M. J. A. 78110100034 50-344 VOOT-LDHELL. R. 78112000999 50-224 Q MANDKE, N. E. 7812110179 50-295 B MENER, M. J. A. 78110100034 50-345 VOOT-LDHELL. R. 781100034 50-345 Q MANDKE, N. E. 7812210179 50-295 B MENER, M. J. A. 7811010034 50-334 VOOT-LDHELL. R. 781100034 50-345 Q MANDKE, N. E. 7812210179 50-295 B MENER, M. J. A. 7811010034 50-334 VOOT-LDHELL. R. 781100034 50-345 Q MANDKE, N. E. 7812210214 50-295 B MERL M. J. A. 7811010034 50-334 VOOT-LDHELL. R. 781100035 50-347 Q MANDKE, N. E. 7812210214 50-295 B MERL M. J. A. 781100034 50-334 VOOT-LDHELL. R. 781100035 50-347 Q MANDKE, N. E. 7812210214 50-295 B MERL M. J. A. 7811100034 50-334 VOOT-LDHELL. R. 781100035 50-347 Q MANDKE, N. E. 7812210214 50-295 B MERL M. J. A. 7811100036 50-345 Q MANDKE, N. E. 7812210149 50-344 Q MANDK									
VEREY. E. 7812101016 50-437 A MADKE, R. E. 781210161 50-295 B MEIBB.E.R. 7810200036 50-232 VISSCHER, H. P. 7812101020 50-437 A MADKE, R. E. 781210161 50-238 VISSCHER, H. P. 7812101020 50-437 A MADKE, R. E. 781210161 50-295 B MEIBB.E.R. 7812200158 50-200 VISSCHER, H. P. 7812101030 50-234 A MADKE, R. E. 781210161 50-295 B MEILB.E.R. 7812200158 50-200 VISSCHER, H. P. 781210103018 50-234 A MADKE, R. E. 781210170 50-295 B MEILB.E.R. 7811290046 50-314 VISSCHER, H. P. 781210170 50-295 B MEILB.E.R. 7811290046 50-314 MADKE, R. E. 781210170 50-295 B MEILB.E.R. 7811210100030 50-314 MADKE, R. E. 78121010170 50-295 B MEILB.E.R. 7811210100030 50-314 MADKE, R. E. 78121010170 50-295 B MEILB.E.R. 7811210100030 50-314 MADKE, R. E. 78121010170 50-295 B MERLINO, J. A. 7810100030 50-324 MADKE, R. E. 7812210170 50-295 B MERLINO, J. A. 7810100030 50-324 MADKE, R. E. 7812210217 50-295 B MERLINO, J. A. 7810100030 50-324 MADKE, R. E. 7812210217 50-295 B MERLINO, J. A. 7810100034 50-325 MADKE, R. E. 7812210217 50-295 B MERLINO, J. A. 7810100034 50-325 MADKE, R. E. 7812210217 50-295 B MERLINO, J. A. 7811130018 50-346 MADKE, R. E. 7812210217 50-295 B MERLINO, J. A. 7811130018 50-346 MADKE, R. E. 7812210217 50-295 B MERLINO, J. A. 7811130018 50-346 MADKE, R. E. 7812210217 50-295 B MERLINO, J. A. 7811130018 50-346 MADKE, R. E. 7812210217 50-295 B MERLINO, J. A. 7811130018 50-334 VISWOKAA. 781120149 50-446 MADKE, R. E. 7812210217 50-344 MADKE, R. E. 7812210179 50-344 MADKE, R. E. 7812210179 50-340 MADKE, R. E. 7812210179 50-3									
VISSCHER, H. B. VISSCH									
VISSCHER, H. B. 7812101205 50-395 A HANDKE, N. E. 7812110161 50-295 B MEIBR, E. 7812200198 50-314 7811270045 50-304 7811270075 B MELLER, R. A. 7811270175 50-304 7811270075 50-314 7811270175 50-325 B MERLING, J. A. 7811270175 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314 7810100314	VEZEY, E. E.	7B12110116+	50-447 A						
VORT-LOBELLE 7810130091 90-364 0 MANDRE N E 791210131 90-299 8 MELLER R A 7911270107 90-344 VORT-LOBELLE 7810130099 50-321 0 MANDRE N E 791210160 30-295 8 MERLER R A 7911270107 90-344 VORT-LOBELLE 7810130099 50-321 0 MANDRE N E 791210160 30-295 8 MERLEN A 7911270107 90-344 VORT-LOBELLE R 7810130099 50-324 0 MANDRE N E 791210179 30-295 8 MERLEN A 7911270107 90-344 VORT-LOBELLE R 7810130099 50-482 0 MANDRE N E 791210179 30-295 8 MERLEN A 7911270107 90-334 VOIDTH H 7810140028 50-482 0 MANDRE N E 7912210214 50-295 8 MERLEN A 7911030164 50-334 VOIDTH H 7811010305 50-482 0 MANDRE N E 7912210217 50-295 8 MERLEN A 7911130218 50-334 VOLUMEN R J 7911030164 50-345 VOLUMEN R J 7911030164 50-334 VOLUMEN R J 7911030164 50-345 VOLUMEN R J 7911030164 50-345 VOLUMEN R J 7911030164 50-346 WERLEN R J 7911								•	
VORT-LDIELLE. 78101300999 90-221 Q MANDRE.N.E. 7812101070 90-295 B MERLING.J.A. 78112701079 90-244 VORT-LDIELLE. 7811210109 90-295 B MERLING.J.A. 78101000304 90-245 Q MANDRE.N.E. 7812101079 90-295 B MERLING.J.A. 7810100034 90-334 VORT-LDIELLE. 7812101079 90-295 B MERLING.J.A. 7810100034 90-334 VORT-LDIELLE. 7812101079 90-295 B MERLING.J.A. 7810100034 90-334 VORT-LDIELLE. 781210214 90-295 B MERLING.J.A. 7811000104 30-334 VORT-LDIELLE. 781210217 90-304 B MERLING.J.A. 7811000104 30-334 VORT-LDIELLE. 7811010101010101010101010101010101010101		7812010205					WE188, E. R.	7812260158	50-339
VOIDHT.H.H. 78111200999 50-546 MANDKE, N.E. 7812110140 30-295 MERLING, J.A. 7810100034 30-334									
VOIDTLEAN 7811030994 50-424 9 MANDRE, N.E. 7812110179 50-295 8 MERLING, J.A. 7810100034 30-334 VOIDT, M.H. 7811130399 50-546 9 MANDRE, N.E. 7812210217 30-295 8 MERLING, J.A. 7811030164 30-334 VOIDT, M.H. 7811010134 50-346 9 MANDRE, N.E. 7812210217 30-304 8 MERLING, J.A. 7811030164 30-335 VOIDT, M.H. 781116030 50-367 9 MANDRE, N.E. 7812210217 30-304 8 MERLING, J.A. 7811130218 50-334 VOIDT, M.H. 7811003167 50-466 9 MANDRE, N.E. 7812210217 30-304 8 MERLING, J.A. 78111302206 50-334 VOIDT, M.H. 7811020167 50-466 9 MARD, R.E. 7812210213 30-295 8 MERLING, J.A. 7811170214 30-334 VOIDT, M.H. 7811020167 50-466 9 MARD, R.E. 7812210234 30-295 8 MERLING, J.A. 7811170214 30-334 VOIDT, M.H. 7811020167 50-466 9 MARD, R.E. 7811020306 50-373 9 MERLING, J.A. 7811170217 30-334 VOIDT, M.H. 781102018 50-312 9 MARD, R.E. 7811020306 50-333 9 MERLING, J.A. 7811170172 30-334 VOIDT, M.H. 7811160147 30-34 VOIDT, M.H. 7811160147 30-34 VOIDT, M.H. 7811160147 30-34 VOIDT, M.H. 781110018 50-397 9 MARD, R.E. 7811200306 50-282 MERLING, J.A. 7811170224 30-334 VOIDT, M.H. 7811100018 50-397 9 MARD, R.E. 7811200306 50-282 MERLING, J.A. 7811170224 30-334 MACHTER, L.J. 7811200308 50-283 MARD, R.D. 7811200308 50-283 MARD, R.D. 7811200308 50-293 MARD, R.D. 7811200308 50-294 MARD, R.D. 7811200308 50-294 MARD, R.D. 7811200308 50-295 MARD, R.D. 7811200308 50-296 MERLING, J.A. 7812120149 50-334 MACHTER, L.J. 7812120336 50-283 MARD, R.D. 78121200308 50-297 MARD, R.D. 78121200308 50-297 MARD, R.D. 78121200308 50-298 MERLING, J.A. 7812120149 50-334 MACHTER, R.D. 7812120336 50-298 MARD, R.D. 78121200308 50-298 MARD, R.D. 78121200308 50-298 MARD, R.D. 78121200308 50-298 MARD, R.D. 78121200308 50-298 MA				HANDRE N.E.					
VOIGHT, H. H. 7811130399 50-548 Q HANDKE, N. E. 7812110214 50-299 B HERLING, J. A. 781103014 50-334 VOIGT, H. H. 7810140028 50-452 Q HANDKE, N. E. 7812210227 50-293 B HERLING, J. A. 781103014 50-334 VOILEN, R. J. 7811100301 50-344 Q HANDKE, N. E. 7812210217 50-204 B HERLING, J. A. 781103014 50-334 VOILEN, R. J. 781110030 50-367 Q HANDKE, N. E. 7812210217 50-204 B HERLING, J. A. 7811130220 50-334 VOILEN, R. J. 78111202169 50-466 Q HANDKE, N. E. 7812270193 50-106 P HERLING, J. A. 7811130220 50-334 VOILEN, R. J. 7811202169 50-466 Q HAND, J. J. 7811270213 50-409 Q HERLING, J. A. 7811170214 50-334 VOILEN, R. J. 78112021818 50-434 Q HARD, K. D. 7811200223 50-409 Q HERLING, J. A. 7811170219 50-334 VOILEN, R. J. 78112021818 50-438 Q HERLING, J. A. 7811170172 50-334 VOILEN, R. J. 78112021818 50-338 Q HERLING, J. A. 7811170172 50-334 VOILEN, R. J. 781120018 50-394 P HARD, K. D. 78112100221 50-282 S HERLING, J. A. 7811170221 50-334 HARD, M. H. 781120018 50-397 Q HARD, M. H. 7811200300 50-282 S HERLING, J. A. 7811170221 50-334 HARD, M. H. 7811200308 50-331 Q HERLING, J. A. 7812120143 50-334 HARD, M. H. 7811200308 50-331 Q HERLING, J. A. 7812120143 50-334 HARD, M. H. 7811200308 50-282 S HERLING, J. A. 7812120143 50-334 HARD, M. H. 781220036 50-282 P HARD, J. J. 7811200309 50-298 Q HERLING, J. A. 7812120143 50-334 HARD, M. D. 7812200308 50-331 Q HERLING, J. A. 7812120143 50-334 HARD, M. D. 7812200308 50-339 Q HARD, M. D. 7812200308 50-329 Q HARD, M. D. 7812000308 50-329 Q HERLING, J. A. 7812120143 50-334 HARD, M. D. 7812000308 50-329 Q HERLING, J. A. 7812120143 50-334 HARD, M. D. 7812000308 50-329 Q HERLING, J. A. 7812120148 50-334 HARD, M. D. 7812000308 50-329 Q HARD, M. D. 7812000308 50-329 Q HERLING, J. A. 781220036 50-334 HARD, M. D. 7812000308 50-329 Q HERLING, J. A. 781220036 50-334 HARD, M. D. 7812200038 50-339 Q HARD, M. D. 7812200038 50-339 Q HARD, M. D. 7812200038 50-339 Q HARD, M. D.									
VOIDT.H.H. 7810140028 50-452 0 MANDKE, N.E. 7812210227 50-293 8 MERLING, J. A. 7811030164 50-304 VOIDT.H.H. 7811010136 50-364 0 MANDKE, N.E. 7812210217 50-204 8 MERLING, J. A. 7811130218 50-304 VOILEN, R.J. 7811160303 30-367 0 MANDKE, N.E. 7812210217 50-204 8 MERLING, J. A. 7811130218 50-304 VOILEN, R.J. 7811020169 30-466 9 MANDKE, N.E. 7812210217 50-204 8 MERLING, J. A. 7811170214 30-304 VOILEN, R.J. 7811020169 30-466 9 MANDKE, N.E. 7812270193 50-106 P MERLING, J. A. 7811170214 30-304 VOILEN, R.J. 7811020169 50-406 9 MARD, R.D. 7811010039 50-307 0 MERLING, J. A. 7811170172 50-304 VOILEN, R.J. 7811270039 50-312 0 MARD, R.D. 7811300221 50-308 0 MERLING, J. A. 7811170179 50-304 VOILH, R.J. 7811270039 50-304 MARD, R.D. 7811300221 50-304 MERLING, J. A. 7811170179 50-304 VOILH, R.J. 7811270157 50-304 VOILH, R.J. 7811270157 50-304 VOILH, R.J. 7811270157 50-304 MARD, R.J. 7811170215 50-304 VOILH, R.J. 7811270157 50-304 MARD, R.J. 7811170215 50-304 VOILH, R.J. 7811170215 50-304 MARD, R.J. 7811170215 50-304 MERLING, J.A. 7811170216 50-304 VOILH, R.J. 7811170216 50-304 MARD, R.J. 7811170216 50-304 MARD, R.J. 7811170230 50-282 8 MERLING, J.A. 7811170234 50-304 MARD, R.J. 7811270216 50-304 MARD, R.J. 7811270226 MERLING, J.A. 7811270216 50-304 MARD, R.J. 7811270226 50-304 MARD, R.J. 7811270226 50-304 MARD, R.J. 7811270226 MARD, R.J. 7811270226 50-304 MARD, R.J. 7811270226 50-304 MARD, R.J. 7811270226 50-304 MARD, R.J. 7811270236 50-304 MARD, R.J. 7811270236 50-304 MARD, R.J. 7811270236 50-304 MARD, R.J. 7811270236 50-304 MARD, R.J				MANDINE I RE	/BIE1101/7	30-273 8	MERLINGIO. A.	7810100034*	30-334
VOIDT.H.H. 7810140028 50-452 9 MANDKE, N.E. 7812210227 50-295 8 MERLING, J. A. 7811030164 50-354 VOIDT.H.H. 7811010164 50-354 VOIDT.H.H. 7811140030 50-367 9 MANDKE, N.E. 7812210217 50-304 8 MERLING, J. A. 7811130228 50-334 VOMACKA, A. 7811020167 50-466 9 MANDKE, N.E. 7812270193 50-106 P MERLING, J. A. 7811170214 50-334 VOMACKA, A. 781102016** 50-466 9 MARD, K. B. 7812270193 50-106 P MERLING, J. A. 7811170219 50-334 VOMACKA, A. 781020176** 50-466 9 MARD, M. B. 7810240236** 50-498 9 MERLING, J. A. 7811170219 50-334 VOMACKA, A. 781027018** 50-466 9 MARD, M. B. 7810240236** 50-498 9 MERLING, J. A. 7811170172 50-334 VOMACKA, A. 781027018** 50-466 9 MARD, M. B. 7811300221** 50-398 9 MERLING, J. A. 7811170172 50-334 VOMACKA, A. 7811270039** 50-398 9 MERLING, J. A. 7811170172 50-334 VOMACKA, A. 7811270039** 50-398 9 MERLING, J. A. 7811170219 50-394 VOMACKA, A. 7811170219 50-3					7812210214	50~295 8	WERLING, J. A.	7B101000B4	50-334
VOLLER, R. J. 78111030136 50-346 Q MANDKE, N. E. 7812210217 50-304 8 MERLING, J. A. 7811130218 50-334 VOLLER, R. J. 7811020169 50-466 Q MANDKE, N. E. 7812210234 50-295 8 MERLING, J. A. 7811170214 50-334 VOMACKA, A. 7811020176+ 50-466 Q MANDKE, N. E. 7812210236+ 30-295 8 MERLING, J. A. 7811170214 50-334 VOMACKA, A. 7811020176+ 50-466 Q MARD, R. D. 78110100379+ 50-407 Q MERLING, J. A. 7811170217 50-334 VOMACKA, A. 781127038+ 50-466 Q MARD, R. D. 78110100379+ 50-373 Q MERLING, J. A. 7811170172+ 50-334 VOMACKA, A. 781127038+ 50-312 Q MARD, R. D. 7811000214+ 50-336 Q MERLING, J. A. 7811170172+ 50-334 VOMACKA, A. 7811170173+ 50-334 VOMACKA, A. 7811170173+ 50-334 VOMACKA, A. 7811170173+ 50-334 VOMACKA, A. 7811170173+ 50-334 MARD, R. D. 781120024+ 50-282 S MERLING, J. A. 7811170221+ 50-334 MARD, R. D. 7811200330+ 50-282 S MERLING, J. A. 7811170234+ 50-334 MACHTER, L. J. 7810170242+ 50-243 P MARD, R. D. 7811200330+ 50-299 Q MERLING, J. A. 7812120149+ 50-334 MACHTER, L. J. 781020030+ 50-283 P MARD, J. J. 7812200330+ 50-299 Q MERLING, J. A. 7812120149+ 50-334 MACHTER, L. J. 781020030+ 50-283 P MARD, R. D. 781210034+ 50-331 Q MERLING, J. A. 7812120149+ 50-334 MACHTER, L. J. 781020030+ 50-283 P MARD, R. D. 781210034+ 50-331 Q MERLING, J. A. 7812120149+ 50-334 MACHTER, L. J. 781020030+ 50-283 P MARD, R. D. 781210034+ 50-331 Q MERLING, J. A. 7812120149+ 50-334 MACHTER, L. J. 781020030+ 50-283 P MARD, R. D. 781210034+ 50-331 Q MERLING, J. A. 7812120149+ 50-334 MACHTER, L. J. 781020030+ 50-283 P MARD, R. D. 781210034+ 50-335 Q MERLING, J. A. 781220022+ 50-334 MACHTER, L. J. 781020030+ 50-283 P MARD, R. D. 781210034+ 50-335 Q MERLING, J. A. 781220034+ 50-334 MACHTER, R. Q. 781020034+ 50-390 Q MARD, R. D. 7812200037+ 50-336 Q MERLING, J. A. 781220022+ 50-334 MACHTER, R. P. 781020030+ 50-390 Q MARD, R. D. 7812200037+ 50-336 Q MERLING, J. A. 781220022+ 50-334 MACHTER, R. P. 781020030+ 50-391 Q MARD, R. D. 7810200037+ 50-386 Q MERLING, J. A. 781220023+ 50-334 MACHTER, R. P. 781020030+ 50-391 Q MARD, R. D. 7810200036+ 50-391 Q MARD,		7810140028		WANDKE, N. E.	7812210227	50~295 8	HERLING, J. A.	7811030164	
VOLCER, N. J. 781140030 50-364 9 MANDRE, N. E. 7812210334 30-295 8 MERLING, J. A. 7811170214 50-334 VONACKA, A. 7811020149 50-466 9 MANDRE, N. E. 7812270193 50-106 P MERLING, J. A. 7811170214 50-334 VONACKA, A. 78110201618 50-466 9 MARD, K. D. 7811000598 50-337 0 MERLING, J. A. 7811170172 50-334 VONACKA, A. 7811070598 50-312 3 MARD, K. D. 7811000598 50-313 0 MERLING, J. A. 7811170179 50-334 VOTH, H. H. 7811160147 50-54 P MARD, K. D. 78111700218 50-328 MERLING, J. A. 7811170219 50-334 VOTH, H. H. 78112270157 50-54 P MARD, M. H. 7811160181 50-397 0 MARD, M. H. 7811260181 50-462 8 MERLING, J. A. 78111702348 50-334 MACHTER, L. J. 78101702428 50-263 P MARD, J. J. 78112003308 50-298 0 MERLING, J. A. 78121201438 50-334 MACHTER, L. J. 7810200800 50-263 P MARD, M. D. 78112003308 50-331 0 MERLING, J. A. 78121201438 50-334 MACHTER, L. J. 7810200800 50-263 P MARD, M. D. 78112003308 50-331 0 MERLING, J. A. 78121201438 50-334 MACHTER, L. J. 7810280338 50-282 D MARD, M. D. 7812100244 50-331 0 MERLING, J. A. 7812120180 50-334 MACHTER, L. J. 7810200360 50-263 P MARD, M. D. 7812100244 50-331 0 MERLING, J. A. 7812120180 50-334 MACHTER, L. J. 781020036 50-282 D MARD, M. D. 7812100244 50-331 0 MERLING, J. A. 7812120189 50-334 MACHTER, L. J. 781020036 50-282 D MARD, M. D. 7812100244 50-329 D MERLING, J. A. 781220180 50-334 MACHTER, L. J. 781020036 50-282 D MARD, M. D. 7812003308 50-329 D MERLING, J. A. 7812200368 50-334 MACHTER, L. J. 7810200368 50-390 0 MARD, M. D. 7812000379 50-389 0 MERLING, J. A. 78122900226 50-334 MADD, M. D. 7812000308 50-390 0 MARD, M. D. 7812000308 50-264 D MERLING, J. A. 78122900227 50-334 MALMER, R. 7811202208 50-331 0 MARD, M. D. 7812200038 50-390 0 MERLING, J. A. 78122900227 50-334 MALMER, R. 7811202208 50-331 0 MARD, M. D. 7812200038 50-409 0 MERLING, J. A. 78122900227 50-334 MALMER, R. 7811202208 50-331 0 MARD, M. D. 7812200038 50-409 0 MERLING, J. A. 78122900227 50-334 MALMER, R. 781120200 50-331 0 MARD, M. D. 7812200038 50-299 0 MERLING, J. A. 78122900227 50-334 MALMER, R. 781120200 50-331 0 MARD, M.							WERLING, J. A	7811130218	
VOMACKA.A. 7811020176* 50-466 Q HARD. J. J. 7810240236* 50-498 Q HERLING.J. A. 7811170219 50-334 VORACKA.A. 7810202181* 50-466 Q HARD. J. J. 781010039* 50-373 Q HERLING.J. A. 7811170219 50-334 VORDERBRUEOGEN 7811270058* 50-312 Q HARD. K.D. 781100039* 50-373 Q HERLING.J. A. 7811170178* 50-334 VOTH. H. H. 7811160147 50-54 P HARD. K.D. 781017024 50-282 8 HERLING.J. A. 7811170221 50-334 VOTH. H. H. 7811290157 50-54 J HARD. H. P. 7811160181 50-482 8 HERLING.J. A. 7811170221 50-334 VOTH. H. H. 7812290157 50-54 J HARD. H. P. 7811160181 50-482 8 HERLING.J. A. 7811170221 50-334 HACHTER.L. J. 7810170262* 50-263 P HARD. J. J. 7811200330* 50-298 Q HERLING.J. A. 7812120143 50-334 HACHTER.L. J. 7810200308 50-263 P HARD. J. J. 7811200330* 50-298 Q HERLING.J. A. 7812180180 50-334 HACHTER.L. J. 78122038 50-263 P HARD. J. J. 781220030* 50-298 Q HERLING.J. A. 7812180180 50-334 HACHTER.L. J. 78122038 50-263 P HARD. J. J. 781220030* 50-298 Q HERLING.J. A. 7812180180 50-334 HACHTER.L. J. 78122038 50-263 P HARD. J. J. 781220030* 50-298 Q HERLING.J. A. 7812180180 50-334 HACHTER.L. J. 78122038 50-282 Q HARD. K.D. 7812160341* 50-445 Q HERLING.J. A. 7812180180 50-334 HACHTER.L. J. 781220036 50-282 Q HARD. K.D. 781216028* 50-332 Q HERLING.J. A. 781220222* 50-334 HACHTER.L. J. 781220036 50-298 Q HARD. K.D. 7812160178* 50-282 Q HERLING.J. A. 7812270222* 50-334 HACHTER.L. J. 781270386* 50-390 Q HARD. K.D. 7812060057* 50-282 Q HERLING.J. A. 7812270223* 50-334 HACHTER.L. J. 7812003040 50-391 Q HARD. K.D. 7812270078* 50-398 Q HERLING.J. A. 7812270323* 50-334 HACHTER.R. P. 7812003404 50-331 Q HARD. K.D. 7812270078* 50-389 Q HERLING.J. A. 7812270323* 50-334 HALKER. R. 781220230* 50-331 Q HARD. K.D. 7812270078* 50-398 Q HERLING.J. A. 7812270323* 50-334 HALKER. R. 781220230* 50-331 Q HARD. K.D. 7812270078* 50-480 Q HERLING.J. A. 7812270323* 50-334 HALKER. R. 781220230* 50-331 Q HARD. K.D. 7812270078* 50-480 Q HERLING.J. A. 7812270323* 50-334 HALKER. R. 781220230* 50-331 Q HARD. K.D. 781200006* 50-282 P HERNER. L. 781027034; 50-344 HALKER. R. 781202			30-367 Q				WERLING. J. A.		50-334
VORDERBRUEGGEN 7811270388 50-312 G MARD, R. D. 7811010379 50-333 G MERLING, J. A. 7811170172 50-334 VORTH, H. H. 7811270388 50-312 G MARD, R. D. 7811010379 50-328 G MERLING, J. A. 7811170172 50-334 VORTH, H. H. 7811270187 50-334 P MARD, R. D. 7811160181 50-482 8 MERLING, J. A. 7811170221 50-334 VOTH, H. H. 7811290157 50-34 J MARD, M. H. 7811160181 50-482 8 MERLING, J. A. 7811170221 50-334 VOTH, H. H. 7811200185 50-334 MARD, M. H. 7811160181 50-482 8 MERLING, J. A. 7811170234 50-334 MARD, M. H. 7811160181 50-482 8 MERLING, J. A. 7811210143 50-334 MARD, M. D. 78112800329 50-263 P MARD, J. J. 78112800329 50-269 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 78112800330 50-298 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 78112800330 50-298 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 78112800330 50-298 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 78112800330 50-298 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 78112800330 50-298 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 7812120034 50-331 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 7812120034 50-334 MARD, J. J. 781220034 50-282 0 MARD, M. D. 7812100249 50-329 0 MERLING, J. A. 7812120140 50-334 MARD, M. D. 781210034 50-329 0 MERLING, J. A. 7812290224 50-334 MARD, M. D. 781220034 50-329 0 MERLING, J. A. 7812290224 50-334 MARD, M. D. 781220036 50-282 0 MARD, M. D. 7812000370 50-282 8 MERLING, J. A. 7812290224 50-334 MARD, M. D. 7812200036 50-282 8 MERLING, J. A. 7812290224 50-334 MARD, M. D. 7812200036 50-282 8 MERLING, J. A. 7812290224 50-334 MARD, M. D. 78122000059 50-282 8 MERLING, J. A. 7812290224 50-334 MARD, M. D. 78122000059 50-282 8 MERLING, J. A. 7812290224 50-334 MARD, M. D. 78122000059 50-282 8 MERLING, J. A. 7812290223 50-334 MARD, M. D. 78122000059 50-282 8 MERLING, J. A. 7812290223 50-334 MARD, J. J. 78122000059 50-282 8 MERLING, J. A. 7812290223 50-334 MARD, J. J. 78122000059 50-282 8 MERLING, J. A. 7812290223 50-334 MARD, J. J. 7812200006 50-282 9 MARD, J. J. 781220006 50-282 9 MARD, J. J. 781220006 50-282 9 MARD, J. J. 781220006 50-282 9	TO THE REAL PR.	\B1105019A	3U-400 ¥	WANG, C. H.	7812270193	⊅0~106 P	HERLING: J. A.	7811170214	50-334
VORDERBRUEGGEN 7811270388 50-312 G MARD, R. D. 7811010379 50-333 G MERLING, J. A. 7811170172 50-334 VORTH, H. H. 7811270388 50-312 G MARD, R. D. 7811010379 50-328 G MERLING, J. A. 7811170172 50-334 VORTH, H. H. 7811270187 50-334 P MARD, R. D. 7811160181 50-482 8 MERLING, J. A. 7811170221 50-334 VOTH, H. H. 7811290157 50-34 J MARD, M. H. 7811160181 50-482 8 MERLING, J. A. 7811170221 50-334 VOTH, H. H. 7811200185 50-334 MARD, M. H. 7811160181 50-482 8 MERLING, J. A. 7811170234 50-334 MARD, M. H. 7811160181 50-482 8 MERLING, J. A. 7811210143 50-334 MARD, M. D. 78112800329 50-263 P MARD, J. J. 78112800329 50-269 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 78112800330 50-298 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 78112800330 50-298 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 78112800330 50-298 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 78112800330 50-298 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 78112800330 50-298 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 7812120034 50-331 0 MERLING, J. A. 7812120143 50-334 MARD, M. D. 7812120034 50-334 MARD, J. J. 781220034 50-282 0 MARD, M. D. 7812100249 50-329 0 MERLING, J. A. 7812120140 50-334 MARD, M. D. 781210034 50-329 0 MERLING, J. A. 7812290224 50-334 MARD, M. D. 781220034 50-329 0 MERLING, J. A. 7812290224 50-334 MARD, M. D. 781220036 50-282 0 MARD, M. D. 7812000370 50-282 8 MERLING, J. A. 7812290224 50-334 MARD, M. D. 7812200036 50-282 8 MERLING, J. A. 7812290224 50-334 MARD, M. D. 7812200036 50-282 8 MERLING, J. A. 7812290224 50-334 MARD, M. D. 78122000059 50-282 8 MERLING, J. A. 7812290224 50-334 MARD, M. D. 78122000059 50-282 8 MERLING, J. A. 7812290224 50-334 MARD, M. D. 78122000059 50-282 8 MERLING, J. A. 7812290223 50-334 MARD, M. D. 78122000059 50-282 8 MERLING, J. A. 7812290223 50-334 MARD, J. J. 78122000059 50-282 8 MERLING, J. A. 7812290223 50-334 MARD, J. J. 78122000059 50-282 8 MERLING, J. A. 7812290223 50-334 MARD, J. J. 7812200006 50-282 9 MARD, J. J. 781220006 50-282 9 MARD, J. J. 781220006 50-282 9 MARD, J. J. 781220006 50-282 9	VONACKA, A.	7811020174=	50-466 O	HARD1	7010040007-	40-400 0	DEBITAR I A	2011120210	
VORDERBRUEOGEN 78112700388 50-312 G MARD K.D 7811300321* 50-383 G MERLING.J.A. 7811170178* 50-334 VOTH.H.H 781120137 50-84 P MARD.E.C. 7810170224 50-282 8 MERLING.J.A. 7811170231* 50-334 VOTH.H.H 7812290157 50-84 J MARD.K.D. 7811280032* 50-331 G MERLING.J.A. 7811170234* 50-334 MACHTER.L.J. 7810170242* 50-263 P MARD.J.J. 7811200330* 50-298 G MERLING.J.A. 781220148* 50-334 MACHTER.L.J. 781020080* 50-263 P MARD.K.D. 7811200330* 50-298 G MERLING.J.A. 7812120148* 50-334 MACHTER.L.J. 781020080* 50-263 P MARD.K.D. 781220030* 50-298 G MERLING.J.A. 7812120148* 50-334 MACHTER.L.J. 781280339* 50-263 P MARD.K.D. 781210024* 50-331 G MERLING.J.A. 7812120148* 50-334 MACHTER.L.J. 781220038* 50-282 D MARD.K.D. 781210024* 50-331 G MERLING.J.A. 7812180180* 50-334 MACHTER.L.J. 7812210036* 50-282 D MARD.K.D. 7812140028* 50-332 G MERLING.J.A. 7812270222* 50-334 MACHTER.L.J. 781270222* 50-263 P MARD.K.D. 7812060034* 50-329 G MERLING.J.A. 7812270222* 50-334 MACHTER.L.J. 781270222* 50-263 P MARD.K.D. 781200030* 50-298 G MERLING.J.A. 7812270222* 50-334 MACHTER.L.J. 781270388* 50-390 G MARD.K.D. 7812000178* 50-266 G MERLING.J.A. 7812270222* 50-334 MACHTER.L.J. 781270388* 50-390 G MARD.K.D. 781200007* 50-282 S MERLING.J.A. 7812270228* 50-334 MACHTER.P.F. 7812040316* 50-346 G MARD.K.D. 7812270078* 50-389 G MERLING.J.A. 7812270228* 50-334 MALNER.R. 7812200340* 50-331 G MARD.K.D. 7812270078* 50-389 G MERLING.J.A. 7812270228* 50-334 MALNER.R. 7812040316* 50-346 G MARD.J.J. 7812070002* 50-128 G MERLING.J.A. 7812290223* 50-334 MALNER.R. 7812040316* 50-331 G MARD.J.J. 7812070002* 50-128 G MERLING.J.A. 781229023* 50-334 MALNER.R. 781120220* 50-331 G MARD.J.J. 781200006* 50-267 B MERNER.L. 781027034* 50-344 MALACE.J.J. 7810270379* 50-334 MARD.J.J. 7810270002* 50-128 G MERLING.J.A. 781229023* 50-334 MALACE.R. 7810240037* 50-331 G MARD.J.J. 7812270002* 50-128 G MERLING.J.A. 7812220037* 50-334 MALACE.J.J. 781020003* 50-331 G MARD.J.J. 781020016* 50-267 B MERNER.R. 781027034* 50-344 MALACE.J.J. 781020003* 50-366 G MARD.J.J.J. 781030016* 50-267 B MERNE			30-446 D						
VOTH, H. H. 781140147 30-34 P. MARD, E. C. 7810170224 50-282 S. MERLING, J. A. 7811170221 50-334 VOTH, H. H. 7812290157 50-54 J. MARD, H. H. 78112800324 50-331 G. MERLING, J. A. 78111702314 50-334 VOZENILBA, H. MARDITER, L. J. 78101702624 50-263 P. MARD, J. J. 78112003304 50-298 G. MERLING, J. A. 7812120143 50-334 MACHTER, L. J. 78102003805 50-263 P. MARD, R. D. 78112100244 50-331 G. MERLING, J. A. 7812120148 50-334 MACHTER, L. J. 78102003805 50-263 P. MARD, R. D. 78112100244 50-331 G. MERLING, J. A. 7812120148 50-334 MACHTER, L. J. 7811220338 50-263 P. MARD, R. D. 78112100244 50-331 G. MERLING, J. A. 7812120148 50-334 MACHTER, L. J. 7811220038 50-282 D. MARD, R. D. 7812100244 50-331 G. MERLING, J. A. 7812120184 50-334 MACHTER, L. J. 7812210036 50-282 D. MARD, R. D. 7812100244 50-329 G. MERLING, J. A. 78122702224 50-334 MACHTER, L. J. 78122702245 50-334 MARD, R. D. 78121001785 50-266 G. MERLING, J. A. 78122702245 50-334 MACHTER, L. J. 78122702345 50-334 MARD, R. D. 78122702345 50-334 MALNER, R. 78122702345 50-334 MARD, J. J. 78122702245 50-334 MALNER, R. 78122040345 50-331 G. MARD, R. D. 78122700025 50-128 G. MERLING, J. A. 78122702235 50-334 MALNER, R. 78122040345 50-331 G. MARD, J. J. 78120700025 50-128 G. MERLING, J. A. 78122702235 50-334 MALNER, R. 7812040345 50-331 G. MARD, J. J. 7812040034 50-331 G. MARD, J. J. 7812040034 50-331 G. MARD, J. J. 7812040035 50-334 MARD, J. J. 7812040035 50-335 G. MARD, J	VORDERBRUEGGEN		50-312 G						
VOZENILEA. H 781120018 50-34 J WARD. W. N. 7811160181 50-482 8 MERLING. J. A. 7811170234 50-334 VOZENILEA. H 781100018 50-397 0 WARD. K. D. 7811200320 50-298 0 WERLING. J. A. 7812120143 50-334 WARD. J. J 7810200080 50-263 P WARD. K. D. 7811200330 50-298 0 WERLING. J. A. 7812120143 50-334 WARD. MACHTER. L. J. 7810200080 50-263 P WARD. K. D. 7811210024 50-331 0 WERLING. J. A. 7812120148 50-334 WARD. MACHTER. L. J. 7811280339 50-263 P WARD. K. D. 7811210024 50-331 0 WERLING. J. A. 7812180180 50-334 WARD. MACHTER. L. J. 781221036 50-282 0 WARD. K. D. 7812140028 50-329 0 WERLING. J. A. 7812180184 50-334 WARD. K. D. 7812140028 50-329 0 WERLING. J. A. 7812290226 50-334 WARD. K. D. 781240028 50-329 0 WERLING. J. A. 7812290226 50-334 WARD. K. D. 7812060178 50-266 0 WERLING. J. A. 7812290226 50-334 WARD. K. D. 7812290228 50-334 WARD. J. J. 7812900008 50-128 0 WERLING. J. A. 7812290238 50-334 WARD. J. J. 7812900008 50-128 0 WERLING. J. A. 7812290238 50-334 WARD. J. J. 7812900008 50-128 0 WERLING. J. A. 7812290238 50-334 WALLACE. R. 781202209 50-334 WARD. J. J. 7812900016 50-267 8 WERNER, L. 7810202758 50-344 WALLACE. J. J. 781020209 50-300 R WARD. J. J. 78121000164 50-267 8 WERNER, L. 7810202758 50-344 WALLACE. J. J. 781020007 50-366 0 WARD. MARRING. D. 7810300164 50-267 8 WERNER, L. 781027034 50-461 WALLACE. J. R. 781020007 50-364 WARD. J. J. 7810300169 50-267 8 WERNER, L. 7810270248 50-461 WALLACE. J. R. 781020007 50-364 WARD. J. J. 7810300169 50-267 8 WERNER, L. 781027044 50-461 WALLACE. J. R. 781020007 50-364 WARD. J. J. R. 7810200169 50-267 8 WERNER, L. 781020047 50-461 WALLACE. J. R. 781020007 50-364 WARD. J. J. R. 7810200169 50-267 8 WERNER, L. 781020047 50-461 WALLACE. J. R. 781020007 50-36		7811160147	50-34 P						
VOZENILEM, H 781110001B 50-397 0 MARD, K. D. 7811280032+ 50-331 0 MERLINO, J. A. 7812120143 50-334 MACHTER, L. J. 7810170262+ 50-325 P MARD, J. J 781120030+ 50-298 0 MERLINO, J. A. 7812120148+ 50-334 MACHTER, L. J 7811280338 50-263 P MARD, K. D. 7811210024+ 50-331 0 MERLINO, J. A. 7812120148+ 50-334 MACHTER, L. J 7812210036 50-263 P MARD, K. D. 7812140028+ 50-329 0 MARD, K. D. 781200215 50-328 MARD, K. D. 7812002057- 50-38 MARD, K. D. 7812002057- 50-38 MARD, K. D. 7812002057- 50-38 MARD, MARD, K. D. 7812000304- MARD, K. D. 7812000305- 50-38 MERLING, J. A. 7812270223- 50-334 MALKER, R. 781200306- 50-324 MARD, K. D. 7812000057- 50-388 MERLING, J. A. 7812270223- 50-334 MALKER, R. 781200306- 50-324 MARD, J. J. 7812000057- 50-388 MERLING, J. A. 7812270223- 50-334 MALKER, R. 781200306- 50-329 MARD, J. J. 7812000164 50-329 MARD, J. J. 7812100215 50-344 MALLACE, J. J. 781020007 50-366 MARD, J. J. 7810300164 50-267 8 MERNER, L. 781027034+ 50-344 MALLACE, J. J. 781020007 50-461 MARD, J. J. 7810300164 50-267 8 MERNER, R. 7812210130 50-445 50-324 MARD, J. J. 7810200167 50-267 8 MERNER, R. 7812210130 50-445 50-324 MARD, J. J. 7810200167 50-267 8 MERNER, R. 7812210130 50-445 50-324 MARD, J. J. 7810200167 50-267 8 MERNER, R. 781027024+ 50-344 MALLACE, J. J. 781020027 50-461	VOTH, M. H.	7812290157	50-54 J	WARD: W. H.					
MACHTER.L. J. 7810170362e 50-263 P MARD. J. J. 7811200330e 50-298 0 MERLING.J. A. 7812120149e 50-334 MACHTER.L. J. 781020080e 50-263 P MARD. J. J. 7812100330e 50-263 D MARD. K. D. 7811210024e 50-331 0 MERLING.J. A. 7812180184e 50-334 MACHTER.L. J. 7812210036 50-282 D MARD. K. D. 7812140028e 50-329 0 MERLING.J. A. 7812210036e 50-334 MACHTER.L. J. 7812210036 50-282 D MARD. K. D. 7812140028e 50-329 0 MERLING.J. A. 7812270222e 50-334 MARD. K. D. 7812140028e 50-329 0 MERLING.J. A. 7812270222e 50-334 MARD. K. D. 7812140028e 50-329 0 MERLING.J. A. 7812270222e 50-334 MARD. K. D. 781200037e 50-262 B MERLING.J. A. 7812270216 50-334 MARD. K. D. 781200037e 50-358 0 MERLING.J. A. 7812270216 50-334 MARD. K. D. 781200037e 50-358 0 MERLING.J. A. 7812270216 50-334 MARD. K. D. 7812000037e 50-358 0 MERLING.J. A. 7812270216 50-334 MARD. K. D. 7812000037e 50-358 0 MERLING.J. A. 7812270216 50-334 MARD. K. D. 78122700002e 50-128 0 MERLING.J. A. 7812270223e 50-334 MARD. K. D. 78122700002e 50-128 0 MERLING.J. A. 7812270223e 50-334 MARD. K. D. 78122700002e 50-128 0 MERLING.J. A. 7812270239e 50-334 MARD. J. J. 7812000037e 50-128 0 MERLING.J. A. 7812270239e 50-334 MARD. J. J. 7812000037e 50-128 0 MERLING.J. A. 7812270239e 50-334 MARD. J. J. 7812000037e 50-128 0 MERLING.J. A. 7812270239e 50-334 MARD. J. J. 7812000037e 50-128 0 MERLING.J. A. 7812270239e 50-334 MARD. J. J. 7812000037e 50-128 0 MERLING.J. A. 7812270239e 50-334 MARD. J. J. 7812000037e 50-267 8 MERLING.J. A. 7812270341 50-244 MALLACE.J. J. 7810200037 50-566 0 MARD. J. J. 7810300169 50-267 8 MERNER. R. 7812210150 50-465 MARD. J. J. 7810300169 50-267 8 MERNER. R. 7812210150 50-465 MARD. J. J. 7810300169 50-267 8 MERNER. R. 7812210170 50-465 MARD. J. J. 7810300169 50-267 8 MERNER. R. 7812210170 50-465 MARD. J. J. 7810300169 50-267 8 MERNER. R. 7810200479 50-461 MARD. J. J. 7810300169 50-267 8 MERNER. R. 7810200479 50-461 MARD. J. J. J. MARD. J. J. MARD. J. J. MARD. J. J. J.	UMTENTI EV U	3011105-15							
MACHTER.L. J. 78102000809 50-263 P MARD. K. D. 78112100244 50-331 G MERLING. J. A. 781210180 50-334 MACHTER.L. J. 781122039 50-283 P MARD. J. J. 781220603414 50-445 G MERLING. J. A. 7812210184 50-334 MACHTER.L. J. 7812210036 50-282 D MARD. K. D. 78121002089 50-329 G MERLING. J. A. 7812270222 50-334 MACHTER.L. J. 7812270224 50-334 MARD. K. D. 78120601789 50-266 G MERLING. J. A. 7812270224 50-334 MARD. E. C. 7811070215 50-262 S MERLING. J. A. 7812270224 50-334 MARD. K. D. 78122700215 50-334 MARD. K. D. 78122700216 50-334 MARD. K. D. 781227002089 50-338 G MERLING. J. A. 7812290216 50-334 MALD. MARD. K. D. 78122700789 50-469 G MERLING. J. A. 78122902239 50-334 MALD. MARD. K. D. 78122700029 50-128 G MERLING. J. A. 78122902239 50-334 MALD. MARD. K. D. 78120700029 50-128 G MERLING. J. A. 7812290239 50-334 MALD. MARD. K. D. 78120700029 50-128 G MERLING. J. A. 7812290239 50-334 MALD. MARD. K. D. 78120700029 50-128 G MERLING. J. A. 7812290239 50-334 MALD. MARD. K. D. 78120700029 50-128 G MERLING. J. A. 7812290239 50-334 MALD. MARD. J. J. 78120700029 50-128 G MERLING. J. A. 7812290239 50-334 MARD. J. J. 78120700029 50-128 G MERLING. J. A. 7812290239 50-334 MARD. J. J. 78120700029 50-128 G MERLING. J. A. 7812290239 50-334 MARD. J. J. 781200700029 50-128 G MERLING. J. A. 7812290239 50-334 MARD. J. J. 781200700029 50-128 G MERLING. J. A. 7812290239 50-334 MARD. J. J. 7812100209 50-344 MARD. J. J. 78102100009 50-348 MARD. J. J. J. 781021						50~331 0			
HACHTER.L. J. 7812180338 30-263 P HARD. J. J. 781220341* 50-345 0 HERLING. J. A. 7812180180* 50-334 MACHTER.L. J. 781221036 50-282 0 HARD. K. D. 781214028* 50-329 0 HERLING. J. A. 7812270222* 50-334 MACHTER.L. J. 7812270222* 50-334 MACHTER.L. J. 7812270224* 50-285 P HARD. K. D. 7812060178* 50-266 Q HERLING. J. A. 7812270224* 50-334 MACHTER.A. D. 7812270386* 30-390 Q HARD. K. D. 7812060057* 50-282 8 HERLING. J. A. 7812270216* 50-334 MACHTER.P. F. 7812040316* 30-390 Q HARD. K. D. 7812060057* 50-388 Q HERLING. J. A. 7812270218* 50-334 MALKER.R. P. 7812040316* 30-391 Q HARD. K. D. 7812270078* 50-409 Q HERLING. J. A. 7812270223* 50-334 MALKER.R. P. 7812040316* 30-331 Q HARD. J. J. 78122700708* 50-128 Q HERLING. J. A. 7812270227* 50-334 MACHTER.R. P. 781210220* 30-331 Q HARD. J. J. 7812060141 50-282 P HERNER.L. 7810270341 50-344 MALKER.R. 7811210220* 30-331 Q HARD. J. J. 7812180424* 50-39 Q HERNER.L. 7810270341 50-344 MALKER.R. 781210220* 30-331 Q HARD. J. J. 7812180424* 50-39 Q HERNER.L. 7810270341 50-344 MALKER.L. 781027037* 50-344 MALKER.L. 7810240037 50-366 Q HARD. MAREHBURG.D. 7810300164 50-267 8 HERNER.R. 7812210150 50-445 MALKER.L. 781020027* 50-461 MAREHBURG.D. 7810300169 50-267 8 HERNER.R. 7812210150 50-446 MALKER.L. 781020024* 50-324 MAREHBURG.D. 7810300169 50-267 8 HERNER.R. 7812210150 50-446 MALKER.L. 781020024* 50-324 MAREHBURG.D. 7810300169 50-267 8 HERNER.R. 7812210150 50-446 MALKER.L. 781020024* 50-324 MAREHBURG.D. 7810300169 50-267 8 HERNER.R. 7812210150 50-446									
MACHTER,L. J. 7812210036 50-282 0 MARD, K.D. 7812100289 50-329 0 MERLING, J. A. 7812270282 50-334 MACHTER,L. J. 7812070222* 50-263 P MARD, K.D. 7812060178* 50-266 Q MERLING, J. A. 7812270226* 50-334 MACHTER, A. G. 7811070279* 50-390 Q MARD, E. C. 7811070215 50-282 B MERLING, J. A. 7812270216 50-334 MALDNER, P. F. 7812040316 50-466 Q MARD, K. D. 7812270078* 50-469 Q MERLING, J. A. 7812270227* 50-334 MALKER, R. 7812040340* 50-331 Q MARD, J. J. 7812070002* 50-128 Q MERLING, J. A. 7812270235* 50-334 MALKER, R. D. 7811140267* 50-331 Q MARD, J. J. 7812040002* 50-128 Q MERLING, J. A. 7812270235* 50-334 MALKER, R. 781120200 50-331 Q MARD, J. J. 78120400141 50-282 P MERNER, L. 781020275* 50-344 MALKER, R. 781120200 50-331 Q MARD, J. J. 7812180424* 50-39 Q MERNER, L. 7810270341 50-344 MALLACE, J. J. 781070159* 50-305 R MARD, MARD, J. J. 7810300169 50-267 8 MERNER, R. 7812210150 50-446 MALLACE, J. J. 7810240037 50-566 Q MARBNER, D. 7810300169 50-267 8 MERNER, R. 7812210150 50-446 MALLACE, J. J. 7810240037 50-566 Q MARBNER, D. 7810300169 50-267 8 MERNER, R. 7812210150 50-446 MALLACE, J. J. 7810240037 50-566 Q MARBNER, D. 7810300169 50-267 8 MERNER, R. 7812210150 50-446 MALLACE, J. J. 781040002 50-321									
MACHTER.L.J. 7812070222* 50-263 P MARD.K.D. 7812060178* 50-266 Q MERLING.J.A. 7812270226* 50-334 MARD.E.C. 7811070215 50-282 8 MERLING.J.A. 7812270216 50-334 MARD.E.C. 7812060057* 50-388 Q MERLING.J.A. 7812270216 50-334 MALDRER.P. 7812040316 50-334 MARD.K.D. 7812270078* 50-469 Q MERLING.J.A. 7812270223* 50-334 MALDRER.R. 7812040316 50-331 Q MARD.K.D. 7812070002* 50-128 Q MERLING.J.A. 7812270278* 50-334 MARD.J.J. 7812070002* 50-128 Q MERLING.J.A. 7812270278* 50-334 MARD.J.J. 7812070002* 50-128 Q MERLING.J.A. 7812270278* 50-334 MARD.J.J. 7812102200* 50-334 MARD.J.J. 7812100200* 50-30* MARD.J.J. 7812100200* 50-30* MERLING.J.A. 7812270278* 50-344 MALDRER.R. 7811210220* 50-331 Q MARD.J.J. 7812180424* 50-39 Q MERNER.L. 781027034† 50-344 MALLACE.J.J. 781070159* 50-305 R MARD.M.D.J.J. 7810300164 50-267 8 MERNER.R. 7812210150 50-448 MALLACE.J.J. 78102003* 50-304*									
HAGNER, A. G. 7811070279* 50-390 0 HARD, E. G. 7811070215 50-282 8 HERLING, J. A. 7812270216 50-334 HALLER, R. 7812040316 50-346 0 HARD, K. D. 7812270078* 50-409 0 HERLING, J. A. 7812270227* 50-334 HALLER, R. 7812040340* 50-331 0 HARD, J. J. 7812070002* 50-128 0 HERLING, J. A. 7812270227* 50-334 HALLER, R. 7812040340* 50-331 0 HARD, J. J. 7812070002* 50-128 0 HERLING, J. A. 7812270235* 50-334 HALLER, R. 781121020* 50-331 0 HARD, J. J. 78120400141 50-282 P HERLER, L. 7811020275* 50-344 HALLER, R. 781121020* 50-331 0 HARD, J. J. 7812104034* 50-39* 0 HERLER, L. 7810270341 50-344 HALLAGE, J. J. 781071015** 50-305 R HARBHOURG, D. 7810300164 50-267 8 HERNER, R. 7812210150 50-446 HALLAGE, J. A. 7811040002 50-304 0 HARBHOURG, D. 7810300169 50-267 8 HERNER, R. 7812210150 50-446 HALLAGE, J. A. 7811040002 50-304 0 HARBHOURG, D. 7810300169 50-267 8 HERNER, R. 7812210150 50-446 HALLAGE, J. A. 7811400002 50-304 0 HARBHOURG, D. 7810300169 50-267 8 HERNER, R. 7812210150 50-446 1 HALLAGE, J. A. 7811400002 50-304 0 HARBHOURG, D. 7810300169 50-267 8 HERNER, R. 7812210150 50-446 1 HALLAGE, J. A. 7811400002 50-304 0 HARBHOURG, D. 7810300169 50-267 8 HERNER, R. 7812210150 50-446 1 HALLAGE, J. A. 7811400002 50-304 0 HARBHOURG, D. 7810300169 50-267 8 HERNER, R. 7812210150 50-446 1 HALLAGE, J. A. 7811400002 50-304 0 HARBHOURG, D. 7810300169 50-267 8 HERNER, R. 7812210150 50-446 1 HARBHOURG, J. 7810300169 50-267 8 HERNER, R. 7812210150 50-461 1 HARBHOURG, J. 7810300169 50-267 8 HERNER, R. 7812210150 50-461 1 HARBHOURG, J. 7810300169 50-267 8 HERNER, R. 7812210150 50-461 1 HARBHOURG, J. 7810300169 50-267 8 HERNER, R. 7812210150 50-461 1 HARBHOURG, J. 7810300169 50-267 8 HERNER, R. 7812210150 50-461 1 HARBHOURG, J. 7810300169 50-267 8 HERNER, R. 7812210150 50-461 1 HARBHOURG, J. 7810300169 50-267 8 HERNER, R. 7812210150 50-461 1 HARBHOURG, J. 7810300169 50-267 8 HERNER, R. 7812210150 50-461 1 HARBHOURG, J. 7810300169 50-267 8 HERNER, R. 7812210150 50-461 1 HARBHOURG, J. 7810300169 50-267 8 HERNER, R. 78122000169 50-267 8 HERNER, R. 781220					. # 1 E 1 74/40 F	JV-UE7 E	PENLITOI V. A.	101RELAKE	au-334
HARDER, R. D. 7812702209 50-331 G HARD, E. C. 7812060057* 50-388 G HERLING, J. A. 7812270215 50-334 HALLER, R. D. 7812040316 50-331 G HARD, L. D. 7812070002* 50-128 G HERLING, J. A. 7812290227* 50-334 HALLER, R. D. 7812040316 50-331 G HARD, J. J. 7812070002* 50-128 G HERLING, J. A. 7812290237* 50-334 HALLER, R. D. 7812040340* 50-331 G HARD, J. J. 7812070002* 50-128 G HERLING, J. A. 7812290237* 50-334 HALLER, R. D. 78112020* 50-331 G HARD, J. J. 7812070002* 50-128 G HERLING, J. A. 7812290237* 50-334 HALLER, R. 78112020* 50-331 G HARD, J. J. 7812060141 50-282 P HERNER, L. 781020275* 50-344 HALLER, R. 78112020* 50-331 G HARD, J. J. 7812180424* 50-59 G HERNER, L. 781020275* 50-344 HALLER, R. 781020275* 50-344 HALLER, R. 781024037 50-546 G HARRHBURG, D. 7810300164 50-267 8 HERNER, R. 7812210150 50-446 HALLER, J. 781020037 50-556 G HARRHBURG, D. 7810300169 50-267 8 HERNER, R. 7812210150 50-446 HALLER, J. 781020037 50-556 G HARRHBURG, D. 7810300169 50-267 8 HERDETT, H. M. 7812290247* 50-446 HALLER, J. 781020037 50-556 G HARRHBURG, D. 7810300169 50-267 8 HERDETT, H. M. 7812290247* 50-446 HALLER, J. 781020025* 50-334 HARRHBURG, D. 7810300169 50-267 8 HERDETT, H. M. 7812290247* 50-461	MACHTER.L.J.				7812060178*	50-266 0	HERLING, J. A.	7812290224=	50-334
HALDIER, R. 7812270386 30-390 G MARD, K. D. 78122060057* 50-388 G MERLING, J. A. 7812270232* 50-334 MARD, R. D. 7812270078* 50-409 G MERLING, J. A. 7812270278* 50-334 MARD, J. J. 78127007002* 50-128 G MERLING, J. A. 7812270278* 50-334 MARD, J. J. 7812070002* 50-128 G MERLING, J. A. 7812270278* 50-334 MARD, J. J. 7812070002* 50-128 G MERLING, J. A. 7812270278* 50-334 MARD, J. J. 781210200* 50-331 G MARD, J. J. 7812180404* 50-282 P MERNER, L. 781027034* 50-344 MALLACE, J. J. 781070157* 50-305 R MARD, J. J. 7812180424* 50-39 G MERNER, L. 781027034* 50-344 MARD, J. J. 7812180404* 50-39 G MERNER, L. 781027034* 50-344 MARD, J. J. 781020016* 50-267 8 MERNER, R. 7812210150 50-448 MARD, J. J. 781030016* 50-267 8 MERNER, R. 7812210150 50-448 MARD, J. J. 781030016* 50-267 8 MERNER, R. 7812210150 50-448 MARD, J. J. 781030016* 50-267 8 MERNER, R. 7812210150 50-448 MARD, J. J. 781030016* 50-267 8 MERNER, R. 7812210150 50-448 MARD, J. J. 781030016* 50-267 8 MERCOTTH, M. 781227047* 50-448	HAGNER, A.C.				7811070215	50~262 B			
HALLACE.L. E. 781024037 50-305 R MARD.R.D. 7810200169 50-407 B MERNER.R. 781020027* 50-334 MARD.R.D. 7810200002* 50-334 MARD.J.J. 7810200002* 50-128 G MERLING.J.A. 781020027* 50-334 MARD.E.C. 7810200002* 50-128 G MERLING.J.A. 781020027* 50-334 MARD.E.C. 7810200002* 50-128 G MERLING.J.A. 781020027* 50-334 MARD.E.C. 7810200002* 50-128 G MERNER.L. 781020075* 50-344 MARD.E.C. 781020014 50-282 P MERNER.L. 781020075* 50-344 MARD.E.C. 7810200164 50-267 B MERNER.R. 7810210150 50-445 MARD.E.C. 7810200169 50-267 B MERNER.R. 7810220027* 50-461 MARD.E.C. 7810200169 50-267 B ME	HALDNER P F						WERLING, J. A.	7812290223#	
HALLACE. L. E. 7810240037 50-356 Q HARDURG. D. 7810300169 50-267 8 HERNER, R. 7812290247* 50-461	HALKER, R	7812040316						7812290227#	50~334
HALKER, R. 78112102200 30-331 0 MARD, J. J. 78121804244 50-399 0 MERNER, L. 78110202758 50-344 MALLACE, J. J. 78101701598 50-305 R MAREMBURG, D. 7810300164 50-267 8 MERNER, R. 7812210150 50-445 HALLACE, J. A. 7811210220	THE SECOND SEC.	/ B1 EVOUS404	30-331 G	HARDI J. J.	7812070002*	20-158 0	WERLING, J. A.	7812290235*	
HALKER, R. 78112102200 50-331 G MARD, J. J 78121804244 50-399 G MERNER, L 78110202754 50-344 MALLACE, J. J. 78101701594 50-305 R MAREMBURG, D. 7810300164 50-267 8 MERNER, R. 7812210150 50-445 MALLACE, J. A 7811080002 50-331 G MAREMBURG, D. 7810300169 50-267 8 MERNER, R. 7812210150 50-445	HALKER, R. D.	78111402A7+	50-373 n	MARIN. P. C.	701001014	80.000 0	I FOLICA :		<u></u>
HALLACE, J. J. 7810170189* 50-309 R HAREMBURG, D. 7810300164 50-267 8 HERNER, R. 7810210150 50-445 HALLACE, L. 8. 7810240037 50-366 Q HAREMBURG, D. 7810300169 50-267 8 HERCTT, H. M. 7812290247* 50-461	HALKER, R.								
HALLACE: E. 7810240037 50-866 0 HAREHBURG. D. 7810300189 50-267 8 HEBCOTT.H. 7812270247* 50-461	HALLACE: J. J.								
WALLACE J. A TRILLOGONO SO-221 A HARMANIA	HALLACE, L. E.	7810240037	50-566 Q			50-267 S			
	WALLACE, J. A	7811090002							
								+ + + + + + + + + + + + + + +	

PERSONAL AUTHOR INDEX

7811060344 7811200007 7811170003 7811200420 7811200415

WOLFE S. J. WOLFE B. J. WOLFE B. J. WOLFE S. J.

HOLFE, S. J.

50-62 50-313 50-368 50-313

50~62

P 8 0

7812200232

7812180120 7812200224 7812210135 7812200221

80-854 50-444 50-554 50-556 50-556

AUTHOR	ACCESSION NUMBER	EUBJECT CATEQURY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCESSION NUMBER	CATEOC
HEBSMAN, Q. L.	7811060115	50-237 P	HIGGINTON, D	7812080143	50-334 P	WILLIAMSON, T. O.	7812260144	50-62
WESSMAN, Q. L	7811130200	50-267 P	WIONT, J. B.	7812040031*	30-344 O	HILL IAMB. D. H.	7812270247	30-313
HESSMAN, C. L. HESTERMAN, T. F.	7811240232 7810130053*	50-267 K 50-313 0	WIGHT, J. 8. Wilbur, L. C.	7812280266 7811240038	50-344 @ 50-134 V	HILL IAMS, D. H.	7812270299	50-348
WESTERMAN, T. F.	7810140092 *	50-313 Q	WILLEMBEN, B.	7811240038 7811240241*	50-134 V 50-265 B	WILLIAMS.D.H. WILLBEY.W 8.	7912280127 7910270186	50-313 50-277
WESTERMAN, T. F.	7611210501+	50-313 0	WILLIAMSON T Q.	7612200222	50-62 P	HILLBEY, H. B.	7811170130	50-277
WESTERMAN, T. F. WESTERMAN, T. F.	7812210169* 7812190061*	50-368 0 50-313 0	WILLIAMSON, T. G.	7811010102	50-62 P	HILLSEY, W. B.	7812080109	50-277
WESTERMAN, T. F.	78121700814	50-313 0	NILLIAMB D. H WILLIAMB D. H.	7810110301* 7810190096	50-313 G 50-368 P	WILLBEY,W B. WILBON,J.N.	7812180154 78101801 7 5	50-277 50-322
WETHY, C. M.	7812080200	50-335 8	WILLIAMS, D. W.	7810120114	50-36B 8	WILSON, K.R.	7810200170*	20-598
WETTERHAIN, M. J.	7810270313	50-395 0	HILLIAME D. H	7810100019	50-368 8	WILSON, S. M.	7810170141	50-021
WETTERHAHN, M. J. WETTERHAHN, M. J.	7810310017 7811220159	50-395 0 50-510 0	WILLIAMS, D. H. WILLIAMS, D. H	7810100023 7810110137	50-348 8 50-348 8	WILSON, S. M.	7810170142	50-366
WETTERHAHNIM. J.	7612040331	50-272 0	WILLIS, E	7810130124*	50-324 R	WILBON, J. N. WILBON, F. R.	7810200231 7811070152	50-322 50-344
HETTERHAHN M. J.	7812130025	50-375 0	WILLIAMS, D. H.	7810170143	50-313 8	WILSON, B. D.	7811170137	50-352
WETTERHAHNIH.J. WETTERHAHNIH.J.	7612130299 7812180400	50-356 G 50-395 G	WILLIAMS D. H. WILLIAMS D. H	7810170190	50-368 8	HILSON, K. R.	7811080141*	50-270
WETTERHAHNIM J.	7812180301	50-272 0	WILLIAMS, D. H.	7811210125 * 7810200067	50-313 G 50-313 R	WIĽBON, 8. WIĽBON, 8.	7811160068* 7811160110*	50-321 50-346
WHARTON: A.	7811160018	50-466 G	HILLIAMS, P. M	7810190014	50-267 P	WILSON, K. R.	7811220188*	50~269
WHARTON, A.	7811160155	50-466 G	WILLIAMS D. H.	7810230200	50-313 J	HILBON, K.R.	7811300174*	50-270
WHEELER, J. R. WHIDDON, D.	7812170112 7810310025	50-320 H 50-14 P	WILLIAMS, C. C. WILLIAMS, D. H.	7811200034 * 7810190039	50-324 G 50-368 P	WILBON, K. R. WILBON, T. R.	7812010245# 7812050101	50~249 50~244
HHITAKER M. S.	7811210397	50-395 A	WILLIAMS D. H.	7810190087	50-368 P	WILBON, F. R.	7812110169	50-344
WHITENER, H. L. WHITENER, H. L.	7811010428# 7810130051#	50~280 @ 50~366 @	WILLIAMS, D. H. WILLIAMS, D. H	7811060145 7811060175	50-368 8 50-313 8	WILSON, K. R.	7812180196*	50-270
						MILSON. B	7612150294*	50-321
MHITE。J.R. MHITE。J.R.	7811070038* 7811300250*	50-317 G 50-334 G	WILLIAMS, D. H. WILLIAMS, D. H.	7811080303 7810240130	50-348 P 50-348 P	WILSON, 8. WILSON, K. R.	7812130347* 7812130172*	50-366 50-267
HHITE, L.D.	7810160111+	30-244 P	WILLIAMS, D. H.	7B10⊋40098	50-313 P	HILBON, K. R.	7812190156#	50-287
WHITE: L. D. WHITE: L. D.	7810160129 7810230256	50-244 P 50-244 0	WILLIAMS, D. H. WILLIAMS, D. H.	7610240135 7810250098	50-368 P 50-313 P	HILBON, J. N. HILBON, K. R.	7812200134 7812190130+	50-322 50-269
HHITE, L. D.	7810170162	50-244 P	WILLIAMS, D. H.	7810310075	50-368 P	HILBON, J. N.	7812200131	50-355
WHITE, L. D.	7810170257	50-244 F	WILLIAMS, D. H.	7B11070010	50-368 8	WILBON, K.R.	7812290218*	50-287
HHITE, L. D. HHITE, L. D.	7810170243* 7810180150*	50-244 P 50-244 P	WILLIAMB, D. H. WILLIAMB, G. C.	7810250149 7811280032+	50-368 F 50-331 G	HILT, D. D. Wilt, D. D.	7810240016# 7811240072#	50-440 50-440
HHITE, L. D.	7810190049*	30-244 P	WILLIAMS, C. C.	7811210024	50-331 0	WIBNER, C. E.	7811070308*	30-445
WHITENER, H. L.	7B12120237#	50-250 G	WILLIAMS O. H	7812010182+	50-160 Q	WISNER, C. E.	7812270020#	50-313
WHITE: A. White: A.F.	7811160048 7811200150	30-549 Q 50-549 Q	WILLIAMS D. H. WILLIAMS D. H.	7810310119 7811130327#	80-313 R 50-313 G	WITHERS.B.D. WITHERS.S.D.	7811070286 7810170144	50-344 50-344
WHITE, L. D.	7811060088	50-244 P	WILLIAMS D. H	7811060075	50-313 P	WITHERS.B.D.	7810200107	50-344
WHITE, L. D.	7811070142	50-244 P	WILLIAMB D. H.	7811030106	50-313 P	WITHERS, B. D.	7810310167	50-344
HHITE, L.D. HHITE, L.D.	7811070102 7811130232	50-244 P 50-244 P	WILLIAMS, D. H. WILLIAMS, D. H.	7811030159 1 7811060154	50~313 P 50~313 B	WITHERS, B. D. WITHERS, B. D.	7811070193 7811140139	50-344 50-344
HHITE A.F.	7812040133	50-549 G	HILLIAMB, D. H.	7811080134	50-313 P	WITHERB.B.D.	7812080079	50-344
WHITENER, H. L.	7812140277*	50-335 G 50-244 P	HILLIAMS, D. H.	7811080174	50-369 P	NITHERS, B. D.	7812120149	50-344
WHITE, L. D.	7811140241		WILLIAMS, D. H.	7811130264		WITKOWSKY, F. P.	7810160116*	50-334
HHITENER, H. L. HHITE, L. D.	7812180345* 7811270245	50-324 G 50-244 J	WILLIAMSON, T. O. WILLIAMS, D. H.	78110B0179 7811170065	50-62 P 50-313 F	WITKOWSKY, F. P. WITKOWSKY, F. P.	7811160111# 7812110132#	50-334 50-334
WHITE, L. D.	7811280216	50-244 P	WILLIAMS, D. H.	7811030151	50-313 R	WITTEN, A. J.	7810140076	50-395
WHITENER, H L. WHITE, L.D.	7612070148* 7811290179	50-321 4 50-244 P	HILLIAMS, D. H. HILLIAMS, D. H.	7811130190 7811200145	50-313 F 50-368 B	HIZNERID. O. HIZNERID. O.	7811140232+ 7812270226+	50-316 50-315
WHITE: L. D.	7612050152	50-244 P	WILLIB, E	78111600740	50-324 R	HOESBNER, J. D.	7810240094+	50-133
WHITE L.D.	7812050152 7812050187	50-244 P	WILLIB, E. WILLIAMS, D. H.	78111600Y4# 7811200189	8 BAC-08	WOESSNER, J. D.	7612070296*	50-206
WHITE, L. D.	7812080123	50-244 P	WILLIAMB, D. H.	7B11090160	50-368 P	WOEBBHER, J. D.	7812140039*	50-312
HHITE, L.D. HHITE, A.F.	7812080128 7812270454	50-244 P 50-549 0	WILLIAMS, D. H. WILLIAMS, D. H.	7811090170 7811200176	50-313 F 50-313 B	HOESSNER, J. D. HOESSNER, J. D.	7812270456* 7812280358*	50-133 50-344
MHITE, L.D.	7812220118*	50-244 P	WILLIAMS D. H.	7811160061	50-368 B	WOFFORD, A. W.	7810230133+	50-322
WHITE, L.D.	7812130012	50-244 F	WILLIAMS D. H.	7611160129	50-313 P	HOPFORD, A. H.	7811140234+	50~322
HHITE, L.D. HHITLER, J.D.	7812290090 7810240214	50-244 P 50-498 M	WILLIAMS, C.C. Williams, D.H.	7812130134* 7812060211*	50-33; @ 50-349 G	HOFFORD, A. H. HOFFORD, A. H.	7811280044 7812290258+	20-322 20-322
WHITLOW, M.	7811080068	00-556 A	WILLIAMS D. H	7811170207	50-368 P	WOFFORD, A. W.	7812270478#	20-355
WHITHER C. F.	7810100039	50-321 F	HILLIAMS D. H.	7811210331	50-348 P	HOFFORD, A. H.	7812260136	50-322
WHITMER.C.F. WHITMER.C.F.	7810170166 7810170170*	50-366 K 50-366 K	WILLIAMS D.H. WILLIAMS D.H.	7811280209 7812210519	50-348 G	HOLCH, H. HOLCH, H.	78110800564 78121403024	50-70 50-70
WHITMER, C. F.	7810110089	50-321 Q	WILLIAMS, D. H.	7811270138	50-348 B	HOLF, J. F.	7811090219	30-51B
WHITMER, C. F.	7810110135	50-346 P	WILLIAMS, D. H.	7812130321#	50-313 0	WOLF J. F.	7812140041	50-261
WHITMERIC.F.	7810160104 7810240110	50-321 P 50-321 P	Williamb, D. M. Williamb, D. M.	7811280232 7811300244	50-348 P 50-348 P	WOLFE, B. J. WOLFE, B. J.	7810270345= 7810140033	50-344 50-437
WHITMER, C. F.	7810270101	50-366 P	HILLIAMS, D. H.	7812210220*	50-313 G	HOLFE, S. J.	7810160221	50-344
WHITHER:C.F. WHITHER:C.F.	7811170205 7811280223	50-321 J 50-321 F	Williams D.H. Williams G.H.	7812210226# 7812140059#	50-368 G 50-269 G	WOLFE: 8. J. WOLFE: 8. J.	7610230109 7810230240	50-344 50-556
WHITMER C. F.	7811300192	50-424 A	WILLIAMS, D. H.	7812040236	50-313 P	WOLFE, S. J.	7810200243	30-556
WHITMER, C. F.	781208009B	50~366 A	WILLIAMS, D. H.	7812120131	50-313 B	WOLFE B. J.	7810200239	50~556
WHITMER.C.A. WHITTEMORE,F.C.	7812270274 7810160201	50-321 P 50-322 9	HILLIAMS, J.L.	7812120105 7812150332#	50-514 A 50-324 R	WOLFE, B. J. WOLFE, B. J.	7810200234 7811030238	30-854 30-354
MHITTEMORE, F. C.	7810270394	50-322 A	Willibje Williamb, D. H.	7812150332# 7812140124	50-313 P	HOLFE, S. J.	7811010227	50-437
HHITTEMORE F. C.	7810200059*	50-516 0	WILL JAMB, D. H.	7812280125	90-313 N	HOLFE, B. J.	7811010419	80-466
WHITTEMORE, F. C.	7610230180 7810240042	50-322 0 50-511 0	Williams, D. H. Williams, D. H.	7812120136 7612140133	50-313 R 50-368 S	HOLPE, 8, J. Holpe, 8, J.	78110 70330 7811200125	50~556 50~344
HHITTEMORE, F. C.	7812110281	50-325 6	WILLIAMS. D. H.	7812190151	50-368 R	HOLFE: B. J.	7811090208	50~466
MHITTEMORE, F. C.	7812280333	50-325 8	WILLIAMS, D. H.	7812290160	50-368 8	WOLFE, B. J.	7811080216	30~466

50~463 50~463 50~395 50~568

50-582

HAH

WILLIAMSON, T. O.

WILLIAMS, D. H. WILLIAMS, D. H. WILLIAMS, D. H. WILLIAMSON, T. G.

7811220141

7811220172 7812200145 7812200190

7812200249

WICKSTRON 8.

WICKSTROM, 8, WIESEMANN, R. A. WIESEMANN, R. A. WIESEMANN, R. A.

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEOURY	AUTHOR	ACCESSION SUB NUMBER CAT
HOLFE, S. J.	7811200312	50~437 0	YORE, J R	7812140315	50-514 0	Z IEMANN, D. L.	7811130297 50-2
WOLFE, S J	7811290301	50-556 G 50-556 G	YORE, J. R. YORE, J. R	7812210306 7812210306	50-592 G 50-514 G	Z IEMANN, D. L. Z IEMANN, D. L.	7811140053 50-2
HOLFE, 8 J. HOLFE, 8. J.	7812010375 7812060047	50-555 G	YORK, R N.	7811240048*	20-54 1	ZIEMANN, D. L.	7811140095* 50-2 7811140097* 50-2
WOLFE, S. J	7812110266	50-465 0	YOUNGDAHL, R. C.	7812040174+	50-255 0	ZIEMANN, D. L.	7811140053* 50-2
HOLFE, S. J.	7812130056	50-556 T	YOUNG C.	7812290268#	50-556 0	ZIEMANN, D. L.	7811130321 50-2
WOLFE, S J	7812130060 7812130364	50-556 T 50-556 T	YOUNG, R.H. YOUNG, R.H.	781012009& *	50-245 B	Z I EMANN, D. L. Z I EMANN, D. L.	7811130441 30-4 7811150270 50-4
HOLFE, S. J HOLFE, S. J	7812200325	50-556 T	YOUNG . R. H	7810200072*	50-245 S	ZIEMANN,D L.	7811240090 50-2
HOLFE, B J	7812200320	50-356 T	YOUNG R.	7610200088*	50-245 R	ZIEMANN.D L	7811170297 50-2
WOLFE, B. J.	7812200324	50-556 T	YOUNG R. H	7810230210*	30~245 9	ZIEMANN, D. L.	7811210223 90-2
WOLFE, B. J. WOLFE, B. J.	7812200321 7812280359	50-556 T 50-556 G	YOUNG . T YOUNG . R.	7811220267 * 7811170115•	90-275 G 50-245 R	ZIEMANN.D.L ZIEMANN.D.L	7611270071 50-1 7611270073* 50-1
WOLF INGER, P. A	7810170321*	50-366 5	YOUNG R.H.	7811140191+	50-245 \$	ZIEMANN, D. L.	7811270081* 50~1
HONO, H. J	7812010303+	50-317 9	YOUNG I R. H.	7811140093*	50-245 8	ZIEMANN, D. L	7811270132 50-2
WONG, H J.	7812010136*	50-219 Q 50-333 Q	YOUNG, T. YOUNG, R. H.	7812150004* 7811210271*	50-275 G 50-245 B	Z SEMANNI D. L.	7611290095 50-2
NONG, H. D NOOD, M	7812060367* 7810300165*	50-514 Q	YOUNG R. H.	7812080118*	50-245 B 50-245 9	ZIEMANN, D. L. ZIEMANN, D. L	7811290099* 50-2 7811290106* 50-2
WDOD, E. C.	7811030137 7810230007	50-307 B 50-498 M	YOUNG R.H. YOUNG R.A.	7812080129* 7812210225*	50-245 8 50-275 A	ZIÉMANN, D. L.	7811280080 50-2
MDOD, J C		••				Z IEMANN. D. L	78112800B2¥ 50-2
WOOD, E. C. WOOD, E. C.	7811030131 7811220213	50-309 S 50-309 S	YOUNGBLOOD, J. YOUNG, R. H	7812140138 7812260219+	50-592 A 50-245 B	ZIEMANN, D. L. ZIEMANN, D. L	7811240086 50-4 7811270140 50-1
MDOD, J. C.	7812130104	50-498 M	YOUNG R. H.	7612290212	50-245 8	ZIEMANN, D. L.	7811270140 50-1
HOOD, E. C. HOOD, J. C	7811220200 7812280176	50-309 S 50-498 M	ZARAKAB,P. ZARAKAB,P.	7811060238* 7812070180	50-3 G 50-3 P	ZIEMANN.D.L. ZIEMANN.D.L.	7812040069 50-2 7812040007 50-2
WOOD, E. C WOOD, E. C	7812200213 7812200252	50-309 6 50-309 8	ZAVADOSKI,R W. ZAVADOSKI,R,W.	7811240081* 7812280348*	50-302 0 50-250 0	ZIEMANN, D. L. ZIEMANN, D. L.	7812040012* 50-2 7812060377 50-1
HDODARD. J	7611130232	50-536 Q	ZECH. @ 0	7811220259	50-272 P	ZIEMANN. D. L.	7812060420 50-2
WOODARD, J. 18 WOODHEAD, C. P.	7811240083 7811290026	50-536 G 30-536 G	ZELINBKY, W. M ZELL, J.	7812150183 7810230275*	50-387 M 50-346 B	ZIEMANN, D. L. ZIEMANN, D. L.	7812060297 50-2 7812110135 50-2
MOODHEAD, C. P. MOODHEAD, C. P.	7810110035 7810140025	50-40 <i>9 0</i> 50-556 0	ZELL, J. Ziemann, D. L	7612190116* 7610250198	50-346 6 50-237 P	Z JEMANN, D. L. Z JEMANN, D. L.	7812110139* 50-2 7812130156 50-2
HOODHEAD, C. P.	7810240036	50-409 G	ZIEMANNID L. Ziemannid L	7811100010	50-219 P	Z I EMANN, D. L.	7812130334 50-2
WOODHEAD, C. P. WOODHEAD, C. P.	7811060083 7811150228	50~556 G 50-409 G	ZIEMANN.D. L.	7811100013# 7811090202	50-219 P 50-219 S	ZIEMANN, D. L. ZIEMANN, D. L.	7812130345= 50-2 7812070028 50-2
WOODHEAD, C. P	7811150277	50-409 0	ZTEMANNID. L.	7811130304	50-244 P		
NOODHEAD, C. P.	7811280463	50-409 0 50-219 0	ZIEHANN D. L.	7811130304	50-206 P	ZIEMANN, D. L. ZIEMANN, D. L.	7812140316 50-2 7812140318+ 50-2
WOODHEAD, C. P. WOODHEAD, C. P.	7612050085 7612050254	50-219 0 50-510 0	ZIEMANN.D. L. ZIEMANN.D. L.	7810200026 7810200029*	50-206 P	ZIEMANN.D.L.	7812140339* 50-2
WOODHEAD, C. P	7812040319	50-409 G	ZIEMANN.D. L.	7810110070	50-245 P	ZIEMANN, D. L. ZIEMANN, D. L.	7812110004 50-2 7812110011 50-1
WOODHEAD, C. P.	7812110286	50-466 0	ZIEMANNID. L.	7810110073*	50-245 P	ZIEMANN, D. L.	7812110019 50-2
WDODHEAD, C. P.	7812130051	50-466 C	ZIEMANN, D. L.	7810190045	50-219 P	ZIEMANN.D.L.	7812110019 50-2 7812110038 50-2
HOODHEAD: C. P. HOODHEAD: C. P.	7812130365 7812180407	30-466 G 30-556 G	ZIEMANN.D.L. ZIEMANN.D.L.	7810270404 7810270410+	50-213 P 50-213 P	ZIEMANN, D. L. Ziemann, D. L.	7812110041 50-2
WOODRUFF, R. W.	7811280016	50-331 P	ZIEMANN.D. L.	7810270422*	50-213 P	ZIEMANN, D. L.	7812110056 50-2 7812110061 50-4
HOODS, D. C.	7810230174+	50-339 R	ZIEMANNID. L.	7610190138	50-29 P	ZIEMANN, D. L.	7812110066 50-2
H0008, J. H0008, D. C.	7811020251+	50-187 P	ZIEMANN.D.L.	7810190169*	50-29 P	ZIEMANN, D. L.	7812110326 50-2
WDDD8, D. C.	7811170109* 7812200257*	50-338 R 50-338 R	ZIEMANN.D. L. Ziemann.d. L.	7810190182* 7810250018	50-29 P 50-244 F	ZIEMANN.D.L. ZIEMANN.D.L.	7812110328 50-2 7812140292 50-2
MD008+ D. C.	7812200255*	50-338 R	ZIEMANN.D. L.	7810250012	50-206 P	ZIEMANN, D. L.	7812140304# 50-2
HOODWARD, J. R	7811270193	50-554 G	ZIEMANN, D. L	7810310019	50-409 P	ZIEMANN, D. L.	781214030B+ 50-2
WOOLEVER, E. J. WOOLEVER, E. J.	7811280458* 7811070377*	50~412 B 50~412 B	ZIEMANN.D.L ZIEMANN.D.L.	7810310021 7810310024	50-213 H 50-10 H	Z IEMANN, D. L. Z IEMANN, D. L.	7812110055 50-1
HOOLEVER, E J.	7812140109	50-334 F	Z IEMANN, D. L.	7810310027	50-155 P	ZIEMANN, D. L.	7812130281 50-1 7812140024 50-2
WOOLEVER, E. J	7812190144	50-334 F	ZIEMANNID, L.	7810310034	50-219 H	ZIEMANN, D. L.	7912140027* 50-2
WORTHINGTON, J. D WRIGHT, R. W	7812210386	50-275 B	ZIEMANN, D. L.	7810310037	50-245 H	ZIEMANN, D. L.	7812140034* 50-2
WRIGHT, Q. C.	7810230239 7811130010*	50-553 G 50-331 G	ZIEMANN, D. L. ZIEMANN, D. L.	7810310159 7810310173	50-29 H 50-244 H	ZIEMANN, D. L. ZIEMANN, D. L.	7812130322 50~2 7812150072 50~2
WRIGHT, R. W.	7811290323*	50-566 @	Z IEMANN. D. L.	7810310298	50-219 P	ZIEMANN, D. L.	7812150077* 50-2
HRIGHT, Q. C.	7812070078*	90-893 G	Z I EMANN. D. L	7811010051	50-206 H	ZIEMANN, D. L	7812150086# 50~2
WRIGHT, Q. C. WRIGHT, R. W.	7812200109* 7812110313*	50-263 G 50-364 G	ZIEMANN.D.L. ZIEMANN.D.L.	7811020392 7811020395*	50-409 P 50-409 P	ZIEMANN, D. L.	7812130330 50-2 7812190176 50-2
WRIGHT, R. W.	7812290070*	50-438 Q	ZIEMANN.D.L.	7811080275	50-10 P	ZIEMANN.D.L ZIEMANN.D.L	7812190176 50-2 7812210295 50-2
L'AGIOUN L'AGIOUN	7811090142* 7811090119*	50-237 B 50-237 B	ZIEMANN, D. L. Ziemann, D. L.	78110200 33 7810270278	50~206 P 50~255 P	ZIEMANN, D. L. ZIEMANN, D. L.	7812210301* 50-2
HUJCION, J.							7812210312* 50-2
J. AO1DLUM	7811090130* 7811140163*	50-237 8 50-237 8	Z IEMANN, D. L. Z IEMANN, D. L.	7810270286* 7810270293*	50-255 P 50-255 P	Z IEMANN, D. L. Z IEMANN, D. L.	7812140299 50-2 7812140314 50-4
HUJCIGA,J.	7811160125* 7811210304*	50-237 B	ZIEMANN.D.L.	7810310147	50-244 P	ZIEMANN, D. L.	7812140361 50-1
HULLER, Q. E.	7811210304 4 7812080228	50-237 B 50-461 G	ZIEMANN.D.L. ZIEMANN.D.L.	7811100105 7811090039	50~10 P 50~155 P	ZIEMANN, D. L. ZIEMANN, D. L.	7812270046 50-2 7812210078 50-1
YANICHKO B. E.	7812080142*	50~306 P					
YANICHKO, S. E.	7811140133*	50~266 P	Z IEMANN. D. L. Z IEMANN. D. L.	7811090071* 7811090088*	50-155 P 50-155 P	ZIEMANN,D.L. ZIEMANN,D.L.	7812130005 50-1 7812130093 50-2
YELDERMAN, J. C. YIN, I. T.	7811200128 7811090006#	50-466 G 50-341 G	ZIEMANN.D.L. ZIEMANN.D.L.	7611070302	50-213 P	ZIEMANN, D. L.	7812150099 50-1
YIN, 1, T.	7B11090007#	50-341 G	ZIEMANN, D. L.	7811070307* 7811070313*	50-213 P 50-213 P	Z IEMANN, D. L. Z IEMANN, D. L.	7812150101 50-2 7812150105 50-2
YIN. I. T.	7011020111+	50-315 G	ZIEMANN, D. L.	7811080334	50-237 Q	ZIEMANN, D L.	
YIN, I. T. YIN, I. T.	7811170264*	50-358 G	ZIEMANN.D.L.	7811100027	50-29 P	Z IEMANN, D. L.	781215010B 50-2 7812150111 50-4
YIN, I. T.	7B11140054# 7B11300260#	50-329 G 50-358 G	ZIEMANN,D,L. ZIEMANN,D,L.	7811100141 7811100152	50-206 P 50-244 P	ZIEMANN, D. L. ZIEMANN, D. L.	7812150115 50-2
YIN, I. T.	7812210131#	50~266 Q	ZIEMANN.D.L.	7811100156	50-217 P	ZIEMANN, D. L.	781221001B 50-2 7812210021 50-2
YORE, J. R.	7810230030+	50-70 Q	ZIEMANN, D. L.	7811100142	50-409 P	ZIEMANN, D. L.	
YORE, J. R. YORE, J. R.	7810140128 7810260195	50-35B Q	ZIEMANN.D.L.	7811130047	50-155 P	ZIEMANN, D. L.	7819210034 50-2
YORE, J. R.	7811170009	50-341 Q 50-450 ₽	ZIEMANN.D.L. Z <i>iemann.d.</i> L	7811140014 7811060164	9 01-06 9 912-06	ZIEMANN, D. L. ZIEMANN, D. L.	7812210047 50-2
YORE, J. R.	7812040346	50-522 G	ZIEMANN,D. L.	7811170051	50-206 P	TIEMANN, D. L.	7812210050* 50-2 7812210055* 50-2

EMANN, D. L	7812210095	50.514	P	ZUFELY, E.	7810130132*	50~333	R
EMANN, D. L	7812260289*	50-249	P	ZUFELT. E	7811140123*	50~333	R
EMANN.D L	7812270048	50-219	P	ZUFELT.E	7812150274*	50~333	R
EMANN+D. L.	7812270039	50-155	P	ZULL, L M	7810170114	50~333	P
EMANN, D. L.	7812270147	50-255	P	ZULL, L. M	7812120082*	50~333	P
MMERMANNIC. J.	7812010205	50-395	Α	ZULLA, S G	7812150241+	30-286	R
MMERMAN, R P	7811290389#	50-272	a	ZWETZIG.G B	7610200228	50~289	Q

ZWETZIO.O B.

7812280267* 50-269



CORPORATE SOURCE INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

An asterisk following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
			0		7811140152	50-348	P
Abbatt, H. 8	7012010042+	50-471			7811140225	50-34B	8
Adams, D. B.	7812270075*	50-485	a		7811140233+	50-348	8
	7812270076#	50-485	0			50-348	8
	7012270001	50-485	٥		7811140237+		8
Advisory Council on Historic Preservation	7010240109	50-546	A		7811140242+	50-348	8
Agriculture, Dept of	7812140168	50-361	n		78111402464	50-348	8
Air Force Dept. of	7810260147	50-320	P		7811140251+	50-348	
MIT Purcer Dope, or	7811030174	50-320	P	•	7811160085	50-34B	R
	7012270033*	50-320	9		7811160090+	50-348	R
Akin, Gump, Haver & Feld	781026000B	50-498	M		7811170038	50~348	a
•	70.00.100.00	50-498	M		7811210176	50 -348	R
	7812040050		H		7811210179*	50-348	R
	7812270416	50-498			7811210258	50-34B	F
Alabama Power Co	7810100066	50-34B	8		7811210355	50-348	8
***	7810100072*	50-34B	8		7811210338+	50-348	é
	7810100085	50-348	В		, # 1 1 1 1 1 0 3 3 3 ·	•	
	78101000B6*	50-348	8		7811270176	50-348	P
	7810110102	50-346	P		7811280258	50-348	
	781013004B	50-348	G		7811280267	50-348	8
		30-348	Ř		7811280272*	50-34B	8
	7810180079 7810180082*	50-348	Ř		7811280283	50-348	P
			_		7811280336	50-348	8
	7810180097	50-34B	8		7811280339+	50-348	8
	7810180100#	50~348	8		7811280342*	50-348	8
	7810180145	50-348	8		7811280348	50-34B	8
	7810180149*	50-348	8		7812010253	50-348	ä
	7810180151	50-348	В		\81\$010833		
			_		7812010254#	50-348	9
	7810180154*	50-348	8		7B12030010+	50-348	Q.
	7810200077	50-348	8		7812050159	50-348	P
	7810200081*	50-348	9		7812070022+	50-364	G.
	7810200085#	50-348	8		7812080324	50-348	8
	7810200089	50-348	8				
			_		7812110134	50-348	8
	7810250112	50-348	8		7812110138*	50-348	8
	7810250114#	50-346	8		7812110307	50-364	G
	7810250141	30-348	8		7B12130131	50-348	P
	7810250145*	50-346	8		7812140117	50-348	Q
	7810250229	50-34B	G				_
			^		7812180351+	50-348	a
	7810250238	50~348	Q.		7812200163	50-348	8
	7810270311	50-34B	8		7812200165+	50-348	8
	7810310070	50-348	P		7812210202	50-348	R
	7810310131	50-34B	8		7812210212+	30-348	R
	7810310135	50-348	8				F
		8024.4	0		7812270169	50-348	S
	7811020351	50~364			7012270278	50-348	8
	7811070229	50-34B	Q.		7812270283+	50-348	
	7811080140	50-348	P		7812270306	50-348	. 9
	7811080159	50-348	F		7B12270308	50-348	. 8
	7811070111	50-348	F		·	50-348	9
	7611090111	50~349	f		7812270309+ 7812270311+	50-348	8
		50-348	8		78122703134	50-348	8
	7811090183	50-348	ă			50-348	P
	7811090187#	50-348	8		7812290127	50-572	м
	78110901924		8	Allen, D. R.	7B11070315	J-376	•••
	7811090196#	50-348			7812180144	50-332	A
	7811090200#	50-348	8	Allied General Nuclear Services	7812180147	50-332	A
	7811130204	50-364	G	million	7810120062	50-316	
	7811130226	50-348	g	American Electric Power Co., Inc.	7810120067#	50-314	
	7811140111	50-348	P		7811080138	50-315	o o
		50-348	P				
	7811140152	30	•				

			AFFILIATION	NUMBER	CATEGORY
American Nuclear Society Argonne National Laboratory	7811210446 7811020298• 7811130333• 7810230382 7812030222	30-315 G 30-39 P 50-284 P 30-267 G 50-329 D		7811060156# 7811060158# 7811060160# 7811060175 7811060180#	50-348 8 50-313 8 50-368 8 50-313 8
	7812050222 7812050225 7812050225 7812050227 7812050227	50-329 D 50-329 D 50-329 D 50-329 D 50-329 D		7811060183* 7811060189* 7811070010 7811080136 7811080176	50-313 8 50-313 8 50-368 8 50-313 P 50-368 P
	7812050232 7812050232 7812050239 7812050239 7812050244	50-329 D 50-329 D 50-329 D 50-329 D 50-329 D		7811080309 7811080310# 7811090160 7811090170 7811130190	50-368 P 50-368 P 50-368 P 50-313 F 50-313 P
	7812050244 7812050250 7812050250 7812050255 7812050255	50-329 D 50-329 D 50-329 D 50-329 D 50-329 D		7811130284 7811130284 7811130327* 7811160061 7811160062	50-313 P 50-313 P 50-313 0 50-348 8 50-313 P
Arizana Public Service Co.	7812200053 7810300181 7810310140 7810310140 7810310288•	50-70 P 50-528 A 50-592 I 50-592 I 50-528 Q		7811160063* 7811160064* 7811160121 7811160129 7811170069	50-348 8 50-313 P 50-368 P 50-313 P 50-313 F
	7810310294• 7810310365• 7811040087 7811090086 7811090086	50-528 Q 50-528 8 50-592 C 50-592 C		7811170207 7811200145 7811200149* 7811200176 7811200180*	50-368 P 50-368 8 50-368 8 50-313 8
	7811150130# 7811270150 7811270150 7812110126 7812170071	50-528 C 50-592 C 50-592 C 50-528 F 50-528 B		7811200189 7811200191# 7811210125# 7811210187 7811210192#	50-368 8 50-368 8 50-313 0 50-368 R 50-368 R
	7812190071 7812190071 7812190073* 7812190073* 7812190073*	50-528 B 50-528 B 50-528 B 50-528 B 50-528 B		7811210331 7811220134 7811220190 7811270138 7811270142#	50-368 P 50-368 P 50-368 P 50-368 B
	7812210114* 7812210114* 7812210114* 7812210119* 7812210119*	50-528 8 50-528 8 50-528 8 50-528 8		7811270144# 7811270146# 7811270149# 7811280208 7811280211#	50-368 8 50-368 8 50-368 8 50-368 8
Arizona. State of Arkansas Power & Light Co.	7812210117* 7812210132 7812140138 7810100018 7810100023	50-528 9 50-592 A 50-592 A 50-368 9 50-368 9		7811280232 7811300244 7812040236 7812040211# 7812120131	50-368 P 50-368 P 50-313 P 50-368 G 50-313 B
	7810100081 7810110137 7810110139* 7810110301* 7810120114	50-313 P 50-368 9 50-368 9 50-313 0 50-368 9		7812120137# 7812120138 7812120142# 7812130321# 7812140124	50-313 B 50-313 R 50-313 R 50-313 G 50-313 P
	7810170143 7810170146* 7810170149* 7810170190 7810170196*	50-313 8 50-313 8 50-313 8 50-348 8 50-348 8		7812140155 7812140164* 7812180120 7812180163 7812190151	50-348 8 50-368 9 50-313 P 50-348 P 50-348 R
	7810180091 7810180117 7810190039 7810190087 7810190096	50-572 A 50-368 P 50-368 P 50-368 P 50-368 P		7812190152* 7812200226 7812200229* 7812210135 7812210220*	50-368 R 50-368 B 50-368 B 50-313 0
	7810200067 7810200070* 7810230200 7810240078 7810240078	50-313 R 50-313 R 50-313 J 50-313 P 50-313 P		7812210226* 7812210518 7812270247 7812270249* 7812270299	50-368 0 50-368 9 50-313 9 50-313 9 50-368 9
	7810240130 7810240135 7810250056 7810250078 7810250149	50-368 P 50-368 P 50-592 8 50-313 P 50-368 F		7612270304* 7612270310* 7612280125 7612280127 7612290140	50-368 8 50-368 8 50-313 % 50-313 R 50-368 8
	7810310075 7810310119 7811030106 7811030151 7811030159	50-368 P 50-313 R 50-313 P 50-313 R 50-313 P	Armedillo Goalition of Texas Arnold & Porter Atlantic County, NJ	7812290164* 7812060038 7812060041 7811020381 7811280089	50-368
	7811060075 7811060145 7811060149* 7811060151* 7811060154	50-313 P 50-368 9 50-368 8 50-368 8 50-313 8	Babcock & Wilcox Co. Baher & Botte	7810120077* 7812200156 7810130097 7810130195 7810270392	50-329 A 50-13 G 50-466 G 50-466 G 50-469 G

7812040024	50-466	0		7812130170	50-318	6
7812040331	50-466	G .		7812130174	50-318	8
7812040367	50-498	ò			50-318 50-318	8
7812050037	50-466	0		76121301374		
7812050046	30-466	0			50-317	9
7812070058 7812110235	50-466 50-466	0			50-317 50-317	S 9
7812120224	50-466	Ğ		7812220076	50-317	R
7612130026	50-466	0		7812220076	50-317	R
7812130219	30-466	٥		7812220077+	50-317	R
7812180258	50-445	M		7812220077*	50-317	8 8
7810300062 7810270297	50-70 50-498	M		7812260244 7812260248+	50-318 50-318	8
7810100031	30-317	8	Bancroft, M. H	7812220040+	50-358	A
7810100058+	50-317	8	Bangor Hydro-Electric Co.	7811070145+	50-443	ı
7810110169	50-317	8	Battelle Memorial Institute	7810250121	50-360	J
7810110174» 7810130173	50-317 50-317	8 8	Battelle Memorial Institute. Columbus Laboratories	7810270097#	50-219	R
7810130176#	30-317	ë	Bechtel Corp.	78101601974	50-329	Q.
7410170147	90-210	P	Bechtel Power Corp. (subs. of Bechtel	7810120085+	50-387	S
7810170162 7810180073	50-318 50-318	é	Corp. 1			_
7810230148	50-317	P F		7810120091 7810170194#	50-344 50-250	e P
7810230162 7810230162	50~317 50-317	F		7810200075*	50-250	ρ
				7811090149# 7811090149*	50-329 50-329	A
7810230178 7810230178	50-317 50-317	R R				
7810230182*	50-317	R		7811090156#	50-329 50-329	A
7810230182# 781023024A	50-317 50-318	Ř		7811090156+ 7811100062+	50-367	8
7810230246		•		7812110273*	50-482	A B
7810250143	50-317	P P	Black & Veatch	7810310051	50-556	
7810260202 7810270235	50-317 50-317	8	Blum & Sheely	7811080060	50~369	0
7610270240*	50-317	8		7811290350 7812190112	50-369 50-320	н
7810310102	50-317	8	Boeing Co. Boston Edison Co.	7810170136	50-293	P
7810310105*	50-317	6		7810170160	50-471	٨
7810310197 7810310200>	50-317 50-317	9		7810170164+	50-471	A
7810310209	50-318	8		7810180113 7810180130	50-293 50-293	P
7810310216*	50-310	8		7810180131*	50-293	R
7810310271	50-317	F		7810230205	50-293	1
7811010113	50-317	8		7810230205	50-293	1
7811010116# 7811030112	50-317 50-317	8		7810250107	50-293 50-293	P
7811030117#	50-317	8		7810270105 7810310158	50-293	В
7811040133	50-318	8		7810310163*	50-293	8
7811060155	50-318	8		7811070004+	50-471	٥
7811040141# 7811090030#	50-318 50-317	9		7811070185	50-293 50-293	P 8
7811130166	50-318	8		7811080152 7811080156*	50-273	8
7811130211	50-319	8		7811090140	50-471	I
7811130214*	50-318	9		7811090161	50-293	8
7811140164 7811140170#	50-318 50-318	8 8		7811090168#	50-293	9
7811130153	50-317	F		7811140132 7811140193	50-293 50-293	K 8
7811150189	50-317	F		7811140188*	50-293	8
7011150269#	50-317	a		7811140200	50-471	^
7811130269*	50-317	Q. P		7811140207	50-293	8
7811170121 7811170165	50-317 50-318	ä		7811140212# 7811130168	50-293 50-293	9 F
		8		7811210263	50-293	R
7811170171# 7811170179	50-318 50-318	8		7811210269*	50-293	R
7811170187#	50-318			7811210326	50-471	I
7811170197 7811200206	50-317 50-317	P		7611210341 7811210345#	50-293 50-293	8
		•		7811210345*	50-293	
7811200206	50-317 50-317	Р 8			50-293	8
7811210407 7811210409#	50-317	B		7811280333 7811280335+	50-293	8
7811240183	50-317 50-317			7812010050#	50-471 50-471	9
7811240183				7812010039# 7812040173	50-293	
7811240214	50-317 50-317			7812040176*	50-293	8
7011240214 7011240215	50-317	R		7812050185	50-293	. 8
7811240217*	50-317			7812030192=	50-273 50-273	
7811290264	50-317	-		7812050228 7812060223	50-293	
7811290267*	50-317			•	50-293	4
7811300196 7811300199*	50-317 50-317	-		7812080185 7812110166	50-293	P
7811300211	50-318	1 8		7812120135	50-293	
7811300223#	50-318	8		7812120141 + 78121801 68	50-293 50-293	
7812010295*	50-317			•		
7812010295#	50-317 50-317	, a		7812180172 * 7812200183	50-293 50-293	Я
7812080096 7812080123	50-317	, a		78122001834		
7812080125	50-317	, a				

Baldwin: W. A Balaugh: R. C. Daltimore Gas & Electric Co.

AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJEC CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
Brookhaven National Laboratory	7812210258 7812240218 7812240223+ 7810110074+ 7810270417+	50-293 50-293 50-293 50-245 50-213	Р К К Р Р		7811160092* 7811160094* 7811160119 7811160120*	50-325 B 50-324 R 50-324 R 50-324 R 50-261 R
Burndy Husty C-E Power Systems	7812120119 7812120125* 7812130386 7812270068 7811130099*	50-250 50-250 50-358 50-309	F P A P		7811160132 78111601334 7811160135 7811160137 7811160138	50-325 8 50-325 8 50-324 P 50-325 8 50-325 6
California Polytech State Univ. California, State of California, Univ. of, Berkeley	7812070666 7811060044* 7811220094 7812270171 7611300213	50-394 50-582 50-592 50-275 50-433	Р 0 Н J		7811160141* 7811160144* 7811170127 7811170209 7811170213*/	50-325 8 50-325 8 50-325 8 50-325 8
California, Univ. of, Davis California, Univ. of, Irvine California, Univ. of, Los Angeles California, Univ. of, Ban Diago Caroline Environmental Study Group	7810140043¢ 7812060143 7812080099 7811010388¢ 7811080060	50-213 50-326 50-142 50-275 50-369	U 8 P 0 0		7811170238= 7811170238+ 7811220177 7811220180+ 7811220183	50-324 Q 50-324 Q 50-325 P 50-325 P 50-325 B
Carolina Power & Light Co.	7810100029 7810100032+ 7810100043 7810100048+ 7810100049	50-324 50-324 50-261 50-261 50-325	8 6 8 8		7811220187* 7811260226 7811300165 7812010232 7812070065*	50-324 8 50-400 F 50-400 0 50-261 R 50-261 0
	7810100053# 7810110108 7810110110 7810110110 7810110229#	50-325 50-261 50-324 50-324 50-261	8 P P Q		7812070165 7812070168* 7812070175 7812070181* 7812070187	50-325 8 50-325 9 50-324 8 50-324 8 50-400 8
	7810110242+ 7810130121 7810130121 7810130122 7810130122	50-324 50-324 50-324 50-324 50-324	Q R R A		7812070188* 7812070188* 7812070188* 7812070188* 7812070181	50-400 8 50-400 8 50-400 8 50-400 8 50-325 8
	7810130124* 7810130143 7810130143 7810130152 7810130156*	50-324 50-324 50-324 50-325 50-325	R P 8 8		7812070217* 7812080127 7812080130* 7812110133 7812130115	50-325 8 50-325 8 50-325 8 50-261 F 50-324 q
	7810130158 7810130162* 7810130177 7810130181* 7810130189	50-325 50-325 50-324 50-324 50-325	8 8 8		7812130251* 7812130296* 7812130383 7812140158 7812140160*	50-261 0 50-324 0 50-400 0 50-325 8 50-325 8
	7810160147 7810160149* 7810190270 7810230020* 7810230143	50-261 50-261 50-261 50-261 50-324	R R G B		7812140163 7812140165* 7812150330 7812150332*	50-261 8 50-261 8 50-324 R 50-324 R 50-324 R
	7810230146# 7810230193 7810230195# 7810240127 7810240249	50-324 50-324 50-324 50-324 50-324	8 8 6 0		7812150348 7812150351# 7812180334# 7812180334# 7812180334#	50-261 R 50-261 R 50-400 G 50-400 G
	7810250249 7810270111 7810270111 7810270123 7810270147	50-324 50-324 50-324 50-400 50-261	9 9 0 A		7812180334* 7819180335 7812170118 7812170123* 7812200178	50-400 0 50-324 0 50-261 J 50-261 J 50-324 S
	7810270215 7810270226* 7810300140 7810310122 7810310123	50-261 50-261 50-400 50-261 50-261	8 8 A G		7812200199* 7812200200 7812200201* 7812210181 7812210185*	50~324 6 50-324 8 50-324 8 50-325 8 50-325 8
	7810310127* 7810310139 7810310142* 7810310143 7810310133*	50-261 50-324 50-324 50-261 50-261	8 8 8 8		7812210187 7812210192* 7812210218 7812210222* 7812210319	50-325 8 50-325 8 50-325 8 50-325 8 50-400 0
	7810310210 7810310217 7810310219* 7810310222* 7810310232	50-261 50-324 50-261 50-324 50-324	8 9 8 8		7812210319 7812270192 7812270207 7812270257 7812270263*	50-400 G 50-324 P 50-324 P 50-261 B
	7810310236* 7811090013* 7811090109 7811090186 7811090191*	50-324 50-324 50-324 50-241 50-261	8 0 P 8	Cathey. Goodwin & Hamilton	7812270286 7812270292# 7812270298 7812270303# 7810240001	50-325 8 50-325 8 50-324 8 50-324 8 50-313 P
	7811090194 7811090197* 7811140216 7811160088 7811160091	50-325 50-325 50-400 50-325 50-324	9 8 8 R	Cathalic Univ. Center for Law in the Public Interest	7810170186 7810160135 7810190262# 7810190262# 7810190267#	50-77 P 50-275 G 50-275 G 50-275 G 50-275 G

AUTHOR AFF IL I ATION	ACCESSION NUMBER	BUBJECT CATEOOR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y_
	7810190267*	50-275	Q	Commerce Dept. of. National Bureau of Standards	7812060286*	50-184	G .
Cherry, M. M./Cherry, Flynn & Kanter	7810190269* 7810190269* 7812010048 7812060126	50-275 50-275 50-275 50-329	0	Commonwealth Edison Co.	7810100025 7810100027 7810100035 7810100078	50-295 50-237 50-373 50-10	P P R
	7812060126 7812060172* 7812060172* 7812280340*	50-329 50-329 50-329 50-329	0 0 0		7810110277 7810110291* 7810120036 7810120080	50-10 50-324 50-295 50-265	9 9 P F
Chickering & Gregory	7811060050	50-361	0		76101200B0	50-237	F
Cincinnati 9as & Electric Co.	7812010142 7812130093 7810110157 7811010169 7811010171	50-206 50-206 50-358 50-358 50-358	F H A K		7810120080 7810120080 7810130165 7810130170* 7810170172	50-265 50-265 50-237 50-237 50-265	6 6 7 8
	7811070370 7811090069 7811210170 7811220008 7812060016	50-358 50-358 50-358 50-358 50-358	0 К Ј 0 0		7810170180# 7810170181 7810170184 7810170184 7810170185	50-265 50-295 50-295 50-295 50-237	9 9 8 P
	7812070119 7812070147 7812150306 7812190084 7812190146	50-358 50-358 50-358 50-358 50-358	К Р К F А		7810170187* 7810170189* 7810170189* 7810170195 7810170198	50-295 50-295 50-295 50-249 50-245	8 8 8
	7812200148 7812200214 7812200218• 7812200228 7812210163	50-358 50-358 50-358 50-358 50-358	A K G		7810170202* 7810170203* 7810170204 7810170207 7810170208	50-265 50-247 50-10 50-275 50-304	8 8
Citizens Against Nuclear Dangers	7812270191 7612270305 7811010435> 7812260003 7812260008+	50-358 50-358 50-387 50-387 50-387	K Q Q Q		7810170211* 7810170212* 7810170214 7810170216* 7810170216	50-304 50-295 50-295 50-10 50-304	8 9 8
Citizens Concerned About Nuclear Power.	7812110054	50~498	e		7810170219	50-295	6
inc.	7812110054 7812110057* 7812110057* 7812210057*	50-498 50-498 50-498 50-331	0 0 0		7810170222* 7810170223* 7810170225 7810170227*	50-304 50-295 50-295 50-295	9 8 8
Citizens United for Responsible Energy Citizens for Energy & Employment	7810240023	50-341	0		7610170228*	50-295	9
Citizens to Preserve the Hudson Valley	7811080282 7812130191 7812130202* 7812180052	50-341 50-341 50-341 50-549	0 0 0		7810170231 7810170232 7810170234* 7810170235*	50-275 50-254 50-275 50-254	8
Cleveland Electric Illuminating Co.	7810100007 7810110261* 7811130230* 7811130230* 7811130230*	50-440 50-440 50-346 50-346 50-440	A G M M G		7810170239 7810170241 7810170242* 7810170246* 7810170231	50-304 50-275 50-304 50-275 50-304	8 8 8
Claveland, OH Coalition for Safe Power	7811270281 7811270281 7812070230# 7812150279 7811020037	50-440 50-440 50-440 50-346 50-344	G B M G		7810170253* 7810180049* 7810180050 7810180060 7810180086	50-304 50-295 50-295 50-295 50-273	8 R 9 P J
Coest Quard, Transportation, Dept. of	7811020235 7812260332 7810240003 7810240085 7811200083*	50-344 50-344 50-437 50-437 50-437	Q Q A A		7810180090* 7810180101 7810180104* 7810170148 7810170148	50-373 50-10 50-10 50-10 50-10	J R R P
	7811200102* 7811200276* 7811270166 7811270261 7812130387*	50-437 50-437 50-317 50-437 50-344	A P A P		7810200086 7810200092 78102000974 7810200113 7810200113	50-10 50-937 50-237 50-295 50-295	
Colt Industries, Inc.	7811090134* 7811090135*	50-423 50-423 50-423	8 9 8		7810230181 7810230181 7810230194	50-373 50-373 50-295	
Combs.Archer & Peterson	7811090136* 7811220237 7812040316	50-466 50-466	9		7810230256 + 7810230258 +	50-373 50-373	
Combustion Engineering, Inc.	7810190089* 7810190090* 7810190092* 7810300244 7811160077	50-368 50-368 50-368 50-470 50-470			7810240100 7810240101 7810240102+ 7810240116 7810240121+	50-249	. :
	7811290143 7811300213* 7812120074 7812120152* 7812200223*	50-470 50-361 50-470 50-470 50-309	K		7810240136 7810240141 7810240148 7810240150 7810240158	50-10	
Commerce, Dept. of	7612270163 7612270166* 7612290278* 7611210320	50-470 50-407 50-596 50-184	K B		7810250102 7810250102 7810250111 7810260153	50-295 50-296 50-254 50-10	5 1

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEQURY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUB CAT
	7810270180 7810270229 78102702314 7810270234 7810270236	50-237 P 50-249 8 50-249 8 50-237 8 50-237 8		781121038B 7811210342* 7811210410 7811220031 7811220033*	50-1 50-1 50-2 50-2 50-2
	7810270287 7810270296* 7810270302 7810270303* 7810300097	50-237 S 50-237 S 50-249 S 50-249 S 50-295 P		7811220033* 7811240127 7811240127* 7811240135 7811240139*	50-2 50-2 50-2 50-3
	7810300097 7810300190 7810310093 7811010009 7811010069	50-295 P 50-373 J 50-10 Q 50-10 9 50-295 P		7811240145 7811240147* 7811240153 7811240136* 7811240175	50 - 3 50 - 3 50 - 2 50 - 2 50 - 2
	7811010069 7811010131* 7811010141 7811010141 7811020258	50-295 P 50-295 R 50-295 R 50-295 R 50-373 K		7811240176. 7811240177* 7811240178* 7811240179 7811240181*	50-3 50-3 50-3 50-3
	7611020259+ 7611020322 7611020322 7611020322 7611020322	50-373 K 50-10 P 50-10 P 50-10 P 50-10 P		7811240192 7811240193* 7811240195 7811240196* 7811240197	50-2 50-3 50-3 50-2
	7811020322 7811020375# 7811020375# 7811030143 7811030145#	50-10 P 50-254 F 50-254 F 50-237 S 50-237 B		7811240178# 7811240200 7811240201# 7811240203 7811240204#	50-2 50-2 50-2 50-2 50-2
	781 1030161 781 1030161 781 1030161 781 1030161 781 1030161	50-10 P 50-10 P 50-10 P 50-10 P 50-10 P		7811240205 7811240204* 7811240207 7811240208* 7811240210	50-2 50-2 50-2 50-2 50-2
	7811030184 7811030191* 7811060120 7811060139 7811060162*	50-249 B 50-249 B 50-254 G 50-249 B 50-249 B		7811240211* 7811240212 7811240213* 7811240218 7811240220*	50~2 50~2 50~2 50~3
	7811070118 7811070118 7811070148 7811070148 7811070148	50-254 8 50-254 8 50-275 P 50-275 P 50-10 8		7811240221 7811240222 7811240223* 7811240224* 7811240227	50-2 50-2 50-2 50-2
	7811090116 7811090119* 7811090124* 7811090125 7811090126*	50-237 B 50-237 B 50-10 B 50-249 B 50-249 B		7811240229* 7811240237 7811240239 7811240240* 7811240241*	50~3 50~3 50~3 50~2 50~2
	7811090129 7811090130* 7811090138 7811090142* 7811130202	50-237 B 50-237 B 50-237 B 50-237 B 50-295 0		78:127007! 78:1270138 78:1270170 78:1280194 78:1280199*	50-1 50-1 50-1 50-1
	7811130202 7811140099 7811140105 7811140119 7811140119	50-295 Q 50-10 R 50-237 P 50-10 R 50-10 R		7811280213 7811280213 7811280213 7811280213 7811280213	50-: 50-: 50-: 50-:
	7811140160 7811140163* 7811140169* 7811140175 7811140175	50-237 B 50-237 B 50-10 R 50-373 H 50-237 9		7811280213 7811280246 7811280246 7811280246 7811280246	50-: 50-: 50-: 50-:
	7811140199+ 7811140203 7811140213+ 7811140213 7811140220+	50-237 I 50-237 B 50-237 B 50-237 B 50-237 B		7811280264 7811280264 7811280269* 7811280269* 7811280278	50-1 50-1 50-1 50-1
	7811140222 7811140227# 7811160112 7811160113# 7811160122	50-247 6 50-249 9 50-237 8 50-237 8 50-237 8		7811280301 7811280309* 7812040190 7812040191 7812040195*	50-1 50-1 50-1 50-1
	7811160125* 7811210177 7811210161* 7811210257 7811210301	50-237 8 50-237 8 50-237 8 50-237 P 50-237 8		7812040201 7812040201 7812040201 7812040201 7812040204*	50 50 50
	7611210304# 7611210314 7611210333 7811210339# 7811210356	50-237 S 50-454 A 50-249 S 50-249 S 50-237 S		7812040204* 7812040204* 7812040204* 7812040207* 7812040208	50 50 50 50

AUTHOR AFFIL IATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	CATE
	7812040210+ 7812040210+ 7812040212	50-454 50-454 50-456	00000		7812200219 7812200235 7612200241* 7812200241* 7812210189	50-25 50-25 50-25 50-25
	7812040214+ 7812040214+ 7812050100 7812050100 7812050107	50-456 50-456 50-373 50-373 50-10	С С К К Р		7812210195# 7812210203 7812210213# 7812210214 7812210217	50-23 50-29 50-29 50-29 50-30
	7812050107 7812050107 7612050107 7812060020 7812060020	50-10 50-10 50-10 50-254 50-254	0 9 0		7912210219# 7812210221# 7812210227 7812210228# 78122102284	50-29 50-30 50-29 50-29 50-29
	7812040059 7812040153 7812040153 7812070121 7812070121	50-456 50-373 50-373 50-454 50-454	9 F F К		7812210237+ 7812210242 7812210244 7812210245+ 7812210252+	50-24 50-24 50-24 50-24
	7812070121 7812070121 7812070172 7812070172 7812070185	50-454 50-454 50-237 50-237 50-434	K F F K		7812220093 7812220093 7812270223 7812270223 7812270261	50-2: 50-2: 50-2: 50-2:
	7812070185 7812070185 7812070185 7812070211 7812070211	50-454 50-454 50-454 50-275 50-275	К К Р Р		7812270271 * 7812270284 7812270289* 7812270300 7812270302*	20-5 20-5 20-5 20-5 20-5
	7812070223 7812080095 7812080114 7812110109 7812110109	50-440 50-295 50-10 50-373 50-373	8 P P A	Cannecticut Yankee Atomic Power Co.	7812270327 7812280280* 7812290210 7812290215* 7810130166	50-1 50-2 50-2 50-2
	7812110124 7812110129# 7812110144 7812110147# 7812110151	50-295 50-295 50-295 50-295 50-295	8 8		7810130169* 7810180134 7810180136* 7810240093 7810250106	50-2 50-2 50-2 50-2 50-2
	7812110154* 7812110157 7812110159* 7812110160 7812110161	50-295 50-295 50-295 50-295 50-295	8 8 8		7810250110* 7810260171 7810260182 7811030097 7811060103	50-2 50-2 50-2 50-2 50-2
	7812110163# 7812110164# 7812110175 7812110176 7812110178#	50-295 50-295 50-295 50-254 50-254	9 8 8		7811060107# 7811170208 7811170217 7811210282 7811210284#	50 - 6 50 - 6 50 - 6 50 - 6
	7812110179 7812110180* 7812110181 7812110182* 7812110183*	50-295 50-295 50-254 50-255 50-254	9 9 9		7811210308 7811210311* 7811210378 7811210385* 7811240163	50-: 50-: 50- 50-
	7812120070 7812120130 7812120134* 7812120135 7812120135	50-237 50-249 50-249 50-10 50-10	P 8 9 P		7811300212 7812050134 7812050160 7812050164* 7812180142	50- 50- 50- 50-
	7812120175 7812120175 7812120175 7812130126 7812130184	50-237 50-237 50-237 50-456 50-10		Connacticut, State of	7812210101 7812210201 7812210204* 7812220061 7810270157	50- 50- 50- 50- 50-
	7812130186* 7812150230 7812150230 7812150270	50-10 50-454 50-454 50-237	R K B	Conner, Maore & Corber	7810270313 7810310017 7811030038 7811220159 7811290066	50 50 50 50
	7812150272* 7812180145 7812180148* 7812180152 7812180174	50-249	9 9 8 R 8		7812040351 7812130025 7812130279 7812180301 7812180400	50 50 50 50
	7812180178 7812180177* 7812180178* 7812180210 7812180223 7812180228	50-10 50-249 50-10 50-237	8 8 7 8	Consolidated Edison Co. of New Yor	7812280197 7810100067 7810100071 7810110099 7810110153	* 50
	7812190109 7812190109 7812190109 7812190109 7812200195	50-10 50-10 50-10 50-10	j		7810110155 7810160103 7810160110 7810160113 7810160138	50)* 50)* 50

7810160165 7810200064 7810200064	50-3 50-3	5 R R	7810190233 7810230192 7810230192	30-255 30-329 30-329	K K
7610200064 7610230149 7610230150#	50-3 50-247 50-247	R R	7810230196* 7810230196* 7810230065	30-329 30-329 50-155	K K P
7810240108 7810240108	50-3 50-3	P P	7810250096 7810250099	30-133 30-133 30-329	8
7810240108 7810240108 7811040239*	50-3 50-3	•	7810250099 7810250100*	50-329 50-329	A
7811070120	50-3	P P	7810250100*	50-329	A
7811070157 7811070163+	50-247 50-247	P	7810270075 7810270142	50-155 50-329	P R
7811070221	50-247	8	7810270168	50-329	K
7811070230• 7811070274	50-247 50-247	8 F	7810310130 7810310133*	50-155 50-155	9
7811140255+ 7811170160	50~3 50~3	4 P	7811010165 7811020212	30-133 30-133	P P
7B11200155	50-247	F	7811020218*	50-155	Þ
7811200181 7811210340	50-3 50-3	F R	7811030136 7811030139#	50-155 50-155	8
7811210340 7811210344*	50-3 50-3	A R	7811060084 7811070149	50-155 50-329	C
7811220076	50-3	J	7811070183	50-255	s
7811220076 7811220153	50-3 50-3	J R	7811070204* 7811070210	50-255 50-255	8
7811220153	50-3	R	7811070217	50-155	8
7811280260 7811280270*	50-247 50-247	9 9	7811070218* 7811070224*	50-155 50-155	8
7812010206 7812010206	50-3 50-3	R R	7811070336	50-329 50-329	g
7812040229	50-247	8	7811090015 7811090143	50-329 50-329	A
7812070180 7812070180	50-3 50-3	P P	7811090203 7811090205*	50-155 50-155	8
7812070180 7812070182*	50-3 50-3	P P	7811090223*	50-155	8
7812070192#	50-3	p '	7611070226* 7811070229*	50-155 50-155	8
7812070182* 7812070182*	50-3 50-3	P P	7811090234 * 7811140146	50-155 50-155	8
7812190075	30-247	P F	7811140147	50-255	R
7812190102 7812190121	50-247 50-247	S	7811140148# 7811140150#	50-255 50-155	R
7812190131* 7812190174	30-247 50-3	9 P	7811140151* 7811140223	50-155 50-255	8
7812190174	50-3	P	7811140228+	50-255	В
7812190174 7812190180#	50-3 50-3	P P	7811150080 7811150080	50-329 50-329	9
7812190180* 7812190180*	50-3 50-3	P ·	7811150158 7811170212	50-155 50-329	P 8
7812200193	50-247	8	7811170222	50-329	9
7812200206 7812200208#	50-247 50-247	8 8	7811170222 7811170294	50-329 50-329	8
7812210207 7812210211*	50-3 50-3	R R	7811170294	50-329	C
7919210211+	50-3	R	7811170298* 7811170298*	50-329 60-329	C
7812270040 7812270188	50-247 50-3	G R	7811200079 7811200112	50-255 50-255	Q: R
7812270188 7812270188	50-3 50-3	R R	7811200121 7811200159	50-329 50-329	Ä
7810230156	50-327	A	7811210172	50-155	Р
7810100015 7810100019+	50-255 50-255	8 B	7811210330 7811210335#	50-255 50-255	9
7810110104 7810110106+	50-155 50-155	B 8	7811210337* 7811210337*	50-255 50-155	8
7810110111	50-255	P	7811210353	50-255	6
7810110119 7810110122*	50-255 50-255	R R	7811210369 7811210418	50-155	8
7810110164 7810180072	50-155 50-329	P A	7811220176 7811240170	50-329 50-135	9
7810120072	90-329	<u> </u>	7811240231	50-155	В
7810130137 7810130171	50-255 50-155	R 8	7811240235# 7811270094	50-155 50-155	8
7810130175# 7810130179#	50-155 50-155	B 9	7811270147	50-329	A
7810130103*	50~155	8	7811270147 7811270151*	50-329 50-329	A
7810140097 7810140194	50-155 50-329	P G	7811270151*	20-355	A
7810160196	50-329	Q	7811270152 7811270152	50-329 50-329	A
7810170217	50-155	8	7811280052	50-155	Q
7810170244 7810170248#	50-255 50-255	6 8	7811280124 7811280124	50-329 50-329	9
7810180095 7810190066	50-329 50-329	8 A	7811280282 7812010251	50-329 50-329	Č
7610190218	50-155	p	7812010252*	90-354	ĥ

Consulting Engineering Geologist Consumers Power Co.



	7812040164 7812040174# 7812040178#	50-255 50-255 50-255	K P G G B		7810100004* 7810120035 7810120039* 7810130229 7810160142	50~409 50~409 50~409 50~409 50~409
	7812040220 7812040237 7812040239+	50-155 50-155 50-155	8 P 8 8		7810160146* 7810160151* 7810230136 7810240123 7810240143	50-409 50-409 50-409 50-409 50-409
	7812050142 7812050167 7812050175#	50-329 50-255 50-255	P A 9 9 A		7810270300 7810310066 7810310080 7811070034 7811070316	50-409 50-409 50-409 50-409 50-409
	7812050224 7812060022 7812060024	50-155 50-255 50-255	A P Q Q Q		7811130206 7811130209# 7811170220 7811240233 7811270109	50-409 50-409 50-409 50-409 50-409
	7812070215 7812080192 7812080249 7812110122 7812110125*	50-155 50-329 50-255	P G G R R		7812010354 7812040216 7812040219# 7812070307 7812080137	50-409 50-409 50-409 50-409 50-409
	7812110171 7812110174* 7812110206 7812110210* 7812120068	50-155	8 6 8 8 A		7812080140* 7812110156 7812110158* 7812110165 7812110167*	50-409 50-409 50-409 50-409 50-409
	7812120068 7812120093 7812120097* 7812120100 7812120104	50-329 50-255 50-255 50-255 50-255	A 8 9 P A		7812120126 7812120132* 7812140162 7812200216 7812290161	50-409 50-409 50-409 50-409 50-409
	7812120104 7812120109 7812120111+ 7812120112+ 7812120164	50-327 50-155 50-327 50-155 50-327	A R A R K	Dalton, A.T. Dames & Moore Darling Valve & Mfg.	7812050052 7812130196 7812130341 7812010205 7812210396	50-556 50-556 50-556 50-395 50-482
	7612120162 7612120162 7612130133 7612130161 7612130161	50-155 50-155 50-155 50-155 50-155	Р Р Р	Day, Berry & Howard DeGraff, Foy, Conway & Holt-Harria	7811010166 7811160048 7811200:50 7812040133 7812040137*	50-245 50-349 50-349 50-549 50-549
	78\$2140080 78\$2140080 78\$2150261 78\$2\$50265* 78\$2\$70095	50-329 50-329 50-255 50-255 50-329	0 9 8 C	Depayoise & I,iberman	7812270454 7810110064 7810110279 7810120020 7810140030	50-549 50-397 50-445 50-369 50-488
	7812210230 7812210232* 7812220074 7812220075* 7812220104	50-255 50-255 50-155 50-155 50-255	8 8 9 9		7810140030 7810140030 7810140139 7810140139 7810140139	50-488 50-488 50-488 50-488 50-488
	7812220107# 7812260188 7812260188 7812260188 7812260212	50-255 50-329 50-329 50-255 50-155	8 A A P P		7810200001 7810200137 7810230389 7811070174 7811300008	50-397 50-498 50-369 50-498 50-443
	7812270146 7812270174 7812270180 7812270184 7812270198	50-255 50-255 50-155 50-329 50-155	K P G B R	Defanas/Dept. of	7812180278 7812200224 7812270141 7812270123 7811070351	50-498 50-445 50-397 50-445 50-70
	7819270254 7819280134 7819290146 7819290209 7819290907+	50-329 50-155 50-329 50-255 50-255	9 P 8 9	Defense, Dept. of. Defense Nuclear Agency Delawere, Univ. of Detroit Edison Co.	7810130227 7810230145 7810120021 7810130146 7810200111	50-170 50-98 50-16 50-341 50-452
Cooper Industries, Inc. Cornell Univ.	7812120121= 7708090684= 7810120038 7811060092 7812050290=	50-295 50-295 50-97 50-157 50-97	8 8 P H Q		7810310025 7811070096 7811070285 7811070076 7811070169	50-16 50-341 50-341 50-341 50-341
Coulee Region Energy Coalition	7610110288 7810250041 7810300204 7811200395 7812040263	50-409 50-409 50-409 50-409 50-409			7811090178* 7811210082 7811210299* 7811280231 7812260204*	50-341 50-341 50-341 50-341 50-341
Covington & Burling Deiryland Power Cooperative	7812270337 78122703374 7812270133 7812280051 7810100003	50-409 50-409 50-389 50-389 50-409	g M H	Diel.Jennings.Windham.Thomas & Roberts Dittert. J. L. Doc-Bearch Associates Dow Chemical Go.	7818210374 7810140085 7812210004 7810110098 7810300037	50-395 50-466 50-335 50-264 50-264

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER
Dube Power Co.	7812210077* 7810110084 7810110090 7810110090	50-245 P 50-367 A 50-369 A 50-287 P 50-287 P		7811020359 7811030221 7811030221 7811070214 7811080107
	7810110145 7810110145 7810110147* 7810130056 7810130096	50-369 A 50-369 A 50-369 A 50-269 G 50-413 G		7811080137 78110801414 78110802114 78110802114 7811090110
	7810130136 7810130174 7810130174 7810130174 7810140063*	50-269 P 50-269 P 50-269 P 50-269 P 50-488 9		7811100110* 7811100110* 7811100110* 7811100115* 7811100115*
	7810140066* 7810140127 7810140127 7810160101 7810160101	50-468 Q 50-369 0 50-369 0 50-369 A 50-369 A		7811100115* 7811130034 7811130354 7811130374 7811140114
	7810180076 7810180076 7810180196 7810180126 7810180126	30-369 A 50-369 A 50-269 F 30-269 F 50-269 F		7811140114 7811140114 7811150179 7811140065 7811160065
	7810190027 7810200007 7810200068 7810200068 7810200076	90-369 0 50-369 0 90-369 A 50-369 A 50-369 M		7811160065 7811160079 7811160079 7811160079 7811160134
	7810200082 7810200082 7810200082 7810200083 7810200083*	50-269 R 50-269 R 50-269 R 50-269 R 50-269 R		7811160134 7811160134 7811160133 7811220185 7811220188*
	7810200083 7810200115 7810200132 7810200132 7810200182	50-269 R 50-369 J 50-369 T 50-369 T 50-269 B		7811220231 7811220272 7811240063 7811270157 7811270157
	7810200170# 7610230029 7810230058# 7810230069 7610230159	50-269 8 50-369 0 50-369 0 50-488 0 50-269 P		7811270159# 7811270159# 7811270165 7811270165 7811270168#
	7810230214 7810230214 7810240002 7810240002 7810240002	50-413 G 50-413 G 50-269 R 50-269 R 50-269 R		7811270168* 7811280378 7811270227 7811300172 7811300174*
	7810240147 7810240147 7810240147 7810250089 7810250089	50-269 P 50-269 P 50-269 P 50-369 B 50-369 B		7812010143 7812010162 7812010168* 7812010244 7812010245*
	7810250093* 7810250093* 7810250119 7810250153 7810250200	50-369 8 50-369 8 50-413 A 50-269 P 50-369 Q		7812040147 7812040231 7812040231 7812040277 7812040277
	7810280217 7810230217 7810260081 7810260106 7810270072	50-413 Q 50-413 Q 50-413 Q 50-369 Q 50-267 P		7812040281# 7812040281# 7812040328# 7812040328# 7812040328#
	7810270076* 7810270129 7810300182 7810300330* 7810300377	50-287 P 50-269 P 50-269 P 50-488 Q 50-369 Q		7812050025# 7812060272 7812060320 7812070317 7812070317
	7810310008 7810310008 7810310008 7810310289 7810310289	50-269 F 50-269 F 50-269 F 50-369 G 50-369 G		7812120230 7812130169 7812130172* 7812130175 7812130287
	7810310302 7810310336 7810310336 7811010104 7811010160	50-369 G 50-369 G 50-369 G 50-269 P 50-369 B	·	7812130306 7812130306 7812130306 7812130369 7812140041
	7811010160 7811010169* 7811010162* 7811010412 7811010255	50-369 8 50-369 8 50-369 8 50-369 F 50-269 P		7812140041 7812140041 7812140053 7812140053 7812140053

BUBJ

50-26 50-26 50-26 50-26

50-27 50-27 50-36

50-36 50-36

50-26 50-26 50-26 50-26 50-26

50-26 50-36 50-36 50-36 50-26

50-26 50-26 50-27 50-26 50-26

50-26 50-26 50-26 50-26

20-59 20-39 20-39 20-59

50-48 50-36 50-48 50-36 50-36

50-36 50-36 50-36 50-36 50-36

50-34 50-26 50-41 50-27

50-48 50-36 50-36 50-26 50-26

50-26 50-26 50-26 50-41

50-41 50-41 50-26 50-26 50-26

50-26 50-26 50-26 50-26 50-26

50-46 50-26 50-26 50-26 50-49

50-26 50-26 50-26 50-26

50-26 50-26 50-26

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCEBBION NUMBER	BUBJECT CATEODS		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOGRY
	7812150226 7812150226 7812180131 7812180188 7812180196+	50-413 50-413 50-269 50-270 50-270	A A P B B	Ecology Action of Obwago	7811300203 7811300205# 7812210066 7810300055 7811010267	50-591 50-591 50-245 50-443 50-443
	7812190127 7812190130+ 7812190153 7812190156+ 7812200312	50-269 50-269 50-287 50-287 50-488	8 8 8 9	Eichhorn Morrow & Eichhorn Electric Power Research Institute	7811210467 7812150268# 7812280268# 7812180111 7812210183#	50-485 50-443 50-220 50-367 50-500
	7812210035 7812210059 7812210059 7812210157 7812210157	50-413 50-413 50-413 50-267 50-267	0 G G R R	Ellis, L.J. Energy, Dept. of	7812140247 7810140123# 7810250062 7811210086# 7812110014	50-518 50-344 50-269 50-70 50-537
	7812210157 7612210160* 7612210160* 7812210160* 7812270211	50-269 50-269 50-269 50-269 50-369	R R R A	Energy, Dept. of, Clinch River Breeder Reactor Plant	7812150058 7812150293 7810170154 7810170257*	50-201 50-466 50-537 50-537
	78122702144 7812270244 78122703594 7812280133 7812280133	50-369 50-269 50-369 50-369 50-369	А Р Ф К		7811170177 7812050276 7812050280* 7812120090	50-537 50-537 50-537 50-537 50-537
	7812280135# 7812280135# 7812290209 7812290214# 7812290218#	50-369 50-369 50-287 50-287 50-287	K 8 8	Environmental Coalition on Nuclear Power Environmental Protection Agency	7812200243 7612200247* 7812200251* 7812280327 7810140048* 7810310273	50-537 50-537 50-387 50-213 50-568
Duncen, Allen & Mitchell Duquesne Light Co.	7811160036 7810100030 7810100034* 7810100084 7810110144	50-592 50-334 50-334 50-334 50-334	M 8 8 9		7810310281* 7810310286* 7811140138 7811220139 7811240169	50-568 50-568 50-445 50-568 50-466
	7810160114 7810160116+ 7810180072 78101800747 7810200050+	50-334 50-334 50-334 50-334 50-334	Я В Р Р		7812050174 7812050174 7812060157* 7812280026* 7812280040*	50-390 50-582 50-437 50-250 50-250
	7810200100 7810270189* 7810270195 7811030107 7811030164	50-334 50-334 50-334 50-334 50-334	8 G P	Evergreen Legal Bervices Exxon Nuclear Co., Inc. (subs. of Esxon Corp.)	7812290268# 7811130128 7811200144 7810270108	50-596 50-522 50-522 50-277
	7811030169 7811070377# 7811070378# 7811130R18 7811130220#	50-334 50-412 50-412 50-334 50-334	R 8 9 9	Fitchburg Qas & Electric Light Co. Fleischeker. D. B.	7811130179 7811130249* 7811070148* 7810190257 7810190257	50-564 50-564 50-443 50-275 50-276
	7811160109 7811160111# 7811170172 7811170178# 7811170214	50-334 50-334 50-334 50-334 50-334	R R 8 8		7810190262* 7810190262* 7810190267* 7810190267* 7810190269*	50-275 50-275 50-275 50-275 50-275
	7811170219 7811170221 7811170234# 7811280458# 7811200243#	50-334 50-334 50-334 50-412 50-334	8 8 8 8 9		7810190269* 7810270294 7810270294 7810200128	50-275 50-275 50-275 50-275
	7812080182 7812110128 7812110122* 7812120143	50-334 50-334 50-334 50-334	Р R R	Fiorida Power & Light Co.	7810300128 7811130314 7810100091 7810100092* 7810100093*	50-275 50-275 50-335 50-335 50-335
	7812120148 7812140109 7812180180 7812180184 7812190144	50-334 50-334 50-334 50-334 50-334	8 9 8		7610100094* 7610100097* 7610100102*	50-335 50-335 50-335
	7812220071 7812220071 7812260214 7812260216#	50-334 50-334 50-334 50-334	P P P		7810110121 7810110123 7810110159 7810110251#	50-335 50-251 50-250 50-250
	7812290216 7812290222 7612290223+ 7612290223+	50-334 50-334 50-334	8 8 8		7810120022 7810120022 7810120023# 7810120023#	50-250 50-250 50-250 50-250
680, Inc.	7819290297# 7819290235# 7810230375 7810930375	50-334 50-334 50-206 50-206	8 8 A A		7810120028 7810120049 7810120050 7810120051# 7810120052#	50-250 50-335 50-251 50-335 50-251

AUTHOR AFFILIATION	ACCESSION NUMBER				7811300190# 7812010043 7812010043 7812010100	50-335 50-250 50-250 50-250	0 0
	7810120075 7810120081* 7810120081* 7810170191* 7810170243	50-250 50-250 50-250 50-250 50-335	F F P 9		7812010100 7812010119* 7812010119* 7812010128* 7812010128*	50-250 50-250 50-250 50-250 50-250	0 0 0 0
	7810170245* 7810180115 7810200045 7810200093 7810200096*	50-335 50-335 50-250 50-251 50-251	8 J P 8 8		7812040187 7812040189* 7812040221 7812040222* 7812050131	50-250 50-251 50-251 50-251	8 8 8
	7810200114 7810200117* 7810200188 7810200232 7810230032*	50-251 50-250 50-335 50-335	9 0 0		7812050133* 7812050176 7812050181* 7812050195 7812050198*	50-335 50-251 50-251 50-335 50-335	8 8 8 8
	7810230140 7810230140 7810230166 7810230169* 7810230250	50-250 50-250 50-335 50-335 50-251	8 8 7		7812050240 7812060356 7812080200 7812120145 7812120239*	50-250 50-387 50-335 50-387 50-250	0 8 A 9
	7810230253+ 7810230329 7810240071+ 7810240075+ 7810240088	50-251 50-335 50-250 50-250 50-369	8 Q Q A		7812140146 7812140150 7812140150 7812140152* 7812140195	50-251 50-250 50-250 50-251 50-335	P P P D
	7810260007* 7810260070 7810270182 7810270182 7810300107	50-250 50-389 50-250 50-250 50-250	0 P P		7812180138 7812180141 * 7812180316 * 7812190233 7812210068	50-250 50-250 50-335 50-250 50-250	9
	7810300107 7810310002 7810310121 7810310121 78110301684	50-250 50-335 50-250 50-250 50-250	J F G		7812210068 7812210138 7812210196 7812270187 7812270190	50-250 50-335 50-251 50-250 50-250	0 9 P F
	7811030148* 7811030224 7811040095 7811040142 7811040144	50-250 50-335 50-335 50-250 50-250	0 6 8		7812270195 7812270267 7812270275* 7812270275* 7812270312*	50-250 50-335 50-335 50-251 50-251	8 8 8 8
	7811060148* 7811060152* 7811060157 7811060163* 7811070144	50-250 50-251 50-251 50-251 50-250	1 8 8	Florida Power Corp.	7812280019 7812280139 7812280339* 7812290147 7810110097	50-250 50-250 50-250 50-335 50-302	6 6 6
	7811070144 7811070144 7811070180 7811070180 7811070309	50-250 50-250 50-250 50-250 50-250	I I P P G	,	7810110116 7810110120* 7810110151 7810110152* 7810110170	50-302 50-302 50-302 50-302	9 9 9 8
	7811080148 7811080150+ 7811080208 7811080217+ 7811090248	50-251 50-251 50-335 50-335 50-335	9 9 8		7810110173* 7810130130 7810160091 7810160094> 7810170249	50-302 50-302 50-302 50-302 50-302	8 R R B
	7811090246+ 7811100083+ 7811100083+ 7811130221 7811140219	50-335 50-250 50-250 50-250 50-335	8 9 F P		7810170252* 7810180105 7810180107* 7810180110 7810180111*	20-305 20-305 20-305 20-305	8 8 8
	7811160107 7811160139 7811160142* 7811160142* 78111210188	50-335 50-250 50-250 50-250 50-250	P P P G	•	7810180147 78101801524 7810180153 7810180155* 7810200152	50-302 50-302 50-302	99
	7811210186 7811210327 7811210328 7811210338 7811210338	50-250 50-335 50-335 50-250 50-250	0 P P P		7810200158* 7810200160 7810240124* 7810240124* 7810240160	50-302 50-302 50-302	9 9
	7811210338 7811220002 7811220201 7811220203* 7811240007*	50-250 50-250 50-250 50-250 50-335	P G B G		7810240162* 7810270165 7810310136 7810310141* 7810310164	50-302 50-302	. 8
	7811240025 7811240207 7811270161 7811270161 7811280228	50-250 50-335 50-250 50-250 50-250	G P P P		7810310167* 7811010299 7811070136 7811070137* 7811070204	50-302 50-302 50-302	2 6
	7811280228 7811290229 7811290235* 7811290320 7811300004*	50-250 50-335 50-335 50-389 50-335	P 8 0 0		, 3, 3		. •

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	Y	AUTHOR AFFIL]ATION	ACCESSION NUMBER	SUBJECT
	781 1 070208* 781 1 070226 781 1 070235* 781 1 080165 781 1 1 00021*	50-302 50-302			7811200392* 7811210231 7811210267 7811270099* 7812010248	50-275 50-344 50-220 50-155 50-447
	781 1 1 30181 781 1 1 40109 781 1 2 40129 781 1 1 40136 781 1 1 40140+	50-302 50-302 50-302 50-302	P J B		7812010249# 7812040018* 7812050220 7812050221 * 7812050231 *	90-447 50-536 50-447 50-447 50-237
	781 1 1 70103 781 1 200184 781 1 200187• 781 1 240074¤ 781 1 240214	50-302 50-302 50-302 50-302	F R R O P		7812080131 7812110113 7812110113 7812110113 7812110116#	30-70 50-447 50-447 50-447 50-447
	781 1280268 781 1280271# 781 1280303 781 1280307* 781 2010246	20-305 20-305 20-305 20-305 20-305	R R B B		7812110116# 7812110116# 7812110272 7812110274# 7812110277#	50-447 50-447 50-277 50-277 50-277
	781 2010247* 781 2040199 781 2050067* 781 2140127 781 2180150	20-305 20-305 20-305 20-305 20-305	8 P Q F		7812120082	50-333 30-447 50-70 50-219 50-70
	761 2160155+ 781 2200176 761 2200178 761 2200179+ 761 2200181+	20-305 20-305 20-305 20-305 20-305	8 R B		7812180435 7812210331 7812270162 7812270172 7812270172	50-30 50-70 50-447 50-447 50-447
	781 2200270 781 22002734 781 2200264 781 22103374 781 2220081	50-302 50-302 50-302 50-302	8 8 0 8	General Physics Corp. General Public Utilities - GPU Service Corp.	7812280099 7812280100* 7812280275 7810200130 7810120068	50-447 50-447 50-70 50-341 50-219
	781 2220084+ 781 2220102 781 2220105+ 781 2270239 781 2270243+	50-302 50-302 50-302 50-302	5 6 8 8		7810240132 7810300148 7810300133# 7810300137# 7811060092	30-219 50-219 30-209 50-219 50-320
Florida State Univ. Florida, State of Florida, Univ. of, Gainesville	781 2270291 781 2270293* 781 0240005* 781 2270168 781 0110198*	50-302 50-302 50-437 50-250 50-83	8 8 A H Q	Georgia Power Co.	7812010127 7810100039 7810100039 7810100045# 7810100045#	50-146 50-321 50-321 50-321 50-321
Fontana, L. Ford Bacon & Dayle Utah, Inc.	781 0 1 80081 781 20 60149 781 1 0 80180 781 0 1 70036 781 1 2002214	50-83 50-83 50-382 50-201 50-201	P P P		7810110089 7810110135 7810130043 7810130092 7810130092	90-321 50-386 50-386 50-321 50-321
Friends of the Earth	781 01 90193 781 02 30084 781 20 40348 781 21 10278 781 22 10512	50-70 50-70 50-70 50-70 50-70	0 0 0		7810169104 7810160104 7810170141 7810170142 7810170166	50-321 50-321 50-321 50-355 50-366
Ft. Colling, CA Gaga-Baboock Associates, Inc. General Atomic Co. (mubs. of Gulf Dil Co.)	761 21 50279 761 2270102+ 781 0270107+ 781 11 30200	50-346 50-275 50-163 50-267	M F A		7810170170# 7810170226 7810170230# 7810170233	50-366 50-366 50-364 50-321
General Atomic Co. (wubs. of Gulf Dil	7811240232 7811240234+ 7812190143 7810270104	50-267 50-267 50-89 50-163	u B F		7810170236 7810170238* 7810170255 7810170256	50-366 50-366 50-321
Corp.) General Electric Co.	781 1 Q60115 781 0 1 10165	50-237 50-70			7810170258# 7810170261#	50-366 50-321
	78 1 0 1 70114+ 78 1 0 1 90108 78 1 0 300138+ 78 1 0 300138+ 78 1 0 300138+	50-333 50-447 50-447 50-447 50-447	P A A		7810170291 7810170298# 7810170309 7810170311 7810170312	50-321 50-321 50-346 50-366 50-366
	78 1 0 3 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1	50-447 50-447 50-447 50-70 50-556	A A O		78101703134 78101703144 78101703154 7810170318 78101703214	50-366 50-366 50-366 50-366
	7811040122 7811070115 7811070340 7811070340	50-556 50-70 50-556 50-556	0 P 0		7810170322 7810170326 7810170327 7810180001 7810180003#	50-346 50-346 50-346 50-346
	78 1 1 060008+ 78 1 1 130177 78 1 1 170157 78 1 1 200384+	50-18 50-552	P . A		7810180010 7810180011# 7810180014# 7810180019	50-321 50-321 50-321 50-366

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEOOR	Y		JTHOR -IATION	ACCESSION NUMBER
	7610180020 7810180022* 7810180023 7810180024* 7810180026*	50-366 50-366 50-366 50-366 50-366	8 6 8			7811220026 7811220028* 7811220034 7811220034 7811240061
	7810180029 7810180031 7810180033* 7810180037 7810180039*	50-321 50-366 50-366 50-366 50-366	8 8 8			7811240061 7811280006 7811280006 7811280217 7811280220*
	7810180112 7810180114* 7810180116 7810180118* 7810180120	50-321 50-321 50-366 50-366 50-366	8 8 8			7811280222 7811280223 7811280223 7811280224* 7811280235
	7810180122* 7810230175 7810230176* 7810230188 7810230190*	50+366 50-321 50-321 50-366 50-366	8 9 9			7811280242* 7811280268 7811280293* 7811300192 7812060343
	7810230206 7810240110 7810270101 7810210117 7810310146	50-366 50-321 50-366 50-321 50-321	3 6 6			7812070039 7812070033 7812070038 7812070038 7812070082
	7810310150* 7910310151 7810310154* 7810310157 7810310160	50-321 50-366 50-321 50-321	ខ ១ ១ ខ ន			7812070082 7812080078 7812150287 7812150294* 7812150334
	7810310162* 7810310165 7810310166* 7810310171* 7810310175	50-321 50-321 50-321 50-321 50-366	8 8 8			7812150347* 7812180135 7812180162 7812180164 7812180165
	7810310181# 7810310182# 7810310205 7810310214# 7811010062	50-366 50-321 50-366 50-366 50-321	8 8 8 8			7812180167* 7812180167* 7812180179 7812180179 7812180182
	7811020163 7811030044 7811060131 7811060135 7811060138+	50-424 50-424 50-321 50-321 50-321	0 8 8			7812180183* 7812180186* 7812180198 7812180201 7812180202*
	7811060140* 7811060150 7811060153* 7811080162 7811080162	50-321 50-366 50-366 50-424 50-424	8 9 •			7812180205* 7812180214* 7812180217* 7812180220 7812180223*
	7811100168# 7811130261# 7811130261# 7811140156 7811140162#	50-321 50-321 50-321 50-321 50-321	8 G G			7812180231 7812180234* 7812260154 7812260156* 7812270266
	7811140198 7811140204* 7811140209 7811140211* 7811140245	50-366 50-366 50-366 50-366 50-366	8 9 9			7812270273# 7812270274 7812270290 7812270285# 7812270295
	7811140254* 7811150073 7811160066 7811160068* 7811160106	50-366 50-321 50-321 50-321 50-366	В Р Я R R			7812270296* 7812270314 7812270317* 7812270318*
	7811160110# 7811170205 7811200173 7811200259# 7811200259#	50-366 50-321 50-424 50-424 50-424	R J A A			7612270319 7812270321* 7812270325 7812270326 7612270329*
	7811210217 7811210217 7811210226* 7811210238 7811210243*	50-424 50-424 50-424 50-366 50-366	A A B B			7812270331* 7812280069* 7812280286 7812290139 7812290145
	7811210246 7811210253* 7811210342 7811210346* 7811210351	50-366 50-366 50-381 50-381 50-366	8 8 8 8	Gaorgia, State of Gibbs & Hill, Inc.	(subs. of Dravo Corp.	7812290145 7812290152* 7812290152* 7810230104 1 7811080030*
	7811210361 7811210366+ 7811210370+ 7811210398 7811210404+	50-321 50-321 50-366 50-366 50-366	8 8 8 6			7811080033* 7811240125 7811240128* 7812170103 7812270138

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Gilbert/Commonwealth Cos.	7812290143# 7812180226	50-584 50-595	A F		7810240042 7810270394	50-511 G 50-322 A 50-450 O
Gordon, Walter J Graham, R. L	7812180232* 7810110025 7811160050		F P G		7811130435 7811200307 7811290087	50-450 9 50-516 9 50-516 9
Green Bay Packing, Inc. Green, Feldman, Hall & Woodard	7810160017 7810230075 7811150232 7811240083 7811270193	50-305 50-556 50-556 50-556 50-556	0 0 0 0		7812080171 7812110281 7812130212 7812210306 7812210311+	50-338 G 50-322 G 50-463 G 50-247 G 50-247 G
Gulf States Utilities Co	7812110215 7812130193 7810110272* 7811070244 7811070252*	50-556 50-556 50-458 50-510 50-510	G G Q A A	Idaho State Univ. Ihrig. R.	7812260307 7812280333 7812070202 7812070204* 7810190202	50-247 Q 50-322 Q 50-284 P 50-284 P 50-484 Q
	7812260148 7812260148 7812260148 7812260166 7812260166	50-458 50-459 50-458 50-458 50-458	A A A A	filinois Power Co.	7810197220* 7810300369 7810110037* 7812080228 7812260141	30-484 Q 30-484 Q 30-461 Q 30-461 Q
Hanford Conversion Project Harvard Univ.	7812260170* 7811100018 7812040072 7812040084* 7810160013*	50-458 50-397 50-397 50-397 50-471	A 0 0 0	Illinois, State of	7811130202 7811240022 7812050047 7812050047 7812050051*	50-295 @ 50-295 @ 50-295 @ 50-295 @ 50-295 @
Hazelton Environmental Sciences Corp. Hetrel, W.C. House of Rep.	7812010122 7811220198 7810110268 7810110271 7810230042+	50-298 50-352 50-70 50-70 50-275	P G O G	Indiana & Michigan Power Co.	7812030051* 7812080025 7812120211 7810100024 7810100044	50-275 0 50-247 P 50-295 0 50-315 8 50-316 B
	7810230084 7810300272 7811070353* 7811130246 7811290297	50-70 50-556 50-70 50-70 50-70	G G P G		7810100064* 7810100068* 7810110080 7810110154 7810110188	50-316 B 50-316 9 50-315 P 50-315 B 50-316 B
	7811300100 7811300100 7812010046+ 7812050044+ 7812060216	50-338 50-338 50-471 50-213 50-338	A Q U H		7810110192* 7810180002 7810180004* 7810180005* 7810180016	50-315 8 50-316 8 50-316 9 50-316 8 50-316 9
Houston Lighting & Power Co.	7812040216 7812180229 7812180289 7812210171 7810110294	50-338 50-70 50-275 50-70 50-466	H H Q Q		7810180018* 7810180027 7810180030* 7810180032* 7810180106	50-316 8 50-316 8 50-316 8 50-315 8
	7810120024 7810120024 7810120061 7810120061 7810140062+	50-498 50-498 50-498 50-498 50-498	K H A A K		7810180109* 7810180158* 7810200053 7810200056* 7810230177	30-315 8 30-315 8 30-316 R 30-316 R 50-316 8
	7810140159 7810300086 7810310179* 7811010144 7811020387*	50-466 50-498 50-498 50-498 50-498	0 A H A Q		7810230183* 7810230185* 7810230198 7810230202* 7810230242	50-316 9 50-316 9 50-315 8 50-315 8 50-316 P
	7811020367* 7811020393* 7811020393* 7811030214 7811090106	50-478 50-478 50-478 50-478 50-478	9 9 8 8		7810250117* 7810270191 7810270193* 7810270309 7810270314*	50-315 8 50-315 8 50-316 8 50-316 8
	7811160131 7811170090# 7811240114 7811240114 7811240116#	50-498 50-466 50-498 50-498 50-498	A G C C		7810310090 7810310090 7810310145 7810310155* 7810310190	50-315 P 50-315 P 50-315 E 50-316 E
	7811240116* 7811300216 7811300382* 7812040127* 7812040301	50-498 50-498 50-498 50-498 50-446	0 0 0 0		7810310199* 7810310204 7810310204 7811020252 7811030103	50-316 E 50-315 F 50-315 F 50-315 E
	7812040302* 7812050200 7812050203* 7812190147 7812210029*	50-466 50-466 50-478	9 9 9		7811070151 7811090153* 7811090158* 7811090225 7811140154	50-316 50-316 50-316 50-315 50-315
Hudson Light & Power Dept. Hunton & Williams	7812280151 7812280152* 7811070150* 7810160201 7810190223		0 0 1 8		7811140210 7811140218* 7811140228* 7811140232* 7811170204	50-316 50-316 50-316 50-316 50-315
	7610200059 7610200059 7610230130 7610240036 7610240036				78:12:0260 78:12:0265* 78:12:027: 78:12:0276* 78:12:0383	50-315 50-315 50-315 50-315 50-315

7811200341	AUTHOR AFFILTATION	ACCESSION NUMBER	CATEOD		AUTHOR AFFIL IATION	ACCESSION NUMBER
PRINCIPLES PRI		7811210437 7811210438+ 7811240172+	50~316 50~316 50~315	R R S		7810240112 7810310220 7810310227 7811070121 7811080002
781 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791 1000 791		7811270069 7811270080+ 7811270171	50-315 50-315 50-315	8 9 P		7811170159 7811210090 7811210354 7811210390 7811210394
100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100 100		7811290247 7811290251+ 7811290251+	50-315 50-315 50-315	K K		7811270150 7811270160 7811270202
Tell Section Section		7811300185# 7811300168# 7811300193#	50-316 50-316 50-316	8 8		7811280206 7811280237 7811290238
7812000005 50-316 8 7812100179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 78122700179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 7812270179 781227017		7812070218 7812080061 7812080088•	50-315 50-316 50-316	P S 8		7812050156 7812110106 7812130136 7812130140 7812130145
Tell color Tel		7812090086 7812080087# 7812080089#	50-316 50-315 50-316	8 8		7812190137 7812190139 7812270297 7812270301 7812290130
7812120184 50-315		7812080122# 7812110137 7812120162	50-314 50-315 50-315	8 R 8		7811060073 7811060074 7810250111 7812060166 7812200188
Tell		7812120186+ 7812120384 7812180207	50-316 50-315 50-316	\$ P 8	lehem. Lincoln & Beele	7810120112 7810160202 7810190131
7812200262 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700260 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270 7812700270		7812200174* 7812200203 78122002054	50-315 50-316 50-316	R R R	•	7810260199 7810300311 7811010433
781227022e		7812260242 7812270178 7612270178	50-315 50-315 50-315	P P		7811130060 7811130252 7811140047
Telegroup Tele		7812270226+ 7812270252 7812270255+	50-315 50-316 50-316	8 8		7811210036 7811210107 7811240074
Tel 1280145 50-316 F		7812270268# 7812270272# 7812270277#	50-316 50-316 50-316	8 8		7812050281
Interior, Dept. of 7812010137 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 7812140087 781220038 7812140087 781220038 7812140087 781220038 781240087 781220038 781240087 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 781220038 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008 78122008		7812280145 7812290083 7812290179	50-316 50-316 50-315	P 8 P		
Tellogoog		7812010133 7810110142 7810230134	50-546 50-498 50-274	A C P		7812140087 7812140087 7812140285
Telephone Tele		7810310092 7811070123 7811090063	50-568 50-568 50-274	A A P		7812180383 7812270010
7810200061 50-331 R 7810100075 78102000639 50-331 R 7810110118 7810230173 50-331 F 7810120076 7810240104 80-231 R	_	7812180431 7812200236 7810110141	50-70 50-274 50-331	P H S	Jersey Central Power & Light Co.	7812280350 7812290013 7812290255
		7810200061 7810200063* 7810230173	50-331 50-331 50-331	R R F		7810110118 7810120071 7810120076

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	!Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC
	7810160120* 7810160143 7810170200 7810170240 7810180006	50-219 50-219 50-219 50-219	P P R P B		7810300359 7811030217 7811160186# 7811160189* 7811170249*	50-462 50-462 50-462 50-462 50-482
	7810180007* 7810230259 7810230261* 7810240105 7810240107*	50-219 50-219 50-219 50-219	8 R R 8		7812110271* 7812110276* 7812110282* 7812200348 7812200349*	50-482 50-482 50-482 50-482 50-482
	7810270074 7811030114 7811070105 7811070304 7811080100	50-219 50-219 50-219 50-219	R P 8 P	Kansas State Univ. Kansas. Univ. op Keiler & Buckley Kudzu Allience	7810110029 7811170293* 7812060319* 7811010389* 7811140034	50-188 50-148 50-148 50-524 50-400
	7811080189* 7811080234* 7811080258* 7811200160 7811200164*	50-363 50-219 50-219 50-219 50-219	0 0 P P	Leke County, OH Lakeshore Citizens for Bafe Energy	7811290J39 7812140114* 7812220121 7811160160* 7811200268	50-400 50-400 50-400 50-440 50-266
	7811200204 7811200207* 7811210239 7811210241* 7811210321	50-219 50-219 50-219 50-219	8 8 R R		7811200275 7812110306 7812140359 7812140359 7812140368#	50-266 50-305 50-266 50-266 50-266
	781 121 0324# 781 1220129 781 1240194 781 1280193 781 1280196#	50-219 50-219 50-219 50-219 50-219	8 8 8	LeBoouf, Lamb, Leibų & MacRae	7812140368* 7812270452 7810140628 7810160108 7810180148	50-266 50-266 50-452 50-244 50-244
	7811200262 7812010131* 7812070218 7812070220* 7812070288*	50-219 50-219 50-219 50-219 50-219	P Q 8 8		7810190058 7810230238 7810230050 7810270368 7810270387*	50-244 50-244 50-285 50-341 50-341
	7812110093 7812110097* 7812120123 7812120127* 7812120133	50-219 50-219 50-219 50-219 50-219	8 8 8		7810270408* 7811010136 7811060099 7811060241 7811130399	50-341 50-546 50-285 50-485 50-548
	7812120136* 7812180161* 7812180204 7812180208* 7812190105	50-219 50-363 50-219 50-219 50-219	6 9 8 8		7811210293 7811240102 7812040283 7812050340 7812220002	50-341 50-220 50-485 50-341 50-341
	7819190107* 7819200180 7819200182* 7819200236 7819200240*	50-219 50-219 50-219 50-219 50-219	# R R B	League of Women Voters of Lancaster Co., PA	7812220113 7812240014 7812240202 7812270138 7811220141	50-244 50-247 50-341 50-247 50-463
	7812270185 7812270316 7812270323* 7812280231 7812280236*	50-219 50-219 50-219 50-219 50-219	P 8 8 8	Leegue of Women Voters of Buffolk Co., NY Leed, R.M.	7811220172 7811020077 7811300400 7812080165 7812110199	50-463 50-516 50-522 50-522 50-522
Justice:Dept. af	7819290089 7819290097* 7819290213 7819290219* 7810200120	50-219 50-219 50-219 50-219 50-498	8 8 8 M	Long Island Lighting Co.	7810100017 7810180074 7810200091 7810230133* 7810230274	50-322 50-322 50-322 50-322 50-516
	7810240214 7810270354 7811200050 7811200103 7812040032	50-498 50-344 50-498 50-389 50-346	M 0 M M		7810270190 7811140234+ 7811280044 7812070115+ 7812140166	50-322 50-322 50-322 50-322 50-322
	7812040260 7812130235 7812140207 7812140280 7812180410	50-369 50-369 50-346 50-498 50-498	М Н Н М		7812260125 7812260129* 7812260136 7812260139* 7812260196	50-322 50-322 50-322 50-322
	7812180410 7812180412 7812180412 7812260137 7812280177	50-498 50-498 50-498 50-443 50-498	м н н н п		7812260211 7812260215 7812260221 7812270478* 7812270258*	50-322 50-322 50-322 50-322 50-322
Justice, Dept. of, Attorney General's Office KMC, Inc. Kefin, R.J.	7810140023 7811290304* 7812210210* 7810200136 7810270285	50-344 50-70 50-272 50-349 50-349	P G F G	Looney, Nichols, Johnson & Hayes Los Alamos Bcientific Leboratory Louisiane Power & Light Co.	7811080225 7811170297 7811220012 7812140105 7810110115	50-445 50-266 50-358 50-322 50-382
Kafoury & Hagen Kansas Gas & Electric Co.	7812180404 7811140027 7810250031= 7810270320	50-549 50-244 50-482 50-482	0 0 0	•••	7811010004 7811010033# 7811170086# 7811300233	20-385 20-385 20-385 20-385

**************************************	NUNDER	CHIEBONT	AFFICIATION	NUMBER
	7812130152 7812110155 7812110230* 7812130152	50-382 A 50-382 Q 50-382 Q 50-382 A		7812010214 7812150355 7812150357 7812200213 7812200217
	7812190092 7812200133 7812200133+ 7812200242 7812200245+	50-382 A 50-382 A 50-382 C 50-382 C	Mapleton Intervenors	7812200220 7812200252 7812200254 7811010014 7811100146
Lowell, Univ. of	7812200248 7812200250+ 7812290175 7811020177* 7812070055	50-382 K 50-382 K 50-382 P 50-223 Q 50-223 P	Marsh & McLennan.Inc., M & M Nuclear Consultants.Inc. Div.	7811100146 7811150039 7811210040 7811210040 7811240044
Lowenstein: Newman, Rais, Axelrad & Toll	7810130091 7810130195 7810140017 7810140019 7810200003	50-466 @ 50-466 @ 50-498 M 50-344 @ 50-344 @	Maryland, State of Massachusetts Institute of Technology Massachusetts Municipal Wholesale Co. Massachusetts, State of	7812260286 7812060185 7812080093 7811070153
	7810230324 7810270322 7810270386 7811020041 7811020047+	50-344 Q 50-498 Q 50-344 Q 50-376 Q 50-376 Q	Hassachusevit. State of	7810110109 7810110310 7810230197 7810300257 7811160126
	7811080021 7811080054 7811130259 7811130404 7811130431	50-498 M 50-466 Q 50-387 M 50-398 M 50-389 M	Matthews, Nowlin, Macfarlane & Barrett McCutchen, Doyle, Brown & Emersen	7812010044 7812010044 7810230007 7812130104 7812280176
	7812040024 7812040028 7812040031* 7812040274 7812040329	50-466 Q 50-344 Q 50-344 Q 50-466 Q 50-466 Q	Means. Donald S. Metford & Dattilo Metropolitan Edison Co.	7812150054 7811130126 7810230229 7810100046 7810100076
	7812040331 7812040333 7812040343 7812040343 7812040367	50-466 Q 50-466 Q 50-466 Q 50-466 Q 50-498 Q		7810100080 7810100088 7810100090 7810100099 7810100099 7810110082
	7812050037 7812050044 7812070058 7812110256 7812120048	50-466 Q 50-466 Q 50-466 Q 50-466 Q		7810110083 7810110130 7810110134 7810110149 7810170147
	7812120224 7812130020 7812130026 7812130219 7812180258	30-466 Q 30-466 Q 30-466 Q 30-466 Q 30-443 M		7810170148 7810180132 7810180165 7810180168
	7812180438 7812270405 7812270410 7812270485 7812280266	50-344 Q 50-498 M 50-389 M 50-344 Q 50-344 Q		7810180174 7810190001 7810240097 7810240119
MHB Technical Associates Maine Public Service Co. Maine Yankee Atomic Power Co.	7812280269 7812280308 7812210521 7811070169* 7810110171	50-478 M 50-582 Q 50-275 Q 50-443 I 50-307 P		7810240119 7810240120 7810240125 7810240129 7810240131
	7810120066 7810170150 7810170151+ 7810180137 7810190056	U 90E-06 A 90E-06 A 90E-06 A 90E-06 A 90E-06		7810240134 7810300137 7810310184 7810310192 7811070101
	7610230137 7610230153 7610250160 7610270077 7811030131	50-307 J 50-309 P 50-27 P 50-309 P 50-309 8		7811070191 7811070191 7811080204 7811090048 7811090054
	7811030135* 7811030137 7811030140* 7811140112 7811140166*	50-307 8 50-307 8 50-309 8 50-309 R 50-309 R		7811090171 7811090171 7811090174 7811090247 7811090274
	7811150091 7811150095* 7811220200 7811220202* 7811220213	50-309 P 50-309 Q 50-309 B 50-309 B		7811140103 7811140172 7811140172 7811150145 7811150141
	7811220217+ 7811270086 7811290243 7812010093+ 7812010214	50-309 R 50-309 P 50-309 P 50-309 Q 50-309 Q		7811160145 7811210184 7811210186 7811210332 7811210336

	7811210380 7811210384* 7811240110 7811240110 7811270155	50-320 50-320 50-267 50-267 50-320	# # P F	Margan, Lawis & Bockius	7810140029 7810140104 7811080329 7811160167 7811210451	50-409 30-409 30-556 30-409 50-70
	781 1280243 7812050098 7812060161	50-289 50-289 50-289	P P P	N.M. Neumark Consulting Engineering Bervices	7811300034 7812040321	50-70 50-275
	7812060168 7812060171 7812060177#	50-209 50-320 50-320	F 8 8	NUB Corp. National Lawyers Guild, Houston Chapter	7811130336 7811150127 7811020169	50-341 50-592 50-466
	7812070203 7812070206* 7812080090 7812110146	50-320 50-320 50-289 50-289	р Р В	Natural Resources Defense Council	7811020176* 7811020181* 7810120088 7810300063 7810300268	50-466 50-466 50-369 50-237 50-437
	7612120092 7612130195 7612130197* 7612180167 7612190096	50-289 50-320 50-320 50-320 50-320	H B P P		7811130391# 7811150223 7811150227 7818110070 7818110074#	50-220 50-237 50-437 50-437 50-437
	7612190113 7812190132 7812190134* 7812190166 7812190170*	50-289 50-320 50-320 50-289 50-289	F R R R	Nebrasia Public Power District	7812260002 7812270036 7812280271 7812280280+ 7610120037	50-247 50-437 50-237 50-237 50-298
	7812200171 7812200278 7812200278* 7812260191 7812260194	50-289 50-320 50-320 50-289 50-289	0 8 8 8		7810170152 7810170268 7810170299* 7810230213* 7810300173	50-278 50-278 50-278 50-278 50-278
	7812260259 7812260261 * 7812280116 7812290086 7812290093	50-320 50-320 50-320 50-269 50-320	9 0 P B		7810300177* 7810300201 7810300229# 7811020253 7811080110*	50-298 50-298 50-298 50-298 50-298
Miami, FL. Univ. of Michigan, State of	7818290129 7818290131 7811160001 7810190237* 7810190240*	50-289 50-320 50-463 50-255 50-255	P P R R		7811140130 7811160113 7811160114* 7811170210 78111200115	50-278 50-278 50-278 50-336 50-278
	78110901894 7811240190 7812060152 7812260065 7812260065	50-329 50-329 50-329 50-329 50-329	A 0 0		7811270129* 7812040196 7812050135 7812050138* 7812050144	50-298 50-298 50-298 50-298 50-298
Michigan, Univ. of Mid-America Coalition for Energy Alternatives Midland City, Ml	7812260067* 7812260067* 7811080135 7811160181 7811240184	50-329 50-329 50-2 50-482 50-329	0 0 8 8		7812050145* 7812050166 7812050170* 7812060052* 7812060148	50-278 50-278 50-278 50-278 50-278
Midland County, MI	781 1840186 781 1840188 781 1840199 781 031 0061 781 1840166	50-329 50-329 50-329 50-329 50-329	A A A		7812130158 7812130160* 7812130166 7812200259 7812200271	50-278 50-278 50-278 50-278 50-278
Minnesute Pollution Control Agency Minnesute: State of Mississippi Power & Light Co.	7811240185 7812260044 7812260323 7812260328 7811150097	50-329 50-263 50-263 50-263 50-416	A Q P P G	Neil, R. M.	7818200274* 7818270328 7818290197 7818270201* 7811200219	50-278 50-278 50-278 50-278 50-338
	7611150164 7611160073 7611160073	50-416 50-416 50-416	A	Nepom & Ross New Bedford Gae & Edison Light Co. New England Coalition on Nuclear	7812040118 7811070171+ 7812150273+	50-397 50-443 50-443
	7811170198 7812010223 7812010223	80-416 80-416	К	Poliution New England Legal Foundation	7812150283* 7811170173	50-443 50-56 9
	7812010227* 7812010227* 7812050171 7812060400	50-416 50-416 50-416 50-416	K A B	New England Power Co,	7810110078 7811040097 7811080195 7811210344 7811240048*	80-749 80-749 80-749 80-749 80-89
	7812040400 7812070179 7812120098 7812140133 7812270209	50-416 50-416 50-416 50-416 50-416	A Q	New Hampshire, State of	7811280040 7812040151 7812080104 7810180077 7810230867	50-568 50-568 50-568 50-443 50-568
	781 227 0209 781 2290133 781 2290256 781 2290260 781 2290260	50-416 50-416 50-416 50-416 50-416	9	New Jersey: State of	7610270147 7611130254 7612010259 7612180233 7612270027	50~443 50~345 50~272 50~254 50~272
Missouri, Univ. of, Rolla Montaup Electric Go.	7810110079 7811040076 7812290080 7811070166*	50-186 50-186 50-186 50-443	8	New Merico, Univ. of New York State Electric & Ges	7812140153 7811270077# 7812290264	50-252 50-495 50-896

AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJE CATEO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJE(
	7812290264 7812290265 7812290265 7812290266 7812290266	50-596 50-596 50-596 50-596 50-596	F 8		7810160123* 7810160126 7810160130* 7810170140 7810170140	50-245 50-336 50-336 50-245 50-245	8 R R P
	7812290267+ 7812290267+ 7812290271+ 7812290271+ 7812290275+	50-596 50-596 50-596 50-596 50-596	B		7810170210 7810200060 7810200071 7810200072* 7810200087	50-336 50-336 50-245 50-245 50-245	P P 8 8
	7612290275+ 7812290275+ 7812290278+ 7812290278+ 7812290278+	30-396 30-396 30-396 30-396 30-396	8 B B		7810200088* 7810230207 7810230210* 7810240099 7810270203	50-245 50-245 50-245 50-245 50-245	# 8 P
New York, State Univ. of, Suffelo New York, State of Newport News Industrial Corp. (subs. of Newport News Shipbuilding & DryDock Co.	7810300187 7810120055 7810240159 7812210517 7611220191*	50-57 50-333 50-549 50-97 50-920	A Q		7810310073 7810310077 7811070196 7811080143 7811080146*	50-245 50-336 50-336 50-336 50-336	P G P B
Niegara Mohaut Power Corp.	7810100054 7810100059# 7810110088 7810160119 7810160121#	50-220 50-220 50-220 50-220 50-220	8 P R		7811080135 7811080161* 7811090132 7811090133* 7811130193	50-336 50-336 50-423 50-423 50-213	8 8 8 9
·	7810170188 78102600224 7810300146 7811030141 7811070114	50-220 50-220 50-220 50-220	F 0 P 8 P		7811140110 7811140113* 7811140155 7811140155 7811140167	50-336 50-336 50-213 50-213 50-245	R R P P
	7811090155 7811090165* 7811090204* 7811090271 7811090273*	50-220 50-220 50-220 50-220 50-220			7811140187 7811140191* 7811140202 7811140205* 7811140205*	50-245 50-245 50-336 50-336 50-245	9 8 8
	7811130319 7811130400 7811150041+ 7811150188+ 7811210281	50-220 50-220 50-220 50-220	9 9 9		7811160093* 7811160152 7811170104 7811170115* 7811210178	50-245 50-245 50-245 50-245 50-496	g R R
	7811210283+ 7811210287+ 7811210292+ 7811210302 7811210303+	50-220 50-220 50-220 50-220	8 8 8 8		78112101834 7811210232 7811210268 7811210275* 7811210280	50-476 50-336 50-336 50-336 50-245	8 8 8
	7811220193+ 7811240103+ 7811270192 7812050148 7812070192	50-220 50-220 50-220 50-220 50-410	P 9 P 8		7811210291* 7811240187 7811240187 7811240189* 7811240189*	50-245 50-245 50-245 50-245 50-245	B K K
	7812070219 7812120102 7812120103+ 7812140136 7812140149	50-410 50-220 50-220 50-220 50-220	A R R F		7811270183 7811280295 7811280300* 7812050153 7812050161*	50-213 50-336 50-336 50-336 50-336	8 8 8
	7812140154+ 7812200194 7812200202 7812270176 7812270240	50-220 50-220 50-410 50-220 50-220	8 P P P		7812070184 7812080117 7812080116* 7812080121 7812080126	50-245 50-245 50-245 50-245 50-245	9 9 P 8
North Anna Environmental Coalition North Carolina, State of Northcutt Ely	7812270287 7812280196 7812040220* 7811080230 7812140244	50-220 50-410 50-338 50-488 50-445	P G H A M		7812080129# 7812120108 7812120113# 7812120116 7812120129#	50-245 50-336 50-336 50-336 50-336	8 8 8
Northeast Nuclear Energy Co. (subs. of Northeast Utilities)	7812140244 7812140244 7812140244 7812140244 7811290292 7811290332	50-445 50-445 50-443 50-245	M M R		7812150301 7812150308# 781219083 7812200187 7812260168	50-336 50-336 50-245 50-336 50-496	R P P A
	7812180143 7812210056+ 7812210070+ 7812260012 7812290061+	50-245 50-245 50-245 50-245 50-336	P Q P P O		7812240174* 7812240213 7812240219* 7812280137 7812280142*	50-496 50-245 50-245 50-336 50-336	A 8 8 0 0
Northeast Utilities	7810110128 7810110129* 7810110140 7810110176 7810120089	50-336 50-336 50-245 50-245 50-245	8 8 9 9	Northern Indiana Public Bervica Co.	7812290169 7812290173* 7812290205 7812290212* 7810130139	50-245 50-245 50-245 50-245 50-367	R R 9 8
	7810120096* 7810130138 7810160117	50-245 50-245 50-245	8 9 8		7810140136 7810270091 7811030144 7811030147 7811080224	50-367 50-376 50-367 50-367 50-367	A A P

	7811140208 7811170106 7811210360 7811290178 7812050183	50-367 50-367 50-367	A A A A A		7812120094* 7612120094* 7612140143 7812140159 7812140151*	50-282 50-263 50-306 50-306
	7812050184 7812110119 7812200142 7812210174 7812280120	50-367 50-367 50-367 50-367 50-367	A R A R		7812200211 7812200215= 7812200283 7812200287= 7812210036	50-263 50-263 50-263 50-263 50-282
Northern States Power Co	7810110180 7810110183* 7810120029 7810120030 7810120031*	20-585 20-593 20-593 20-593	8 8 8 8		781 2210036 781 2210190 781 2260193 781 2260207 781 2260207*	50-282 50-263 50-263 50-282
	7810120032* 7810120033* 7810140116 7810160122 7810170099	50-263 50-282 50-484 50-263 50-263	R R A F		7818260222 7618260237* 7618260836 7618260238* 7818270232	50-306 50-306 50-263 50-263 50-263
	7810170220 7810170224 7810170262# 7810180012 7810180013*	50-282 50-282 50-282 50-282	្ត ទ ទ ទ		7812270237* 7812270241 7812270245* 7812270246 7812270231*	50-263 50-263 50-263 50-263
	7810180021 7810180025* 7810180034 7810180036* 7810200078	50-306 50-306 50-306 50-306 50-863	8 8 8	Nuclear Associates International Corp.	78:1020248 76:1020251# 78:1140149 78:2130342# 78:0120042#	50-187 50-187 50-187 50-187 50-305
	7810200080* 7810240117 7810250076 7810250076 7810300145	20-593 20-593 20-593 30-593	6 8 8 8	(subs. of Control Data Corp.) Nuclear Energy Liability Insurance Association	7811090096 7811220078* 7811220081* 7812110172*	50-259 50-3 50-3 50-344
	7810300155 7810300154 7810300191 7810300196• 7810300237	20~585 20~593 20~593 20~593 20~593	1 1 9 8 P	Nuclear Fuet Services, Inc. (subs. of	7612110177% 7612180151* 7612180218* 7610300338*	50-344 50-213 50-10 50-201
	7810310078 7811070213 7811070213 7811070247 7811070259*	50-282 50-282 50-282 50-484	G B B B	Qetty Q11 Co. 1	781 1 1 0 0 1 2 5 7 6 1 1 1 7 0 2 3 3 7 6 1 1 2 7 0 2 3 7 7 6 1 1 2 7 0 2 7 0	50-201 50-201 50-201 50-201
	7811140115 7811140117# 7811140117# 7811140143	90-585 90-585 90-585 90-585	R R R	Nuclear Insurance Consultants	7811280118 7812150036 7810130223 7811070159	50-201 50-201 50-395 50-272 50-259
	7811140190 7811140194 7811150115 7811140116 7811140117*	50-263 50-263 50-263 50-263	J F P R R	Nuclear Safety Associates	7812010254 7812010254 7812040223 7812040223 7812050354*	50-259 50-272 50-272 50-549
	7811210307 7811210334 7811240124 7811240126#	50-263 50-263 50-263	F 8 8	Nygard- C. R. O'Kelly. A. P. O'Neil & Backus	7810200134 7810190199 7810170060 7812260087	50-409 50-522 50-443 50-443
	7811240162 7811260195 7811260195 7811260234 7811280239*	50-262 50-262 50-262 50-262	P 8 8	Cat Ridge National Laboratory	7812260092+ 7812260092+ 7810140076 7811270054+	50-443 50-443 50-395 50-468
	7811280244* 7811280249* 7811280253* 7811280256* 7811280263*	50-263 50-263 50-263 50-263 50-247	9 8 8 9	Ocean County, NJ Difference Fower Bystems (aubs. of Hestinghouse Electric Corp.)	7812080097 7812270182 7811240029 7811240032* 7810160112	50-395 50-247 50-343 50-363 50-437
	7811280279 7811280279 7811280338 7812010218	90-593 90-585 90-588	ь ь ь		7810230383 7810240103 7811090163 7811150257 78111200058#	50-437 50-437 50-437 50-437 50-437
	7812050177 7812040141 7812040141 7812040318 7812070221	50-263 50-263 50-263			7812060155 7812070176 7812200160 7812210451	50-437 50-437 50-437 50-437
	781207022* 7812070311 7812080133 7812080133*	50-263 30-484 30-306	P G P	Ohio Edison Co.	7812220097 7812290019 7810130137 7810130128 2810220201	50-437 50-437 50-580 50-580 50-580
	7812110116 7812110136 7812110140* 7812120091	50-393 50-593	P A A		7810230201 7810230201 7810250115	20-280 20-280

ì

	7811150126			
hio State Univ	7811150131* 7812050196 7812270204 7811200095* 7811200098*	50-580 50-580 50-580 50-346 50-346	B A A R	Pacific Gas & Electric Co
tlahoma. Univ of maha Public Power District	7810110167 7811090082 7810100010 7810100014#	50-112 50-112 50-285 50-285	P 9 9	
	7810110100 7810110103* 7810110112 7810110113 7810110114*	50-285 50-285 50-285 50-285	8 8 8 8 8	
	7810110117* 7810110189 7810110193* 7810110223* 7810130125 7810130126*	50-285 50-285 50-285 50-285 50-285 50-285	R R Q R R	
	7810130151 7810180159 7810180162# 7810250063# 7810250079	50-285 50-285 50-285 50-285 50-285	P 8 8 P	
	7810250101 7811040079 7811060200 7811060204* 7811070099	50-285 50-285 50-285 50-285 50-285	F 9 9 9	
	7811090180 7811130184 7811140107 7811140161# 7811140197	50-285 50-285 50-285	P G R R	
	7811150132 7811170193 7811210368 7811210371* 7811280257	50-285 50-285 50-285 50-285 50-285	P 9 9 9	
	7811280280 7811290390 7812010238 7812010240* 7812040161	50-285 50-285 50-285 50-285 50-285	H 8 8	
	7812050173 7812050179* 7812050173 7812060048* 7812060282*	50-285 50-285 50-285 50-285	9 8 F 0	
	7812130111 7812130178 7812130181* 7812200227 7812200221*	50-285 50-285 50-285 50-285 50-285	0 R R S	
	7812200264 7812200265 7812200277 7812200272* 7812260203*	50-265 50-265 50-265 50-265 50-265	8 8 8	
	7812270213 7812270217* 7812270219 7812270224* 7812270225	50-265 50-265 50-285 50-285 50-285	8 8 9	
	7812270262* 7812270332 7812270333* 7812290176 7812290225	50-265 50-265 50-285 50-285 50-285	9 9 9 P	
Oragon State Univ. Oragon, State of	7812290228* 7812270193 7812270197* 7810300162 7810300165*	50-285 50-106 50-106 50-514 50-514	8 P Q	Parsons, Brinkerhoff, Quade & Dougla Inc. Pearce & Brand
	7810300167* 7811080062 7811100174 7811150140 7812010341	50-514 50-344 50-344 50-344 50-344	0 0	Pennsylvania Power & Light Co.

30-580

50-580

Oswego, NY PMB Systems Engineering, Inc. 7812210235* 7812210235*

7812030356*

7810250190*

	7811130073+ 7811130077+ 7811170123 7811200165 7811200165	50-387 50-387 50-387 50-387 50-387	8 8 8 8		7812110213 7812130083# 7812130098# 7812130130	50-35 50-35 50-35 50-27
	7811200190# 7811270114 7812050178 7812120096 7812120118	50-387 50-387 50-387 50-387 50-387	K A A A C		7812130162 7812180154 7812180154 7812180157* 7812180160 7812180221	50-27 50-27 50-27 50-27 50-27 50-27
	7812210168 7812210168 7812210173 7812210173 7812210177	50-367 50-367 50-367 50-367 50-367	A A A A		7812210074* 7812210165 7812220063 7812220063 7812220064*	50-24 50-27 50-27 50-27 50-27
Perkins, Cole, Stone, Olsen & Williams	7612210177 7612270221 7610130087 7610300109 7611070357	50-387 50-250 50-522 50-522 50-522	A P Q Q	Portland Cament Association Portland General Electric Co.	7812220064* 7812260192 7812290198 7812110279* 7810110161	50-27 50-27 50-27 50-48 50-34
Pfefferkorn & Coolsy, P.A.	7812130227 7810260065 7810300332 7810300332 7810300332	50-522 50-498 50-468 50-468 50-468	0 0 0 0		7810120009 7810120026 7810120106 7810130147 7810130150*	50-34 50-34 50-34 50-34 50-34
	7810300336* 7810300336* 7810300336* 7810300389 78103040297	50-488 50-488 50-488 50-488 50-488	0 0 0		7810140087 7810140122 7810170144 7810170145÷ 7810180070	50-34 50-34 50-34 50-34 50-34
Philadelphia Electric Co.	7810100038 7810100088 7810100096 7810100161 7810110103	50-277 50-277 50-278 50-277 50-277	8 8 8 6 P		7810190184 7810190217 7810200015 7810200107 7810200108*	50-34 50-34 50-34 50-34 50-34
	7810130155 7810130155 7810130163+ 7810200094 7810230164	50-277 50-277 50-277 50-277 50-277	B 8 9 9 9		7810240091 7810310167 7810310170* 7811010075 7811010149	50-34- 50-34- 50-34- 50-34- 50-51-
	7810230167+ 7810240164 7810270007 7810270186 7810270186	50-277 50-277 50-463 50-277 50-277	R S O P P		7811020103 7811070112 7811070152 7811070162 7811070193	50-34- 50-34- 50-34- 50-34-
	7810270188+ 7810270261 7810270270+ 7811010089+ 7811080094	50-277 50-278 50-278 50-277 50-277	P B B G B		7811070198* 7811070286 7811070364 7811080228 7811100114	50-34- 50-34- 50-34- 50-34-
	7811090137 7811090141* 7811090146 7811090152* 7811140086	50-277 50-277 50-277 50-277 50-278	8 8 8		7811100121* 7811100126* 7811100128* 7811100133* 7811140139	50-34- 50-34- 50-34- 50-34- 50-34-
	7811140142 7811140144* 7811150116 7811150117* 7811160084	50-277 50-277 50-171 50-171 50-277	R H H		7811140141* 7811140141* 7811140159 7811140101* 7811140101	50-34 50-34 50-34 50-34 50-34
	7811160084 7811160086* 7811160095 7811170130 7811170130	50-277 50-277 50-277 50-277 50-277	R B B R		78112803174 7811280324 7811280327# 7811300374 7812040031#	50-34 50-34 50-34 50-34
	7811170131+ 7611170131+ 7611280225 7811280227 7611280230+	50-277 50-277 50-277 50-278 50-278	R R B B		7812080078 7812110006 7812110147 7812120105 7812120147	50-34 50-34 50-34 50-51 50-34
	7811280248 7811280248 7811280254* 7811280254* 7811280470	50-352 50-352 50-352 50-352 50-278	8 8 9 9		7812120133* 7812140211 7812140287 7812140377 7812220096	50-34 50-51 50-34 50-34 50-34
	7611300217 7811300220+ 7612010012+ 7812070173 7612070210	50-277 50-277 50-277 50-277 50-277	0 0 8 9	Power Authority of the State of New York	7812280128 7812280130* 7812280179 7810100022 7810100026*	50-34 50-34 50-34 50-33 50-33
	7812070213* 7812080109 7812080111* 7812080112* 7812110213		8 R R R		7810100098 7810100100* 7810110085 7810110094 7810110154	50-28 50-28 50-28 50-33

APFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	CAT
	7610110160 7810120045 7810120046* 7810120038 7810120060*	50-286 P 50-333 8 50-333 8 50-286 8 50-286 8		7812030354# 7812050356# 7812060113 7812070174 7812070178#	50-3 50-3 50-3 50-3
	7810120073 7810120079* 7810130128 7810130132* 7810130167	50-333 8 50-333 8 50-333 R 50-333 R 50-286 R		7812110153 7812120080 7812130168 7812130171* 7812150237	50-3 50-3 50-3 50-3
	7810130180* 7810170108 7810170111* 7810170175 7810180075	50-286 R 50-333 P 50-333 P 50-333 P 50-333 P		7612150241* 7812150267 7812150274* 7812180368 7812190114	50-2 50-2 50-3 50-3
	7810230186 7810230189• 7810230191 7810230263 7810230265*	50-333 8 50-333 8 30-286 P 50-333 8 50-333 8		7812220095 7812220098* 7812220099 7812220100* 7812260019*	50-2 50-2 50-3 50-3
	7810230308 7810230310+ 7810240080 7810240122 7810240126+	\$0-333 B \$0-333 8 \$0-349 A \$0-333 8 \$0-333 8		7812260023* 7812260130 7812260189 7812270242 7812270250*	50-2 50-3 50-3 50-3
	7810240133 7810240139+ 7610250135+ 7810260109 7810270149	50-333 8 50-333 8 50-284 0 50-284 F 50-333 F	Public Citizen Litigation Group	7812290140 7812290170 7812290246 7811270009 7812010357	50-3 50-3 50-4 50-4
	7810300275 7810300280+ 7811010111 7811030079 7811040210	50-333 9 50-333 9 50-333 P 50-549 A 50-286 B	Public Interest Research Oroup Public Bervice Co. of Colorado	7812180077 7810270201 7811010010* 7811010013* 7810100005	50-4 50-3 50-3 50-3
	7811060215* 7811070126 7811070244 7811070248* 7811070253	50-286 8 50-333 F 50-333 8 50-333 B 50-286 P		7810100012 7810110136 7810110264* 7810120063 7810120064*	50-2 50-2 50-2 50-2 50-2
	7811070256* 7811070318 7811070323* 7811080086* 7811080110	50-286 P 50-333 8 50-333 8 50-286 0 50-286 P		7810160100 7810160103* 7810160131 7810170139 7810170174	50-2 50-2 50-2 50-2 50-2
	7811080111* 7811080123* 7811080127* 7811080189* 7811080183	50-286 P 50-286 P 50-286 P 50-286 P 50-286 P		7810180141 7810230165 7810250067 7810260205 7810270228	50-2 50-2 50-2 50-2 50-2
	7811080184* 7811100129* 7811100138* 7811100145* 7811100158*	50-286 Q 50-286 Q 50-286 Q 50-286 Q		7810270232* 7810270276 7810270283* 7810300164 7810300166*	50-2 50-2 50-2 50-2
	7811140104 7811140106* 7811140101 7811140103* 7811140038	50-286 R 50-286 R 50-333 R 50-333 R 50-333 B		7810300179 7810300180* 7810300189 7810300194* 7810300309	50-2 50-2 50-2 50-2
	7811140247 7811140248+ 7811140230+ 7811160069 7811170110	50-284 8 50-333 8 50-284 9 50-333 P 50-333		7810300312* 7810310085 7810310094 7810310225 7810310230*	50-1 50-1 50-1 50-1
	7811200023 7611210274 7811210300 7811210389 7811210414	50-549 A 50-247 P 50-333 P 50-333 P 50-333 B		7811070234 7811070238* 7811160071 7811160096 7811240226	50-2 50-2 50-2 50-2
	7811210422* 7811220189 7811220192* 7811280291 7811280297	50-333 8 50-286 8 50-286 8 50-333 P 50-349 9		7811240228* 7811270154 7811270156* 7811280285 7811280289*	50-4 50-4 50-4 50-4
	7811280302* 7811290182 7812010076* 7812010085* 7812040156	50-549 0 50-286 P 50-286 0 50-286 0 50-333 8		7611280312 7811280318* 7812070186 7812120089 7812130135	50-1 50-1 50-1 50-1
	7812040139* 7812040209 7812050139 7812050316 7812050350	50-333 B 50-549 A 50-549 E 50-549 A		7812130141* 7812130163 7812130164 7812130167* 7812130176	50-2 50-2 50-2

i

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	,	AUTHOR AFPILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	7812130179* 7812130166* 7812130190 7812130192* 7812180243	50-267 50-267 50-267	8 8 8		7810250069 7810250083 7810250083 7810250103 7810250104+	50-311 50-311 50-311 50-272 50-272	A F R R
	7812180245* 7812200164 7812200209 7812200210* 7812220062	50-267 50-267 50-267 50-267 50-267	R P 9 F		7810230118 7810230252* 7810230252* 7810310137 7810310180	50-272 50-354 50-354 50-272 50-272	9 9 9 8
	7812220069* 7812270177 7812270201 7812270206* 7810110138	50-267 50-267 50-267 50-267 50-546	F 9 9		7810310254 7810310260# 7811030119 7811030120# 7811030124#	50-272 50-272 50-311 50-311 50-311	K 8 8
	7810300184 7810300365 7811130194 7812080202 7812130128	50-546 50-546 50-546 50-546 50-546	6 A A		7811040089 7811040091 7811070178 7811070181* 7811070242	50-272 50-272 50-272 50-272 50-272	មេ៤០២២
Public Bervice Co. Of New Hampshire	7812290124 7810310189* 7810310189* 7811010244 7811070140*	50-546 50-443 50-443 50-443 50-443	A A 0 1		7811070265# 7811070266 7811070268# 7811080102 7811080227	50-272 50-272 50-272 50-311 50-311	88844
	7811070140+ 7811090147 7811090147 7811090256 7811290341+	50-443 50-443 50-443 50-443 50-443	1 8 8		7811090084 7811130119* 7811130233 7811130263 7811130266	50-311 50-272 50-311 50-272 50-272	A A 8 8
Public Service Co. of Oklahoma	7811290341* 7810180146 7810240095 7811130066 7811130222	50-443 50-554 50-556 50-556 50-554	8 0		7811140274# 7811160074 7811160075* 7811170181 78111200152	50-311 50-272 50-272 50-272 50-311	8 8 3 5
	7811130222 7811140192 7811140192 7811140214 7811150135	50-556 50-556 50-556 50-556 50-556	L b B		7811200201 7811200203* 7811200352* 7811200437* 7811210323	50-272 50-272 50-437 50-437 50-272	8 8 A R
	7811180136* 7811160081 7811160081 7811280250 7812050285*	50-554 50-554 50-554 50-554 50-554	6 A B 9		7811210343 7811240132 7811240137* 7811240141 7811240142*	50-272 50-272 50-272 50-311 50-311	R B B A A
	7812130138 7812220115 7812220115 7812270200 7812270200	50-554 50-554 50-554 50-554 50-554	***		7811240219 7811240225 7811280275 7811280304 7811280313*	50-272 50-311 50-272 50-272 30-272	5 C 7 C 6
Public Bervice Electric & Gas Co. of New Jersey	7818870231 7810100080 7810100080 7810100088 7810100033*	50-556 50-354 50-354 50-272 50-978	A B B		7611280460 7812050229 7812070224 7812080113 7812080115+	50-272 50-272 50-354 50-272 50-272	8 8 8
	7810100033* 7810100037 7810100087 7810100089 7810110091	50-278 50-272 50-272 50-272 50-272 50-272	8 9 9		7812080134 7812080136= 7812110150 7812120151 7812140167	50-272 50-272 50-272 50-272 50-272	R R G R 8
	7810130134 7810160084 7810160090> 7810170132 7810170132	50-311 50-272 50-272 50-272 50-272	A R R P	·	7812140169* 7812150242 7812150244* 7812200072 7812210206	50-272 50-272 50-272 50-311 50-272	47
	7810170133* 7810170133* 7810170135* 7810170135*	50-272 50-272 50-272 50-272 50-272	Р Р		7812220085 7812220086+ 7812220143 7812270194 7812270248	50-272 50-272 50-311 50-339 50-477	8 8 ¥
	7810180092 7810180128 7810180128 7810180144 7810180144	50-979 50-278 50-278 50-278	R R R R		7812270248 7812290346 7812290200+ 7812280200+ 7812280204+	50-477 50-272 50-477 50-477 50-477	6000
	7810200117 7810200125* 7810230243 7810230249* 7810230252	50-27£ 50-27£ 50-27£	2 8 8	Puget Sound Pawer & Light Co.	7812280204* 7812280216* 7812290181 7811080142 7811080153	50-477 50-311 50-272 50-522 50-522	9 9 F A
	7810230295 7810230295 7810230304 7810240081 7810240149	50-272	6 6 P	Pyle, R.S. Rand Corp. Reilly & Like	7812050180 7812140247 7811200018# 7811200019# 7810110307	50-522 50-518 50-437 50-437 50-322	A 0 A C C

AUTHOR AFFILIATION	ACCEBBION REMUN	BUBJEC.	RY	AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEODRY
	7810190226 7810190226 7810190235 7810200156 7810200156	50-516 50-516 50-516 50-516 50-516	0 0 0		7811160078* 7811170117 7811210261 7811210319 7811270096*	50-312 R 50-312 P 50-312 F 50-312 P 50-312 Q
	7810240087 7810270301 7810310374 7811200002 7811200020	50-516 50-322 50-516 50-322 50-516	0 A 0		7611280209 7612050114 7812050146 7812080094 7812110170	50-312 P 50-312 P 50-312 P 50-312 B
Rensselær Polytechnic Inst. Rhode Island, State of	7812110012 7812150019 7812210471 7811010071 7810180084	50-568 50-322 50-322 50-322	9 9 3 A		7812110173* 7812120147 7812120107 7812140142 7812180159	50-312 8 50-312 8 50-312 P 50-312 0 50-312 F
Rochester Gas & Electric Corp.	7811010132 7811010436 7812010204 7812010335+ 7810160111+	50-566 50-568 50-568 50-568 50-244	A G A G P	Bafe Energy for New Haven	7812200159 7812200196 7812200197* 7811010310 7812130084*	50-312 P 50-312 R 50-312 R 50-502 0
	7810160129 7810170182 7810170213 7810170213* 7810170257	50-244 50-244 50-244 50-244 50-244	P R R F	Baginaw Archaeological Commission San Diego Gas & Electric Co. San Luis Obispo Mothers for Peace	7810130231 7810260118* 7811280007* 7810300008 7811010324	50-329 A 50-361 K 50-206 P 50-275 0 50-275 0
	7810170263* 7810180150* 7810190069* 7810230256 7811010376	50-244 50-244 50-244 50-244 50-485	P P G G	Sargent & Lundy, Inc. Scribe, NY Senate	7812180309 7812050190* 7812130090 7810110203* 7810110205*	50-275 Q 50-267 A 50-220 Q 50-70 P 50-70 P
	7811060088 7811070142 7811070182 7811130232 7811140241	50-244 50-244 50-244 50-244 50-244	F P P P		7810240011* 7810240137* 7811080039 7811280132 7811240094*	50-440 A 50-480 H 50-70 P 50-267 U 50-70 U
	7811280216 7811290179 7811290245 7812050152 7812050187	50-244 50-244 50-244 50-244 50-244	P J P P		7012080211* 7812130326 7812140331* 7812190236 7812280248	50-302 U 50-400 U 50-437 H 50-440 G 50-502 H
	7812080123 7812080126 7812130012 7812220118* 7812280191	50-244 50-244 50-244 50-244 50-485	P P F P G	Senate, Governmental Affairs Shaw, Pittman, Potts & Trowbridge	7612260254 7812120041* 7810130225 7810140022 7810140091	50-338 H 50-580 H 50-266 9 50-484 9
Rockwell International Corp. Ropes & Gray	7812290090 7810270197 7810310185 7811070001 7811070004+	50-244 50-94 50-443 50-471 50-471	P J A G G		7810190210 7810190230 7810200034 7810200177 7810200177	50-484
Bacramento Municipal Utility District	7811070138 7812010057* 7810100016 7810100021* 7810100050	50-443 50-471 50-312 50-312 50-312	1 9 8		7810200182* 7810200182* 7810230326 7810240227 7810240227	50-483 Q 50-483 Q 50-246 Q 50-483 Q
	7810100056# 7810100061 7810100069# 7810100073 7810100077#	50-312 50-312 50-312 50-312 50-312	8 8 8 8	•	7810270005 7810300247 7810310078 7811010080 7811010285	50-484 Q 50-580 Q 50-484 Q 50-484 Q 50-436 M
	7810110124 7810110124+ 7810120027 7810130131 7810130135=	90-315 90-315 90-315 90-315	R R P 8 8		7811010285 7811070137 7811070322 7811130071 7811130146	70-346 M 70-440 A 70-502 G 70-483 Q 70-346 M
	7810130178 7810170179 7810170201# 7810200104 7810200104*	20-315 20-315 20-315 20-315	6 6 8 8		7811130146 7811130146 7811130146 7811130230* 7811130230*	50-346 M 50-346 M 50-346 M 50-346 M
	7810230079 7810230160 7810230277 7810230285* 7810250184	50-312 50-312 50-312 50-312	F 8 8		7811130230* 7811270048 7811270048 7811270050* 7811270050*	50-346 M 50-483 G 50-483 G 50-483 G
	7810310067 7811030149 7811030152* 7811030153 7811030156*	50-312 50-312 50-312 50-312	8 8 8		7812010314 7812080233 7812110254 7812130057 7812210456	50-400 Q 50-580 Q 50-483 Q 50-483 Q 50-020 Q
	7811070201 7811130089 7811140230 7811140236* 7811160076	50-312 50-312 50-312 50-312	P G B S R		7812220109 7812220141 7812280079 7812280345 7812290100	50~502 0 50~320 0 50~400 0 50~440 0 50~502 0

AUTHOR AFFILIATION	ACCEBBION NUMBER	BUBJECT CATEGOR		AUTHOR AFFILIATION	ACCEBBION NUMBER	SU CA
Sheldon, Harmon & Weiss	7812290105* 7810300039 7810300039 7810300057* 7810300057+	50-338 50-338 50-338 50-309	о Р С		781 1080103 781 1100045 781 1100045 781 1100046 781 1100047	50- 50- 50- 50-
Bierra Club	7810300065* 7810300065* 7812110101 7812280138 7811280157*	50-338 50-338 50-338 50-338 50-458	0 0 0		7811100048 7811140177 7811140181# 7811160080 7811160082#	50- 50- 50- 50- 50-
Bimmonds, Hinslow, Hillis & Abbott Bkagitonians Concerned About Nuclear Power	7812270009+ 7811210140 7810130009 7812130259	50-220 50-471 50-522	9 4 0		781 1210315 781 1210377 781 1220145 781 1220168	50- 50- 50-
	7812190080	30-443 50-522	9		7811220169* 7811220169*	50-
Snell & Wilmer Bouth Carolina Electric & Gas Co	7811020082 7810120070* 7810120137 7810130046 7810130108*	30-592 50-395 50-395 50-395 50-395	M A Q C		7811280212 7811280219 7811280245 7811280259	50- 50- 50-
	7810170105 7810170163 7810170227 7810170239* 7810230161	50-395 50-395 50-395 50-395 50-395	A 0 0 0		7811260277 7811280281* 7811300209 7812040193 7812030186	50- 50- 50- 50-
	7810300217 7810300384 7810300387* 7810310083 7811010120	50-395 50-395 50-395 50-395 50-395	A 0 0 A K		7812050219 7812060089 7812120101 7812130177 7812130210#	50- 50- 50- 50-
	7811010125* 7811010173 7811070128 7811080151* 7811090232	50-395 50-395 50-395 50-395 50-395	K C A Q		7812130280 7812190120 7812190120 7812190124 7812190124	50- 50- 50- 50-
	7811150062* 7811150181 7811210286 7811210297 7811220184	50-395 50-395 50-395 50-395 50-395	G F K A		7812190150 7812190157 7812190159* 7812200132 7812210098*	50- 50- 50- 50-
	7811220260 7812010329 7812040167 7812040201 7812040028*	50-395 50-395 50-395 50-395 50-395	۵ ۹ ۵		7812210263* 7812210263* 7812210265* 7812210265* 7812210368*	50- 50- 50- 50-
	7812040374 7812120089 7812120156 7812120200 7812120206*	50-395 50-395 50-395 50-395 50-395	Q Q A R R		7812220082 7812270165 7812270196 7812270199* 7812270205	50- 50- 50- 50- 50-
	7612130364 7812140037 7812200266 7612200269* 7812280302	50-395 50-395 50-395 50-395 50-395	0 8 1	Spiegel & McDiaratd	7812290113 78122901154 7810270390 7811030245 7811080064	50- 50- 50- 50-
South Carolina, Univ. of Southern Celifornia Edison Co.	7810#40077# 78101100% 7810130159 7810130160# 7810170103	50-269 50-206 50-206 50-266	R P R R		7811100163 7811100180 7812040260 7812180246 7812180339	50- 50- 50- 50-
	7810180083 7810180089 7810180184 7810180187	50-361 50-206 50-361 50-206	A 8 A 8	Standardized Nuclear Unit Power Plant Bystem	7812180342# 7812270069 7812270071 7812270058	50- 50- 50-
	7810230101 7810230105 7810230155 7810230268 7810250039 7810250066	50-361 50-206 50-206 50-206 50-206	9 P P J P	Stewart & DeChant Co. Stewart & Mebster, Inc.	7811020313 7811240072* 7811240072* 7812200177* 7812290275*	50- 50- 50- 50- 50-
	7810250123 7810240113 7810240118# 7810240118# 7810270214	50-206 50-361 50-361 50-361 50-206	8 K K	Buffolk County, NY	7810140107 7811210110 7811290311 7811300373 7818210411	50 50 50 50
	7810270214# 7810300098 7810310132 7811010167 7811010167	50-206 50-206 50-361 50-361	P P H	Sulliven, W. F. Taunton Municipal Lighting Plant Tennesses Valley Authority	7812260322 7812070054* 7811070156* 7810100002 7810100006*	50 50 50 50
	7811060050 7811060084 7811060104 7811070243	50-361 50-206 50-206 50-206	F		7810100036 7810100040* 7810100049 7810100047*	50 50 50

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEO	PΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	7810110107 7810110107 7810110158 7810120065 7810160106	50-259 50-259 50-327 50-259 50-259	P P A P R		7811060090 7811060094 7811060094 7811060096 7811060096	50-390 50-327 50-327 50-390 50-390	9 A A S
	7810160106 7810160106 78101601090 78101701610 7810170197	50-259 50-259 50-259 50-259 50-327	25 25 25 25 25 25 25 25 25 25 25 25 25 2		7811070109 7811070132 7811070236 7811070236 7811070240*	50-438 50-296 50-327 50-327 50-327	K P 8 9 A
	7810170206 7810170206 7810170237* 7810180093 7810180093	50-390 50-390 50-321 50-327 50-327	A 8 A A		7811070240* 7811070245 7811070245 7811070249* 7811070249*	50-327 50-518 50-518 50-518 50-518	A 8 9
	7810180138 7810180142* 7810190164 7810190164 7810190228	50-260 50-260 50-327 50-327 50-370	8 9 8 A		7811070276 7811070277 7811070277 7811070277 7811070277	50~327 50-327 50-327 50-327 50-327	8 A A A
	7810230135 7810230135 7810230227* 7810230244 7810230244	50-327 50-327 50-259 50-259 50-259	F G P P		7811070277 7811070277 7811070277 7811070277 7811070281*	50-327 50-327 50-327 50-327 50-327	A A A
	7810230244 7810240037 7810240144 7810240144 7810240146	50-259 50-564 50-259 50-259 50-276	P G P P S	·	7811070281* 7811070281* 7811070281* 7811070281* 7811070281*	50-327 50-327 50-327 50-327 50-327	A A A
	7810240151* 7810240153 7810250035 7810250080 7810250082	50-296 50-259 50-260 50-296 50-260	8 8 8 P		7811070281* 7811070281* 7811080114 7811080114 7811080132	50-327 50-327 50-390 50-390 50-390	A A A
	7810250085# 7810250088 7810250088 7810250095 7810250095	50-240 50-566 50-566 50-327 50-327	Р F Q G		7611080132 7811080134* 7811080134* 7811080160 7811080164	50-390 50-390 50-390 50-390 50-518	K K F A
	7810250120 7810250120 7810250122* 7810250122* 7810300103	50-327 50-327 50-327 50-327 50-259	A A A R		7811080164 7811080164 7811080164 7811080167* 7811080234*	50-518 50-518 50-518 50-518 50-438	A A A
	7810300103 7810300169 7810300171* 7810310064* 7810310076	50-259 50-260 50-260 50-259 50-259	R 9 0 F		7811090204* 7811130013* 7811130013* 7811130013* 7811140134	50-259 50-259 50-259 50-259 50-327	0 0 0 F
	7810310076 7810310113 7810310113 7810310183 7810310186*	50-259 50-327 50-327 50-259 50-259	F F 8 8		7811140134 7811140137 7811140140* 7811140140* 7811140165	50-327 50-259 50-259 50-259 50-294	F R R B
	7811010073 7811010073 7811020074 7811020231 7811020231	50-327 50-327 50-438 50-438 50-438	A A K K		7811140169 7811140186 7811140193> 7811140201 7811140206>	50-296 50-296 50-296 50-296 50-296	8 9 9
	7611020234* 7611020234* 7811020362 7811030076* 7811030101	50-438 50-438 50-259 50-438 50-390	К 8 0 Р		7811140217 7811140221* 7811140240 7811140244* 7811150120	50-259 50-259 50-259 50-259 50-390	8 8 8 H
	7811030104# 7811030257 7811030257 7811030260# 7811030260#	50-370 50-438 50-438 50-438 50-438	A 8 8		7811150120 7811150123 7811150123 7811150128 7811150129*	50-390 50-327 50-327 50-260 50-260	4 4 4
	7811030263 7811030263 7811030265* 7811030265* 7811060063	50-327 50-327 50-327 50-327 50-370	8 9 8 A		7811150137 7811150152 7811150152 7811150176* 7811150176*	50-327 50-327 50-327 50-327 50-327	A A A
	7811060063 7811060063 7811060063 7811060063 7811060063	50-327 50-390 50-327 50-390 50-390	8 8 8 9		7811150196# 7811150199* 7811160067 7811160067 7811160072*	50-327 50-327 50-438 50-438 50-438	A A B B
	7811060063 7811060063 7811060069# 7811060069# 7811060090	50-327 50-327 50-390 50-390 50-390	8 8 8		7811160072* 7811160098 7811160099 7811160099 7811160104*	50-438 50-327 50-327 50-296 50-296	8 A 8 8

CORPORATE SOURCE INDEX

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOGR	Υ	AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEGOR	
	781116014B 781116014B 7811170113 7811170113 7811170113	50-327 50-327 50-259 50-259 50-259	A A P P		7812080213 7812080213 7812080213 7812080221* 7812080221*	50-518 50-518 50-518 50-518 50-518	9 8 8
	7811170175 7811170175 7811170215 7811170215 7811170215	50-259 50-259 50-259 50-259 50-259	P P P P		7812080221* 7812080221* 7812080221* 7812080221* 7812080229	50-518 50-518 50-518 50-518 50-390	8 8 8
	7811200200 7811200200 7811210305 7811210310* 7811210406	50-259 50-259 50-327 50-327 50-518	F F A A		7812110017 7812110017 7812110142 7812110148 7812110168 7812120075	50-390 50-390 50-327 50-296 50-390	9 A B A
	7811210406 7811220091* 7811220147 7811220147 7811220211	50-518 50-260 50-390 50-390 50-553	A G A A		7612120099 7612120099 7612120156 7612120156 7612120164	50-390 50-390 50-327 50-327 50-327	G A A K
	7811280187 7811280191+ 7811280201 7811280203+ 7811280205	50-259 50-259 50-260 50-260 50-259	8 8 8 8		7812120166 7812180170 7812120170 7812120174 7812120177#	50-327 50-327 50-327 50-260 50-260	K A A 9 9
	7811280207* 7811280214 7811280251 7811280255 7811280294	50-259 50-259 50-438 50-296 50-296	9 8 A P 8		7812130372 7812130372 7812130372 7812130372 7812140286 7812140286	50-259 50-259 50-259 50-327 50-327	0 0 8 8
	7811290298 7811290248 7811290248 7811290252* 7811290252*	50-276 50-390 50-390 50-390 50-390	8 K K K		7812140288* 7812140288* 7812180248 7812180350 7812180130	50-327 50-327 50-276 50-327 50-327	¥ 8 8
	7811300198 7812010266 7812010266 7812010268# 7812010268#	50-327 50-327 50-327 50-327 50-327	K 9 8 9		7812180130 781219098 7812190110 7812190111# 7812190119	50-327 50-390 50-296 50-296 50-296	8 8 8 8
	7612040055+ 7612040055+ 7612040192 7612040197+ 7612040226	50-390 50-390 50-327 50-327 50-390	0 8 8		7812190122* 7812190161 7812190161 7812190161 7812190162*	50-276 50-257 50-257 50-257 50-257	B R R R
	7612040226 7612040227* 7612040227* 7612050117* 7612030117*	50-390 50-390 50-390 50-327 50-327	B B G Q		7812190162# 7812190162# 7812200154 7812200154 7812200154	50-259 50-259 50-259 50-259 50-259	R R P P
	7812050125# 7812050171 7812050189 7812050199 7812050201#	50-327 50-296 50-259 50-296 50-296	Q P P B		7812200244 7812200244 7812200244 7812200246# 7812200246#	50-259 50-259 50-259 50-259 50-259	K K K K
	7812050243 7812050265 7812050265 7812050266 7812050266	50~259 50~327 50~327 50~390 50~390	P 8 8 8		781 2200246#* 781 2200256 781 2200256 781 2200256 781 2210248	50-259 50-259 50-259 50-259 50-327	K P P
	7812050248+ 7812050248+ 7812050270+ 7812050270+ 7812040021+	50-390 50-390 50-327 50-327 50-259	9 9 9		781 221 0248 781 2260 131 781 2260 131 781 2260 134 781 2260 134 781 2260 134	50-327 50-327 50-327 50-327 50-327	FKKK
	7812060074* 7812060074* 7812060121 7812060121 7812060129*	50-327 50-327 50-327 50-327 50-327	0 8 8 8		7812240163 7812870175 7812870175 7812870202 7812870202	50-257 50-257 50-257 50-327 50-327	PPAA
	7812040129# 7812070170 7812070177 7812070183 7812070250	50-327 50-259 50-327 50-566 50-390	8 P Q A B		7812270265 7812270249+ 7812270043+ 7812270043+ 7812270058+	50~259 50~259 50~390 50~390 50~438	8 0 0
	7812070250 7812070259* 7812070259* 7812070264 7812080091	50-390 50-390 50-390 50-260 50-327	8 8 8		781 2290117* 781 2290117* 781 2290124 781 2290217 781 2290217	50-327 50-327 50-390 50-259 50-259	9 4 4 4
	7812080101 7812080103*	50-260 50-260	8 8	Teangagge, Ghate at	7812270221 7812270224*	80-840 80-840	B

AUTHOR AFFILIATION	ACCESSION NUMBER	TOBLEUR	AUTHOR AFFILIATION	ACCESSION NUMBER	5
Texas Public Interest Research Group	7812220080# 7810160132 7810160134# 7811160196 7811210038	50-59 F 50-466 H 50-466 H 50-466 G		7811070273 7811070275# 7811090131 7811090178 7811090179#	50 50 50
Texas Tech Univ. Texas Utilities Co.	7811210044* 7812180306 7811210046 7810140141 7810240221*	50-466 Q 50-466 Q 50-456 A 50-445 M 50-445 Q		7811130230# 7811140135 7811140136# 7811150124 7811170100	50 50 50 50
Texas Utilities Generating Co.	7811170133 7812190070 7812210150 7812270259 7810240161	50-445 A 50-445 K 50-445 A 50-445 K 50-445 A		7811200087 7811200100* 7811200106* 7811200178 7811200209	50 50 50 50
	7810240186 7811030249* 7811070134 7811070260* 7811070260*	50-445 A 50-445 Q 50-445 B 50-445 Q 50-445 Q		7811200212# 7811210347 7811210352# 7811210357# 7811210359#	50 50 50 50
	7811080031 7811210348 7811210401 7811280183 7811280218	50-445 Q 50-445 A 50-445 B 50-445 B 50-445 A		7811210362* 7811210372 7811210374* 7811210375* 7811210379*	50 50 50 50
	7811280367 7811280367 7811300020* 7811300109* 7812070111	50-445 8 50-445 9 50-445 0 50-445 6 50-445 K		7811210382* 7811220158 7811220174 7811240159 7811280198	50 50 50 50
	7812070111 7812070116* 7812070116* 7812150264 7812150266*	50-445 H 50-445 K 50-445 K 50-445 C 50-445 C		7811280202* 7812010207 7812010213* 7812040228 7812050157	50 50 50 50
	7812190142* 7812190142* 7812190232 7812190232 7812190232 7812200184	50-445 G 50-445 G 50-445 G 50-445 G 50-445 A		7812050162* 7812050163 7812050204 7812050206* 7812050217	50 50 50 50
	7812200184 7812200186* 7812200186* 7812280109 7812280109	30-443 A 30-445 A 30-445 A 30-445 B 30-445 B		7812050218* 7812070196 7812070198 7812070199* 7812070201*	50 50 50 50
Texas Utilities Bervices, Inc. Texas, State of Thomsen, F. T.	7811220083 7811020378 7811290014 7812130231 7810190199	50-445 A 50-445 M 50-478 G 50-478 M 50-522 G		7812120140 7812120146* 7812120145 7812120172 7812120173*	50 50 50 50
Taledo Edison Cp.	7810100060 7810100063* 7810120074 7810120078* 7810120084*	50-346 8 50-346 8 50-346 8 50-346 8 50-346 8		7812120181* 7812140137 7812140140* 7812130278 7812130278	50 50 50 50
	7810130142 7810130144* 7810160124 7810160127* 7810160137	50-346 R 50-346 R 50-346 8 50-346 S 50-346 B		7812130276 7812130278* 7812180134 7812180206 7812190081	50 50 50 50
	7810160140* 7810180041 7810180042* 7810230269 7810230275*	50-346 8 50-346 8 50-346 8 50-346 8 50-346 8		7812170115 7812170116# 7812200166 7812270256 781227020	50 50 50 50
	7810270171 7810270177 7810310194 7810310201# 7810310303	50-346 P 50-346 P 50-346 B 50-346 B 50-346 B	Trans-Eastern Inspection Services, Inc. Transportation, Dept. of Transury, Dept. of Trojan Decommissioning Alliance	7812270208# 7812200127 7810230170 7812140325 7812080156#	50 50 50 50
	7810310309* 7810310330* 7810310342* 7810310346* 7811010066	30-346 8 50-346 8 50-346 8 50-346 8 50-500 A	Union Carbide Corp. Union Electric Co.	7811160147 7812190091 7812270164 7812270157 7812200237	50 50 50 50
	7811010066 7811010129 7811010129 7811030137 7811030138*	50-500 A 50-500 I 50-500 I 50-346 8 50-346 8	Valentine, P. C. Varmont Electric Cooperative, Inc. Varmont Electric Power Co., Inc.	7812290277 7811070358 7811070143* 7811070161* 7811070143*	50 50 50 50
	7811060118 7811070184 7811070188* 7811070264 7811070267*	50-346 P 50-346 S 50-346 B 50-346 B 50-346 B	Vermont Yenkee Nuclear Power Corp.	7810160135 7810170192 7810170193* 7810200090 7810310244	56 56 56

AUTHOR AFFIL IATION	ACCEBBION NUMBER	SUBJECT CATEOORY		authgr Affiliation	ACCEBSION NUMBER	CATECORY
	7810310248+ 7811020175+ 7811090166 7811140123 7811140127+	50-271 (50-271) 50-271 (9 9 H R R		7810270112 7810270153 7810270153 7810270174 7810270174	50-404 A 50-338 P 50-338 P 50-280 P 50-280 P
	7811140224 7811160102 7811160103# 7811160128 7811160130#	50-271 50-271 50-271	P 8 8 8 8		78102702234 78102702234 7810300022 7810300022 7810310089	50-280 P 50-280 P 50-280 F 50-280 F 50-338 Q
	7811270130 7611270134* 7812050130 7812150270 7812150292*	50-271 50-271 50-271	P P F R R		7810310238 7810310242* 7810310252* 7811010415* 7811020306	50-338 8 50-338 8 50-280 0 50-338 R
	7812180173 7812180176* 7812180170 7812180193 7812180194*	50-271 50-271 50-271	8 8 8 8		7811020306 7811020306 78110203124 7811030160 7811030160	50-338 R 50-338 R 50-338 R 50-338 P 50-338 P
	7812180199# 7812180213 781218021&# 7812180219 7812180222#</td><td>50-271 50-271 50-271</td><td>8 8 8 8</td><td></td><td>7811060038* 7811060078 7811060102 7811060211 7811060213*</td><td>50-338 Q 50-338 P 50-339 A 50-281 S 50-281 S</td></tr><tr><td>Varmont, State of Virginia Electric & Power Co.</td><td>7612180237 7612180241# 7812270276 7810240145 7810100057</td><td>50-271 50-271</td><td>8 8 F P B</td><td></td><td>7811060217# 7811060233 7811060237# 7811060240# 7811060242#</td><td>50-338 8 50-338 8 50-338 8 50-338 8</td></tr><tr><td></td><td>7810100045* 7810100074 7810100079* 7810110127 7810110132*</td><td>50-280 50-280 50-280 50-280</td><td>8 9 9</td><td></td><td>7811040245+ 7811070130 7811070130 7811070146 7811070146</td><td>50-338 8 50-280 P 50-280 P 50-338 P</td></tr><tr><td></td><td>7810110149 7810110149 7810110148 7810110142 7810120034</td><td>50-338 50-338 50-338 50-338 60-280</td><td>e e J J e</td><td></td><td>7811070151* 7811070151* 7811070190 7811070190 7811070228</td><td>50-338 P 50-338 P 50-280 P 50-338 8</td></tr><tr><td></td><td>7810130140 7810130141 7810130148* 7810130148* 7810160139</td><td>50-338 50-338 50-338 50-338 50-280</td><td>9 0 8 8 P</td><td></td><td>7811070233+ 7811070237+ 7811070241+ 7811070258 7811070261+</td><td>50-338 8 50-338 8 50-338 8 50-338 8 50-338 8</td></tr><tr><td></td><td>7610160198 7810170109 7810170163 7810180119 7810180119</td><td>50-280 50-404 50-338 50-280 50-260</td><td>P A P P</td><td></td><td>7811070326 7811070367 7811070367 7811070177 7811070210+</td><td>50-339 9 50-338 0 50-338 0 50-280 9 50-280 9</td></tr><tr><td></td><td>7810180121* 7810180139 7810200054 7810200058 7810200073</td><td>50-280 50-338 50-339 50-339 50-338</td><td>P J A A P</td><td>·</td><td>7811070215* 7811070217* 7811070219* 7811070236 7811070240*</td><td>20-581 8 20-581 8 20-590 8 20-590 8 20-590 8</td></tr><tr><td>·</td><td>7810200109 7810200110 7810200112# 7810200118# 7810230171</td><td>50-281 50-280 50-280 50-338</td><td>9 9 8 R</td><td></td><td>7811070243 7811130149 7811130238* 7811140101 7811140128</td><td>50-339 8 50-338 8 50-280 0 50-336 P 50-280 P</td></tr><tr><td></td><td>7810230174* 7810230184 7810230184 7810230187* 7810230187*</td><td>50-338 50-280 50-280 50-280 50-280</td><td>R R R R</td><td></td><td>7811140129 7811160087 7811170107 7811170109+ 7811170182</td><td>50-337 8 50-337 A 50-338 R 50-338 R 50-338 B</td></tr><tr><td></td><td>7810230254 7810230257 7810230260# 7810230262# 7810230264</td><td>50-338 50-281 50-338 50-281 50-339</td><td>9 9 8 8</td><td></td><td>7811170183 7811170183 7811170184+ 7811170185+ 7811170185+</td><td>50-280 8 50-280 9 50-238 8 50-280 8 50-280 8</td></tr><tr><td></td><td>7810230283 7810230291# 7810230297 7810230307 7810240140</td><td>50-338 50-338 50-339 50-404 50-339</td><td>Y Y 8</td><td></td><td>7811170189* 7811170192* 7811170192* 78111200133* 7811200194</td><td>50-338 8 50-280 R 50-260 R 50-260 Q 50-260 R</td></tr><tr><td></td><td>7810250232 7810240121 78102401284 78102401294 78102401304</td><td>50-280 50-238 50-238 50-338 50-338</td><td>P B B B</td><td></td><td>7811200194 7811200198+ 7811200198+ 7811210259 7811210266+</td><td>50-260 R 50-280 R 50-260 R 50-281 8 50-261 8</td></tr><tr><td></td><td>7810260131# 7810260132# 7810260133# 7810260135# 7810260164#</td><td>50-338</td><td>8 8 8 8</td><td></td><td>7811210290 7811210294* 7811210309 7811210313 7811210315*</td><td>50-338 B 50-339 B 50-339 B 50-338 B 50-338 B</td></tr><tr><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>					

AUTHOR AFFILIATION	ACCEBBION NUMBER	9UBJEC1 CATEGOR	4¥	AUTHOR AFF IL 1ATION	ACCESSION NUMBER	SUBJE
	7811210399 7811220145 7811220145 7811220148+ 7811220148+	50-339 50-336 50-336 50-338 50-338	6 P P P		7812180433 7812190079 7812190088 7812190088 7812190090	50-280 50-280 50-280 50-280 50-280
	7811240050+ 7811240111 7811240111 7811280200 7811280236	50-338 50-338 50-338 50-404 50-280	Q P A B		7812190090 7812190148 7812190148 7812190149* 7812190149*	50-280 50-280 50-280 50-280
	7811280238* 7811280247 7811280247 7811280286 7811280292*	50-280 50-280 50-280 50-281 50-281	8 P 8 8		7812200169 7812200169 7812200204 7812200204 7812200207#	50-280 50-280 50-280 50-280 50-280
	7811280308 7811280316 7811280320• 7811280321• 7811280322	50-338 50-338 50-338 50-338 50-338	P 8 9 8		7812200207* 7812200212 7812200225 7812200234 7812200239*	50-260 50-339 50-339 50-338
	7811280325+ 7811280326+ 7811280330+ 7811300222 7811300222	50-238 50-238 50-238 50-280 50-280	3 8 8 8 P P		7812200253 7812200255* 7812200257* 7812200260	50-338 50-338 50-338 50-280
	7812010255 7812010255 7812010255 7812010264	50-338 50-338 50-338	A A A		7812200260 7812200262# 7812220078 7812240195 7812240195	50-280 50-280 50-339 50-338 50-338
	7812010265* 7812010321 7812040209 7812040211* 7812040213*	50-338 50-339 50-338 50-338	R 6 8 8 8 8		7812260252 7812260255 7812270170 7812270170 7812270189	50-280 50-339 50-338 50-338 50-338
	7812040217* 7812040217* 7812040230 7812040233* 7812050208 7812050209*	50-338 50-280 50-280 50-280 50-280 50-280	3 9 8 8 8		7812270189 7812270235 7812270238* 7812270270 7812270281* 7812270290	50-338 50-338 50-338 50-281 50-281
	7812030211* 7812030214* 7812030223 7812030226* 7812060134	50-280 50-280 50-338 50-338 50-338	9 9 9		7812270274# 7812270320 7812270324# 7812280132 7812280136	50-280 50-280 50-280 50-280 50-338
	7812060134 7812060142* 7812060142* 7812070189 7812070190*	50-338 50-338 50-336 50-338 50-338	ធ ១ ១ ទ ទ	Virginia. Btate of Virginia. Univ. of	7812280259 7812280259 7810180143 7811080035 7811010102	50-338 50-338 50-437 50-338
	7812070193 7812070195* 7812070271 7812110090 7812110149	50-338 50-338 50-338 50-338 50-338	8 9 8 P		7811080179 7812200221 7812200222 7812200222 7812200232	50-62 50-62 50-62 50-62
	7812110191 7812110192* 7812110193 7812110196* 7812110204	50-338 50-338 50-338 50-338 50-338	9 9 9 9	Vollen, R.J. & Whicher, J.M. Mald. Harkrader & Ross Washington Public Pawer Supply Bystem	7811160050 7812180246 7810110206* 7811010119 7811020245	50-367 50-329 50-460 50-397 50-460
	7812110208* 7812120063 7812120117 7812130381 7612130381	50-338 50-339 50-339 50-260 50-260	В А А Q		7811020245 7811020249* 7811020249* 7811070147* 7811070249	50-460 50-460 50-460 50-397
	7812130381 7812130381 7812140125 7812140126# 7812140129#	50-260 50-260 50-280 50-280 50-260	G G 9 8		7811070270* 7811150021 7811220197* 7811280245 781280245	50-397 50-397 50-397 50-397 50-397
	7812140131* 7612140224 7812140229* 7612140234* 7612150094	50-280 50-261 50-261 50-281 50-338	8 8 9 8		7912130110 7812130190 7812210141* 7812270193 7812280144	50-397 50-397 50-460 50-397
	7812150277 7812150282 7812150289 7812150304 7812180302+	50-338 50-280 50-338 50-338	P P P Q	Washington, State of	7812270148 7812270151* 7905070295 7811080098	50-508 50-508 50-397 50-397
	7812180358+ 7812180358+ 7812180433 7812180433	50-280 50-280 50-280	Q Q P P	Hatts, A. R.	7811140279 7811140279 7811160042 7811160042 7811200411	50-522 50-522 50-522 50-522
	7812180433	50-280	P	Hestinghouse Electric Carp	7810190184	50-393

:

Wisconsin Paper Council Wisconsin Public Bervice Corp.	78122701584 7812270452 7812010079 7810100055	50-30: 50-26: 50-30: 50-30:	5 0		7811270255 7811270344+ 7811270344+ 7811200378	50-29 50-443 50-443 50-29
	7812150305 7812260169 7812260169 7812260172 7812260172 7812270157		5 F 5 F 6 F		7811280323+ 7811280328 7811280322+ 7811280473 7811290198 7811290203+	50-29 50-29 50-29 50-29 50-29
	7812110110 7812110189 7812120085 7812120087 7812130084		6 8 6 R		7811240236 7811280221 7811280224 7811280290 7811280314	50-29 50-29 50-29 50-29 50-29
	7812050049 7812050049 7812050101 7812050188 7812060253	50-246 50-246 50-266 50-301	P P		7811170201 7811170211 7811210317 7811210325 7811240167	50-29 50-29 50-29 50-29 50-29
	7811240158* 7811280229 7811280240 7811300179 7812010225	50-266 50-266 50-502 50-502 50-266	P B A		7811090150* 7811140120 7811140122* 7811140190 7811170200	50-443 50-29 50-29 50-29 50-29
	7811240131 7811240134+ 7811240136+ 7811240149 7811240155	50-301 50-301 50-301 50-266 50-266	. 8		7810240145# 7811020246 7811020247 7811090145 7811090150#	50-27 50-27 50-27 50-27 50-443
	7811210262 7811210349 7811210393 7811240119 7811240130	50-246 50-301 50-266 50-261			7810200051 7810240085 7810240152 7810240154 7810240154	50-29 50-29 50-29 50-29
	7811140173+ 7811140174 7811140178# 7811150167 7811150173+	50-266 50-266 50-266 50-202	8 R F		7810170178* 7810180008 7810180009* 7810180015 7810180017*	50-27 50-27 50-27 50-27 50-27
	7811140102 781114010B* 7811140124 7811140124 7811140171	50-502 50-564 50-565 50-505	ለ ሉ የ የ	Y 1, Inc. Yankme Atomic Electric Co.	7812080203* 7810110163 7810110177 7810130127 7810170176	50-546 50-29 50-29 50-29 50-29
	7810230272 7810230086 7810230108 7811070374 7811130203	50-266 50-502 50-866 50-866	P A O P	Hisconsin, Univ. of, Milwautee Horcester Polytechnic Inst.	7612220029* 7612220031* 7612270050 7611200092* 7611240038	50-305 50-305 50-266 50-346 50-134
	7810180046+ 7810180099 7810180102+ 7810190136+ 7810230272	50-266 50-301 50-301 50-266 50-266	19 R P P		7810170088* 7810170088* 7811200040 7812130087* 7812220027	30-266 30-266 30-464 30-302 30-303
	7810170171 7810170173* 7810180038 7810180040* 7810180043	50-266 50-266 50-266 50-266 50-266	8 8 8	Wisconsin. State of	7812150234* 7812210194 7812270171 7810190085 7810190085	50-305 50-305 50-305 50-266 50-266
Wilt, D.D Wisconsin Electric Power Co.	7812290136 7812290141* 7810240016* 7810170153 7810170153	50-480 50-480 50-440 50-266 50-266	A A P P		78112803034 78112803104 7812080108 7812130220 7812130232	50-305 50-305 50-305 50-305 50-305
	7812190140 7812200145 7812200190 7812200249 7812200251+	50-545 50-395 50-568 50-582 50-537	А Н А Н		7811140118# 7811140196 7811280196 7811280199# 7811280299	50-305 50-305 50-305 50-305 50-305
	7812080039 7812080039 7812080043* 7812080043* 7812080142*	50-272 50-272 50-272 50-272 50-306	Р Р Р		7810240138* 7810270139 7810300105 7811070227 7811140116	50-305 50-305 50-305 50-305 50-305
	7811140133* 7811160127 7811210234 7811240164 7811240165	50-266 50-572 50-275 50-445 50-445	Р В А А		7810170156 7810170159+ 7810230247 7810230251+ 7810240128	50-305 50-305 50-305 50-305 50-305
	7810190248 7811030146 7811140131* 7811140131* 7811140133*	50-87 50-22 50-266 50-266 50-266	0 0 P P		7810100062* 7810110093 7810110130 7810120041 7810130149	50-305 50-305 50-305 50-305 50-305

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	CATEG	ORY
	7812010145 7812010224 7812040171 7812040234 7812050128	50-29 50-29 50-29 50-29 50-29	9 P P		7812080116 7812140145 7812150286 7812150288*	50-29 50-29 50-29 50-29	P P R R
		**	•		7812190087 7812200230	50-29 50-29	F

REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents. An asteriak following the accession number in this index indicates that the document is an enclosure to another document. To obtain the accession number of the principal document under which the enclosure is listed, refer to the index entitled "Cross Reference of Enclosures to Principal Documents."

REPORT NUMBER	ACCEBBION NUMBER	BUBJECT CATEGORY	OTHER REPORT NUMBER
108-78/M178PF	7812270181*	50-315 P	
5182~087-09	7810120070*	30-395 A	
7811210046	7811210046	50-416 A	
7812130385	7812130386	50-305 P	
BAH-1 504	7811160064#	50-313 P	
CEN-039(A)-NP	7810190089*	50-388 P	
CEN-039(A)-NP/I	7810190090#		
CEN-Q7L(A)-NP/L	7810190092#	50-34B P	
CEN-077(M)-NP	7812200223*		
CEN-093(M)-NP	7811150099#	50-309 P	
CEN-1-4(N)-NP	7812260142+	50-336 0	
E2A4365	7812010249*		
FBDU-247-01	7811200221*		
IWL-6343-432	7811020312#		
NEDC-21974	78112700994	50-155 F	NUS3234
NEDD-23978	7812110116#		
NEDO-2404B	7810300138*		
NED0~240B3	7812270172	50-447 A	
NEDO∽24129-1 801	7810170114#		
NEDO-24129-2 802	7812120082*	50-333 F	•
NEDO-24136 RO1	7812050251+		
NEB 01A0073 ROI	78101601 4 6#		
NEB 81A054B RO1	7810160151#		
NEB81A0032	7812080140#		
NNI-77-7NP	7811220171*	50-220 F	•

REPORT NUMBER	ACCEBSION NUMBER	BUBJECT CATEGORY	
NUREG-0036 ADD DAFT	7811170341)
NUREQ-0309 B01	7811040070*	50-522	-
NUREQ-0428	7811210199	50-466 1	D
NUREO-0437	7811210069		В
NUREQ-0455	7811210428		D
NUREO - 0469	7811020010#	50-5B2 (E
NUREO-0470	7812270414	50-466 1	D-
NUREG-0473 DRFT	7811280104#	50-373	A.
NUREG-0485 VOI	7B11100109#	50-10	Þ
NUREQ - 0486	7811100035		D
NUREG-0490	7812040263	50-361	מ
NUREQ-0491	7811280090	50-572 (E
P77-54-19	7812080136*	50-272	R
RH-78-4-801	7810250122*	50-327	A
8CE-1-A	7812130210#	50-361	A
9ECY-78-553	7811200239+		A
8ECY-R-73-694	7811200084*	50-437	A
SECY-R-74-072	7811200279*	50~437	A
WARD-D-0165 RQ1	7810170259*	50-337	A
WARD-D-0178	7819200251*	50-537	A
WARD-0-0218	7812200247*		A
HCAP-0587 BOL ROL	7811240165	50-445	A
HCAP-9212	781208014 2 *	405-08	P
WCAP-9331	7811140131	50-266	P E119-102
WCAP-9357	7811140133*	20-579	Þ
WM28-1-45-102	7811150196*	80-327	A

TO PRINCIPAL DOCUMENTS

Items listed as enclosures are those indicated by an asterisk following the accession number in the indexes. The second column gives the accession number of the principal document under which the enclosure is listed. Knowing the accession number of the principal document, the date issued, and the category enables locating the title listing of the enclosure.

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

ACCEBBION	NUMBER			
~~~~	PRINCIPAL	DATE	BUBJECT	•
ENCLIDEURE	DOCUMENT	IBBUED	CATEGOR	
7807150839	7809180532	78/09/05	50-13	J
7810100004	7810100003	78/09/26	50-409	P
7810100006 7810100014	7810100002 7810100010	78/09/29 78/10/03	50~296 50~285	8 8
7810100019	7810100010	78/10/02	50-255	8
	. 4.0000			_
7810100021	7B10100016	78/07/20	50-312	8
78101000R6	7B101000RR	78/10/03	50-333	8
7810100002	7810100029	78/10/00	50-324	8
7810100033	7610100028	78/10/03	50-272	9
7810100034	7810100030	78/09/25	50~334	B
7810100040.	7810100036	78/10/02	80-259	9
7810100041	7810100037	78/10/03	50-272	ě
7810100045	7810100039	78/09/21	80-321	F
7810100047	7810100042	78/09/29	80-294	8
7810100048	7B10100Q43	7 <b>8</b> /10/02	80-591	B
				_
7810100053	7810100049	78/10/03	50-325	8
7010100056	7810100000	78/07/05	50-312	9
7810100038 7810100039	7810100001 7810100004	78/09/26 78/09/29	50-317 50-220	9 8
7810100062	7810100055	78/10/02	50-305	ä
	,01010000	707101	00 000	
7810100063	7810100040	78/09/29	30~346	В
7810100064	7810100044	78/09/29	20-314	6
7810100068	7810100057	78/10/03	50-281	Ð
7810100068	7810100044	78/09/29	50-314	0
7810100049	7810100061	78/08/15	50-312	6
7810100071	7810100067	78/09/27	60-247	8
7810100072	7810100004	78/10/02	50-348	ä
7810100075	7810100070	78/09/29	50-219	ë
7810100077	7810100073	78/07/17	50-312	6
7810100079	7810100074	78/10/03	80-280	B
				_
7010100000	7810100076	78/09/R7	50-320	ë
7010100096 7010100089	7810100085	78/10/02	50-34B	8
7810100089	7810100087 7810100091	78/10/03 78/09/27	60-272 60-336	B
7810100073	7810100071	78/09/27	50-335	B
	. 3.0.00071		22	-
7810100074	7810100071	78/09/27	50-335	8
7810100075	7610100088	79/09/86	90-350	8
7810100097	7810100091	78/09/27	50-335	8
7810100099	7810100090	78/09/28	50-289	ŧ
7810100100	7810100098	78/10/03	30-286	8
7810100102	7810100091	78/09/28	50-335	8
7810110043	7810110041	78/10/03	50-281	ō
7810110044	7810110041	78/10/03	50-281	P
7B1011004B	7810110041	78/10/03	60-261	P
7810110054	7810110052	78/09/08	50-10	Q.
78101100==	7816416675	70 /00 /02	90-444	a
7810110057 7810110059	7810110053	78/09/29 78/09/24	50-461 50-259	Q.
7810110069	7810110054 7810110052	78/09/08	50-10	å
7810110073	7810110070	78/09/25	50-245	P
7810110074	7010110070	78/09/24	50-246	þ

ACCEBB10N	NUMBER			
ENCL DISURE	PRINCIPAL DOCUMENT	DATE 199UED	SUBJECT	
7810110075	7810110070	78/09/26	50-243	P
7810110076	7810110070	78/09/26	50-245	P
7810110083	7810110082	78/10/02	50~320	e
7810110092	7810110090	78/09/29	50-287	P
7810110101	7010110098	78/10/05	50-264	J
7810110103	7810110100	78/09/29	50-285	8
7810110106 7810110114	7810110104	78/10/03	50-155	8
7810110117	7610110112	78/10/06 78/09/21	50-265 50-265	8 B
7810110120	7810110116	78/10/03	20-305	ĕ
7810110122	7810110119	78/10/04	50-255	R
7810110126	7810110124	78/09/30	50-312	R
7810110129	7810110125	78/10/04	50-336	B
7810110132	7810110127	78/10/06	30-280	8
7810110134	7810110130	78/10/04	50-320	8
7810110139	7810110137	78/09/28	50~349	8
7810110146	7810110143	78/10/04	50-331	Ų
7810110147 7810110152	7810110145 7810110151	78/10/03 78/10/02	50-369 50-302	A
7810110155	7810110151	78/10/04	50-247	8
7810110173 7810110174	7810110170 7810110169	78/10/03 78/10/06	50-302 50-317	8
7810110174 7810110191	7810110169 781011017 <b>8</b>	78/09/07	50-317	0
7810110193	7810110180	78/10/06	50~843	ĕ
7810110184	7810110178	78/09/07	50-367	Ģ
7610110185	7810110182	78/09/06	50-305	G.
7810110172	7810110154	78/10/03	50-315	8
7810110193	7810110189	78/10/03	50-265	R
78101101 <b>94</b> 7810110196	7810110190 7810110187	78/08/28 78/10/02	50-438 50-83	9
	7810110107			
7810110198	7810110187	78/10/02	50-63	a
7810110201	7810110187	78/10/02	50-83 50-70	Qi P
7810110203 7810110204	7810110200 78101101 <b>6</b> 7	78/10/04 78/10/02	50-70	o,
7810110205	7810110200	78/10/04	50-70	þ
7810110204	7810110202	76/09/28	30-460	æ
7810110207	7810110200	78/10/04	50-70	P
7810110212	7810110209	78/09/08	50-361	g .
7810110223	7810110219	78/09/27	50-265	g
7810110229	7810110226	78/09/28	50-261	œ
7810110231	7810110226	79/07/29	50-241	q
7910110233 7810110234	7810110226 7810110226	78/09/28 78/09/28	50-241 50-241	Q Q
7910110238	7810110225	78/07/20	50-445	Ğ
7810110238	7810110234	78/09/29	50-466	ō
7810110241	7810110234	78/09/29	50-466	•
7810110242	7810110240	78/09/27	50-324	a
7810110245	7810110240	78/09/27	50-324	o.
7810110249	7810110240	78/09/27	50-324 50-466	9
7810110250	7610110234	78/09/2 <del>9</del>	30-465	•

7910130169

7B10130170

7810130175

7810130166

7810130165

7810130171

78/10/06

78/10/02

78/10/09

50-237

50-155

8

8

78/10/11

78/10/10

50-250

50-271

7B10200045

7810170192

7810170191

7810170193

	PRINCIPAL	DATE	SUBJECT						
ENCLOSURE	DOCUMENT	188UED	CATEGOR		C	PRINCIPAL	DATE	SUBJEC1	
					ENCLOBURE	DOCUMENT	1884ED	CATEGOR	ŧΥ
7810170194	7910200045	78/10/16	50~250	P	78101B0154	7810180131	78/10/12	50-348	8
7810170196	7810170190	78/10/06	50-36B	8	7810180155	7810180153	78/10/12	50-302	8
7810170201 7810170202	7810170199 7810170198	78/10/05	50~312	8	7810180158	7810180106	78/09/27	50-315	8
7810170203	7810170175	78/09/26 78/10/06	50-265 50-249	8	7810180162	7810180159	78/10/11	50-285	8
•		70710700	30-241	•	7810180168	7810180165	78/09/29	50-320	8
7810170211	7810170208	78/09/08	50-304	В	7810180174	7810180171	70.40.400	30-320	_
7810170212	7010170207	78/09/22	50-295	8	7810180179	7810180177	78/10/03 78/09/05	50-244	8
7810170215	7810170213	78/10/06	50-244	R	7810180181	7810180178	78/09/06	30-20	ä
7810170216 7810170222	7810170204 7810170218	78/10/03	50-10	8	7810180192	7810180189	78/09/08	50-335	ō
7010170020	7010170218	78/10/05	50-304	8	7810180209	7B101B0206	78/08/25	8AC-06	G
7810170223	7810170214	78/09/29	50-295	8	7810180215	7810180210			_
7810170227	7810170219	78/09/25	50-295	8	7810180217	7810180210	78/09/28 78/09/28	50-334 50-334	0
7810170228	7810170225	78/09/26	50-295	В	7810190001	7810180221	78/10/03	50-320	ŏ
7810170230 7810170234	7810170226	78/09/25	50-366	8	7810190005	7810180221	78/10/03	50-320	ă
701017040	7810170231	78/10/06	50-295	8	7810190004	7810180221	78/10/03	50-320	a
7810170235	7810170232	78/10/03	50-254	9	7810190007	7810180221	20110100	** ***	_
7810170237	7010170233	78/09/25	50-321	8	7010190015	7810190012	78/10/03 78/10/02	50-320 30-549	0
781017023B	7010170236	78/09/20	50-344	8	7810190018	7810190012	78/10/02	50-549	ĕ
7810170242 7810170245	7810170239	78/10/04	50-304	В	7810190021	7810190012	78/10/02	50-549	Ğ
7510170243	7810170243	78/10/05	50-335	8	7810190024	7810190012	78/10/02	50-549	O
7810170246	7810170241	78/10/02	50-295	8	7810190029	7010100004			_
7810170248	7810170244	78/09/29	50-255	8	7810170027	7810190026 7810190027	78/09/12 78/10/04	50-305	a
7810170292	7810170249	78/10/11	50~302	8	7810190061	7810170027	78/09/05	50-369 50-390	0
7810170253	7810170251	78/09/25	50-304	8	7810190069	7810190068	78/10/18	50-244	P
7810170258	7810170255	78/09/25	50-366	8	7810190088	7810190005	78/10/02	50~246	G
7810170259	7810170154	78/10/06	50-537	A	7810100000	701010000-	20110115	80.515	_
7810170261	7810170256	78/09/25	20-351	8	7810190089 7810190090	7810190087 7810190087	78/10/12	50-368 50-368	P
7810170262	7810170099	78/10/12	50-263	P	7810170072	7810190087	78/10/12 78/10/12	50-36B	P
7610170263	7810170182	78/10/11	50-244	P	7810190093	7810190091	78/09/14	50-397	Ġ
7810170298	7810170291	78/09/25	50~321	8	78101 90107	7810170104	78/09/29	50-57	G
7810170299	7810170268	78/10/05	50-298	R	hm45				
7810170313	7810170309	78/10/04	50-366	9	7810190116	7810190104	78/09/29	50-57	G
7810170314	7810170312	78/10/04	50-366	8	78101 90133 78101 90136	7810190130 7810190130	78/10/11	50-266 50-266	ъ Б
7810170315	7810170311	78/09/29	50~366	B	7810190169	7810190158	78/10/11 78/10/06	50-266	P
7810170321	7810170318	76/10/03	50~366	В	7810190175	7810190158	78/10/04	50-29	P
7010170704	1010.0000	70410400		_					
7810170326 7810180003	7810170322 7810180001	78/10/03 78/10/06	50 -366 50 -366	8	7810190177	7810190027	78/10/04	50-369	0
7810180004	7810180002	78/10/03	20-316	8	7810190182 7810190198	7810190158	78/10/06	50-29	P
7810180005	7810180002	78/10/03	50-316	ä	7810170170	7810190197 7810190197	78/09/29 78/09/29	50-549 50-549	0
7810180007	7810180006	78/10/12	50-219	B	7810190204	7810190197	78/09/29	50-549	G
									•
7810180009	7810180009	78/10/10	50-29	8	7810190206	7810190197	78/09/29	50-549	G
7810180011 7810180013	7810180010 7810180012	78/10/06	50-321	8	7810190214	7810190197	78/09/29	50-549	G
7810180013	7810170329	78/09/26 78/09/29	20-351 20-565	8	7810190220 7810190234	7610190202 7610190234	78/09/08	50-484 50-155	0
7810180017	7810180015	78/10/13	30-27	8	7810170237	7810170233	78/10/10 78/10/04	20-522	G R
							,		.,
781018001B	7810180016	78/09/27	50-316	В	7810190239	7810190229	78/10/02	50-395	0
7810180022	7810180019	78/10/02	50-366	8	7810190240	7810190233	78/10/04	50-255	R
7810180024 7810180025	7810180020 7810180021	78/10/09 78/10/12	50-366 50-306	8 8	7810190245 7810190247	7810190219 7810190234	78/08/31	50-454 50-155	œ
7810180026	7810180023	78/10/05	50-36A	8	7810170247	7810190219	78/10/10 78/08/31	50-454	0
				_	70,01,0202	, 0.04.04.7	,0,00,0.	50 457	•
7810180030	7810180027	78/10/11	50-316	8	7810190262	7810190257	76/09/28	50-275	٥
7810180032	7910180030	78/10/11	50-314	8	7810170267	7810190257	78/09/28	30-275	0
7910180033 7810180035	7810180031	78/09/27	44C-05	В	7810190269	7810190257	78/09/28	50-275	0
7810180036	7810180028 7810180034	78/10/11 78/09/12	50-133 50-306	6	7810200021 7810200024	7810200017 7810200017	78/10/02 78/10/02	50-193 50-193	P
		, , ,		-					•
7810180039	7810180037	78/10/03	50-366	8	7810200029	7810200026	76/09/25	50-206	P
7810180040	7810180038	78/10/04	50-266	В	7810200031	7810200026	78/09/25	20-509	P
7810180042 7810180046	7810180041	78/09/27 78/09/12	50-346	8 8	7810200050 7810200056	7810200047 7810200053	78/10/17	50-334	P
7810180049		78/10/06	50-266 50-295	R	7810200058	7810200054	78/10/10 78/10/16	50-316 50-339	R
,	78101000	, 5, 10, 00	30 - E 7 5		70.020000	, 01040000-	70710710	30 557	
7810180082		78/10/12	50-34B	A	7810200059	7810240038	78/10/05	50-516	9
7810180090	7810180084	78/10/13	50~373	J	7810200063	7810200061	78/10/11	50-331	R
7810180100	7810180097	78/10/10	50-348	8	7810200070	7810200067	78/10/10	50-313	R
7810180102 7810180104		78/10/05 78/10/12	50-301 50-10	R	7810200072 7810200075	7810200071 7810200045	79/10/12 79/09/13	50-245 50-250	8 p
701010101	7810180101	/0/10/12	30-10		7010200015	7010400040	,0,0,,,,	40 200	•
7810180107	7810180105	78/10/12	50-302	8	7810200080	7810200078	78/10/13	50-263	P
7810180109	7810180106	78/09/27	50-315	6	7810200001	7810200077	78/10/16	50-348	9
7810180111	7810180110	78/10/13	50-302	8	7810200093	7810200002	79/10/16	50-269	R
7810180114	7810180112	78/09/27	50-321	8	7810200085 7810200088	7810200077 7810200087	78/10/16 78/10/13	50-24B 50-245	8 R
7810180118	7810180116	78/09/29	50-366	8	76108000dB	/8104000B/	10110113	30-243	ĸ
7810180121	7810180119	78/10/13	50-280	P	7810200 <b>09</b> 7	7810200077	78/10/16	50-348	B
7810180122	7810180120	78/10/03	50-366	6	7810200076	7810200093	78/10/11	50-251	8
7810180125	7810180123	78/10/09	50-133	R	7910200097	7810200092	78/10/13	50-237	В
7810180131	7810180130	78/10/01	50-293	A	7810200106 7810200108	7810200104	78/10/16	50-312	8
7810180134	7810180134	78/10/13	20-513	R	7810200108	7810200107	70/10/16	50-344	8
7810190140	7810180139	78/10/11	50-338	J	7810200112	7810200109	78/10/17	50-281	9
7810180142		78/10/13	20-540	8	7810200117	7810200114	78/10/11	50-251	8
7810180149	7810180145	78/10/11	50-34B	8	7810200118	7810200110	78/10/17	50-280	8
7810180150	7810180148	78/10/16	50-244	P	7810200125	7610200119	78/10/14	50-272	8
7810180152	7810180147	78/10/12	50-302	8	7B10200158	7610200132	78/08/09	20-305	8

ACCEBSION	NUMBER				ACCE8910N	NUMBER			
	PRINCIPAL	DATE 189VED	SUBJECT CATEODA	v	ENCLOSURE	PRINCIPAL DOCUMENT	DATE DBU881	CATEGORY	,
7810200170	7810200162	78/10/04	50-269	B	781024003	7810240032 7810240067	78/01/19 78/10/10		9
7810200182 7810200199	7810200177 7810200194	78/10/06 78/10/10	50-483 50-261	Ģ P	7810240071 7810240075	7B10240067	78/10/10 78/10/16	50-250 50-269	Ğ R
7810200201 7810230016	7810200196 7810230011	78/10/10 78/10/10	50-261 50-277	P P	7810240077 7810240094	7810240002 7810240092	78/09/18	50-133	ā
7810230018	7810200240	78/10/0B	30-466	0	7810240102 7810240107	7810240100 7810240105	78/10/12 78/10/16	50-249 50-219	8 8
7810230019 7810230020	7810230011	78/10/10 78/10/11	50-277 50-261	o O	7810240113 7810240121	7810240111 7810240116	78/10/20 78/10/12	50-133 50-249	P 8
7810230023 7810230024	7810230013 7810230011	78/10/11 78/10/10	50-261 50-277	Q P	7810240124	7810240118	78/10/17	50-302	8
7810230025	7810230013	78/10/11	50-261	Q.	7810240126 7810240129	7810240122 7810240125	78/10/19 78/10/13	50~333 50~320	8 8
7810230027 7810230026	7810230013 7810230011	78/10/11 78/10/10	50-261 50-277	g P	7810240134 7810240137	7810240131 7810240115	78/10/16 78/10/17	50-320 50-488	8 H
7810230030 7810230033	7810230026 7810230029	77/11/11 78/10/10	50~70 50~369	q	7810240138	7810240128	78/10/18	50-305	8
7810230036	7B10230029	78/10/10 78/10/06	50-369 50-275	g A	7810240139 7810240141	7810240133 7810240136	78/10/19 78/10/17	50-333 50-249	8
7810230042 7810230043	7810230038 7810230039	7B/10/10	50-271 50-271	P P	7810240150 7810240151	7810240148 7810240146	78/10/12 78/10/20	50-10 50-296	8
7810230044 7810230048	7810230039 7810230039	78/10/10 78/10/10	50~271	þ	7B10240154	7810240152	78/10/18	50-29	8
7810230052	7810230049	78/10/10 78/10/11	50-335 50-349	9	7810240162 7810240165	7810240160 7810240156	78/10/17 78/10/18	50-302 50-29	8
7810230058 7810230059	7810200258 7810230049	78/10/10	50-335	ā	7810240207 7810240208	7810240204 7810240067	78/09/13 78/10/10	50-390 50-250	Q G
7610230061 7810230064	7810200258 7810200258	78/10/11 78/10/11	50-369 50-369	G.	7810240210	7810240204	78/09/13	50-390	a
7810230067	7810200258	78/10/11	50-349 50-335	G G	7810240211 7810240217	7810240067 7810240067	78/10/10 78/10/10	50-250 50-250	9
781023006 <b>8</b> 7810230072	7810230049 7810230049	78/10/10 78/10/10	50-335	g	7810240221 7810240228	7810240214 7810240225	78/10/10 78/10/17	50~445 50~368	G P
7810230092 7810230094	7810230090 7810230091	78/09/20 78/09/22	50 - 70 50 - 508	G G	7810240230	7810240225	78/10/17	846-06	P
7810230133	7810230130	78/10/11	50-322	0	7810240236 7810250015	7810240233 7810250007	78/09/15 78/09/07	50-498 50-445	o o
7810230146 7810230150	7810230143 7810230149	78/10/11 78/10/16	50-324 50-247	B A	7810250031 7810250052	7810250027 7810250048	78/10/05 78/09/11	50-482 50-311	G G
7810230167 7810230169	7810230164 7810230166	78/10/13 78/10/13	50-277 50-335	R 8	7810250063	7810250060	78/10/24	50-285	P
7810230174	7810230171	78/10/16	50-338 50-321	R S	7810250085 7810250091	7810250082 7810250074	78/10/19 78/09/14	50-260 50-424	P G
781023017 <i>6</i> 7810230182	7810230175 7810230178	78/10/13 78/10/15	50-317	R	7810250093 7810250100	7810250089 7810250099	78/10/19 78/10/18	50-329 50-329	8 A
7610230183 7810230185	7810230177 7810230177	78/10/19 78/10/19	50-314 30-314	8	7810250104	7810250103	78/10/18	50-272	R
7810230187	7810230184	78/10/13 78/10/18	50-280 50-333	R 9	7810250110 7810250114	7810250106 7810250112	78/10/17 78/10/19	50~213 50~34B	8 8
7810230189 7810230190	7810230186 7810230188	78/10/13	50~366	8	7610250117 7810250122	7810110154 7810250120	78/10/03 78/10/19	50-315 50-327	6 A
7810230195 7810230196	7810230193 7810230192	78/10/11 78/10/17	50-324 50-329	8 K	7810250135	7810250134	78/10/12	20-š8P.	<b>.</b> .
7810230202	7810230198 7810230207	78/10/16 78/10/13	50-315 50-245	8	7610250136 7810250137	7810250134 7810250134	78/10/12 78/10/12	50-286 50-286	Q.
7610230210	7810230209	78/10/04 78/10/10	50-29B 50-413	ā	7810250138 7810250140	7810250134 7810250137	78/10/12 78/09/14	50-286 50-280	9
7810230223 7810230224	7810230214 7810230218	78/10/11	50-338	ă	7810250145	7810250141	78/10/18	50-348	8
7810230227 7810230230	7810230226 7810230226	78/10/06 78/10/06	50-259 50-259	0	7810250154 7810250190	7810250116 7810250186	78/09/14 78/10/11	50-302 50-387	9
7810230237	7810230218 7810230218	78/10/11 78/10/11	50-338 50-338	G.	7810250194 7810250197	7810250186 7810250186	78/10/11 78/10/11	50~387 50~387	œ œ
7810230241 7810230249	7810230243	78/10/18	50-272	8	7810250903	7810250200	78/19/10	50-369	Q.
7810230251	7610230247 7610230230	78/10/09 78/10/13	50-305 50-251	8	7810250207 7810250209	7810250186 7810250200	78/10/11 78/10/10	50~387 50~369	g g
7010230253 7010230255	7810230252	78/10/18	50-272 50-373	8	7810250212 7810250220	7810250206 7810250216	78/10/13 78/09/19	50-275 50-331	A
7010230250 7010230260		78/10/16 78/10/16	50-339	ŝ	7810250221	7810250217	78/10/05	50-413	a
7010230261 7010230262		78/10/12 78/10/12	50-219 50-281	A 9	7810250222 7810250227	7810250216 7810250226	78/09/19 78/09/18	50-331 50-219	9
7810230265	7810230263	78/10/18	50-333	9	7810250231 7810250234	7810250229 7810250229	78/10/11 78/10/11	50-34B	9
7810230273 7810230275					7810250239	7810250238	78/10/11	50-348	O
7810230279 7810230281		78/10/05 78/10/03	50-313 50-313		7810250246 7810250261	7810250238 7810250258	78/10/11 78/09/12	50-348 50-354	9
7810230285	7810230277	78/10/17	50-312	8	7810250262 7810260007	7810250255 7810260004	78/10/06 78/10/13	50-354 50-250	G.
7810230291 7810230294					7810250010	7810260004	78/10/13	50-250	Q.
7810230301 7810230304					7610240022 7610240023	7810240019	78/10/06 78/10/06	20-550 20-550	0
7810230301	7810230293	78/10/04	50-368	P	7810260025 7810260028		78/10/06 78/10/06	20-530 20-550	a
7810230331					7810260032	7810260030	78/10/16	50-445	A
7810230345 781024000		78/10/13	90-437		7810260064 7810260067	7810260067	78/10/13 78/09/15	50-250 50-261	9
781024001 781024001	7810240009	78/10/17	50-440	A	7810260069 7810260073		78/10/13 78/10/13	50-250 50-250	9
781024001					7810260118		78/10/18	50-361	K

ENCLOBURE	PRINCIPAL DDCUMENT	DATE ISSUED	SUBJECT CATEODR			PRINCIPAL	DATE	SUBJECT	
					ENCLOSURE	DOCUMENT	IBSUED	CATEODR	
7810260128	7810260121	78/10/25	50-336	8 8	7810300269	7810300262	78/09/22	50-389	8
7810260129 7810260130	7810260121 7810260121	78/10/25 78/10/25	50-338 50-338	8	7810300277 7810300280	7810300262 7810300275	78/09/22 78/19/02	50-389 50-333	8
7810260131	7810260121	78/10/25	30-338	8	7810300291	7810300262	78/09/22	50-389	ě
7810260132	7010260121	79/10/25	20-338	9	7810300292	7810300117	78/09/13	50-334	Q.
7810260133	7810260121	78/10/25	50-338	8	7810300307	7810300302	78/10/06	50-556	٥
7810260135 7810260164	7810260121 7810260121	78/10/23 78/10/25	50-338 50-338	8	7810300313	7810300309	78/10/05	50-267	9
7810260175	7810260169	78/09/30	50-341	ő	7810300330 7810300336	7810230069 7810300332	78/09/27 78/10/10	50-468 50-488	9
7810260180	7810260179	79/09/18	50-155	G	7810300338	7810300334	78/10/23	20-501	ē
7810260193	7810240179	78/09/18	50-155	Q	7810300343	7810300334	78/10/23	105-06	٥
7810260184	7810260169	78/08/30	50~341	g	7810300351	7810300334	78/10/23	50-201	ŏ
7910260225 7810260228	7910260219 7810260227	78/10/16 78/10/13	50-275 50-244	A	7810300354	7810300334	78/10/23	50-201	a
7810260232	7810260227	78/10/13	50-344	ŏ	781030035B 7810300362	7810300334 7810300334	78/10/23 78/10/23	30~201 30~201	9
	701071077	30440440	80.044						
7810260243 7810270076	7810260227 7810270072	78/10/13 78/10/17	50-344 50-287	P	7810300380 7810300383	7810300377 7810300375	70/10/17 70/09/22	50-369 50-315	a
7910270097	7810170094	78/10/23	50-219	Я	7810300395	7810300377	78/10/77	50-349	ŏ
7810270107 7810270113	7810270104 7810270103	78/09/15 77/12/27	50-163 50-13	A G	7810300397 7810310033	7810300384	78/08/08	50-395	0
/4102/01/0	7010270103	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	50 13	•	781031003	7810310029	78/09/21	50-182	Q
7810270162	7810270157	78/10/05	50-443	A	7810310054	7810310048	78/09/21	50-2B0	Q
7810270188 7810270189	7810270186 7810270185	78/10/24 78/10/16	50-277 50-334	P	7810310064 7810310069	7810310060 7810310060	78/03/01 78/03/01	50-259 50~259	Q Q
7810270192	7810270185	78/10/16	50-334	Q.	7810310074	7810310060	78/03/01	50-259	õ
7810270193	7810270191	78/10/20	50-315	8	7810310082	7810310081	78/09/22	50-339	O-
7810270194	7810270185	78/10/16	50-334	0	7810310105	7810310102	78/10/20	50-317	8
7810270176	7810270185	78/10/16	50-334	œ	7910310116	7810310115	78/09/23	50-338	O
7810270216 7810270221	7810270214 7810270213	78/10/25 78/09/12	50-206 50-327	œ.	7810310127 7810310133	7810310123 7810310130	78/10/20 78/10/26	50-241 50-155	9 8
7810270223	7810270174	78/10/25	50~280	Р	7810310134	7810310128	78/09/20	50-324	ā
7810270224	7810270215	78/10/16	50-261	В	7010310135	7810310131	78/10/26	50-348	9
7810270231	7810270229	78/10/17	30~249	8	7810310141	7810310134	78/10/23	50~302	9
7810270232	7910270228	78/10/24	50-267	8	2010310142	7810310139	78/10/24	50~324	9
7810270234 7810270240	7810270234 7810270235	78/10/17 78/10/20	50~237 50~317	9 B	7810310144 7810310150	7810310138 7810310146	78/09/19 78/10/12	50-261 50-321	Gr S
7810270246 7810270270	7810270024 7810270261	78/02/08 78/10/16	50~329 50~278	8	7810310153 7810310154	7810310143 7810310151	78/10/23 78/10/24	50-261 50-366	8 8
7810270272	7810270252	78/10/20	50~324	Q	7810310155	7810270309	7B/10/20	50-316	В
7810270293	7810270276	78/10/24	50-267 50-255	8	7810310162	7810310157	78/10/20	50-321	8
7810270296	781027027B	78/10/16	30-839	r	7810310163	7810310158	78/10/24	50~293	-
7810270288	7810270284	78/09/12	50-311	g	7810310166	7810310160	78/10/25	50-321	8
7810270293 7810270296	7810270278 7810270287	78/10/16 78/10/19	50-255 50-237	P 8	7810310168 7810310169	7810310029 7810310164	78/09/21 78/10/23	50~182 50~302	9
7810270305	7810270302	78/10/17	50-249	8	7810310170	7810310167	78/10/25	50-344	8
7010270314	7810270309	78/10/20	50-316	8	7810310171	7810310145	78/10/23	50~321	8
7810270345	7810270341	78/09/27	50-344	۰	7810310179	7810310020	78/10/23	50~498	M
7810270348	7810270341	7B/09/27	90-344	٥	7810310181	7810310175	78/10/25 78/10/24	50~321	8
7810270354 7810270358	7810270341 7810270341	78/09/27 78/09/27	50-344 50-344	ŏ	7810310182 7810310186	7810310117 7810310183	78/10/25	50-259	ទ
7810270373	7810270368	78/10/20	50-341	٥	7810310189	7810310185	78/10/27	50~443	A
7810270376	7810270371	78/09/20	50-301	a	7810310192	7810310184	78/10/20	50-289	8
7810270387	7810270368	78/10/20	50-341	0	7810310199	7810310190	78/1-/26	50-316	9
7810270398 7810270392	7810270385 7810270391	78/09/21 78/09/12	50-315 50-363	G.	7810310200 7810310201	7810310197 7810310194	78/10/20 78/10/25	50-317 50-346	9
7810270378	7810270385	78/09/21	50-315	ā	7810310214	7810310205	78/10/20	90-346	8
7810270406	7810270368	78/10/20	30-341	9	7810310216	7810310209	78/10/20	50-31B	8
7810270410	7810270308	78/10/03	20-513	P	7810310219	7810310210	78/10/25	50-261	9
7810270413	7810270404	78/10/03	50-213	P	7810310222	7810310217 7810310220	78/10/25 78/10/27	50-324 50-331	9 8
7810270417 7810270422	7810270404 7810270404	78/10/03 78/10/03	50-213 50-213	P	7810310227 7810310230	7810310220	78/10/27	50-267	8
							30410400		
7810300017 7810300020	7810200258 7810300018	78/10/11 78/09/07	50-369 50-206	9	7810310236 7810310237	7810310232 7810310233	78/10/23 78/10/06	50-324 50-261	9
7810300007	7810300012	78/10/16	50~338	0	7810310241	7810310233	78/10/06	30-261	P
7810300065	7810300039	78/10/16	50-338 50-344	0	7810310242 7810310243	7810310238 7810310240	78/10/27 78/10/13	50-338 50-244	9 P
7810300077	7810300070	78/10/16	JU-011	•					
7810300113	7810300106	78/10/21	50-341	a	7810310246	7810310233	78/10/06 78/10/26	50-261	P
7810300138 7810300153	7810300124 7810300148	78/10/23 78/10/23	50-447 50-289	A	7810310248 7810310252	7810310244 7810310238	78/10/26 78/10/27	50-271 50-338	8 8
7810300157	7810300148	78/10/23	30-219	P	7810310260	7810310254	78/10/26	50-272	8
7810300165	7810300162	78/10/02	50-514	0	7810310291	7810310273	78/10/18	50-568	A
7810300166	7810300164	78/09/27	50-267	8	7810310286	7810310273	78/10/19	50~569	Ą
7810300167	7810300162	78/10/02	50-514	8	7810310288 7810310294	7810310284 7810310284	78/10/19 78/10/19	50-528 50-528	o o
7610300171 7810300174	7810300168 7810300169	78/10/25 77/11/02	50-260 50-277	P	7810310274	7810310284	78/10/18	50-526	a
7810300177	7810300173	78/10/12	50-298	8	7810310304	7810310299	78/10/17	50-247	P
7810300180	7810300179	78/10/05	50-267	8	7810310305	7810310299	78/10/17	50-247	Р
7810300190	7810300179	78/09/27	50-267	9	7810310307	7610310302	7B/10/10	50-349	œ
7810300196	7810300191	78/10/25	50-263 50-298	8	781031030B 7810310309	7810310284 7810310303	78/10/18 78/09/27	50~528 50-346	8
7810300229 7810300266	7810300201 7810300262	78/09/12 78/09/22	50-389	ō	7810310312	7810310302	78/10/10	50-369	ā

					MVC2001	ON NOMBER			
ENCLOBURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJE CATEO		ENCLOBURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJE	
7910310318	7810310284			G	701400000				
7810310319	7810310302	79/10/10			7811020249 7811020251				
7810310330 7810310340	7910310303		50-346	8	7811020239				
7810310342	7810310338 7810310303	78/09/26 78/09/27			7811020274	7811020272	78/10/12	50-59	P
•	. 010310303	18/07/2/	50-346	₿	7811020275	7811020270	79/10/17	50-344	
7010310346	7810310303			6	7911020277	7811020272	78/10/12	50-59	
7810310365 7811010010	7810310357 7811010008				7811020298	7811020272	76/10/12	50-59	P
7811010012	7811010009			ā	7811020312		78/10/31	50~336	R
7811010013	7811010000	78/10/26		Ä	7811020339 7811020333		78/10/19	50-344	
7811010014					701102000	\ e11050358	78/10/20	50-549	•
7811010014	781101000 <del>4</del> 7811010009	78/10/23 78/10/06		H	7811020343		78/10/19	50-344	Q
7811010022	7811010016	78/09/20		0	7811020355 7811020360		78/10/20	50-364	Q
7811010022	7811010019	78/09/20	50-10	ā	7811020369	781 1020351 781 1020365	78/10/20 78/09/22	50~364 50~459	0
7811010029	7811010009	78/10/06	50-10	9	7811020375	7811020349	78/10/25	50-254	Q F
7811010033	7811010004	79/09/29	50-382	B	201102020	*********			
7811010037	7811010032	78/09/21	50-361	ā	7811020387 7811020389	7811020384 7811020385	78/10/25 78/10/18	50-498	Q
7811010041 7811010053	7611010036	78/10/24	60-244	Q	7811020393	7811020384	78/10/25	50-549 50-498	H G
7811010055	7811010050 7811010052	78/09/14 78/10/19	50-359	ŏ	7811020395	7811050395	78/10/11	50-409	P
		70710717	50-414	A	7811020399	7811020392	78/10/11	50-409	P
7811010057	7811010050	78/09/14	50-358	G	7811020400	7811020392	78/10/11	50-409	Р
781101005B 7811010059	7811010052 7811010047	78/10/19	50-414	A	7B1102044Q	7811020119	78/10/25	50-160	ď
7811010061	7811010052	78/09/19 78/10/19	80-373 80-414	Q A	7811020449	7811020442	78/09/29	50-445	ŏ
7811010064	7811010052	78/10/19	50-414	Ä	7811030016 7811030019	7811030013	78/10/13	50-366	P
7811010068	704101000				, 5.1.00001.	1011030013	78/10/13	90-366	P
7611010076	7811010032 7811010067	78/10/19 78/09/19	80-414	A	7811930022	7811030013	78/10/13	50-366	P
7811010089	7811010085	78/10/10	50-254 50-277	9	7811030036 7811030037	7811030034	78/09/11	50-285	a
7811010093	7811010085	78/10/10	50-277	ā	7811030037	7811030035 7811030035	78/09/22 78/09/22	50~466	g
7611010095	7811010085	78/10/10	50-277	O.	7811030047	7811030044	78/10/24	50~466 50-424	Q.
7811010099	7811010083	78/10/10	50-277	G	70.4.000.0				•
7611010116	7811010113	78/10/26	50-317	ě	7811030054 7811030078	7811030044 7811030057	78/10/24	50-424	a
7611010125	7811010120	78/10/31	50-395	K	7811030090	7B11030057	78/10/23 78/10/21	50-438 50-318	O P
7811010131 7811010135	7811010141 7811010187	78/11/01 78/09/15	50-275	R	7811030084	7811030057	78/10/23	50-436	ď
		78707715	50-443	Q	7811030085	781 1030076	78/10/21	50-318	P
7811010162	7811010160	78/10/19	50-369	е	7811030088	7811030076	78/10/21	50-318	P
7811010191 '	7611010186	78/09/21	50-336	G.	7811030089	7811030057	78/10/23	50-438	G
7811010309	7811010306	78/09/13 78/09/15	50-259 50-346	g g	7811030072	7811030057	78/10/23	50~438	ē
7811010368	7811010342	78/10/13	50-320	õ	7811030104 7811030117	7811030101 7811030112	78/10/23	50-390	A
7811010384	7011010000			_	,,	1011020118	78/10/27	50-317	8
7811010398	7811010382 7811010382	78/10/24 78/10/24	50-275 50-275	9	7811030120	7811030119	78/11/01	50-311	ж
7011010399	7811010387	78/09/29	50-524	Ä	7811030124 7811030135	7811030119	7B/11/01	50-311	K
7611010393	7811010390	78/10/03	50-277	P	7811030139	7811030131 7811030136	78/10/25 78/10/31	50-309	8
7B11010400	78) 1010370	. 78/10/03	50-277	P	7811030140	7811030137	78/09/29	50-155 50-309	9 8
7811010402	7811010397	78/09/21	50~324	G _i	2011000440				-
7811010408	7811010390	78/10/03	50-277	P	7811030145 7811030152	7811030143 7811030149	78/10/24	50-237	8
7811010411	7811010407	78/09/21	50~250	Q.	7811030156	7811030183	78/09/26 78/09/27	20-315 20-315	8
7811010418 7811010423	7811010414 7811010414	77/19/16 77/19/16	50-260 50-260	Q Qr	7811030159	7811030157	78/10/27	50-346	8
	,	,,,,,,,,,,	20-400	u	7811030168	7811030003	78/10/24	50-250	Q
7811010428	7811010414	77/12/16	50~260	Q	7811030171	7811030003	78/10/24	50-250	
7611010435 7611020010	7811010432 7811020003	78/10/17	80-387	9	7611030175	7811030003	78/10/24	50-250	G Gr
7811020047	7811020041	78/10/24 78/10/16	50-382 50-376	9	7811030178	7811030003	78/10/24	50-250	ä
7811020052	781102004B	78/09/19	50-445	Q.	7811030191 7811030198	7811030184 7811030194	78/10/27	50-249	8
7811020055	781102004B	78/09/19	50-445				78/10/19	50-346	G
7811020059	7811020033	78/10/16	50-206	Q P	761103020g	7811030205	7B/10/17	50-331	P
7811020071	7811020066	78/10/13	50-271	P	7611030210 7611030215	7811030205	78/10/17	50-331	P
7811020081 781102008A	7811020066	78/10/13	50-271	P	7811030228	7811030205 7811030224	78/10/17 78/10/12	50-331 50-113	P
\a11050089	7811020066	78/10/13	50-271	А	7811030231	7811030226	78/10/23	50-335	g
7811020007	7811020084	78/10/03	50-312	Р	7811030232				
7611020093	7811020084	78/10/03	50-312	P	7811030232	7811030224 7811030226	78/10/12	90-113	ρ
7811020096 7811020098	7811020091	78/10/27	50-313	P	7811030249	7811030244	78/10/93 78/10/94	50-335 50-445	g O
7811020111	7811020084 7811020106	78/10/03 78/09/25	50-312 50-315	P Qi	7811030260	7811030257	78/10/18	50-438	8
			00 410	•	7811030245	7811030263	78/10/16	50-327	8
7811020146 7811020150	7811020140	78/10/12	50-2	P	7811060008	7811060007	78/09/29	50-288	a
7811020168	7811020140 7811020166	78/10/12 78/09/27	50-2 50-341	Pi A	7811060015	7811040013	78/10/13	50~25B	P
7811020175	7811020170	78/10/13	50~34) 50-271	G G	7811060019	7811060013	78/10/13	50-2	P
7811020176	7811020169	78/10/11	50-466	ŏ	7811060038 7811060044	7811060036 7811030040	78/10/23	90-338	a
7811020177	7811020060	70/10/10	80			- 02 - 020070	78/10/24	50~562	9
7811020177	7811020060	78/10/10 78/10/10	20-553 20-553	9	7811060053	7811060051	78/09/12	50-298	Q.
7611020179	7811020170	78/10/13	50-223 50-271	Q .	7811060055 7811060066	7811060051	78/09/12	50-298	ā
7811020191	7811020169	78/10/11	50-466	9	7811060069	7811060065 7811060063	78/10/20 78/10/30	50-341 50-390	A
7811020162	7811020060	78/10/10	20-553	0	7811060070	7811060068	78/10/20	50-390 50-522	8 E
7811020183	7811020170	78/10/13	50-271	G	7811060074				-
7011020186	7811020060	78/10/10	50-223	Q	7811060074 7811060093	7811060073 7811060093	78/10/28 78/10/23	50-116	8
76:1020:86 78:10202:8	7811020170 7811020212	78/10/13	50-271	9	7911060096	7811060090	78/10/17	50-554 50-390	<i>©</i> 8
7811020216	7811020212	78/10/20 78/10/27	50-155 50-439	P K	7811040100	7811060083	78/10/23	30-376	0
			J7JD	-	7811060101	7811060098	78/09/26	90~382	ă

# PRINCIPAL DOCUMENTS

ACCE6810	N NUMBER				ACCESSION NUMBER	
ENCLOBURE	PRINCIPAL DOCUMENT	DATE 198UED	SUBJEC			ECT GORY
7811040105 7811040104 7811040107 7811040125 7811040128	7811040078 7811040083 7811040103 7811040124 7811040124	78/09/26 78/10/23 78/10/27 78/10/16 78/10/16	50-382 50-556 50-213 50-277 50-277	0 8 P P	7811070265 7811070262 78/11/01 50-27 7811070267 7811070264 78/11/01 50-34 7811070266 7811070266 78/11/02 50-27 7811070270 7811070279 78/10/30 50-37 7811070270 7811070273 78/11/01 50-34	6 8 2 8 7 C
7811060130 7811060138 7811060140 7811060148 7811060149	7811040124 7811040131 7811040138 7811040144 7811040148	78/10/16 78/10/30 78/10/30 78/10/27 78/10/13	50-277 50-321 50-321 50-250 50-368	P 8 8 8	7811070281 7811070277 78/10/19 50-32 7811070294 7811070288 78/10/31 50-24 7811070307 7811070302 78/10/24 50-21 7811070308 7811070305 78/10/03 50-44 7811070311 7811070302 78/10/24 50-21	5 P 3 P 5 G
7811060151 7811060152 7811060153 7811060156 7811060158	7811060145 7811060142 7811060150 7811060145 7811060154	79/10/13 79/10/27 78/10/27 78/10/13 78/10/27	50-313 50-256 50-366 50-368	9 9 9	7811070313 7811070302 78/10/24 50-21 7811070314 7811070309 78/10/23 50-25 7811070320 7811070309 78/10/23 50-25 7811070323 7811070318 78/11/01 50-33 7811070355 7811070351 78/10/24 50-70	0 0
7811060160 7811060161 7811060162 7811060163 7811060180	7811060145 7811060155 7811060159 7811060157 7811060175	78/10/13 78/10/31 78/10/30 78/10/27 78/10/13	90-368 90-318 90-249 90-291 50-313	9 9 8	7911070377 7811070373 78/10/17 50-41 7811070378 7811070373 78/10/17 50-41 7811080008 7811080003 78/10/20 50-27 7811080018 7811080013 78/10/24 50-15 7811080024 7811080013 78/10/24 50-15	2 B 5 A 7 P
7811060183 7811060189 7811060204 7811060213 7811060213	7811060175 7811060175 7811060200 7811060211 7811060210	79/10/13 78/10/13 78/10/31 78/11/01 78/11/01	50-285 50-285 50-285 50-281 50-286	8 8 8 8	7811080030 7811080026 78/10/30 50-58 7811080033 7811080026 78/10/30 50-58 7811080031 7811080036 78/10/30 50-38 7811080047 7811080034 78/10/20 50-70 7811080056 7811080037 78/10/20 50-70	4 A 4 P 6 A
7811040217 7811040237 7811040238 7811040239 7811040240	7811060211 7811060233 7811060224 7811060224 7811060233	78/11/01 78/11/01 78/10/20 78/10/20 78/11/01	50-281 50-338 50-3 50-3 50-338	8 9 0	7811080070 7811080066 78/10/04 90-29 7811080074 7811080066 78/10/04 90-29 7811080076 7811080067 78/10/23 90-25 7811080080 7811080077 78/10/02 90-25 7811080086 7811080082 78/10/27 50-28	5 G 6 H 4 G
7811040242 7811040244 7811040245 7811040247 7811070004	7811060233 7811060224 7811060233 7811060224 7811070001	78/11/01 78/10/20 78/11/01 78/10/20 78/10/20	50-338 50-3 50-338 50-3 50-471	B G G O	7811080087 7811080087 78/10/18 50-34 7811080090 7811080082 78/10/27 50-28 7811080092 7811080082 78/10/27 50-28 7811080096 7811080091 78/09/20 50-31 7811080097 7811080082 78/10/27 50-28	6 Q 6 Q 7 Q
7811070053 7811070057 7811070050 7811070063 7811070064	7811070013 7811070013 7811070013 7811070013 7811070059	78/10/23 78/10/23 78/10/23 78/10/23 78/10/30	50-269 50-269 50-269 50-368	P P P A	7811080098 7811080059 78/10/18 50-34 7811080104 7811080101 78/10/02 50-31 7811080111 7811080110 78/11/02 50-39 7811080112 7811080104 78/10/03 50-29 7811080127 7811080123 78/11/03 50-28	5 Q 6 P 8 G
7811070068 7811070071 7811070139 7811070140 7811070143	7811070013 7811070013 7811070136 7811070138 7811070138	78/10/93 78/10/93 78/11/01 78/10/31 78/10/31	50-259 50-269 50-302 50-443 50-443	р 8 1 1	7811080129 7811080123 78/11/03 50-28 7811080134 7811080133 78/11/03 50-39 7811080141 7811080137 78/11/02 50-37 7811080145 7811080143 78/11/02 50-37 7811080150 7811080148 78/11/01 50-25	0 K 0 B 6 B
7811070145 7811070147 7811070148 7811070150 7811070151	7811070138 7811070133 7811070138 7811070138 7811070146	78/10/01 78/06/20 78/10/01 78/10/01 78/11/00	50-443 50-397 50-443 50-443 50-338	1 Q 1 1 P	7811080151 7811080147 78/10/27 30-39 7811080154 7811080147 78/10/27 30-39 7811080156 7811080132 78/11/02 30-39 7811080157 7811080147 78/10/27 30-39 7811080158 7811080147 78/10/27 30-39	5 Q 3 8 5 Q
7811070153 7811070156 7811070161 7811070163 7811070164	7811070138 7811070138 7811070138 7811070157 7811070133	78/10/31 78/10/31 78/10/31 78/11/03 78/06/20	50-443 50-443 50-443 50-247 50-397	1 1 P Q	7811080161 7811080155 78/11/02 50-33 7811080164 7811080163 78/09/27 50-39 7811080167 7811080164 78/10/20 50-33 7811080177 7811080172 78/09/20 50-33 7811080184 7811080183 78/11/02 50-28	5 0 6 A 3 0
7811070166 7811070169 7811070171 7811070179 7811070181	7811070138 7811070138 7811070138 7811070133 7811070178	78/10/31 78/10/31 78/10/31 78/06/20 78/11/02	50-443 50-443 50-443 50-397 50-272	B 1 1	7811080189 7811080175 78/10/16 50-36 7811080191 7811080187 78/09/27 50-32 7811080192 7811080173 78/10/16 50-36 7811080196 7811080173 78/10/16 50-36 7811080196 7811080174 78/09/27 50-32	7 0 3 0 3 0
7811070188 7811070198 7811070206 7811070208 7811070218	7811070184 7811070193 7811070183 7811070204 7811070210	78/11/01 78/10/31 78/11/03 78/11/01 78/11/02	50-346 50-344 50-255 50-302 50-255	8 8 8	7811080200 7811080175 78/10/16 50-36 7811080211 7811080205 78/10/27 50-36 7811080213 7811080205 78/10/27 50-36 7811080215 7811080205 78/10/27 50-36 7811080217 7811080208 78/11/01 50-33	9 Q 9 Q 9 Q
7811070224 7811070230 7811070233 7811070235 7811070237	7811070217 7811070221 7811070226 7811070226 7811070228	78/11/02 78/11/01 78/11/02 78/11/01 78/11/02	50~155 50~247 50~338 50~302 50~338	8 8 8	7811080220 7811080205 78/10/27 50-36 7811080234 7811080229 78/10/20 50-21 7811080238 7811080229 78/10/20 50-21 7811080242 7811080229 78/10/20 50-21 7811080245 7811080236 78/09/25 50-27	9 0 9 0 9 0
7811070238 7811070240 7811070241 7811070248 7811070249	7811070234 7811070236 7911070228 7811070244 7811070245	78/11/02 78/09/08 78/11/02 78/11/01 78/09/22	50~267 50~327 50~338 50~333 50~518	R 8 8	7811080246 7811080227 78/10/20 50-21 7811080248 7811080244 78/09/19 50-28 7811080234 7811080251 78/10/27 50-42 7811080236 7811080253 78/10/19 50-21 7811080240 7811080253 78/10/19 50-21	6 Q 8 Q 9 Q
7811070282 7811070286 7811070289 7811070260 7811070261	7811070246 7811070253 7811070247 7811070254 7811070258	78/11/03 78/10/31 78/11/01 78/10/24 78/11/03	50~510 50~286 50~282 50~445 50~336	A P B G 8	7811080264 7811080253 78/10/19 50-21 7811080264 7811080253 78/10/19 50-21 7811080289 7811080283 78/09/27 50-21 7811080292 7811080290 78/09/19 50-31 7811080294 7811080231 78/10/27 50-43	9 a 1 9 1 0

ACCESSION					ACCESSIO				
ENCLOSURE	PRINCIPAL COCUMENT	DATÉ 159UED	SUBJECT CATEGORY	,	ENCL DSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGORY	
7811080294 7811080298 7811080300 7811080302 7811080310	7811080250 7811080251 7811080250 7811080251 7811080251	78/10/27 78/10/27 78/10/27 78/10/27 78/10/27	50-369 50-438 50-369 50-438 50-368		7811100021 7811100023 7811100026 7811100006 78111000062	7811100017 7811100017 7811100017 7811100017 7811100056	78/11/01 78/11/01 78/11/01 78/11/01 78/11/01 78/10/20	50-302 50-302 50-302 50-302 50-387	9 9 9 9
7811080314 7811080353 7811090003 7811090005 7811090007	7811080250 7811080243 7811090001 7811090004 7811090004	78/10/27 78/10/30 78/10/03 78/09/20 78/09/20	50-369 50-369 50-367 50-341 50-341	0 0 0	7811100076 7811100093 7811100093 7811100094 7811100097	7811100075 7811100082 7811100082 7811100092 7811100095	78/10/04 78/10/31 78/10/31 78/10/04 78/09/27	50-213 50-250 50-250 50-213 50-443	9 0 0 0
7811090013 7811090017 7811090018 7811090021 7811090024	7811090009 7811090016 7811090015 7811090015 7811090015	78/11/01 78/09/25 78/10/25 78/10/25 78/10/25	50-324 50-247 50-250 50-250 50-250	0 Р Р	7811100102 7811100109 7811100110 7811100115 7811100121	7811100099 7811100105 7811100103 7811100103 7811100114	78/09/26 78/10/19 78/10/26 78/10/26 78/10/27	50~311 50~10 50~269 50~269 50~344	9 0 0
7811090030 7811090032 7811090034 7811090038 7811090040	7811090025 7811090025 7811090025 7811090025 7811090037	78/10/26 78/10/26 78/10/26 78/10/26 78/10/03	50-317 50-317 50-317 50-317 50-2	0 0 0	7811100124 7811100126 7811100128 7811100127 7811100130	7811100103 7811100114 7811100114 7811100120 7811100103	78/10/26 78/10/27 78/10/27 78/10/20 78/10/26	50-269 50-344 50-344 50-286 50-269	a 0 0 0
7811090041 7811090044 7811090054 7811090058 7811090071	7811090037 7811090043 7811090048 7811090053 7811090039	78/10/03 78/10/31 78/11/08 78/09/21 78/10/20	50-2 50-87 50-320 50-277 50-155	0 6 6 9	7811100133 7811100138 7811100148 7811100148 7811100158	7811100114 7811100120 7811100120 7811100142 7811100120	78/10/27 78/10/20 78/10/20 78/10/05 78/10/20	50~344 50~286 50~286 50~311 50~286	0
7811070077 7811070088 7811070117 7811070124 7811070126	7811070039 7811070039 7811070116 7811070113 7811090125	78/10/20 78/10/20 78/10/27 78/10/30 78/10/19	50-155 50-155 50-237 50-10 50-249	P 8 8 8	7811100164 7811100165 7811100165 7811100172 7811100181	7811100157 7811100120 7811100106 7811100120 7811100120	78/10/02 78/10/20 78/10/21 78/10/20 78/10/20	50-286 50-286 50-286 50-286	а а а в
7811090130 7811090133 7811090134 7811090135 7811090136	7811090129 7811090132 7811090132 7811090132 7811090132	78/11/03 78/11/03 78/11/03 78/11/03 78/11/03	50-237 50-423 50-423 50-423 50-423	8 8 8	781113005 78113007 781113001 7811130013 7811130014	7811130004 7811130003 7811130004 7811130004 7811130009	78/10/02 78/08/24 78/10/02 78/10/31 78/09/29	50-331 50-250 50-331 50-259 50-332	0 0 0 0
7811090141 7811090142 7811090149 7811090150 7811090152	7811090137 7811090138 7811090143 7811090147 7811090146	78/10/24 78/10/27 78/11/03 78/10/27 78/11/01	50-277 50-237 50-329 50-443 50-277	8 8 8 8	7811130018 7811130022 7811130047 7811130073 7811130077	7811130006 7811130006 7811130006 7811130069 7811130069	78/10/31 78/10/31 78/10/31 78/10/25 78/10/25	50-259 50-259 50-259 50-387 50-387	0 0 6 8
7811090153 7811090156 7811090158 7811090159 7811090165	7811090151 7811090143 7811090151 7811090143 7811090155	78/11/01 78/11/03 78/11/01 78/11/03 78/11/02	50-316 50-329 50-316 50-329 50-220	8 8 8	7811130080 7811130083 781113018 7811130119 7811130120	7811130075 7811130075 7811130095 7811130115 7811130113	78/10/26 78/10/26 78/10/02 78/10/03 78/10/03	50-250 50-250 50-327 50-272 50-438	P Q G
7611090168 7611090172 7611090174 7811090179 7611090168	7611070161 7611070167 7611070171 7811070178 7611070182	79/11/02 78/11/03 78/11/01 78/11/03 78/10/04	50-293 50-341 50-320 50-346 50-315	8 8 8 9	7811130151 7811130170 7811130175 7811130192 7811130209	7811130135 7811130075 7811130075 7811130169 7811130206	78/09/27 78/10/26 78/10/26 78/10/21 78/11/06	50-387 50-250 50-250 50-329 50-409	Q P P Q R
7811090187 7811090189 7611090191 7811090192 7811090194	7811070183 7811070182 7811070184 7811070183 7811070183	78/11/02 78/10/04 78/11/01 78/11/02 78/11/02	50-348 50-315 50-261 50-348 50-348	9 9 8 8	7811130214 7811130220 7811130228 7811130229 7811130230	7811130211 7811130218 7811130226 7811130226 7811130146	78/11/02 78/11/04 78/10/30 78/10/30 78/11/03	50-318 50-334 50-348 50-348 50-346	8 0 0 M
7811070177 7811070200 7811070204 7811070205 7811070206	7811090194 7811090183 7811090198 7811090203 7811090135	78/11/02 78/11/02 78/10/26 78/10/26 78/11/02	50-325 50-348 50-259 50-155 50-220	8 6 8 8	7811130231 7811130238 7811130239 7811130240 7811130241	7811130227 7811130237 7811130237 7811130237 7811130237	78/09/28 78/11/08 78/11/08 78/11/08 78/11/08	30-344 50-280 50-280 50-280 30-280	G G G
7811090210 7811090215 7811090217 7811090219 7811090223	7811090177 7811090177 7811090177 7811090177 7811090203	78/11/06 78/11/06 78/11/06 78/11/06 78/10/26	50-280 50-280 50-280 50-280 50-155	9 8 8 8	7611130249 7811130241 7811130249 7611130248 7811130275		78/11/07 78/11/06 78/11/06 78/11/06 78/10/04	50-564 50-321 50-321 50-321 50-334	A G G
7811070226 7811070229 7811070234 7811070235 7811070238	7811090203 7811090203 7811090203 7811090232 7811090232	78/10/26 78/10/26 78/10/26 78/10/26 78/10/26	30-135 30-135 30-135 50-395 50-395	8 8 9 9	7811130205 7811130206 7811130207 7811130301 7811130327	7811130255 7811130289 7811130299	78/10/05 78/11/06 78/11/07 78/11/02 78/11/03	50-334 50-321 50-373 50-333 50-313	0 0 D P 0
7811070240 7811070246 7811070267 7811070273 7811070278	7811090236 7811090242 7811090266 7811090271 7811090274	78/11/06 78/10/18 78/10/02 78/11/02 78/11/01	50-281 50-335 50-332 50-220 50-320	8 9 9	7811130302 7811130303 7811130303 7811130343 7811130344	781113033 ^r 7811130059 7811130340	78/10/24 78/10/24 78/08/17 78/09/21 78/11/03	50-362 50-264 50-10 50-329 50-580	A P G H
7811090279 7811090290 7811090303 7811100012 7811100013	7811090275 7811090284 7811090298 781110008 7811100010	78/09/25 78/09/21 78/10/03 78/09/27 78/09/01	50-390 50-320 50-255 50-293 50-219	0 0 0 P	7811130350 7811130357 781113034 7811130376 7811130381	7811130354 7811130354 7811130374	78/09/21 78/10/25 78/10/25 78/10/30 78/10/30	50-327 50-369 50-369 50-369 50-369	9 9 9 9

ACCESSION NUMBER					ACCESS 10	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1980ED	BUBJECT CATEOOR	łY	ENCLOSURE	PRINCIPAL DOCUMENT	DATE 1860ED	SUBJECT	
7811130391 7811130393 7811130412 7811130419 7811140033	7811220186 7811130386 7811130409 7811130410 7811140030	78/11/15 78/09/28 78/10/05 78/10/06 78/10/16	50-220 50-364 50-302 50-338 50-250	P 0 0 P	7811140265 7811140267 7811140269 7811140274 7811140277	7811140258 7811140264 7811140268 7811140271 7811140271	78/10/27 78/10/12 78/10/06 78/11/02 79/11/02	50-410 50-373 50-341 50-311 50-311	A G G
7811140036 7811140039 7811140043 7811140034 7811140035	7811140030 7811140030 7811140037 7811140048 7811140033	78/10/16 78/10/16 78/10/04 78/10/10 78/10/31	50-250 50-250 50-311 50-329 50-206	Р С С Р	7811140278 7811140280 7811150041 7811150043 7811150045	7811140271 7811140271 7811150038 7811150038 7811150038	79/11/02 - 79/11/02 79/11/01 79/11/01 79/11/01	50-311 50-311 50-220 50-220 50-220	0 0 0
7811140057 7811140063 7811140106 7811140108 7811140113	7811140053 7811140053 7811140104 7811140102 7811140110	78/10/31 78/10/31 78/11/01 78/10/30 78/11/08	50-204 50-204 50-286 50-502 50-336	P R A R	7811150049 7811150053 7611150063 7811150063 7811150067	7811150038 7811150053 7811150058 7811150058 7811150058	79/11/01 79/10/12 79/11/07 79/11/07 79/11/07	50-220 50-346 50-395 50-395 50-395	0 0 0
7811140117 7811140118 7811140122 7811140123 7811140127	7811140115 7811140116 7811140120 7811140121 7811140125	78/11/09 78/11/08 78/11/10 78/11/10 78/11/10	50-282 50-305 50-29 50-333 50-271	R R R	781115008 7811150079 7811150079 7811150100 7811150102	7811150086 7811150092 7811150091 7811150092 7811150092	78/10/13 78/11/03 78/11/09 78/11/03 78/11/03	50-331 50-309 50-309 50-309 50-309	0 0 P 0
7811140131 7811140133 7811140136 7811140140 7811140141	7811140124 7811140124 7811140125 7811140127 7811140127	78/11/08 78/11/08 78/11/08 78/11/09 78/11/06	50-246 50-246 50-346 50-259 50-344	P ያ የ የ	7811150103 7611150109 7811150119 7811150129 7811150130	7811150092 7811150107 7811150116 7811150128 7811150127	78/11/03 78/10/30 78/11/06 78/11/07 78/10/23	50-309 50-329 50-171 50-260 50-528	9 4 4 P C
7811140144 7811140145 7811140148 7811140150 7811140151	7811140142 7811140126 7811140147 7811140146 7811140146	78/11/09 78/11/09 78/11/08 78/11/10 78/11/10	50-277 50-275 50-255 50-155 50-155	R R 8	7811130131 7811150136 7811130149 7811130159 7811150173	7811150126 7811150135 7811150146 7811150154 7811150167	78/11/06 78/11/03 78/11/10 78/10/30 78/11/06	50~580 50~556 50~133 50~220 50~266	8 R P F
7811140161 7811140162 7811140163 7811140166 7811140169	7811140107 7811140156 7811140160 7811140112 7811140119	78/11/08 78/11/02 78/10/27 78/11/10 78/11/08	50-285 50-321 50-237 50-309 50-10	R 8 9 9 R	7811150175 7811150176 7811150182 7811150188 7811150190	7811150171 7811150137 7811150171 7811150184 7811150184	78/11/06 78/11/07 78/11/06 78/11/03 78/11/03	50-247 50-327 50-247 50-220 50-220	Р А Р О
7811140170 7811140173 7811140178 7811140181 7811140188	7811140164 7811140171 7811140174 7811140177 7811140183	78/11/02 78/10/30 78/11/08 78/11/06 78/11/10	50-243 50-206 50-206 50-273	8 8 8 8	7811150192 7811150194 7811150194 7811150199 7811150249	7811130184 7811130184 7811130137 7811150137 7811150245	78/11/03 78/11/03 78/11/07 78/11/07 78/11/02	50-220 50-220 50-327 50-327 50-317	0 A A Q
7811140189 7811140191 7811140195 7811140199 7811140204	7811140185 7811140187 7811140186 7811140193 7811140198	78/10/11 78/11/06 78/11/08 78/11/01 78/11/03	50-315 50-245 50-296 50-237 50-366	0 8 8 1	7811150272 7811150274 7811150274 7811160046 7811160083	7811150265 7811150265 7811150265 7811160045 7811160061	78/11/02 78/11/02 78/11/02 78/10/29 78/11/08	50-317 50-317 50-317 50-466 50-368	0 0 0 9
7811140208 7811140206 7811140211 7811140212 7811140213	7811140202 7811140201 7811140209 7811140207 7811140203	78/11/06 78/11/08 78/11/02 78/11/07 78/11/02	50-336 50-296 50-366 50-293 50-237	9999	7811160044 7811160058 7811160072 7811160075 7811160078	7811160062 7811160066 7811160067 7811160074 7811160076	78/11/09 78/11/08 78/11/06 78/11/09 78/11/07	50-313 50-321 50-438 50-272 50-312	P R B R
7811140218 7811140220 7811140221 7811140226 7811140227	7811140210 7811140215 7811140217 7811140210 7811140222	78/11/08 78/11/02 78/11/08 78/11/08 78/11/01	50-316 50-237 50-259 50-316 50-249	9 8 8	7811160082 7811160086 7811160090 7811160092 7811160093	7811160080 7811160084 7811160085 7811160088 7811160089	78/11/05 78/11/09 78/11/02 78/11/09 78/11/07	50-206 50-277 50-348 50-325 50-245	A R R 8
7611140228 7611140232 7611140233 7611140234 7611140236	7811140223 7811140210 7811140225 7811140229 78111140230	78/11/09 78/11/08 78/11/07 78/11/02 78/11/06	50-255 50-316 50-348 50-322 50-312	8 9 9	78:116094 78:1160101 78:1160103 78:1160104 78:1160110	7811160091 7811160100 7811160102 7811160099 7811160106	78/11/10 78/11/06 78/11/13 78/11/08 78/11/08	50-324 50-344 50-271 50-296 50-366	R R 8 S R
7811140237 7811140239 7811140242 7811140243 7811140244	7811140225 7811140229 7811140225 7811140229 7811140240	78/11/07 78/11/02 78/11/07 78/11/02 78/11/08	50-348 50-322 50-348 50-322 50-259	8 9	78:11601:1 78:11601:1 78:11601:3 78:11601:7 78:11601:7	7811140109 7811140113 7811140112 7811140114 7811140119	78/11/11 78/11/03 78/11/09 78/11/13 78/11/19	50-334 50-298 50-237 50-263 50-261	R B R A
7811140246 7811140248 7811140249 7811140250 7811140251	7811140285 7811140288 7811140289 7811140247 78111140225	78/11/07 78/11/10 78/11/02 78/11/09 78/11/07	50-348 50-333 50-322 50-286 60-348	8 9 9 8	76:1160125 76:1160123 76:1160123 76:1160140 76:1160141	7811160122 7811160128 7811160132 7811160136 7811160137	78/11/02 78/11/13 78/11/09 78/11/06 78/11/06	50-237 50-271 50-325 50-302 50-325	8 8 9
7611140253 7611140253 7611140253 7611140254 7811140255	7811140090 7811140090 7811140090 7811140245 78111140252	78/10/04 78/10/04 78/10/04 78/10/27 78/11/03	50~518 50~518 50~518 50~366 50~3	0 0 8 0	76:1160142 76:1160144 76:1160159 76:1160160 76:1160182	7811160139 7811160138 7811160158 7811160157 7811160181	78/11/10 78/11/07 78/11/01 78/11/08 78/10/16	50-250 50-325 50-556 50-440 50-482	P 9 6 8
7811140205 7811140209 7811140261 7811140262 7811140265	7811140252 7811140252 7811140258 7811140252 78111140258	78/11/03 78/11/03 78/10/27 78/11/03 78/10/27	50-3 50-3 50-410 50-3 50-410	Q A Q A	7811160186 7811160189 7811170086 7811170090 7811170109	7811160181 7811160181 7811170085 7811170087 7811170107	78/10/16 78/10/16 78/11/02 78/11/03 78/11/14	50-482 50-482 50-382 60-446 50-338	8 0 0 R

ACCESSION NUMBER ACCESSION NUMBER

ACCESSION						N NUMBER			
ENCL D SURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJECT	Y	ENCLOSURE	PRINCIPAL DOCUMENT	DATE IBSUED	SUBJECT	łΥ
7811170114 7811170115 7811170119 7811170131 7811170142	7811170111 7811170104 7811170111 7811170130 7811170141	78/10/06 78/11/13 78/10/06 78/11/09 78/11/03	50-128 50-245 50-128 50-277 50-344	G R G R	7811200168 7811200170 7811200172 7811200174 7811200177	7811200006 7811200006 7811200006 7811200006 7811200006	78/10/27 78/10/27 78/10/27 78/10/27 78/10/27	50-437 50-437 50-437 50-437 50-437	A A A A
7811170143 7811170171 7811170174 7811170178 7811170184	7811170141 7811170165 7811170168 7811170172 7811170182	78/11/03 78/11/10 78/10/17 78/11/13 78/11/14	50-344 50-318 50-556 50-334 50-338	P 8 0 8	7811200180 7811200183 7811200186 7811200187 7811200188	7811200176 7811200006 7811200004 7811200184 7811200182	78/11/06 78/10/27 78/10/27 78/11/15 78/10/11	50-313 50-437 50-437 50-302 50-518	B A R G
7811170185 7811170187 7811170189 7811170192 7811170213	7811170183 7811170179 7811170182 7811170188 7811170209	78/11/14 78/11/13 78/11/14 78/11/14 78/11/14	50-280 50-318 50-338 50-280 50-325	8 6 8 8	7811200190 7811200191 7811200192 7811200196 7811200198	7811200183 7811200189 7811200004 7811200004 7811200194	78/11/17 78/11/03 78/10/27 78/10/27 78/11/14	50-367 50-368 50-437 50-437 50-280	K S A A R
7811170234 7811170238 7811170240 7811170242 7811170245	7811170221 7811170232 7811170232 7811170232 7811170232	76/11/13 78/11/08 78/11/08 78/11/09 78/11/09	50-334 50-324 50-324 50-324 50-324	0	7611200202 7811200203 7811200205 7611200207 7811200208	7811200006 7811200201 7811200006 7811200204 7811200006	78/10/27 78/11/14 78/10/27 78/11/15 78/10/27	50-437 50-272 50-437 50-219 50-437	A 8 A 8 A
7911170249 7811170259 7811170262 7811170264 7811170265	7811170247 7811170256 7811170260 7811170260 7811170256	78/11/03 78/11/01 78/10/03 78/10/03 78/11/01	50-462 50-282 50-358 50-358 50-282	0 0 0 P	7611200210 7811200211 7611200212 7811200213 7811200214	7811200127 7811200006 7811200209 7811200006 7811200127	78/11/08 78/10/27 78/11/15 78/10/27 78/11/08	50-280 50-437 50-346 50-437 50-280	0 A B A Q
7811170268 7811170293 7811170298 7811170299 7811170319	7811170256 7811170289 7811170294 7811170295 7811170316	78/11/01 78/11/02 78/11/10 78/10/06 78/10/16	50-282 50-14B 50-329 50-311 50-6	P Q C G	7811200215 7811200217 7811200218 7811200220 7811200220	7811200006 7811200216 7811200216 7811200006 7811200219	78/10/27 78/10/06 78/10/06 78/10/27 78/10/10	50-437 50-498 50-498 50-437 50-201	<b>A</b> G G A P
7811200013 7811200015 7811200019 7811200024 7811200026	7811200006 7811200006 7811200006 7811200021 7811200006	78/10/27 78/10/27 78/10/27 78/10/13 78/10/27	50-437 50-437 50-437 50-327 50-437	A A Q A	7811200224 7811200232 7811200236 7811200238 7811200239	7811200006 7811200006 7811200006 7811200006 7811200235	78/10/27 76/10/27 78/10/27 78/10/27 78/10/27 78/08/11	50-437 50-437 50-437 50-437 50-437	A A A A
7811200032 7811200034 7811200037 7811200043 7811200049	7811200006 7811200029 7811200006 7811200006 7811200006	78/10/27 78/10/11 78/10/27 78/10/27 78/10/27	50-437 50-324 50-437 50-437 50-437	A G A A	7811200242 7811200243 7811200246 7811200248 7811200233	7811200006 7811200006 7811200006 7811200006 7811200006	78/10/27 78/10/27 78/10/27 78/10/27 78/10/27	50~437 50~437 50~437 50~437 50~437	* * * * *
7811200053 7811200058 7811200063 7811200067 7811200069	7811200004 7811200004 7811200004 7811200004 7811200004	78/10/27 78/10/27 78/10/27 78/10/27 78/10/27	50-437 50-437 50-437 50-437 50-437	A A A A	7611200258 7811200259 7811200261 7811200267 7811200267	7811200006 7811200173 781120006 781120006 781120006	78/10/27 78/11/17 78/10/27 78/10/27 78/10/27	50-437 50-424 50-437 50-437 50-437	* * * *
7811200075 7811200076 7811200078 7811200080 7811200082	781120000A 781120000A 781120000A 7811200060 781120000A	78/10/27 78/10/27 78/10/27 78/05/16 78/10/27	50-437 50-437 50-437 50-346 50-437	A A A P A	7811200270 7811200272 7811200276 7811200279 7811200285	7811200006 7811200006 7811200006 7811200006 7811200006	78/10/27 78/10/27 78/10/27 78/10/17 78/10/27	50-437 50-437 50-437 50-437 50-437	A A A A
7811200083 7811200086 7811200089 7611200092 7811200093	7811200004 7811200004 7811200004 7811200087 7811200006	78/10/27 78/10/27 78/10/27 78/10/03 78/10/27	50-437 50-437 50-437 50-346 50-437	A A R A	7811200288 7911200291 7811200294 7811200298 7811200298	7811200264 781120006 7811200264 781120006 781120006	78/11/07 78/10/27 78/11/07 78/10/27 78/10/27	50-395 50-437 50-395 50-437 50-437	0 4 0 4 4
7811200075 7811200076 7811200078 7811200100 7811200102	7811200087 7811200087 7811200087 7811200087 7811200006	78/10/03 78/10/27 78/10/03 78/10/03 78/10/27	50-346 50-437 50-346 50-346 50-437	R A R R	7811200302 7811200310 7811200313 7811200327 7611200330	7811200006 7811200006 7811200006 7811200006 7811200323	78/10/27 78/10/27 78/10/27 78/10/27 78/10/18	50-437 50-437 50-437 50-437 50-298	A A A
7811200105 7811200106 7811200108 7811200110 7811200114	7811200004 7811200087 7811200006 7811200006 7811200006	79/10/27 78/10/03 78/10/27 78/10/27 78/10/27	50-437 50-346 50-437 50-437 50-437	A A A	7811200331 7811200339 7811200349 7811200349 7611200352	7811200006 7811200006 7811200006 7811200006 7811200006	78/10/27 78/10/27 78/10/27 78/10/27 78/10/27	50-437 50-437 50-437 50-437 50-437	***
7811200130 7811200133 7811200134 7811200136 7811200138	7811200006 7811200127 7811200006 7811200006 7811200006	78/10/27 78/11/08 78/10/27 78/10/27 78/10/27	50-437 50-280 50-437 50-437 50-437	A A A	7811200356 7811200359 7811200369 7811200369 7811200375	7811200350 7811200006 7811200006 7811200006 7811200006	78/11/17 78/10/27 78/10/27 78/10/27 78/10/27	50-313 50-437 50-437 50-437 50-437	P A A A
7811200140 7811200142 7811200147 7811200149 7811200151	7811200127 7811200006 7811200006 7811200145 7811200006	78/11/08 78/10/27 78/10/27 78/11/01 78/10/27	50-280 50-437 50-437 50-368 50-437	Q A A B	7811200380 7811200384 7811200384 7811200390 7811200392	7811200006 7811200366 7811200006 7811200006 7811200366	78/10/27 78/11/09 78/10/27 78/10/27 78/11/09	50-437 50-275 50-437 50-437 50-275	A A A A
781 1200153 761 1200156 761 1200157 761 1200162 781 1200164	7611200004 7611200004 7611200004 7811200004 7911200160	78/10/27 78/10/27 78/10/27 78/10/27 78/10/27 78/11/15	50-437 50-437 50-437 50-437 50-219	A A A P	7811200396 7811200403 7811200408 7811200417 7811200424	7811200006 7811200006 7811200006 7811200006	78/10/27 78/10/27 78/10/27 78/10/27 78/10/27	50-437 50-437 50-437 50-437 50-437	4444

1811500435	7911200006	78/10/27	50-437		7911210394	7811210380	70.44.4.4	00 B (C	- 5
7811200433 7811200434	7811200006	78/10/27	50-437	A	7911210383	7811210378	78/11/15 78/04/04		
7011200434	7811200006	78/10/27	50-437	A	7911210391 7911210393		78/11/14	50-315	A
7811200435	7811200006	78/10/27	50-437	A			78/11/13	50-10	8
7811200436 7811200437	7811200006 7811200006	78/10/27	50-437	Ä	7911210394 7811210404		78/11/13		R
7811200438	7811200006	78/10/27 78/10/27	50-437 50-437	A	7811210409	7811210407	78/11/09 78/11/16		
7811200439	7B11200006	78/10/27	50-437	Ã	7811210422 7811210424	7811210414	78/11/17	50-333	
7811200440	7811200006	76/10/27	50-437		7811210436	7811210415	78/10/16	50-266	G
7811200441	7811200006	78/10/27	50-437	Á	7811210436		78/11/14	50-316	R
7811200442 7811210013	7811200006 7811210005	78/10/27	50-437	A	7811210476 7811210487		78/11/06	30-336	н
7811210024	7811210018	78/10/19 78/10/19	50-456 50-331	0	7811210501	7811210460	78/10/04 78/10/04	50-313 50-313	a
7811210027	7811210022			_	7911220003	7811220002	78/11/09	50- 335	ā
7811210044	7B11210022	78/10/18 78/11/01	50-456 50-466	9	7811220005		78/11/09	50-335	Q
7811210086 7811210088	7811210065	78/11/13	50-70	ů	7911220028 7911220033		78/11/14	50-321	8
7811210106	7811210083 7811210103	78/10/10 78/10/03	50-339 50-440	ō	7811220059		78/11/09 78/11/13	50-254 50-321	R
			20-440	ū	7811220060	7811220058	78/11/07	50-549	ī
7811210112 7811210115	7811210103 7811210114	78/10/03 78/09/14	50-440	0	7811220062	7811220058	78/11/07	50-549	т
7811210121	7811210114	78/09/14	50-313 50-313	0	7811220064	7811220034	78/11/13	50-321	ė
7811210125 7811210128	7811210114	78/09/14	50-313	G	7811220065 7811220068	7811220038 7811220058	78/11/07 78/11/07	30-549 30-349	Ţ
\011E10150	7811210114	78/09/14	50-313	q	7811220070	781122005B	78/11/07	50-549	T T
7811210169	7811210164	78/11/13	50-275	F	7811220077	7811220039	70/11/07		
7811210173 7811210179	7811210170 7811210176	78/10/06 78/11/15	50-358 50-348	J	7811220078	7811220076	78/11/07 78/11/15	50-549 50-3	J
7011210181	7811210177	78/11/13	50~237	R S	7811220081 7811220082	7811220076	78/11/15	50-3	J
7811210183	7811210178	78/10/24	50-496	Á	7811220084	7611220058 7611220058	78/11/07 78/11/07	30-349 30-349	7
7811210186	7811210184	78/11/15	50-289	R	7911720000				
7811210192	7811210187	78/11/13	50-368	R	7811220088 7811220091	7811220039 7811220087	78/11/07 78/11/15	50-549 50-260	T G
7811210205 7811210207	7811210200 7811210200	78/11/06 78/11/06	20-589 20-587	P	7811220092	7811220058	78/11/07	30-349	Ť
7811210213	7811210200	78/11/06	30-266	ř	7811220093 7811220095	7811220087 7811220087	78/11/15 78/11/15	50-260	g
7811210216	7811210214	78/10/12	80-771				,0,11,13	50-260	q
7811210220	7811210214	78/10/12	50-331 50-331	0	7811220096 7811220099	7811220038 7811220087	78/11/07	50-549	Ţ
7811210226 7811210241	7811210217	78/11/13	50-424	A	7811220118	7611220113	78/11/15 78/11/09	50~260 50~34B	Q P
7811210243	7811210239 7811210238	78/11/14 78/11/14	50-219 50-366	R 8	7811220123 781 <i>122012</i> 5	7811220113	78/11/09	50-348	ρ
701101000						1911850113	78/11/09	50-34B	P
7811210253 7811210245	7811210246 7811210260	78/11/07 78/11/14	50-366 50-315	8 P	7811220140	7811220138	78/10/30	50-263	ρ
7811210266	7011210259	78/11/14	50-201	8	7811220143 7811220144	7811220138 7611220138	78/10/30 78/10/30	50-263 50-263	P
7811210269 7811210275	7811210263 7811210268	78/11/01	50-293 50-334	R B	7811220148	7811220145	78/11/03	30-338	þ
	,011210400		JD JJU		7811220152	7811220149	78/11/06	30-566	0
7811210278 7811210283	7811210271	78/11/15	50-315	8	7811220169	7811220168	78/11/14	50-361	A
7811210284	7811210261 7811210282	78/11/13 78/11/14	50-220 50-213	8 8	7911220178 7911220180	7811220176 7811220177	78/11/17 78/09/22	50-329 50-325	8 P
7811210297	7811210281	78/11/15	50~220	8	7811220182	78:1220181	78/11/20	50-275	Ā
7811210289	7811210242	78/11/09	50-338	q	7811220187	7811220183	78/11/15	50-324	8
7811210291	7811210280	78/11/16	50-245	8	7911220199	7811220185	78/11/15	50-269	8
7811210292 7811210294	7811210281 7811210290	78/11/15 78/11/14	50-338 50-220	8 8	7911220191 7911220192	7811220186 7811220189	78/11/15 78/11/17	50-220	P
7811210299	7811210293	78/11/20	50-341	ĸ	7911220193	7811220184	78/11/15	50-286 50-220	8 P
7811210303	7811210302	78/11/08	50-220	R	7811220197	7811220195	78/11/17	50-397	9
7811210304	7811210301	78/10/27	50-237	8	7811220199	7811220198	78/11/17	50-305	8
7811210310 7811210311	7811210305	78/11/15	50-327 50-213	A	7811220202 7811220203	7811220200	78/11/08	50-309	8
7811210311	781121030 <b>8</b> 7811210313	78/09/R5 78/11/17	50-338	8 8	7811220217	7811220201 7811220213	78/11/08 78/11/01	50-250 50-309	8 8
7811210318	7811210113	78/11/14	50-275	A	7811220252	7811220251	78/10/27	50-220	P
7811210324	7811210321	78/11/18	50-219	8	7811220256	7611220234	78/10/16	50-261	Q.
7011210325	7811210317	78/11/15	50-29	8	7811220257	7811220263	78/10/17	50-275	ĕ
7811210335 7811210336	7811210330 7811210332	78/11/16 78/11/15	50-255 50-320	8 8	7811220282 7811220284	7811220280 7811220280	78/11/09 78/11/09	50-395 50-395	0
7811210337	7811210330	78/11/16	50-255	ŝ	7811240007	7811240001	78/11/13	50-335	ă
7011010200	7011010077	70/11/01	50-249	8	7811240009	7811240001	78/11/13	50-335	o
7811210339 7811210344	7811210333 7811210340	78/11/01 78/11/15	50-3	R	7811240011	7611240001	78/11/13	50-335	å
7811210345	7811210341	78/11/14	50-293	8	7811240013 7811240027	7611240001	78/11/13	50-335	9
7811210346 7811210352	7811210342 7811210347	78/11/13 78/11/13	50-321 50-346	8	7811240027 7811240032	7811240025 7811240029	78/11/09 78/11/13	50-250 50-363	O H
					7811240093				
7811210357 7811210358	7811210347 7811210355	78/11/13 78/11/13	50-346 50-348	8 8	7811240048	7611240025 7611240044	78/11/09 78/10/10	50-250 50-29	Ĵ
7811210359	7811210333	78/11/13	50-346	8	7811240050	7811240046	78/11/15	50-336	g
7811210362	7811210347	78/11/13 78/11/15	50-346 50-321	8 B	7911240052 7811240055	7811240046 7811240046	78/11/15 78/11/15	50-33 <b>8</b> 50-338	g G
7811210366	7B11210361	\A\11\13			-				
7811210370	7811210351	78/11/09	50-366	8	7811240057 7811240065	7811240046 7811240061	78/11/15 78/11/13	50-338 50-424	G G
7811210371 7811210374	7811210348 7811210347	78/11/08 78/11/13	50-285 50-346	8 8	7811240068	7811240061	78/11/13	50-424	q
7811210375	7811210372	78/11/14	50-346	8	7811240072 7811240074	7811240067 7811240071	78/11/17 78/11/14	50-440 50-302	0
7811210379	7811210372	78/11/14	50-346	8	/8118400/4	> 0 1 1 E 4 / V	/0/11/14		•

## CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCESSION NU					ACCESSION				
	INCIPAL CCUMENT	DATE 188UED	SUBJECT CATEGORY	,	ENCLOBURE	PRINCIPAL DOCUMENT	DATE 168UED	BUBJECT CATEODR	
		78/11/14	20-305	a	7811270146	7811270138	78/11/20 78/11/20	50-36B	8
7811240081 78	11 [240071	78/11/14 78/11/14	50-302 50-302	0	7811270149 7811270150 78]1270151	7811270138 7811270148 7811270147	78/06/30 78/11/21	50-331 50-329	8 A
		78/11/15 78/11/15	50-70 50-70	U	7811270156	7811270154	78/11/21	50-267	P
		78/11/21	50-220 50-49B	e C	7811270159 7611270168	7811270157 7811270165	78/11/20 78/11/17	50~369 50~369	A K
7811240126 78	311240124	78/11/22 78/10/25	50-263	8	7811270178 7811270181	7811270177 7811270177	78/10/18 78/10/18	50-482 50-482	9
		78/11/16 78/10/13	90-384 50-295	8	7811270199	7811270194	78/10/10	50-522	G
	311240131 311240130	78/10/13 78/10/12	50-301 50-301	9	7811270205 7811270209	7811270201 7811270201	78/10/11 78/10/11	50-382 50-382	0
7811240137 78		78/11/20 78/11/05	50-272 50-304	8	7811270246 7811270250	7811270243 7811270243	78/11/09 78/11/09	50-333 50-333	P
	311240141	78/11/20	50-311	Ā	7811270253	7811270243	78/11/09	50-333	P
	911240154 911240153	78/10/19 78/11/03	50-304 50-263	8 8	7811280007 7811280008	7811280004 7811280004	78/11/08 78/11/13	50-206 50-321	P G
7811240138 78	311240155 311240157	78/10/23 78/11/13	50~322 50~322	8	7811280012 7811280032	7811280006 7811210018	78/11/13 78/10/19	50-321 50-331	0 0
	911240171	78/11/01	50-315	В	7811280054	7611260050	78/10/16	50-556 50-285	0
	911240171 911240171	78/11/01 78/11/01	50~315 50~315	8	7811280060 7811280062	7811280058 7811280058	78/10/12 78/10/12 78/11/14	50-265 50-29	g P
	311240175 911240176	78/10/19 78/11/14	50~254 50~304	8 8	7811280082 7811280083	7811280080 7811280080	78/11/14 78/11/14 78/11/14	50-29 50-29	þ
	811240179	78/10/27	50-254	8	7811280084 7811280104	7811280080 7811280101	78/11/14	50-27	A
7811240193 76	811240187 811240192	78/11/17 78/10/26	30-245 30-265	8	7611280159 7611280159 7811280172	7811280157 7811280170	78/11/20 78/11/08	50-458 50-250	Î
7B11240198 7	811240195 811240197	78/10/25 78/10/13	50-304 50-295	8	7811280174 7811280178	7811280170 7811280170	78/11/08 78/11/08	50-250 50-250	F
	B11240200	78/10/13	50-293	8	781 1280191	7811280187	78/11/21	50-259	8
7811240206 76	B11240203 B11240205	78/10/30 78/11/03	50-265 50-295 50-295	8	7811280196 7811280199	7811280193 7811280194	78/11/16 78/11/17	50-219 50-249	8
7811240211 7	811240207 811240210	78/11/03 78/10/17 78/10/13	50-277 50-275	6 6 6	7811280202 7611280203	7811280198 7811280201	78/11/22 78/11/24	50-346 50-260	8
	B11240212 B11240215	78/11/15	50-317	R	7811290206	7811280204	78/11/20	30-331	8
7811240720 7	811240218 B11240221	78/10/13 78/10/13	50-304 50-295	8	7811280207 7811280211	7811260205 7811280208	78/11/22 78/11/16	50-259 50-368	8
7811240224 7	811240222 811240226	78/10/20 78/11/17	50-265 50-267	8	7811280220 7811280224	7811280217 7811280222	78/11/20 78/11/20	30-366 30-366	8
	811240227	78/10/27	50-295	8	7811280230	7811280227	78/11/20	50-278	8
	811240232 811240231	78/11/17 78/10/06	50-267 50-155	8 6	7811280238 7911280239	7811280234 7811280234	78/11/21 78/11/22	50-280 50-243 50-321	8
	811240237 811240239	78/10/23 78/11/01	50-254 50-265	8	7811280242 7811280244	7811270235 7811280234	78/11/20 78/11/22	50-263	B
	811270011	78/10/16	50-338	G	7811280249 7811280253	7811280234 7811280234	78/11/22 78/11/22	50-263 50-263	8 8
7811270017 7	B11270011 B11270018	78/10/16 78/11/08	50-338 50-315	G P P	7811280254 7811280254 7811280254	7811270248 7811280234	78/11/22 78/11/22	50-352 50-243	8
	811270018 811270018	78/11/08 78/11/08	50-313 50-313	P	7811280253	7811280260	78/11/17	50-247	8
	811270018 811270039	78/11/08 78/10/12	50-315 30-445	P Q	7811280269 7811280270	7811280264 7811280260	78/11/27 78/11/17	50-373 50-247	K B
7811270043 7	811270041 811270044	78/11/01 78/10/16	50-298 50-361	Ē	7811280271 7811280272	7811280268 7811280267	78/11/20 78/11/22	50~302 50~348	8
	811270048	78/11/08	50-483	ě	7811280276	7811280275	78/11/91	50-272	J
	811270052 811270054	78/11/07 78/10/24	50-488 50-312	A	7811260281 7811290289	7811280277 7811280285	78/11/21 78/11/22	50-206 50-267	8
7811270061 7	611270059 B11270059	78/11/13 78/11/13	50-34B 50-34B	P	7611260270 7811290272	7811270284 7811280286	78/11/20 78/11/20	50-29 50-281	8 8
	811270039	78/11/13	50-348	P	7811280293	7811280288	78/11/20	50-366	8
7811270077 7	7811270071 7811270050	78/11/09 78/11/22	50-10 50-495	P	7811280298 7811280300	7811280294 7811280295	78/11/21 78/11/21	50~336	8
	PB11270071 PB11270069	78/11/09 78/11/03	50-10 50-315	8 8	7811280302 7811280305	7811280297 7811280299	78/11/22 78/11/22	50-549 50-305	9
	7811270071	78/11/09	50-10	P	7811280307	7811280303	78/11/20	50-302	8
7911270093 7	7811270088 7811270088	78/10/20 78/10/20	50-312 50-312	9	7811280309 7811280310	7811280301 7811280299	78/11/13 78/11/22 78/11/22	50-249 50-305 50-272	8 8 8
7811270097	7811270088 7811270088	78/10/20 78/10/20	20-315	9	7811280313 7811280317 7811280317	7811280304 7811280315	78/11/22 78/11/24 78/11/22	50-344 50-267	P B
	7811270094	78/11/21	50-155	P	7811280318 7811280320	7811280312 7811280316	78/11/22	50-338	8
7811270106	7811270100 7811270100	78/11/06 78/11/06 78/10/19	50-263 50-263 50-344	Р G	7811280321 7811280321 7811280323	7811280316 7811270314	78/11/22 78/11/22	50-338 50-29	8
7811270110	7811270102 7811270100 7811270111	78/11/06 78/11/06 78/10/16	50-344 50-263 50-344	P G	7811280325 7811280326	7811280322 7811280322	78/11/20 78/11/20	50~53B 50~33B	8
	7811270121	78/10/19	50-70	G.	7811280327	7811280324	78/11/22	50-344	0
7811270129	7811270123 7811270130	78/11/13 78/11/17	50-298 50-271	Q P	7811280330 7811280332	7811280322 7811280328	78/11/20 78/11/20	50-338 50-29	8 8
7811270142	7811270138	78/11/20	50-348	8	7811280335 7811280335	7811280333 781128033A	78/11/22 78/11/20	50-293 50-348	9 8

PRINCIPAL

DATE

BUBJECT

ENCLOSURE	DOCUMENT	DATE 188UED	CATEGOR	łγ			PRINCIPAL	DATE	SUBJECT	r
7811260342	7811280336	78/11/20	50-348	8		ENCLOSURE	DOCUMENT	ISSUED	CATEGOR	
7811280348	7811280336	78/11/20	50-348	S		7911300248	7811300241	78/11/03	50-334	0
7811280390 7811280398	7811280378 7811280378	78/11/06 78/11/06	50-269 50-269	a		7811300250 7811300254	7811300241 7811300251	78/11/03	50-334	0
7011200434	7811280425	78/11/09	50-269	O A	7	7811300260	7811300237	78/10/26 78/10/25	50-440 50-358	0
7811260458	7811280454	78/11/06	BO 440		•	7811300264	7811300261	78/10/25	50-10	0
7811200493	7811280491	78/09/29	50-412 50-331	9 P		7911300268	7811300261	78/10/25	50-10	a
7811260494 7811290005	7811280491 7811290000	78/09/29	50-331	P		7811300298 7811300306	7811300295	78/10/10	50-272	G
7811290006	7811270003	78/11/14 78/11/14	50-572 50-572	A A	7	7811300318	7811300303 7811300314	78/10/10 78/09/29	50-322 50-255	9
7811290046					•	7811300339	7811300336	78/10/18	50-390	ō
7811270077	7811290044 7811290095	78/11/03 78/11/11	50-314 50-219	Q P		7811300340	7811300337	78/10/19	50-247	0
7811290104	7811270095	78/11/11	50-219	P		7811300342 7811300347	7811300341	78/10/24	50-213	Q
7811270106 7811270166	7811290095 7811290192	78/11/11 78/11/06	50-219	P		7911300350	7811300345 7811300349	78/10/17 78/10/27	50-412 50-255	0
		,0,11,00	50-260	Р	7	7811300392	7811300344	78/11/13	56 592	H
7811290168 7811290172	7811270152 7811270152	78/11/06 78/11/06	50-260	P		7811300354	7811300349	76/10/27	50-255	o.
7811290175	7811290152	7B/11/06	50-280 50-280	P P		7811300362	7811300361	78/09/13	50-184	œ
7811290203 7811290235	7811290198	78/11/25	50-29	9		7811300353 7811300377	7811300361 7811300366	78/09/13 78/10/18	50-184 50-20	o a
701127023	7811290229	78/11/16	50-335	8		7811300380	7811300366	78/10/18	50-20	ä
7811290251 7811290252	7811270247	78/11/27	50-315	K	7	7811300392	7811300370	7B/11/16	50-490	a
7B11290267	7811290248 7811290244	78/11/24 78/11/24	50-390 50-317	К 8		7811300397	7811300383	78/10/13	30-410	ã
7811270292	7811290291	78/11/13	50-245	R		811300401 811300402	7811300398 7811300397	78/09/29 78/10/23	50-263 50-373	9
7811290304	7811290297	78/10/26	50-70	0		012010012	7812010008	78/11/13	50-277	G G
7611290315	7811290310	78/11/02	50-112	P	7	7812010014	7812010010	78/11/21	50~275	A
7611290318 7611290319	7811290317 7811290317	78/11/08 78/11/08	50~309	P	7	812010015	7812010010	78/11/21	50-275	Ä
7611290322	7811290320	78/11/08	50-309 50-389	P G		812010016 812010019	7812010008 7812010010	78/11/15 78/11/21	50-277 50-275	Q.
7811290323	7811290321	78/10/19	50-566	Q		B12010025	7812010008	78/11/15	50-277	Ĝ
7811290325	7811270020	78/11/14	50-389	0	7	812010031	7812010008	78/11/13	90-277	g
7811290326 7811290331	7011270324	78/10/25	50-320	0	7	812010036	7812010034	78/10/20	50-333	ĕ
7611270332	7811290327 7811290328	78/10/23 78/11/17	50-346 50-336	<b>0</b> 0		7812010040 7812010041	7812010038 7812010037	78/10/18 79/10/20	50-586 50-586	0
7811290335	7811290328	70/11/17	50-336	ö		812010042	7812010039	78/11/21	50-47t	3
7811290336	7811290000	78/10/23	50-266	a	7	812010044	7812010039	78/11/21	50-471	0
7811290308	7811270328	78/11/17	50-336	Q	7	812010046	7812010039	78/11/21	50-471	Ğ
7811270339 7811270341	7811290328 7811290337	70/11/17 78/11/14	50-336 50-443	0 5		B12010050 B12010057	7812010039 7812010039	78/11/21 78/11/21	50-471 50-471	G
7811290344	7811270337	78/11/14	50-443	8		812010059	7812010039	78/11/21	50-471	å
7811290358	7811290346	78/11/03	50-400	0	7	812010062	7812010047	78/10/23	50-285	a
7811290366	7811270346	78/11/03	50-400	ö		812010070	7812010045	78/09/29	50-305	ů
7811290389 7811290397	7811270387	78/10/13	50-272	0		812010076	7812010033	78/11/09	50-286	g
7811300004	7811290393 7811300003	78/10/23 78/11/17	50-123 50-335	0		B120100B1	7812010033 7812010033	78/11/09 78/11/09	50-284 50-284	0
7811300010	7811300003	78/11/17	50-335	a	7	812010089	7812010033	78/11/09	50-286	G
7811300011	7811300007	78/11/17	50-329	A		815010035	7812010033	78/11/09	50-286	o o
7811300013	7811300003	78/11/17	50-335	g .		812010073	7812010090	78/11/17	50-309	Q
7811300019 7811300020	7811300007 7811300017	78/11/17 78/11/16	50-329 50-445	A Q		'812010096 '812010097	7812010033 7812010090	78/11/09 78/11/17	50-286 50-309	O O
					7	2015010000	7017010000	70/11/12	50-700	
7811300023 7811300055	7811300007 7811300063	78/11/17 78/11/24	50-329 50-133	á		.615010103 .615010044	7812010090 7812010090	78/11/17 78/11/17	50-309 50-309	0
7811300064	7811300058	78/11/19	50-237	P		812010104	7812010100	78/11/15	50-250	Q
7811300057 7811300070	7811300058 7811300058	78/11/13 78/11/13	50-237 50-237	P P		812010107 812010111	7812010100 7812010108	78/11/13 78/10/19	50-250 50-29	G G
					7	01.7010118	7812010116	78/11/14	50-250	G
7811300073 7811300077	7811300058 7811300058	78/11/13 78/11/13	50-237 50-237	ь Б		B12010117 B12010126	7812010116	78/11/16 78/10/27	50-235	ā
7011300005	7811300058	78/11/13	50-237	P	7	812010128	7812010125	78/10/16	50-250	Q.
7611300102 7611300102	7811300100	78/10/30 78/11/17	50-338 50-445	A Q		815010131 815010154	7812010124 7812010130	78/10/27 78/11/20	50-235 50-219	0
	7811300105	/8/11/1/		_				78/11/20	50-219	a
7811300117 7811300138	7811300114 7811300135	78/11/20 78/10/26	50-255 50-155	G G	ź	812010132 812010134	7812010130 7812010130	78/11/20	50-219	Ö
7811300136	7811300135	78/10/26	50-155	ŏ	,	812010136	7812010130	78/11/20	30-219	G
7811300167	7811300165	78/11/02	50~400 50~400	0		812010150 812010168	7612010147 7612010162	78/10/18 78/11/14	50-244 50-369	G A
7011300170	7811300165	78/11/02						70/10/20	50-160	G
7811300174 7811300181	7811300172	78/11/22 78/11/22	50-270 50-314	8 8		B12010182	7812010175 7812010207	78/10/20 78/11/27	50-346	8
7811300185	7811300177 7811300177	78/11/22	50-316	8			7812010214	78/11/27	50-309 50-416	G.
7811300188	7B11300177	78/11/22	30-316	8		B12010227 B12010240	7812010223 7812010238	78/11/30 78/11/25	50-285	8
7811300190	7811300184	78/11/17	50-335	8			7812010244	78/11/27	50-269	8
7811300193	7811300177	7B/11/22	50-316	8			7812010244 7812010246	78/11/27 78/11/24	90-302	8
7811300199 7811300205	7811300176 7811300203	78/11/17 78/11/22	50-317 50-391	8 K	7:	812010249	7812010248	78/11/15	50-447	A K
7811300213	7811300203 7811300209	78/11/20	30-361	0			7812010251 7812010253	79/11/27 78/11/27	50-329 50-348	8
7811300218	7811300215	78/11/14	50-433	J						
7811300220	7811300217	78/11/22	50-277	0			7812010264 7812010266	78/11/29 78/10/26	50-338 50-327	Я 9
7811300221 7811300223	7811300228 7811300211	78/09/29 78/11/24	50-358 50-318	Q 8	71	B12010274	7812010272	78/10/20	50-245	0
7811300243	7811300241	78/11/03	50-334	9		812010276 812010278	7812010275 7812010277	78/10/23 78/10/10	50-219 50-29	o o
7811300246	7811300241	78/11/03	50-334	a	•			-		

ACCEBBION NU						ACCERSION				
ENGLOGURE I	TINCIPAL DOSUMENT	DATE (SSUED	SUBJECT CATEGORY	Y		NCLOBURE	PRINCIPAL DOCUMENT	DATE 03V281	BUBJECT CATEGORY	,
7812010292 78 7812010296 78 7812010295 76 7812010296 76	812010280 812010284 812010291 812010291	78/10/18 78/10/23 78/11/06 78/11/06	50-320 50-409 50-317 50-317	0 0 0 0	7 7 7 7	812050016 812050017 812050018 812050019 812050020	7812050012 7812050003 7812050008 7812050012 7812050012	78/11/18 78/11/16 78/11/16 78/11/24 78/11/18 78/11/16	50-259 50-348 50-259	P P P P
7812010335 76 7812010336 76 7812010347 76	B12010331 B12010336 812010344	78/11/04 78/11/22 78/10/20 78/11/14 78/11/14	50-317 50-368 50-320 50-312 50-312	Q Q F F	7 7 7	7812050022 7812050023 7812050025 7812050026 7812050027	7812050003 7812050003 7812050021 7812050003 7812050011	78/11/16 78/11/16 78/11/20 78/11/16 78/10/30	50-259 50-259 50-259 50-259 50-10	P 0 P 0
7812010374 76 7812010377 76 7812010380 78	812010370 812010370 812010370	78/11/14 78/11/13 78/11/13 78/11/13 78/11/13	50-312 50-313 50-313 50-313 50-313	6 6 6	7 7 7	7812050029 7812050030 7812050031 7812050044 7812050081	7812030021 7812030021 7812030021 7812030043 7812030047	78/11/20 78/11/20 78/11/20 78/11/27 78/11/09	50~269 50~269 50~269 50~213 50~295	0 0 0 0
7812040017 78 7812040019 76 7812040020 76	B12040007 B12040014 B12040007	78/11/17 78/11/17 78/11/20 78/11/17 78/10/25	50-206 50-206 50-556 50-206 50-452	P T P G	7 7 7	7812050057 7812050058 7812050067 7812050070 7812050072	7812030033 7812030033 7812030063 7812030063 7812030063	78/10/27 78/11/09 78/11/24 78/11/24 78/11/24	50~259 50~356 50~302 50~302 50~302	9 9 9
7812040038 71 7812040046 71 7812040035 71	B12040033 B12040033 B12040049	78/11/20 78/10/31 78/10/31 78/11/21 78/11/21	50-344 50-234 50-234 50-390 50-390	0 0 0	7 7 7	7812050074 7812050094 7812050097 7812050117 7812050125	7812050063 7812050092 7812050092 7812050111 7812050111	78/11/24 78/11/17 78/11/17 78/11/21 78/11/21	50-302 50-329 50-329 50-327 50-327	Q A Q Q
7612040066 71 7612040074 71 7612040079 73	812040049 812040071 812040071	78/11/21 78/11/21 78/11/16 78/11/16 78/11/15	50-390 50-390 50-148 50-148 50-397	0 0 P P	7 7 7	7612050133 7612050138 7612050140 7612050145 7612050147	7812050131 7812050135 7812050111 7812050144 7812050111	78/11/24 78/10/13 78/11/21 78/11/13 78/11/21	50-335 50-298 50-327 50-298 50-327	8 9 8
7812040137 7 7812040144 7 7812040159 7	812040122 812040133 812040141 812040156 812040160	78/11/16 78/11/07 78/11/09 78/11/28 78/10/26	50-498 50-549 50-305 50-333 50-546	0 0 8 0	7	7812030150 7812030161 7812030162 7812030164 7812030165	7812050111 7812050153 7812050157 7812050160 7812050158	78/11/21 78/11/28 78/11/28 78/11/28 78/10/23	50-327 50-336 50-346 50-213 50-327	0 8 9
7012040174 7 7812040175 7 7812040176 7	812040167 812040172 812040167 812040173 812040172	78/11/13 78/06/12 78/11/13 78/11/27 78/06/12	50-395 50-255 50-395 50-293 50-255	0 0 0 0		7812050170 7812050172 7812050175 7812050179 7812050181	7812050166 7812050169 7812050167 7812050173 7812050176	78/10/25 78/11/30 78/11/30 78/11/37	50-298 50-295 50-255 50-251	8 8 8 8
7812040199 7 7812040195 7 7812040197 7	812040180 812040187 812040191 912040192 812040201	78/10/18 78/11/24 78/11/17 78/10/20 78/11/30	50-395 50-250 50-237 50-327 50-454	8 8 0		7812050190 7812050192 7812050198 7812050201 7812050203	7812050184 7812050185 7812050195 7812050199 7812050200	78/12/04 78/11/29 78/11/27 78/11/27 78/12/04	50-367 50-293 50-335 50-296 50-446	A 8 8 8
7812040210 7 7812040211 7 7812040213 7	812040201 812040208 812040209 812040209 812040212	78/11/30 78/11/30 78/11/29 78/11/29 78/11/30	50-454 50-454 50-338 50-338 50-456	C 8 C		7812050206 7812050209 7 <i>812050211</i> 7812050214 7812050218	7812030204 7812050208 7812050208 7812050208 7812050217	78/11/28 78/11/30 78/11/30 78/11/30 78/11/28	50-346 50-280 50-280 50-280 50-346	6 9 5 5
7812040217 7 7812040219 7 7812040222 7	7812040209 7812040209 7812040216 7812040221 7812040224	78/11/29 78/11/29 78/11/27 78/11/20 78/11/16	50-338 50-338 50-409 50-251 50-272	9 8 6 F		7812050221 7812050226 7812050238 7812050241 7812050242	7812050220 7813050223 7813050236 7813050236 7813050240	78/11/30 78/11/30 78/10/19 78/10/19 78/11/16	50-447 50-338 50-456 50-456 50-250	A 9 0 0
7812040233 7 7812040239 7 7812040241 7	7812040226 7812040230 7812040237 7812040237 7812040243	78/10/27 78/11/29 78/11/29 78/11/29 78/11/17	30-390 50-280 50-155 50-155 50-89	8 13 8 8 P		7812030246 7812050249 7812050251 7812050252 7812050268	7812030240 7812030240 7812030243 7812030243 7812030266	78/11/16 78/11/16 78/11/30 78/11/09 78/11/09	50-250 50-250 50-259 50-305 50-390	9 9 9 8
7812040288 7 7812040302 7 7812040324 7	7812040277 7812040285 7812040301 7812040321 7812040322	78/09/22 78/11/09 78/11/27 78/11/15 78/10/23	50-413 50-305 50-466 50-275 50-260	8 0 0		7812050270 7812050280 7812050284 7812050285 7812050289	7812050265 7812050276 7812050283 7812050281 7812050283	78/11/03 78/11/30 78/11/24 78/11/07 78/11/24	50-327 50-537 50-437 50-556 50-437	8 A •
7812040328 7 7812040330 7 7812040332 7	7812040321 7812040326 7812040321 7812040326 7812040321	78/11/15 78/11/22 78/11/15 78/11/22 78/11/15	50~275 50~269 50~275 50~269 50~275	9		7812050270 7812050273 7812050275 7812050277 7812050278	7812030286 7812030283 7812030286 7812030286 7812030286	78/11/07 78/11/24 78/11/07 78/11/24 78/11/07	50-97 50-437 50-97 50-437 50-97	Q A Q G
7812040308 7 7812040339 7 7812050002 7	7812040326 7812040321 7812040326 7812030001 7812030001	78/11/R2 78/11/15 78/11/R2 78/10/27 78/10/27	50-269 50-275 50-269 50-13 50-13	9		7812030301 7812030304 7812030304 7812030307 7812030343	7812050263 7812050286 7812050286 7812050303 7812050336	78/11/24 78/11/07 78/11/07 78/10/24 78/11/16	50-437 50-97 50-97 50-327 50-333	А 9 0 Р
7812050010 7 7812050013 7 7812050014 7	7812030003 7812030008 7812030004 7812030008 7812030008	78/11/16 78/11/24 77/12/13 76/11/24 78/11/24	50~259 50~348 50~3 50~348 50~348	9		7812050348 7812050351 7812050354 7812050356 7812050372	7812050336 7812050336 7812050350 7812050350 7812050370	78/11/16 78/11/16 78/11/08 78/11/08 78/11/13	50-333 50-333 50-549 50-549 50-341	P T T

### CROSS REFERENCE OF ENCLOSURES TO PRINCIPAL DOCUMENTS

ACCE8810	NUMBER					N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188VED	SUBJECT CATEODE		ENCLOBURE	PRINCIPAL DOCUMENT	DATE ISSUED	SUBJEC	
7812060009 7812060013	7812040003 7812040003	78/11/16	50-321 50-321	P	7812070063	7812070056	78/11/15	50-275	E
7812060021 7812060026	7812060015 7812060015	78/11/28 78/11/28	50-259 50-259	G G	7812070065 7812070067 7812070069	7812070059 7812070056	78/11/28	30-261 30-275	E
7812060028	7812060025	78/11/29	50-395	Ğ	7812070071	7812070059 7812070059	78/11/28 78/11/28	50-261 50-261	o o
7812060029 7812060000	7812060025 7812060015	78/11/29 78/11/28	50-395 50-2 <b>5</b> 9	0	7812070075 7812070078	7812070059 7812070074	78/11/28 78/10/30	50-261 50-263	0
7812060032 7812060033	7812060025 7812060015	78/11/29 78/11/28	50-395 50-259	g G	7812070097 7812070108	7812070082 7812070105	78/11/20 78/11/03	50-321 50-456	ā O
7812060003	7812040023	78/11/29	50-395	Q	7812070113	7812070110	78/11/21	20-355	8
7612060048 7812060052	7812060044 7812060049	78/11/21 78/11/29	50-298 50-298	0	7912070116 7812070148	7812070111 7812070082	78/11/30 78/11/20	50-445 50-321	K. Q
7812060067 7812060070	7812060064 7812060064	78/11/03 78/11/03	50~329 50~329	a	7812070162 7812070168	7812070103 781207016 <b>5</b>	78/11/30 78/11/30	50-556 50-325	i.
7812060074 7812060077	7812060065	78/11/30 78/11/03	50-327	G G	7812070178	7812070174	78/12/05	80-333	8
7812060112 7812060117	7812060072 781206010B	78/11/03 78/10/30 78/11/16	50-409 50-483 50-321	G P	7812070181 7812070182	7812070175 7812070180	78/11/30 78/12/03	50-324 50-3	8
7812060128 7812060129	7812060124 7812060121	78/10/27 78/11/08	50-305 50-327	G B	7819070188 7819070190 7819070193	7812070187 7812070189	78/11/28 78/12/04	50-400 50-338	8 8
7812060142	7812060134	79/11/22	50-338	8	7812070179	7812070193 7812070196	78/12/04 78/11/29	50-338 50-346	8
7812060137 7812060172	7812060155 7812060126	78/11/29 78/11/13	50~437 50~329	Ā	7812070201 7812070204	7812070198 7812070202	78/11/30 78/11/21	50-346 50-284	9 P
7812060177 7812060178	7812060171 7812060174	78/11/28 78/10/31	50-320 50-266	8	7812070206 7812070213	7812070203 7812070210	78/12/04 78/11/29	50-320 50-277	8
7812060185	7812060180	78/11/24	50-20	Q	7812070217	7812070214	78/11/28	30-325	8
7612060194 7612060203	7812060180 7812060190	78/11/Q4 78/11/24	50~20 50~20	G G	7812070220 7812070222	7812070218 7812070221	78/12/01 78/12/01	50-219 50-263	8 P
7812060211 7812060219	7812060207 7812060160	78/11/27 78/11/24	50~368 50~20	G G	7812070230 7812070231	7812070223 7812070228	78/12/01 78/11/20	50-440 50-344	8
7812060220	7812040216	78/10/30	50-336	н	7812070237	7812070227	78/11/20	30-275	т
7812040230	7812040224 7812040225	78/10/23 78/10/31	50-338 50-254	a	7812070242 7812070246	7812070027 7812070238	78/11/20 78/10/27	50-275 50-361	Œ
7612060234 7812060236	7812060231 7812060231	78/10/31 78/10/31	50-295 50-295	a Q	7812070299 7812070289	7812070250 7812070284	78/11/17 78/11/16	50-390 50-219	8 0
7812060244 7812060262	7812060242 7812060238	78/11/25 78/10/23	50-317 50-280	g	7812070290 7812070291	7812070264	78/11/16	50-219	0
7812060272 7812060274	7812060256 7812060260	78/11/R4 78/10/31	50-269 50-327	9 0	7812070275 7812070295 7812070296	7812070264 7812070264 7812070283	78/11/16 78/11/16 78/11/08	30-219 30-219 30-206	G
7812060282	7812060278	78/11/29	50~285	õ	7812070309	7812070301	78/10/30	30-261	G
7812060286 7812060291	7812060275 7812060287	78/10/13 78/10/31	50-184 50-327	ō.	7812070312 7812070315	7812070301 7812070313	78/10/30 78/11/03	145-00 <b>9</b> 46-00	0
7812060293 7812060300	7812060288 7812060286	78/11/01 78/10/13	50-261 50-164	0	7612070319 7612070320	7812070317 7812070317	78/11/28 78/11/28	50-269 50-269	ā
7812060302	7812060296	78/11/28	50-466	٨	7812080010	7812080006	78/11/03	20-580	G
7812060304 7812060307	7812060298 7812060299	78/10/27 78/10/20	50-244 50-534	g Q	7818080015 7818080083	7812080007 7812080013	78/12/01 78/11/18	465-06 846-08	P
7812060308 7812060316	7812060286 7812060286	78/10/13 78/10/13	50-184 50-184	9	7812080085 7812080029	7612080013 7612080013	78/11/10 78/11/10	50-368 - 50-349	P
7812060319	7812040311	78/11/20	50-148	q	7912080043	7812080039	78/12/01	80-272	P
7812060326 7812060329 7812060331	7812060324 7812060320	78/10/13 78/11/21	50-148 50-269	Q G F	7619089059 7619080059 7619080067	7812080046 7812080046	78/11/02 78/11/02	50-519 50-519 30-358	0
7812060331 7812060332 7812060333	7812040327 7812040324	78/11/R4 78/10/13	50~367 50~148 50~269	0	7812080068 7812080070	7612080065 7612080061 7812080061	78/11/09 78/19/01 78/19/01	50-316 50-316	6
7812060335	7812060320 7812060334	78/11/21 78/11/01	50-338	9	. 7819080083	7812080080	78/11/02	50-334	G.
7812060339 7812060340	7812060338 7812060337	78/10/20 78/06/27	50-445 50-331	ğ	78120 80087 78120 80089	7812080075 7812080084	78/19/01 78/19/04	50-315 30-316	6
7812060341 7812060342	7812060335 7812060338	78/10/25 78/10/20	50-445 50-445	ā	7812080103 7812080111	7812080101 7812080109	78/19/04 78/19/05	50-260 50-277	e R
7812060345	7812060343	78/11/27	20-321	œ	7812080112	7819080109	79/19/05	80-277	R
7812060346 7812060349	7812060344 7812060348	78/10/25 78/10/31	50-271 50-285	0	7812080115 78120 <b>8</b> 0118	7812080113 7812080117	78/11/06 78/11/30	50-272 50-245	8
7812060350 7812060351	7812060343 7812060348	78/11/27 78/10/31	50-321 50-285	Q Q	7812080120 7812080122	7812080119 7812080119	78/19/05 78/19/06	50-316 50-316	8
7812060355	7812060353	78/10/25	50-311	9	7818080129 7818080130	7612080124 7612080127	78/12/01 78/12/01	50-245 50-325	8
7812060357 7812060358	7812060356 7812060352	78/11/22 78/11/03	50-389 50-454	9	7818080136 7818080136	7812080134 7812080138	78/11/80 78/12/06	50-372 50-304	R
7612060362 7812060367	7812060336 7812060363	78/11/22 78/10/27	50-389 50-333	ā	7812080140	7812080137	78/11/29	30-409	P
7812060381 7812060391	7812060376 7812060388	78/11/30 78/10/24	50-361 50-315	A	7819080149 7819080145	7812080135 7812080144	78/12/06 78/11/03	50-306 50-334	P
7812070002 7812070022	7812070001 7812070019	78/11/20 78/11/28	50-128 50-364	ã	7818080147 7818080186	7812080144 7812080048	78/11/03 78/11/17	80-334 80-344	0
7812070023	7812070016	78/10/27	50-518	G	7812080170	7812080168	78/11/22	50-333	P
7812070024 7812070024	7812070019 7812070019	78/11/26 78/11/26	50-364 50-364	g g	7812080173 7812080176	7812080168 7812080168	78/11/22 78/11/22	50-333 50-333	b b
7812070030 7812070045	7812070019 7812070041	78/11/28 78/10/31	50-364 50-106	9	7812080190 7812080193 7812080193	7812080188 7812080188	78/12/01 78/12/01	90-305 50-305	P
7812070054	7812070052	78/11/28	50- <b>37</b> 3	۸	7812080205	7812080202	78/11/21	50-546	A

ACCE9610N	NUMBER				POT ES 3 D D A	NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 186060	BUBJECT Categor		ENCLOSURE	PRINCIPAL DOCUMENT	DATE 158UED	BUBJECT CATEGOR	
7812080211 7812080219 7812080221 7812080238 7812110033	7812080210 7812080215 7812080213 7812080237 7812110031	78/11/28 78/10/30 78/11/02 78/10/31 78/11/29	50-302 50-13 50-518 50-326 50-566	U G B Q A	7812120082 7812120087 7812120087 7812120094 7812120093	7812120080 7812120085 7812120095 7812120095 7812120102	78/12/06 78/12/09 78/12/08 78/12/07 78/12/07	50-233 50-264 50-262 50-253 50-220	P R R R R
7812110036 7812110042 7812110057 7812110069 7812110072	7812110031 7812110031 7812110034 7812110068 7812110070	78/11/29 78/11/29 78/11/22 78/12/01 78/11/30	50-566 50-566 50-498 50-522 50-437	A 0 0 0	7812120110 7812120111 7812120112 7812120113 7812120118	7812120093 7812120104 7812120109 7812120108 7812120093	78/11/30 78/12/07 78/12/05 78/12/06 78/11/30	50-518 50-329 50-155 50-336 50-518	A R B A
7812110074 7812110097 7812110116 7812110125 7812110129	7812110070 7812110093 7812110122 7812110122 7812110124	78/11/30 78/11/22 78/12/04 78/12/04 78/11/17	50-437 50-219 50-447 50-255 50-295	9 A R 8	7812120121 7812120124 7812120125 7812120127 7812120128	7812120115 7812120093 7812120119 7812120123 7812120093	78/12/05 78/11/30 78/12/06 78/12/07 78/11/30	50-295 50-318 50-250 50-219 50-318	8 F 8 A
7812110132 7812110138 7812110139 7812110140 7812110143	7812110128 7812110134 7812110135 7812110136 7812110135	78/12/06 76/12/04 76/11/24 76/12/09 76/11/24	50-334 50-348 50-29 50-263 50-29	R B P R P	7812120129 7812120132 7812120134 7812120134 7812120137	7812120116 7812120126 7812120130 7812120133 7812120131	78/12/07 78/12/06 78/11/30 78/12/05 78/11/30	50-336 50-409 50-249 50-219 50-313	9 R 8 8
7812110145 7812110147 7812110154 7812110158 7812110159	7612110135 7612110144 7812110151 7612110156 7812110157	78/11/24 78/11/17 78/11/20 78/12/04 78/11/17	50-29 50-295 50-295 50-409 50-295	8 8 8	7812120139 7812120141 7812120142 7812120146 7812120148	7812120093 7812120135 7812120136 7812120140 7812120143	78/11/30 78/12/05 78/12/07 78/12/07 78/12/06	50-518 50-293 50-313 50-346 50-334	A 8 8 8
7812110163 7812110164 7812110167 7812110172 7812110173	7812110161 7812110160 7812110165 7812110169 7812110170	78/11/17 78/11/22 78/11/30 78/12/04 78/12/04	50-295 50-295 50-409 50-344 50-312	8 6 8 8	7812120152 7812120153 7812120157 7812120157 7812120157	7812120074 7812120149 7812120162 7812120165 7812120174	78/12/07 78/12/05 78/12/07 78/12/06 78/12/07	50-470 50-344 50-315 50-346 50-260	K R 8 9
7812110174 7812110177 7812110176 7812110180 7812110182	7812110171 7812110169 7812110176 7812110175 7812110179	78/12/06 78/12/04 78/11/21 78/11/20 78/11/22	50-155 50-344 50-254 50-295 50-295	98878	7812120181 7812120186 7812120206 78121202231	7812120172 7812120178 7812120200 7812120216 7812120225	78/12/07 78/12/07 78/12/05 78/11/09 78/11/06	50-346 50-316 50-395 50-331 50-305	8 R G
7812110183 7812110192 7812110196 7812110208 7812110210	7812110181 7812110191 7812110193 7812110204 7812110206	78/11/15 78/12/07 78/12/07 78/12/06 78/12/06	50-254 50-336 50-336 50-338 50-255	8 8 8	761 21 20 23 5 761 21 20 23 7 761 21 20 24 5 761 21 20 24 6 761 21 20 24 6	7812120232 7812120232 7812120236 7812120241 7812120241	78/10/17 78/10/17 78/12/04 78/10/17 78/10/17	50-250 50-250 50-250 50-363 50-363	0 0 0
7812110225 7812110230 7812110235 7812110235 7812110240	7812110222 7812110220 7812110232 7812110237 7812110237	78/11/02 78/11/14 78/11/01 78/10/24 78/10/24	50-280 50-392 50-334 50-361 50-361	0 0 0 0	7812130004 7812130005 7812130008 7812130008 7812130044	7812130001 7812130001 7812130002 7812130035 7812130038	78/11/01 78/11/01 78/12/03 78/11/09 78/11/16	50-327 50-327 50-133 50-315 50-566	900
7812110251 7612110268 7612110271 7612110273 7812110274	7612110246 7612110264 7812110264 7812110264 7812110272	78/11/03 78/11/30 78/11/30 78/11/30 78/10/17	50-324 50-462 50-462 50-462 50-277	G A A A	7812130049 7812130069 7812130072 7812130084	7812130035 7812130061 7812130070 7812130071 7812130080	78/11/09 78/11/21 78/11/24 78/10/16 78/11/21	50-315 50-549 50-471 50-352 50-502	9999
7612110276 7612110277 7612110279 7612110292 7612110297	7812110264 7812110272 7812110264 7812110264 7812110295	78/11/30 78/10/17 78/11/30 78/11/30 78/11/02	50~482 50~277 50~482 50~482 50~336	A A 0	7812130087 7812130092 7812130098 7812130103 7812130103	7812130090 7812130071 7813130071 7812130071 7812130071	78/11/21 78/10/16 78/10/16 78/10/16 78/10/16	50-352 50-352 50-352 50-352	00000
7612110301 7812110305 7812110309 7612110310 7812110313	7812110295 7812110303 7812110307 7812110303 7812110307	78/11/02 78/10/27 78/11/30 78/10/27 78/11/30	50-334 50-245 50-364 50-245 50-364	9	7812130106 7812130112 7812130134 7812130140 7812130141	7812130096 7812130071 7812130129 7812130136 7812130135	78/11/25 78/10/16 78/11/09 78/12/08 78/12/06	50~344 50~352 50~331 50~331 50~267	0 0 0 0
7612110316 7612110320 7612110322 7612110323 7612110329	7812110314 7812110319 7812110319 7812110319 7812110326	78/10/23 78/11/22 78/11/22 78/11/22 78/11/30	50-245 50-333 50-333 50-333 50-219	0 P P P	7812130145 7812130160 7812130167 7812130177 7812130172	7812130136 7812130158 7812130163 7812130166 7812130167	78/12/08 78/12/06 78/12/04 78/12/06 78/12/07	50-331 50-298 50-267 50-286 50-267	P R G S
7812120017 7812120018 7812120020 7812120024 7812120026	7812120014 7812120014 7812120014 7812120022 7812120022	78/11/30 78/11/30 78/11/30 78/10/17 78/10/17	50-424 50-424 50-424 50-322 50-322	0	7812130174 7812130179 7812130181 7812130183 7812130186	7812130170 7812130176 7812130178 7812130176 7812130184	78/12/07 78/12/07 78/12/08 78/12/07 78/12/08	50-318 50-267 50-285 50-267 50-10	8 R 8 R
7812120030 7812120032 7812120033 7812120034 7812120035	7612120027 7612120027 7612120029 7612120027 7812120027	78/12/04 78/12/04 78/11/27 78/12/04 78/12/04	30-445 30-445 50-395 50-445 50-445	A G A A	7812130187 7812130192 7812130194 7812130197 7812130200	7812130183 7812130190 7812130189 7812130195 7812130149	78/12/07 78/12/06 78/12/07 78/12/04 78/11/22	50-318 50-267 50-317 50-320 50-263	8 8 9 P
7812120036 7812120041 7812120042 7812120044 7812120049	7812120027 7812120036 7812120038 7812120038 7812120029	78/12/04 78/12/04 78/12/04 78/12/04 78/11/27	50-445 50-580 50-580 50-580 50-393	А Н Н	7812130202 7812130207 7812130209 7812130210 7812130210	7812130191 7812130177 7812130206 7812130177 7812130241	78/12/04 78/12/08 78/11/09 78/12/08 78/12/07	50~341 50~361 50~315 50~361 50~261	9 4 9

## PRINCIPAL DOCUMENTS

ACCE8830A					ACCESSION NUMB	ER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 199UED	SUBJEC.			CIPAL UMENT	DATE 1980ED	SUBJECT CATEGOR	
7612130286	7812130201	78/12/01	50-155	P	7612140275 7812	140273	79/12/07	50-275	
7812130299 7812130295 7812130296	7812130287 7812130287	78/12/04 78/12/04	50-491 50-491	0	7812140278 7812	140195 140273	78/12/01 78/12/07	50~335 50~275	0
7812130298	7812130294 7812130287	78/12/07 78/12/04	50-324 50-491	9		140273 140273	79/12/07 78/12/07	50-275 50-275	0
7812130300 7812130304	7812130294 7812130294	78/12/07 78/12/07	50-324 50-324	0		140286	78/11/29 78/11/29	80-327	8
7812130310 7812130311	7812130294 7812130306	78/12/07 78/12/05	50~324 50~269	g g	7812140304 7812	140297 140292	78/11/30	50-70 50-206	H P P
7812130314	7812130301	78/11/17	50-275	Ğ		1 40292 1 40299	78/11/30 78/12/07	90-509 90-509	P
7812130317 7812130319	7812130306 7812130316	78/12/05 78/11/15	50-269 50-344	g 0		140316 140325	78/11/27 78/11/16	50-245 50-437	P H
7912130321 7812130324	7812130309 7812130316	78/12/07 78/11/13	50-313 50-344	0	7812140339 7812	140316	78/11/27 78/11/13	50-245 50-266	P H
7912130327	7812130309	78/12/07	50-313	q		150001	78/11/16	50-275	0
7812130332 7812130336	7812130309 7812130309	78/12/07 78/12/07	50-313 50~313	Q.	7812100063 7812	150030 150057	78/11/07 78/11/07	50-327 50-261	g G
7812130338 7812130342	7812130331	7B/11/09 7B/12/01	50-295 50-187	G.	7812150082 78121	150072 150072	78/12/04 78/12/04	50-245 50-245	P
7812130345	7812130334	78/11/24	50-219	p -			78/12/04	50-245	Р
7812130346 7812130347	7812130331 7812130331	78/12/01 78/12/01	50-187 50-187	0	7912150117 7812	50107	78/12/05 78/12/05	50-285 50-285	P
7812130350 7812130351 7812130353	7812130331 7812130334	78/12/01 78/11/24	50-187 50-219	Q P	7812150185 7812:	150107 1501B0	78/12/05 78/11/03	20-507 20-582	e g
7812130353	7812130334 7812130363	78/11/24 78/12/05	50-219 50-344	P P		150192	78/11/06	50-390	a E
7812130373 7812130376	7812130363 7812130363	78/12/05 78/12/05	50-344 50-344	P P	7812150240 7812	150232 150214 150237	78/12/11 78/11/01 78/12/11	50-305 50-245 50-266	8 3 R
7812130380 7812130385	7812130363 7812130363	78/12/05 78/12/05	50-344 50-344	Р	7812130244 7812	150242 150261	78/12/11 78/12/12	50-272 50-255	R 9
7B12130397	7812130343	78/12/05	50-344	P		150264	78/12/11	50-445	c
7812130390 7812140012	7812130389 7812140010	78/12/06 78/10/31	50-275 50-263	A	7812130269 78121	150259 150270	78/11/15 78/12/09	50-443 50-237	Č B
7812140014 7812140016	7812140013 7812140010	78/12/01 78/10/31	50-368 50-263	P G	7812150273 7812	150259 150267	78/11/15 78/12/09	50-443 50-333	Q R
7812140017	7812140013	78/12/01	50-368	P	7012150293 7.8129	150259	78/11/15	50-443	0
7812140020 7812140027	7812140013 7812140024	78/12/01 78/12/01	30-348 30-245	þ	7812150292 78121	150286 150270	78/12/11 78/12/11	50-27 I	R R
7812140026 7812140030	7812140021 7812140024	78/10/27 78/12/01	50-329 50-245	Ģ P		150297 150296	78/12/07 78/12/08	50-321 50-344	R A
7812140034	7812140024	78/12/01	30-245	Р Р		50301	78/12/11	50-336	R R
7812140039 7812140039 7812140042	7812140033 7812140037	78/11/28 78/11/14	\$0-213 \$0-312	Q. P	7819150339 7819	150310 150330	78/12/08 78/12/11 78/12/01	50~133 50~324 50~400	R
7812140046	7812140040 7812140041	78/11/27 78/12/05	50-29 50-269	ā		150343 150334	78/12/07	50-366	Ř
7812140048 7812140055	7812140041 7812140053	78/12/05 78/12/05	50-269 50-269	g g		150348 150355	78/12/11 78/12/11	50-261 50-309	R R
7812140059 7812140066	7812140053 7812140063	78/12/03 78/11/08	50-269 50-331	ä	7812180037 7812	180027	78/11/30 78/11/22	50-275 50-289	P
7812140069	7812140065	78/10/27	50-97	P		80045	78/11/22	50-289	P
7812140072 7812140086	7812140070 7812140081	78/10/31 78/12/01	50-70 50-10	9	7812190058 7812.	180043 180057	78/11/22 78/11/03	50-287 50-3	9
7812140098 7812140114	7812140095 7812140108	78/11/28 78/12/06	50-20 50-400	P 0	7812180075 78121	180060 180072	78/11/29 78/11/27	20-13	P
7812140118	7812140117	78/12/05	50-348	a		180076	79/11/28	50-182 50-285	P P
7812140119 7812140122	7812140117 7812140117	78/12/05 78/12/05	50-348 50-348	0	7812180092 7812	180072 180078	78/11/27 78/11/03 78/11/27	50-265 50-285	e P
7812140126 7812140129 7812140131	7812140125 7812140125	78/12/12 78/12/12	80-280 80-280 50-280	8 8	7812180086 78121	180076 180104	78/11/28 78/11/30	50-182 50-277	P P
7812140131	7812140125 7812140130	78/12/12 78/11/09	50-329	0		180104	79/11/30	50-277	P
7812140140 7812140147	7812140137 7812140141	78/12/09 78/11/13	50-346 50-266	8	7912180100 7812	180104 180104	79/11/30 79/11/30	50-277 50-277	P P
7812140152 7812140154	7812140146 7812140149	78/12/08 78/12/08	50-251 50-220	P B	7812180141 7812	180138 180145	78/12/11 78/12/08	50-250 50-249	3 8
7812140156	7812140151	78/11/07	50-280	G.	7812180151 7812.	180142	78/12/13	50-213	J
7812140157 7812140160	7812140153 7812140158	78/12/06 78/11/11	50-252 50-325	8	7812180157 7812	160150 160154	79/12/11 79/12/12	50-302 50-277	B
7812140161 7812140164	7812140159 7812140155	78/12/12 78/12/07	50-304 50-368	8 6		160153 160162	78/11/29 78/12/01	50-363 50-366	8
7812140165	7812140163	78/11/11	50-261	В		180165	78/12/08	50-321	9
7812140169 7812140181	7812140167 7812140177	78/12/11 78/12/12	50-272 50-443	8	7812160172 7812	160164 160168 160173	78/11/20 78/12/09 78/07/24	50-321 50-293 50-271	8
7819140229 7819140234	7812140224 7812140224	78/12/12 78/12/12	50-281 50-281	8		100174	78/12/08	50-10	8
7812140246 7812140257	7812140244 7812140255	78/11/14 78/12/01	50-445 50-406	M G		180178 180179	78/12/07 78/12/10	30-249 30-366	6 0
7812140263 7812140265	7812140252 7812140252 7812140195	78/12/07 78/12/01	50-364 50-335	ă	7812180184 7812	180180 180182	78/12/08 78/11/22	50-334 50-366	9 8
7812140270	7812140175	78/12/01	90-335	ŏ		180190	78/07/25	50-271	9

	PRINCIPAL	DATË	gusjec1			~	PRINCIPAL	DATE	SUBJECT	
ENCLOSURE	BOCUMENT	188060	CATEGOR	Υ .		CLOSURE	DOCUMENT	1880ED	CATEOOR	
7812160176 7812180177	7812180188 7812180193	78/12/05 78/07/24	50-270 50-271	9			7812200103 7812200133	78/11/17 78/12/15	50-382 50-263	O A
7812180202 7812180205	7812180198 7812180201	78/12/07 78/11/28	50-366 50-366	8	76:	12200161	7 812200156 7 812200156	78/12/08 78/12/08	50-13 50-13	0
7812190208	7812180204	78/12/13	50-219	8	78.	12200165	7819200163	78/12/15	50-348	8
7812180212 7812180216	7812180207 7812180213	78/12/12 78/07/24	50-316 50-271	8		12200174 12200177	7812200173 7812200175	78/12/14 78/11/01	50-315 50-458	R A
7812180217 7812180218	7912180214 7812180210	78/12/11 78/12/12	50-10 50-266	8		12200179 12200181	7812200176 7812200178	78/12/11 78/12/11	50-302 50-302	e S
7812180222	7812180219	76/12/13	50-271	\$	78	15500165	7812200180	78/12/14	50-219	R
7812180225 7812180228	7812180220 7812180223	78/12/08 78/12/08	50-366 50-237	9 9		12200186 12200185	7812200183 7812200184	78/12/01 78/12/15	50-293 50-445	R A
7812180232 7812180234	7812180226 7812180231	78/12/06 78/11/22	50-395 30-366	F		12200195 12200197	7812200193 7812200194	76/12/13 78/12/12	50-247 50-312	8 R
7812180239	7812190236	78/11/30	50-295	P		12200199	781220019B	78/12/13	50-324	8
7812180240 7812180241	7812180236 7812180237	78/11/30 78/08/10	50-295 50-271	5	78	15500502	7812200200 7812200203	7 <del>0</del> /12/13 7 <del>0</del> /12/14	50-324 50-316	8 R
7812180242 7812180244	7812180236 7812180236	78/11/30 78/11/30	50-295 50-295	þ		12200207 1220020B	7 812200204 7 812200204	78/12/13 78/12/13	50-280 50-247	9 8
7812160245	7812180243	78/08/23	50-267	Ħ	78	15500510	7812200209	78/12/14	50-267	8
7812180302 7812180311	7812180292 7812180308	78/12/10 78/11/09	50-338 50-302	0		12200215 12200217	7812200211 7812200213	78/12/15 78/12/13	50-263 50-309	8 8
7812180316 7812180317	7812180315 7812180312	78/12/07 78/11/08	50-335 50-302	g g		12200223 12200218	7812200214 7812200220	78/12/18 78/12/14	50-358 50-309	K P
7812180323	7812180321	78/12/11	50-267	P	76	12200229	7812200226	78/12/14	90-368	8
7812180325 7812180331	7812180320 7812180328	78/11/09 78/11/03	50-259 50-267	0		12260231 12200239	7812200227 7812200234	78/12/12 78/12/14	50-285 50-338	8
7812180334 7812180334	7812180333	78/12/08 79/12/08	50-400 50-400	g Q		12200240 12200241	7812200236 7812200235	78/12/14 78/11/28	50-219 50-254	8 R
7812180338	7812180333	78/12/09	50-400	Ğ		12200245	7812200242	78/12/15	50-382	C
7812180340 7812180342	7812180335 7812180339	78/11/14 78/12/11	50-324 50-389	g M		12200246 12200247	7812200244 7812200243	78/11/30 78/12/13	50-259 50-537	K A
7812180343 7812180345	7812180333 7812180335	78/12/09	50-400 50-324	9	79	12200250	7812200248 7812200243	78/12/15 78/12/13	50-382 50-537	K A
7812180350	7812180348	78/10/30	30-298	Q		12200254	7812200252	78/12/13	50-309	8
7812180351 7812180353	7812180346 7812180349	78/12/08 78/11/08	50-34B 50-416	9		12200255 12200257	7812200253 7812200253	78/12/12 78/12/12	50-338 50-338	R
7812180356 7812180358	7812180348 7812180352	78/10/30 78/12/11	50-278 50-280	Q.	78	155005/5	7812200260 7812200264	78/12/01 78/12/08	50-280 50-285	8 9
7812180380	7812180376	78/11/30	50-285	Ρ		12200273	7812200270	78/12/11	50-302	8
7812180389 7812180390	7812180386 7812180376	78/11/30 78/11/30	50-160 50-285	E		12200274	7812200271 7812200116	78/12/08 78/11/29	50-29B 50-219	8 P
7812180401 7812180424	7812180401 7812180421	78/03/21 78/12/01	50-70 50-39	9	78	12200278	7812200275 7812200116	78/12/11 78/11/29	50-320 50-219	8 P
7812190020	7812190001	78/12/14	50-70	þ		12200287	7812200283	78/12/14	50~263	8
7812190059 7812190061	7812190053 7812190053	78/10/31 78/10/31	50-313 50-313	G G		12200299	7812200288 7812200292	78/11/20 78/11/17	50~395 50~358	J
7812190073 7812190074	7812190071 7812190072	78/12/08 78/12/12	50-52B 50-597	Ä	78	12200300	7812200299 7812200299	78/11/15	50-255 50-255	G G
7812190107	7812190105	78/12/14	50-219	8		12200307	7812200296	76/12/15	90-280	0
7812190111 7812190116	7812190110 7812190115	78/12/11 78/12/13	50~296 50~346	8 8		12200308	7812200306 7812200312	78/11/17 78/12/07	50-374 50-488	g Q
7812190122 7812190123	7812190119 7812190118	78/12/13 78/12/14	50~241	8	78	112200318	7812200312 7812200348	78/12/07 78/11/24	50-488 50-482	9
7812190124	7812190120	78/12/12	50-361	ĸ		12210005	7812210003	78/11/17	50-358	Q
7812190129 7812190130	7812190117 7812190127	78/10/27 78/12/11	50~483 50~269	9		112210029	7812210027 7812210035	78/12/07 78/12/07	50-498 50-413	Q Q
7812190131 7812190134	7812170121	78/12/08 78/12/15	50~247 50~320	8 R	76	12210043	7812210041 7812210035	78/11/21 78/12/07	50~358 50~413	Q Q
7812190139	7812190137	78/12/14	50~331	R		12210049	7812210046	78/11/14	20-565	0
7812190142 7812190149	7812190089 7812190148	78/12/08 78/12/15	50-445 50-280	G P		12210050	7812210047 7812210047	78/12/08 78/12/08	50-244 50-244	P
7812190132 7812190155	7B12190151	78/12/07	50-369 50-493	R	76	12210054	7812210046 7812210047	78/11/14 78/12/08	50-262 50-244	O)
7812190156	7812190117 7812190153	78/10/27 78/12/08	50-287	8		112210056	7812210053	78/11/24	50-245	Œ
7812190159 7812190160	7812190157 7812190158	78/12/06 78/11/17	50-206 50-329	R G		312210061 312210064	7812210059 7812210059	78/12/11 76/12/11	50-413 50-413	G G
7812170162 7812170170	7812190161	78/12/02	50-259	A	7€	312210070 312210071	7812210066 7812210068	78/11/17 78/12/11	50-245 50-250	P G
7812170170	7812190166 7812190171	78/12/13 78/11/29	50-289 50-344	R		312210074	7812210066	78/11/17	50-245	P
7812190160 7812190185	7812190174	78/12/14	50-3 50-454	P		312210075 312210076	7812210069 7812210068	78/11/17 78/12/11	50-546 50-250	Q Q
7812190188 7812190193	7812190184 7812190184	78/12/05 78/12/05	50-454 50-454	A	76	312210077 312210078	7912210066 7812210081	78/11/17 78/12/14	50-245 50-361	P
7812190197	7812190187 7812190194	78/11/08 78/11/17	50-267 50-133	0		915510105	7812210100	78/12/15	50-324	P
7812190238 7812190243	7812190235 7812190235	78/12/06	50-250 50-250	a		B12210104 B12210107	7812210100 7812210100	78/12/13 78/12/13	50-324 50-324	P P
7812200057 7812200057 7812200075	7812200036	78/12/05 78/11/30	50-556	0 H	76	812210109 B12210113	7812210100 7812210108	78/12/15 78/11/13	50-324 50-280	P
7812200099	7812200091 7812200091	78/11/09 78/11/09	20~585 20~585	0		12210114	7812210110	78/12/15	50-328	8

ACCE8810					ACCESSID	N NUMBER			
ENCLOSURE	PRINCIPAL DOCUMENT	DATE 188UED	SUBJECT CATEGOR		ENCLOGURE		DATE ISBUED	BUBJEC 1 CATEGOR	
7812210119 7812210131 7812210147 7812210149 7812210153	7812210110 7812210120 7812210143 7812210138 7812210143	78/12/15 78/11/17 78/11/08 78/12/06 78/11/08	50-528 50-264 50-460 50-335 50-460	8 0 0 0	7812260072 7812260129 7812260134 7812260134 7812260136	7812260087 7812260126 7812260131 7812260136 7812260134	78/11/30 78/12/18 78/12/18 78/12/18 78/11/07	50-443 50-322 50-327 50-322 50-321	0 A K K
7612210154 7612210155 7612210160 7812210161 7612210162	7812210138 7812210152 7812210157 7812210143 7812210159	78/12/06 78/11/09 78/12/15 78/11/08 78/10/24	50-335 50-324 50-269 50-460 50-368	0 R 0	7612260170 7612260172 7612260174 7612260174 7612260203	7812260166 7812260169 7812260168 7812260191 7812260200	78/12/13 78/12/14 78/12/14 78/12/15 78/12/20	50-458 50-266 50-496 50-289 50-285	A F A 8
7812210166 7812210169 7812210175 7812210179 7812210183	7812210143 7812210159 7812210167 7812210178 7812210167	78/11/08 78/10/24 78/12/15 78/11/13 78/12/15	50-460 50-368 50-500 50-445 50-500	0 9 A 0 A	7812260204 7812260209 7812260216 7812260219 7812260223	7812260202 7812260207 7812260214 7812260213 7812260218	78/12/22 78/12/20 78/12/14 78/12/14 78/12/18	50-341 50-282 50-334 50-245 50-273	К В В В К
7812210184 7812210185 7812210192 7812210193 7812210200	7812210180 7812210181 7812210187 7812210189 7812210193	78/11/17 78/12/14 78/12/14 78/12/15 78/12/06	50-298 50-325 50-325 50-237 50-275	0 8 8 8	7812260237 7812260248 7812260258 7812260261 7812260289	7812260222 7812260244 7812260256 7812260259 7812260288	78/12/20 78/12/14 78/12/19 78/12/13 78/12/08	50-306 50-318 50-263 50-320 50-245	9 9 8 8
7912210204 7912210209 7812210210 7912210211 7912210212	7812210201 7812210197 7812210206 7812210207 7812210202	78/12/13 78/11/30 78/12/14 78/12/15 78/12/14	50-213 50-275 50-272 50-3 50-349	R A F R	7912260295 7812260301 7912260305 7812260306 7812260328	7812260288 7812260288 7812260298 7812260288 7812260323	76/12/08 76/12/08 76/11/28 76/12/08 76/12/13	50-245 50-245 50-329 50-245 50-263	P P G P
7812210219 7812210219 7812210220 7812210221 7812210222	7812210203 7812210214 7812210216 7812210217 7812210218	78/12/01 78/12/06 78/12/11 78/12/08 78/12/14	50-295 50-295 50-313 50-304 50-325	8 9 8	7812270009 7812270020 7812270023 7812270033 7812270040	7812270003 7812270017 7812270018 7812270030 7812270030	78/12/15 78/11/09 78/12/04 78/11/30 78/11/30	50-220 50-313 50-243 50-320 50-320	9 0 0 0
7812210225 7812210226 7812210228 7812210232 7812210235	7812210223 7812210224 7812210227 7812210230 7812210229	78/12/01 78/12/11 78/12/07 78/12/18 78/11/28	50-275 50-368 50-275 50-255 50-275	A G B B	761 2270/51 781 2270/56 781 2270/56 781 2270/57 781 2270/66	7812270047 7812270030 7812270030 7812270047 7812270062	78/11/21 78/11/30 78/11/30 78/11/21 78/11/20	50-269 50-320 50-320 50-289 50-346	0 0 0 0
7812210239 7812210245 7812210252 7812210260 7812210263	7812210234 7812210242 7812210244 7812210259 7812210261	78/12/11 79/11/30 78/11/30 78/12/01 78/12/15	50-295 50-249 50-249 50-397 50-361	8 8 9	7812270070 7812270075 7812270076 7812270078 7812270151	7812270062 7812270073 7812270073 7812270074 7812270034	78/11/20 78/12/12 78/12/12 78/11/29 78/11/09	50-346 50-485 50-485 50-409 50-341	9 9 9
7812210265 7812210267 7812210301 7812210308 7812210312	7812210261 7812210281 7812210295 7812210295 7812210295	78/12/15 78/12/13 78/12/06 78/12/06 78/12/06	50-361 50-276 50-29 50-29 50-29	В 9 Р Р	7812270159 7812270156 7812270158 7812270166 7812270181	7812270149 7812270034 7812270157 7812270163 7812270178	78/11/13 78/11/09 78/12/06 78/12/20 78/12/20	50-334 50-341 50-502 50-407 50-315	0 С И Р
7812210324 7812210337 7812210344 7812210345 7812210346	7812210319 7812210333 7812210333 7812210319 7812210333	79/12/08 79/12/08 79/12/08 79/12/08 79/12/08	50-400 50-302 50-302 50-400 50-302	@ @ @ @	7812270197 7812270199 7812270206 7812270214 7812270217	7612270193 7612270196 7612270201 7812270211 7812270213	78/12/18 78/12/15 78/12/20 78/12/16 78/12/22	50-106 50-206 50-267 50-369 50-285	P B A B
7612210350 7612210363 7612210376 7612210380 7612210366	7812210333 7812210355 7812210370 7812210370 7812210370	78/12/08 78/11/08 78/11/15 78/11/15 78/11/15	50-206 50-206 50-306 50-302	0 0 0 0	7612270224 7612270226 7612270236 7612270238 7612270243	7812270219 7812270220 7812270232 7812270233 7812270239	78/12/22 78/12/20 78/12/21 78/12/20 78/12/19	50-285 50-315 50-263 50-338 50-362	8 6 6
7812210399 7812210401 7812210511 7812220029 7812220031	7812210370 7812210396 7812210506 7812220027 7812220027	79/11/15 79/12/06 79/12/15 79/11/30 78/11/30	50-206 50-482 50-247 50-305 50-305	@ 8 9 9	7812270245 7812270245 7812270250 7812270251 7812270251	7812270241 7812270247 7812270242 7812270246 7812270252	78/12/21 78/12/19 78/12/20 78/12/21 78/12/20	50-263 50-363 50-333 50-263 50-316	8 8 8
7812220040 7812220064 7812220069 7812220075 7812220077	7812220037 7812220063 7812220062 7812220074 7812220076	78/12/04 78/12/14 78/12/11 78/12/14 78/12/15	50-358 50-277 50-267 50-155 50-317	A R F 8 R	7812270260 7812270263 7812270263 7812270264 7812270268	7812270252 7812270258 7812270257 7812270252 7812270252	78/12/20 78/12/22 78/12/19 78/12/20 78/12/20	50-316 50-265 50-261 50-316 50-316	8 6 9 8
7812220080 7812220084 7812220086 7812220098 7812220100	7812220079 7812220081 7812220085 7812220095 7812220099	78/12/18 78/12/15 78/12/18 78/12/18 78/12/18	50-59 50-302 50-272 50-286 50-333	F 8 8	7612270259 7612270272 7612270272 7612270273 7612270273	7812270265 7812270261 7812270252 7812270264 7812270267	78/12/19 78/12/19 78/12/20 78/12/20 78/12/18	50-259 50-237 50-316 50-366 50-335	8 8 8 8
7812220105 7812220107 7812220118 7812260008 7812260019	7612220102 7812220106 7812220113 7812260003 7812260014	79/12/15 79/12/14 79/12/21 79/12/15 78/12/15	50-302 50-255 50-244 50-387 50-247	9 9 0 P	76:2270277 76:227027 76:2270262 76:2270263 78:2270265	7812270252 7812270270 7812270252 7812270252 7812270280	78/12/20 78/12/20 78/12/20 78/12/22 78/12/14	30-316 50-281 50-316 50-348 50-321	8 8 8 8
7812260023 7812260039 7812260057 7812260064 7812260067	7812260014 7812260014 7812260044 7812260062 7812260063	78/12/15 78/12/15 78/12/08 78/12/13 78/11/28	50-247 50-247 50-259 50-269 50-329	P P O P O	7612270296 7612270279 7612270279 7612270273 7612270273	7812270252 7812270284 7812270288 7812270291 7812270290	78/12/20 78/12/14 78/12/19 78/12/21 78/12/20	50-314 50-249 50-325 50-302 50-280	8 8 8

7812270301 7812270302 7812270303 7812270304	7812270297 7812270300 7812270298 7812270299	78/12/13 78/12/12 78/12/21 78/12/19	50-331 50-237 50-324 50-369	5 8 8	/81228034 761228036 781228035 781228035	7812280328 7812280351	78/12/19 78/12/19 78/12/11 78/12/11	50-250 50-250 50-466 50-466	0.0
7812270309 7812270310 7812270311 7812270312	7812270306 7812270299 7812270308 7812270307	78/12/21 78/12/19 78/12/20 78/12/15	50-348 50-348 50-348 50-251 50-348	8 8 8	781229036 781229000 781229001 781229001 781229001	7812290007 7812290007 7812290009	78/11/22- 78/12/19 78/12/19 78/11/24	50-344 50-62 50-62 50-305	9 P 9
7812270317 7812270317 7812270318 7812270321 7812270323	7812270304 7812270314 7812270315 7812270319 7812270316	78/12/20 78/12/20 78/12/18 78/12/20 78/12/21	50-366 50-321 50-366 50-219	8 8 8	781227002 781227002 781227002 781227003	7812290017 7812290017 7812290022 7812290028	78/11/24 78/11/24 78/11/24 78/11/24 78/11/13	50-305 50-255 50-255 50-266 50-317	9 9 9
7812270329 7812270329 7812270331 7812270333 7812270339	7812270325 7812270325 7812270326 7812270332 7812270337	78/12/20 78/12/18 78/12/20 78/12/22 78/11/15	50-280 50-366 50-366 50-285 50-409	8 8 8	7612290043 7812290044 781229004 781229004 781229004	7812290042 7812290038 7812290038 7812290038	78/12/15 78/11/13 78/12/15 78/12/15 78/12/15	50-390 50-311 50-390 50-390 50-390	9 9 9
7812270359 7812270364 7812270368 7812270372 7812270382	7812270357 7812270357 7812270357 7812270357 7812270377	78/12/15 78/12/15 78/12/15 78/12/15 78/11/28	50-369 50-369 50-369 50-369 50-397	0 0 0	781229005 781229005 781229006 781229006 781229006	7812290051 7812290055 7812290057	78/12/15 78/11/09 78/12/15 78/12/07 78/12/15	50-220 50-271 50-438 50-336 50-438	P 0 0
7812270385 7812270391 7812270409 7812270415 7812270423	7812270383 7812270387 7812270401 7812270401 7812270417	78/11/15 78/11/27 78/12/14 78/12/14 78/11/13	50-390 50-508 50-73 50-73 50-278	0 P P	781227006/ 781227006/ 781227007/ 781227007/ 781227008/	7 7812290055 7812290055 7812290076	78/11/22 78/12/15 78/12/15 78/11/13 78/11/17	50-339 50-439 50-439 50-201 50-280	9 9 9
7812270430 7812270436 7812270449 781227045	7812270424 7812270432 7812270446 7812270450	79/12/14 79/11/22 78/11/13 78/11/22	50-247 50-243 50-220 50-133	0 0 0	781229009 781229010 781229010 7812290101	7 7812290089 1 7812290094 2 7812290095 5 7812290100	78/11/30 78/12/18 78/12/22 78/12/05	50-219 50-302 50-275 50-502	8 0 F 0
7812270457 7812270478 7812280012 7812280015 7812280016	7812270453 7812270469 7812280009 7812280011 7812280011	79/11/13 79/12/06 78/11/13 79/12/12 79/12/12	50-333 50-322 50-272 50-305 50-305	0 0 P P	761227010' 761229011 781229011 781229011' 781229011'	7912290109 2 7812290094 3 7812290113	78/12/18 78/11/14 78/12/18 78/12/26 78/12/20	50-302 50-553 50-302 50-361 50-327	9 0 A 9
7612280018 7812280026 7612280040 7612280069 7612280070	7812280019 7812280019 7812280019 7812280055	78/12/12 78/12/07 78/12/07 78/12/15	50-305 50-250 50-250 50-424 50-424	P P 0 0	781 229012 781 229012 781 229012 781 229014	7812290114 7812290114 8 7812290114 1 7812290136	78/12/20 78/12/20 78/12/20 78/12/27	50-327 50-327 50-327 50-480 50-384	G G A
7812280070 7812280080 7812280100 7812280100 7812280130	7812280066 7812280066 7812280066 7812280079 7812280128	78/12/15 78/12/15 78/12/15 78/12/15 78/12/21 78/12/20	50-424 50-424 50-427 50-344	8 0 0	781229014 781229015 781229015 781229016 781229017	1 7812290148 2 7812290145 4 7812290160	78/12/27 78/12/19 78/12/20 78/12/07 78/12/20	50-508 50-424 50-368 50-245	A A B B R
7612280135 7812280142 7612280152 7612280200	7812280133 7812280137 7812280151 7812280157	78/12/21 78/12/16 78/12/21 78/12/20	50-369 50-336 50-466	8 6 K	781229018 781227020 781227020 781227020	7812290182 7812290197 7812290202 8 7812290200	78/12/22 78/12/07 78/12/26 78/12/22	50-315 50-298 50-255 50-346	P 8 8
7812280204 7812280215 7812280224 7812280229 7812280236	7812280197 7812280210 7812280223 7812280226 7812280231	78/12/20 78/12/08 78/11/28 78/11/21 78/11/30	50-477 50-311 50-361 50-456 50-219	0 0 0	781229021 781229021 781229021 781229021 781229021	4 7812290209 5 7812290210 8 7812290209	78/19/22 78/19/22 78/19/21 78/19/22 78/19/22	50-245 50-287 50-237 50-287	8 8 8
7812280239 7812280244 7812280245 7812280247	7812280237 7812280237 7812280241 7812280238	78/11/13 78/11/13 78/11/17 78/12/18	30-367 30-367 30-361 30-269	0 0 0 P	7612240.22 7812240.22 7612240.22 7612240.22	0 7812290211 3 7812290216 4 7812290221 6 7812290222	78/11/15 78/12/22 78/12/21 78/12/19 78/12/22	50-334 50-334 50-260 50-334	9 8 8
7812280264 7812280267 7812280277 7812280280	7812280238 7812280238 7812280238 7812280274 7812280271	79/12/18 79/12/19 78/12/19 78/12/19 78/12/08	50-269 50-269 50-269 50-267 50-237	6 E B B B	761229022 791229022 791229022 761229023 761229024	8 7812290225 5 7812290216 8 7812290234 3 7812290241	78/12/22 78/12/22 78/11/16 78/12/11	50-285 50-334 50-387 50-461	8 0 0
7812280288 7612280290 7812280291 7812280294 7812280306	7812280283 7812280284 7812280284 7812280284 7812280302	78/12/15 78/12/14 78/12/15 78/12/14 78/12/13	50-321 50-321 50-321 50-375	0 E Q	781229024 781229024 781229024 781229025 781229025	7812290242 7 7812290241 3 7812290249	78/11/28 78/12/20 78/12/11 78/11/15 78/12/04	30-267 50-498 50-461 50-485 50-322	9 9 9
7812280309 7812280310 7812280315 7812280316 7812280319	7612260300 7812260307 7812260302 7812260307 7612280313	78/11/08 78/12/15 78/12/13 78/12/15 78/11/09	50-293 50-440 50-395 50-440 50-318	0 0 0	781829024 781229024 781229027 781229027 781229027	8 7612290255 1 7812290266 5 7812290266	78/12/29 78/12/07 78/12/29 78/12/29 78/12/29	50~576 30~556 30~596 50~596 50~596	A 9 9
7612260332 7812280334 7812280339 7612280340 7612280342	7812280325 7812280325 7812280328 7812280325 7812280326	78/12/07 78/12/07 78/12/19 78/12/07 78/12/19	50-329 50-329 50-260 50-329 50-260	0 0	79080 <b>8</b> 0	A 7812120115	78/11/03	50-295	8
		•	<b>-</b>	_					



#### APPENDIX

## **DEFINITIONS OF DOCKET 50 CATEGORIES**

# A. APPLICATION/CONSTRUCTION STAGE DOCUMENTS AND CORRESPONDENCE

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Application for construction permit.
- 2. General Information submitted with construction permit application.
- 3. Amendments and changes to items 1 and 2.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Correspondence and documents relating to unresolved design and construction issues.
- 6. Meeting announcements and summaries of meeting discussions on issues of item 5.
- 7. Correspondence regarding the Preliminary Safety Analysis Report (PSAR).
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Construction Permit, amendments, and correspondence relating to the construction permit.
- 10. Scheduling of license application submission or review.
- 11. Environmental review information.
- 12. Application for operating license.
- 13. General Information submitted with operating license application.
- 14. Amendments and changes to items 12 and 13.
- 15. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 16. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 17. Reports of site visits.
- 18. Backup technical documents (e.g., topical reports) submitted in support of the application.

### B. UTILITY PRELIMINARY SAFETY ANALYSIS REPORT (PSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

- 1. Preliminary Safety Analysis Report (PSAR) submitted by utility (formerly called Hazards Summary Report or Safety Analysis Report).
- 2. Amendments and changes to the PSAR.

#### C. UTILITY ENVIRONMENTAL REPORT (ER), AMENDMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are filed in Categories A, D, M, P or R.

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal and acknowledgement letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal register notices citing the availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

## D. NRC DRAFT AND FINAL ENVIRONMENTAL (IMPACT) STATEMENTS (DES AND FES), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other environmental documents and correspondence are in categories A, C, M, P or R.

- 1. Draft and Final Environmental (Impact) Statements (DES and FES) prepared by the NRC.
- 2. Supplements to the DES and FES.
- 3. Correspondence relating to the DES and FES.
- 4. Comments from other federal, state and local government agencies.
- 5. Transmittal and acknowledgement letters.
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Federal register notice citing availability of items 1 and 2.
- 9. Site visits to obtain information for DES or FES.
- Meeting announcements or reports of meetings where the primary subject of discussion is the DES or FES.

#### E. NRC SAFETY EVALUATION REPORT (SER), SUPPLEMENTS AND CORRESPONDENCE

This category is strictly limited to the items listed below. Other documents dealing with safety related issues are filed in categories A, P or W, depending on the phase of the licensing process.

- 2. Supplements to SER.
- 3. Correspondence relating to SER.
- 4. Federal register notices citing availability of items 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- Meeting announcements or reports of meetings where the primary subject of discussion is the SER.
- 8. Transmittal and acknowledgement letters.

#### F. SECURITY, MEDICAL, EMERGENCY AND FIRE PROTECTION PLANS

All plans in this category are individual submissions. Information submitted as part of the PSAR or FSAR is excluded.

- 1. Fire Hazard Protection Plan and surveys.
- 2. Plant evacuation correspondence.
- 3. Safeguards Contingency Plans.
- 4. Review of Health Physics Program.
- Correspondence relating to aforementioned plans.
- 6. Supplements, changes and revisions to plans.

#### G. LEGAL AND ADJUDICATORY CORRESPONDENCE

This category contains all non-antitrust legal and adjudicatory documentation, except for transcripts, briefings and testimony, which are filed in category T.

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) hearing related documents.
- 2. Federal register notices regarding hearings.
- 3. Requests to make appearances at hearings.
- 4. Motions, briefs, arguments, statements and related correspondence filed by participants for hearings.
- 5. Transmittal of supporting documents (e.g., SER, FES) to the boards.
- 6. Correspondence to and from intervenors.
- 7. Board orders and decisions.
- 8. Petitions for Commission action.
- 9. Legal filings and Commission orders and decisions resulting from item 8.

tion are included.

- 1. Change of address notifications.
- 2. Changes in structure of organization.
- 3. Changes in service lists.
- 4. NRC requests to applicant for additional copies of documents.
- 5. Correspondence from the public requesting information about the facility and NRC responses.
- 6. Correspondence on strictly administrative matters.
- 7. Letters of support, concern or opposition to the facility.
- 8. Correspondence regarding the Local Public Document Rooms (LPDRs).
- 9. Professional qualification statements not pertaining to the hearing process.

#### I. FINANCIAL INFORMATION

This category contains all financial information except that submitted as part of the application or its amendments or relating to the imposition of civil penalties.

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

#### J. INSURANCE AND INDEMNITY INFORMATION

- 1. Indemnity agreements and amendments.
- 2. Endorsements insurance policies.
- 3. Other correspondence regarding indemnity and insurance matters.

#### K. UTILITY FINAL SAFETY ANALYSIS REPORT (FSAR) AND AMENDMENTS

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR) (formerly called Final Hazards Summary Report).
- 2. Amendments and changes to the FSAR.

of items 1 and 2.

applicants can carry out limited site preparation and construction prior to the granting of a construction permit.

- 1. Limited Work Authorizations (LWA) and amendments.
- 2. Correspondence pertaining to work performed under LWA's.

## M. ANTITRUST REVIEW AND ANTITRUST CORRESPONDENCE

- Document submitted as part of the applications for a construction permit and operating license
  entitled "Information Requested by the Attorney General for Antitrust Review"
- 2. Correspondence where the primary topic of discussion is antitrust matters.
- All antitrust proceeding related documents except for hearing transcripts, testimony and briefings, which are filed in category N.

## N. ANTITRUST HEARING TRANSCRIPTS, TESTIMONY AND BRIEFINGS

This category contains word-for-word transcripts of hearings, testimony and briefings in antitrust matters. Related correspondence falls in category M.

# O. ADVISORY COMMITTEE ON REACTOR SAFEGUARDS (ACRS) REPORTS AND CORRESPONDENCE

- 1. Correspondence and letter reports relating to Advisory Committee on Reactor Safeguards (ACRS) reviews.
- 2. Correspondence from ACRS.
- 3. Announcement of ACRS meetings.
- 4. Transmittal and acknowledgement letters.
- 5. ACRS reports.
- 6. Statements and written testimony by ACRS members or presented by individuals at ACRS proceedings.
- 7. Minutes at ACRS Subcommittee Meetings.

#### P OPERATING LICENSE STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Application/Construction Stage (category A) file for general technical items dated from the issuance of the operating license to the application for termination of the license.

- 1. Operating license, amendments, proposed amendments, changes and related correspondence.
- 2. Technical specifications and changes.

- 5. Correspondence regarding the Final Safety Analysis Report (FSAR).
- 6. All general technical correspondence, meeting announcements or meeting summaries relating to technical specifications, the operating license or technical issues arising after the issuance of the operating license.
- 7. Correspondence regarding codes (e.g., ASME), regulations, laws or changes in policy that may affect plant operation or bear on the operating license.
- 8. Information on the Standard Review Plan (STP).
- 9. Results of surveys or tests conducted in accordance with the technical specifications (not periodic reports, which fall in category R).
- 10. Correspondence relating to NRC's Systematic Evaluation Program (SEP).
- 11. Owner's group meeting announcements and reports.
- 12. Quality assurance information.
- 13. Environmental matters (technical).
- 14. Emergency core cooling system documents.
- 15. Radioactive waste information.
- 16. Correspondence regarding expansion of spent fuel storage pool.
- 17. Start-up test reports.
- 18. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 19. Reports of site visits.

# Q. INSPECTION REPORTS; IE BULLETINS, CIRCULARS AND INFORMATION NOTICES; CIVIL PENALTIES AND RELATED CORRESPONDENCE

- 1. Inspection reports.
- 2. IE Bulletins (formerly called Regulatory Operations (RO) Bulletins), Circulars and Information Notices.
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Pre-service and in-service inspections and procedures.
- 7. Correspondence and orders relating to imposition and payment of civil penalties, including Notification of Significant Enforcement Actions (EN's).
- 8. Any correspondence relating to inspection and enforcements that does not specifically relate to incidents or events as defined in category S.

- 1. Monthly, semiannual, or annual operating reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Periodic personnel exposure reports.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks on Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets.

5. Correspondence or other documents relating to the above listed items.

#### S. REPORTABLE OCCURRENCES, PNO'S, PNS'S AND RELATED CORRESPONDENCE

This category contains all materials relating to abnormal, unusual, reportable or nonroutine occurrences or events. This includes:

- 1. All 24-hour, 10-day, 30-day, interim and final Licensee Event Reports (LER's) and follow-up correspondence (also called incident reports, abnormal occurrence reports and reportable occurrences).
- 2. Potential or possible reportable deficiency reports and related correspondence.
- 3. Personnel exposure reports.
- 4. Construction deficiency reports submitted under 10 CFR 50.55e.
- 5. Preliminary Notification of Occurrence (PNO's) and Preliminary Notification of Safeguards Events (PN's).
- 6. Environmental Technical Specifications violation reports and Environmental Event reports.
- 7. Part 21 Reports of defects and noncompliance.
- 8. Correspondence or other documents relating to items 1-7.

#### T. TRANSCRIPTS, TESTIMONY AND BRIEFINGS ON NON-ANTITRUST MATTERS

This category contains all word-for-word transcripts, except for antitrust matters (category N), testimony and briefings, and congressional matters (category U).

- 1. Atomic Safety and Licensing Board (ASLB) and Atomic Safety and Licensing Appeal Board (ASLAB) transcripts.
- 2. Testimony and statements submitted to ASLB and ASLAB.
- 3. Commission meeting transcripts.
- 4. NRC staff briefings to the Commission.
- 5. Statements and written testimony submitted at Commission meeting or hearings.
- 6. Transcripts of utility briefs to NRC staff.
- 7. Advisory Committee on Reactor Safeguards (ACRS) meeting transcripts.

#### CONGRESSIONAL/EXECUTIVE CORRESPONDENCE

This category contains correspondence on substantive matters. Routine responses to constituent inquiries are filed in category H.

- 1. Statements and testimony before Congress or before bodies/committees appointed by the Executive or Legislative Branches.
- 2. Preparatory and backup documents for item 1.
- 3. Correspondence to and from NRC Office of Congressional Affairs, Congress and the Executive Branch on other than constituent response matters.

### V. LICENSING OPERATORS AND RELATED CORRESPONDENCE

- 1. Operator licenses or administrative information bearing on licensing of operators.
- 2. NRC examination results.
- 3. Power plant examination summary sheet.

#### W. DECOMMISSIONING STAGE DOCUMENTS AND CORRESPONDENCE

This file assumes the position of the Operating License Stage (category P) file for general technical items from the application for termination of the operating license onward.

- 1. Application for authority to voluntarily surrender license.
- 2. Application to dismantle the facility and dispose of component parts.
- Technical documents submitted in support of items 1 and 2, such as: Decommissioning Plan,
  Dismantling Plan, Environmental Report on Dismantling, Safety Analysis Report on Decommissioning.
- 4. Documents relating to disposal of radioactive material and decontamination of the site.
- 5. Other correspondence relating to above items.
- 6. All documentation relating to the ongoing operation of the plan, formerly filed in category P.

NOKEG-0540
Special Edition
RECIPIENT'S ACCESSION NO.
5. DATE REPORT COMPLETED  MONTH   YEAR AUGUST   1981  DATE REPORT ISSUED  MONTH   YEAR SEPTEMBER   YEAR  6. (Leave blank)  8. (Leave blank)  10. PROJECT/TASK/WORK UNIT NO.  11. CONTRACT NO.
ED (Inclusive dates)
14. (Leave Olank)
ceived and generated by material from 1978 that t. The documents in this ource, and report number.

17. KEY WORDS AND DOCUMENT ANALYSIS

17a. DESCRIPTORS